

| <b>VE64BHP</b>            | <b>A&amp;E</b>                                                        |              | <b>Derriford Amb Stn</b> |              |              |                      |                 |
|---------------------------|-----------------------------------------------------------------------|--------------|--------------------------|--------------|--------------|----------------------|-----------------|
| <b>PDI Inspection</b>     | <b>23/01/2015</b>                                                     | <b>10:57</b> | <b>11/03/2015</b>        | <b>13:02</b> | <b>167</b>   | <b>Derriford</b>     | <b>DE017796</b> |
| 02 Cab Assembly 1         | Replaced vehicle dimension sticker                                    |              |                          |              |              |                      |                 |
| 71 Body Exterior 1        | Fit manger charging bracket                                           |              |                          |              |              |                      |                 |
| PDI Inspection            |                                                                       |              |                          |              |              |                      |                 |
| <b>SAFETY INSPECTION</b>  | <b>16/03/2015</b>                                                     | <b>07:25</b> | <b>16/03/2015</b>        | <b>09:42</b> | <b>682</b>   | <b>Derriford</b>     | <b>DE018033</b> |
| 02 Cab Assembly 1         | Refitted knob on centre storage box                                   |              |                          |              |              |                      |                 |
| 18 Wheels Check Torques   |                                                                       |              |                          |              |              |                      |                 |
| 86 Door Lock              | Side door locking its self                                            |              |                          |              |              | Awaiting Warranty    |                 |
| Safety Inspection         |                                                                       |              |                          |              |              |                      |                 |
| <b>Vehicle Deep Clean</b> | <b>16/03/2015</b>                                                     | <b>12:00</b> | <b>17/03/2015</b>        | <b>12:09</b> | <b>682</b>   | <b>Derriford</b>     | <b>DE018037</b> |
| Vehicle Deep Clean        | Vehicle Deep Clean                                                    |              |                          |              |              |                      |                 |
| <b>Unplanned Repair</b>   | <b>07/04/2015</b>                                                     | <b>07:30</b> | <b>07/04/2015</b>        | <b>08:41</b> | <b>2,930</b> | <b>Derriford</b>     | <b>DE018129</b> |
| 16 Suspension 1           | Check for knocking noise found rear anti roll bar loose tighten bolts |              |                          |              |              |                      |                 |
| <b>Unplanned Repair</b>   | <b>10/04/2015</b>                                                     | <b>10:00</b> | <b>10/04/2015</b>        | <b>16:36</b> | <b>3,690</b> | <b>Derriford</b>     | <b>DE018147</b> |
| 44 Add Ad Blue            | Top up adblue                                                         |              |                          |              |              |                      |                 |
| 71 Body Exterior 1        | Remove inscure slider plate & straighten cover plate                  |              |                          |              |              | Awaiting Body Repair |                 |
| <b>SAFETY INSPECTION</b>  | <b>27/04/2015</b>                                                     | <b>07:04</b> | <b>27/04/2015</b>        | <b>10:36</b> | <b>5,200</b> | <b>Derriford</b>     | <b>DE018221</b> |
| 18 Wheels Check Torques   |                                                                       |              |                          |              |              |                      |                 |
| 31 Battery Aux            | Checklist Defect 2x battery connections secured                       |              |                          |              |              |                      |                 |
| 71 Body Exterior 1        | Remove inscure slider plate & straighten cover plate                  |              |                          |              |              | Awaiting Body Repair |                 |
| 86 Door Lock              | Side door locking its self Been repaired under warranty               |              |                          |              |              |                      |                 |
| 86 Doors                  | Checklist Defect Scoop door catch adjusted                            |              |                          |              |              |                      |                 |
| Safety Inspection         |                                                                       |              |                          |              |              |                      |                 |

|                                                                           |                                                                                                               |              |                   |              |               |                  |                 |
|---------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b>                                                 | <b>27/04/2015</b>                                                                                             | <b>11:00</b> | <b>27/04/2015</b> | <b>14:25</b> | <b>5,200</b>  | <b>Derriford</b> | <b>DE018224</b> |
| Vehicle Deep Clean                                                        | Vehicle Deep Clean                                                                                            |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>                                                   | <b>13/05/2015</b>                                                                                             | <b>10:00</b> | <b>13/05/2015</b> | <b>10:15</b> | <b>7,193</b>  | <b>Derriford</b> | <b>DE018323</b> |
| 44 Add Ad Blue                                                            | Topped up by crew                                                                                             |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>                                                   | <b>26/05/2015</b>                                                                                             | <b>07:38</b> | <b>26/05/2015</b> | <b>13:00</b> | <b>8,354</b>  | <b>Derriford</b> | <b>DE018358</b> |
| 45 Engine Ad Blue<br>56 Comms Equipment                                   | Topped up by crew<br>Sat nav not working                                                                      |              |                   |              |               |                  |                 |
| <b>SAFETY INSPECTION</b>                                                  | <b>08/06/2015</b>                                                                                             | <b>07:02</b> | <b>09/06/2015</b> | <b>15:00</b> | <b>10,152</b> | <b>Derriford</b> | <b>DE018435</b> |
| 15 Steering 1<br>18 Wheels Check Torques<br>86 Doors<br>Safety Inspection | Checklist Defect Adjust tracking<br>Checklist Defect Side door top magnet not contacting<br>Awaiting Warranty |              |                   |              |               |                  |                 |
| <b>Vehicle Deep Clean</b>                                                 | <b>09/06/2015</b>                                                                                             | <b>07:41</b> | <b>09/06/2015</b> | <b>11:09</b> | <b>10,152</b> | <b>Derriford</b> | <b>DE018444</b> |
| Vehicle Deep Clean                                                        | Vehicle Deep Clean                                                                                            |              |                   |              |               |                  |                 |
| <b>Defect Repair</b>                                                      | <b>15/06/2015</b>                                                                                             | <b>07:09</b> | <b>15/06/2015</b> | <b>13:52</b> | <b>10,691</b> | <b>Derriford</b> | <b>DE018465</b> |
| 17 Tyres                                                                  | Renew n.s.f. tyre & adjust tracking. Spare Continental fitted                                                 |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>                                                   | <b>24/06/2015</b>                                                                                             | <b>12:00</b> | <b>24/06/2015</b> | <b>13:06</b> | <b>11,987</b> | <b>Derriford</b> | <b>DE018511</b> |
| 02 Mirrors<br>44 Add Ad Blue                                              | Renewed ns cover<br>Topped up by crew                                                                         |              |                   |              |               |                  |                 |

|                         |                   |              |                   |              |               |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>10/07/2015</b> | <b>09:30</b> | <b>10/07/2015</b> | <b>10:07</b> | <b>14,058</b> | <b>Derriford</b> | <b>DE018586</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

|                            |                                                              |  |  |  |  |  |  |
|----------------------------|--------------------------------------------------------------|--|--|--|--|--|--|
| 03 Instruments & Sensors 1 | Vehicle in limp mode check & clear stored faults & road test |  |  |  |  |  |  |
|----------------------------|--------------------------------------------------------------|--|--|--|--|--|--|

|                  |                   |              |                   |              |               |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Breakdown</b> | <b>14/07/2015</b> | <b>11:42</b> | <b>14/07/2015</b> | <b>13:46</b> | <b>14,223</b> | <b>Derriford</b> | <b>DE018598</b> |
|------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

|                               |                                                             |  |  |  |  |  |  |
|-------------------------------|-------------------------------------------------------------|--|--|--|--|--|--|
| 17 Tyres Replace<br>Breakdown | O/s/r outer tyre replaced by ATS<br>R/O tyre has a hole in. |  |  |  |  |  |  |
|-------------------------------|-------------------------------------------------------------|--|--|--|--|--|--|

|                          |                   |              |                   |              |               |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>20/07/2015</b> | <b>07:11</b> | <b>20/07/2015</b> | <b>10:47</b> | <b>15,620</b> | <b>Derriford</b> | <b>DE018621</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

|                                                                                                                                         |                                                                                                                                                                                             |  |  |  |  |  |  |
|-----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|--|
| 02 Cab Assembly 1<br>18 Wheels Check Torques<br>31 Battery Comms<br>71 Body Exterior 1<br>86 Doors<br>87 Stretcher<br>Safety Inspection | repaired cab storage knob on centre storage<br>rescured comms battery<br>Renewed nsf lower body corner<br>Checklist Defect Side door top magnet not contacting<br>supplied stryker pedimate |  |  |  |  |  |  |
|-----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|--|

|                           |                   |              |                   |              |               |                  |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>20/07/2015</b> | <b>10:50</b> | <b>21/07/2015</b> | <b>08:54</b> | <b>15,620</b> | <b>Derriford</b> | <b>DE018623</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

|                    |                    |  |  |  |  |  |  |
|--------------------|--------------------|--|--|--|--|--|--|
| Vehicle Deep Clean | Vehicle Deep Clean |  |  |  |  |  |  |
|--------------------|--------------------|--|--|--|--|--|--|

|                 |                   |              |                   |              |               |                  |                 |
|-----------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>ACCIDENT</b> | <b>27/07/2015</b> | <b>07:00</b> | <b>03/08/2015</b> | <b>11:38</b> | <b>16,075</b> | <b>Derriford</b> | <b>DE018653</b> |
|-----------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

|               |                  |  |  |  |  |  |  |
|---------------|------------------|--|--|--|--|--|--|
| Acc Rep Front | Front end damage |  |  |  |  |  |  |
|---------------|------------------|--|--|--|--|--|--|

|                         |                   |              |                   |              |               |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>11/08/2015</b> | <b>08:00</b> | <b>11/08/2015</b> | <b>13:08</b> | <b>16,671</b> | <b>Derriford</b> | <b>DE018717</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

|                                                                              |                                                                                                                                                                                                                                                  |  |  |  |  |                   |
|------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|-------------------|
| 34 Emergency Lights<br>52 Electrical Aux<br>54 Reversing Systems<br>86 Doors | Replaced n/s scene & rear body blue light that had been smashed off<br>Electrical Auxs PHONE CHARGER NOT WORKING PCE dealing<br>Electrical Auxs REVERSING CAMERA U/S<br>Emg Warning Devices constant alert locker door unless slammed shut Notes |  |  |  |  | Awaiting Warranty |
|------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|-------------------|

|                                |                                                               |       |            |       |        |                      |          |
|--------------------------------|---------------------------------------------------------------|-------|------------|-------|--------|----------------------|----------|
| SAFETY INSPECTION              | 01/09/2015                                                    | 07:14 | 01/09/2015 | 12:14 | 19,906 | Derriford            | DE018804 |
| 17 Tyres Replace               | Renewed 6x tyres                                              |       |            |       |        |                      |          |
| 18 Wheels Check Torques        |                                                               |       |            |       |        |                      |          |
| 54 Reversing Systems           | Electrical Auxs REVERSING CAMERA U/S,repaired warranty        |       |            |       |        |                      |          |
| Safety Inspection              |                                                               |       |            |       |        |                      |          |
| 92 - C Service                 |                                                               |       |            |       |        |                      |          |
| Service C                      |                                                               |       |            |       |        |                      |          |
| Tail Lift 6 Monthly Inspection | Statutory Inspection                                          |       |            |       |        |                      |          |
| Vehicle Deep Clean             | 01/09/2015                                                    | 12:17 | 03/09/2015 | 13:57 | 19,906 | Derriford            | DE018807 |
| Vehicle Deep Clean             | Vehicle Deep Clean                                            |       |            |       |        |                      |          |
| Breakdown                      | 09/09/2015                                                    | 17:52 | 10/09/2015 | 07:26 | 20,893 | Derriford            | DE018853 |
| 17 Tyres Replace               | renewed ns tyres                                              |       |            |       |        |                      |          |
| 18 Wheels                      | renewed 2x ns wheels                                          |       |            |       |        |                      |          |
| 18 Wheels Removal              | Body Exterior Both nearside wheels damaged, Repaired as above |       |            |       |        |                      |          |
| Breakdown                      | 2 x tyres flat, wheel damaged.                                |       |            |       |        |                      |          |
| Unplanned Repair               | 21/09/2015                                                    | 07:00 | 21/09/2015 | 07:14 | 22,396 | Derriford            | DE018902 |
| 34 Lights Bulb Replacement     | renewed os dipped beam bulb                                   |       |            |       |        |                      |          |
| Breakdown                      | 24/09/2015                                                    | 18:22 | 25/09/2015 | 15:25 | 22,820 | Derriford            | DE018926 |
| 71 Body Exterior 1             | Damage to o/s of body                                         |       |            |       |        | Awaiting Body Repair |          |
| 71 Body Exterior 2             | Replaced autoeject socket cover                               |       |            |       |        |                      |          |
| Breakdown                      | Charger point                                                 |       |            |       |        |                      |          |
| SAFETY INSPECTION              | 12/10/2015                                                    | 07:06 | 12/10/2015 | 11:22 | 25,239 | Derriford            | DE018996 |
| 13 Brake Pads                  | renewed front pads                                            |       |            |       |        |                      |          |

|                                                                                   |                                                                                                                                                                                                                                                 |              |                   |              |               |                  |                 |
|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| 18 Wheels Check Torques<br>45 Engine 1<br>71 Body Exterior 1<br>Safety Inspection | Engine engine management light , cut out x2<br>Damage to o/s of body                                                                                                                                                                            |              |                   |              |               |                  |                 |
| <b>Vehicle Deep Clean</b>                                                         | <b>12/10/2015</b>                                                                                                                                                                                                                               | <b>11:39</b> | <b>13/10/2015</b> | <b>08:58</b> | <b>25,239</b> | <b>Derriford</b> | <b>DE019004</b> |
| Vehicle Deep Clean                                                                | Vehicle Deep Clean                                                                                                                                                                                                                              |              |                   |              |               |                  |                 |
| <b>Breakdown</b>                                                                  | <b>02/11/2015</b>                                                                                                                                                                                                                               | <b>06:13</b> | <b>06/11/2015</b> | <b>15:10</b> | <b>28,131</b> | <b>Derriford</b> | <b>DE019087</b> |
| Breakdown                                                                         | MDT/Radio/Satnav                                                                                                                                                                                                                                |              |                   |              |               |                  |                 |
| <b>ACCIDENT</b>                                                                   | <b>02/11/2015</b>                                                                                                                                                                                                                               | <b>10:46</b> | <b>06/11/2015</b> | <b>15:09</b> | <b>28,131</b> | <b>Derriford</b> | <b>DE019093</b> |
| 02 Mirrors<br>71 Body Exterior 1                                                  | Body Exterior near side mirror struck & shattered Already been repaired<br>O/S body damage                                                                                                                                                      |              |                   |              |               |                  |                 |
| <b>SAFETY INSPECTION</b>                                                          | <b>23/11/2015</b>                                                                                                                                                                                                                               | <b>07:16</b> | <b>23/11/2015</b> | <b>09:49</b> | <b>30,269</b> | <b>Derriford</b> | <b>DE019172</b> |
| 02 Cab Assembly 2<br>18 Wheels Check Torques<br>Safety Inspection                 | Refitted cab storage pivot                                                                                                                                                                                                                      |              |                   |              |               |                  |                 |
| <b>Vehicle Deep Clean</b>                                                         | <b>23/11/2015</b>                                                                                                                                                                                                                               | <b>11:00</b> | <b>23/11/2015</b> | <b>14:32</b> | <b>30,271</b> | <b>Derriford</b> | <b>DE019176</b> |
| Vehicle Deep Clean                                                                | Vehicle Deep Clean                                                                                                                                                                                                                              |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>                                                           | <b>01/12/2015</b>                                                                                                                                                                                                                               | <b>09:00</b> | <b>03/12/2015</b> | <b>15:15</b> | <b>31,148</b> | <b>Derriford</b> | <b>DE019222</b> |
| 03 Instruments & Sensors 1<br>56 Comms Equipment<br>86 Doors Rear<br>Travel Time  | Engine Stalls, cant start engine at times Repaired by Mercedes of Plymouth<br>Electrical Auxs Satnav not powering up.Been repaired<br>O/s/r door stay has sheared off from floor mount Replaced under warranty<br>Collect vehicle from Mercedes |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>                                                           | <b>04/12/2015</b>                                                                                                                                                                                                                               | <b>08:00</b> | <b>04/12/2015</b> | <b>14:59</b> | <b>31,196</b> | <b>Derriford</b> | <b>DE019242</b> |

03 Instruments & Sensors 1 Ad blue light & engine managment lights on See notes Mercedes P/O 151120372  
Travel Time Collect vehicle from dealers

**Unplanned Repair 11/12/2015 07:00 12/12/2015 09:46 31,589 Derriford DE019274**

03 Instruments & Sensors 1 EML light on Nox sensor replaced by Mercedes of Plymouth  
34 Lights Bulb Replacement Locate missing n/s headlight bulb holder & replaced bulb & refitted  
Travel Time Take vehicle to Dealers

**BREAKDOWN 14/12/2015 13:00 18/12/2015 16:52 31,866 Derriford DE019289**

03 Instruments & Sensors 1 Eml light on vehicle gone back into limp mode Repaired by Mercedes of Plymouth  
Travel Time

**SAFETY INSPECTION 04/01/2016 08:15 05/01/2016 11:06 34,523 Derriford DE019369**

13 Brakes 1  
18 Wheels Check Torques  
34 Lights Bulb Replacement  
43 Exhaust System 1  
45 Engine Ad Blue  
89 Seats Rear seat swivel bearings stiff Awaiting Warranty  
Safety Inspection  
MOT Pre Test  
Travel Time  
MOT Done by A J Motors P/O 151121170

**Vehicle Deep Clean 08/01/2016 07:12 08/01/2016 10:40 34,894 Derriford DE019406**

Vehicle Deep Clean Vehicle Deep Clean

**SAFETY INSPECTION 11/02/2016 07:00 11/02/2016 14:47 38,573 Derriford DE019569**

18 Wheels Check Torques  
71 Body External Steps Side step end cover renewed

|                                |                                                                             |       |            |       |        |           |                   |
|--------------------------------|-----------------------------------------------------------------------------|-------|------------|-------|--------|-----------|-------------------|
| 89 Seats                       | Rear seat swivel bearings stiff                                             |       |            |       |        |           | Awaiting Warranty |
| Safety Inspection              |                                                                             |       |            |       |        |           |                   |
| 93 - D Service                 |                                                                             |       |            |       |        |           |                   |
| Service D                      |                                                                             |       |            |       |        |           |                   |
| Tail Lift 6 Monthly Inspection | Statutory Inspection                                                        |       |            |       |        |           |                   |
| Tail Lift Annual Service       | Statutory Inspection and Weight Test Done by South West Lifts P/O 151124578 |       |            |       |        |           |                   |
| Vehicle Deep Clean             | 12/02/2016                                                                  | 06:56 | 12/02/2016 | 14:37 | 38,578 | Derriford | DE019572          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                          |       |            |       |        |           |                   |
|                                |                                                                             |       |            |       |        |           |                   |
| Unplanned Repair               | 21/03/2016                                                                  | 12:05 | 22/03/2016 | 10:38 | 42,903 | Derriford | DE019728          |
| 03 Instruments & Sensors 1     | Engine 'service overdue' warning message Reset service mileage              |       |            |       |        |           |                   |
| 45 Engine 1                    | Engine noisy shuddering when starting. hissing sound Repaired by Mercedes   |       |            |       |        |           |                   |
| 89 Seatbelts                   | As above                                                                    |       |            |       |        |           |                   |
| 89 Seats                       | Rear seat swivel bearings stiff Replaced seat bearings                      |       |            |       |        |           |                   |
| Travel Time                    | Take vehicle to dealers                                                     |       |            |       |        |           |                   |
| Breakdown                      | 24/03/2016                                                                  | 20:39 | 25/03/2016 | 08:00 | 43,158 | Derriford | DE019760          |
| 03 Instruments & Sensors 1     | Checked with star & cleared out stored fault codes                          |       |            |       |        |           |                   |
| Breakdown                      | vehicle goes into LIMP mode frequently                                      |       |            |       |        |           |                   |
| SAFETY INSPECTION              | 25/03/2016                                                                  | 07:03 | 25/03/2016 | 13:59 | 43,158 | Derriford | DE019763          |
| 02 Cab Assembly 1              | Brake pedal rubber split No parts                                           |       |            |       |        |           | Awaiting Parts    |
| 02 Mirrors                     | Replaced o/s mirror frame & glass                                           |       |            |       |        |           |                   |
| 13 Handbrake                   | Reset h/brake cables                                                        |       |            |       |        |           |                   |
| 17 Tyres Replace               | Replaced n/s/f & all rear tyres                                             |       |            |       |        |           |                   |
| 18 Wheels Check Torques        |                                                                             |       |            |       |        |           |                   |
| 34 Lights Bulb Replacement     | Replaced n/s headlight bulb                                                 |       |            |       |        |           | Awaiting Parts    |
| 44 Add Ad Blue                 | Topped up add blue & clean off excess                                       |       |            |       |        |           |                   |
| 87 - Stretchers/Chairs/Boards  | Replace grip tape on carry chair                                            |       |            |       |        |           |                   |
| 89 Seats                       | Adjust rear swivel seat lock pin Attendants seat adjuster bar Missing       |       |            |       |        |           |                   |
| Safety Inspection              |                                                                             |       |            |       |        |           |                   |
| Fit Throw Lines & SOP          |                                                                             |       |            |       |        |           |                   |

|                                       |                                                                       |              |                   |              |               |                  |                 |
|---------------------------------------|-----------------------------------------------------------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b>             | <b>28/03/2016</b>                                                     | <b>07:14</b> | <b>28/03/2016</b> | <b>14:20</b> | <b>43,304</b> | <b>Derriford</b> | <b>DE019773</b> |
| Vehicle Deep Clean                    | Vehicle Deep Clean                                                    |              |                   |              |               |                  |                 |
| <b>Defect Repair</b>                  | <b>30/03/2016</b>                                                     | <b>09:52</b> | <b>06/04/2016</b> | <b>12:29</b> | <b>43,450</b> | <b>Derriford</b> | <b>DE019783</b> |
| 02 Cab Assembly 1                     | Replaced brake pedal rubber                                           |              |                   |              |               |                  |                 |
| 03 Instruments & Sensors 1            | Rail pressure sensor replaced by Mercedes of Plymouth                 |              |                   |              |               |                  |                 |
| 34 Lights Bulb Replacement            | Replaced n/s headlight bulbs                                          |              |                   |              |               |                  |                 |
| Travel Time                           | Take vehicle to dealer                                                |              |                   |              |               |                  |                 |
| <b>Defect Repair</b>                  | <b>11/04/2016</b>                                                     | <b>08:00</b> | <b>19/04/2016</b> | <b>12:47</b> | <b>44,003</b> | <b>Derriford</b> | <b>DE019840</b> |
| 03 Instruments & Sensors 1            | Engine loss of power engine management on See notes                   |              |                   |              |               |                  |                 |
| Travel Time                           | Take vehicle to dealers                                               |              |                   |              |               |                  |                 |
| <b>Camera Installation</b>            | <b>12/04/2016</b>                                                     | <b>11:15</b> | <b>12/04/2016</b> | <b>13:42</b> | <b>44,003</b> | <b>Derriford</b> | <b>DE019851</b> |
| Camera Installation                   |                                                                       |              |                   |              |               |                  |                 |
| Install Saloon CCTV Camera            | Done By John Coles                                                    |              |                   |              |               |                  |                 |
| 85 Body Int Alcohol Gel Dispen Fitted |                                                                       |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>               | <b>26/04/2016</b>                                                     | <b>08:00</b> | <b>26/04/2016</b> | <b>09:09</b> | <b>44,700</b> | <b>Derriford</b> | <b>DE019926</b> |
| 02 Mirrors                            | Replaced n/s mirror glass top & bottom                                |              |                   |              |               |                  |                 |
| <b>SAFETY INSPECTION</b>              | <b>09/05/2016</b>                                                     | <b>07:09</b> | <b>10/05/2016</b> | <b>11:13</b> | <b>46,399</b> | <b>Derriford</b> | <b>DE019971</b> |
| 02 Mirrors                            | body exterior ns wing mirror glass broken                             |              |                   |              |               |                  |                 |
| 17 Tyres Replace                      | replaced front tyres                                                  |              |                   |              |               |                  |                 |
| 18 Wheels Check Torques               |                                                                       |              |                   |              |               |                  |                 |
| 56 Radio                              | body interior vehicle radio will not contact control                  |              |                   |              |               |                  |                 |
| 71 Body External Steps                | renewed decal                                                         |              |                   |              |               |                  |                 |
| 86 Doors                              | body exterior sliding/rear door interior handles not opening          |              |                   |              |               |                  |                 |
| 89 Seats                              | Adjust rear swivel seat lock pin Attendants seat adjuster bar Missing |              |                   |              |               |                  |                 |
| Safety Inspection                     |                                                                       |              |                   |              |               |                  |                 |
| UB Fire Suppression Discharge         | Under Bonnet Fire Suppression 5 Year Discharge Test                   |              |                   |              |               |                  |                 |



|                              |                                                                                  |              |                   |              |               |                  |                 |
|------------------------------|----------------------------------------------------------------------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| Annual Air Con Service       | Annual Air Condition Service                                                     |              |                   |              |               |                  |                 |
| Annual Heater Service        | Annual Heater Service                                                            |              |                   |              |               |                  |                 |
| Wheel Studs & Nuts Replaceme |                                                                                  |              |                   |              |               |                  |                 |
| Handbrake Cable Replacement  | Replace rear handbrake cables                                                    |              |                   |              |               |                  |                 |
| <b>Vehicle Deep Clean</b>    | <b>10/05/2016</b>                                                                | <b>10:49</b> | <b>11/05/2016</b> | <b>06:54</b> | <b>46,399</b> | <b>Derriford</b> | <b>DE019980</b> |
| Vehicle Deep Clean           | Vehicle Deep Clean                                                               |              |                   |              |               |                  |                 |
| <b>Breakdown</b>             | <b>31/05/2016</b>                                                                | <b>18:37</b> | <b>03/06/2016</b> | <b>14:30</b> | <b>48,887</b> | <b>Derriford</b> | <b>DE020061</b> |
| 02 Mirrors                   | Replaced n/s mirror assy                                                         |              |                   |              |               |                  |                 |
| 03 Instruments & Sensors 1   | EML light on checked with star found air flow sensor fault vehicle taken to merc |              |                   |              |               |                  |                 |
| 17 Tyres                     | wheel wobble at 70MPH                                                            |              |                   |              |               |                  |                 |
| 86 Doors                     | Side door will not open from out side Warranty form sent                         |              |                   |              |               |                  |                 |
| Breakdown                    | NS mirror loose                                                                  |              |                   |              |               |                  |                 |
| <b>SAFETY INSPECTION</b>     | <b>20/06/2016</b>                                                                | <b>07:20</b> | <b>20/06/2016</b> | <b>12:07</b> | <b>51,698</b> | <b>Derriford</b> | <b>DE020159</b> |
| 18 Wheels Check Torques      |                                                                                  |              |                   |              |               |                  |                 |
| 71 Body Exterior 1           | o/s body damaged                                                                 |              |                   |              |               |                  |                 |
| 87 Boards                    | Removed repaired and refitted scoop strap                                        |              |                   |              |               |                  |                 |
| Safety Inspection            |                                                                                  |              |                   |              |               |                  |                 |
| Reposition grab bag shelf    |                                                                                  |              |                   |              |               |                  |                 |
| Gearbox Oil & Filter Change  |                                                                                  |              |                   |              |               |                  |                 |
| <b>Vehicle Deep Clean</b>    | <b>20/06/2016</b>                                                                | <b>13:29</b> | <b>21/06/2016</b> | <b>11:05</b> | <b>51,700</b> | <b>Derriford</b> | <b>DE020164</b> |
| Vehicle Deep Clean           | Vehicle Deep Clean                                                               |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>      | <b>27/06/2016</b>                                                                | <b>10:36</b> | <b>29/06/2016</b> | <b>11:07</b> | <b>52,089</b> | <b>Derriford</b> | <b>DE020196</b> |
| 03 Instruments & Sensors 1   | Engine engine warning light LOP                                                  |              |                   |              |               |                  |                 |

|                                |                                                                       |       |            |       |        |           |                                    |
|--------------------------------|-----------------------------------------------------------------------|-------|------------|-------|--------|-----------|------------------------------------|
| SAFETY INSPECTION              | 29/07/2016                                                            | 07:07 | 29/07/2016 | 15:00 | 55,794 | Derriford | DE020334                           |
| 02 Cab Assembly 1              | Replace 1 x torch resecure wiring behind n/s door pillar trim         |       |            |       |        |           | Awaiting Body Repair<br>Monitoring |
| 03 Instruments & Sensors 1     | Check & cleared stored faults                                         |       |            |       |        |           |                                    |
| 13 Brakes 1                    | Replaced front discs & pads                                           |       |            |       |        |           |                                    |
| 18 Wheels Check Torques        |                                                                       |       |            |       |        |           |                                    |
| 71 Body Exterior 1             | Various body damaged                                                  |       |            |       |        |           |                                    |
| 89 Seats                       | Atendants seat adjuster missing                                       |       |            |       |        |           |                                    |
| Safety Inspection              |                                                                       |       |            |       |        |           |                                    |
| 92 - C Service                 |                                                                       |       |            |       |        |           |                                    |
| Service C                      |                                                                       |       |            |       |        |           |                                    |
| Tail Lift 6 Monthly Inspection | Statutory Inspection                                                  |       |            |       |        |           |                                    |
| Vehicle Deep Clean             | 08/08/2016                                                            | 07:07 | 08/08/2016 | 10:36 | 57,008 | Derriford | DE020379                           |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |        |           |                                    |
| Unplanned Repair               | 10/08/2016                                                            | 10:30 | 10/08/2016 | 11:57 | 57,275 | Derriford | DE020400                           |
| 03 Instruments & Sensors 1     | Reset sevice light indicator                                          |       |            |       |        |           |                                    |
| 86 Doors Rear                  | Replace o/s/r door swivel bolt                                        |       |            |       |        |           |                                    |
| Unplanned Repair               | 17/08/2016                                                            | 12:30 | 17/08/2016 | 13:14 | 58,510 | Derriford | DE020432                           |
| 34 Lights Bulb Replacement     | Replaced o/s headlight bulbs                                          |       |            |       |        |           |                                    |
| Unplanned Repair               | 30/08/2016                                                            | 07:18 | 31/08/2016 | 11:52 | 60,085 | Derriford | DE020500                           |
| 03 Instruments & Sensors 1     | Inlet pipe seal replaced by Mercedes of Plymouth P/O 151138060        |       |            |       |        |           |                                    |
| 71 Body Exterior Roof          | Body Exterior shattered skylight Replaced skylight Glass & blast film |       |            |       |        |           |                                    |
| Travel Time                    | Take vehicle to Dealer                                                |       |            |       |        |           |                                    |
| Defect Repair                  | 05/09/2016                                                            | 13:38 | 05/09/2016 | 13:40 | 60,773 | Derriford | DE020540                           |
| 34 Lighting System             | OSF day running bulb renewed                                          |       |            |       |        |           |                                    |

|                                                                                                                     |                                                                                                                                           |              |                   |              |               |                  |                 |
|---------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b>                                                                                            | <b>07/09/2016</b>                                                                                                                         | <b>07:07</b> | <b>07/09/2016</b> | <b>11:10</b> | <b>60,939</b> | <b>Derriford</b> | <b>DE020548</b> |
| 13 Brake Pads<br>17 Tyres Replace<br>18 Wheels Check Torques<br>71 Body Exterior 1<br>89 Seats<br>Safety Inspection | Renewed rear pads<br>renewed 4x rear tyres<br><br>Various body damaged<br>Atendants seat adjuster missing                                 |              |                   |              |               |                  |                 |
| <b>Breakdown</b>                                                                                                    | <b>09/09/2016</b>                                                                                                                         | <b>05:44</b> | <b>10/09/2016</b> | <b>14:10</b> | <b>61,138</b> | <b>Derriford</b> | <b>DE020565</b> |
| Breakdown                                                                                                           | VMT Not Transmitting                                                                                                                      |              |                   |              |               |                  |                 |
| <b>Defect Repair</b>                                                                                                | <b>09/09/2016</b>                                                                                                                         | <b>07:48</b> | <b>09/09/2016</b> | <b>07:50</b> | <b>61,138</b> | <b>Derriford</b> | <b>DE020567</b> |
| 87a - Medical Equipment RepairMangar charger renewed                                                                |                                                                                                                                           |              |                   |              |               |                  |                 |
| <b>Vehicle Deep Clean</b>                                                                                           | <b>15/09/2016</b>                                                                                                                         | <b>07:15</b> | <b>15/09/2016</b> | <b>12:17</b> | <b>61,879</b> | <b>Derriford</b> | <b>DE020612</b> |
| Vehicle Deep Clean                                                                                                  | Vehicle Deep Clean                                                                                                                        |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>                                                                                             | <b>20/09/2016</b>                                                                                                                         | <b>07:18</b> | <b>26/09/2016</b> | <b>07:13</b> | <b>62,390</b> | <b>Derriford</b> | <b>DE020636</b> |
| 03 Instruments & Sensors 1<br>03 Instruments & Sensors 2<br>Travel Time                                             | EML light on mass air flow sensor fault See notes<br>Engine losing power<br>Take vehicle to Dealers                                       |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>                                                                                             | <b>04/10/2016</b>                                                                                                                         | <b>13:45</b> | <b>04/10/2016</b> | <b>14:15</b> | <b>63,792</b> | <b>Derriford</b> | <b>DE020748</b> |
| 02 Cab Assembly 1<br>86 Sliding Door                                                                                | Cushon between cab & saloon window missing Part in store<br>Replaced side door roller bearings ( partailly siezed )<br><br>Awaiting Parts |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>                                                                                             | <b>12/10/2016</b>                                                                                                                         | <b>11:31</b> | <b>12/10/2016</b> | <b>11:33</b> | <b>65,096</b> | <b>Derriford</b> | <b>DE020805</b> |

34 Lights Bulb Replacement os side light bulb

|                         |                   |              |                   |              |               |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>20/10/2016</b> | <b>15:30</b> | <b>20/10/2016</b> | <b>16:07</b> | <b>66,483</b> | <b>Derriford</b> | <b>DE020869</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

17 Tyres Replace Replaced both front tyres

|                          |                   |              |                   |              |               |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>21/10/2016</b> | <b>07:11</b> | <b>21/10/2016</b> | <b>13:08</b> | <b>66,578</b> | <b>Derriford</b> | <b>DE020870</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

02 Cab Assembly 1 Cushon between cab & saloon window fitted, easy install.

17 Tyres Tracking Adjust tracking.

18 Wheels Check Torques

55 Tail Lift Guardrail upright secured

71 Body Exterior 1 Bridge plate guide secured

86 Doors Rear Internal mechanism adjusted

Safety Inspection

UB Fire Suppression Service Warning sounding

Remove Ventilator Brackets Remove Ventilator Brackets and Fill

MOT Pre Test

Awaiting Warranty

|                           |                   |              |                   |              |               |                  |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>31/10/2016</b> | <b>07:00</b> | <b>31/10/2016</b> | <b>12:03</b> | <b>67,098</b> | <b>Derriford</b> | <b>DE020912</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

Vehicle Deep Clean Vehicle Deep Clean

|                          |                   |              |                   |              |               |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>05/12/2016</b> | <b>06:57</b> | <b>08/12/2016</b> | <b>09:30</b> | <b>72,475</b> | <b>Derriford</b> | <b>DE021128</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

02 Windscreen Wipers renewed

15 Steering 1 N/s track rod end worn Replaced under warranty by Mercedes of Plymouth

16 Suspension 1 front struts worn Replaced under Warranty by Mercedes of plymouth

18 Wheels Check Torques

71 Body External Steps new trim fitted

87 - Stretchers/Chairs/Boards Body Interior stretcher release clip on floor will not release.lubed

Safety Inspection

UB Fire Suppression Service Warning sounding

Travel Time

MOT

Awaiting Parts

|                                                                                                                                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                          |              |                   |              |               |                  |                   |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|---------------|------------------|-------------------|
| <b>Vehicle Deep Clean</b>                                                                                                                                                                                                                                                                                         | <b>08/12/2016</b>                                                                                                                                                                                                                                                                        | <b>09:00</b> | <b>08/12/2016</b> | <b>16:00</b> | <b>72,564</b> | <b>Derriford</b> | <b>DE021155</b>   |
| Vehicle Deep Clean                                                                                                                                                                                                                                                                                                | Vehicle Deep Clean                                                                                                                                                                                                                                                                       |              |                   |              |               |                  |                   |
| <b>BREAKDOWN</b>                                                                                                                                                                                                                                                                                                  | <b>16/12/2016</b>                                                                                                                                                                                                                                                                        | <b>12:00</b> | <b>19/12/2016</b> | <b>12:24</b> | <b>73,623</b> | <b>Derriford</b> | <b>DE021216</b>   |
| 45 Engine 1<br>Travel Time                                                                                                                                                                                                                                                                                        | Auxiliary drive belt shredded Replaced by mercedes of plymouth<br>take vehicle to dealer                                                                                                                                                                                                 |              |                   |              |               |                  |                   |
| <b>SAFETY INSPECTION</b>                                                                                                                                                                                                                                                                                          | <b>16/01/2017</b>                                                                                                                                                                                                                                                                        | <b>07:13</b> | <b>17/01/2017</b> | <b>08:54</b> | <b>77,179</b> | <b>Derriford</b> | <b>DE021361</b>   |
| 02 Cab Assembly 1<br>02 Windscreen Wipers<br>18 Wheels Check Torques<br>34 Emergency Lights<br>42 Coolant System<br>Safety Inspection<br>Travel Time<br>UB Fire Suppression Service<br>93 - D Service<br>Service D<br>Medical Device and Equip Chec<br>Tail Lift 6 Monthly Inspection<br>Tail Lift Annual Service | repaired and rebuilt cab storage unit<br>renewed wipers<br><br>renewed both rear top corner lights<br>coolant leaking thermostat hsg warranty<br><br>Warning sounding<br><br><br><br>Statutory Inspection<br>Statutory Inspection and Weight Test Done by south west lifts P/O 151145540 |              |                   |              |               |                  | Awaiting Warranty |
| <b>Vehicle Deep Clean</b>                                                                                                                                                                                                                                                                                         | <b>17/01/2017</b>                                                                                                                                                                                                                                                                        | <b>06:27</b> | <b>17/01/2017</b> | <b>13:30</b> | <b>77,179</b> | <b>Derriford</b> | <b>DE021369</b>   |
| Vehicle Deep Clean                                                                                                                                                                                                                                                                                                | Vehicle Deep Clean                                                                                                                                                                                                                                                                       |              |                   |              |               |                  |                   |
| <b>Unplanned Repair</b>                                                                                                                                                                                                                                                                                           | <b>17/01/2017</b>                                                                                                                                                                                                                                                                        | <b>14:22</b> | <b>18/01/2017</b> | <b>12:14</b> | <b>77,179</b> | <b>Derriford</b> | <b>DE021372</b>   |
| 42 Coolant System<br>Travel Time                                                                                                                                                                                                                                                                                  | Thermostat housing replaced by mercedes of plymouth<br>Collect vehicle from Dealer                                                                                                                                                                                                       |              |                   |              |               |                  |                   |
| <b>Defect Repair</b>                                                                                                                                                                                                                                                                                              | <b>23/01/2017</b>                                                                                                                                                                                                                                                                        | <b>09:30</b> | <b>23/01/2017</b> | <b>10:32</b> | <b>77,702</b> | <b>Derriford</b> | <b>DE021400</b>   |
| 71 Body External Steps                                                                                                                                                                                                                                                                                            | Straighten step frame & adjust switthch pin                                                                                                                                                                                                                                              |              |                   |              |               |                  |                   |

|                             |                                                                                           |              |                   |              |               |                  |                 |
|-----------------------------|-------------------------------------------------------------------------------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Defect Repair</b>        | <b>30/01/2017</b>                                                                         | <b>07:24</b> | <b>30/01/2017</b> | <b>14:23</b> | <b>78,539</b> | <b>Derriford</b> | <b>DE021441</b> |
| 13 Brakes 1<br>Travel Time  | Brakes ESR warning light on dash. brakes unresponsive veh reqs warranty<br>Take to dealer |              |                   |              |               |                  |                 |
| <b>SAFETY INSPECTION</b>    | <b>02/03/2017</b>                                                                         | <b>09:38</b> | <b>02/03/2017</b> | <b>16:31</b> | <b>82,630</b> | <b>Derriford</b> | <b>DE021616</b> |
| 13 Brakes 1                 | Replaced rear discs & pads                                                                |              |                   |              |               |                  |                 |
| 17 Tyres Replace            | Replaced all rear tyres                                                                   |              |                   |              |               |                  |                 |
| 18 Wheels Check Torques     |                                                                                           |              |                   |              |               |                  |                 |
| 44 Add Ad Blue              | Topped up add blue                                                                        |              |                   |              |               |                  |                 |
| 71 Body Exterior 1          | Replaced o/s/r body corner & reflector                                                    |              |                   |              |               |                  |                 |
| 71 Body External Steps      | Straighten bent side step                                                                 |              |                   |              |               |                  |                 |
| 89 Seats                    | Refit & tighten swivel seat lock pins                                                     |              |                   |              |               |                  |                 |
| Safety Inspection           |                                                                                           |              |                   |              |               |                  |                 |
| Handbrake Cable Replacement | Replace rear handbrake cables Not required                                                |              |                   |              |               |                  |                 |
| <b>Vehicle Deep Clean</b>   | <b>03/03/2017</b>                                                                         | <b>06:33</b> | <b>03/03/2017</b> | <b>13:59</b> | <b>82,631</b> | <b>Derriford</b> | <b>DE021618</b> |
| Vehicle Deep Clean          | Vehicle Deep Clean                                                                        |              |                   |              |               |                  |                 |
| <b>Vehicle Deep Clean</b>   | <b>10/04/2017</b>                                                                         | <b>07:01</b> | <b>10/04/2017</b> | <b>10:31</b> | <b>87,037</b> | <b>Derriford</b> | <b>DE021806</b> |
| Vehicle Deep Clean          | Vehicle Deep Clean                                                                        |              |                   |              |               |                  |                 |
| <b>SAFETY INSPECTION</b>    | <b>10/04/2017</b>                                                                         | <b>11:10</b> | <b>12/04/2017</b> | <b>13:13</b> | <b>87,037</b> | <b>Derriford</b> | <b>DE021815</b> |
| 03 Instruments & Sensors 1  | Check & clear stored faults & reset service mileage indicator                             |              |                   |              |               |                  |                 |
| 13 Brake Pads               | Replaced front pads                                                                       |              |                   |              |               |                  |                 |
| 18 Wheels Check Torques     |                                                                                           |              |                   |              |               |                  |                 |
| 44 Add Ad Blue              |                                                                                           |              |                   |              |               |                  |                 |
| 71 Body Exterior 1          | Tail lift bridge plate sliders insecure drill out sheared bolts & resecure                |              |                   |              |               |                  |                 |
| 71 Body External Steps      | Side step bent Straighten step                                                            |              |                   |              |               |                  |                 |
| Safety Inspection           |                                                                                           |              |                   |              |               |                  |                 |
| Annual Air Con Service      | Annual Air Condition Service Done by Espar P/O 151151250                                  |              |                   |              |               |                  |                 |
| Annual Heater Service       | Annual Heater Service As above                                                            |              |                   |              |               |                  |                 |

|                                |                                                                |              |                   |              |               |                  |                 |
|--------------------------------|----------------------------------------------------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>COMMS.FAILURE CHECK</b>     | <b>13/04/2017</b>                                              | <b>14:30</b> | <b>13/04/2017</b> | <b>16:26</b> | <b>87,166</b> | <b>Derriford</b> | <b>DE021843</b> |
| MDT Failure/Issue              | Checked vehicle found Comms battery had failed Swapped battery |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>        | <b>08/05/2017</b>                                              | <b>07:30</b> | <b>08/05/2017</b> | <b>09:01</b> | <b>90,108</b> | <b>Derriford</b> | <b>DE021964</b> |
| 44 Add Ad Blue                 | Replaced missing adblue cap                                    |              |                   |              |               |                  |                 |
| <b>SAFETY INSPECTION</b>       | <b>22/05/2017</b>                                              | <b>07:13</b> | <b>22/05/2017</b> | <b>15:00</b> | <b>92,050</b> | <b>Derriford</b> | <b>DE022058</b> |
| 02 Cab Ass Fire Extinguisher   | changed fire exhtingushers                                     |              |                   |              |               |                  |                 |
| 18 Wheels Check Torques        |                                                                |              |                   |              |               |                  |                 |
| 85 Body Interior 1             | renewed broken biosafe strap                                   |              |                   |              |               |                  |                 |
| 86 Doors                       | Renewed osf door seal                                          |              |                   |              |               |                  |                 |
| 86 Doors Rear                  | fitted rear door plates                                        |              |                   |              |               |                  |                 |
| 87 Stretcher                   | Traced and retified charging fault                             |              |                   |              |               |                  |                 |
| Safety Inspection              |                                                                |              |                   |              |               |                  |                 |
| <b>Vehicle Deep Clean</b>      | <b>23/05/2017</b>                                              | <b>06:59</b> | <b>23/05/2017</b> | <b>11:11</b> | <b>92,051</b> | <b>Derriford</b> | <b>DE022065</b> |
| Vehicle Deep Clean             | Vehicle Deep Clean                                             |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>        | <b>14/06/2017</b>                                              | <b>16:00</b> | <b>14/06/2017</b> | <b>16:35</b> | <b>94,824</b> | <b>Derriford</b> | <b>DE022211</b> |
| 17 Tyres Replace               | Replace o/s/r outer tyre ( punctured )                         |              |                   |              |               |                  |                 |
| <b>Unplanned Repair</b>        | <b>21/06/2017</b>                                              | <b>10:30</b> | <b>21/06/2017</b> | <b>12:58</b> | <b>95,756</b> | <b>Derriford</b> | <b>DE022249</b> |
| WAS Firetrace rework & Service | Completed by John Coles                                        |              |                   |              |               |                  |                 |
| <b>SAFETY INSPECTION</b>       | <b>03/07/2017</b>                                              | <b>06:59</b> | <b>03/07/2017</b> | <b>14:32</b> | <b>97,486</b> | <b>Derriford</b> | <b>DE022312</b> |

|                                |                                                            |
|--------------------------------|------------------------------------------------------------|
| 02 Cab Assembly 1              | Lighting System Interior cab light not working ?bulb blown |
| 17 Tyres Replace               | renewed front tyres                                        |
| 18 Wheels Check Torques        |                                                            |
| 71 Body Exterior 1             | renewed 2x body corners                                    |
| 89 Seats                       | renewed swivel seat pin                                    |
| Safety Inspection              |                                                            |
| MGS Gas Storage Modifications  | MGS Gas Storage Modifications                              |
| 92 - C Service                 |                                                            |
| Service C                      |                                                            |
| Tail Lift 6 Monthly Inspection | Statutory Inspection                                       |

|                           |                   |              |                   |              |               |                  |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>04/07/2017</b> | <b>06:59</b> | <b>04/07/2017</b> | <b>10:39</b> | <b>97,486</b> | <b>Derriford</b> | <b>DE022326</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|---------------|------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                 |                   |              |                   |              |                |                  |                 |
|-----------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>ACCIDENT</b> | <b>27/07/2017</b> | <b>13:00</b> | <b>27/07/2017</b> | <b>14:46</b> | <b>100,171</b> | <b>Derriford</b> | <b>DE022472</b> |
|-----------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|            |                                                                       |
|------------|-----------------------------------------------------------------------|
| 02 Mirrors | Replace o/s mirror arm & ancillaries Smashed off by hit & run vehicle |
|------------|-----------------------------------------------------------------------|

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>31/07/2017</b> | <b>07:38</b> | <b>31/07/2017</b> | <b>09:12</b> | <b>100,549</b> | <b>Derriford</b> | <b>DE022476</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                           |                                 |
|---------------------------|---------------------------------|
| 17 Tyres Replace          | Replaced o/s/f tyre (punctured) |
| Replace Vehicle Fuel Card | Replace Vehicle Fuel Card       |

|                          |                   |              |                   |              |                |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>14/08/2017</b> | <b>07:28</b> | <b>17/08/2017</b> | <b>13:35</b> | <b>102,096</b> | <b>Derriford</b> | <b>DE022545</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                              |                                                                    |            |
|------------------------------|--------------------------------------------------------------------|------------|
| 02 Cab Ass Fire Extinguisher | Swapped cab & saloon fire extinguishers fo service                 |            |
| 02 Cab Assembly 1            | Replace centre consol catch button                                 |            |
| 02 Mirrors                   | Replaced n/s mirror glass                                          |            |
| 15 Steering 1                | Top up power steering oil level                                    |            |
| 16 Suspension 1              | Rear spring slipper pads split Replaced by Mercedes under warranty |            |
| 16 Suspension 2              | Slight play in front ball joints                                   | Monitoring |
| 17 Tyres Replace             | Replace both n/s & o/s/r inner tyres                               |            |
| 18 Wheels Check Torques      |                                                                    |            |
| 34 Lights Bulb Replacement   | Replaced n/s wing indicator light bulb                             |            |
| 71 Body Exterior 1           | Fit correct address decal                                          |            |
| 71 Body External Steps       | Motor keeps running Repaired under warranty                        |            |



|                                |                                                                                 |       |            |       |         |                   |          |
|--------------------------------|---------------------------------------------------------------------------------|-------|------------|-------|---------|-------------------|----------|
| 89 Seats                       | Tighten rear swivel seat lock pin                                               |       |            |       |         |                   |          |
| Safety Inspection              |                                                                                 |       |            |       |         |                   |          |
| Travel Time                    | Take vehicle to dealers                                                         |       |            |       |         |                   |          |
| Gearbox Oil & Filter Change    | Change oil & filter sump not sealed remove & refit                              |       |            |       |         |                   |          |
| Vehicle Deep Clean             | 16/08/2017                                                                      | 08:00 | 17/08/2017 | 07:10 | 102,096 | Derriford         | DE022561 |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                              |       |            |       |         |                   |          |
| Unplanned Repair               | 15/09/2017                                                                      | 07:00 | 15/09/2017 | 07:44 | 105,596 | Derriford         | DE022746 |
| 55 Ramp                        | Body Exterior Tail lift rail magnet too strong checked and renewed due to plate |       |            |       |         |                   |          |
| SAFETY INSPECTION              | 22/09/2017                                                                      | 06:30 | 22/09/2017 | 12:00 | 106,574 | Derriford         | DE022781 |
| 01 Air Conditioning 1          | condensor fan noisy                                                             |       |            |       |         | Awaiting Warranty |          |
| 13 Brake Pads                  | renewed rear pads                                                               |       |            |       |         |                   |          |
| 16 Suspension 2                | Slight play in front ball joints                                                |       |            |       |         |                   |          |
| 18 Wheels Check Torques        |                                                                                 |       |            |       |         |                   |          |
| 44 Add Ad Blue                 | topped up                                                                       |       |            |       |         |                   |          |
| 71 Body External Steps         | freed off and lubricated                                                        |       |            |       |         |                   |          |
| 87a - Medical Equipment Repair | Battery/Charging Sys EPCR cradle not charging all ok                            |       |            |       |         |                   |          |
| 89 Seats                       | refitted seat adjusting lever                                                   |       |            |       |         |                   |          |
| Safety Inspection              |                                                                                 |       |            |       |         |                   |          |
| Vehicle Deep Clean             | 26/09/2017                                                                      | 10:00 | 26/09/2017 | 14:25 | 106,986 | Derriford         | DE022811 |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                              |       |            |       |         |                   |          |
| Unplanned Repair               | 28/09/2017                                                                      | 09:47 | 03/10/2017 | 13:38 | 107,064 | Derriford         | DE022833 |
| 03 Instruments & Sensors 1     | Ad blue Tank & pump & sensor replaced by Mercedes of Plymouth                   |       |            |       |         |                   |          |
| Travel Time                    | Take vehicle to dealers                                                         |       |            |       |         |                   |          |

|                              |                                                                 |              |                   |              |                |                   |                 |
|------------------------------|-----------------------------------------------------------------|--------------|-------------------|--------------|----------------|-------------------|-----------------|
| <b>Breakdown</b>             | <b>03/10/2017</b>                                               | <b>20:35</b> | <b>04/10/2017</b> | <b>08:01</b> | <b>107,064</b> | <b>Derriford</b>  | <b>DE022863</b> |
| 56 Comms Equipment Breakdown | Loss of power to MDT & radio repaired by PCE<br>No Power to MDT |              |                   |              |                |                   |                 |
| <b>Defect Repair</b>         | <b>12/10/2017</b>                                               | <b>12:25</b> | <b>12/10/2017</b> | <b>13:00</b> | <b>108,064</b> | <b>Derriford</b>  | <b>DE022910</b> |
| 89 Seats                     | Refit rear swivel seat lock pin & tighten lock nut              |              |                   |              |                |                   |                 |
| <b>SAFETY INSPECTION</b>     | <b>02/11/2017</b>                                               | <b>06:58</b> | <b>02/11/2017</b> | <b>13:43</b> | <b>110,797</b> | <b>Derriford</b>  | <b>DE023035</b> |
| 01 Air Conditioning 1        | condenser fan noisy                                             |              |                   |              |                | Awaiting Warranty |                 |
| 11 Axle Rear                 | Rear anti roll bar bushes renewed                               |              |                   |              |                |                   |                 |
| 13 Brake Pads                | Front pads renewed                                              |              |                   |              |                |                   |                 |
| 18 Wheels Check Torques      |                                                                 |              |                   |              |                |                   |                 |
| 34 Emergency Lights          | OSF body blue not working, Warranty sent                        |              |                   |              |                | Awaiting Warranty |                 |
| 34 Lighting System           | 2x sidelight bulbs renewed                                      |              |                   |              |                |                   |                 |
| 34 Lights                    | NS cab door downlight not working Warranty sent                 |              |                   |              |                | Awaiting Warranty |                 |
| 71 Body Exterior 1           | Spray suppression secured                                       |              |                   |              |                |                   |                 |
| 71 Body External Steps       | Side step straightened                                          |              |                   |              |                |                   |                 |
| 85 Body Interior 1           | Saloon ar vent broken                                           |              |                   |              |                | Monitoring        |                 |
| 86 Doors Rear                | Catches/latches require adjustment                              |              |                   |              |                | Monitoring        |                 |
| 86 Sliding Door              | Centre rollers worn, Warranty sent                              |              |                   |              |                | Awaiting Warranty |                 |
| Check Winter Pack            |                                                                 |              |                   |              |                |                   |                 |
| Safety Inspection            |                                                                 |              |                   |              |                |                   |                 |
| MOT Pre Test                 |                                                                 |              |                   |              |                |                   |                 |
| UB Fire Suppression Service  |                                                                 |              |                   |              |                |                   |                 |
| <b>Vehicle Deep Clean</b>    | <b>07/11/2017</b>                                               | <b>07:00</b> | <b>07/11/2017</b> | <b>11:36</b> | <b>111,376</b> | <b>Derriford</b>  | <b>DE023056</b> |
| Vehicle Deep Clean           | Vehicle Deep Clean                                              |              |                   |              |                |                   |                 |
| <b>Unplanned Repair</b>      | <b>24/11/2017</b>                                               | <b>08:45</b> | <b>24/11/2017</b> | <b>13:19</b> | <b>113,633</b> | <b>Derriford</b>  | <b>DE023162</b> |
| 01 Air Conditioning 1        | condenser fan noisy Replaced by Espar under warranty            |              |                   |              |                |                   |                 |

|                     |                                                           |
|---------------------|-----------------------------------------------------------|
| 34 Emergency Lights | OSF body blue not working, Repalced under Warranty        |
| 34 Lights           | NS cab door downlight not working Replaced under Warranty |
| 86 Doors Rear       | Replace o/s/r rear door stay ( sheared off)               |
| 86 Sliding Door     | Centre rollers worn, replaced under Warranty              |

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>14/12/2017</b> | <b>07:45</b> | <b>14/12/2017</b> | <b>08:01</b> | <b>115,883</b> | <b>Derriford</b> | <b>DE023292</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|               |                                                                |                   |
|---------------|----------------------------------------------------------------|-------------------|
| 15 Steering 1 | Check for power steering fault found pump to be noisy level ok | Awaiting Warranty |
|---------------|----------------------------------------------------------------|-------------------|

|                          |                   |              |                   |              |                |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>18/12/2017</b> | <b>07:11</b> | <b>19/12/2017</b> | <b>08:28</b> | <b>116,526</b> | <b>Derriford</b> | <b>DE023310</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                      |                                                                         |                   |
|----------------------|-------------------------------------------------------------------------|-------------------|
| 02 Cab Assembly 1    | Bulkhead grommet renewed                                                |                   |
| 02 Windscreen Wipers | OS washer pipe split                                                    |                   |
| 15 Steering 1        | power steering fault found pump to be noisy level ok Heavy at low speed | Awaiting Warranty |

|                         |                                       |            |
|-------------------------|---------------------------------------|------------|
| 18 Wheels Check Torques |                                       |            |
| 71 Body External Steps  | Freed off, roller renewed             |            |
| 85 Body Interior 1      | Saloon ar vent broken                 | Monitoring |
| 86 Doors Rear           | Outer handle renewed, cables adjusted |            |

|                                |                                                                             |
|--------------------------------|-----------------------------------------------------------------------------|
| Safety Inspection              |                                                                             |
| 93 - D Service                 |                                                                             |
| Service D                      |                                                                             |
| Tail Lift 6 Monthly Inspection | Statutory Inspection                                                        |
| Tail Lift Annual Service       | Statutory Inspection and Weight Test Done by south west lifts P/O 151163980 |

|            |                   |              |                   |              |                |                  |                 |
|------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>MOT</b> | <b>19/12/2017</b> | <b>09:00</b> | <b>19/12/2017</b> | <b>13:38</b> | <b>115,883</b> | <b>Derriford</b> | <b>DE023328</b> |
|------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|             |                                  |
|-------------|----------------------------------|
| MOT         | Done by A J motors P/O 151162747 |
| Travel Time |                                  |

|                           |                   |              |                   |              |                |                  |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>19/12/2017</b> | <b>12:30</b> | <b>20/12/2017</b> | <b>08:30</b> | <b>116,526</b> | <b>Derriford</b> | <b>DE023329</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                      |                   |              |                   |              |                |                  |                 |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Defect Repair</b> | <b>11/01/2018</b> | <b>07:21</b> | <b>17/01/2018</b> | <b>16:17</b> | <b>118,381</b> | <b>Derriford</b> | <b>DE023449</b> |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|               |                                                                         |
|---------------|-------------------------------------------------------------------------|
| 15 Steering 1 | Power steering pump replaced by Mercedes of plymouth                    |
| 45 Engine 1   | Engine smell of burning and fuel fumes in cab Checked by Mercedes N.F.F |

|                             |                                                                                           |
|-----------------------------|-------------------------------------------------------------------------------------------|
| 89 Seatbelts<br>Travel Time | Emg Warning Devices 'Seatbelt System Checked by Mercedes N.F.F<br>Take vehicle to dealers |
|-----------------------------|-------------------------------------------------------------------------------------------|

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>23/01/2018</b> | <b>07:00</b> | <b>25/01/2018</b> | <b>08:50</b> | <b>118,998</b> | <b>Derriford</b> | <b>DE023526</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                                          |                                                                                                       |
|------------------------------------------|-------------------------------------------------------------------------------------------------------|
| 27 Transmission Automatic<br>45 Engine 1 | Engine 3rd gear auto gearbox issues.<br>LOP Merc 24 diagnosed EGR pipe, Renew EGR cooler P/O151167555 |
|------------------------------------------|-------------------------------------------------------------------------------------------------------|

|                          |                   |              |                   |              |                |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>24/01/2018</b> | <b>07:13</b> | <b>25/01/2018</b> | <b>08:51</b> | <b>118,998</b> | <b>Derriford</b> | <b>DE023533</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                                                                                                                         |                                                                                                             |
|-------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|
| 17 Tyres Replace<br>18 Wheels Check Torques<br>55 Tail Lift<br>85 Body Interior 1<br>86 Doors Rear<br>Safety Inspection | Renew OSR Outer tyre<br><br>Bridge plate guides secured<br>Saloon ar vent broken<br>Adjust & free mechanism |
|-------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>30/01/2018</b> | <b>07:15</b> | <b>30/01/2018</b> | <b>07:43</b> | <b>119,487</b> | <b>Derriford</b> | <b>DE023572</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                            |                                  |
|----------------------------|----------------------------------|
| 34 Lights Bulb Replacement | Replace n/s/f running light bulb |
|----------------------------|----------------------------------|

|                           |                   |              |                   |              |                |                  |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>02/02/2018</b> | <b>05:45</b> | <b>02/02/2018</b> | <b>13:15</b> | <b>119,675</b> | <b>Derriford</b> | <b>DE023600</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                      |                   |              |                   |              |                |                  |                 |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Defect Repair</b> | <b>09/02/2018</b> | <b>06:30</b> | <b>09/02/2018</b> | <b>08:14</b> | <b>120,335</b> | <b>Derriford</b> | <b>DE023651</b> |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                            |                                                           |
|----------------------------|-----------------------------------------------------------|
| 34 Lights Bulb Replacement | 2x DRL bulbs renewed. Non stock bulbs from 06/06/16 used. |
|----------------------------|-----------------------------------------------------------|

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>20/02/2018</b> | <b>12:05</b> | <b>21/02/2018</b> | <b>13:46</b> | <b>121,548</b> | <b>Derriford</b> | <b>DE023715</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                                 |                                                                      |
|---------------------------------|----------------------------------------------------------------------|
| 31 Charging System<br>Breakdown | Replaced alternator checked charging<br>alt warning on loss of power |
|---------------------------------|----------------------------------------------------------------------|

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>05/03/2018</b> | <b>08:04</b> | <b>05/03/2018</b> | <b>08:08</b> | <b>122,621</b> | <b>Derriford</b> | <b>DE023802</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                     |                                    |
|---------------------|------------------------------------|
| 34 Emergency Lights | Replaced n/s wing blue light mount |
|---------------------|------------------------------------|

|                          |                   |              |                   |              |                |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>12/03/2018</b> | <b>06:31</b> | <b>13/03/2018</b> | <b>12:04</b> | <b>123,344</b> | <b>Derriford</b> | <b>DE023855</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                                |                                                       |
|--------------------------------|-------------------------------------------------------|
| 01 Heating 1                   | Saloon heater exhaust replaced by Espar P/O 151162810 |
| 13 Discs                       | renewed front discs and pads                          |
| 15 Steering 1                  | renewed ns track rod end adjusted tracking            |
| 17 Tyres Replace               | renewed osf,nsf,nsr,osri tyres                        |
| 18 Wheels Check Torques        |                                                       |
| 43 Exhaust System 1            | Renewed exhaust tail pipe and brackets                |
| 71 Body External Steps         | straightened step and lubed                           |
| Safety Inspection              |                                                       |
| 85 Body Int Alcohol Gel Dispen |                                                       |
| Annual Heater Service          | Annual Heater Service                                 |
| Annual Air Con Service         | Annual Air Condition Service                          |
| Wheel Hub Flanges Replaceme    | Rears only Replaced no fronts                         |
| Handbrake Cable Replacement    | Replace rear handbrake cables                         |

Awaiting Parts

|                           |                   |              |                   |              |                |                  |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>14/03/2018</b> | <b>07:00</b> | <b>14/03/2018</b> | <b>10:59</b> | <b>123,403</b> | <b>Derriford</b> | <b>DE023875</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                          |                   |              |                   |              |                |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>20/04/2018</b> | <b>08:58</b> | <b>23/04/2018</b> | <b>11:54</b> | <b>127,753</b> | <b>Derriford</b> | <b>DE024085</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                             |                                         |
|-----------------------------|-----------------------------------------|
| 01 Heating 1                | Demist inlet insecure                   |
| 02 Cab Assembly 1           | 1x torch missing                        |
| 11 Axle Front               | Renew front wishbones                   |
| 13 Brake Pads               | Renew rear pads & discs                 |
| 17 Tyres Replace            | OSR outer tyre puncture                 |
| 18 Wheels Check Torques     |                                         |
| 34 Lighting System          | OSF white body marker partially working |
| 71 Body Exterior 1          | NSF bottom body corner to renew         |
| 71 Body Exterior 2          | Spray supression insecure               |
| Safety Inspection           |                                         |
| Wheel Hub Flanges Replaceme | Rears only Replaced no fronts           |
| Fit Poster Holder           | Fit Poster Holder                       |

|                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                                                 |              |                   |              |                |                  |                                                                                                          |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|----------------------------------------------------------------------------------------------------------|
| <b>Defect Repair</b>                                                                                                                                                                           | <b>30/04/2018</b>                                                                                                                                                                                                                                                                                               | <b>09:00</b> | <b>30/04/2018</b> | <b>10:24</b> | <b>128,298</b> | <b>Derriford</b> | <b>DE024133</b>                                                                                          |
| 03 Instruments & Sensors 1<br>31 Battery Chassis<br>Medical Devices Check                                                                                                                      | other driver seatbelt warning on Check connections & clear fault code<br>Replaced chassis battery<br>Supply pedi mate                                                                                                                                                                                           |              |                   |              |                |                  |                                                                                                          |
| <b>Vehicle Deep Clean</b>                                                                                                                                                                      | <b>01/05/2018</b>                                                                                                                                                                                                                                                                                               | <b>07:07</b> | <b>01/05/2018</b> | <b>14:01</b> | <b>128,453</b> | <b>Derriford</b> | <b>DE024139</b>                                                                                          |
| Vehicle Deep Clean                                                                                                                                                                             | Vehicle Deep Clean                                                                                                                                                                                                                                                                                              |              |                   |              |                |                  |                                                                                                          |
| <b>Defect Repair</b>                                                                                                                                                                           | <b>17/05/2018</b>                                                                                                                                                                                                                                                                                               | <b>13:36</b> | <b>17/05/2018</b> | <b>13:38</b> | <b>130,496</b> | <b>Derriford</b> | <b>DE024262</b>                                                                                          |
| 02 Mirrors                                                                                                                                                                                     | NS mirror back renewed                                                                                                                                                                                                                                                                                          |              |                   |              |                |                  |                                                                                                          |
| <b>Unplanned Repair</b>                                                                                                                                                                        | <b>29/05/2018</b>                                                                                                                                                                                                                                                                                               | <b>08:00</b> | <b>29/05/2018</b> | <b>08:23</b> | <b>131,536</b> | <b>Derriford</b> | <b>DE024323</b>                                                                                          |
| 02 Windscreen Wipers                                                                                                                                                                           | Repair split n/s washer pipe                                                                                                                                                                                                                                                                                    |              |                   |              |                |                  |                                                                                                          |
| <b>Vehicle Deep Clean</b>                                                                                                                                                                      | <b>04/06/2018</b>                                                                                                                                                                                                                                                                                               | <b>08:13</b> | <b>05/06/2018</b> | <b>07:00</b> | <b>132,944</b> | <b>Derriford</b> | <b>DE024361</b>                                                                                          |
| Vehicle Deep Clean                                                                                                                                                                             | Vehicle Deep Clean                                                                                                                                                                                                                                                                                              |              |                   |              |                |                  |                                                                                                          |
| <b>SAFETY INSPECTION</b>                                                                                                                                                                       | <b>05/06/2018</b>                                                                                                                                                                                                                                                                                               | <b>06:00</b> | <b>05/06/2018</b> | <b>14:00</b> | <b>132,922</b> | <b>Derriford</b> | <b>DE024369</b>                                                                                          |
| 02 Cab Assembly 1<br>02 Cab Assembly 2<br>02 Windscreen<br>13 Brakes 1<br>15 Steering 1<br>17 Tyres Tracking<br>18 Wheels Check Torques<br>55 Ramp<br>71 Body Exterior 1<br>71 Body Exterior 2 | Torch missing,Replaced<br>Tool box cover cracked,<br>windscreen seal adrift,Refitted<br>Brake pedal rubber worn,Renewed<br>NS track rod end worn,Renewed<br>checked tracking<br><br>Both tail lift leds smashed,Dave sourcing leds<br>Body Interior NSR corner damage Cornish wall,Repaired<br>OS of body holed |              |                   |              |                |                  | Awaiting Parts<br><br><br><br><br><br><br>Awaiting Parts<br>Awaiting Body Repair<br>Awaiting Body Repair |

|                                |                                    |
|--------------------------------|------------------------------------|
| 71 Body External Steps         | Side step not working,Repaired     |
| 85 Body Interior 1             | track cupboard shut adrit,Repaired |
| 85 Body Interior 2             | Forms holder broken,Repaired       |
| 86 Door Seals                  | NS door seal ripped,Renewed        |
| 86 Sliding Door                | Top latch insecure,Repaired        |
| Safety Inspection              | Carried out                        |
| Tail Lift 6 Monthly Inspection | Statutory Inspection               |

|                            |                   |              |                   |              |                |                  |                 |
|----------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>COMMS.FAILURE CHECK</b> | <b>22/06/2018</b> | <b>07:30</b> | <b>22/06/2018</b> | <b>08:46</b> | <b>134,722</b> | <b>Derriford</b> | <b>DE024497</b> |
|----------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                   |                                                        |
|-------------------|--------------------------------------------------------|
| 45 Engine 1       | Checked for smell of fuel Already been repaired        |
| MDT Failure/Issue | Checked comms battery found to be u/s Battery replaced |

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>24/06/2018</b> | <b>12:00</b> | <b>25/06/2018</b> | <b>12:30</b> | <b>134,750</b> | <b>Derriford</b> | <b>DE024499</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                              |                                                              |
|------------------------------|--------------------------------------------------------------|
| 56 Comms Equipment Breakdown | MDT screen n/w repaired by PCE<br>MDT frozen; cannot restart |
|------------------------------|--------------------------------------------------------------|

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>29/06/2018</b> | <b>06:07</b> | <b>29/06/2018</b> | <b>14:23</b> | <b>135,333</b> | <b>Derriford</b> | <b>DE024536</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                              |                                                         |
|------------------------------|---------------------------------------------------------|
| 56 Comms Equipment Breakdown | MDT screen n/w Repaired by PCE<br>MDT will not power up |
|------------------------------|---------------------------------------------------------|

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>29/06/2018</b> | <b>18:44</b> | <b>02/07/2018</b> | <b>08:09</b> | <b>135,333</b> | <b>Derriford</b> | <b>DE024542</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|           |                        |
|-----------|------------------------|
| Breakdown | side door not shutting |
|-----------|------------------------|

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>02/07/2018</b> | <b>06:00</b> | <b>02/07/2018</b> | <b>07:13</b> | <b>135,362</b> | <b>Derriford</b> | <b>DE024546</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|              |                                                 |
|--------------|-------------------------------------------------|
| 86 Door Lock | Strippedtop door lock on side door and repaired |
|--------------|-------------------------------------------------|

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>09/07/2018</b> | <b>09:34</b> | <b>11/07/2018</b> | <b>11:49</b> | <b>136,061</b> | <b>Derriford</b> | <b>DE024603</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                      |                                                    |
|----------------------|----------------------------------------------------|
| 02 Windscreen Wipers | Washer valve renewed                               |
| 41 Turbo             | Check for LOP found turbo had failed, Unit renewed |

|                              |                                                                   |              |                   |              |                |                  |                 |
|------------------------------|-------------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| Breakdown                    | LOP - EML on                                                      |              |                   |              |                |                  |                 |
| <b>Unplanned Repair</b>      | <b>13/07/2018</b>                                                 | <b>08:50</b> | <b>13/07/2018</b> | <b>11:43</b> | <b>136,176</b> | <b>Derriford</b> | <b>DE024633</b> |
| 03 Instruments & Sensors 1   | EML light on Check fault codes found air temp fault see notes     |              |                   |              |                |                  |                 |
| <b>SAFETY INSPECTION</b>     | <b>16/07/2018</b>                                                 | <b>08:51</b> | <b>17/07/2018</b> | <b>06:49</b> | <b>136,456</b> | <b>Derriford</b> | <b>DE024637</b> |
| 02 Cab Ass Fire Extinguisher | Swapped out of date                                               |              |                   |              |                |                  |                 |
| 02 Cab Assembly 2            | Tool box cover cracked,                                           |              |                   |              |                |                  |                 |
| 16 Suspension 1              | slight play osf strut                                             |              |                   |              |                |                  |                 |
| 18 Wheels Check Torques      |                                                                   |              |                   |              |                |                  |                 |
| 55 Ramp                      | Both tail lift leds smashed,Dave sourcing leds                    |              |                   |              |                |                  |                 |
| 71 Body Exterior 1           | Body Interior NSR corner damage Cornish wall,Repaired             |              |                   |              |                |                  |                 |
| 71 Body Exterior 2           | OS of body holed                                                  |              |                   |              |                |                  |                 |
| 85 Body Interior 1           | Renewed broken bio safe starp                                     |              |                   |              |                |                  |                 |
| 85 Body Interior 2           | Repaired cupboard shut on track cupboard                          |              |                   |              |                |                  |                 |
| Safety Inspection            |                                                                   |              |                   |              |                |                  |                 |
| 92 - C Service               |                                                                   |              |                   |              |                |                  |                 |
| Service C                    |                                                                   |              |                   |              |                |                  |                 |
| <b>Vehicle Deep Clean</b>    | <b>17/07/2018</b>                                                 | <b>08:00</b> | <b>17/07/2018</b> | <b>13:54</b> | <b>136,456</b> | <b>Derriford</b> | <b>DE024648</b> |
| Vehicle Deep Clean           | Vehicle Deep Clean                                                |              |                   |              |                |                  |                 |
| <b>Defect Repair</b>         | <b>01/08/2018</b>                                                 | <b>14:01</b> | <b>01/08/2018</b> | <b>14:36</b> | <b>137,811</b> | <b>Derriford</b> | <b>DE024762</b> |
| 15 Steering 1                | Investigate leak, secure pipe from tank, clean residue, road test |              |                   |              |                |                  |                 |
| <b>Unplanned Repair</b>      | <b>02/08/2018</b>                                                 | <b>08:00</b> | <b>07/08/2018</b> | <b>08:44</b> | <b>137,916</b> | <b>Derriford</b> | <b>DE024765</b> |
| 15 Steering 1                | Power steering pump noisy Replaced power steering pump            |              |                   |              |                |                  |                 |
| <b>BREAKDOWN</b>             | <b>07/08/2018</b>                                                 | <b>15:19</b> | <b>08/08/2018</b> | <b>08:46</b> | <b>137,984</b> | <b>Derriford</b> | <b>DE024800</b> |
| 15 Steering 1                | Power steering noise Rechecked level & topped up                  |              |                   |              |                |                  |                 |



|                                                                                                                                                                                                |                                                                                                                                                                                                                                                                              |              |                   |              |                |                  |                 |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b>                                                                                                                                                                               | <b>09/08/2018</b>                                                                                                                                                                                                                                                            | <b>20:12</b> | <b>10/08/2018</b> | <b>13:51</b> | <b>138,019</b> | <b>Derriford</b> | <b>DE024815</b> |
| 15 Steering 1<br>45 Engine 1<br>Breakdown                                                                                                                                                      | Replaced power steering pipe from pump to rack & top up oil level<br>Replaced auxillary drive belt tensioner<br>shuddering at low speeds on corners                                                                                                                          |              |                   |              |                |                  |                 |
| <b>breakdown</b>                                                                                                                                                                               | <b>13/08/2018</b>                                                                                                                                                                                                                                                            | <b>07:00</b> | <b>17/08/2018</b> | <b>17:06</b> | <b>138,085</b> | <b>Derriford</b> | <b>DE024834</b> |
| 15 Steering 1                                                                                                                                                                                  | power steering oil leak See notes                                                                                                                                                                                                                                            |              |                   |              |                |                  |                 |
| <b>ACCIDENT</b>                                                                                                                                                                                | <b>23/08/2018</b>                                                                                                                                                                                                                                                            | <b>08:00</b> | <b>24/08/2018</b> | <b>14:15</b> | <b>138,864</b> | <b>Derriford</b> | <b>DE024896</b> |
| 71 Body External Steps                                                                                                                                                                         | Side step has been smashed bent & buckled Seen notes                                                                                                                                                                                                                         |              |                   |              |                |                  |                 |
| <b>SAFETY INSPECTION</b>                                                                                                                                                                       | <b>28/08/2018</b>                                                                                                                                                                                                                                                            | <b>07:22</b> | <b>29/08/2018</b> | <b>11:51</b> | <b>139,341</b> | <b>Derriford</b> | <b>DE024907</b> |
| 02 Windscreen Wipers<br>17 Tyres Replace<br>18 Wheels Check Torques<br>34 Lights<br>43 Exhaust System 1<br>56 Comms Power Failure<br>86 Sliding Door<br>Check Winter Pack<br>Safety Inspection | N/s washer pipe connector broken Replaced connectors<br>Renew both front & o/s/r inner tyres<br><br>Replaced o/s/r lower fog light<br>Checked for reported exhaust fumes in cab N.F.F<br>MDT Failure/Issue MDT power failing Checked batteries all ok<br>Adjust door catches |              |                   |              |                |                  |                 |
| <b>Vehicle Deep Clean</b>                                                                                                                                                                      | <b>29/08/2018</b>                                                                                                                                                                                                                                                            | <b>07:05</b> | <b>29/08/2018</b> | <b>11:48</b> | <b>139,342</b> | <b>Derriford</b> | <b>DE024918</b> |
| Vehicle Deep Clean                                                                                                                                                                             | Vehicle Deep Clean                                                                                                                                                                                                                                                           |              |                   |              |                |                  |                 |
| <b>Breakdown</b>                                                                                                                                                                               | <b>13/09/2018</b>                                                                                                                                                                                                                                                            | <b>18:40</b> | <b>14/09/2018</b> | <b>11:22</b> | <b>140,000</b> | <b>Derriford</b> | <b>DE025015</b> |
| 34 Emergency Light System<br>43 Exhaust System 1<br>Breakdown                                                                                                                                  | Genysis unit secured check siren operation<br>Reseal downpie, manufactre bolt for clamp<br>fumes in cab&siren button on steering whel o/s                                                                                                                                    |              |                   |              |                |                  |                 |

|                                                                                                              |                                                               |              |                   |              |                |                  |                 |
|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Defect Repair</b>                                                                                         | <b>17/09/2018</b>                                             | <b>14:17</b> | <b>18/09/2018</b> | <b>10:56</b> | <b>141,244</b> | <b>Derriford</b> | <b>DE025036</b> |
| 43 Exhaust System 1                                                                                          | Fumes in cab, stripped reseated                               |              |                   |              |                |                  |                 |
| <b>Defect Repair</b>                                                                                         | <b>04/10/2018</b>                                             | <b>09:15</b> | <b>04/10/2018</b> | <b>09:31</b> | <b>143,230</b> | <b>Derriford</b> | <b>DE025159</b> |
| 02 Mirrors                                                                                                   | Mirrors Caught mirror on object, broken glass. Replaced glass |              |                   |              |                |                  |                 |
| <b>SAFETY INSPECTION</b>                                                                                     | <b>08/10/2018</b>                                             | <b>06:10</b> | <b>08/10/2018</b> | <b>10:59</b> | <b>143,975</b> | <b>Derriford</b> | <b>DE025175</b> |
| 18 Wheels Check Torques<br>71 Body External Steps<br>85 Body Interior 1<br>Safety Inspection<br>MOT Pre Test | straightened and repaired<br>repaired cupboard                |              |                   |              |                |                  |                 |
| <b>Vehicle Deep Clean</b>                                                                                    | <b>11/10/2018</b>                                             | <b>09:30</b> | <b>12/10/2018</b> | <b>10:56</b> | <b>144,212</b> | <b>Derriford</b> | <b>DE025213</b> |
| Vehicle Deep Clean                                                                                           | Vehicle Deep Clean                                            |              |                   |              |                |                  |                 |
| <b>Unplanned Repair</b>                                                                                      | <b>01/11/2018</b>                                             | <b>07:45</b> | <b>01/11/2018</b> | <b>08:15</b> | <b>146,367</b> | <b>Derriford</b> | <b>DE025362</b> |
| 34 Lights Bulb Replacement                                                                                   | replace n/s headlight bulb                                    |              |                   |              |                |                  |                 |
| <b>Unplanned Repair</b>                                                                                      | <b>13/11/2018</b>                                             | <b>07:00</b> | <b>13/11/2018</b> | <b>07:31</b> | <b>147,904</b> | <b>Derriford</b> | <b>DE025434</b> |
| 89 Seats                                                                                                     | removed and renewed broken seat pin on saloon seat            |              |                   |              |                |                  |                 |
| <b>Vehicle Deep Clean</b>                                                                                    | <b>19/11/2018</b>                                             | <b>05:45</b> | <b>19/11/2018</b> | <b>09:56</b> | <b>148,587</b> | <b>Derriford</b> | <b>DE025469</b> |

|                                |                                                                             |              |                   |              |                |                  |                 |
|--------------------------------|-----------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| Vehicle Deep Clean             | Vehicle Deep Clean                                                          |              |                   |              |                |                  |                 |
| Sealing of stretcher clamp     | Sealing of stretcher clamp                                                  |              |                   |              |                |                  |                 |
| <b>SAFETY INSPECTION</b>       | <b>19/11/2018</b>                                                           | <b>12:38</b> | <b>20/11/2018</b> | <b>12:45</b> | <b>148,587</b> | <b>Derriford</b> | <b>DE025479</b> |
| 02 Windscreen Wipers           | Washer bottle cap not fitting                                               |              |                   |              |                |                  |                 |
| 13 Brake Pads                  | Removed and renewed rear pads freed off sliders                             |              |                   |              |                |                  |                 |
| 17 Tyres Replace               | Removed and renewed nsr tyres                                               |              |                   |              |                |                  |                 |
| 18 Wheels Check Torques        |                                                                             |              |                   |              |                |                  |                 |
| 56 Comms Equipment             | Electrical Auxs Microphone in saloon yanked from its housing, Renewed       |              |                   |              |                |                  |                 |
| 71 Body Exterior 1             | various body damage and rear valance damaged                                |              |                   |              |                |                  |                 |
| 86 Door Seals                  | O/S cab door seal ripped, Renewed                                           |              |                   |              |                |                  |                 |
| Safety Inspection              |                                                                             |              |                   |              |                |                  |                 |
| Tail Lift 6 Monthly Inspection | Statutory Inspection                                                        |              |                   |              |                |                  |                 |
| UB Fire Suppression Service    |                                                                             |              |                   |              |                |                  |                 |
| Tail Lift Annual Service       | Statutory Inspection and Weight Test Done by South west lifts P/O 151179706 |              |                   |              |                |                  |                 |
| <b>Unplanned Repair</b>        | <b>12/12/2018</b>                                                           | <b>12:00</b> | <b>12/12/2018</b> | <b>13:34</b> | <b>150,960</b> | <b>Derriford</b> | <b>DE025656</b> |
| 03 Instruments & Sensors 1     | Reset service mileage & update satnav                                       |              |                   |              |                |                  |                 |
| 71 Body External Steps         | Carry out step wiring mod                                                   |              |                   |              |                |                  |                 |
| <b>SAFETY INSPECTION</b>       | <b>27/12/2018</b>                                                           | <b>06:41</b> | <b>28/12/2018</b> | <b>11:02</b> | <b>152,913</b> | <b>Derriford</b> | <b>DE025729</b> |
| 13 Brake Pads                  | Removed and renewed front pads free off sliders                             |              |                   |              |                |                  |                 |
| 16 Suspension 1                | 4x rear spring slipper pads split/adrift                                    |              |                   |              |                |                  |                 |
| 17 Tyres Replace               | OSRO tyre replaced                                                          |              |                   |              |                |                  |                 |
| 18 Wheels Check Torques        |                                                                             |              |                   |              |                |                  |                 |
| 34 Lights                      | nsf fog lamp damaged and insecure                                           |              |                   |              |                |                  |                 |
| 55 Ramp                        | Tail lift bridge plate sliders adrift                                       |              |                   |              |                |                  |                 |
| 71 Body Exterior 2             | Various body damage o/s punctured,renewed ns top body corner                |              |                   |              |                |                  |                 |
| Safety Inspection              |                                                                             |              |                   |              |                |                  |                 |
| Travel Time                    |                                                                             |              |                   |              |                |                  |                 |
| MOT                            | Done by Mercedes of Plymouth P/O 151179880                                  |              |                   |              |                |                  |                 |
| Gearbox Oil & Filter Change    |                                                                             |              |                   |              |                |                  |                 |

|                           |                   |              |                   |              |                |                  |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>08/01/2019</b> | <b>09:29</b> | <b>08/01/2019</b> | <b>14:28</b> | <b>154,386</b> | <b>Derriford</b> | <b>DE025806</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>21/01/2019</b> | <b>07:23</b> | <b>25/01/2019</b> | <b>12:55</b> | <b>155,902</b> | <b>Derriford</b> | <b>DE025897</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                            |                                                 |
|----------------------------|-------------------------------------------------|
| 01 Heating 1               | Found pollen filter contaminated replace filter |
| 02 Mirrors                 | n/s mirror glass cracked Replaced Glass         |
| 03 Instruments & Sensors 1 | Check & clear stored faults                     |
| 44 Fuel System 1           | Investigate reported fumes in cab See Notes     |
| Breakdown                  | fumes in cab                                    |
| Camera Installation        | N/s/f body camera smashed John Coles aware      |
|                            | Awaiting Parts                                  |

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>26/01/2019</b> | <b>18:22</b> | <b>28/01/2019</b> | <b>12:13</b> | <b>156,064</b> | <b>Derriford</b> | <b>DE025941</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                            |                           |
|----------------------------|---------------------------|
| 03 Instruments & Sensors 1 | Check for fault See notes |
| Breakdown                  | limp mode loss of power   |

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>30/01/2019</b> | <b>10:00</b> | <b>06/02/2019</b> | <b>14:02</b> | <b>156,219</b> | <b>Derriford</b> | <b>DE025972</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                   |                                                           |
|-------------------|-----------------------------------------------------------|
| 02 Cab Assembly 1 | Replaced interior light bulb & center consol latch button |
| 45 Engine 1       | Engine Gone into limp mode See notes P/O 151183316        |
| Travel Time       | Take vehicle to dealers                                   |

|                          |                   |              |                   |              |                |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>11/02/2019</b> | <b>09:47</b> | <b>13/02/2019</b> | <b>08:05</b> | <b>156,744</b> | <b>Derriford</b> | <b>DE026045</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                         |                                            |
|-------------------------|--------------------------------------------|
| 17 Tyres Replace        | osf renewed                                |
| 18 Wheels Check Torques |                                            |
| 34 Lighting System      | repaired marker wiring                     |
| 55 Ramp                 | Refitted guides                            |
| 85 Body Interior 1      | repaired track shut                        |
| Camera Installation     | N/s/f body camera smashed John Coles aware |
| Safety Inspection       |                                            |
| 93 - D Service          |                                            |
| Service D               |                                            |

|                            |                                                   |              |                   |              |                |                  |                 |
|----------------------------|---------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b>  | <b>14/02/2019</b>                                 | <b>07:39</b> | <b>15/02/2019</b> | <b>08:14</b> | <b>156,799</b> | <b>Derriford</b> | <b>DE026073</b> |
| Vehicle Deep Clean         | Vehicle Deep Clean                                |              |                   |              |                |                  |                 |
| <b>Defect Repair</b>       | <b>04/03/2019</b>                                 | <b>10:33</b> | <b>04/03/2019</b> | <b>10:34</b> | <b>158,715</b> | <b>Derriford</b> | <b>DE026178</b> |
| 34 Lights Bulb Replacement | OS repeater bulb renewed                          |              |                   |              |                |                  |                 |
| <b>Unplanned Repair</b>    | <b>08/03/2019</b>                                 | <b>07:20</b> | <b>08/03/2019</b> | <b>09:52</b> | <b>159,074</b> | <b>Derriford</b> | <b>DE026216</b> |
| 01 Heating 1               | Saloon heater n/w Overhaul saloon heater          |              |                   |              |                |                  |                 |
| <b>Unplanned Repair</b>    | <b>11/03/2019</b>                                 | <b>08:45</b> | <b>11/03/2019</b> | <b>08:50</b> | <b>159,415</b> | <b>Derriford</b> | <b>DE026226</b> |
| 87 Stretcher               | Replaced spare stryker battery                    |              |                   |              |                |                  |                 |
| <b>Defect Repair</b>       | <b>21/03/2019</b>                                 | <b>10:32</b> | <b>21/03/2019</b> | <b>10:34</b> | <b>160,299</b> | <b>Derriford</b> | <b>DE026299</b> |
| 34 Lights Bulb Replacement | OS repeater bulb renewed                          |              |                   |              |                |                  |                 |
| <b>SAFETY INSPECTION</b>   | <b>25/03/2019</b>                                 | <b>07:16</b> | <b>26/03/2019</b> | <b>10:59</b> | <b>160,870</b> | <b>Derriford</b> | <b>DE026315</b> |
| 02 Cab Assembly 1          | O/S electric window switch broken                 |              |                   |              |                |                  |                 |
| 02 Cab Assembly 2          | N/S electric window switch broken                 |              |                   |              |                |                  |                 |
| 16 Suspension 1            | Slight play in both front struts                  |              |                   |              |                |                  |                 |
| 16 Suspension 2            | Slight play in both front lower ball joints       |              |                   |              |                |                  |                 |
| 18 Wheels Check Torques    |                                                   |              |                   |              |                |                  |                 |
| 34 Lighting System         | renewed scene light                               |              |                   |              |                |                  |                 |
| 34 Lights                  | N/S side light n/w                                |              |                   |              |                |                  |                 |
| 34 Lights Bulb Replacement | N/S mainbeam n/w                                  |              |                   |              |                |                  |                 |
| 55 Tail Lift               | Renewed broken platform led                       |              |                   |              |                |                  |                 |
| 71 Body Exterior 1         | N/S/F body camera smashed off,John coles repaired |              |                   |              |                |                  |                 |
| 71 Body Exterior 2         | Various body damage                               |              |                   |              |                |                  |                 |
| 85 Body Interior 1         | Track cupboard shut insecure                      |              |                   |              |                |                  |                 |
| Safety Inspection          |                                                   |              |                   |              |                |                  |                 |

Monitoring  
Monitoring

Awaiting Body Repair

|                              |                                                                        |              |                   |              |                |                  |                      |
|------------------------------|------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|----------------------|
| Fit 3rd Helmet Restraint     | Fit 3rd Helmet Restraint in Cab                                        |              |                   |              |                |                  |                      |
| Annual Heater Service        | Annual Heater Service                                                  |              |                   |              |                |                  |                      |
| Annual Air Con Service       | Annual Air Condition Service                                           |              |                   |              |                |                  |                      |
| Handbrake Cable Replacement  | Replace rear handbrake cables                                          |              |                   |              |                |                  |                      |
| <b>Vehicle Deep Clean</b>    | <b>27/03/2019</b>                                                      | <b>07:02</b> | <b>27/03/2019</b> | <b>14:52</b> | <b>160,929</b> | <b>Derriford</b> | <b>DE026333</b>      |
| Vehicle Deep Clean           | Vehicle Deep Clean                                                     |              |                   |              |                |                  |                      |
| <b>Breakdown</b>             | <b>30/03/2019</b>                                                      | <b>02:05</b> | <b>01/04/2019</b> | <b>15:19</b> | <b>161,153</b> | <b>Derriford</b> | <b>DE026354</b>      |
| 02 Windows/Glass             | National windscreens fitted temporary window                           |              |                   |              |                |                  |                      |
| 71 Body Exterior Acc Repair  | Strapes & scratches down o/s of body                                   |              |                   |              |                |                  | Awaiting Body Repair |
| Breakdown                    | Shattered offside window and scratches                                 |              |                   |              |                |                  |                      |
| <b>SAFETY INSPECTION</b>     | <b>07/05/2019</b>                                                      | <b>07:01</b> | <b>08/05/2019</b> | <b>09:24</b> | <b>165,345</b> | <b>Derriford</b> | <b>DE026609</b>      |
| 02 Cab Ass Fire Extinguisher | Swapped saloon fire ex.                                                |              |                   |              |                |                  |                      |
| 02 Cab Assembly 1            | Centre console lid secured                                             |              |                   |              |                |                  |                      |
| 13 Brake Pads                | Rear pads renewed                                                      |              |                   |              |                |                  |                      |
| 16 Suspension 1              | Slight play in both front struts                                       |              |                   |              |                |                  | Monitoring           |
| 16 Suspension 2              | Slight play in both front lower ball joints                            |              |                   |              |                |                  | Monitoring           |
| 17 Tyres Replace             | Renew NSF & OSR Inner tyre                                             |              |                   |              |                |                  |                      |
| 18 Wheels Check Torques      |                                                                        |              |                   |              |                |                  |                      |
| 44 Fuel System 1             | Fuel leak top of tank. no obvious leak, cleaned, check next inspection |              |                   |              |                |                  | Monitoring           |
| 71 Body Exterior 1           | NSR light cluster damage                                               |              |                   |              |                |                  | Awaiting Parts       |
| 71 Body Exterior 2           | Various body damage                                                    |              |                   |              |                |                  | Monitoring           |
| 71 Body Exterior 3           | Bridge plate guides insecure                                           |              |                   |              |                |                  |                      |
| 71 Body Exterior Acc Repair  | Strapes & scratches down o/s of body                                   |              |                   |              |                |                  |                      |
| 86 Doors Rear                | Door stay sheared bolt renewed                                         |              |                   |              |                |                  |                      |
| 86 Sliding Door              | Centre bearings renewed                                                |              |                   |              |                |                  |                      |
| Safety Inspection            |                                                                        |              |                   |              |                |                  |                      |
| Tail Lift Inspection         |                                                                        |              |                   |              |                |                  |                      |
| UB Fire Supp 6mts Service    | UB Fire Supp 6mts Service                                              |              |                   |              |                |                  |                      |
| <b>Vehicle Deep Clean</b>    | <b>08/05/2019</b>                                                      | <b>08:00</b> | <b>09/05/2019</b> | <b>07:01</b> | <b>165,345</b> | <b>Derriford</b> | <b>DE026621</b>      |
| Vehicle Deep Clean           | Vehicle Deep Clean                                                     |              |                   |              |                |                  |                      |
| <b>Breakdown</b>             | <b>10/05/2019</b>                                                      | <b>18:39</b> | <b>13/05/2019</b> | <b>06:31</b> | <b>165,432</b> | <b>Derriford</b> | <b>DE026641</b>      |

|            |                                         |
|------------|-----------------------------------------|
| 02 Mirrors | Rebuild o/s                             |
| Breakdown  | O/S mirror glass and casing smashed VOR |

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>28/05/2019</b> | <b>22:36</b> | <b>30/05/2019</b> | <b>06:57</b> | <b>167,697</b> | <b>Derriford</b> | <b>DE026775</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                           |                                               |                |
|---------------------------|-----------------------------------------------|----------------|
| 02 Windows/Glass          | replaced temp side glass                      |                |
| 34 Emergency Light System | Checked bull horn all ok at time of test      |                |
| 89 Seats                  | Stripped seat lumbar adj broken merc sourcing | Awaiting Parts |
| Breakdown                 | seat lumbar support & horn not working        |                |

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>14/06/2019</b> | <b>07:00</b> | <b>14/06/2019</b> | <b>07:13</b> | <b>169,216</b> | <b>Derriford</b> | <b>DE026873</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                 |                          |
|-----------------|--------------------------|
| 86 Sliding Door | Resecured top door catch |
|-----------------|--------------------------|

|                          |                   |              |                   |              |                |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>17/06/2019</b> | <b>07:15</b> | <b>19/06/2019</b> | <b>14:52</b> | <b>169,453</b> | <b>Derriford</b> | <b>DE026883</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                              |                                                                    |                      |
|------------------------------|--------------------------------------------------------------------|----------------------|
| 02 Cab Ass Fire Extinguisher | Replaced for service                                               |                      |
| 02 Mirrors                   | replace n/s mirror glass                                           |                      |
| 16 Suspension 1              | Slight play in both front struts                                   | Monitoring           |
| 16 Suspension 2              | Slight play in both front lower ball joints Within merc wear limit |                      |
| 17 Tyres Replace             | Replaced o/s/r outer & both n/s/r & o/s/f tyres                    |                      |
| 18 Wheels Check Torques      |                                                                    |                      |
| 34 Lights Bulb Replacement   | Replaced n/s headlight bulb                                        |                      |
| 44 Fuel System 1             | Fuel leak top of tank. no obvious leak, cleaned See notes          |                      |
| 71 Body Exterior 1           | Replace n/s/r light cluster mount & brake/tail & fog lamps         |                      |
| 71 Body Exterior 2           | Various body damage                                                | Awaiting Body Repair |
| 71 Body Exterior 3           | Resecure ramp slider plates                                        |                      |
| 89 Seats                     | Stripped seat lumbar adj broken Unavailable have to buy whole seat |                      |
| Safety Inspection            |                                                                    |                      |

|                           |                   |              |                   |              |                |                  |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>21/06/2019</b> | <b>07:00</b> | <b>21/06/2019</b> | <b>14:00</b> | <b>169,593</b> | <b>Derriford</b> | <b>DE026916</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                                                                                                                                                                                                                                                                    |                                                                                                                                                                                                                                                                                           |              |                   |              |                |                  |                                                                          |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|--------------------------------------------------------------------------|
| <b>Breakdown</b>                                                                                                                                                                                                                                                   | <b>27/06/2019</b>                                                                                                                                                                                                                                                                         | <b>19:42</b> | <b>28/06/2019</b> | <b>09:32</b> | <b>170,338</b> | <b>Derriford</b> | <b>DE026952</b>                                                          |
| 03 Instruments & Sensors 1<br>45 Engine 1<br>Breakdown                                                                                                                                                                                                             | Checked veh no EML on plugged in no dtc's stored<br>Rd tested vehicle driving all ok no noise unable to fault vehicle at present<br>limp mode, turbo gone?; loud noise                                                                                                                    |              |                   |              |                |                  |                                                                          |
| <b>Defect Repair</b>                                                                                                                                                                                                                                               | <b>12/07/2019</b>                                                                                                                                                                                                                                                                         | <b>10:44</b> | <b>12/07/2019</b> | <b>13:32</b> | <b>170,756</b> | <b>Derriford</b> | <b>DE027080</b>                                                          |
| 55 Tail Lift<br>86 Sliding Door                                                                                                                                                                                                                                    | Free off handrail, secure bridge plate guides<br>Difficult to open, adjust catches & reset door                                                                                                                                                                                           |              |                   |              |                |                  |                                                                          |
| <b>Defect Repair</b>                                                                                                                                                                                                                                               | <b>22/07/2019</b>                                                                                                                                                                                                                                                                         | <b>08:24</b> | <b>22/07/2019</b> | <b>09:41</b> | <b>172,786</b> | <b>Derriford</b> | <b>DE027121</b>                                                          |
| 86 Sliding Door                                                                                                                                                                                                                                                    | Side door outside handle broken,Renewed and set cables                                                                                                                                                                                                                                    |              |                   |              |                |                  |                                                                          |
| <b>SAFETY INSPECTION</b>                                                                                                                                                                                                                                           | <b>29/07/2019</b>                                                                                                                                                                                                                                                                         | <b>09:27</b> | <b>30/07/2019</b> | <b>15:32</b> | <b>173,573</b> | <b>Derriford</b> | <b>DE027177</b>                                                          |
| 15 Steering 1<br>16 Suspension 1<br>16 Suspension 2<br>18 Wheels Check Torques<br>34 Lights Bulb Replacement<br>71 Body Exterior 1<br>85 Body Interior 1<br>86 Doors<br>86 Sliding Door<br>Safety Inspection<br>Engine Change Oil & Filter<br>Tail Lift Inspection | Tighten loose resevoir return pipe clamp<br>Slight play in both front struts<br>Replaced rear spring rear eye bushes<br><br>Replaced n/s driving light bulb<br>Replaced front no plate<br>Replace 1 x bio strap<br>Drivers door stay mount split<br>Top door catch cover missing No parts |              |                   |              |                |                  | Monitoring<br><br><br><br><br><br>Awaiting Body Repair<br>Awaiting Parts |
| <b>Vehicle Deep Clean</b>                                                                                                                                                                                                                                          | <b>31/07/2019</b>                                                                                                                                                                                                                                                                         | <b>09:43</b> | <b>01/08/2019</b> | <b>09:59</b> | <b>173,574</b> | <b>Derriford</b> | <b>DE027191</b>                                                          |
| Vehicle Deep Clean                                                                                                                                                                                                                                                 | Vehicle Deep Clean                                                                                                                                                                                                                                                                        |              |                   |              |                |                  |                                                                          |



|                           |                                                             |              |                   |              |                |                  |                 |
|---------------------------|-------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b>   | <b>07/08/2019</b>                                           | <b>08:00</b> | <b>07/08/2019</b> | <b>08:30</b> | <b>174,247</b> | <b>Derriford</b> | <b>DE027226</b> |
| 31 Battery Comms          | Replace comms battery                                       |              |                   |              |                |                  |                 |
| <b>Unplanned Repair</b>   | <b>16/08/2019</b>                                           | <b>08:31</b> | <b>19/08/2019</b> | <b>09:51</b> | <b>175,258</b> | <b>Derriford</b> | <b>DE027284</b> |
| 31 Battery Aux            | Replace auxiliary battery                                   |              |                   |              |                |                  |                 |
| 31 Battery Chassis        | Replace chassis battery                                     |              |                   |              |                |                  |                 |
| 31 Charging System        | Check charging systems all ok                               |              |                   |              |                |                  |                 |
| 56 Comms Power Failure    | Checked by PCE                                              |              |                   |              |                |                  |                 |
| <b>Unplanned Repair</b>   | <b>19/08/2019</b>                                           | <b>07:14</b> | <b>19/08/2019</b> | <b>09:52</b> | <b>175,512</b> | <b>Derriford</b> | <b>DE027297</b> |
| MDT Failure/Issue         | powering down Checked by PCE                                |              |                   |              |                |                  |                 |
| <b>SAFETY INSPECTION</b>  | <b>09/09/2019</b>                                           | <b>09:47</b> | <b>13/09/2019</b> | <b>05:53</b> | <b>177,959</b> | <b>Derriford</b> | <b>DE027423</b> |
| 13 Brake Pads             | Renew front pads, rear pads & discs                         |              |                   |              |                |                  |                 |
| 16 Suspension 1           | Slight play in both front struts                            |              |                   |              |                |                  |                 |
| 18 Wheels Check Torques   |                                                             |              |                   |              |                |                  | Monitoring      |
| 34 Lighting System        | NSF sidelight repaired OSR top red renewed                  |              |                   |              |                |                  |                 |
| 71 Body Exterior 1        | NSF bottom body corner renewed, bridge plate guides secured |              |                   |              |                |                  |                 |
| 71 Body Exterior 2        | Various body damage                                         |              |                   |              |                |                  | Monitoring      |
| 86 Doors                  | Drivers door stay mount split                               |              |                   |              |                |                  |                 |
| 86 Sliding Door           | Top door catch cover renewed                                |              |                   |              |                |                  | Monitoring      |
| Safety Inspection         |                                                             |              |                   |              |                |                  |                 |
| <b>Vehicle Deep Clean</b> | <b>10/09/2019</b>                                           | <b>12:05</b> | <b>11/09/2019</b> | <b>11:01</b> | <b>177,959</b> | <b>Derriford</b> | <b>DE027432</b> |
| Vehicle Deep Clean        | Vehicle Deep Clean                                          |              |                   |              |                |                  |                 |
| <b>SAFETY INSPECTION</b>  | <b>21/10/2019</b>                                           | <b>06:48</b> | <b>21/10/2019</b> | <b>14:37</b> | <b>183,356</b> | <b>Derriford</b> | <b>DE027740</b> |
| 02 Cab Assembly 1         | Torch repaired                                              |              |                   |              |                |                  |                 |
| 02 Cab Assembly 2         | Centre console ram repaired                                 |              |                   |              |                |                  |                 |

|                                |                                                                       |       |            |       |         |           |            |          |
|--------------------------------|-----------------------------------------------------------------------|-------|------------|-------|---------|-----------|------------|----------|
| 02 Windscreen Wipers           | Blades renewed                                                        |       |            |       |         |           |            |          |
| 03 Instruments & Sensors 1     | Service mileage reset                                                 |       |            |       |         |           |            |          |
| 16 Suspension 1                | Slight play in both front struts                                      |       |            |       |         |           | Monitoring |          |
| 18 Wheels Check Torques        |                                                                       |       |            |       |         |           |            |          |
| 34 Emergency Lights            | NS Scene light renewed                                                |       |            |       |         |           |            |          |
| 71 Body Exterior 1             | Bridge plate guides repaired                                          |       |            |       |         |           |            |          |
| 71 Body Exterior 2             | Various body damage                                                   |       |            |       |         |           | Monitoring |          |
| 86 Doors                       | Drivers door stay mount split                                         |       |            |       |         |           | Monitoring |          |
| Safety Inspection              |                                                                       |       |            |       |         |           |            |          |
| Tail Lift Inspection           |                                                                       |       |            |       |         |           |            |          |
| UB Fire Supp 6mts Service      | UB Fire Supp 6mts Service                                             |       |            |       |         |           |            |          |
| Tail Lift 12M Service & Weight | Tail Lift 12M Service & Weight Done by South west lifts P/O 151193513 |       |            |       |         |           |            |          |
| Defect Repair                  | 23/10/2019                                                            | 13:05 | 23/10/2019 | 13:07 | 183,523 | Derriford |            | DE027766 |
| 03 Instruments & Sensors 1     | Clear historic codes                                                  |       |            |       |         |           |            |          |
| 44 Add Ad Blue                 | Topped up                                                             |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                    |       |            |       |         |           |            |          |

|                            |                                                                    |              |                   |              |                |                      |                 |
|----------------------------|--------------------------------------------------------------------|--------------|-------------------|--------------|----------------|----------------------|-----------------|
| 34 Lights Bulb Replacement | replace o/s headlight bulb                                         |              |                   |              |                |                      |                 |
| 45 Engine 1                | oil leak Clean off engine & front cross member monitor             |              |                   |              |                | Monitoring           |                 |
| 89 Seats                   | Rear seat swivel seat lock pins loose Tighten lock nuts            |              |                   |              |                |                      |                 |
| Safety Inspection          |                                                                    |              |                   |              |                |                      |                 |
| UB Fire Supp 12mts Service | Service of fire suppression system                                 |              |                   |              |                |                      |                 |
| MOT                        | Done by mercedes of plymouth P/O 151195029                         |              |                   |              |                |                      |                 |
| <b>Breakdown</b>           | <b>14/12/2019</b>                                                  | <b>03:53</b> | <b>14/12/2019</b> | <b>16:22</b> | <b>188,946</b> | <b>Derriford</b>     | <b>DE028159</b> |
| Breakdown                  | Scratch to O/S Body                                                |              |                   |              |                | Monitoring           |                 |
| <b>BREAKDOWN</b>           | <b>20/12/2019</b>                                                  | <b>09:00</b> | <b>14/01/2020</b> | <b>09:13</b> | <b>189,657</b> | <b>Derriford</b>     | <b>DE028216</b> |
| 43 Exhaust System 1        | OS cylinder bank manifold split see notes Mercedes P/O 15119757    |              |                   |              |                |                      |                 |
| <b>Vehicle Deep Clean</b>  | <b>14/01/2020</b>                                                  | <b>08:46</b> | <b>14/01/2020</b> | <b>12:01</b> | <b>189,670</b> | <b>Derriford</b>     | <b>DE028379</b> |
| Vehicle Deep Clean         | Vehicle Deep Clean                                                 |              |                   |              |                |                      |                 |
| <b>SAFETY INSPECTION</b>   | <b>15/01/2020</b>                                                  | <b>05:54</b> | <b>16/01/2020</b> | <b>06:28</b> | <b>189,670</b> | <b>Derriford</b>     | <b>DE028392</b> |
| 02 Cab Assembly 1          | Tool cover broken, Renewed                                         |              |                   |              |                |                      |                 |
| 02 Mirrors                 | N/S mirror head damaged, Renewed                                   |              |                   |              |                |                      |                 |
| 16 Suspension 1            | Slight play in both front struts, Servicable                       |              |                   |              |                |                      |                 |
| 18 Wheels Check Torques    |                                                                    |              |                   |              |                |                      |                 |
| 24 Driveshaft 1            | Rear prop, rear u'j worn, Renewed                                  |              |                   |              |                |                      |                 |
| 34 Lights                  | DRL dim, Swapped                                                   |              |                   |              |                |                      |                 |
| 34 Lights Bulb Replacement | OS dipped beam n/w, Renewed                                        |              |                   |              |                |                      |                 |
| 45 Engine 1                | oil leak Clean off engine & front cross member monitor, Checked ok |              |                   |              |                |                      |                 |
| 55 Ramp                    | Tail lift bridge plate guides loose, Repaired                      |              |                   |              |                |                      |                 |
| 71 Body Exterior 2         | Various body damage                                                |              |                   |              |                | Awaiting Body Repair |                 |
| 85 Body Interior 1         | PCR holder broken, Repaired                                        |              |                   |              |                |                      |                 |
| 85 Body Interior 2         | Bio safe strap broken, Repaired                                    |              |                   |              |                |                      |                 |
| 86 Door Hinges             | N/S check strap loose, Tightened                                   |              |                   |              |                |                      |                 |
| 86 Doors                   | Drivers door stay mount split                                      |              |                   |              |                | Awaiting Body Repair |                 |
| 86 Sliding Door            | top magnet not striking, Adjusted                                  |              |                   |              |                |                      |                 |
| 89 Seats                   | swivel seat pins loose, Tightened                                  |              |                   |              |                |                      |                 |

Safety Inspection  
 Brakes Replace Brake Fluid  
 Tail Lift Inspection

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>22/01/2020</b> | <b>20:21</b> | <b>23/01/2020</b> | <b>08:37</b> | <b>190,185</b> | <b>Derriford</b> | <b>DE028458</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                          |                                                       |
|--------------------------|-------------------------------------------------------|
| 13 Brakes 1<br>Breakdown | Renew OSF wear sensor<br>Brakes were warning light on |
|--------------------------|-------------------------------------------------------|

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>BREAKDOWN</b> | <b>29/01/2020</b> | <b>08:11</b> | <b>29/01/2020</b> | <b>09:23</b> | <b>190,741</b> | <b>Derriford</b> | <b>DE028505</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                                      |                                                                                                   |
|--------------------------------------|---------------------------------------------------------------------------------------------------|
| 31 Battery Aux<br>31 Battery Chassis | Auxiliary battery replaced<br>non start at A+E Travel to A&E jump start vehicle return to station |
|--------------------------------------|---------------------------------------------------------------------------------------------------|

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>29/01/2020</b> | <b>12:25</b> | <b>30/01/2020</b> | <b>13:44</b> | <b>190,743</b> | <b>Derriford</b> | <b>DE028514</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|           |                                              |
|-----------|----------------------------------------------|
| Breakdown | NONE START -RECOVERY CHECKED UNABLE TO FAULT |
|-----------|----------------------------------------------|

|                  |                   |              |                   |              |                |                  |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Breakdown</b> | <b>09/02/2020</b> | <b>08:04</b> | <b>10/02/2020</b> | <b>07:18</b> | <b>191,000</b> | <b>Derriford</b> | <b>DE028590</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                              |                                                                                   |
|------------------------------|-----------------------------------------------------------------------------------|
| 86 Sliding Door<br>Breakdown | Removed and renewed side door inner handle<br>side door internal handle is broken |
|------------------------------|-----------------------------------------------------------------------------------|

|                          |                   |              |                   |              |                |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>24/02/2020</b> | <b>07:01</b> | <b>26/02/2020</b> | <b>15:07</b> | <b>193,309</b> | <b>Derriford</b> | <b>DE028689</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                                                                                                                                                                                                                 |                                                                                                                                                                                                                                                                                                               |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 02 Cab Assembly 1<br>02 Cab Assembly 2<br>16 Suspension 1<br>17 Tyres Replace<br>18 Wheels Check Torques<br>34 Emergency Light System<br>34 Lighting System<br>45 Engine 1<br>45 Engine 2<br>71 Body Exterior 1 | Cab storage button renewed<br>Torch replaced, brake pedal rubber renewed<br>Rear ARB bushes renewed<br>Renew NSR tyres<br>Adjust bullhorn switch<br>NSF top body marker light renewed<br>NS oil leak, inlet pipe O ring broken, renewed, wash engine<br>Route Firetrace correctly<br>Spray supression secured |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

|                              |                                                                              |       |            |                      |         |           |          |
|------------------------------|------------------------------------------------------------------------------|-------|------------|----------------------|---------|-----------|----------|
| 71 Body Exterior 2           | Various body damage                                                          |       |            | Awaiting Body Repair |         |           |          |
| 86 Doors                     | Drivers door stay mount split                                                |       |            |                      |         |           |          |
| 86 Sliding Door              | Not opening from inside, lubed & adjusted                                    |       |            |                      |         |           |          |
| 89 Seats                     | Drivers seat cover & cushion renewed                                         |       |            |                      |         |           |          |
| Road Test                    | Road, brake test & wash engine                                               |       |            |                      |         |           |          |
| Safety Inspection            |                                                                              |       |            |                      |         |           |          |
| Pollen Filter Change         | Pollen Filter Change                                                         |       |            |                      |         |           |          |
| Fuel Filter Change           | Change Fuel Filter                                                           |       |            |                      |         |           |          |
| Air Filter Change            | Air Filter Change                                                            |       |            |                      |         |           |          |
| Replace Handbrake Cables     | Replace Handbrake Cables                                                     |       |            |                      |         |           |          |
| Annual Air Con Service       | Annual Air Condition Service                                                 |       |            |                      |         |           |          |
| Annual Heater Service        | Annual Heater Service                                                        |       |            |                      |         |           |          |
| Vehicle Deep Clean           | 26/02/2020                                                                   | 07:00 | 26/02/2020 | 14:37                | 193,309 | Derriford | DE028711 |
| Vehicle Deep Clean           | Vehicle Deep Clean                                                           |       |            |                      |         |           |          |
| Unplanned Repair             | 28/02/2020                                                                   | 08:30 | 28/02/2020 | 09:09                | 193,415 | Derriford | DE028742 |
| 16 Suspension 1              | Check for reported knocking noise from rear tighten anti roll bar link bolts |       |            |                      |         |           |          |
| Unplanned Repair             | 20/03/2020                                                                   | 06:56 | 20/03/2020 | 06:58                | 195,509 | Derriford | DE028884 |
| 86 Doors Rear                | swapped carry chair rear door mount                                          |       |            |                      |         |           |          |
| SAFETY INSPECTION            | 06/04/2020                                                                   | 07:00 | 07/04/2020 | 08:19                | 197,215 | Derriford | DE029020 |
| 02 Cab Ass Fire Extinguisher | Renew saloon extinguisher                                                    |       |            | Awaiting Body Repair |         |           |          |
| 02 Windscreen Wipers         | NS washer connector renewed                                                  |       |            |                      |         |           |          |
| 03 Instruments & Sensors 1   | Service mileage reset                                                        |       |            |                      |         |           |          |
| 13 Brake Pads                | Front discs & pads renewed                                                   |       |            |                      |         |           |          |
| 18 Wheels Check Torques      |                                                                              |       |            |                      |         |           |          |
| 34 Lights                    | OSR top indicator renewed                                                    |       |            |                      |         |           |          |
| 45 Engine 1                  | Secured Lambda sensor wiring, top of engine.                                 |       |            |                      |         |           |          |
| 71 Body Exterior 1           | Spray supression secured, front bumper footplate renewed                     |       |            |                      |         |           |          |
| 86 Doors                     | Drivers door stay mount split                                                |       |            |                      |         |           |          |
| 86 Sliding Door              | Not opening from inside, linkage adjusted, lubed                             |       |            |                      |         |           |          |
| Safety Inspection            |                                                                              |       |            |                      |         |           |          |
| UB Fire Supp 6mts Service    | UB Fire Supp 6mts Service                                                    |       |            |                      |         |           |          |

Tail Lift Inspection  
Engine Change Oil & Filter

**Vehicle Deep Clean**      **07/04/2020**      **07:43**      **07/04/2020**      **11:45**      **197,215**      **Derriford**      **DE029031**

Vehicle Deep Clean      Vehicle Deep Clean

**SAFETY INSPECTION**      **18/05/2020**      **07:42**      **20/05/2020**      **06:33**      **200,947**      **Derriford**      **DE029413**

|                            |                                                                     |                |
|----------------------------|---------------------------------------------------------------------|----------------|
| 02 Cab Assembly 1          | Centre console button missing                                       | Awaiting Parts |
| 03 Instruments & Sensors 1 | Diagnose & renew OSR brake sensor loom                              |                |
| 03 Instruments & Sensors 2 | ESN kit fitted                                                      |                |
| 13 Brake Pads              | Rear pads renewed                                                   |                |
| 18 Wheels Check Torques    |                                                                     |                |
| 71 Body Exterior 1         | Bridge plate guide bolt renewed                                     |                |
| 86 Doors                   | Drivers door stay mount split                                       | Monitoring     |
| 86 Doors Rear              | NS difficult to open from inside, OS hinge adjusted, catch adjusted |                |
| 89 Seats                   | 2nd saloon seat lock pin renewed                                    |                |
| Safety Inspection          |                                                                     |                |
| Axle Oil Change            | Axle Oil Change                                                     |                |

**Vehicle Deep Clean**      **21/05/2020**      **07:00**      **21/05/2020**      **14:35**      **201,045**      **Derriford**      **DE029447**

Vehicle Deep Clean      Vehicle Deep Clean

**Defect Repair**      **12/06/2020**      **07:49**      **12/06/2020**      **07:52**      **203,369**      **Derriford**      **DE029626**

87 Stretcher      Renew battery

**Breakdown**      **13/06/2020**      **22:08**      **15/06/2020**      **15:17**      **203,514**      **Derriford**      **DE029636**

Breakdown      reversing camera not working      Awaiting Parts

**SAFETY INSPECTION**      **29/06/2020**      **06:45**      **30/06/2020**      **08:45**      **205,038**      **Derriford**      **DE029746**

|                              |                                |
|------------------------------|--------------------------------|
| 02 Cab Ass Fire Extinguisher | Swap cab extinguisher          |
| 02 Cab Assembly 1            | Centre console button refitted |

|                            |                                               |              |                   |              |                |                      |                 |
|----------------------------|-----------------------------------------------|--------------|-------------------|--------------|----------------|----------------------|-----------------|
| 02 Cab Assembly 2          | Renew torch                                   |              |                   |              |                |                      |                 |
| 15 Steering 1              | Check & adjust tracking                       |              |                   |              |                |                      |                 |
| 17 Tyres Replace           | Renew front tyres                             |              |                   |              |                |                      |                 |
| 18 Wheels Check Torques    |                                               |              |                   |              |                |                      |                 |
| 42 Coolant System          | Header tank renewed                           |              |                   |              |                |                      |                 |
| 45 Engine 1                | Belt tensioner renewed                        |              |                   |              |                |                      |                 |
| 71 Body Exterior 1         | Secure bridge plate guides                    |              |                   |              |                |                      |                 |
| 86 Doors                   | Drivers door stay mount split                 |              |                   |              |                | Awaiting Body Repair |                 |
| 86 Doors Rear              | Adjust catches                                |              |                   |              |                |                      |                 |
| 86 Sliding Door            | Centre rollers renewed                        |              |                   |              |                |                      |                 |
| Breakdown                  | reversing camera not working                  |              |                   |              |                | Monitoring           |                 |
| Safety Inspection          |                                               |              |                   |              |                |                      |                 |
| Tail Lift Inspection       |                                               |              |                   |              |                |                      |                 |
| <b>Vehicle Deep Clean</b>  | <b>30/06/2020</b>                             | <b>07:30</b> | <b>30/06/2020</b> | <b>14:17</b> | <b>205,038</b> | <b>Derriford</b>     | <b>DE029758</b> |
| Vehicle Deep Clean         | Vehicle Deep Clean                            |              |                   |              |                |                      |                 |
| <b>Unplanned Repair</b>    | <b>01/07/2020</b>                             | <b>15:00</b> | <b>01/07/2020</b> | <b>15:56</b> | <b>205,110</b> | <b>Derriford</b>     | <b>DE029779</b> |
| 31 Battery Chassis         | Chassis battery failed replaced battery       |              |                   |              |                |                      |                 |
|                            |                                               |              |                   |              |                |                      |                 |
| <b>Defect Repair</b>       | <b>05/07/2020</b>                             | <b>10:50</b> | <b>05/07/2020</b> | <b>10:52</b> | <b>205,539</b> | <b>Derriford</b>     | <b>DE029801</b> |
| 86 Sliding Door            | Investigate side door locking fault, repaired |              |                   |              |                |                      |                 |
|                            |                                               |              |                   |              |                |                      |                 |
| <b>SAFETY INSPECTION</b>   | <b>11/08/2020</b>                             | <b>08:19</b> | <b>11/08/2020</b> | <b>13:40</b> | <b>209,357</b> | <b>Derriford</b>     | <b>DE030069</b> |
| 02 Cab Assembly 1          | Centre console button renewed                 |              |                   |              |                |                      |                 |
| 03 Instruments & Sensors 1 | OSF pad sensor wire routed correctly          |              |                   |              |                |                      |                 |
| 17 Tyres Replace           | Renew OSR tyres                               |              |                   |              |                |                      |                 |
| 18 Wheels Check Torques    |                                               |              |                   |              |                |                      |                 |
| 55 Tail Lift               | Handrail magnet U/S                           |              |                   |              |                | Awaiting Parts       |                 |
| 86 Doors                   | Drivers door stay mount split                 |              |                   |              |                | Monitoring           |                 |
| Breakdown                  | reversing camera not working                  |              |                   |              |                | Monitoring           |                 |
| Safety Inspection          |                                               |              |                   |              |                |                      |                 |
| Replace Vehicle Fuel Card  | Replace Vehicle Fuel Card                     |              |                   |              |                |                      |                 |

|                            |                                                                  |              |                   |              |                |                  |                      |
|----------------------------|------------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|----------------------|
| <b>Vehicle Deep Clean</b>  | <b>12/08/2020</b>                                                | <b>07:00</b> | <b>12/08/2020</b> | <b>14:20</b> | <b>209,428</b> | <b>Derriford</b> | <b>DE030082</b>      |
| Vehicle Deep Clean         | Vehicle Deep Clean                                               |              |                   |              |                |                  |                      |
| <b>Defect Repair</b>       | <b>09/09/2020</b>                                                | <b>06:50</b> | <b>09/09/2020</b> | <b>07:55</b> | <b>212,890</b> | <b>Derriford</b> | <b>DE030304</b>      |
| 03 Instruments & Sensors 1 | EML on check codes, perform regen                                |              |                   |              |                |                  |                      |
| <b>SAFETY INSPECTION</b>   | <b>22/09/2020</b>                                                | <b>06:07</b> | <b>23/09/2020</b> | <b>07:12</b> | <b>214,325</b> | <b>Derriford</b> | <b>DE030388</b>      |
| 02 Cab Assembly 1          | Cab storage knob missing, RENEWED                                |              |                   |              |                |                  |                      |
| 03 Instruments & Sensors 1 | EML on, DPF, REGENERATED                                         |              |                   |              |                |                  |                      |
| 16 Suspension 1            | Slight play in front lower b/js all ok at present                |              |                   |              |                |                  |                      |
| 18 Wheels Check Torques    |                                                                  |              |                   |              |                |                  |                      |
| 55 Tail Lift               | Handrail magnet U/S, RENEWED                                     |              |                   |              |                |                  |                      |
| 71 Body Exterior 1         | Tail lift bridge plate runners insecure/adrift, SECURED REFITTED |              |                   |              |                |                  |                      |
| 85 Body Interior 1         | Intercom mic loose, RECTIFIED                                    |              |                   |              |                |                  |                      |
| 86 Doors                   | Drivers door stay mount split, BODYSHOP REQD                     |              |                   |              |                |                  | Awaiting Body Repair |
| 89 Seats                   | Attendants seat adjuster bar insecure, SECURED                   |              |                   |              |                |                  |                      |
| Breakdown                  | reversing camera not working, JOHN COLES REQD, Notes             |              |                   |              |                |                  | Monitoring           |
| MDT Failure/Issue          | Power button missing on MDT, REPORTED PCE                        |              |                   |              |                |                  |                      |
| Safety Inspection          |                                                                  |              |                   |              |                |                  |                      |
| Supply Sat Nav             | Update sat nav                                                   |              |                   |              |                |                  |                      |
| Tail Lift Inspection       |                                                                  |              |                   |              |                |                  |                      |
| UB Fire Supp 6mts Service  | UB Fire Supp 6mts Service                                        |              |                   |              |                |                  |                      |
| <b>Vehicle Deep Clean</b>  | <b>23/09/2020</b>                                                | <b>07:07</b> | <b>23/09/2020</b> | <b>11:58</b> | <b>214,325</b> | <b>Derriford</b> | <b>DE030401</b>      |
| Vehicle Deep Clean         | Vehicle Deep Clean                                               |              |                   |              |                |                  |                      |
| <b>Unplanned Repair</b>    | <b>30/09/2020</b>                                                | <b>05:32</b> | <b>30/09/2020</b> | <b>06:19</b> | <b>215,260</b> | <b>Derriford</b> | <b>DE030446</b>      |
| 03 Instruments & Sensors 1 | drive by eml on plugged texa in unknown error, cleared           |              |                   |              |                |                  |                      |



|                      |                   |              |                   |              |                |                  |                 |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Defect Repair</b> | <b>28/10/2020</b> | <b>06:48</b> | <b>28/10/2020</b> | <b>06:50</b> | <b>219,085</b> | <b>Derriford</b> | <b>DE030635</b> |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                            |                          |
|----------------------------|--------------------------|
| 34 Lights Bulb Replacement | OS repeater bulb renewed |
|----------------------------|--------------------------|

|                          |                   |              |                   |              |                |                  |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>02/11/2020</b> | <b>06:55</b> | <b>03/11/2020</b> | <b>09:37</b> | <b>219,762</b> | <b>Derriford</b> | <b>DE030653</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                                |                                                                            |                      |
|--------------------------------|----------------------------------------------------------------------------|----------------------|
| 02 Cab Assembly 1              | Torch not working                                                          |                      |
| 03 Instruments & Sensors 1     | EML on.                                                                    |                      |
| 13 Brake Pads                  | Renew Front & rear pads                                                    |                      |
| 17 Tyres Replace               | 1X puncture, 2x worn out, replace all with cross climate                   |                      |
| 18 Wheels Check Torques        |                                                                            |                      |
| 34 Lighting System             | Body Interior rear interior light not working                              |                      |
| 71 Body Exterior 1             | Body Exterior reversing camera not working                                 | Awaiting Parts       |
| 71 Body Exterior 2             | OSR light cluster damage, OS body corner renewed                           | Awaiting Parts       |
| 86 Doors                       | Drivers door stay mount split, BODYSHOP REQD                               | Awaiting Body Repair |
| 86 Doors Rear                  | Doors O/S rear door stay Broken                                            |                      |
| 86 Sliding Door                | Adjust catches                                                             |                      |
| Breakdown                      | reversing camera not working, JOHN COLES REQD, Notes                       |                      |
| Safety Inspection              |                                                                            |                      |
| Tail Lift 12M Service & Weight | Tail Lift 12M Service & Weight test Done by South west lifts P/O 151209140 |                      |
| Tail Lift Inspection           |                                                                            |                      |

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>05/11/2020</b> | <b>11:00</b> | <b>06/11/2020</b> | <b>05:45</b> | <b>219,901</b> | <b>Derriford</b> | <b>DE030687</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|          |                                                                |
|----------|----------------------------------------------------------------|
| 86 Doors | Stripped and adjusted side door handle inner mech with j coles |
|----------|----------------------------------------------------------------|

|                           |                   |              |                   |              |                |                  |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>09/11/2020</b> | <b>07:21</b> | <b>09/11/2020</b> | <b>12:21</b> | <b>220,353</b> | <b>Derriford</b> | <b>DE030709</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                         |                   |              |                   |              |                |                  |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Unplanned Repair</b> | <b>09/11/2020</b> | <b>15:06</b> | <b>10/11/2020</b> | <b>13:35</b> | <b>220,654</b> | <b>Derriford</b> | <b>DE030714</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                            |                                                               |
|----------------------------|---------------------------------------------------------------|
| 03 Instruments & Sensors 1 | check for EML light on found nox sensor fault Replaced sensor |
|----------------------------|---------------------------------------------------------------|

|                      |                   |              |                   |              |                |                  |                 |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|
| <b>Defect Repair</b> | <b>12/11/2020</b> | <b>06:46</b> | <b>12/11/2020</b> | <b>07:29</b> | <b>220,654</b> | <b>Derriford</b> | <b>DE030734</b> |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|------------------|-----------------|

|                 |                                   |
|-----------------|-----------------------------------|
| 86 Sliding Door | Not opening, bottom catch renewed |
|-----------------|-----------------------------------|

|                            |                                                                 |              |                   |              |                |                  |                      |
|----------------------------|-----------------------------------------------------------------|--------------|-------------------|--------------|----------------|------------------|----------------------|
| <b>Defect Repair</b>       | <b>30/11/2020</b>                                               | <b>07:20</b> | <b>30/11/2020</b> | <b>10:49</b> | <b>222,498</b> | <b>Derriford</b> | <b>DE030852</b>      |
| 01 Heating 1               | Other Cab Heating not working, blower motor renewed             |              |                   |              |                |                  |                      |
| <b>Unplanned Repair</b>    | <b>04/12/2020</b>                                               | <b>09:00</b> | <b>04/12/2020</b> | <b>09:59</b> | <b>223,181</b> | <b>Derriford</b> | <b>DE030891</b>      |
| 86 Door handle             | renewed outer rear handle                                       |              |                   |              |                |                  |                      |
| <b>Unplanned Repair</b>    | <b>10/12/2020</b>                                               | <b>06:00</b> | <b>10/12/2020</b> | <b>06:32</b> | <b>223,808</b> | <b>Derriford</b> | <b>DE030936</b>      |
| 34 Lights Bulb Replacement | Removed firetrace exh, R&R o/s dipped bulb and refitted parts   |              |                   |              |                |                  |                      |
| <b>SAFETY INSPECTION</b>   | <b>14/12/2020</b>                                               | <b>06:40</b> | <b>15/12/2020</b> | <b>13:35</b> | <b>224,285</b> | <b>Derriford</b> | <b>DE030961</b>      |
| 02 Cab Assembly 1          | Centre storage unit knob renewed                                |              |                   |              |                |                  |                      |
| 03 Instruments & Sensors 1 | Remove ESN install                                              |              |                   |              |                |                  |                      |
| 16 Suspension 1            | OSF strut shroud renewed                                        |              |                   |              |                |                  |                      |
| 16 Suspension 2            | 2x rear spring pads renewed                                     |              |                   |              |                |                  |                      |
| 16 Suspension 3            | NSF bottom arm renewed                                          |              |                   |              |                |                  |                      |
| 18 Wheels Check Torques    |                                                                 |              |                   |              |                |                  |                      |
| 71 Body Exterior 1         | Body Exterior reversing camera not working                      |              |                   |              |                |                  | Monitoring           |
| 71 Body Exterior 2         | OSR light cluster damage, OS body corner renewed                |              |                   |              |                |                  | Monitoring           |
| 71 Body Exterior 3         | Top & bottom NS body corners renewed                            |              |                   |              |                |                  |                      |
| 86 Doors                   | Drivers door stay mount split, BODYSHOP REQD                    |              |                   |              |                |                  | Awaiting Body Repair |
| 86 Sliding Door            | Diifficult to open from inside, mechanism adjusted              |              |                   |              |                |                  |                      |
| Safety Inspection          |                                                                 |              |                   |              |                |                  |                      |
| Travel Time                |                                                                 |              |                   |              |                |                  |                      |
| Engine Change Oil & Filter |                                                                 |              |                   |              |                |                  |                      |
| UB Fire Supp 12mts Service | Service of fire supression system                               |              |                   |              |                |                  |                      |
| MOT                        | Done by Mercedes of Plymouth P/O 151208163                      |              |                   |              |                |                  |                      |
| <b>Unplanned Repair</b>    | <b>31/12/2020</b>                                               | <b>13:00</b> | <b>31/12/2020</b> | <b>14:49</b> | <b>226,023</b> | <b>Derriford</b> | <b>DE031065</b>      |
| 86 Door handle             | Remove n/s/r door inner panel straighten bent mechanism & refit |              |                   |              |                |                  |                      |

|                                |                                                              |       |            |       |         |                                    |          |
|--------------------------------|--------------------------------------------------------------|-------|------------|-------|---------|------------------------------------|----------|
| Unplanned Repair               | 04/01/2021                                                   | 07:55 | 04/01/2021 | 07:58 | 226,459 | Derriford                          | DE031071 |
| 86 Doors Rear                  | stripped rear door inner panel and repaired door handle mech |       |            |       |         |                                    |          |
| Breakdown                      | 18/01/2021                                                   | 17:16 | 20/01/2021 | 15:20 | 228,676 | Derriford                          | DE031188 |
| Breakdown<br>Supply Sat Nav    | SatNav not powering on<br>To be replaced next inspection     |       |            |       |         | Awaiting Parts                     |          |
| SAFETY INSPECTION              | 21/01/2021                                                   | 08:21 | 22/01/2021 | 11:50 | 228,676 | Derriford                          | DE031207 |
| 02 Mirrors                     | Secure OS mirror                                             |       |            |       |         |                                    |          |
| 18 Wheels Check Torques        |                                                              |       |            |       |         |                                    |          |
| 45 Engine 1                    | Noisy pulley, Tensioner u/s, renewed                         |       |            |       |         | Monitoring<br>Awaiting Body Repair |          |
| 71 Body Exterior 1             | Body Exterior reversing camera not working                   |       |            |       |         |                                    |          |
| 86 Doors                       | Drivers door stay mount split, BODYSHOP REQD                 |       |            |       |         |                                    |          |
| 86 Sliding Door                | Not opening from inside, cables/linkage adjusted             |       |            |       |         |                                    |          |
| Safety Inspection              |                                                              |       |            |       |         |                                    |          |
| Supply Sat Nav                 | To be replaced next inspection. Checked ok on road test      |       |            |       |         |                                    |          |
| Auto G/box Oil & Filter Change | Auto G/box Oil & Filter Change                               |       |            |       |         |                                    |          |
| Vehicle Deep Clean             | 26/01/2021                                                   | 07:08 | 26/01/2021 | 07:09 | 228,677 | Derriford                          | DE031239 |
| Vehicle Deep Clean             | Vehicle Deep Clean                                           |       |            |       |         |                                    |          |
| Vehicle Deep Clean             | 26/01/2021                                                   | 07:10 | 26/01/2021 | 11:56 | 228,976 | Derriford                          | DE031240 |
| Vehicle Deep Clean             | Vehicle Deep Clean                                           |       |            |       |         |                                    |          |
| Unplanned Repair               | 28/01/2021                                                   | 08:34 | 29/01/2021 | 15:18 | 229,215 | Derriford                          | DE031259 |
| 43 Exhaust System 1            | DPF bracket found to be broken DPF replaced P/O 151212381    |       |            |       |         |                                    |          |
| 45 Engine 1                    |                                                              |       |            |       |         |                                    |          |
| Unplanned Repair               | 03/02/2021                                                   | 07:30 | 08/02/2021 | 09:30 | 229,584 | Derriford                          | DE031303 |

|                            |                                                              |
|----------------------------|--------------------------------------------------------------|
| 03 Instruments & Sensors 1 | Addblue fault                                                |
| 45 Engine 1                | Investigate engine rattle See Notes being repaired at Exeter |

|                  |                   |              |                   |              |                |               |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|---------------|-----------------|
| <b>BREAKDOWN</b> | <b>09/02/2021</b> | <b>07:46</b> | <b>05/03/2021</b> | <b>13:12</b> | <b>229,584</b> | <b>Exeter</b> | <b>EX028101</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|---------------|-----------------|

|                            |                                                                          |
|----------------------------|--------------------------------------------------------------------------|
| 002 Major Unit Replace Eng |                                                                          |
| 45 Engine 1                | vehicle came from Derriford to city west reported timing chain,see notes |

|                          |                   |              |                   |              |                |               |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|---------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>05/03/2021</b> | <b>12:14</b> | <b>11/03/2021</b> | <b>10:29</b> | <b>229,653</b> | <b>Exeter</b> | <b>EX028239</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|---------------|-----------------|

|                               |                                                                                  |            |
|-------------------------------|----------------------------------------------------------------------------------|------------|
| 01 Air Conditioning 1         | condenser fan seized, Frame work rusted and holed                                |            |
| 01 Heating 1                  | Heater exhaust clamp loose                                                       |            |
| 02 Cab Ass Fire Extinguisher  | Fire extingusiher expired Warning bypassed                                       |            |
| 02 Windscreen Wipers          | Wipers not clearing screen, REPLACED                                             |            |
| 03 Instruments & Sensors 1    | No power to DVR + Plug melted wiring burnt REPAIRED WIRING REPLACED PLUG AND PIN |            |
| 03 Instruments & Sensors 2    | No reverse camera FAULT WAS WITHIN DVR REPAIRED                                  |            |
| 13 Brakes 1                   | Handbrake travel exssive, unable to adjust, SEE NOTES                            |            |
| 16 Suspension 1               | Slight lift in both front shocks + Ubolts insecure - SECURED                     |            |
| 18 Wheels Check Torques       |                                                                                  |            |
| 34 Emergency Lights           | N/S/F CORNER BLUE LIGHT damaged but serviceable                                  | Monitoring |
| 34 Lights                     | Indicators activate reverse and O/S Side lights on rear                          |            |
| 42 Coolant System             | Radiator not clipped in                                                          |            |
| 43 Exhaust System 1           | Exhaust pipe holed                                                               |            |
| 45 Engine 1                   | Engine mounts split both sides                                                   |            |
| 71 Body Exterior 1            | MULTIPLE SEE NOTES                                                               |            |
| 85 Body Interior 1            | MULTIPLE SEE NOTES                                                               |            |
| 86 Doors                      | Drivers door stay mount split, BODYSHOP REQD                                     |            |
| 86 Sliding Door               | Side door seized + cannot open from outside + Top magnet split - REPLACED        |            |
| 89 Seats                      | Seat stops loose ADJUSTED + front swivel worn MONITOR                            |            |
| Safety Inspection             |                                                                                  |            |
| UB Fire Supp Repair           | Fire suppression low pressure in system                                          |            |
| Replace Handbrake Cables      | Replace Handbrake Cables                                                         |            |
| Tail Lift Inspection          |                                                                                  |            |
| UB Fire Supp 6mts Service     | UB Fire Supp 6mts Service                                                        |            |
| UB Fire Suppression Discharge | Under Bonnet Fire Suppression 5 Year Discharge Test                              |            |
| Annual Air Con Service        | Annual Air Condition Service                                                     |            |

|                            |                                                                          |       |            |       |         |            |          |
|----------------------------|--------------------------------------------------------------------------|-------|------------|-------|---------|------------|----------|
| Vehicle Deep Clean         | 11/03/2021                                                               | 08:22 | 11/03/2021 | 14:39 | 229,658 | Exeter     | EX028277 |
| Vehicle Deep Clean         | Vehicle Deep Clean                                                       |       |            |       |         |            |          |
| Breakdown                  | 12/03/2021                                                               | 16:20 | 15/03/2021 | 06:29 | 229,676 | Exeter     | EX028297 |
| Breakdown                  | slow puncture, rectified by ATS                                          |       |            |       |         |            |          |
| Unplanned Repair           | 19/03/2021                                                               | 09:38 | 19/03/2021 | 09:54 | 229,676 | Exeter     | EX028355 |
| 002 Major Unit Replace Eng | additional costs for AIRCON REPAIRS                                      |       |            |       |         |            |          |
| Breakdown                  | 14/04/2021                                                               | 03:38 | 14/04/2021 | 07:46 | 234,822 | Exeter     | EX028569 |
| 71 Body Exterior 1         | rear corner samshed off see notes                                        |       |            |       |         |            |          |
| Breakdown                  | damaged offside end of the vehicle; SEE NOTES                            |       |            |       |         |            |          |
| Travel Time                | collect from EDOC for repair                                             |       |            |       |         |            |          |
| SAFETY INSPECTION          | 19/04/2021                                                               | 14:09 | 21/04/2021 | 07:00 | 235,275 | Exeter     | EX028618 |
| 16 Suspension 1            | N/S/F Strut boot split MONITOR                                           |       |            |       |         | Monitoring |          |
| 16 Suspension 2            | O/S Anti rollbar link arm worn - REPLACED                                |       |            |       |         |            |          |
| 18 Wheels                  | No wheel markers on N/S/F Wheel - Fit new wheel markers                  |       |            |       |         |            |          |
| 18 Wheels Check Torques    |                                                                          |       |            |       |         |            |          |
| 34 Emergency Lights        | N/S/F CORNER BLUE LIGHT damaged but serviceable                          |       |            |       |         |            |          |
| 34 Lights                  | Multiple light defects see notes                                         |       |            |       |         |            |          |
| 34 Lights Bulb Replacement | O/S/F DRL inop                                                           |       |            |       |         |            |          |
| 55 Tail Lift               | Tail lift swaying when accelerating SEE NOTES                            |       |            |       |         |            |          |
| 71 Body Exterior 1         | blue auto eject cracked + O/S/R Light pod surround holed - Temp repaired |       |            |       |         |            |          |
| 85 Body Interior 1         | Various interior defects SEE NOTES                                       |       |            |       |         |            |          |
| 86 Door Lock               | Rear door not locking SEE NOTES                                          |       |            |       |         |            |          |
| 89 Seatbelts               | drivers seat belt frayed - Sleaned up frayed edges - Serviceable         |       |            |       |         |            |          |
| Road Test                  |                                                                          |       |            |       |         |            |          |
| Safety Inspection          |                                                                          |       |            |       |         |            |          |
| Vehicle Deep Clean         | 20/04/2021                                                               | 14:01 | 21/04/2021 | 14:48 | 235,275 | Exeter     | EX028631 |

|                           |                                                                           |              |                   |              |                |                    |                 |
|---------------------------|---------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| Vehicle Deep Clean        | Vehicle Deep Clean                                                        |              |                   |              |                |                    |                 |
| <b>Defect Repair</b>      | <b>26/04/2021</b>                                                         | <b>15:45</b> | <b>26/04/2021</b> | <b>16:53</b> | <b>236,756</b> | <b>North Devon</b> | <b>NO015487</b> |
| 55 Tail Lift              | Reported tail lift not opening, See notes.                                |              |                   |              |                |                    |                 |
| 86 Doors Rear             | Unable to open from outside, see notes.                                   |              |                   |              |                |                    |                 |
| <b>BREAKDOWN</b>          | <b>04/05/2021</b>                                                         | <b>08:00</b> | <b>04/05/2021</b> | <b>08:55</b> | <b>237,953</b> | <b>Exeter</b>      | <b>EX028726</b> |
| 86 Doors Rear             | unable to open remove cover rectify lever and rod and refit               |              |                   |              |                |                    |                 |
| <b>SAFETY INSPECTION</b>  | <b>02/06/2021</b>                                                         | <b>12:08</b> | <b>03/06/2021</b> | <b>14:03</b> | <b>241,472</b> | <b>Exeter</b>      | <b>EX028947</b> |
| 13 Handbrake              | Requires adjustment RESET SHOES AND CABLES                                |              |                   |              |                |                    |                 |
| 16 Suspension 1           | N/S/F Strut boot split MONITOR                                            |              |                   |              |                |                    |                 |
| 18 Wheels Check Torques   | Monitoring                                                                |              |                   |              |                |                    |                 |
| 24 Driveshaft 1           | Telma wiring to earth point damaged SEE NOTES                             |              |                   |              |                |                    |                 |
| 34 Lighting System        | Side step light inop REPAIRED WIRING                                      |              |                   |              |                |                    |                 |
| 52 Electrical Aux         | Saloon warning SEE NOTES REPAIRED                                         |              |                   |              |                |                    |                 |
| 55 Tail Lift              | O/S drop handle cracked, REPLCED FROM SCRAPPED VEHICLE                    |              |                   |              |                |                    |                 |
| 85 Body Interior 1        | Buckle missing from strap in rear locker REPLACED                         |              |                   |              |                |                    |                 |
| 86 Door Hinges            | O/S/R door dropped, causing door to stick BODYSHOP                        |              |                   |              |                |                    |                 |
| 86 Door Lock              | Unable to override c/locking, NO KEYS                                     |              |                   |              |                |                    |                 |
| 86 Doors                  | Both front doors starting to crack around check strap BODYSHOP            |              |                   |              |                |                    |                 |
| 86 Doors Rear             | Lower lock cover damaged REPLACED                                         |              |                   |              |                |                    |                 |
| 87 Chairs                 | Stowage lock cracked and pulling away from door REPLACED SECOND HAND UNIT |              |                   |              |                |                    |                 |
| Camera Installation       | O/S/R camera dome smashed REPLACED DRILL OUT ROUNDED SCREW                |              |                   |              |                |                    |                 |
| Safety Inspection         |                                                                           |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b> | <b>03/06/2021</b>                                                         | <b>11:25</b> | <b>03/06/2021</b> | <b>14:54</b> | <b>241,479</b> | <b>Exeter</b>      | <b>EX028955</b> |
| Vehicle Deep Clean        | Vehicle Deep Clean                                                        |              |                   |              |                |                    |                 |
| <b>Breakdown</b>          | <b>21/06/2021</b>                                                         | <b>05:59</b> | <b>21/06/2021</b> | <b>07:40</b> | <b>244,549</b> | <b>Exeter</b>      | <b>EX029112</b> |

|                      |                                                      |                |
|----------------------|------------------------------------------------------|----------------|
| 45 Engine Oil Top Up | Added 2ltr, No extrenal leaks                        |                |
| 89 Seatbelts         | Driver reported frayed, clean edges ORDERED NEW UNIT | Awaiting Parts |
| Breakdown            | low oil warning, drivers seat belt frayed            |                |

|                      |                   |              |                   |              |                |               |                 |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|---------------|-----------------|
| <b>Defect Repair</b> | <b>07/07/2021</b> | <b>12:00</b> | <b>07/07/2021</b> | <b>14:30</b> | <b>245,426</b> | <b>Exeter</b> | <b>EX029286</b> |
|----------------------|-------------------|--------------|-------------------|--------------|----------------|---------------|-----------------|

|                 |                                                                |            |
|-----------------|----------------------------------------------------------------|------------|
| 16 Suspension 1 | N/S/F Strut boot split MONITOR                                 | Monitoring |
| 86 Door Hinges  | O/S/R door dropped, causing door to stick BODYSHOP             | Monitoring |
| 86 Door Lock    | Unable to override c/locking, NO KEYS                          |            |
| 86 Doors        | Both front doors starting to crack around check strap BODYSHOP | Monitoring |
| 89 Seatbelts    | Driver reported frayed, clean edges FITTED NEW UNIT            |            |

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>05/08/2021</b> | <b>06:00</b> | <b>12/08/2021</b> | <b>07:53</b> | <b>245,595</b> | <b>St Leonards</b> | <b>SL034021</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                             |                                                                             |
|-----------------------------|-----------------------------------------------------------------------------|
| 13 Brakes 1                 | Front discs worn. Replaced.                                                 |
| 16 Suspension 1             | N/S/F Strut boot split MONITOR.Done.                                        |
| 16 Suspension 2             | Front struts worn,lower ball joints worn. Replaced.                         |
| 16 Suspension 3             | Rear shocks covers corroded.Replaced.Free siezed bolts.                     |
| 17 Tyres Tracking           | Both front tyres worn inner edge @ 3mm.Cleaned rims, replaced.Set tracking. |
| 18 Wheels Check Torques     | Checked.                                                                    |
| 86 Door Hinges              | O/S/R door dropped, causing door to stick BODYSHOP.Done.                    |
| 86 Door Lock                | All saloon lock barrells siezed.Replaced.                                   |
| 86 Doors                    | Both front doors starting to crack around check strap BODYSHOP.Done.        |
| 86 Doors Rear               | O/S stay bent. Replaced.                                                    |
| 86 Sliding Door             | Rollers siezed. Replaced.                                                   |
| Safety Inspection           | Carried out inspection.                                                     |
| Wheel Hub Flanges Replaceme | Front flanges poor condition. Replaced.                                     |
| Tail Lift Inspection        | Done. Free siezed gate drop mech, tightened gate legs.                      |

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>11/08/2021</b> | <b>10:48</b> | <b>11/08/2021</b> | <b>10:51</b> | <b>245,595</b> | <b>St Leonards</b> | <b>SL034108</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>11/08/2021</b> | <b>10:51</b> | <b>12/08/2021</b> | <b>09:00</b> | <b>245,595</b> | <b>St Leonards</b> | <b>SL034110</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                                      |                                                                                                         |              |                   |              |                |                     |                 |
|--------------------------------------|---------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|---------------------|-----------------|
| <b>Breakdown</b>                     | <b>13/08/2021</b>                                                                                       | <b>17:56</b> | <b>17/08/2021</b> | <b>15:00</b> | <b>245,694</b> | <b>St Leonards</b>  | <b>SL034133</b> |
| 42 Coolant System Breakdown          | Rad damaged. Req new Rad.<br>Coolant leak                                                               |              |                   |              |                |                     |                 |
| <b>02 Pipeline Annual Inspection</b> | <b>16/08/2021</b>                                                                                       | <b>09:01</b> | <b>16/08/2021</b> | <b>09:03</b> | <b>245,694</b> | <b>MDT Ferndown</b> | <b>TF001519</b> |
| 02 Pipeline Annual Inspection        | Annual Inspection and Pressure Test                                                                     |              |                   |              |                |                     |                 |
| <b>SAFETY INSPECTION</b>             | <b>06/09/2021</b>                                                                                       | <b>06:34</b> | <b>08/09/2021</b> | <b>08:45</b> | <b>247,108</b> | <b>St Leonards</b>  | <b>SL034294</b> |
| 02 Cab Assembly 1                    | Floor matts holed Replaced .Tool cover broken. Replaced.<br>Washers n/w.                                |              |                   |              |                |                     |                 |
| 02 Windscreen Wipers                 |                                                                                                         |              |                   |              |                |                     |                 |
| 18 Wheels Check Torques              | Cubby box knob broken. Replaced.                                                                        |              |                   |              |                |                     |                 |
| 85 Body Interior 1                   |                                                                                                         |              |                   |              |                |                     |                 |
| Safety Inspection                    | Pollen Filter Change<br>Change Fuel Filter<br>Air Filter Change                                         |              |                   |              |                |                     |                 |
| Pollen Filter Change                 |                                                                                                         |              |                   |              |                |                     |                 |
| Fuel Filter Change                   |                                                                                                         |              |                   |              |                |                     |                 |
| Air Filter Change                    |                                                                                                         |              |                   |              |                |                     |                 |
| Tail Lift Inspection                 |                                                                                                         |              |                   |              |                |                     |                 |
| <b>Vehicle Deep Clean</b>            | <b>06/09/2021</b>                                                                                       | <b>07:39</b> | <b>08/09/2021</b> | <b>08:43</b> | <b>247,108</b> | <b>St Leonards</b>  | <b>SL034296</b> |
| Vehicle Deep Clean                   | Vehicle Deep Clean                                                                                      |              |                   |              |                |                     |                 |
| <b>SAFETY INSPECTION</b>             | <b>11/10/2021</b>                                                                                       | <b>07:00</b> | <b>12/10/2021</b> | <b>08:27</b> | <b>250,047</b> | <b>St Leonards</b>  | <b>SL034621</b> |
| 13 Brakes 2                          | Rear pads worn. Replaced.                                                                               |              |                   |              |                |                     |                 |
| 13 Calipers                          |                                                                                                         |              |                   |              |                |                     |                 |
| 17 Tyres Replace                     | Both rear calipers split rubbers. Replaced N/S& O/S.<br>All rears low tread. Replaced x4.Replaced rims. |              |                   |              |                |                     |                 |
| 18 Wheels Check Torques              |                                                                                                         |              |                   |              |                |                     |                 |
| 89 Seats                             | Checked.                                                                                                |              |                   |              |                |                     |                 |
| Safety Inspection                    |                                                                                                         |              |                   |              |                |                     |                 |
| Annual Heater Service                | Bearing gone in saloon seat.Replaced.<br>Carried out inspection.<br>Annual Heater Service. Done.        |              |                   |              |                |                     |                 |



|                                                                                                                                                                                                                                                                                                                        |                                                                                                                                                                                                                                                                                                                                          |              |                   |              |                |                    |                 |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Breakdown</b>                                                                                                                                                                                                                                                                                                       | <b>06/11/2021</b>                                                                                                                                                                                                                                                                                                                        | <b>19:58</b> | <b>08/11/2021</b> | <b>10:00</b> | <b>252,753</b> | <b>St Leonards</b> | <b>SL034882</b> |
| 56 Comms Equipment Breakdown                                                                                                                                                                                                                                                                                           | MDT not turning on<br>MDT not powering on. Reset MDT.                                                                                                                                                                                                                                                                                    |              |                   |              |                |                    |                 |
| <b>Breakdown</b>                                                                                                                                                                                                                                                                                                       | <b>10/11/2021</b>                                                                                                                                                                                                                                                                                                                        | <b>19:25</b> | <b>11/11/2021</b> | <b>08:30</b> | <b>252,753</b> | <b>St Leonards</b> | <b>SL034917</b> |
| Breakdown                                                                                                                                                                                                                                                                                                              | MDT not powering on. Test batteries, reset comms, ok.                                                                                                                                                                                                                                                                                    |              |                   |              |                |                    |                 |
| <b>Breakdown</b>                                                                                                                                                                                                                                                                                                       | <b>13/11/2021</b>                                                                                                                                                                                                                                                                                                                        | <b>12:46</b> | <b>15/11/2021</b> | <b>08:00</b> | <b>252,753</b> | <b>St Leonards</b> | <b>SL034945</b> |
| 56 Comms Equipment<br>87 - Stretchers/Chairs/Boards<br>Breakdown                                                                                                                                                                                                                                                       | MDT not turning on - Re set comms<br>Carry chair fault - Straighten locks<br>MDT Turning itself off/Batt Check                                                                                                                                                                                                                           |              |                   |              |                |                    |                 |
| <b>SAFETY INSPECTION</b>                                                                                                                                                                                                                                                                                               | <b>23/11/2021</b>                                                                                                                                                                                                                                                                                                                        | <b>08:00</b> | <b>01/12/2021</b> | <b>14:00</b> | <b>252,760</b> | <b>St Leonards</b> | <b>SL035046</b> |
| 02 Windscreen Wipers<br>18 Wheels Check Torques<br>34 Lighting System<br>34 Lights<br>34 Lights Bulb Replacement<br>55 Tail Lift<br>71 Body Exterior 1<br>85 Body Interior 1<br>Safety Inspection<br>UB Fire Supp 6mts Service<br>Engine Change Oil & Filter<br>Tail Lift 12M Service & Weight<br>Tail Lift Inspection | Clean out and adjust washer jets<br><br>Replace o/s headlight cover<br>Replace n/s/r top ind lamp<br>Electrical Auxs Drivers side headlight bulb out<br>Tank leaking - SWL to replace (Parts on back order)<br>Replace o/s/r reflector<br>Repair saloon cupboards<br><br>UB Fire Supp 6mts Service<br><br>Tail Lift 12M Service & Weight |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>                                                                                                                                                                                                                                                                                              | <b>24/11/2021</b>                                                                                                                                                                                                                                                                                                                        | <b>09:54</b> | <b>24/11/2021</b> | <b>13:00</b> | <b>252,760</b> | <b>St Leonards</b> | <b>SL035061</b> |
| Vehicle Deep Clean                                                                                                                                                                                                                                                                                                     | Vehicle Deep Clean                                                                                                                                                                                                                                                                                                                       |              |                   |              |                |                    |                 |
| <b>Breakdown</b>                                                                                                                                                                                                                                                                                                       | <b>03/12/2021</b>                                                                                                                                                                                                                                                                                                                        | <b>01:19</b> | <b>03/12/2021</b> | <b>01:25</b> | <b>252,790</b> | <b>St Leonards</b> | <b>SL035139</b> |

|                                                                                                                        |                                                                                                                                                                                                                   |              |                   |              |                |                    |                 |
|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| Breakdown                                                                                                              | non-starter                                                                                                                                                                                                       |              |                   |              |                |                    |                 |
| <b>Breakdown</b>                                                                                                       | <b>03/12/2021</b>                                                                                                                                                                                                 | <b>14:26</b> | <b>06/12/2021</b> | <b>09:00</b> | <b>252,800</b> | <b>St Leonards</b> | <b>SL035145</b> |
| 31 Battery Chassis Breakdown                                                                                           | Replace 019 battery<br>battery low charge                                                                                                                                                                         |              |                   |              |                |                    |                 |
| <b>MOT EXPIRES</b>                                                                                                     | <b>30/12/2021</b>                                                                                                                                                                                                 | <b>07:00</b> | <b>30/12/2021</b> | <b>16:00</b> | <b>254,764</b> | <b>St Leonards</b> | <b>SL035332</b> |
| MOT                                                                                                                    |                                                                                                                                                                                                                   |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>                                                                                                | <b>07/01/2022</b>                                                                                                                                                                                                 | <b>12:00</b> | <b>11/01/2022</b> | <b>12:27</b> | <b>254,985</b> | <b>St Leonards</b> | <b>SL035416</b> |
| 02 Cab Assembly 1<br>31 Charging System<br>45 Engine 1<br>55 Tail Lift<br>18 Wheels Check Torques<br>Safety Inspection | Torch missi8ng. Replaced.<br>Replace alternator - Jack Franklin - PCS<br>EGR pipe split. Replaced cooler.<br>Guide block adrift. Resecured.<br>Checked.<br>Carried out inspection.                                |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>                                                                                              | <b>11/01/2022</b>                                                                                                                                                                                                 | <b>12:25</b> | <b>12/01/2022</b> | <b>09:49</b> | <b>254,991</b> | <b>St Leonards</b> | <b>SL035441</b> |
| Vehicle Deep Clean                                                                                                     | Vehicle Deep Clean                                                                                                                                                                                                |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>                                                                                                | <b>03/02/2022</b>                                                                                                                                                                                                 | <b>08:30</b> | <b>03/02/2022</b> | <b>09:52</b> | <b>256,731</b> | <b>St Leonards</b> | <b>SL035669</b> |
| 02 Cab Assembly 1<br>02 Windscreen Wipers<br>34 Lights<br>45 Engine 1<br>45 Engine 2<br>86 Door Lock                   | Cab microphone insecure<br>Washer pipe split<br>Lighting System O/S side light blown<br>Engine Amber EML on...Nox sensor ordered<br>Boost seals leaking/making niose<br>Central locking inop....Key batt replaced |              |                   |              |                |                    |                 |
|                                                                                                                        |                                                                                                                                                                                                                   |              |                   |              |                | Monitoring         |                 |

|                                      |                                                    |              |                   |              |                |                     |                 |
|--------------------------------------|----------------------------------------------------|--------------|-------------------|--------------|----------------|---------------------|-----------------|
| <b>Breakdown</b>                     | <b>22/02/2022</b>                                  | <b>06:09</b> | <b>22/02/2022</b> | <b>08:04</b> | <b>257,100</b> | <b>St Leonards</b>  | <b>SL035803</b> |
| Breakdown                            | deisel fumes in cab                                |              |                   |              |                |                     |                 |
| <b>Vehicle Deep Clean</b>            | <b>28/02/2022</b>                                  | <b>08:32</b> | <b>28/02/2022</b> | <b>11:00</b> | <b>258,742</b> | <b>St Leonards</b>  | <b>SL035866</b> |
| Vehicle Deep Clean                   | Vehicle Deep Clean                                 |              |                   |              |                |                     |                 |
| <b>SAFETY INSPECTION</b>             | <b>07/03/2022</b>                                  | <b>07:00</b> | <b>08/03/2022</b> | <b>07:00</b> | <b>258,749</b> | <b>St Leonards</b>  | <b>SL035914</b> |
| 18 Wheels Check Torques              | Checked.                                           |              |                   |              |                |                     |                 |
| Safety Inspection                    | Carried out inspection.                            |              |                   |              |                |                     |                 |
| 45 Engine 1                          | Engine Amber EML on...Nox sensor ordered.Replaced. |              |                   |              |                |                     |                 |
| 45 Engine 2                          | Engine exhaust fumes, engine management light      |              |                   |              |                |                     |                 |
| UB Fire Supp 12mts Service           | Service of fire supression system. Done.           |              |                   |              |                |                     |                 |
| Brake Fluid Change                   | Brake Fluid Change                                 |              |                   |              |                |                     |                 |
| Tail Lift Inspection                 | Done.                                              |              |                   |              |                |                     |                 |
| 01 Heating 1                         | Heater exhaust split. Replaced.                    |              |                   |              |                |                     |                 |
| <b>02 Pipeline Annual Inspection</b> | <b>07/03/2022</b>                                  | <b>13:51</b> | <b>07/03/2022</b> | <b>13:52</b> | <b>258,749</b> | <b>MDT Ferndown</b> | <b>TF001834</b> |
| 02 Pipeline Annual Inspection        | Annual Inspection and Pressure Test                |              |                   |              |                |                     |                 |
| <b>ACCIDENT</b>                      | <b>04/04/2022</b>                                  | <b>10:00</b> | <b>11/04/2022</b> | <b>09:00</b> | <b>261,359</b> | <b>St Leonards</b>  | <b>SL036127</b> |
| 71 Body Exterior Roof                | Skylight smashed                                   |              |                   |              |                |                     |                 |
| 85 Body Interior Roof                | Fit blast film                                     |              |                   |              |                |                     |                 |
|                                      | Monitoring                                         |              |                   |              |                |                     |                 |
| <b>SAFETY INSPECTION</b>             | <b>03/05/2022</b>                                  | <b>08:00</b> | <b>03/05/2022</b> | <b>08:00</b> | <b>263,306</b> | <b>St Leonards</b>  | <b>SL036381</b> |
| 18 Wheels Check Torques              |                                                    |              |                   |              |                |                     |                 |
| Safety Inspection                    |                                                    |              |                   |              |                |                     |                 |
| <b>SAFETY INSPECTION</b>             | <b>03/05/2022</b>                                  | <b>08:00</b> | <b>05/05/2022</b> | <b>12:00</b> | <b>263,306</b> | <b>St Leonards</b>  | <b>SL036382</b> |

|                               |                                                |              |                   |              |                |                    |                 |
|-------------------------------|------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| 18 Wheels Check Torques       |                                                |              |                   |              |                |                    |                 |
| Safety Inspection             |                                                |              |                   |              |                |                    |                 |
| 85 Body Interior Roof         | Fit blast film                                 |              |                   |              |                | Monitoring         |                 |
| Annual Air Con Service        | Annual Air Condition Service                   |              |                   |              |                |                    |                 |
| Replace Handbrake Cables      | Replace Handbrake Cables                       |              |                   |              |                |                    |                 |
| Wheel Hub Flanges Replacement | Front flanges changed - Rears to do - NO PARTS |              |                   |              |                | Monitoring         |                 |
| Tail Lift Inspection          |                                                |              |                   |              |                |                    |                 |
| 02 Windscreen Wipers          | Replaced                                       |              |                   |              |                |                    |                 |
| 34 Lights                     | Replace n/s/r ind lamp and stop/tail lamp      |              |                   |              |                |                    |                 |
| Pollen Filter Change          | Pollen Filter Change                           |              |                   |              |                |                    |                 |
| 02 Cab Ass Fire Extinguisher  | Replaced x2                                    |              |                   |              |                |                    |                 |
| 41 Turbo                      | Replace Turbo seal                             |              |                   |              |                |                    |                 |
| 16 Suspension 1               | Replace rear spring buffer pads x4             |              |                   |              |                |                    |                 |
| 24 Driveshaft 1               | Replace prop centre bearing                    |              |                   |              |                |                    |                 |
| 42 Coolant System             | Replace header tank                            |              |                   |              |                |                    |                 |
| 13 Brakes 1                   | Replace front pads sensor wires                |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>     | <b>06/05/2022</b>                              | <b>05:19</b> | <b>06/05/2022</b> | <b>05:21</b> | <b>263,309</b> | <b>St Leonards</b> | <b>SL036430</b> |
| Vehicle Deep Clean            | Vehicle Deep Clean                             |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>     | <b>06/05/2022</b>                              | <b>05:21</b> | <b>06/05/2022</b> | <b>10:00</b> | <b>263,309</b> | <b>St Leonards</b> | <b>SL036431</b> |
| Vehicle Deep Clean            | Vehicle Deep Clean                             |              |                   |              |                |                    |                 |
| <b>ACCIDENT</b>               | <b>11/05/2022</b>                              | <b>20:06</b> | <b>12/05/2022</b> | <b>13:45</b> | <b>263,325</b> | <b>St Leonards</b> | <b>SL036524</b> |
| Breakdown                     | BLUE LIGHT DRIVERS SIDE REAR SMASHED           |              |                   |              |                |                    |                 |
| 34 Emergency Lights           | Replace o/s/r side blue LED                    |              |                   |              |                |                    |                 |
| <b>Breakdown</b>              | <b>27/05/2022</b>                              | <b>17:19</b> | <b>30/05/2022</b> | <b>06:30</b> | <b>264,467</b> | <b>St Leonards</b> | <b>SL036706</b> |
| Breakdown                     | Missing Aerial ?                               |              |                   |              |                | Monitoring         |                 |
| <b>Breakdown</b>              | <b>10/06/2022</b>                              | <b>04:40</b> | <b>10/06/2022</b> | <b>11:00</b> | <b>265,818</b> | <b>St Leonards</b> | <b>SL036796</b> |
| Breakdown                     | Diesel Leak                                    |              |                   |              |                |                    |                 |

44 Fuel System 1                      Reported fuel leak - No fault found

**SAFETY INSPECTION      20/06/2022      12:43              22/06/2022      06:16              266,377      St Leonards              SL036874**

18 Wheels Check Torques  
 Safety Inspection  
 85 Body Interior Roof              Fit blast film  
 Wheel Hub Flanges Replacement Front flanges changed - Rears to do - NO PARTS  
 Breakdown              Missing Aerial ?  
 17 Tyres              Fronts low  
 16 Suspension 1              Rear ARBs worn  
 52 Electrical Aux              CCTV inop  
 02 Cab Assembly 1              Brake pedal rubber split  
 86 Sliding Door              cover damaged  
 02 Cab Assembly 2              Window switch u/s  
 71 Body Exterior 1              tail lift guides damaged

**Vehicle Deep Clean      22/06/2022      07:56              22/06/2022      15:00              266,377      St Leonards              SL036894**

Vehicle Deep Clean              Vehicle Deep Clean

**Breakdown              02/07/2022      04:08              04/07/2022      06:00              267,149      St Leonards              SL036978**

Breakdown              Fan Belt Slipping                                              Monitoring

**Breakdown              08/07/2022      18:12              11/07/2022      06:00              267,776      St Leonards              SL037067**

Breakdown              Tail lift will not deploy                                              Monitoring

**Breakdown              14/07/2022      18:23              15/07/2022      09:43              268,363      St Leonards              SL037115**

Breakdown              prong bent

|                                                                                                                                                                            |                                                                                                                                                                                                                                                                                                  |              |                   |              |                |                    |                 |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Breakdown</b>                                                                                                                                                           | <b>30/07/2022</b>                                                                                                                                                                                                                                                                                | <b>00:16</b> | <b>01/08/2022</b> | <b>06:00</b> | <b>268,750</b> | <b>St Leonards</b> | <b>SL037217</b> |
| Breakdown                                                                                                                                                                  | Noisy                                                                                                                                                                                                                                                                                            |              |                   |              |                | Monitoring         |                 |
| <b>Unplanned Repair</b>                                                                                                                                                    | <b>12/08/2022</b>                                                                                                                                                                                                                                                                                | <b>07:00</b> | <b>12/08/2022</b> | <b>15:00</b> | <b>271,595</b> | <b>St Leonards</b> | <b>SL037312</b> |
| 32 Starting System 1                                                                                                                                                       | Non start                                                                                                                                                                                                                                                                                        |              |                   |              |                |                    |                 |
| <b>ACCIDENT</b>                                                                                                                                                            | <b>16/08/2022</b>                                                                                                                                                                                                                                                                                | <b>17:11</b> | <b>18/08/2022</b> | <b>12:45</b> | <b>271,994</b> | <b>St Leonards</b> | <b>SL037327</b> |
| Breakdown<br>55 Tail Lift                                                                                                                                                  | Ramp sensor plate bent back<br>Straighten and adjust tail lift sensor bracket and end plate.                                                                                                                                                                                                     |              |                   |              |                | Monitoring         |                 |
| <b>Vehicle Deep Clean</b>                                                                                                                                                  | <b>08/09/2022</b>                                                                                                                                                                                                                                                                                | <b>11:30</b> | <b>08/09/2022</b> | <b>11:33</b> | <b>273,203</b> | <b>St Leonards</b> | <b>SL037475</b> |
| Vehicle Deep Clean                                                                                                                                                         | Vehicle Deep Clean                                                                                                                                                                                                                                                                               |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>                                                                                                                                                  | <b>08/09/2022</b>                                                                                                                                                                                                                                                                                | <b>11:33</b> | <b>09/09/2022</b> | <b>08:00</b> | <b>273,203</b> | <b>St Leonards</b> | <b>SL037476</b> |
| Vehicle Deep Clean                                                                                                                                                         | Vehicle Deep Clean                                                                                                                                                                                                                                                                               |              |                   |              |                |                    |                 |
| <b>SAFETY INSPECTION</b>                                                                                                                                                   | <b>08/09/2022</b>                                                                                                                                                                                                                                                                                | <b>13:30</b> | <b>08/09/2022</b> | <b>13:30</b> | <b>273,203</b> | <b>St Leonards</b> | <b>SL037478</b> |
| 18 Wheels Check Torques<br>Safety Inspection                                                                                                                               |                                                                                                                                                                                                                                                                                                  |              |                   |              |                |                    |                 |
| <b>SAFETY INSPECTION</b>                                                                                                                                                   | <b>08/09/2022</b>                                                                                                                                                                                                                                                                                | <b>13:30</b> | <b>13/09/2022</b> | <b>15:00</b> | <b>273,203</b> | <b>St Leonards</b> | <b>SL037479</b> |
| 18 Wheels Check Torques<br>Safety Inspection<br>Breakdown<br>89 Seats<br>13 Brakes 1<br>45 Engine 1<br>UB Fire Supp 6mts Service<br>Tail Lift Inspection<br>44 Add Ad Blue | Checked<br>Checked<br>Ramp sensor plate bent back No fault found.<br>Body Interior sallon seat not locking into Position<br>Brakes squeeky. Replace F/Disc & Pads.<br>Engine Amber ! Fault found to EGR Carbon . Clean out unit.<br>UB Fire Supp 6mts Service<br>Inspected.<br>Top up unit. 9.7L |              |                   |              |                |                    |                 |

|                           |                                                                                 |            |
|---------------------------|---------------------------------------------------------------------------------|------------|
| 17 Tyres                  | Replace N/S/R Tyre. Clean hubs. Fit new Valve extentions                        |            |
| 52 Electrical Aux         | Siran noy working. Fault found to speaker unit.                                 |            |
| 34 Emergency Light System | O/S/F upper light unit not working. Fault found to light unit. Replace unit.    |            |
| 56 Comms Equipment        | Replace damaged Mic                                                             |            |
| 34 Emergency Lights       | Replace damaged 240v L.E.D Display lights.                                      |            |
| 86 Doors                  | R/Doors                                                                         |            |
| 89 Seatbelts              | Repair saloon seatbelts.                                                        |            |
| 45 Engine 2               | Oil leak found at reat main bearing oil seal. Awaiting confermation to proceed. | Monitoring |

|                         |                   |              |                   |              |                |                    |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Unplanned Repair</b> | <b>07/10/2022</b> | <b>06:00</b> | <b>07/10/2022</b> | <b>15:00</b> | <b>274,495</b> | <b>St Leonards</b> | <b>SL037748</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                      |                 |
|----------------------|-----------------|
| 31 Charging System   | Charging fault  |
| 32 Starting System 1 | Non start       |
| 34 Lights            | Indicators inop |

|                  |                   |              |                   |              |                |                    |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Breakdown</b> | <b>01/11/2022</b> | <b>17:52</b> | <b>02/11/2022</b> | <b>06:30</b> | <b>276,500</b> | <b>St Leonards</b> | <b>SL038004</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|           |                     |            |
|-----------|---------------------|------------|
| Breakdown | heating not working | Monitoring |
|-----------|---------------------|------------|

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>08/12/2022</b> | <b>08:38</b> | <b>08/12/2022</b> | <b>08:39</b> | <b>280,070</b> | <b>St Leonards</b> | <b>SL038379</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                         |  |
|-------------------------|--|
| 18 Wheels Check Torques |  |
| Safety Inspection       |  |

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>08/12/2022</b> | <b>08:40</b> | <b>14/12/2022</b> | <b>14:00</b> | <b>280,070</b> | <b>St Leonards</b> | <b>SL038380</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                            |                                                             |            |
|----------------------------|-------------------------------------------------------------|------------|
| 18 Wheels Check Torques    | Checked                                                     |            |
| Safety Inspection          | Unit checked .And is Operational at time of Inspection.     |            |
| Breakdown                  | heating not working. Service Req. Now working.              |            |
| 31 Charging System Battery | Pin Damaged. Repaired                                       |            |
| Annual Heater Service      | Annual Heater Service. Serviced                             |            |
| Tail Lift Inspection       | Rust found on Tail lift but operational at time of service. | Monitoring |
| Engine Change Oil & Filter | Oil & Filter Replaced.                                      |            |
| MOT                        | Booked @ Ferndown comm,s on 13/12/2022.                     |            |
| 02 Windscreen Wipers       | Replace cap Clean out bottle                                |            |
| 01 Air Conditioning 1      | Clean out intake box Replace Filter                         |            |
| 45 Engine Ad Blue          | Replace damaged filler pipes & Top up unit.                 |            |

|                            |                                                                               |            |
|----------------------------|-------------------------------------------------------------------------------|------------|
| 52 Electrical Aux          | Replavce damaged O/S Window switch                                            |            |
| 03 Instruments & Sensors 1 | Repair damaged say nav braketts & Support frame                               |            |
| 34 Lights                  | Replace N/S/F indecator bulb                                                  |            |
| 16 Suspension 1            | Replace both F/Lower arm due to excessive play.                               |            |
| 16 Suspension 2            | Replace both F/Struts due to excessive side play.                             |            |
| 17 Tyres Replace           | Replace 3 R/Tyres. 1 under 4.5 2 Damaged.                                     |            |
| 45 Engine 1                | Oil leak found to oil filler neck . Replace filler neck.                      |            |
| 54 Horns                   | Manufacturers Horn has been noted to be faulty. No fault found @ time of test | Monitoring |
| 71 Body Exterior 1         | Bodywork shows to be in poor conditon.                                        | Monitoring |
| 85 Body Interior 1         | Replace saloon cupboard                                                       |            |

|                           |                                                  |              |                   |              |                |                    |                 |
|---------------------------|--------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>14/12/2022</b>                                | <b>10:36</b> | <b>14/12/2022</b> | <b>10:38</b> | <b>280,070</b> | <b>St Leonards</b> | <b>SL038461</b> |
| Vehicle Deep Clean        | Vehicle Deep Clean                               |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b> | <b>14/12/2022</b>                                | <b>10:38</b> | <b>14/12/2022</b> | <b>10:40</b> | <b>280,070</b> | <b>St Leonards</b> | <b>SL038462</b> |
| Vehicle Deep Clean        | Vehicle Deep Clean                               |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b> | <b>14/12/2022</b>                                | <b>10:40</b> | <b>15/12/2022</b> | <b>11:30</b> | <b>280,070</b> | <b>St Leonards</b> | <b>SL038463</b> |
| Vehicle Deep Clean        | Vehicle Deep Clean                               |              |                   |              |                |                    |                 |
| <b>Breakdown</b>          | <b>24/01/2023</b>                                | <b>04:31</b> | <b>24/01/2023</b> | <b>05:05</b> | <b>283,770</b> | <b>St Leonards</b> | <b>SL038886</b> |
| Breakdown                 | Won't go into gear                               |              |                   |              |                |                    |                 |
| <b>Breakdown</b>          | <b>24/01/2023</b>                                | <b>04:44</b> | <b>24/01/2023</b> | <b>05:05</b> | <b>283,770</b> | <b>St Leonards</b> | <b>SL038887</b> |
| Breakdown                 | No Lights/multiple malfunctions                  |              |                   |              |                |                    |                 |
| <b>Breakdown</b>          | <b>24/01/2023</b>                                | <b>08:10</b> | <b>24/01/2023</b> | <b>13:00</b> | <b>283,741</b> | <b>St Leonards</b> | <b>SL038891</b> |
| Breakdown                 | non start , aux elcs not working , not unlocking |              |                   |              |                |                    |                 |
| 52 Electrical Aux         | Replace key, test ok.                            |              |                   |              |                |                    |                 |



|                                                     |                                                                                                                                                                                                |              |                   |              |                |                     |                 |
|-----------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|---------------------|-----------------|
| <b>Unplanned Repair</b>                             | <b>24/02/2023</b>                                                                                                                                                                              | <b>08:30</b> | <b>24/02/2023</b> | <b>10:00</b> | <b>286,524</b> | <b>St Leonards</b>  | <b>SL039200</b> |
| 31 Battery Chassis<br>56 Comms Power Failure        | Fit Chassis battery<br>Reset MDT                                                                                                                                                               |              |                   |              |                |                     |                 |
| <b>Breakdown</b>                                    | <b>05/03/2023</b>                                                                                                                                                                              | <b>04:47</b> | <b>06/03/2023</b> | <b>07:48</b> | <b>287,148</b> | <b>St Leonards</b>  | <b>SL039283</b> |
| Breakdown<br>86 Sliding Door                        | Sidedoor opening easily under a little pressure<br>Side door opening while driving (see notes)                                                                                                 |              |                   |              |                |                     |                 |
| <b>O2 Pipeline Annual Inspection</b>                | <b>10/03/2023</b>                                                                                                                                                                              | <b>13:43</b> | <b>11/03/2023</b> | <b>13:45</b> | <b>287,663</b> | <b>MDT Ferndown</b> | <b>TF002562</b> |
| 02 Pipeline Annual Inspection                       | Annual Inspection and Pressure Test - No faults found.                                                                                                                                         |              |                   |              |                |                     |                 |
| <b>Unplanned Repair</b>                             | <b>13/03/2023</b>                                                                                                                                                                              | <b>14:38</b> | <b>14/03/2023</b> | <b>11:30</b> | <b>287,670</b> | <b>St Leonards</b>  | <b>SL039361</b> |
| 43 Exhaust System 1<br>34 Emergency Lights          | Exhaust blow. (see notes)<br>os front wing blue light insecure. resecured to wing.                                                                                                             |              |                   |              |                |                     |                 |
| <b>BREAKDOWN</b>                                    | <b>22/03/2023</b>                                                                                                                                                                              | <b>05:26</b> | <b>22/03/2023</b> | <b>09:45</b> | <b>288,060</b> | <b>St Leonards</b>  | <b>SL039438</b> |
| 86 Sliding Door                                     | Doors side door handle has snapped off                                                                                                                                                         |              |                   |              |                |                     |                 |
| <b>Breakdown</b>                                    | <b>30/03/2023</b>                                                                                                                                                                              | <b>14:53</b> | <b>30/03/2023</b> | <b>16:24</b> | <b>290,077</b> | <b>St Leonards</b>  | <b>SL039538</b> |
| Breakdown                                           | Door stay                                                                                                                                                                                      |              |                   |              |                |                     |                 |
| <b>Unplanned Repair</b>                             | <b>02/04/2023</b>                                                                                                                                                                              | <b>06:00</b> | <b>02/04/2023</b> | <b>07:30</b> | <b>290,305</b> | <b>St Leonards</b>  | <b>SL039565</b> |
| 56 Comms Equipment<br>86 Doors Rear<br>87 Stretcher | MDT Failure/Issue not tracking on mdt. tested comms battery, ok, and charging ok<br>Rear door stay snapped off. drilled out and replace broken bolt on osr.<br>Replace missing stretcher strap |              |                   |              |                |                     |                 |

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>06/04/2023</b> | <b>06:00</b> | <b>06/04/2023</b> | <b>14:41</b> | <b>290,971</b> | <b>St Leonards</b> | <b>SL039605</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>07/04/2023</b> | <b>09:00</b> | <b>10/04/2023</b> | <b>08:10</b> | <b>290,971</b> | <b>St Leonards</b> | <b>SL039627</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                              |                                                                       |
|------------------------------|-----------------------------------------------------------------------|
| 18 Wheels Check Torques      |                                                                       |
| Safety Inspection            |                                                                       |
| Tail Lift Inspection         | Rust found on Tail lift but operational at time of service.           |
| 54 Horns                     | Manufacturers Horn has been noted to be faulty. NFF                   |
| 71 Body Exterior 1           | Bodywork shows to be in poor conditon. NFF                            |
| 02 Cab Ass Fire Extinguisher | Cab and saloon fire extighuishers out of date                         |
| 89 Seats                     | Passenger and drivers seat base badly worn                            |
| 17 Tyres Replace             | Rerplace both front tyres due to being worn                           |
| 56 Comms Equipment           | Rear mic damaged. Replaced                                            |
| 55 Tail Lift                 | Intermittent flickering from tail lift leds. Tilt switch not in stock |
| 86 Sliding Door              | Slats on window stuck shut.                                           |

|            |
|------------|
| Monitoring |
| Monitoring |

|                  |                   |              |                   |              |                |                    |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Breakdown</b> | <b>17/05/2023</b> | <b>09:13</b> | <b>17/05/2023</b> | <b>10:30</b> | <b>293,795</b> | <b>St Leonards</b> | <b>SL040158</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|           |                                                                                  |
|-----------|----------------------------------------------------------------------------------|
| Breakdown | central locking                                                                  |
| 86 Doors  | Central locking inop - New key on order. Crew to manually lock until key arrives |

|            |
|------------|
| Monitoring |
|------------|

|                 |                   |              |                   |              |                |                    |                 |
|-----------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>ACCIDENT</b> | <b>17/05/2023</b> | <b>13:51</b> | <b>22/05/2023</b> | <b>12:39</b> | <b>293,900</b> | <b>St Leonards</b> | <b>SL040161</b> |
|-----------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                             |                     |
|-----------------------------|---------------------|
| Breakdown                   | NS blue lights      |
| 71 Body Exterior Acc Repair | Accident damage n/s |

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>20/05/2023</b> | <b>06:00</b> | <b>21/05/2023</b> | <b>21:05</b> | <b>293,845</b> | <b>St Leonards</b> | <b>SL040209</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                         |                                                                       |
|-------------------------|-----------------------------------------------------------------------|
| 18 Wheels Check Torques |                                                                       |
| Safety Inspection       |                                                                       |
| 55 Tail Lift            | Intermittent flickering from tail lift leds. Tilt switch not in stock |
| 86 Sliding Door         | Slats on window stuck shut.                                           |
| 86 Doors                | Central locking inop - Keys replaced                                  |
| Tail Lift Inspection    |                                                                       |
| 85 Body Interior 1      | Fit P clips for AVP                                                   |
| 34 Lights               | Side door step light inop                                             |

|                             |                                                           |              |                   |              |                |                    |                 |
|-----------------------------|-----------------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b>   | <b>22/05/2023</b>                                         | <b>07:00</b> | <b>22/05/2023</b> | <b>13:07</b> | <b>293,845</b> | <b>St Leonards</b> | <b>SL040224</b> |
| Vehicle Deep Clean          | Vehicle Deep Clean                                        |              |                   |              |                |                    |                 |
| <b>BREAKDOWN</b>            | <b>31/05/2023</b>                                         | <b>11:29</b> | <b>31/05/2023</b> | <b>12:21</b> | <b>294,583</b> | <b>St Leonards</b> | <b>SL040352</b> |
| 31 Battery Comms            | Power fail to comms                                       |              |                   |              |                |                    |                 |
| <b>Breakdown</b>            | <b>17/06/2023</b>                                         | <b>17:36</b> | <b>18/06/2023</b> | <b>04:54</b> | <b>296,004</b> | <b>St Leonards</b> | <b>SL040613</b> |
| Breakdown                   | Tail lift stuck                                           |              |                   |              |                |                    |                 |
| <b>SAFETY INSPECTION</b>    | <b>01/07/2023</b>                                         | <b>14:33</b> | <b>03/07/2023</b> | <b>11:53</b> | <b>296,121</b> | <b>St Leonards</b> | <b>SL040817</b> |
| 18 Wheels Check Torques     |                                                           |              |                   |              |                |                    |                 |
| Safety Inspection           |                                                           |              |                   |              |                |                    |                 |
| 71 Body External Steps      | OTHER SIDE STEP WILL NOT STAY IN                          |              |                   |              |                |                    |                 |
| 71 Body Exterior Acc Repair | Doors n/s door lip bent out of shape                      |              |                   |              |                |                    |                 |
| UB Fire Supp 12mts Service  | Service of fire supression system                         |              |                   |              |                |                    |                 |
| UB Fire Supp 6mts Service   | UB Fire Supp 6mts Service                                 |              |                   |              |                |                    |                 |
| Annual Air Con Service      | Annual Air Condition Service                              |              |                   |              |                |                    |                 |
| Replace Handbrake Cables    | Replace Handbrake Cables                                  |              |                   |              |                |                    |                 |
| Pollen Filter Change        | Pollen Filter Change                                      |              |                   |              |                |                    |                 |
| Engine Change Oil & Filter  |                                                           |              |                   |              |                |                    |                 |
| 13 Brakes 1                 | Brakes poor and excess travel.                            |              |                   |              |                |                    |                 |
| 86 Doors Rear               | Excessive wear in upper door striker plate                |              |                   |              |                |                    |                 |
| Camera Installation         | CCTV showing fault                                        |              |                   |              |                |                    |                 |
| 13 Brakes 2                 | Talma not working. control box full of water and corroded |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>   | <b>04/07/2023</b>                                         | <b>14:00</b> | <b>05/07/2023</b> | <b>14:26</b> | <b>296,121</b> | <b>St Leonards</b> | <b>SL040856</b> |
| Vehicle Deep Clean          | Vehicle Deep Clean                                        |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>     | <b>07/07/2023</b>                                         | <b>17:48</b> | <b>07/07/2023</b> | <b>17:51</b> | <b>297,422</b> | <b>St Leonards</b> | <b>SL040910</b> |

|                           |                                             |
|---------------------------|---------------------------------------------|
| 55 Tail Lift              | Ramp/Lift/Tail Hoist tail lift wont go down |
| 87 Stretcher              | Wont raise                                  |
| Replace Vehicle Fuel Card | Replace Vehicle Fuel Card                   |

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>10/08/2023</b> | <b>06:00</b> | <b>10/08/2023</b> | <b>13:00</b> | <b>299,260</b> | <b>St Leonards</b> | <b>SL041468</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>12/08/2023</b> | <b>06:00</b> | <b>12/08/2023</b> | <b>14:00</b> | <b>299,260</b> | <b>St Leonards</b> | <b>SL041498</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                         |                                 |
|-------------------------|---------------------------------|
| 18 Wheels Check Torques |                                 |
| Safety Inspection       |                                 |
| Air Filter Change       | Air Filter Change               |
| Fuel Filter Change      | Change Fuel Filter              |
| Tail Lift Inspection    |                                 |
| 15 Steering 1           | Steering wheel u/s              |
| 13 Brake Pads           | Fronts low                      |
| 16 Suspension 1         | ARBs worn 2x                    |
| 71 Body Exterior 1      | Rear flap loose                 |
| 86 Door Seals           | Rear door seals u/s             |
| 34 Lights               | side light out                  |
| 02 Windscreen Wipers    | Blades poor washer jets blocked |

|                         |                   |              |                   |              |                |                    |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Unplanned Repair</b> | <b>18/09/2023</b> | <b>10:00</b> | <b>29/09/2023</b> | <b>04:39</b> | <b>301,537</b> | <b>St Leonards</b> | <b>SL041976</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|               |                                             |
|---------------|---------------------------------------------|
| 86 Doors Rear | Rear door hinges worn - Autospray to repair |
|---------------|---------------------------------------------|

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>29/09/2023</b> | <b>05:50</b> | <b>29/09/2023</b> | <b>12:15</b> | <b>301,528</b> | <b>St Leonards</b> | <b>SL042127</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>30/09/2023</b> | <b>06:30</b> | <b>01/10/2023</b> | <b>10:26</b> | <b>301,537</b> | <b>St Leonards</b> | <b>SL042143</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                         |                                          |
|-------------------------|------------------------------------------|
| 18 Wheels Check Torques | Checked.                                 |
| Safety Inspection       | Carried out inspection.                  |
| 56 Comms Equipment      | Radio & Comm System vehicle not tracking |
| 56 Comms Power Failure  | Comms Power Check Not tracking           |

|                      |                                                       |            |
|----------------------|-------------------------------------------------------|------------|
| 86 Doors Rear        | DOORS BACK DOOR HAS DROPPED                           | Monitoring |
| Tail Lift Inspection | Done.                                                 |            |
| Recall Notification  | Mercedes airbag recall. Done.                         |            |
| 15 Steering 1        | N/S track-rod end worn. Replaced.                     |            |
| 02 Cab Assembly 1    | Torch n/w. Replaced.                                  | Monitoring |
| 02 Cab Assembly 2    | Passenger window switch broken. Replaced.             |            |
| 55 Tail Lift         | O/S gate stuck down, LED's n/w. Rewired and repaired. |            |

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>02/11/2023</b> | <b>11:23</b> | <b>03/11/2023</b> | <b>11:00</b> | <b>304,761</b> | <b>St Leonards</b> | <b>SL042629</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>03/11/2023</b> | <b>08:00</b> | <b>03/11/2023</b> | <b>13:00</b> | <b>304,761</b> | <b>St Leonards</b> | <b>SL042639</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                                |                                                            |            |
|--------------------------------|------------------------------------------------------------|------------|
| 18 Wheels Check Torques        |                                                            |            |
| Safety Inspection              |                                                            |            |
| 86 Doors Rear                  | DOORS BACK DOOR HAS DROPPED                                | Monitoring |
| 02 Cab Assembly 1              | Torch n/w. Replaced.                                       |            |
| Tail Lift 12M Service & Weight | Tail Lift 12M Service & Weight - Done by SWL               |            |
| 27 Transmission Automatic      | Rear gearbox mount worn. Replaced                          |            |
| 34 Lights Bulb Replacement     | N/S/F DRL not working. Replaced                            |            |
| 13 Brakes 1                    | Handbrake reading poor. Adjusted shoes, reading now better |            |

|                         |                   |              |                   |              |                |                    |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Unplanned Repair</b> | <b>20/11/2023</b> | <b>07:20</b> | <b>20/11/2023</b> | <b>07:35</b> | <b>304,965</b> | <b>St Leonards</b> | <b>SL042855</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|           |                      |
|-----------|----------------------|
| 34 Lights | DRL out              |
| 18 Wheels | Nut markers missing. |

|                  |                   |              |                   |              |                |                    |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Breakdown</b> | <b>27/11/2023</b> | <b>07:40</b> | <b>27/11/2023</b> | <b>08:52</b> | <b>307,655</b> | <b>St Leonards</b> | <b>SL042943</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|           |                                   |
|-----------|-----------------------------------|
| Breakdown | Headlights out , renew 2 x bulbs. |
|-----------|-----------------------------------|

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>13/12/2023</b> | <b>12:00</b> | <b>15/12/2023</b> | <b>15:15</b> | <b>309,755</b> | <b>St Leonards</b> | <b>SL043182</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                         |
|-------------------------|
| 18 Wheels Check Torques |
|-------------------------|

|                                |                   |              |                                                                                |              |                |                    |                 |
|--------------------------------|-------------------|--------------|--------------------------------------------------------------------------------|--------------|----------------|--------------------|-----------------|
| Safety Inspection              |                   |              |                                                                                |              |                |                    |                 |
| 86 Doors Rear                  |                   |              | Rear door hinges worn.                                                         |              |                | Monitoring         |                 |
| Auto G/box Oil & Filter Change |                   |              | Auto G/box Oil & Filter Change                                                 |              |                |                    |                 |
| Annual Heater Service          |                   |              | Annual Heater Service                                                          |              |                |                    |                 |
| MOT                            |                   |              |                                                                                |              |                |                    |                 |
| 52 Electrical Aux              |                   |              | Mangar charger u/s. replaced charger.                                          |              |                |                    |                 |
| 85 Body Interior 1             |                   |              | x2 Saloon interior locker door hinges loose. resecured.                        |              |                |                    |                 |
| 13 Handbrake                   |                   |              | Adjusted shoes and cables.                                                     |              |                |                    |                 |
| 34 Lights                      |                   |              | NSR Fog light inop and osr reverse inop. replaced both.                        |              |                |                    |                 |
| 71 Body Exterior 1             |                   |              | Rear bridge plate guide resecured to body.                                     |              |                |                    |                 |
| 16 Suspension 1                |                   |              | Rear anti roll bar upper drop link bushes worn. replaced x2 bushes.            |              |                |                    |                 |
| 13 Brakes 1                    |                   |              | Both front brake caliper sliders seized. replaced slider kit.                  |              |                |                    |                 |
| 13 Brakes 2                    |                   |              | NSR Slider seized. replaced pin kit.                                           |              |                |                    |                 |
| 55 Tail Lift                   |                   |              | O/S Lift ram hose perished. replaced hose. - magnet bracket corroded. replaced |              |                |                    |                 |
| Tail Lift Inspection           |                   |              |                                                                                |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>      | <b>15/12/2023</b> | <b>06:00</b> | <b>15/12/2023</b>                                                              | <b>12:00</b> | <b>309,755</b> | <b>St Leonards</b> | <b>SL043209</b> |
| Vehicle Deep Clean             |                   |              | Vehicle Deep Clean                                                             |              |                |                    |                 |
| <b>Breakdown</b>               | <b>25/12/2023</b> | <b>07:32</b> | <b>26/12/2023</b>                                                              | <b>05:09</b> | <b>312,500</b> | <b>St Leonards</b> | <b>SL043306</b> |
| Breakdown                      |                   |              | Puncture                                                                       |              |                |                    |                 |
| <b>Breakdown</b>               | <b>03/01/2024</b> | <b>09:26</b> | <b>03/01/2024</b>                                                              | <b>09:54</b> | <b>312,500</b> | <b>St Leonards</b> | <b>SL043442</b> |
| Breakdown                      |                   |              | knocking sound nearside front                                                  |              |                |                    |                 |
| <b>Unplanned Repair</b>        | <b>06/01/2024</b> | <b>06:00</b> | <b>06/01/2024</b>                                                              | <b>08:30</b> | <b>312,693</b> | <b>St Leonards</b> | <b>SL043490</b> |
| 34 Lighting System             |                   |              | OSR Lights u/s. plug on underside damaged & corroded. replaced plug and pins.  |              |                |                    |                 |
| <b>Unplanned Repair</b>        | <b>08/01/2024</b> | <b>12:00</b> | <b>08/01/2024</b>                                                              | <b>17:13</b> | <b>312,760</b> | <b>St Leonards</b> | <b>SL043517</b> |
| 34 Lights                      |                   |              | O/S/R side lights inop                                                         |              |                |                    |                 |

|                         |                   |              |                   |              |                |                    |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Unplanned Repair</b> | <b>11/01/2024</b> | <b>12:00</b> | <b>12/01/2024</b> | <b>11:00</b> | <b>313,000</b> | <b>St Leonards</b> | <b>SL043550</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                                                     |  |  |  |  |  |  |
|--------------------|-----------------------------------------------------|--|--|--|--|--|--|
| 56 Comms Equipment | MDT fault - Error code 14 - Re set comms, test, ok. |  |  |  |  |  |  |
|--------------------|-----------------------------------------------------|--|--|--|--|--|--|

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>24/01/2024</b> | <b>15:23</b> | <b>29/01/2024</b> | <b>11:33</b> | <b>314,364</b> | <b>St Leonards</b> | <b>SL043712</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                                |                                                                 |
|--------------------------------|-----------------------------------------------------------------|
| 18 Wheels Check Torques        | Checked.                                                        |
| Safety Inspection              | Carried out inspection.                                         |
| 86 Doors Rear                  | Rear door hinges worn.                                          |
| 34 Lights                      | Lighting System O/S HEADLIGHT OUT - LOOSE CONNECTION DISCOVERED |
| 56 Comms Power Failure         | Comms Power Check no power going to the MDT.Re-set              |
| Tail Lift 12M Service & Weight | Tail Lift 12M Service & Weight                                  |
| Tail Lift Inspection           | Done.                                                           |
| UB Fire Supp 6mts Service      | UB Fire Supp 6mts Service                                       |
| 17 Tyres Replace               | N/S/F tyre low tread. Replaced .                                |
| 34 Lighting System             | O/S running light backing cap missing. Find & fitted 2nd hand.  |
| 34 Lights Bulb Replacement     | N/S headlight no pattern. Replaced bulb.                        |
| 02 Cab Assembly 1              | Drivers window switch broken. Replaced.                         |
| 02 Cab Assembly 2              | Gear lever boot torn.                                           |
| 31 Charging System             | Auto-eject cover broken. Replaced.                              |
| 86 Door Lock                   | Scoop locker key n/w. Replaced barrel.                          |
| 71 Body External Steps         | Side step not deploying. Straightened and lubbed.               |
| 42 Coolant System              | Anti-freeze low. Drain & topped 4Ltrs.                          |
| 71 Body Exterior 1             | Rear panel/guide blocks u/s.Replaced & 2x number plate lights.  |

Monitoring

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>29/01/2024</b> | <b>07:00</b> | <b>29/01/2024</b> | <b>15:44</b> | <b>314,370</b> | <b>St Leonards</b> | <b>SL043761</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |  |  |  |  |  |  |
|--------------------|--------------------|--|--|--|--|--|--|
| Vehicle Deep Clean | Vehicle Deep Clean |  |  |  |  |  |  |
|--------------------|--------------------|--|--|--|--|--|--|

|                  |                   |              |                   |              |                |                    |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Breakdown</b> | <b>08/02/2024</b> | <b>16:21</b> | <b>09/02/2024</b> | <b>18:00</b> | <b>315,076</b> | <b>St Leonards</b> | <b>SL043899</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|           |                                                             |  |  |  |  |  |  |
|-----------|-------------------------------------------------------------|--|--|--|--|--|--|
| Breakdown | MDT not powering back on after powering off - SSS to repair |  |  |  |  |  |  |
|-----------|-------------------------------------------------------------|--|--|--|--|--|--|

|                         |                   |              |                   |              |                |                    |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Unplanned Repair</b> | <b>22/02/2024</b> | <b>13:45</b> | <b>22/02/2024</b> | <b>14:44</b> | <b>316,528</b> | <b>St Leonards</b> | <b>SL044101</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                                                                                                                                                                                                                                    |                                                                                                                                                                                                                                                                                                        |              |                   |              |                |                     |                 |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|---------------------|-----------------|
| 71 Body External Steps                                                                                                                                                                                                             | Side step not deploying                                                                                                                                                                                                                                                                                |              |                   |              |                |                     |                 |
| <b>Unplanned Repair</b>                                                                                                                                                                                                            | <b>25/02/2024</b>                                                                                                                                                                                                                                                                                      | <b>09:17</b> | <b>25/02/2024</b> | <b>11:54</b> | <b>316,600</b> | <b>St Leonards</b>  | <b>SL044132</b> |
| 56 Comms Equipment                                                                                                                                                                                                                 | MDT fault                                                                                                                                                                                                                                                                                              |              |                   |              |                |                     |                 |
| <b>02 Pipeline Annual Inspection</b>                                                                                                                                                                                               | <b>07/03/2024</b>                                                                                                                                                                                                                                                                                      | <b>12:34</b> | <b>07/03/2024</b> | <b>12:37</b> | <b>317,583</b> | <b>MDT Weymouth</b> | <b>DW001608</b> |
| 02 Pipeline Annual Inspection<br>Med Devices Recall                                                                                                                                                                                | Annual Inspection and Pressure Test<br>airflow + obsoleteat, change for airflow 24 c/w mounting bracket                                                                                                                                                                                                |              |                   |              |                |                     |                 |
| <b>Vehicle Deep Clean</b>                                                                                                                                                                                                          | <b>10/03/2024</b>                                                                                                                                                                                                                                                                                      | <b>09:48</b> | <b>11/03/2024</b> | <b>08:28</b> | <b>317,609</b> | <b>St Leonards</b>  | <b>SL044336</b> |
| Vehicle Deep Clean                                                                                                                                                                                                                 | Vehicle Deep Clean                                                                                                                                                                                                                                                                                     |              |                   |              |                |                     |                 |
| <b>SAFETY INSPECTION</b>                                                                                                                                                                                                           | <b>12/03/2024</b>                                                                                                                                                                                                                                                                                      | <b>06:00</b> | <b>12/03/2024</b> | <b>18:00</b> | <b>317,609</b> | <b>St Leonards</b>  | <b>SL044360</b> |
| 18 Wheels Check Torques<br>Safety Inspection<br>02 Cab Assembly 2<br>56 Comms Equipment<br>55 Tail Lift<br>87 - Stretchers/Chairs/Boards<br>87 Stretcher<br>85 Body Interior 1<br>85 Body Interior 2<br>18 Wheels<br>13 Brake Test | Gear lever boot torn.<br>Comms Power Check MDT wont turn on at all<br>Tail lift inspection<br>Carry chair roll pins loose<br>Stretcher belts in wrong positions<br>Saloon seat N/S/R swivel pin insecure<br>Saloon locker 'BH3' shelf broken<br>N/S/R/I Wheel rim old type (dot - dash) badly corroded |              |                   |              |                |                     |                 |
| <b>Breakdown</b>                                                                                                                                                                                                                   | <b>01/04/2024</b>                                                                                                                                                                                                                                                                                      | <b>21:13</b> | <b>02/04/2024</b> | <b>14:26</b> | <b>318,801</b> | <b>St Leonards</b>  | <b>SL044714</b> |
| Breakdown                                                                                                                                                                                                                          | COOLANT LEVELS WARNING FUMES IN CAB                                                                                                                                                                                                                                                                    |              |                   |              |                |                     |                 |
| <b>Unplanned Repair</b>                                                                                                                                                                                                            | <b>06/04/2024</b>                                                                                                                                                                                                                                                                                      | <b>11:23</b> | <b>07/04/2024</b> | <b>04:40</b> | <b>318,978</b> | <b>St Leonards</b>  | <b>SL044789</b> |



31 Battery Comms  
Travel Time

Battery u/s

**Vehicle Deep Clean**      **18/04/2024**      **07:22**      **19/04/2024**      **08:55**      **320,695**      **St Leonards**      **SL044948**

Vehicle Deep Clean      Vehicle Deep Clean

**SAFETY INSPECTION**      **23/04/2024**      **10:00**      **25/04/2024**      **14:31**      **320,695**      **St Leonards**      **SL045015**

18 Wheels Check Torques  
Safety Inspection  
Engine Change Oil & Filter

34 Lights      Both front foglights damaged. replaced both lamps  
71 Body Exterior 1      Rear body upper blue trim strip insecure. rescured.  
86 Sliding Door      1-Sliding door outer runner assembly worn. replaced. 2-Outer handle resecured  
86 Doors Rear      Rear door inner handle stiff. stripped door and lubricated handle cables.  
55 Tail Lift      Tail lift hand rails repaired, adjusted and lubricated.  
71 Body External Steps      Step runner bushes worn. replaced bushes and lubricated.  
41 Air Intake      Pipe from air box to turbo split and leaking. replaced pipe.  
45 Engine 1      Both belt tensioners worn. replaced  
43 Exhaust System 1      Exhaust tailpipe corroded. replaced tailpipe.  
16 Suspension 1      X2 rear leaf spring buffers split. replaced  
13 Brakes 1      Front brake pads and discs worn. replaced brake kit.  
31 Battery Chassis      Chassis battery leaking acid. replaced battery and cleaned battery box.  
13 Brakes 2      OSR caliper sliders corroded and seized. -replaced pin kit.  
34 Lights Bulb Replacement      O/S wing indicator inop. replaced lamp unit.

**Vehicle Deep Clean**      **29/05/2024**      **07:34**      **29/05/2024**      **12:17**      **322,001**      **St Leonards**      **SL045522**

Vehicle Deep Clean      Vehicle Deep Clean

**SAFETY INSPECTION**      **02/06/2024**      **08:20**      **03/06/2024**      **13:58**      **322,001**      **St Leonards**      **SL045584**

18 Wheels Check Torques  
Safety Inspection

|                              |                                                      |
|------------------------------|------------------------------------------------------|
| 56 Comms Fitment             | Electrical Auxs No power to MDT or SAT NAV,          |
| 34 Lights                    | Electrical Auxs O/S daytime running light blown      |
| 87 Stretcher                 | Other Power Styker not raising due to plastic caught |
| 85 Body Interior 1           | Window seal adrift                                   |
| 02 Cab Ass Fire Extinguisher | O.O.D                                                |
| 86 Sliding Door              | inside panel damaged                                 |
| 02 Cab Assembly 1            | Replaced centre box lock                             |
| 34 Lighting System           | Headlight inop o/s                                   |
| 02 Windscreen Wipers         | Blades u/s                                           |
| 71 Body Exterior 1           | Auto eject cover damaged                             |
| 17 Tyres                     | o/s/f tyre puncture                                  |
| 13 Brake Pads                | rears low                                            |
| 86 Doors                     | Rear door light damaged                              |

|                         |                   |              |                   |              |                |                    |                 |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Unplanned Repair</b> | <b>08/07/2024</b> | <b>08:00</b> | <b>10/07/2024</b> | <b>14:23</b> | <b>327,005</b> | <b>St Leonards</b> | <b>SL046178</b> |
|-------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                                                 |
|--------------------|-------------------------------------------------|
| 56 Comms Equipment | Comms Power Check MDT and Sat Nav have no power |
| 56 Comms Fitment   | Comms aerial ripped off roof                    |

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>22/07/2024</b> | <b>06:00</b> | <b>22/07/2024</b> | <b>16:43</b> | <b>327,036</b> | <b>St Leonards</b> | <b>SL046438</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                         |                                                          |
|-------------------------|----------------------------------------------------------|
| 18 Wheels Check Torques |                                                          |
| Safety Inspection       |                                                          |
| Brake Fluid Change      | Brake Fluid Change                                       |
| Tail Lift Inspection    |                                                          |
| Check and Fit P-Clips   | Check for the presence of P-Clips and fit if not present |
| 31 Battery Chassis      | Chassis battery u/s. Replaced battery.                   |
| 01 Air Conditioning 1   | Low gas. nitrogen test, no leaks. re- gased system.      |
| 85 Body Interior 1      | various saloon interior defects.                         |
| 15 Steering 1           | PAS Pulley cracked. replaced pump and bled system.       |
| 11 Axle Rear            | Topped up fluid level.                                   |

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>23/07/2024</b> | <b>08:12</b> | <b>23/07/2024</b> | <b>10:33</b> | <b>327,042</b> | <b>St Leonards</b> | <b>SL046465</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                  |                   |              |                   |              |                |                    |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>AVP Check</b> | <b>25/07/2024</b> | <b>07:30</b> | <b>25/07/2024</b> | <b>09:00</b> | <b>327,130</b> | <b>St Leonards</b> | <b>SL046543</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                     |
|--------------------|---------------------|
| Complete AVP Check | Carry out AVP check |
|--------------------|---------------------|

|                    |                     |              |                   |              |                |                    |                 |
|--------------------|---------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>AVP Check</b>   | <b>26/07/2024</b>   | <b>06:45</b> | <b>26/07/2024</b> | <b>08:00</b> | <b>327,201</b> | <b>St Leonards</b> | <b>SL046559</b> |
| Complete AVP Check | Carry out AVP check |              |                   |              |                |                    |                 |
| <b>AVP Check</b>   | <b>29/07/2024</b>   | <b>07:00</b> | <b>29/07/2024</b> | <b>09:00</b> | <b>327,600</b> | <b>St Leonards</b> | <b>SL046594</b> |
| Complete AVP Check | Carry out AVP check |              |                   |              |                |                    |                 |
| <b>AVP Check</b>   | <b>30/07/2024</b>   | <b>07:45</b> | <b>30/07/2024</b> | <b>08:45</b> | <b>327,708</b> | <b>St Leonards</b> | <b>SL046614</b> |
| Complete AVP Check | Carry out AVP check |              |                   |              |                |                    |                 |
| <b>AVP Check</b>   | <b>31/07/2024</b>   | <b>07:45</b> | <b>31/07/2024</b> | <b>08:30</b> | <b>327,762</b> | <b>St Leonards</b> | <b>SL046632</b> |
| Complete AVP Check | Carry out AVP check |              |                   |              |                |                    |                 |
| <b>AVP Check</b>   | <b>01/08/2024</b>   | <b>07:30</b> | <b>01/08/2024</b> | <b>08:45</b> | <b>327,811</b> | <b>St Leonards</b> | <b>SL046637</b> |
| Complete AVP Check | Carry out AVP check |              |                   |              |                |                    |                 |
| <b>AVP Check</b>   | <b>02/08/2024</b>   | <b>06:30</b> | <b>02/08/2024</b> | <b>08:30</b> | <b>327,955</b> | <b>St Leonards</b> | <b>SL046652</b> |
| Complete AVP Check | Carry out AVP check |              |                   |              |                |                    |                 |
| <b>AVP Check</b>   | <b>05/08/2024</b>   | <b>08:25</b> | <b>05/08/2024</b> | <b>10:35</b> | <b>328,216</b> | <b>St Leonards</b> | <b>SL046678</b> |
| Complete AVP Check | Carry out AVP check |              |                   |              |                |                    |                 |
| <b>AVP Check</b>   | <b>06/08/2024</b>   | <b>08:40</b> | <b>06/08/2024</b> | <b>09:20</b> | <b>328,292</b> | <b>St Leonards</b> | <b>SL046693</b> |
| Complete AVP Check | Carry out AVP check |              |                   |              |                |                    |                 |
| <b>AVP Check</b>   | <b>07/08/2024</b>   | <b>06:15</b> | <b>07/08/2024</b> | <b>07:15</b> | <b>328,416</b> | <b>St Leonards</b> | <b>SL046706</b> |
| Complete AVP Check | Carry out AVP check |              |                   |              |                |                    |                 |

|                                      |                                      |              |                   |              |                |                    |                 |
|--------------------------------------|--------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>AVP Check</b>                     | <b>08/08/2024</b>                    | <b>07:25</b> | <b>08/08/2024</b> | <b>09:49</b> | <b>328,498</b> | <b>St Leonards</b> | <b>SL046717</b> |
| Complete AVP Check                   | Carry out AVP check                  |              |                   |              |                |                    |                 |
| <b>AVP Check</b>                     | <b>09/08/2024</b>                    | <b>07:00</b> | <b>09/08/2024</b> | <b>08:00</b> | <b>328,513</b> | <b>St Leonards</b> | <b>SL046734</b> |
| Complete AVP Check                   | Carry out AVP check                  |              |                   |              |                |                    |                 |
| <b>AVP Check</b>                     | <b>12/08/2024</b>                    | <b>08:20</b> | <b>12/08/2024</b> | <b>09:41</b> | <b>328,857</b> | <b>St Leonards</b> | <b>SL046765</b> |
| Complete AVP Check                   | Carry out AVP check                  |              |                   |              |                |                    |                 |
| <b>AVP Check</b>                     | <b>13/08/2024</b>                    | <b>07:20</b> | <b>13/08/2024</b> | <b>07:30</b> | <b>328,961</b> | <b>St Leonards</b> | <b>SL046785</b> |
| Complete AVP Check                   | Carry out AVP check                  |              |                   |              |                |                    |                 |
| <b>AVP Check</b>                     | <b>14/08/2024</b>                    | <b>07:20</b> | <b>14/08/2024</b> | <b>08:20</b> | <b>329,088</b> | <b>St Leonards</b> | <b>SL046797</b> |
| Complete AVP Check                   | Carry out AVP check                  |              |                   |              |                |                    |                 |
| <b>AVP Check</b>                     | <b>15/08/2024</b>                    | <b>08:40</b> | <b>15/08/2024</b> | <b>10:32</b> | <b>329,145</b> | <b>St Leonards</b> | <b>SL046821</b> |
| Complete AVP Check                   | Carry out AVP check                  |              |                   |              |                |                    |                 |
| <b>AVP Check</b>                     | <b>16/08/2024</b>                    | <b>08:45</b> | <b>16/08/2024</b> | <b>10:45</b> | <b>329,248</b> | <b>St Leonards</b> | <b>SL046836</b> |
| Complete AVP Check<br>44 Add Ad Blue | Carry out AVP check<br>Top up Adblue |              |                   |              |                |                    |                 |
| <b>AVP Check</b>                     | <b>19/08/2024</b>                    | <b>06:33</b> | <b>19/08/2024</b> | <b>10:13</b> | <b>329,528</b> | <b>St Leonards</b> | <b>SL046869</b> |
| Complete AVP Check                   | Carry out AVP check                  |              |                   |              |                |                    |                 |
| <b>AVP Check</b>                     | <b>20/08/2024</b>                    | <b>06:45</b> | <b>20/08/2024</b> | <b>07:45</b> | <b>329,531</b> | <b>St Leonards</b> | <b>SL046886</b> |
| Complete AVP Check                   | Carry out AVP check                  |              |                   |              |                |                    |                 |

|                  |                   |              |                   |              |                |                    |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>AVP Check</b> | <b>21/08/2024</b> | <b>07:00</b> | <b>21/08/2024</b> | <b>08:00</b> | <b>329,626</b> | <b>St Leonards</b> | <b>SL046909</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                     |
|--------------------|---------------------|
| Complete AVP Check | Carry out AVP check |
|--------------------|---------------------|

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>26/08/2024</b> | <b>15:32</b> | <b>27/08/2024</b> | <b>10:00</b> | <b>329,696</b> | <b>St Leonards</b> | <b>SL046991</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>29/08/2024</b> | <b>07:37</b> | <b>30/08/2024</b> | <b>09:29</b> | <b>329,696</b> | <b>St Leonards</b> | <b>SL047054</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                                                                                                                                    |                                                                                                  |
|------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|
| 18 Wheels Check Torques<br>Safety Inspection<br>Tail Lift Inspection<br>13 Brake Test<br>34 Emergency Lights<br>85 Body Interior 1 | O/S/F Fog light surround missing<br>Saloon N/S/R Seat base torn. (Risk of cross-contamintaion.). |
|------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|

|                           |                   |              |                   |              |                |                    |                 |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Vehicle Deep Clean</b> | <b>02/10/2024</b> | <b>11:26</b> | <b>03/10/2024</b> | <b>08:34</b> | <b>332,006</b> | <b>St Leonards</b> | <b>SL047553</b> |
|---------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                    |                    |
|--------------------|--------------------|
| Vehicle Deep Clean | Vehicle Deep Clean |
|--------------------|--------------------|

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>05/10/2024</b> | <b>10:20</b> | <b>06/10/2024</b> | <b>07:16</b> | <b>332,006</b> | <b>St Leonards</b> | <b>SL047602</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                                                                                                                                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                                                                   |            |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|
| 18 Wheels Check Torques<br>Safety Inspection<br>UB Fire Supp 12mts Service<br>UB Fire Supp 6mts Service<br>Tail Lift Inspection<br>17 Tyres<br>16 Suspension 1<br>02 Windscreen Wipers<br>02 Cab Assembly 1<br>02 Cab Assembly 2<br>52 Electrical Aux<br>55 Tail Lift<br>34 Lights<br>13 Handbrake<br>Travel Time | Service of fire supression system<br>UB Fire Supp 6mts Service<br><br>Front tyres worn<br>Rear Shocks leaking<br>Blades split<br>Dash Panel damaged<br>Brake pedal rubber worn<br>CCTV not working<br>Rail and Trolley flap siezed<br>N/S DRL out and O/S/R marker inop<br>Cables not replaced...NO STOCK<br>Collect from station | Monitoring |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|

|                                                                                                                                  |                                                                                                                                                                                                                                                                                                            |              |                   |              |                |                    |                 |
|----------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Unplanned Repair</b>                                                                                                          | <b>14/10/2024</b>                                                                                                                                                                                                                                                                                          | <b>13:45</b> | <b>14/10/2024</b> | <b>14:28</b> | <b>333,397</b> | <b>St Leonards</b> | <b>SL047739</b> |
| 34 Lighting System                                                                                                               | No O/S brake lights                                                                                                                                                                                                                                                                                        |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>                                                                                                          | <b>18/10/2024</b>                                                                                                                                                                                                                                                                                          | <b>08:31</b> | <b>18/10/2024</b> | <b>08:34</b> | <b>333,907</b> | <b>St Leonards</b> | <b>SL047826</b> |
| 34 Lights Bulb Replacement                                                                                                       | N/S/F side light not working                                                                                                                                                                                                                                                                               |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>                                                                                                          | <b>25/10/2024</b>                                                                                                                                                                                                                                                                                          | <b>06:15</b> | <b>25/10/2024</b> | <b>07:20</b> | <b>333,970</b> | <b>St Leonards</b> | <b>SL047957</b> |
| 86 Sliding Door                                                                                                                  | Wont open from outside                                                                                                                                                                                                                                                                                     |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>                                                                                                          | <b>03/11/2024</b>                                                                                                                                                                                                                                                                                          | <b>09:05</b> | <b>03/11/2024</b> | <b>09:10</b> | <b>336,161</b> | <b>St Leonards</b> | <b>SL048071</b> |
| 34 Emergency Lights<br>89 Seats                                                                                                  | Blue light above side door not working<br>Saloon seat will not lock in place                                                                                                                                                                                                                               |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>                                                                                                          | <b>03/11/2024</b>                                                                                                                                                                                                                                                                                          | <b>08:00</b> | <b>03/11/2024</b> | <b>12:03</b> | <b>336,161</b> | <b>St Leonards</b> | <b>SL048073</b> |
| 89 Seats<br>34 Lights                                                                                                            | Attendant seat not locking in.<br>Blue light inop                                                                                                                                                                                                                                                          |              |                   |              |                |                    |                 |
| <b>Breakdown</b>                                                                                                                 | <b>04/11/2024</b>                                                                                                                                                                                                                                                                                          | <b>07:44</b> | <b>04/11/2024</b> | <b>08:30</b> | <b>336,161</b> | <b>St Leonards</b> | <b>SL048086</b> |
| Breakdown                                                                                                                        | N/S side blue light not working about side door                                                                                                                                                                                                                                                            |              |                   |              |                |                    |                 |
| <b>SAFETY INSPECTION</b>                                                                                                         | <b>14/11/2024</b>                                                                                                                                                                                                                                                                                          | <b>12:00</b> | <b>15/11/2024</b> | <b>11:28</b> | <b>337,533</b> | <b>St Leonards</b> | <b>SL048235</b> |
| 18 Wheels Check Torques<br>Safety Inspection<br>89 Seats<br>Replace Handbrake Cables<br>13 Handbrake<br>11 Axle Rear<br>17 Tyres | Checked.<br>Carried out inspection.<br>Body Interior Rear back seat not locking into place<br>Replace Handbrake Cables. Done.<br>Adjuster siezed. Replaced. Lower Telma to remove.<br>N/S halfshaft leaking. Removed,cleaned,resealed & refitted.<br>Extension valves missing from inner tyres. Fitted x2. |              |                   |              |                |                    |                 |

|                             |                                                                        |              |                   |              |                |                    |                 |
|-----------------------------|------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| 41 Air Intake               | Leaking oil @ resenator. Pipe bracket broken, replaced pipe, and hose. |              |                   |              |                |                    |                 |
| 86 Door Lock                | scoop locker lock n/w with key.Replaced barrel.                        |              |                   |              |                |                    |                 |
| 02 Cab Assembly 1           | Center consul trim adrift. Repaired.                                   |              |                   |              |                |                    |                 |
| 86 Sliding Door             | Step light n/w.Repair wiring in door.                                  |              |                   |              |                |                    |                 |
| 01 Air Conditioning 1       | Saloon condensor fan siezed. Replaced.                                 |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>   | <b>16/11/2024</b>                                                      | <b>09:34</b> | <b>18/11/2024</b> | <b>07:43</b> | <b>337,564</b> | <b>St Leonards</b> | <b>SL048255</b> |
| Vehicle Deep Clean          | Vehicle Deep Clean                                                     |              |                   |              |                |                    |                 |
| <b>Emergency Deep Clean</b> | <b>12/12/2024</b>                                                      | <b>06:20</b> | <b>12/12/2024</b> | <b>08:58</b> | <b>340,869</b> | <b>St Leonards</b> | <b>SL048647</b> |
| Emergency Deep Clean        |                                                                        |              |                   |              |                |                    |                 |
| <b>MOT EXPIRES</b>          | <b>12/12/2024</b>                                                      | <b>10:00</b> | <b>13/12/2024</b> | <b>13:37</b> | <b>340,869</b> | <b>St Leonards</b> | <b>SL048653</b> |
| MOT                         |                                                                        |              |                   |              |                |                    |                 |
| 87 Stretcher                | Replace mattress and straps                                            |              |                   |              |                |                    |                 |
| 34 Lights                   | Rear lights smashed                                                    |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>   | <b>28/12/2024</b>                                                      | <b>12:37</b> | <b>29/12/2024</b> | <b>12:00</b> | <b>342,241</b> | <b>St Leonards</b> | <b>SL048853</b> |
| Vehicle Deep Clean          | Vehicle Deep Clean                                                     |              |                   |              |                |                    |                 |
| <b>SAFETY INSPECTION</b>    | <b>31/12/2024</b>                                                      | <b>13:30</b> | <b>01/01/2025</b> | <b>07:19</b> | <b>342,241</b> | <b>St Leonards</b> | <b>SL048890</b> |
| Check MDVS for Update       | Check and Install MDVS windows update                                  |              |                   |              |                |                    |                 |
| Safety Inspection           | Carried out inspection.                                                |              |                   |              |                |                    |                 |
| 18 Wheels Check Torques     | Checked.                                                               |              |                   |              |                |                    |                 |
| Road Test                   |                                                                        |              |                   |              |                |                    |                 |
| 89 Seats                    | Body Interior Rear seat broken. Repaired plunger.                      |              |                   |              |                |                    |                 |
| 34 Lights Bulb Replacement  | Body Interior Interior light bulb. Replaced bulb.                      |              |                   |              |                |                    |                 |
| 87 Stretcher                | Med Equip & Devices Stretcher not holding , hanging on the back side   |              |                   |              |                |                    |                 |
| 34 Lights                   | O/S front side marker n/w.Replaced.                                    |              |                   |              |                |                    |                 |
| 85 Body Interior 1          | O/S/R door stay adrift.Replaced.                                       |              |                   |              |                |                    |                 |
| 45 Engine Oil Top Up        | Topped 1Ltr.                                                           |              |                   |              |                |                    |                 |

|                                |                                                                      |              |                   |              |                |                    |                 |
|--------------------------------|----------------------------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Unplanned Repair</b>        | <b>04/01/2025</b>                                                    | <b>07:49</b> | <b>09/01/2025</b> | <b>11:00</b> | <b>342,500</b> | <b>St Leonards</b> | <b>SL048943</b> |
| 31 Charging System             | Alternator charging fault                                            |              |                   |              |                |                    |                 |
| <b>Breakdown</b>               | <b>26/01/2025</b>                                                    | <b>11:25</b> | <b>27/01/2025</b> | <b>05:20</b> | <b>343,722</b> | <b>St Leonards</b> | <b>SL049253</b> |
| Breakdown                      | rear blue light fallen off                                           |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>        | <b>26/01/2025</b>                                                    | <b>13:57</b> | <b>26/01/2025</b> | <b>14:00</b> | <b>343,721</b> | <b>St Leonards</b> | <b>SL049258</b> |
| 34 Emergency Lights            | N/S/F wing blue light fallen off??                                   |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>        | <b>31/01/2025</b>                                                    | <b>15:58</b> | <b>31/01/2025</b> | <b>16:19</b> | <b>344,076</b> | <b>St Leonards</b> | <b>SL049360</b> |
| 71 Body External Steps         | Step warning going off. Adjusted positiong of step to sensor switch. |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>      | <b>11/02/2025</b>                                                    | <b>14:19</b> | <b>14/02/2025</b> | <b>11:50</b> | <b>344,642</b> | <b>St Leonards</b> | <b>SL049506</b> |
| Vehicle Deep Clean             | Vehicle Deep Clean                                                   |              |                   |              |                |                    |                 |
| <b>SAFETY INSPECTION</b>       | <b>17/02/2025</b>                                                    | <b>06:00</b> | <b>17/02/2025</b> | <b>14:00</b> | <b>344,642</b> | <b>St Leonards</b> | <b>SL049575</b> |
| Check MDVS for Update          | Check and Install MDVS windows update                                |              |                   |              |                |                    |                 |
| Safety Inspection              |                                                                      |              |                   |              |                |                    |                 |
| 18 Wheels Check Torques        |                                                                      |              |                   |              |                |                    |                 |
| Road Test                      |                                                                      |              |                   |              |                |                    |                 |
| Tail Lift Inspection           |                                                                      |              |                   |              |                |                    |                 |
| Tail Lift 12M Service & Weight | Tail Lift 12M Service & Weight                                       |              |                   |              |                |                    |                 |
| 13 Handbrake                   | Adjusted shoes and cables.                                           |              |                   |              |                |                    |                 |
| 34 Lights                      | NS Wind indicator mount loose. resecured to wing.                    |              |                   |              |                |                    |                 |
| 87 Stretcher                   | Stretcher battery u/s. replaced battery.                             |              |                   |              |                |                    |                 |
| 16 Suspension 1                | Rear roll bar lower link bushes worn. replaced bushes.               |              |                   |              |                |                    |                 |
| 16 Suspension 2                | NSR Spring, rear buffer bush split. replaced.                        |              |                   |              |                |                    |                 |
| 17 Tyres Replace               | X2 NSR Tyres replaced.                                               |              |                   |              |                |                    |                 |



|                                      |                                                                                |              |                   |              |                |                     |                 |
|--------------------------------------|--------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|---------------------|-----------------|
| <b>Breakdown</b>                     | <b>23/02/2025</b>                                                              | <b>12:07</b> | <b>24/02/2025</b> | <b>08:56</b> | <b>345,718</b> | <b>St Leonards</b>  | <b>SL049670</b> |
| Breakdown                            | Red battery warning -Checked, battery and alternator both ok. road tested. ok. |              |                   |              |                |                     |                 |
| <b>Breakdown</b>                     | <b>26/03/2025</b>                                                              | <b>00:27</b> | <b>26/03/2025</b> | <b>07:19</b> | <b>348,771</b> | <b>St Leonards</b>  | <b>SL050077</b> |
| Breakdown<br>31 Battery Chassis      | Power cut out cant start<br>Chassis battery replaced.                          |              |                   |              |                |                     |                 |
| <b>Unplanned Repair</b>              | <b>29/03/2025</b>                                                              | <b>06:37</b> | <b>30/03/2025</b> | <b>06:40</b> | <b>348,939</b> | <b>St Leonards</b>  | <b>SL050117</b> |
| 89 Seats                             | Saloon Swivel seat not locking in position. Refitted lock                      |              |                   |              |                |                     |                 |
| <b>02 Pipeline Annual Inspection</b> | <b>26/03/2025</b>                                                              | <b>13:05</b> | <b>26/03/2025</b> | <b>13:10</b> | <b>348,783</b> | <b>MDT Ferndown</b> | <b>TF004061</b> |
| 02 Pipeline Annual Inspection        | Annual Inspection and Pressure Test - replace 1x port seal (lot 56119)         |              |                   |              |                |                     |                 |
| <b>Vehicle Deep Clean</b>            | <b>31/03/2025</b>                                                              | <b>15:09</b> | <b>01/04/2025</b> | <b>15:19</b> | <b>349,077</b> | <b>St Leonards</b>  | <b>SL050144</b> |
| Vehicle Deep Clean                   | Vehicle Deep Clean                                                             |              |                   |              |                |                     |                 |
| <b>SAFETY INSPECTION</b>             | <b>03/04/2025</b>                                                              | <b>08:00</b> | <b>03/04/2025</b> | <b>13:14</b> | <b>349,077</b> | <b>St Leonards</b>  | <b>SL050201</b> |
| Check MDVS for Update                | Check and Install MDVS windows update. Done.                                   |              |                   |              |                |                     |                 |
| Safety Inspection                    | Carried out inspection.                                                        |              |                   |              |                |                     |                 |
| 18 Wheels Check Torques              | Checked.                                                                       |              |                   |              |                |                     |                 |
| Road Test                            | Done.                                                                          |              |                   |              |                |                     |                 |
| Annual Air Con Service               | Annual Air Condition Service                                                   |              |                   |              |                |                     |                 |
| Annual Heater Service                | Annual Heater Service                                                          |              |                   |              |                |                     |                 |
| Pollen Filter Change                 | Pollen Filter Change                                                           |              |                   |              |                |                     |                 |
| Tail Lift Inspection                 | Done.                                                                          |              |                   |              |                |                     |                 |
| Engine Change Oil & Filter           |                                                                                |              |                   |              |                |                     |                 |
| 85 Body Int Alcohol Gel Dispen       | Done.                                                                          |              |                   |              |                |                     |                 |
| Air Filter Change                    | Air Filter Change                                                              |              |                   |              |                |                     |                 |
| Fuel Filter Change                   | Change Fuel Filter                                                             |              |                   |              |                |                     |                 |
| UB Fire Supp 6mts Service            | UB Fire Supp 6mts Service                                                      |              |                   |              |                |                     |                 |

|                               |                                                                               |              |                   |              |                |                    |                 |
|-------------------------------|-------------------------------------------------------------------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>BREAKDOWN</b>              | <b>29/04/2025</b>                                                             | <b>14:06</b> | <b>29/04/2025</b> | <b>14:09</b> | <b>350,611</b> | <b>St Leonards</b> | <b>SL050650</b> |
| 55 Tail Lift                  | Tail lift Fault. will not open                                                |              |                   |              |                |                    |                 |
| <b>Breakdown</b>              | <b>14/05/2025</b>                                                             | <b>13:16</b> | <b>14/05/2025</b> | <b>16:00</b> | <b>350,611</b> | <b>St Leonards</b> | <b>SL050950</b> |
| Breakdown                     | flat tyre                                                                     |              |                   |              |                |                    |                 |
| <b>SAFETY INSPECTION</b>      | <b>17/05/2025</b>                                                             | <b>11:00</b> | <b>18/05/2025</b> | <b>14:30</b> | <b>351,652</b> | <b>St Leonards</b> | <b>SL051009</b> |
| Check MDVS for Update         | Check and Install MDVS windows update                                         |              |                   |              |                |                    |                 |
| Safety Inspection             |                                                                               |              |                   |              |                |                    |                 |
| 18 Wheels Check Torques       |                                                                               |              |                   |              |                |                    |                 |
| Road Test                     |                                                                               |              |                   |              |                |                    |                 |
| 55 Tail Lift                  | Body Interior Tail Lift broken. Adjust ram and straighten stow sensor bracket |              |                   |              |                |                    |                 |
| Tail Lift Inspection          |                                                                               |              |                   |              |                |                    |                 |
| 02 Cab Assembly 1             | Replace centre console knob                                                   |              |                   |              |                |                    |                 |
| 34 Lights                     | Replace n/s/f top marker light                                                |              |                   |              |                |                    |                 |
| 85 Body Interior 1            | Secure sallon cuboard door hinges                                             |              |                   |              |                |                    |                 |
| <b>Vehicle Deep Clean</b>     | <b>19/05/2025</b>                                                             | <b>14:30</b> | <b>20/05/2025</b> | <b>12:25</b> | <b>351,658</b> | <b>St Leonards</b> | <b>SL051037</b> |
| Vehicle Deep Clean            | Vehicle Deep Clean                                                            |              |                   |              |                |                    |                 |
| <b>Unplanned Repair</b>       | <b>26/05/2025</b>                                                             | <b>06:00</b> | <b>26/05/2025</b> | <b>08:38</b> | <b>352,286</b> | <b>St Leonards</b> | <b>SL051194</b> |
| 87 - Stretchers/Chairs/Boards | Med Equip & Devices FAULTY WHEELCHAIR. Repaired.                              |              |                   |              |                |                    |                 |
| 71 Body Exterior 1            | Front bumper damaged. Repaired.                                               |              |                   |              |                |                    |                 |
| 54 Sirens                     | Bull horn inop. Repaired.                                                     |              |                   |              |                |                    |                 |
| <b>Breakdown</b>              | <b>12/07/2025</b>                                                             | <b>08:14</b> | <b>13/07/2025</b> | <b>10:00</b> | <b>356,393</b> | <b>St Leonards</b> | <b>SL052029</b> |
| Breakdown                     | faulty passenger's seat                                                       |              |                   |              |                |                    |                 |

|                          |                   |              |                   |              |                |                    |                 |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>SAFETY INSPECTION</b> | <b>28/07/2025</b> | <b>09:00</b> | <b>29/07/2025</b> | <b>16:00</b> | <b>357,525</b> | <b>St Leonards</b> | <b>SL052340</b> |
|--------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                               |                                                                      |            |
|-------------------------------|----------------------------------------------------------------------|------------|
| Check MDVS for Update         | Check and Install MDVS windows update                                |            |
| Safety Inspection             |                                                                      |            |
| 18 Wheels Check Torques       |                                                                      |            |
| Road Test                     |                                                                      |            |
| 89 Seats                      | Body Interior Saloon passenger seat swivels freely NFF               |            |
| 87 Med Handling Equip Inspect | Med Equip & Devices internal tubing faulty. TOLD Medical device team |            |
| 71 Body Exterior 1            | Front bumper cracked. Replaced with one from deommisioned vehicle    |            |
| 45 Engine 1                   | Oil leak on engine. Washed off to monitor                            | Monitoring |
| 17 Tyres                      | 3x tyres replaced. Both fronts and OSR inner                         |            |
| 13 Brake Pads                 | Replace front brake pads.                                            |            |
| 55 Tail Lift                  | Tail lift stay plates seied. Told to leave as decommissioned soon    | Monitoring |

|                  |                   |              |                   |              |                |                    |                 |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Breakdown</b> | <b>08/08/2025</b> | <b>19:16</b> | <b>11/08/2025</b> | <b>13:30</b> | <b>358,437</b> | <b>St Leonards</b> | <b>SL052595</b> |
|------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|           |                                                 |
|-----------|-------------------------------------------------|
| Breakdown | tail lift not deploying / passenger chair loose |
|-----------|-------------------------------------------------|

|                             |                   |              |                   |              |                |                    |                 |
|-----------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|
| <b>Decommission Vehicle</b> | <b>26/08/2025</b> | <b>08:57</b> | <b>15/09/2025</b> | <b>10:12</b> | <b>358,437</b> | <b>St Leonards</b> | <b>SL052905</b> |
|-----------------------------|-------------------|--------------|-------------------|--------------|----------------|--------------------|-----------------|

|                      |                      |
|----------------------|----------------------|
| Decommission vehicle | Decommission vehicle |
|----------------------|----------------------|