

VE64BHW	A&E		Totnes Amb Stn				
PDI Inspection	23/01/2015	11:01	29/01/2015	16:03	182	Derriford	DE017797
PDI Inspection							
Vehicle Deep Clean	07/04/2015	09:05	07/04/2015	10:54	780	Torquay	TO010449
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	07/04/2015	09:38	07/04/2015	13:16	780	Torquay	TO010450
18 Wheels Check Torques Safety Inspection							
Unplanned Repair	29/04/2015	08:17	29/04/2015	09:00	1,162	Torquay	TO010518
45 Engine Ad Blue	Top up Adblue						
Unplanned Repair	05/05/2015	14:13	05/05/2015	14:15	2,275	Torquay	TO010532
45 Engine Ad Blue	Adblue issue						
Unplanned Repair	17/05/2015	12:34	17/05/2015	12:53	4,558	Torquay	TO010574
45 Engine Ad Blue	Crew topped up adblue						
SAFETY INSPECTION	18/05/2015	09:00	18/05/2015	12:09	4,749	Torquay	TO010577
18 Wheels Check Torques 71 Body Exterior 1 71 Body Exterior 2 87 Stretcher Safety Inspection	Checklist Defect No Call sign sticker fitted AWAITING CALL SIGNS Checklist Defect Accident damage to O/S/R light pod B/SHOP Checklist Defect 4 point harness missing and belts fitted incorrectly REPAIRED					Awaiting Parts Awaiting Body Repair	

Vehicle Deep Clean	18/05/2015	11:31	18/05/2015	14:15	4,749	Torquay	TO010579
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/05/2015	07:41	21/05/2015	07:42	4,899	Torquay	TO010586
45 Engine Ad Blue	Crew topped up Adblue						
Unplanned Repair	26/05/2015	07:58	26/05/2015	08:06	5,439	Torquay	TO010594
45 Engine Ad Blue	Crew topped uo adblue						
Unplanned Repair	03/06/2015	10:54	03/06/2015	10:56	7,002	Torquay	TO010627
45 Engine Ad Blue	Crew topped up adblue						
Unplanned Repair	11/06/2015	07:47	11/06/2015	07:50	8,705	Torquay	TO010655
45 Engine Ad Blue	Crew topped up adblue						
Unplanned Repair	22/06/2015	08:05	22/06/2015	08:07	10,878	Torquay	TO010680
45 Engine Ad Blue	Crew topped up Adblue						
SAFETY INSPECTION	03/07/2015	08:42	03/07/2015	16:09	13,605	Torquay	TO010720
18 Wheels Check Torques							
71 Body Exterior 1	Checklist Defect No Call sign sticker fitted AWAITING CALL SIGNS						
71 Body Exterior 2	Checklist Defect Accident damage to O/S/R light pod B/SHOP						
85 Body Interior 1	Checklist Defect Scoop cupbroad corner shelve broken ORDERED 03.07.15						
87 - Stretchers/Chairs/Boards	Checklist Defect Scoop and long broad missing from vehicle MONITOR						
Safety Inspection							
						Awaiting Parts Monitoring	

Vehicle Deep Clean	03/07/2015	08:59	03/07/2015	13:29	13,605	Torquay	TO010721
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/07/2015	15:13	23/07/2015	15:17	17,793	Torquay	TO010796
44 Add Ad Blue	topped up ad blue 15lrts						
Unplanned Repair	13/08/2015	11:14	13/08/2015	12:30	21,498	Derriford	DE018730
17 Tyres Replace	Renewed rear tyres due to low tread and punctured						
Vehicle Deep Clean	14/08/2015	07:13	14/08/2015	14:02	21,694	Torquay	TO010875
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/08/2015	09:08	14/08/2015	13:44	21,694	Torquay	TO010877
18 Wheels Check Torques	ns side body blue nw warranty sent renewed Scoop cupboard corner shelf Scoop and long board missing from vehicle MONITOR all ok C service left as per D Austins instructions via phone call						Awaiting Warranty
34 Emergency Lights							
85 Body Interior 1							
87 - Stretchers/Chairs/Boards							
Safety Inspection							
Unplanned Repair	18/08/2015	07:00	18/08/2015	08:09	22,306	Torquay	TO010888
87 Stretcher	removed cleaned and lubed stretcher clamp						
Unplanned Repair	26/08/2015	13:00	26/08/2015	13:02	23,701	Torquay	TO010915
17 Tyres Replace	Tyres front tyres wearing uneven.?tracking ats repaired						

Unplanned Repair	09/09/2015	10:15	09/09/2015	10:20	26,461	Torquay	TO010949
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

34 Lights Bulb Replacement	Fitted new bulb
----------------------------	-----------------

SAFETY INSPECTION	22/09/2015	09:10	24/09/2015	09:47	28,931	Torquay	TO010991
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

13 Brake Pads	Checklist Defect front pads low REPLACED	
16 Suspension 1	Suspension increasingly loud knocking from n/s rear wheel TIGHTEN ARB BOLTS	
18 Wheels Check Torques		
34 Emergency Lights	ns side body blue nw warranty sent	
34 Lights	Checklist Defect o/s/f+r side marker light damaged REPLACED	
54 Reversing Systems	Body Exterior rear camera bracket bent REPLACED	
55 Tail Lift	Ramp/Lift/Tail Hoist does not self level when elevated from the ground NOTES	
71 Body Exterior 1	other reversing camra bracket u/s	
71 Body External Steps	Checklist Defect Accident damage to lower n/s and o/s, damaged step B/Shop	Partially Completed
Check Winter Pack	Checklist Defect Carry out winter pressure check	
Safety Inspection		
92 - C Service		
Service C		
Tail Lift 6 Monthly Inspection	Statutory Inspection Done by South west lifts P/O 151117226	

Vehicle Deep Clean	22/09/2015	13:53	23/09/2015	14:12	28,931	Torquay	TO010994
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	20/10/2015	12:23	21/10/2015	08:26	33,610	Torquay	TO011086
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

45 Engine 1	Electrical faults with engine and dash notes
-------------	--

Unplanned Repair	22/10/2015	07:52	22/10/2015	08:07	33,845	Torquay	TO011092
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

34 Lights Bulb Replacement	replaced head light bulb
----------------------------	--------------------------

SAFETY INSPECTION	03/11/2015	09:03	03/11/2015	15:19	36,194	Torquay	TO011138
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques	
71 Body Exterior Acc Repair	sprayed side in by step and made repair to o\s\r lamp cluster

71 Body External Steps	straightened side step runner						
89 Seats	tightened saloon seat locking pin						
Safety Inspection							
Vehicle Deep Clean	04/11/2015	07:15	04/11/2015	13:57	36,194	Torquay	TO011143
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/12/2015	10:29	17/12/2015	15:39	43,361	Torquay	TO011285
13 Brake Pads	replaced rear brake pads						
17 Tyres	replaced all tyres (winter)						
18 Wheels Check Torques							
45 Engine Oil Top Up	topped up engine oil level 2ltrs						
87a - Medical Equipment Repair	FITTED NEW STRAP TO MANGA BOARD						
Safety Inspection							
MOT Pre Test							
Travel Time							
MOT							
Vehicle Deep Clean	15/12/2015	13:01	16/12/2015	12:22	43,361	Torquay	TO011288
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	11/01/2016	11:19	11/01/2016	11:22	48,101	Torquay	TO011372
34 Lights Bulb Replacement	replaced n\s\l head light bulb						
Vehicle Deep Clean	26/01/2016	07:41	26/01/2016	13:12	50,759	Torquay	TO011430
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/01/2016	12:05	27/01/2016	15:59	50,759	Torquay	TO011432
02 Cab Assembly 1	replaced brake pedal rubber						
02 Mirrors	Body Exterior Crack in glass of nearside wing mirror.						
18 Wheels Check Torques							

85 Body Interior 1 replaced fire extinguisher in rear body
 Safety Inspection
 93 - D Service
 Service D
 Gearbox Oil & Filter Change

Unplanned Repair **12/02/2016** **10:46** **12/02/2016** **13:12** **53,250** **Torquay** **TO011481**

71 Body External Steps adjusted step and micro switch for step deploy

Breakdown **25/02/2016** **00:32** **25/02/2016** **12:06** **55,307** **Torquay** **TO011520**

01 Heating 1 carried out checks couldnot fine any fault at time??
 Breakdown Rear heater -cold air only

SAFETY INSPECTION **08/03/2016** **08:27** **08/03/2016** **15:55** **57,268** **Torquay** **TO011554**

18 Wheels Check Torques
 34 Lights Fitted spare 477 bulb to glove box
 87 Stretcher fitted missing pedimate
 Safety Inspection
 Tail Lift 6 Monthly Inspection Statutory Inspection

Vehicle Deep Clean **08/03/2016** **11:05** **09/03/2016** **11:34** **57,268** **Torquay** **TO011555**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **06/04/2016** **15:48** **06/04/2016** **15:50** **62,203** **Torquay** **TO011660**

34 Lights Bulb Replacement replaced head light bulb n\s

Vehicle Deep Clean **19/04/2016** **07:51** **20/04/2016** **14:11** **64,576** **Torquay** **TO011701**

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/04/2016	09:30	21/04/2016	14:35	64,576	Torquay	TO011702
13 Brakes 1	replaced front & rear pads & discs and front sensors						
17 Tyres	replaced rear tyres x4						
18 Wheels Check Torques							
34 Lights	replaced n\s\r top red marker						
44 Fuel System 1	replaced fuel cap removed fuel angle						
45 Engine Oil Top Up	topped up oilk level 1.5ltrs						
Safety Inspection							
85 Body Int Alcohol Gel Dispen	fitted dispensor						
Fit Throw Lines & SOP	fitted new throw line						
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by SWL						
Wheel Studs & Nuts Replacem	flanges replaced						
Handbrake Cable Replacement	Replace rear handbrake cables						
Wheel Hub Flanges Replacem	replaced front and rear flanges + new nuts						
Camera Installation	been completed						
Install Saloon CCTV Camera	Been completed						
Unplanned Repair	28/04/2016	11:50	28/04/2016	11:54	65,832	Torquay	TO011729
34 Lights Bulb Replacement	replaced bulb in o\s head light						
ACCIDENT	19/05/2016	14:26	20/05/2016	08:33	69,778	Torquay	TO011802
71 Body Exterior Acc Repair	made temp repair to n\s\lf lower corner						
71 Body External Steps	replaced side step complete and wired in						
SAFETY INSPECTION	31/05/2016	08:44	01/06/2016	08:33	71,898	Torquay	TO011832
02 Cab Ass Fire Extinguisher	replaced cab fire extinguisher						
02 Cab Assembly 1	reatached torch to side locker in cab						
02 Windscreen Wipers	replaced washer motor and cleaned jets and lines						
17 Tyres	replaced both front tyres						
18 Wheels Check Torques	road test retorque						
Safety Inspection							

Annual Heater Service 92 - C Service Service C Reposition grab bag shelf	Annual Heater Service						
Vehicle Deep Clean	31/05/2016	11:38	01/06/2016	13:00	71,898	Torquay	TO011835
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	12/07/2016	11:40	13/07/2016	15:01	79,147	Torquay	TO011958
18 Wheels Check Torques 34 Lights Bulb Replacement 86 Sliding Door 89 Seats Safety Inspection Annual Air Con Service	replaced bulb in indicator lamp n\s wing + n\s head light bulb adjusted side door top magnet mounting bracket tightened saloon seats arm rests Annual Air Condition Service						
Vehicle Deep Clean	13/07/2016	07:19	14/07/2016	13:33	79,147	Torquay	TO011960
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	22/07/2016	08:56	22/07/2016	09:33	80,774	Torquay	TO011990
02 Windscreen Wipers	Washers inop - Removed washer bottle to clean out sludge (pipes also)						
SAFETY INSPECTION	23/08/2016	08:29	24/08/2016	08:30	86,778	Torquay	TO012097
02 Cab Assembly 1 13 Brake Pads 17 Tyres 18 Wheels Check Torques 34 Lighting System 34 Lights Bulb Replacement 45 Engine Oil Top Up 71 Body Exterior Acc Repair Safety Inspection	replaced missing cupboard knob \ fitted new rubber mats replaced front pads and sensors replaced rear tyres x4 replaced rear stop and tail lamp o\s\r replaced o\s frnt side light bulb topped up engine oil level made temp repair before body shop visit						

Tail Lift 6 Monthly Inspection Statutory Inspection

Vehicle Deep Clean **24/08/2016** **07:25** **25/08/2016** **11:23** **86,778** **Torquay** **TO012100**

Vehicle Deep Clean Vehicle Deep Clean

Defect Repair **09/09/2016** **08:15** **09/09/2016** **15:02** **89,868** **Torquay** **TO012165**

02 Cab Ass Fire Extinguisher Fire Trace sounding when vehicle first started WARRANTY CLIAM SUBMITTED JD
 27 Transmission Automatic Clutch doesn't seem to raise through gears NFF SEE NOTES
 44 Add Ad Blue Adblue cap missing REPLACED

SAFETY INSPECTION **04/10/2016** **09:03** **07/10/2016** **14:53** **94,208** **Torquay** **TO012261**

02 Windscreen Wipers replaced windscreen wiper blades
 16 Suspension 1 both front shockers worn Merc to replace WTY
 18 Wheels Check Torques
 34 Emergency Lights n\s\ center blue light fault 1\2 working WTY Awaiting Warranty
 34 Lighting System replaced n\s\ repeter lamp assembly
 45 Engine Oil Top Up Emg Warning Devices oil warning light on, oil level checked and ok
 85 Body Interior 1 repaired folder holder
 Safety Inspection
 93 - D Service
 Service D
 MOT Pre Test

Vehicle Deep Clean **05/10/2016** **10:01** **06/10/2016** **07:01** **94,208** **Torquay** **TO012268**

Vehicle Deep Clean Vehicle Deep Clean

ACCIDENT **11/11/2016** **08:02** **11/11/2016** **11:49** **100,580** **Torquay** **TO012434**

71 Body External Steps made repiar to side step after damage good as new :)

SAFETY INSPECTION	14/11/2016	10:49	16/11/2016	11:32	101,131	Torquay	TO012442
02 Cab Ass Fire Extinguisher	Fire Supression system has a voice warning of pressure low.					Awaiting Warranty	
16 Suspension 1	All 4 rear spring slipper pads starting to split					Awaiting Warranty	
16 Suspension 2	Rear ARB link bushes slight play					Awaiting Warranty	
16 Suspension 3	Slight play in N/S/F shock absorber					Awaiting Warranty	
17 Tyres	N/S/F tyre worn - Replaced						
18 Wheels Check Torques							
34 Emergency Lights	n\s\l center blue light fault 1\2 working WTY					Awaiting Warranty	
34 Lights	Interior light inop						
71 Body External Steps	Checklist Defect Accident damage to lower n/s and o/s, damaged step B/Shop					Monitoring	
85 Body Interior 1	Scoop cupboard bio safe strap broken						
86 Sliding Door	Side door magnet not holding door - Adjusted						
89 Seatbelts	N/S/F saloon seatbelt twisted - Untwisted						
Safety Inspection							
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill						
Gearbox Oil & Filter Change							
Travel Time							
MOT							
UB Fire Suppression Service	Not done due to warranty						
Vehicle Deep Clean	14/11/2016	08:23	15/11/2016	12:17	101,131	Torquay	TO012443
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	25/11/2016	13:51	25/11/2016	14:44	102,941	Torquay	TO012495
02 Mirrors	replaced broken mirror parts						
Unplanned Repair	01/12/2016	08:02	01/12/2016	09:00	103,849	Torquay	TO012519
34 Lights Bulb Replacement	Crew fitted Spare bulb						
SAFETY INSPECTION	27/12/2016	09:02	27/12/2016	15:13	109,464	Torquay	TO012640
13 Brake Pads	replaced rear pads						
17 Tyres	replaced rear and o\s\l tyres						

18 Wheels Check Torques
 Safety Inspection
 Medical Device and Equip Chec

Vehicle Deep Clean	28/12/2016	08:00	28/12/2016	14:12	109,464	Torquay	TO012647
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	04/01/2017	15:38	04/01/2017	15:41	110,859	Torquay	TO012681
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	relaced broken mirror parts
------------	-----------------------------

Unplanned Repair	13/01/2017	16:11	13/01/2017	16:14	112,530	Torquay	TO012728
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Heating 1	made repsair to night heater
--------------	------------------------------

Unplanned Repair	27/01/2017	14:12	27/01/2017	14:16	114,701	Torquay	TO012792
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	replaced day running bulb n\s
----------------------------	-------------------------------

Unplanned Repair	02/02/2017	14:20	02/02/2017	15:22	115,828	Torquay	TO012827
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

27 Transmission Automatic	topped up oil level 1ltr and r\l missing gears?
---------------------------	---

Breakdown	06/02/2017	19:02	07/02/2017	15:43	115,900	Torquay	TO012838
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	O/s rear door buckled and will no longer close. fixed at derriford
-----------	--

SAFETY INSPECTION	08/02/2017	11:47	09/02/2017	13:06	116,753	Torquay	TO012850
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	Fire trace low pressure alarm sounding when ing switched WARRANTY	Awaiting Warranty
13 Brake Pads	Front pads low	
13 Discs	Front discs lipped and close to min thickness	

18 Wheels Check Torques							
34 Lighting System	O/S/F side marker insecure						
54 Warn Dev/System	No volume in saloon for warning device						
Safety Inspection							
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	09/02/2017	10:44	10/02/2017	10:25	116,900	Torquay	TO012855
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	11/02/2017	20:58	13/02/2017	11:15	116,952	Torquay	TO012866
71 Body External Steps	straightened step and replaced x2 roller						
Breakdown	Side steps have been damaged and side arm						
ACCIDENT	07/02/2017	08:00	09/02/2017	13:58	116,740	Torquay	TO012944
86 Doors Rear	Autospray repaired rera doors (plated)						
Unplanned Repair	02/03/2017	08:26	02/03/2017	11:57	119,023	Torquay	TO012946
34 Lights Bulb Replacement	replaced both main beam bulbs						
SAFETY INSPECTION	20/03/2017	08:15	21/03/2017	15:11	122,589	Torquay	TO013010
02 Cab Ass Fire Extinguisher	replaced cab fire extinguisher						
18 Wheels Check Torques							
34 Emergency Lights	made repair to rear top corner blue LED light						
86 Sliding Door	straightened side door magnet bracket						
Safety Inspection							
Annual Heater Service	Annual Heater Service						
Handbrake Cable Replacement	Replace rear handbrake cables NOT Due still under WTY						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	21/03/2017	09:00	21/03/2017	14:06	122,589	Torquay	TO013019
Vehicle Deep Clean	Vehicle Deep Clean						

BREAKDOWN	03/04/2017	08:22	03/04/2017	10:31	124,798	Torquay	TO013064
17 Tyres	stow punc						
18 Wheels Retorque	R\t retorque						
Unplanned Repair	27/04/2017	14:28	27/04/2017	15:10	128,996	Torquay	TO013179
86 Door Lock	ramp door unable to open WTY fixed by John Coles						
SAFETY INSPECTION	02/05/2017	08:50	03/05/2017	14:06	129,788	Torquay	TO013183
01 Heating 1	replaced heater exhaust pipe						
11 Axle Rear	replaced x2 anti roll bushes lower						
17 Tyres	replaced n\s\l and all rear tyres						
18 Wheels	replaced leaking wheel rim						
18 Wheels Check Torques							
45 Engine Oil Top Up	topped up oil level						
86 Sliding Door	replaced damaged hinge cover and straightened magnet bracket						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Vehicle Deep Clean	03/05/2017	07:20	03/05/2017	14:52	129,788	Torquay	TO013191
Vehicle Deep Clean	Vehicle Deep Clean						
Medical Devices Repair	11/05/2017	08:20	11/05/2017	08:23	130,868	MDC West	MW009777
Decontaminated	N/A vehicle						
Defect Sheet Present No							
Defect Sheet Present Yes							
Medical Devices Repair	Reported LSU not charging, fault traced to broken wire behind bulkhead.						

Breakdown	24/05/2017	17:33	26/05/2017	15:15	133,151	Torquay	TO013285
31 Battery Chassis	replaced chassis battery see notes checks carryed out b4 replacement						
86 Door Hinges	replaced rear door stay block and arm						
Breakdown	Requires battery check						
BREAKDOWN	29/05/2017	07:37	29/05/2017	12:15	133,432	Torquay	TO013298
56 Comms Power Failure	Electrical Auxs MDT FAILURE - Reset procedure top cupboard						
SAFETY INSPECTION	12/06/2017	10:56	12/06/2017	16:29	134,495	Torquay	TO013360
02 Cab Assembly 1	resecuired mdt panel						
18 Wheels Check Torques							
55 Ramp	resecuired rear run up ramp blocks x3						
86 Sliding Door	straightened side door top magnet bracket						
89 Seats	resecuired sallon seat rear locking roll pin in base lock						
Safety Inspection							
WAS Firetrace rework & Service							
93 - D Service							
Service D							
Vehicle Deep Clean	12/06/2017	13:31	13/06/2017	14:47	134,495	Torquay	TO013363
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/06/2017	16:00	21/06/2017	12:14	135,301	Torquay	TO013395
71 Body Exterior Roof	Orderer new sky light replaced sky light						
MGS Gas Storage Modifications	30/06/2017	08:15	30/06/2017	08:19	136,246	Torquay	TO013451
MGS Gas Storage Modifications	MGS Gas Storage Modifications						

Defect Repair	05/07/2017	08:25	06/07/2017	09:56	137,111	Torquay	TO013480
31 Battery Comms	Battery/Charging Sys +++constant power fails battery check						
Breakdown	08/07/2017	21:11	10/07/2017	16:22	137,445	Torquay	TO013498
17 Tyres	ATS fitted new tyre						
Breakdown	N/S rear outer						
SAFETY INSPECTION	25/07/2017	13:35	01/08/2017	10:56	140,499	Torquay	TO013573
01 Air Conditioning 1	Condensor fan inop FUSE BLOWN WARRANTY						
01 Air Conditioning 2	Air con tensioner seized WARRANTY						
02 Cab Ass Fire Extinguisher	Fire Suppression system has a voice warning of pressure low.DONE 13.06.17 JC						
16 Suspension 1	All 4 rear spring slipper pads starting to split						
16 Suspension 2	Rear ARB link bushes slight play						
16 Suspension 3	Slight play in N/S/F shock absorber						
18 Wheels Check Torques							
19 Chassis 1	Step mud flap split made repair						
19 Chassis 2	N/S spray suppression loose on mountings						
27 Transmission Automatic	Gear box oil leak POSS WARRANTY						
34 Emergency Light System	replaced cover on o/s quad flair light						
34 Emergency Lights	n\s\center blue light fault 1\2 working WTY						
34 Lights	replaced o/s indicator bulb showing white						
34 Lights Bulb Replacement	O/S dip beam inop REPLACED						
71 Body Exterior 2	Acc damage SEE NOTES FOR DEFECTS						
71 Body External Steps	Checklist Defect Accident damage to lower n/s and o/s, damaged step B/Shop						
86 Door Lock	Scoop locker door unable to over ride c/locking WARRANTY						
86 Doors	Inner and outer bearings on sliding door noisy, door becoming stiff to open WARR						
86 Sliding Door	Sliding door stop bent not holding door						
89 Seats	Both swivel seat stiff to turn						
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	26/07/2017	11:17	01/08/2017	09:19	140,499	Torquay	TO013576
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	04/08/2017	09:59	08/08/2017	14:49	140,854	Torquay	TO013632
56 Comms Equipment	MDT keeps switching off PCE to look at						
Unplanned Repair	10/08/2017	09:03	10/08/2017	10:50	141,209	Torquay	TO013667
31 Battery Comms	replaced coms battery after ferther checks						
BREAKDOWN	14/08/2017	08:12	15/08/2017	15:31	141,934	Torquay	TO013673
56 Comms Equipment	MDT Fault PCE been in and fixed						
SAFETY INSPECTION	04/09/2017	08:27	06/09/2017	08:39	144,353	Torquay	TO013761
02 Cab Ass Fire Extinguisher	moved fire trace pipe away from turbo area						
13 Brakes 1	replaced rear pads and discs						
18 Wheels Check Torques							
34 Emergency Lights	Airport light inop WTY Been Done 5/9/17					Awaiting Warranty	
86 Doors Rear	modified rear door stay and adjusted						
86 Sliding Door	side door rollers nosiey inside and out Been Done 5/9/17					Awaiting Warranty	
89 Seats	both salloon seat bearings noisey Been Done 5/9/17					Awaiting Warranty	
Safety Inspection							
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
MOT Pre Test							
Vehicle Deep Clean	05/09/2017	09:15	06/09/2017	11:34	144,353	Torquay	TO013770
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	15/09/2017	14:14	15/09/2017	15:39	145,244	Torquay	TO013834
18 Wheels Balance & Alignmen	Ats to rebalance front wheels						

ACCIDENT	18/09/2017	08:09	06/10/2017	09:08	145,302	Torquay	TO013837
71 Body Exterior Acc Repair olsside window and body work							
Defect Repair	09/10/2017	08:03	11/10/2017	15:33	145,524	Torquay	TO013936
56 Comms Equipment MDT Failure/Issue MDT blanks out when data transferred to vehicle. note							
SAFETY INSPECTION	16/10/2017	07:50	18/10/2017	15:59	145,524	Torquay	TO013962
02 Mirrors O/S mirror missing REPLACED 13 Brake Pads Front pads low REPLACED, DISCS MEASURED 26.45mm 13 Brakes 1 Free tight sliders REPAIRED 18 Wheels Check Torques 34 Emergency Light System Interior light inop REPAIRED 34 Emergency Lights Airport light inop WTY Been Done 5/9/17 52 Electrical Aux Torch inop/not charging CHECKED CHARGER OK TORCH U/S REPLACED 86 Sliding Door side door rollers nosiey inside and out Been Done 5/9/17 89 Seats both salloon seat bearings noisey Been Done 5/9/17 Safety Inspection Travel Time MOT							
Vehicle Deep Clean	16/10/2017	12:27	17/10/2017	11:53	145,524	Torquay	TO013966
Vehicle Deep Clean Vehicle Deep Clean							
Unplanned Repair	19/10/2017	15:24	20/10/2017	09:57	145,535	Torquay	TO013986
56 Comms Equipment MDT screen fault PCE to look at again!!							
Breakdown	25/11/2017	19:44	27/11/2017	09:29	152,144	Torquay	TO014155
Breakdown Stuck in Mud							
BREAKDOWN	25/11/2017	19:49	25/11/2017	21:50	152,144	Torquay	TO014426

71 Body Exterior 1 AA assistance required

SAFETY INSPECTION **27/11/2017** **11:19** **28/11/2017** **14:07** **152,319** **Torquay** **TO014162**

17 Tyres replaced o\s\r tyres and n\s\r inner
 18 Wheels Check Torques
 Safety Inspection
 UB Fire Suppression Service
 Gearbox Oil & Filter Change
 92 - C Service
 Service C

Vehicle Deep Clean **28/11/2017** **09:11** **28/11/2017** **13:36** **152,319** **Torquay** **TO014163**

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN **21/12/2017** **09:14** **22/12/2017** **14:41** **155,622** **Torquay** **TO014283**

31 Charging System Battery/Charging Sys red light on carried out checks Merc WTY

Breakdown **01/01/2018** **11:44** **08/01/2018** **14:48** **157,752** **Torquay** **TO014316**

45 Engine 1 Fan belt adrift poss wty Merc ex looking at
 Breakdown Belt has come off

SAFETY INSPECTION **08/01/2018** **14:51** **10/01/2018** **16:05** **157,772** **Torquay** **TO014352**

02 Cab Assembly 1 replaced torch battery
 02 Windows/Glass replaced passenger window switch
 17 Tyres replaced both front tyres
 18 Wheels Check Torques
 87 Stretcher ordered new stretcher battery
 Safety Inspection
 Tail Lift 6 Monthly Inspection Statutory Inspection

Awaiting Parts

Vehicle Deep Clean	09/01/2018	13:15	10/01/2018	10:57	157,772	Torquay	TO014355
Vehicle Deep Clean	Vehicle Deep Clean						
Alcohol Gel Dispenser Instal	19/02/2018	09:46	21/02/2018	08:51	163,324	Torquay	TO014550
02 Windows/Glass	replace scrws on windouse						
34 Lights	o/s/f light replaced bubl						
85 Body Int Alcohol Gel Dispen							
85 Body Interior 1	replace gommet on cupburd						
86 Sliding Door	staimntet door catch						
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	20/02/2018	10:55	20/02/2018	13:42	163,324	Torquay	TO014554
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/02/2018	11:38	23/02/2018	15:23	163,548	Torquay	TO014583
01 Heating 1	night heater reset and cleaned						
02 Mirrors	replaced mirror n/s/f						
71 Body External Steps	re straightened step						
87 Stretcher	ordered new stretcher battery						
Unplanned Repair	15/03/2018	09:37	15/03/2018	09:53	166,811	Torquay	TO014676
34 Lights Bulb Replacement	replaced n\s head light bulb						
Breakdown	24/03/2018	16:39	26/03/2018	09:44	168,097	Torquay	TO014725
Breakdown	Bulge in N/S/R outer tyre checked all ok at station W\shop						

SAFETY INSPECTION	04/04/2018	08:12	06/04/2018	14:22	170,194	Torquay	TO014760
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	replaced both cab and body exting
13 Brake Pads	replaced rear pads
17 Tyres	replaced n\s\r inner tyre
18 Wheels Check Torques	
43 Exhaust System 1	replaced exhaust tail pipe assembly
45 Engine 1	replaced bulk head gromit
86 Sliding Door	straightened side door magnet bracket
89 Seatbelts	tightened seat belt assembly
Safety Inspection	
Fit Poster Holder	Fit Poster Holder
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Handbrake Cable Replacement	Replace rear handbrake cables
93 - D Service	
Service D	

ACCIDENT	04/04/2018	13:59	09/04/2018	08:13	170,194	Torquay	TO014768
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body Exterior Acc Repair	body damage and window smashed on side door
-----------------------------	---

Vehicle Deep Clean	05/04/2018	07:29	06/04/2018	11:49	170,194	Torquay	TO014769
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	18/05/2018	11:13	18/05/2018	11:15	176,601	Torquay	TO014969
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	22/05/2018	10:28	23/05/2018	10:56	177,137	Torquay	TO014983
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brakes 1	replaced front pads and discs
17 Tyres	replaced rear tyres o\s x2
18 Wheels Check Torques	
34 Lights	indercator rear water ingress
34 Lights Bulb Replacement	replaced side light bulb n\s & O\s
54 Sirens	siren surround missing Ordered new one
Safety Inspection	

Awaiting Parts

Unplanned Repair	30/05/2018	07:03	30/05/2018	13:14	178,203	Torquay	TO015012
02 Mirrors	Rear veiw mirror smashed						
SAFETY INSPECTION	26/06/2018	09:04	27/06/2018	15:28	183,659	Torquay	TO015135
18 Wheels Check Torques							
34 Lights Bulb Replacement	replaced head light bulb n\s						
54 Sirens	siren suround missing refitted old one						
71 Body Exterior 1	Body Exterior small dent to left rear light cluster casing						
71 Body Exterior 2	Body Exterior Side door plastic surroud been damaged n\s\ low corner						
86 Doors	replaced side door inner panel						
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	27/06/2018	09:19	27/06/2018	14:30	183,659	Torquay	TO015141
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	29/06/2018	08:22	29/06/2018	11:48	183,770	Torquay	TO015148
34 Lights Bulb Replacement	replaced head light bulb						
Unplanned Repair	03/08/2018	13:58	03/08/2018	14:02	189,201	Torquay	TO015300
34 Lights Bulb Replacement	replaced running light o\s						
Breakdown	07/08/2018	20:37	09/08/2018	10:52	189,780	Torquay	TO015315
Breakdown	lop limp mode						
SAFETY INSPECTION	10/08/2018	09:11	10/08/2018	16:00	190,155	Torquay	TO015332
13 Brake Pads	replaced rear pads						

17 Tyres replaced both front tyres and n\s\r both
 18 Wheels Check Torques
 34 Lights Bulb Replacement replaced indercator bulb o\s\l and bulb in glove box
 Safety Inspection
 92 - C Service
 Service C

Vehicle Deep Clean **10/08/2018** **09:38** **10/08/2018** **14:19** **190,155** **Torquay** **TO015333**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **21/08/2018** **06:39** **21/08/2018** **09:51** **191,186** **Torquay** **TO015380**

34 Lights Bulb Replacement replaced day running bulb
 45 Engine 1 carryed out checks visual and fault codes r\t all ok ??
 Breakdown LOP will not accelerate up hills

BREAKDOWN **21/08/2018** **14:27** **13/09/2018** **11:17** **191,196** **Torquay** **TO015385**

002 Major Unit Replace Eng Engine expired
 Breakdown heard pop,smoke from engine

SAFETY INSPECTION **17/09/2018** **09:55** **18/09/2018** **12:35** **191,783** **Torquay** **TO015494**

02 Cab Assembly 1 replaced brake pedal rubber
 15 Steering 1 replaced o\s steering rack joint end and boot
 18 Wheels Check Torques
 24 Driveshaft 1 replaced prop center bearing
 Safety Inspection
 MOT Pre Test
 Travel Time
 MOT

Vehicle Deep Clean **18/09/2018** **07:50** **19/09/2018** **08:45** **191,783** **Torquay** **TO015500**

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN **18/09/2018** **12:31** **19/09/2018** **13:10** **191,783** **Torquay** **TO015503**

45 Engine 1	oil leak from new engine?						
BREAKDOWN	08/10/2018	10:49	09/10/2018	15:13	194,191	Torquay	TO015579
45 Engine 1	Fumes in cab ?? carried out checks and rlt found exhaust clamp lose note						
BREAKDOWN	19/10/2018	11:11	19/10/2018	11:33	195,734	Torquay	TO015640
45 Engine 1	Engine smoking? poss regen and exhaust smoke R\T all ok checked ok						
BREAKDOWN	29/10/2018	00:24	21/11/2018	15:47	197,564	Torquay	TO015674
Breakdown	Smoke and fumes from engine						
SAFETY INSPECTION	29/10/2018	11:18	30/10/2018	10:41	197,031	Torquay	TO015677
01 Heating 1	Saloon did not heat up - Incorrect setting. (Dan user error) Torch not charging. Reset pins Central cab stow lid loose. RESECURED Front Brake pads below 50% Handbrake adjustment Rear, rear packer loose. REPAIRED replace 2 x 205/75 R16. O/S REAR Left alley light casing smashed. AWAITING PARTS Right alley light does not work. AWAITING PARTS Cab festoon bulb blown. mercedes to further investigate fumes in cab Topped up 1.5 L CARGO MAXX Bridge guides loose x 3 small mudflap replaced New battery added to Mobi med box. (57%)						
02 Cab Assembly 1							
02 Cab Assembly 2							
13 Brake Pads							
13 Handbrake							
16 Suspension 1							
17 Tyres							
18 Wheels Check Torques							
34 Emergency Lights							
34 Lights							
34 Lights Bulb Replacement							
43 Exhaust System 1							
45 Engine Oil Top Up							
55 Tail Lift							
71 Body External Steps							
87a - Medical Equipment Repair							
Safety Inspection	Awaiting Parts						
UB Fire Suppression Service							
Vehicle Deep Clean	30/10/2018	07:24	30/10/2018	13:31	197,031	Torquay	TO015680

Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	23/11/2018	10:03	28/11/2018	14:19	197,899	Torquay	TO015788
45 Engine 1	oil leaking from engine checked and confirmed returning to merc						
SAFETY INSPECTION	10/12/2018	15:20	12/12/2018	15:06	199,301	Torquay	TO015871
02 Cab Assembly 1	central cupboard hinge loose						
15 Steering 1	slight play in both lower ball joints. MONITOR						
15 Steering 2	slight play, inner steering rack. MONITOR						
16 Suspension 1	anti roll bar bolt not 'tight'						
16 Suspension 2	rear N/S packer missing bottom half						
18 Wheels Check Torques							
34 Emergency Lights	n/s alley light smashed. o/s alley light inop.						
34 Lights	passenger torch not charging. ADJUSTED PINS						
45 Engine Oil Top Up	top up 1 ltr cargo maxx						
71 Body Exterior 1	large spray supressor loose						
86 Sliding Door	top magnet stay adrift						
Safety Inspection							
Sealing of stretcher clamp	Sealing of stretcher clamp						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	12/12/2018	07:35	12/12/2018	14:23	199,301	Torquay	TO015881
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	18/01/2019	09:42	18/01/2019	14:28	205,337	Torquay	TO016066
18 Wheels	Body Exterior Wheel wobble at speed with excessive vibration note						
SAFETY INSPECTION	18/01/2019	14:39	23/01/2019	09:37	205,338	Torquay	TO016068
13 Brakes 1	replaced rear pads and discs and hubs front and rear						
18 Wheels Check Torques							
34 Lights	o/s\top marker light inop						
Safety Inspection							

Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab
Gearbox Oil & Filter Change	
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by SWL

Vehicle Deep Clean	21/01/2019	09:27	21/01/2019	12:20	205,338	Torquay	TO016072
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	14/02/2019	08:44	15/02/2019	13:42	209,372	Torquay	TO016171
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Plastic at base of sliding door cracked
-----------	---

SAFETY INSPECTION	06/03/2019	12:22	07/03/2019	15:38	212,285	Torquay	TO016271
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	both extinguisher dates up by next SI
02 Cab Assembly 1	button missing on middle cupboard
18 Wheels	fitted x2 xtvs
18 Wheels Check Torques	
55 Tail Lift	N/S handrail stiff
85 Body Interior 1	Lucas cupboard - shelf edge strip broken, sharp edge
85 Body Interior 2	saloon side paper holder broken.
86 Door Seals	side door rubber split. aprox 1 meter
86 Sliding Door	damage to sliding door cover made temp repare
89 Seatbelts	saloon side seat belt plastic lap piece broken and sharp.
Safety Inspection	
93 - D Service	
Service D	

Vehicle Deep Clean	07/03/2019	07:32	07/03/2019	14:03	212,285	Torquay	TO016276
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	29/03/2019	07:13	03/04/2019	14:22	216,287	Torquay	TO016378
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Sliding Door	Other side door stuck u/s opened stuch door & removed pen jamming door
-----------------	--

Breakdown	saloon heater u/s
Annual Heater Service	Annual Heater Service notes

Unplanned Repair	09/04/2019	13:34	09/04/2019	14:49	217,507	Torquay	TO016429
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	replaced wide angle mirror glass
------------	----------------------------------

SAFETY INSPECTION	17/04/2019	08:12	18/04/2019	13:57	219,009	Torquay	TO016472
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	drivers torch not charging - not pin issue as other torch charges in dock
02 Mirrors	n/s mirror casing damaged
15 Steering 1	front tyres wearing heavy n/s inner tread
17 Tyres Replace	all tyres need replacing
18 Wheels	wheel nut tags damaged x 3
18 Wheels Check Torques	
34 Lights Bulb Replacement	spare bulb missing
55 Tail Lift	bridge guies loose
71 Body Exterior 1	n/s + o/s r lower corner damage
71 Body External Steps	damage to step - leaving sharp edges
86 Door Hinges	sliding door catch plastic trim broken
86 Sliding Door	top magnet adrift
Safety Inspection	
Axle Oil Change	Axle Oil Change
Replace Handbrake Cables	Replace Handbrake Cables
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Annual Air Con Service	Annual Air Condition Service

Vehicle Deep Clean	18/04/2019	09:25	18/04/2019	13:51	219,009	Torquay	TO016478
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	01/05/2019	14:02	03/05/2019	08:47	220,786	Torquay	TO016532
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	screenwash almost empty
31 Charging System	Alternator faulty

Unplanned Repair	07/05/2019	09:20	15/05/2019	14:58	221,006	Torquay	TO016550
31 Battery Chassis 45 Engine 1	chassis battery 'bad and replace' eml on dash - investigation req. checked code r\l still faulty Merc to look at						
Vehicle Deep Clean	30/05/2019	08:36	31/05/2019	15:52	224,578	Torquay	TO016646
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/05/2019	15:16	31/05/2019	15:51	224,578	Torquay	TO016654
13 Brakes 1 16 Suspension 1 18 Wheels Check Torques 45 Engine Oil Top Up 55 Ramp Safety Inspection Tail Lift Inspection	replaced front and rear pads and sensors replaced rear rear spring bushes x2 topped up oil level 1 ltr renewed bolts in ramp run up guides x2						
Unplanned Repair	18/06/2019	14:07	19/06/2019	14:46	227,039	Torquay	TO016734
02 Mirrors	replaced wide angle mirror glass						
Unplanned Repair	19/06/2019	14:47	19/06/2019	15:01	227,189	Torquay	TO016739
34 Lights Bulb Replacement	replaced day running blub n\l						
Vehicle Deep Clean	10/07/2019	11:26	11/07/2019	11:39	230,365	Torquay	TO016843
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	12/07/2019	07:32	12/07/2019	14:57	230,365	Torquay	TO016853
01 Air Conditioning 1 02 Cab Assembly 1 16 Suspension 1	Espar done fan and check cupboard missing button both rear ARB replace						

18 Wheels Check Torques	
34 Emergency Light System	Blue light above side door missing
34 Lights Bulb Replacement	n/s sidelight inop
55 Ramp	strange noise coming from lift when lift is raised up.
55 Tail Lift	N/S HANDRAIL SEIZED IN LOWEST POSITION.
71 Body Exterior 1	corner cap missing from was box - n/s front
86 Door Lock	sliding door magnet adrift
86 Sliding Door	door external hinge cover broken
89 Seats	release mechanism roll pin missing
Safety Inspection	
Engine Change Oil & Filter	

BREAKDOWN	05/08/2019	16:08	06/08/2019	07:08	233,725	Torquay	TO016976
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

MDT Failure/Issue	MDT powering down
-------------------	-------------------

BREAKDOWN	12/08/2019	15:41	12/08/2019	15:49	234,950	Torquay	TO017002
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Doors Rear	rear door stay broken
---------------	-----------------------

SAFETY INSPECTION	19/08/2019	06:37	20/08/2019	15:09	235,992	Torquay	TO017017
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	o/s mirror frame and casing broken
16 Suspension 1	play in both lower ball joints
17 Tyres Tracking	
18 Wheels Check Torques	
41 Turbo	turbo seal split. check hoses for ingress and loose parts
42 Coolant System	radiator bottle float starting to deteriorate
45 Engine Oil Top Up	oil on minimum mark
55 Tail Lift	handrails very loose
86 Sliding Door	top magnet adrift
Safety Inspection	
Travel Time	
Tail Lift Inspection	
MOT	
Brakes Replace Brake Fluid	

Vehicle Deep Clean	20/08/2019	07:25	20/08/2019	13:49	235,992	Torquay	TO017025
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	26/08/2019	10:28	26/08/2019	13:02	236,732	Torquay	TO017053
71 Body Exterior 1	rear spray guard 75% loose						
Unplanned Repair	17/09/2019	15:01	19/09/2019	07:13	240,627	Torquay	TO017158
02 Mirrors	o/s mirror smashed						
SAFETY INSPECTION	03/10/2019	08:03	04/10/2019	07:27	242,962	Torquay	TO017226
02 Cab Ass Fire Extinguisher	fire extinguisher out of date						
02 Cab Assembly 1	button on centre storage cupboard missing						
13 Brake Pads	fron and rear pads req replacement						
13 Discs	front discs below manufacturer spec width						
16 Suspension 1	os r packer slipping						
17 Tyres Replace	Rear tyres req replacement						
18 Wheels Check Torques							
34 Lights Bulb Replacement	replace spare bulb						
55 Tail Lift	bridge guides loose						
86 Sliding Door	top lock / catch loose						
89 Seats	swivel pin assy loose						
Check Winter Pack	checked winter pack						
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Vehicle Deep Clean	04/10/2019	09:06	04/10/2019	13:26	242,962	Torquay	TO017235
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	12/11/2019	08:54	13/11/2019	07:12	247,991	Torquay	TO017409

02 Cab Assembly 1	IN CAB FESTOON BULB INOP
17 Tyres	both F tyres 3mm.
18 Wheels Check Torques	
42 Coolant System	coolant to be topped up. strength also needs to be adjusted
43 Exhaust System 1	exhaust has come off mounting rubbers and seems to have been moved backwards???
45 Engine Oil Top Up	
55 Ramp	bridge guide loose
56 Comms Equipment	aerial missing from roof
71 Body External Steps	step missing right roller
86 Sliding Door	top magnet obviously bent
89 Seatbelts	saloon seat anchor coming loose
Medical Devices Service	EPCR battery 2 under 70%
Safety Inspection	
Pollen Filter Change	Pollen Filter Change
Fuel Filter Change	Change Fuel Filter
Air Filter Change	Air Filter Change
UB Fire Supp 12mts Service	Service of fire suppression system
Tail Lift Inspection	

Vehicle Deep Clean	12/11/2019	10:54	12/11/2019	14:19	247,991	Torquay	TO017410
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	15/11/2019	17:03	20/11/2019	14:20	248,445	Torquay	TO017423
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Add Blue Warning light being used lack of spares
-----------	--

BREAKDOWN	03/12/2019	11:35	03/12/2019	11:47	250,221	Torquay	TO017526
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Battery Chassis	chassis battery req paralel to start engine
--------------------	---

Unplanned Repair	10/12/2019	06:36	11/12/2019	07:10	250,873	Torquay	TO017569
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	crew saying wipers are ineffective sweeping glass
----------------------	---

Unplanned Repair	16/12/2019	12:36	16/12/2019	12:39	251,566	Torquay	TO017606
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement replaced x2 bulbs

SAFETY INSPECTION	23/12/2019	11:31	24/12/2019	13:39	252,537	Torquay	TO017642
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	in cab festoon inop
18 Wheels Check Torques	
45 Engine 1	idle/tensioner req replacement
45 Engine 2	turbo intake pipes removed and adjusted / resealed
45 Engine Oil Top Up	require top up
86 Door Seals	side door seal req replacing
86 Doors	side door top magnet bent
86 Sliding Door	roller bearings not operating smoothly
Safety Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight

Vehicle Deep Clean	24/12/2019	09:30	24/12/2019	13:26	252,537	Torquay	TO017643
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	26/12/2019	22:54	27/12/2019	08:34	252,766	Torquay	TO017646
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres	ATS replaced tyre
Breakdown	Puncture O/S/R

BREAKDOWN	17/01/2020	13:48	22/01/2020	11:33	255,018	Torquay	TO017737
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

42 Coolant System	water pump leaking
86 Doors	replaced both passenger and drivers window switches
Check Vehilce Call Signs	Check vehilce call signs are fitted and correct changed call sign front & back

BREAKDOWN	28/01/2020	08:51	28/01/2020	12:08	255,884	Torquay	TO017786
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body External Steps	straightened side step and replaced guide rollers
------------------------	---

ACCIDENT	03/02/2020	08:20	25/02/2020	14:44	256,120	Torquay	TO017821
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body External Steps	Damage to side step
------------------------	---------------------

Vehicle Deep Clean	03/02/2020	08:48	04/02/2020	09:32	256,120	Torquay	TO017824
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	03/02/2020	15:20	05/02/2020	09:27	256,120	Torquay	TO017829
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	extinguisher out of date by next si x 1
02 Cab Assembly 1	IN CAB STORAGE BOX REQ ATTENTION
17 Tyres	rear axle has mix 110/108 + 113/111 tyres
18 Wheels Check Torques	
34 Emergency Light System	nsr scene light inop
34 Emergency Lights	nsr upper blue corner light damaged, - still functioning normally
34 Lights	os high beam 477 inop
34 Lights Bulb Replacement	os indicator 382 inop
71 Body Exterior 1	multiple damages across ns box body, corners arch ect
71 Body Exterior 2	front reg plate damaged considerably
71 Body Exterior 3	siren cover damaged and sharp
71 Body External Steps	retractable step missing, small mudflap hanging off
85 Body Interior 1	lucas cupboard carcass coming away from body
85 Body Interior 2	saloon large vertical handrail insecure
86 Sliding Door	external trimp above rear of door handle broken and sharp
Camera Installation	ns camera above side door damaged
Safety Inspection	
Engine Change Oil & Filter	
Tail Lift Inspection	

Awaiting Body Repair

Awaiting Body Repair

Awaiting Parts

Unplanned Repair	28/02/2020	10:45	28/02/2020	12:12	256,603	Torquay	TO017956
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body External Steps	checked for step fault rewired power to step bypass genysis
------------------------	---

Breakdown	01/03/2020	18:29	02/03/2020	14:28	256,603	Torquay	TO017966
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace	ATS replaced o/s/r/i tyre
Breakdown	offside rear puncture

SAFETY INSPECTION	20/03/2020	09:31	21/03/2020	14:12	258,740	Torquay	TO018054
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	replaced broken parts on n/s mirror
18 Wheels Check Torques	
34 Lights	high beam not in holder correctly and insecure
34 Lights Bulb Replacement	replaced bulb in glove box
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Replace Handbrake Cables	Replace Handbrake Cables
Annual Heater Service	Annual Heater Service
Wheel Hub Flanges Replacement	replaced front flanges and nuts

Unplanned Repair	24/04/2020	07:42	24/04/2020	07:45	260,949	Torquay	TO018227
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	DRL inop
----------------------------	----------

SAFETY INSPECTION	30/04/2020	11:11	01/05/2020	14:44	261,339	Torquay	TO018256
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	storage button missing
13 Brake Pads	R pads req replacement
13 Discs	R disc req replacement
13 Handbrake	handbrake shoes req replacement
16 Suspension 1	ns r packer missing 50% - REPLACED
16 Suspension 2	both A.R.B req replacement
17 Tyres Replace	n/s r tyres 3 mm
18 Wheels Check Torques	
31 Battery Aux	tail lift battery showing 0V on genisys
34 Lights Bulb Replacement	o/s indicator incorrect colour REPLACED
52 Electrical Aux	EML on dash
55 Tail Lift	bridge guides broken x 3
71 Body External Steps	side step slow to deploy
85 Body Interior 1	Lucas cupboard coming away from carcass
85 Body Interior 2	side bag storage strap broken
86 Door handle	sliding door trim broken - PARTS ON SHELF
86 Door Lock	key set missing manual override physical key (BLACK)
86 Doors	side door top lock insecure plate to door body
86 Sliding Door	top magnet bent

89 Seatbelts
89 Seats
Safety Inspection
Tail Lift Inspection

Jany seat 2 belt anchor worked loose
Jany seat 1 roll pin coming out of swivel mech assy - RESECURED

Vehicle Deep Clean **01/05/2020** **11:47** **02/05/2020** **12:38** **261,339** **Torquay** **TO018263**

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN **17/05/2020** **06:11** **18/05/2020** **14:59** **262,303** **Torquay** **TO018328**

45 Engine 1
Breakdown
Supply Sat Nav

EML light on check and cleared code and R\T all ok
Garmin Sat Nav - No power
carryed out checkes and found conector at back of sat nav adrift refitted

Unplanned Repair **05/06/2020** **11:22** **05/06/2020** **11:23** **264,031** **Torquay** **TO018436**

42 Coolant System check coolant level. Look for signs of leaks. top up coolant

Vehicle Deep Clean **10/06/2020** **07:31** **10/06/2020** **07:33** **264,563** **Torquay** **TO018465**

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean **10/06/2020** **07:33** **11/06/2020** **14:17** **264,563** **Torquay** **TO018466**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **10/06/2020** **13:45** **11/06/2020** **15:00** **264,563** **Torquay** **TO018474**

02 Cab Assembly 1
17 Tyres
18 Wheels Check Torques
19 Chassis 1
31 Battery Comms
34 Lights Bulb Replacement
45 Engine 1
85 Body Interior 1

foam seperator moved between cab and body
n\s\f tyre low replaced
replaced rear mud flap
coms battery low? carryed out checks and charged all ok
replaced day running bulb n\s
ad blue tank mounting bolt missing replaced
oxygen bottle cupboard low corner sharp made repair

86 Door Lock	side door top lock lose tightened
86 Doors	side door top magnet mount bent
86 Sliding Door	external trimp above rear of door handle broken and sharp repaired
Safety Inspection	

Breakdown	29/06/2020	20:45	06/07/2020	13:51	266,578	Torquay	TO018549
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	none start issues
Breakdown	None Starter - NOTE

SAFETY INSPECTION	22/07/2020	09:35	24/07/2020	13:52	268,147	Torquay	TO018634
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brake Pads	replaced front pads and sensors
17 Tyres	replaced rear o\s outer tyre
18 Wheels Check Torques	
34 Lights	replaced bulb in DRLights x1
42 Coolant System	radiator leak Merc to look at
43 Exhaust System 1	DPF brackets snapped off Merc to look at
86 Sliding Door	straightened side door magnet bracket
89 Seats	refitted saloon seat Release bar
Safety Inspection	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
Tail Lift Inspection	

Vehicle Deep Clean	24/07/2020	15:16	24/07/2020	15:18	268,147	Torquay	TO018661
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	25/08/2020	12:00	27/08/2020	07:42	268,980	Torquay	TO018799
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Battery Comms	Cooms battery weak REPLACED	
32 Starting System 1	Vehicle Non start SEE NOTES	
45 Engine 1	Temp Repair to N/S engine mount	Awaiting Parts

Unplanned Repair	07/09/2020	11:29	07/09/2020	11:35	273,073	Torquay	TO018842
34 Lights	replaced DLR bulb o/s & cleaned contat on o/s indercator bulb						
SAFETY INSPECTION	08/09/2020	08:42	09/09/2020	13:41	273,148	Torquay	TO018850
01 Heating 1	Split exhaust REPLACED						
02 Cab Ass Fire Extinguisher	OOD REPLACED						
02 Cab Assembly 1	Centre console button missing NO STOCK						
02 Cab Assembly 2	Cab light inop REPLACED						Awaiting Parts
15 Steering 1	Play in N/S track rod and track rod end REPLACED						
15 Steering 2	Pipe clip loose on P/S resivour REPLACED						
17 Tyres Replace	O/S/F tyre 3mm REPLACED						
17 Tyres Tracking	Due to componet replacment						
18 Wheels Check Torques							
34 Emergency Light System	O/S/F scene light damaged STILL WORKING MONITOR						Monitoring
34 Lighting System	O/S/F side marker inop REPLACED						
45 Engine 1	Temp Repair to N/S engine mount						Monitoring
45 Engine 2	Engine oil leaks CLEANED MONITOR						Monitoring
71 Body Exterior 1	multiple damages across ns box body, corners arch ect						Monitoring
71 Body Exterior 2	O/S/R lower corner cap damaged REPLACED						
71 Body External Steps	retractable step missing, small mudflap hanging off						
85 Body Interior 1	Infection control sturts weak NO STOCK						Awaiting Parts
Safety Inspection MOT							
Vehicle Deep Clean	09/09/2020	06:00	10/09/2020	12:01	273,156	Torquay	TO018860
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	06/10/2020	13:32	09/10/2020	11:48	276,473	Torquay	TO018986
45 Engine 1	lack of power and poss sensor issues max 3000rpm not changing gear						
Breakdown	10/10/2020	22:52	12/10/2020	11:21	276,653	Torquay	TO019012
Breakdown	N/S/F Light Cluster/Indicator						

Vehicle Deep Clean	12/10/2020	07:00	12/10/2020	12:34	276,653	Torquay	TO019021
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/10/2020	08:00	13/10/2020	15:37	276,653	Torquay	TO019028
13 Brake Pads	replaced rear pads						
17 Tyres	fitted new c/c to front and put part worns on rear to replace worn rears						
18 Wheels Check Torques							
24 Driveshaft 1	replaced front prop						
34 Emergency Lights	replaced scene light on n/s						
45 Engine Oil Top Up	topped up oil level 1.5ltrs						
71 Body External W&T Repair	n/s/r corner light cluster damage repaid						
86 Sliding Door	straightened side door magnet bracket						
Safety Inspection							
Tail Lift Inspection							
Unplanned Repair	09/11/2020	07:04	10/11/2020	13:48	279,427	Torquay	TO019174
71 Body External Steps	hit step on rock in hedge - note						
Unplanned Repair	16/11/2020	08:36	16/11/2020	11:15	280,205	Torquay	TO019200
34 Lights Bulb Replacement	ns headlight bulb blown						
Unplanned Repair	16/11/2020	15:30	16/11/2020	15:58	280,950	Torquay	TO019207
89 Seats	freed up saloon seat base plunger						
Vehicle Deep Clean	23/11/2020	11:10	24/11/2020	07:25	281,020	Torquay	TO019255
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/11/2020	14:04	25/11/2020	14:36	281,020	Torquay	TO019260
02 Cab Assembly 1	storage box missing knob - REPLACED						
02 Windows/Glass	passenger window switch broken - REPLACED CONTROLL UNIT						

02 Windscreen Wipers	require replacement - REPLACED	
13 Brakes 1	brake pedal smooth - REPLACED	
17 Tyres	incorrect tyre pressures displayed - CORRECTED	
18 Wheels Check Torques		
24 Driveshaft 1	rear small driveshaft bearing starting to fail - REPLACED	
34 Emergency Lights	NSF upper blues 50% inop - MONITOR	Monitoring
34 Lights Bulb Replacement	OS sidelight inop - REPLACED 501	
41 Turbo	turbo charge feed blowing oil onto pollen filt housing - RESET PIPEWORK	
45 Engine 1	oil leak top front of engine - NOTE	
52 Electrical Aux	eml on dash, texa used - NOTE	
55 Tail Lift	bridge guide bolts missing x 2 MADE 2 NEW BOLTS AND REPLACED	
56 Comms Equipment	aerial damaged - REPLACED	
85 Body Interior 1	saloon bag storage strap broken - REPLACED	
86 Door Lock	covers missing top + bottom side door - FOUND IN SALOON AND REPLACED	
86 Doors Rear	chair support coming away from door - REATTACHED	
86 Sliding Door	both magnets split and not able to hold door - REPLACED	
89 Seats	JANY seat 2 O/S armrest loose - TIGHTENED	
Safety Inspection		
Annual Air Con Service	Annual Air Condition Service	
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change	
UB Fire Supp 12mts Service	Service of fire supression system	
Engine Change Oil & Filter		

Unplanned Repair	01/12/2020	12:31	01/12/2020	14:24	281,726	Torquay	TO019300
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	o/s mirror back and glass broken - REPLACED						
------------	---	--	--	--	--	--	--

Unplanned Repair	28/12/2020	10:25	29/12/2020	06:48	284,466	Torquay	TO019443
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	ns big mirror glass broken - REPLACED						
------------	---------------------------------------	--	--	--	--	--	--

Vehicle Deep Clean	07/01/2021	07:23	07/01/2021	14:13	285,411	Torquay	TO019518
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	07/01/2021	11:41	14/01/2021	15:01	285,411	Torquay	TO019520
02 Cab Assembly 1	Centre console button missing NO STOCK						
02 Windscreen Wipers	Washer cap split REPLACED						
17 Tyres Replace	Rear tyres worn 3mm REPLACED						
18 Wheels Check Torques							
34 Emergency Light System	O/S/F scene light damaged STILL WORKING MONITOR						Monitoring
34 Emergency Lights	NSF upper blues 50% inop - MONITOR						Parts ordered in store
34 Lighting System	N/S/R side marker inop						
45 Engine 1	Temp Repair to N/S engine mount						Monitoring
45 Engine 2	Engine oil leaks CLEANED MONITOR						
45 Engine 3	EML showing SEE NOTES						
55 Tail Lift	Lift Hose starting perish MONITOR						Monitoring
71 Body Exterior 1	multiple damages across ns box body, corners arch ect						Monitoring
71 Body Exterior Acc Repair	Body Exterior N/S rear light surround broken						Awaiting Body Repair
85 Body Interior 1	Infection control sturts weak NO STOCK						Monitoring
87 Oxygen System	Leak from O2 system KEV BEHAN ATTENDED						
Road Test	Extended road tests due to EML light defect.						
Safety Inspection							
UB Fire Supp Repair	Repair of UB Fire Supp System TEMP REPAIR SEE NOTES						
Tail Lift Inspection							

Unplanned Repair	15/01/2021	12:48	15/01/2021	15:42	285,827	Torquay	TO019576
34 Lights Bulb Replacement	spare bulb replaced						

Unplanned Repair	18/01/2021	06:23	18/01/2021	07:30	285,976	Torquay	TO019581
34 Lights Bulb Replacement	replaced ns headlight bulb						

Unplanned Repair	05/02/2021	09:19	05/02/2021	11:51	287,769	Torquay	TO019700
02 Mirrors	os mirror motor damaged - REPLACED						

BREAKDOWN	09/02/2021	04:51	09/02/2021	10:58	288,162	Torquay	TO019720
01 Heating 1 Breakdown	blower motor faulty ordered parts Blowers not working						
Breakdown	09/02/2021	12:02	09/02/2021	15:04	288,656	Torquay	TO019728
Breakdown	no heating in rear checked crew error?						
SAFETY INSPECTION	15/02/2021	10:30	17/02/2021	12:43	288,656	Torquay	TO019760
02 Cab Ass Fire Extinguisher	replaced cab fire exting						
13 Brake Pads	replaced rear pads						
13 Brakes 1	replaced front pads and discs						
18 Wheels Check Torques							
34 Emergency Light System	O/S/F scene light damaged STILL WORKING MONITOR						
34 Emergency Lights	Jon coles fitted leds in front bar						
45 Engine Oil Top Up	topped up oil level						
Safety Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight SWL Doing						
Replace Handbrake Cables	Replace Handbrake Cables						
Tail Lift Inspection	Linked to 12mth service						
Vehicle Deep Clean	15/02/2021	07:11	16/02/2021	07:14	288,656	Torquay	TO019761
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	26/03/2021	08:26	26/03/2021	08:29	292,136	Torquay	TO019947
34 Lights Bulb Replacement	replace os drl						
SAFETY INSPECTION	30/03/2021	10:22	01/04/2021	11:39	292,634	Torquay	TO019973
02 Cab Assembly 1	cab storage button missing - REPLACED						
02 Cab Assembly 2	driver torch missing - NO PARTS						Monitoring
02 Mirrors	OS mirror frame twisted, not broken - ADJUSTED						
13 Handbrake	requires adjusting - ADJUSTED						

16 Suspension 1	both A.R.B worn	
17 Tyres Replace	OSF tyre cut down to cords - REPLACED	
17 Tyres Tracking	heavy inner edge wear to os front tyres - TRACKING ADJUSTED	
18 Wheels Check Torques		
34 Emergency Light System	OS rear corner blue plastic broken - MONITOR (C.H.A)	Monitoring
34 Emergency Lights	NSF upper blues 50% inop - MONITOR	Monitoring
34 Lights	cab courtesy light inop - REPLACED	
34 Lights Bulb Replacement	NSF sidelight inop - REPLACED	
42 Radiator	coolant level low - TOPPED UP	
43 Exhaust System 1	tail pipe rusted and thin but not 'holed' - MONITOR	Monitoring
45 Engine 1	Temp Repair to N/S engine mount	
45 Engine 2	both engine mounts torn - REPLACED	
54 Sirens	bull horn intermittent - REPAIRED	
55 Ramp	bridge guides loose x 3 - REPLACED 3 X THROUGH BOLTS	
55 Tail Lift	Lift Hose starting perish MONITOR	
71 Body Exterior 1	multiple damages across ns box body, corners arch ect	Monitoring
71 Body Exterior 2	NSR corner cap damaged - REPAIR MADE	
71 Body Exterior Acc Repair	Body Exterior N/S rear light surround broken - REPAIRED	
85 Body Interior 1	Infection control sturts weak NO STOCK	Monitoring
85 Body Interior 2	laundry cupboard shelf shark - REMOVED SHELF EDGE	
86 Door Lock	rear door lower lock does not hold - ADJUSTED	
86 Sliding Door	top lock coming away from door - REPAIRED W/BODY RIVETS	
87 Chairs	carry chair bracket on rear door insecure - RESECURED TO DOOR	
87a - Medical Equipment Repair	EPCR batts health below 70% - NO PARTS	Monitoring
89 Seatbelts	saloon captains chair belt anchor loose - RESECURED	
89 Seats	cab seat armrests loose x 2 - RESECURED	
Safety Inspection		
Annual Heater Service	Annual Heater Service	

Vehicle Deep Clean	31/03/2021	07:00	31/03/2021	14:29	292,634	Torquay	TO019980
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	17/05/2021	06:00	19/05/2021	10:00	292,645	Dorchester	DC024994
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 2	driver torch missing - NO PARTS	
02 Windscreen Wipers	washers blocked/blades poor	
03 Instruments & Sensors 1	Fire Trace faulty and bypassed	
03 Instruments & Sensors 2	Genisys panel not lighting up selected function	Monitoring
13 Discs	Rear discs worn have lip on them, pads brand new, replace when worn	Monitoring
15 Steering 1	O/S inner and outter rack ends	

16 Suspension 1	Rear shocks/4x slipp pads split							
16 Suspension 2	Front struts and arms have play						Monitoring	
17 Tyres	n/s/f tyre u/s							
18 Wheels	valve extensions missing							
18 Wheels Check Torques								
34 Emergency Light System	OS rear corner blue plastic broken - MONITOR (C.H.A)							
34 Emergency Lights	NSF upper blues 50% inop - MONITOR							
34 Lights	number plate lights inop							
43 Exhaust System 1	tail pipe rusted and thin but not 'holed' - MONITOR							
45 Engine Ad Blue	top up							
52 Electrical Aux	CCTV inop							
71 Body Exterior 1	multiple damages across ns box body, corners arch ect							
85 Body Interior 1	Infection control sturts weak NO STOCK							
85 Body Interior 2	linen cupboard repair has left sharp edges							
86 Door Lock	lock set required							
86 Doors Rear	Rubber seal split hanging off							
86 Sliding Door	bearings rough							
87a - Medical Equipment Repair	EPCR batts health below 70% - NO PARTS							
89 Seats	Drivers seat Swab u/s							
Safety Inspection								
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service							
Air Filter Change	Air Filter Change							
Fuel Filter Change	Change Fuel Filter							
Pollen Filter Change	Pollen Filter Change							
Vehicle Deep Clean	19/05/2021	13:47	20/05/2021	12:00	293,558	Dorchester		DC025042
Vehicle Deep Clean	Vehicle Deep Clean							
SAFETY INSPECTION	23/06/2021	09:44	25/06/2021	12:54	298,183	Dorchester		DC025308
01 Heating 1	Night heater inop							
03 Instruments & Sensors 2	Genisys panel not lighting up selected function						Monitoring	
13 Discs	Rear discs worn have lip on them, pads brand new, replace when worn						Monitoring	
16 Suspension 2	Front struts and arms have play						Monitoring	
18 Wheels Check Torques								
42 Radiator	Rad leaking							
71 Body External Steps	rear step damaged						Monitoring	
85 Body Interior 1	door hold bar stay damaged							
86 Door Seals	rear door seal replaced							
86 Doors	small rear door split on corner							

86 Doors Rear Safety Inspection Tail Lift Inspection	Large rear door has excessive play in bottom hinge					Monitoring	
Vehicle Deep Clean	25/06/2021	14:00	29/06/2021	14:21	298,198	Dorchester	DC025329
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	12/07/2021	11:15	12/07/2021	11:34	300,381	Dorchester	DC025424
71 Body External Steps	Side step bent, straighten out						
Unplanned Repair	19/07/2021	11:45	19/07/2021	13:56	300,381	Dorchester	DC025482
71 Body External Steps	Side step smashed off						
Unplanned Repair	27/07/2021	13:45	27/07/2021	14:04	301,495	Dorchester	DC025553
86 Sliding Door	Door open warning going off. Trace to micro switch. Adjust and test, ok						
Breakdown	03/08/2021	18:14	04/08/2021	13:48	302,816	Dorchester	DC025603
02 Cab Assembly 1 03 Instruments & Sensors 2 13 Brakes 1 13 Discs 16 Suspension 2 56 Comms Equipment 71 Body External Steps 85 Body Interior 1 86 Doors Rear Breakdown Travel Time 18 Wheels Check Torques Safety Inspection	window switch u/s Genisys panel not lighting up selected function fronts worn Rear discs worn have lip on them, pads brand new, replace when worn Front struts and arms have play aerial missing rear step damaged light inop o/s middle Large rear door has excessive play in bottom hinge nearside front wheel wobbling					Monitoring Monitoring	

Brake Fluid Change	Brake Fluid Change						
Vehicle Deep Clean	05/08/2021	08:30	05/08/2021	13:09	302,977	Dorchester	DC025615
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	10/08/2021	22:30	11/08/2021	09:31	303,790	Dorchester	DC025656
54 Sirens	Sirens reported inop.See notes						Awaiting Parts
Unplanned Repair	16/08/2021	09:43	16/08/2021	10:00	304,252	Dorchester	DC025700
54 Sirens	Sirens reported inop.See notes						
Breakdown	07/09/2021	16:34	08/09/2021	10:09	305,436	Dorchester	DC025862
Breakdown	Side door handle snapped off						
SAFETY INSPECTION	11/09/2021	07:51	13/09/2021	15:06	305,500	Dorchester	DC025889
03 Instruments & Sensors 2	Genisys panel not lighting up selected function...REPLACED on DC025700						
18 Wheels Check Torques							
34 Lights							
45 Engine 1							
45 Engine Ad Blue							
85 Body Interior 1							
86 Door Lock							
86 Doors Rear							
86 Sliding Door							
Safety Inspection							
Travel Time							
Engine Change Oil & Filter							
MOT							

Vehicle Deep Clean	14/09/2021	08:00	14/09/2021	16:00	305,833	Dorchester	DC025946
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	26/10/2021	08:56	26/10/2021	13:37	309,443	Dorchester	DC026214
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	26/10/2021	13:42	27/10/2021	14:33	309,450	Dorchester	DC026218
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	Interior light inop,replace bulb	
18 Wheels Check Torques		
34 Lighting System	n/s/ scene light at 50%	Awaiting Parts
44 Fuel System 1	Fuel Angel missing	
45 Engine Oil Top Up		
86 Doors Rear	Large rear door has play in bottom hinge	Monitoring
Safety Inspection		
Tail Lift Inspection		

Unplanned Repair	22/11/2021	08:45	22/11/2021	09:15	310,946	Dorchester	DC026394
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	n/s mirror glass smashed,replace
34 Lights Bulb Replacement	o/s/f indicator inop,replace bulb

SAFETY INSPECTION	11/12/2021	06:20	13/12/2021	08:00	313,870	Dorchester	DC026549
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

03 Instruments & Sensors 1	service light on	
17 Tyres	fronts worn	
18 Wheels	Rim u/s	
18 Wheels Check Torques		
34 Lighting System	n/s/ scene light at 50%	
34 Lights	N/S/R fog and taill light inop	
45 Engine Ad Blue	top up	
55 Tail Lift	LED lamp o/s not working correctly.....NO PARTS	Monitoring
71 Body Exterior 1	N/S marker light damaged and large scratches down n/s	
71 Body Exterior 2	rear flap loose	
86 Doors Rear	Large rear door has play in bottom hinge	Monitoring

Safety Inspection

Travel Time

UB Fire Supp 6mts Service

UB Fire Supp 6mts Service

UB Fire Supp 12mts Service

Service of fire suppression system

Annual Air Con Service

Annual Air Condition Service

Tail Lift Inspection

Vehicle Deep Clean	14/12/2021	08:30	14/12/2021	14:03	313,884	Dorchester	DC026577
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean

Vehicle Deep Clean

ACCIDENT	01/01/2022	05:54	03/01/2022	08:02	316,614	Dorchester	DC026733
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Emergency Lights
Breakdown

n/s/r blue light smashed off. Carry out temp repair. No parts
rear blue light came off/damaged?

Awaiting Parts

Unplanned Repair	15/01/2022	11:00	15/01/2022	13:57	318,123	Dorchester	DC026837
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

85 Body Interior 1

Stryker charger has fallen off

SAFETY INSPECTION	17/01/2022	11:11	18/01/2022	13:00	318,665	Dorchester	DC026850
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher

extinguisher OOD

02 Windscreen Wipers

replace blades

15 Steering 1

reservoir hose loose

17 Tyres Replace

all rears low

18 Wheels Check Torques

34 Emergency Lights

n/s/r blue light smashed off.

41 Turbo

boost seals leaking

44 Add Ad Blue

top up

45 Engine Oil Top Up

top up

55 Tail Lift

LED lamp o/s not working correctly.....NO PARTS

71 Body Exterior 1

mudflap loose

85 Body Interior Roof

roof fan not working, bearings noisy

86 Doors Rear

Large rear door has play in bottom hinge

Safety Inspection
Travel Time
Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Vehicle Deep Clean 18/01/2022 13:18 19/01/2022 10:30 318,669 Dorchester DC026866

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 08/02/2022 14:24 09/02/2022 12:13 322,384 Dorchester DC027041

Breakdown defective back door & bull horn Monitoring

Breakdown 09/02/2022 06:34 10/02/2022 08:18 322,398 Dorchester DC027042

31 Charging System
Breakdown Alternator failure reported
defective back door & bull horn

Unplanned Repair 21/02/2022 08:30 21/02/2022 09:00 322,599 Dorchester DC027107

86 Doors Rear large rear door stay snapped

Vehicle Deep Clean 28/02/2022 12:07 28/02/2022 15:00 323,575 Dorchester DC027147

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 01/03/2022 11:47 03/03/2022 11:46 323,575 Dorchester DC027151

18 Wheels Check Torques
Safety Inspection
Tail Lift Inspection
02 Windscreen Wipers Blades damaged
86 Sliding Door magnet bent
02 Cab Assembly 1 fire ext out of date
34 Lights 2x side light bulbs out
52 Electrical Aux CCTV red light on box
85 Body Interior 1 Panel below attendant seats extremly rusty, replacement required Monitoring
Pollen Filter Change Pollen Filter Change

45 Engine Ad Blue	top up						
03 Instruments & Sensors 1	service light on						
86 Doors Rear	Excessive play in rear door hinges. Bodyshop required					Monitoring	
55 Tail Lift	Lights damaged						
45 Engine 1	injectors blowing						
17 Tyres	o/s/f low						
13 Brake Pads	Rears low						
01 Air Conditioning 1	A/C adjuster u/s						

02 Pipeline Annual Inspection	28/02/2022	11:00	28/02/2022	12:00	323,575	MDT Weymouth	DW000810
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults						
-------------------------------	---	--	--	--	--	--	--

Breakdown	20/03/2022	20:08	21/03/2022	05:25	324,259	Dorchester	DC027307
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	MDT not powering UP,						
-----------	----------------------	--	--	--	--	--	--

Unplanned Repair	22/03/2022	11:45	22/03/2022	12:15	324,259	Dorchester	DC027323
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

52 Electrical Aux	Satnav not working						
-------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	29/03/2022	08:00	29/03/2022	08:15	325,327	Dorchester	DC027358
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

44 Add Ad Blue	top up						
----------------	--------	--	--	--	--	--	--

Unplanned Repair	02/04/2022	08:30	02/04/2022	08:55	325,831	Dorchester	DC027385
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	O/S Headlight bulb						
----------------------------	--------------------	--	--	--	--	--	--

Breakdown	07/04/2022	17:39	08/04/2022	09:02	326,407	Dorchester	DC027421
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	broken side door handle; VOR						
-----------	------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	14/04/2022	07:40	15/04/2022	14:00	326,407	Dorchester	DC027472
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
13 Handbrake	Centre pivot siezed
13 Brake Pads	fronts low
17 Tyres	n/s/f low
34 Lights	n/s DRL out
89 Seats	driver side adjust handle broken
34 Lighting System	Number plate lights not working
71 Body External Steps	Side step switch u/s , bypassed for now..parts on order
43 Exhaust System 1	Tail pipe rottted
45 Engine Ad Blue	top up
86 Sliding Door	magnet bent

Vehicle Deep Clean	19/04/2022	11:18	20/04/2022	08:20	327,725	Dorchester	DC027501
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	26/04/2022	14:00	26/04/2022	15:01	328,537	Dorchester	DC027574
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	LOP reported.Carry out checks.Replace airmass meter, carry out road test
-------------	--

Breakdown	26/04/2022	20:43	28/04/2022	11:54	328,621	Dorchester	DC027575
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	limp mode; VOR
45 Engine 1	EML/LOP.Carry out checks.Lambda sensor failed

Vehicle Deep Clean	24/05/2022	08:30	25/05/2022	08:00	330,488	Dorchester	DC027732
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	24/05/2022	14:36	25/05/2022	15:30	330,488	Dorchester	DC027733
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Annual Heater Service	Annual Heater Service
Engine Change Oil & Filter	

Tail Lift Inspection	
85 Body Interior 1	Panel below attendant seats extremly rusty, replacement required
86 Doors Rear	Excessive play in rear door hinges. Bodyshop required
34 Lights Bulb Replacement	n/s DRL out
02 Cab Assembly 1	brake pedal rubber split
34 Lights	o/s marker light inop
86 Sliding Door	magnet bent again
01 Heating 1	Saloon heater exhaust split
18 Wheels	o/s/f rim cracked,,,,slow puncture
85 Body Interior 2	PPE cupboard wont stay open...defected by crew. struts needed
71 Body External Steps	Step u/s
02 Windscreen Wipers	washers not working

Unplanned Repair	15/06/2022	08:00	27/07/2022	07:49	331,799	Dorchester	DC027902
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

27 Transmission Automatic	gear selector sticking, ecu fault
---------------------------	-----------------------------------

SAFETY INSPECTION	19/07/2022	06:00	20/07/2022	06:29	331,798	Dorchester	DC028107
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
55 Tail Lift	Roll stop siezed
16 Suspension 1	ARB worn
02 Windscreen Wipers	blades u/s
45 Engine Ad Blue	top up
85 Body Interior 1	catch cover damage

Vehicle Deep Clean	27/07/2022	14:30	29/07/2022	09:13	331,812	Dorchester	DC028178
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	24/08/2022	07:39	25/08/2022	12:12	334,153	Dorchester	DC028327
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques

Safety Inspection							
Tail Lift Inspection							
MOT	Marsh road @ 11:00 25.08.2022						
Travel Time							
89 Seats	drivers seat raise/lower lever broken						
44 Add Ad Blue	top up						
45 Engine Oil Top Up	top up						
02 Cab Ass Fire Extinguisher	OOD						
02 Cab Assembly 1	passenger footwell plate damaged						
86 Door Lock	rear door barrel and cylinder seized & catches sticking						
86 Sliding Door	top magnet bracket bent						
18 Wheels	OSR outer rim leaking, tyre found U/S						
Vehicle Deep Clean	26/08/2022	09:03	26/08/2022	15:37	334,170	Dorchester	DC028336
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	11/10/2022	11:00	13/10/2022	08:02	337,792	Dorchester	DC028430
52 Electrical Aux	Radio & Comm System Radio aerial missing						
71 Body Exterior 1	Body Exterior offside rear light housing						
03 Instruments & Sensors 1	ENGINE ENG MAN LIGHT AND AD BLUE						
34 Lights	Lighting System O/S REAR BRAKE LIGHT LENS BROKEN						
71 Body Exterior 2	Lighting System O/s rear break Light broken						
45 Engine Ad Blue	System malfunction						
Breakdown	20/11/2022	21:20	21/11/2022	06:30	343,229	St Leonards	SL038174
Breakdown	Engine management light on - Defect moved to inspection job card					Monitoring	
SAFETY INSPECTION	22/11/2022	13:30	22/11/2022	13:30	343,361	St Leonards	SL038194
18 Wheels Check Torques							
Safety Inspection							
SAFETY INSPECTION	22/11/2022	13:30	25/11/2022	09:00	343,361	St Leonards	SL038195
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						

Breakdown	Engine management light on						
56 Comms Equipment	Comms Power Check MDT turning off						
13 Handbrake	Brakes Hand brake not holding at top notch.						
34 Lights	Electrical Auxs Offside rear reverse light lens (x2) cracked.						
34 Lights Bulb Replacement	Front indicators showing white. Replaced bulbs x2.						
85 Body Interior 1	CCTV cupboard struts u/s. Replaced x1-no parts.						
52 Electrical Aux	230v w/lights broken. No parts.						Monitoring
85 Body Interior Roof	Extractor fan n/w.						Monitoring
85 Body Interior 2	Roof intake button n/w on saloon genisys panel.						Monitoring
44 Fuel System 1	Fuel cap leaking. Replaced.						
02 Cab Assembly 1	Cubby lock & button missing. Replaced.						
17 Tyres Replace	Front tyres worn inner edge. Replaced x2.						
17 Tyres Tracking	Needs tracking.						
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
Tail Lift Inspection							
Vehicle Deep Clean	25/11/2022	11:16	25/11/2022	11:17	343,361	St Leonards	SL038231
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	25/11/2022	11:17	26/11/2022	11:00	343,361	St Leonards	SL038232
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	29/11/2022	14:10	30/11/2022	06:30	343,500	St Leonards	SL038272
Breakdown	defective side door handle						Monitoring
Unplanned Repair	29/11/2022	15:00	29/11/2022	16:00	343,500	St Leonards	SL038291
17 Tyres Replace	N/S/R/O tyre replaced by ATS (Dorchester)						
Breakdown	11/12/2022	11:32	12/12/2022	06:15	344,947	St Leonards	SL038416
Breakdown	Puncture						
Breakdown	12/12/2022	14:30	16/12/2022	12:00	344,947	St Leonards	SL038436

Breakdown 27 Transmission Automatic 41 Turbo	Faulty gearbox; vor Gearbox fault Impeller broken up. Replaced						
Breakdown	18/12/2022	21:47	18/12/2022	22:15	345,163	St Leonards	SL038528
Breakdown	Amber Engine Warning Light						
Breakdown	18/12/2022	21:53	19/12/2022	11:15	345,163	St Leonards	SL038529
Breakdown	O/S R Outer saying its pulling						Monitoring
Unplanned Repair	28/12/2022	09:00	28/12/2022	10:00	346,163	St Leonards	SL038614
71 Body External Steps	Doors Side step coming out and going back in. Repair broken side step wiring						
Annual Air Con Service At	18/01/2023	15:00	18/01/2023	15:30	348,475	St Leonards	SL038835
34 Lighting System	olsf ind n\w, replace bulb & repair connections.						
Unplanned Repair	06/02/2023	07:00	06/02/2023	08:30	350,831	St Leonards	SL039003
34 Emergency Light System	N/S/R top corner blue light damaged						
Breakdown	08/03/2023	10:17	04/04/2023	16:00	354,203	St Leonards	SL039308
Breakdown 001 Recover Vehicle 44 Fuel System 1 002 Major Unit Replace Eng	LOW ON POWER THEN JUDDERED AND STOPPED Vehicle Recovery Replace high pressure fuel pump Engine u/s Rygors Westbury to investigate						
O2 Pipeline Annual Inspected	09/03/2023	14:44	09/03/2023	14:45	354,203	MDT Ferndown	TF002556

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - No faults found.

Vehicle Deep Clean	05/04/2023	10:00	05/04/2023	17:30	354,289	St Leonards	SL039595
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	06/04/2023	09:30	08/04/2023	08:46	354,289	St Leonards	SL039606
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.	
Safety Inspection	Carried out inspection	
52 Electrical Aux	230v w/lights broken. No parts.	
85 Body Interior Roof	Extractor fan n/w.	Monitoring
85 Body Interior 2	Roof intake button n/w on saloon genisys panel.	Monitoring
Breakdown	O/S R Outer saying its pulling	
71 Body External Steps	Body Exterior side step retracting when door open	
Pollen Filter Change	Pollen Filter Change. Done.	
Tail Lift Inspection	Done.	
02 Cab Assembly 1	Interior light n/w. Replaced bulb.	
02 Cab Assembly 2	Cubby lid broken off. Reattached.	
89 Seats	Passenger seat arm rest broken off. Repaired frame & reattached.	
02 Cab Ass Fire Extinguisher	out of date x2. Replaced x2.	
17 Tyres Replace	O/S/F tyre low tread. Replaced.	
31 Battery Comms	comm's not charging from shore line.	

Unplanned Repair	11/04/2023	08:00	13/04/2023	09:00	354,566	St Leonards	SL039676
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine Ad Blue	Ad blue warning light on - Andy Boyt to repair (F/Comms) renew filler.
56 Comms Equipment	MDT inop. Removed, tested & replaced comm's battery
001 Recover Vehicle	Vehicle Recovery
Road Test	Carry out extended road test. All ok @ time of test

Unplanned Repair	18/04/2023	12:30	18/04/2023	13:41	354,739	St Leonards	SL039775
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Aux	Replace Aux battery
----------------	---------------------

Unplanned Repair	20/04/2023	07:00	20/04/2023	08:30	354,870	St Leonards	SL039799
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine Ad Blue	Ad blue warning light on (see notes)								
Unplanned Repair	04/05/2023	08:30	04/05/2023	09:19	356,313	St Leonards	SL040005		
18 Wheels	Wheel rim damaged - Replace wheel and tyre								
Unplanned Repair	07/05/2023	08:27	07/05/2023	11:37	356,436	St Leonards	SL040029		
31 Battery Comms	Comm Battery u/s. repalced								
Breakdown	14/05/2023	20:39	15/05/2023	11:00	357,931	St Leonards	SL040117		
Breakdown	N/S Blue LED Out					Monitoring			
Vehicle Deep Clean	18/05/2023	08:30	18/05/2023	17:00	358,471	St Leonards	SL040177		
Vehicle Deep Clean	Vehicle Deep Clean								
SAFETY INSPECTION	18/05/2023	17:00	20/05/2023	12:06	358,471	St Leonards	SL040188		
18 Wheels Check Torques									
Safety Inspection									
85 Body Interior Roof	Extractor fan n/w. no stock					Monitoring			
85 Body Interior 2	Roof intake button n/w on saloon genisys panel.								
Breakdown	N/S Blue LED Out								
Tail Lift Inspection									
85 Body Interior 1	Fit P clips for AVP								
17 Tyres Replace	N/S/F tyre worn low								
13 Brakes 1	Front brake pads low and discs worn. Replaced								
13 Brakes 2	O/S/F caliper slider seized and bleed nipple Broken off. Replaced and bled								
34 Emergency Lights	N/S Rear side blue light not working due to water ingress. Replaced								
85 Body Interior 3	saloon Mic broken. Replaced								
UB Fire Supp 12mts Service	Service of fire supression system								
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service								
Engine Change Oil & Filter									
Annual Heater Service	Annual Heater Service								

ACCIDENT	29/05/2023	11:06	29/05/2023	11:21	359,464	St Leonards	SL040324
34 Lights	N/S/R pod lights all smashed. Replaced						
Breakdown	30/05/2023	05:12	01/06/2023	09:00	359,781	St Leonards	SL040332
Breakdown 15 Steering 1 Aux drive belt change	Power Steering Gone Replace p/s pump Aux drive belt change						
Unplanned Repair	17/06/2023	11:30	17/06/2023	12:37	362,306	St Leonards	SL040609
17 Tyres	2x rear puncture, 2x rear rims						
SAFETY INSPECTION	29/06/2023	12:30	30/06/2023	12:00	364,001	St Leonards	SL040790
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
85 Body Interior Roof	Extractor fan n/w. no stock						
34 Lights	Lighting System COVER OF NEARSIDE REAR BRAKE LIGHT DAMAGE						
34 Lighting System	Lighting System BROKEN NEARSIDE REAR BRAKE LIGHT COVER						
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
54 Horns	Bull horn n/w. Repaired.						
17 Tyres Replace	O/S/F tyre low tread. Replaced.						
13 Brakes 1	Rear pads low.						
13 Calipers	Rear caliper piston rubbers torn. Replaced x2.						
Vehicle Deep Clean	03/07/2023	07:07	03/07/2023	11:04	364,005	St Leonards	SL040829
Vehicle Deep Clean	Vehicle Deep Clean						
Replace Vehicle Fuel Card	09/07/2023	08:00	09/07/2023	08:00	365,084	St Leonards	SL040951

Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Unplanned Repair	09/07/2023	08:30	09/07/2023	09:30	365,112	St Leonards	SL040952
01 Air Conditioning 1	Aircon belt adrift. Replaced & r/test.						
Breakdown	27/07/2023	14:42	02/08/2023	16:42	368,317	St Leonards	SL041298
Breakdown	noise coming from near side rear wheel area						
11 Axle Rear	Noise from rear axle, Replace rear axle.						
Travel Time	Carry out road test						
Replace Handbrake Cables	Replace Handbrake Cables						
13 Brakes 1	Replace rear brake hoses and bleed rear brakes						
18 Wheels Check Torques	Rear wheels						
Vehicle Deep Clean	07/08/2023	16:00	08/08/2023	13:00	368,689	St Leonards	SL041436
Vehicle Deep Clean	Vehicle Deep Clean						
MOT EXPIRES	10/08/2023	10:15	10/08/2023	11:15	368,689	St Leonards	SL041473
MOT							
SAFETY INSPECTION	10/08/2023	13:00	11/08/2023	08:30	368,689	St Leonards	SL041478
18 Wheels Check Torques							
Safety Inspection							
Check Winter Pack	Fit winter pack						
17 Tyres Replace	Replace n/s/f tyre						
86 Sliding Door	Side door rollers worn - No parts						
34 Lights	Replace interior light bulb						
86 Doors	Repair side door central locking, Adj cables & mechanism so it does not jam.						
Unplanned Repair	05/09/2023	08:30	05/09/2023	09:00	372,293	St Leonards	SL041829
86 Doors Rear	Rear door stay snapped off						

Monitoring

Unplanned Repair	09/09/2023	06:00	09/09/2023	12:01	372,491	St Leonards	SL041873
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

01 Air Conditioning 1	A/C System Saloon no A/c in back of vehicle						
-----------------------	---	--	--	--	--	--	--

Vehicle Deep Clean	18/09/2023	06:00	18/09/2023	13:30	373,401	St Leonards	SL041972
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	20/09/2023	09:30	22/09/2023	09:56	373,401	St Leonards	SL042025
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Tail Lift Inspection							
Replace Handbrake Cables	Done 07/23						
Recall Notification	Mercedes airbag recall						
52 Electrical Aux	Saloon genysys panel faulty. replace						
86 Sliding Door	Top latch insecure. resecure latch holder onto door.						
89 Seatbelts	Drivers seatbelt frayed. replace belt.						
89 Seats	Front attendant seat swivel bearings worn. replace bearings.						
24 Driveshaft 1	Front propshaft uj u/s. replaced propshaft.						
16 Suspension 1	Rear roll bar drop link bushes worn. replace bushes x4.						
15 Steering 1	Osf inner rack joint play. replace rod and end joint. carry out tracking.						
71 Body Exterior 1	Body corner caps x2 damaged. replace caps.						
13 Handbrake	Handbrake excess travel. adjust shoes and cables.						
01 Air Conditioning 1	Saloon ac. replaced rear condensor and replace hose from compressor.						
85 Body Interior 1	Saoon roof extractor u/s. no parts. - MONITOR						
						Monitoring	

Unplanned Repair	25/10/2023	06:00	26/10/2023	17:43	375,437	St Leonards	SL042520
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Doors	Slide Door Faulty see notes.						
----------	------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	31/10/2023	07:00	31/10/2023	16:00	375,868	St Leonards	SL042574
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
85 Body Interior 1	Saoon roof extractor u/s. no parts. - MONITOR						

86 Doors	Doors Spring came off of side door.						
Brake Fluid Change	Brake Fluid Change						
Tail Lift Inspection							
02 Cab Assembly 1	Cab passenger window switch broken.						
02 Cab Assembly 2	Cab drivers window switch broken						
87 - Stretchers/Chairs/Boards	Stretcher belts in wrong position.						
55 Tail Lift	Tail lift side rails loose						
85 Body Interior 2	Saloon rear ceiling grab handle loose.						
13 Brakes 1	Cab handbrake travel becoming excessive.						
86 Doors Rear	N/S/R Door lock overridden						
85 Body Interior 3	Saloon locker 'RH1' hinge broken.						
13 Brake Test	Carry out brake test.						
Vehicle Deep Clean	01/11/2023	09:00	01/11/2023	15:00	375,878	St Leonards	SL042599
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	02/12/2023	08:00	02/12/2023	08:15	377,745	St Leonards	SL043022
34 Lights Bulb Replacement	Replace running light bulb						
Vehicle Deep Clean	10/12/2023	09:39	10/12/2023	16:00	378,233	St Leonards	SL043127
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	12/12/2023	06:00	12/12/2023	16:00	378,233	St Leonards	SL043158
18 Wheels Check Torques							
Safety Inspection							
56 Comms Equipment	MDT Failure/Issue mdt wont allow crew to enter status						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Tail Lift Inspection	Tail lift inspection						
Pollen Filter Change	Pollen Filter Change						
87 - Stretchers/Chairs/Boards	Stretcher belts wrongly fitted						
71 Body External Steps	N/S Side step operating incorrectly						
13 Brake Test	Carry out brake test						
Unplanned Repair	15/12/2023	13:28	15/12/2023	13:29	378,368	St Leonards	SL043215

86 Sliding Door sliding door locking jamming. adjusted inner mechanism and lubricated.

SAFETY INSPECTION 23/01/2024 15:00 24/01/2024 14:03 381,052 St Leonards SL043689

18 Wheels Check Torques
 Safety Inspection
 86 Sliding Door Doors Side door sticking and then opening
 Tail Lift Inspection
 86 Door Seals Both front door seals split - No stock for O/S/F Awaiting Parts
 34 Lights Bulb Replacement N/s headlight and side light bulbs blown
 85 Body Interior 1 Cabin consol lock broken

Vehicle Deep Clean 25/01/2024 08:44 25/01/2024 14:42 381,056 St Leonards SL043715

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean 09/03/2024 11:26 10/03/2024 12:26 386,129 St Leonards SL044333

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 11/03/2024 08:12 11/03/2024 14:10 386,129 St Leonards SL044344

18 Wheels Check Torques Checked.
 Safety Inspection Carried out inspection.
 13 Brakes 1 Front pads worn. Replaced.
 02 Cab Ass Fire Extinguisher Out of date. Replaced.
 86 Door Lock Rear door lock n/w with key. Removed, unsieze,lubbed,refitted.
 02 Cab Assembly 1 Cubby box catch n/w. Repaired.
 02 Cab Assembly 2 Bonnet sound proofing adrift. Resecured.
 45 Engine 1 Inlet seals leaking oil. Replaced resenator.
 86 Sliding Door Rollers siezed. Replaced.
 52 Electrical Aux 230V w/lights broken. No parts. Monitoring

02 Pipeline Annual Inspection 12/03/2024 08:24 12/03/2024 08:26 386,155 MDT Ferndown TF003319

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - No faults found.

Breakdown	17/03/2024	12:03	17/03/2024	12:30	386,850	St Leonards	SL044449
Breakdown 33 Ignition System	Red brake warning Replace key fob						
ACCIDENT	25/03/2024	07:40	27/03/2024	15:43	386,852	St Leonards	SL044570
71 Body Exterior Acc Repair	Involved in incident						
Unplanned Repair	03/04/2024	08:00	03/04/2024	08:15	388,232	St Leonards	SL044740
02 Windscreen Wipers	Replaced						
SAFETY INSPECTION	19/04/2024	15:00	29/04/2024	12:00	390,669	St Leonards	SL044978
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
86 Door Seals	Both front door seals split - No stock for O/S/F. Replaced o/s.						
52 Electrical Aux	230V w/lights broken. No parts.						Monitoring
71 Body Exterior Acc Repair	Body Exterior front number plate come off with accident						
Annual Air Con Service	Annual Air Condition Service. Done.Replaced fitting.						
Engine Change Oil & Filter	Done.						
02 Cab Assembly 1	Replace torch						
34 Lights Bulb Replacement	O/S running light n/w. Replaced bulb.						
45 Engine 1	Oil leak n/s.Washed & replaced inlet seals.						
15 Steering 1	N/S rack end worn. Replaced.						
16 Suspension 1	Front shocks worn. Replaced.						
16 Suspension 2	Lower ball joints worn. Replaced.						
01 Air Conditioning 1	Cab A/C n/w.						
Install Saloon CCTV Camera	N/W. Formatted disc.						
17 Tyres	Fitted valve extensions x2.						
17 Tyres Tracking	Re-set tracking.						
45 Engine 2	Air box cracked						

Vehicle Deep Clean	24/04/2024	13:48	25/04/2024	11:06	390,669	St Leonards	SL045035
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	29/05/2024	13:44	30/05/2024	10:22	394,497	St Leonards	SL045540
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	31/05/2024	15:30	16/07/2024	12:00	394,505	St Leonards	SL045574
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
52 Electrical Aux	230V w/lights broken. No parts.
Tail Lift Inspection	
Fuel Filter Change	Change Fuel Filter
Air Filter Change	Air Filter Change
16 Suspension 1	Rear Spring Broken -Replaced both springs and 'U' bolts/nuts.
43 Exhaust System 1	Fitted new DPF & reset learnt values (DPF Already removed.)

SAFETY INSPECTION	17/07/2024	07:00	19/07/2024	11:02	394,505	St Leonards	SL046352
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight - Done by SWL.
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
Tail Lift Inspection	Done by SWL.
MOT	
13 Handbrake	Adjusted.
45 Engine 1	Intake seals leaking. replaced seals and cleaned all oil.
15 Steering 1	Steering rack leaking at input. replaced whole rack and bled system.
17 Tyres Tracking	Tracking check and adjust carried out after replacement of steering rack
13 Brakes 1	NSF caliper lower slider stiff. removed, cleaned, regreased and refitted
19 Chassis 1	Rear spray flap insecure. resecured frame and replaced rubber flap.
16 Suspension 1	Rear roll bar drop link bushes worn. replaced x4.
19 Chassis 2	Telma earth wire on telma corroded. replaced end connector on telma.
17 Tyres Replace	All 6 Tyres replaced. 205-75-r16c
15 Steering 2	Steering wheel worn. replaced wheel and bolt.
02 Mirrors	NS Mirror housing and frame broken. replaced

89 Seats	Passenger seat base torn. replaced whole base section.
89 Seatbelts	NSF Seatbelt torn. replaced belt.
34 Lights Bulb Replacement	Front drl and sidelight bulbs replaced.
34 Lights	OSR lower tail/brake light water ingress. replaced.
85 Body Interior 1	Whiteboard loose, bh locker loose - resecured . stretcher battery replaced.
45 Engine 2	AC belt tensioner worn. replaced tensioner.

Unplanned Repair	25/07/2024	14:30	25/07/2024	15:27	394,600	St Leonards	SL046554
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

52 Electrical Aux	Charge Issue, Checked,replaced lift batt & aux batt.
-------------------	--

SAFETY INSPECTION	27/08/2024	06:00	27/08/2024	17:06	398,532	St Leonards	SL047002
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	Inspected
71 Body Exterior 1	Body Exterior No. plate damage NFF
UB Fire Supp 12mts Service	Service of fire supression system
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
87 Stretcher	Stryker battery u/s replaced with good spare
Pollen Filter Change	Pollen Filter Changed
13 Brakes 1	Rear brakes pads low. Replaced
86 Doors Rear	Door catch tight. Cleaned and adjusted
13 Handbrake	Adjust handbrake
45 Engine Ad Blue	Adblue fault. Reset level sensor

Vehicle Deep Clean	27/08/2024	12:11	27/08/2024	12:15	398,532	St Leonards	SL047018
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	25/09/2024	10:00	25/09/2024	11:00	404,241	St Leonards	SL047466
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

52 Electrical Aux	EPCR not charging - Replace fuse holders, test, ok.
-------------------	---

SAFETY INSPECTION	01/10/2024	07:26	02/10/2024	14:20	404,421	St Leonards	SL047537
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
 Safety Inspection
 Wheel Hub Flanges Replaceme
 Pollen Filter Change Pollen Filter Change
 Replace Handbrake Cables Replace Handbrake Cables
 Tail Lift Inspection
 86 Doors
 13 Brakes 1 Side Door Handle Damage
 56 Comms Equipment Front brakes worn. Replaced
 13 Brakes 2 Roof aerial missing. Replaced with spare.
 Brake pedal rubber smooth. Replaced

Vehicle Deep Clean	04/10/2024	06:22	04/10/2024	14:38	404,422	St Leonards	SL047581
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

ACCIDENT	17/10/2024	14:42	17/10/2024	14:46	405,915	St Leonards	SL047814
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	O/S Mirror Glass missing	
45 Engine Ad Blue	Adblue low level warning on - Tank is full	Monitoring

Vehicle Deep Clean	13/11/2024	14:52	14/11/2024	09:23	408,342	St Leonards	SL048210
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	14/11/2024	11:00	17/11/2024	11:00	408,342	St Leonards	SL048231
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques		
Safety Inspection		
45 Engine Ad Blue	Adblue fill level sensor faulty. - Vehicle still ok to use (ref JS)	Monitoring
Annual Heater Service	Annual Heater Service	
11 Axle Rear	Rear wheel bearings worn. -Bearings/hubs rebuilt. -brakes & handbrake replaced.	
15 Steering 1	PAS hose from cooler to reservoir leaking. replaced hose and cleaned.	
27 Transmission Automatic	Rear transmission mount perished. replaced mount.	
13 Brakes 1	Telma inop. replaced relay control box.	
17 Tyres Replace	NSR Inner wheel & tyre replaced.	
Axle Oil Change	Axle Oil Change	
85 Body Interior 1	Replace CCTV cupboard gas struts	
85 Body Interior 2	Secure saloon cupboard hinges	
89 Seats	Secure saloon seat bas bolts	

Breakdown	27/11/2024	09:22	27/11/2024	09:57	408,500	St Leonards	SL048412
Breakdown	Key not functioning						
Breakdown	19/12/2024	02:49	20/12/2024	08:00	411,442	St Leonards	SL048720
Breakdown 31 Charging System	battery alternator gone Alternator failed. replaced alternator and left vehicle to charge.						
Vehicle Deep Clean	26/12/2024	14:20	27/12/2024	10:35	411,442	St Leonards	SL048835
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/12/2024	14:00	31/12/2024	09:00	411,442	St Leonards	SL048874
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 45 Engine Ad Blue Tail Lift Inspection 02 Cab Assembly 1 34 Lights	Check and Install MDVS windows update Carried out inspection. Checked. Adblue fill level sensor faulty. - Vehicle still ok to use (ref JS) Done. Replaced magnet. Unsized N/S gate. Refitted stop to O/S gate. Interior light n/w. Replaced bulb. O/S front side marker broken. Replaced.						
Unplanned Repair	27/01/2025	08:10	27/01/2025	17:14	412,924	St Leonards	SL049288
34 Lights	Main beam light coming on when driving. Replaced stalk with good spare						
Unplanned Repair	06/02/2025	07:00	06/02/2025	13:56	413,901	St Leonards	SL049439

45 Engine Ad Blue 71 Body External Steps	Top up 15ltrs Side step u/s						
Vehicle Deep Clean	09/02/2025	11:30	11/02/2025	09:41	414,000	St Leonards	SL049482
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/02/2025	06:38	13/02/2025	10:49	414,000	St Leonards	SL049523
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test UB Fire Supp 6mts Service 02 Glass / Windows	Check and Install MDVS windows update UB Fire Supp 6mts Service N/S window switch broken						
Breakdown	09/03/2025	08:01	09/03/2025	21:08	416,082	St Leonards	SL049854
Breakdown	Addblue warning light on						
Unplanned Repair	15/03/2025	14:04	15/03/2025	15:08	416,582	St Leonards	SL049938
34 Lighting System	Rear right marker light broken off. Replaced						
Vehicle Deep Clean	28/03/2025	17:38	29/03/2025	11:05	417,336	St Leonards	SL050106
Vehicle Deep Clean	Vehicle Deep Clean						
02 Pipeline Annual Inspection	24/03/2025	14:06	24/03/2025	14:08	417,310	MDT Ferndown	TF004043
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - passed all tests.						
SAFETY INSPECTION	01/04/2025	13:00	02/04/2025	14:07	417,336	St Leonards	SL050167
Check MDVS for Update	Check and Install MDVS windows update						

Safety Inspection							
18 Wheels Check Torques							
Road Test							
Tail Lift Inspection							
85 Body Int Alcohol Gel Dispen							
Camera Upgrade			Carry out cctv hard drive format				
86 Doors Rear			O/S/R door stay broken				
31 Charging System			Shoreline connector cover missing				Monitoring
02 Windscreen Wipers			Wiper linkage worn				Monitoring

Breakdown	01/05/2025	14:10	01/05/2025	15:30	417,490	St Leonards	SL050696
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	battery alternator faulty
-----------	---------------------------

Vehicle Deep Clean	15/05/2025	14:34	17/05/2025	13:56	423,336	St Leonards	SL050972
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	18/05/2025	14:00	19/05/2025	14:45	423,336	St Leonards	SL051022
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update. Done.
Safety Inspection	Carried out inspection.
18 Wheels Check Torques	Checked.
Road Test	Done.
31 Charging System	Shoreline connector cover missing. Replaced.
02 Windscreen Wipers	Wiper linkage worn. Told to leave
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight. Told to leave.
Engine Change Oil & Filter	Told to leave.
Axle Oil Change	Axle Oil Change. Told to leave.
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test. Told to leave.
Annual Air Con Service	Annual Air Condition Service. Told to leave.
01 Air Conditioning 1	Saloon A/C n/w. Checked & repaired leaks-regassed.
45 Engine 1	oil leaking @ inlet piping. Replaced seals.
86 Door Lock	Rear door lock barrel n/w. Told to leave.
02 Cab Assembly 1	Passenger window switch broken. Replaced.
02 Mirrors	N/S wide angle mirror cracked. Replaced.
16 Suspension 1	Rear spring leaves out of alignment. Straightened.

55 Tail Lift	Guide blocks adrift x3. Secured x3.						
Med Devices Recall	19/05/2025	14:08	19/05/2025	14:11	423,336	MDT Ferndown	TF004222
Decontaminated Med Devices Recall	Cleaned with clinell wipes Replaced all Mangar Equipment and installed new charger bracket.						
Unplanned Repair	26/05/2025	06:00	26/05/2025	07:30	423,688	St Leonards	SL051191
87 Stretcher 02 Mirrors 15 Steering 1	N/W. Replaced battery. O/S mirror vibrating. Swapped arm from other vehicle. Vehicle reported unstable at high speed.						
Breakdown	23/06/2025	20:02	24/06/2025	08:44	424,100	St Leonards	SL051715
Breakdown	Physical damage to MDVS						
Breakdown	24/06/2025	07:17	25/06/2025	14:00	424,500	St Leonards	SL051716
Breakdown	base radio screen broken						
ACCIDENT	12/07/2025	06:00	12/07/2025	06:42	427,545	St Leonards	SL052012
02 Mirrors	Drivers mirror glass smashed						
Breakdown	20/07/2025	10:13	20/07/2025	11:00	428,372	St Leonards	SL052178
Breakdown	flat tyre offside rear inner					Monitoring	
Vehicle Deep Clean	22/07/2025	06:36	22/07/2025	13:00	428,381	St Leonards	SL052218
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/07/2025	08:00	25/07/2025	12:00	428,382	St Leonards	SL052243

Check MDVS for Update	Check and Install MDVS windows update	
Safety Inspection		
18 Wheels Check Torques		
Road Test		
Breakdown	flat tyre offside rear inner	
02 Mirrors	Mirrors OS WING MIRROR CRACKED FROM RTC	
Tail Lift Inspection		
MOT	Thursday 11:15	
85 Body Interior 1	Middle cab storage compartment pus button missing (still functions)	Monitoring

Breakdown	06/08/2025	14:58	07/08/2025	08:00	429,269	St Leonards	SL052553
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Broken wing mirror
-----------	--------------------

Breakdown	07/08/2025	18:45	08/08/2025	13:00	429,364	St Leonards	SL052572
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	AD Blue light on
-----------	------------------

Decommission Vehicle	26/08/2025	08:53			429,364	St Leonards	SL052903
-----------------------------	-------------------	--------------	--	--	----------------	--------------------	-----------------

Decommission vehicle	Decommission vehicle
----------------------	----------------------