

WM64JUC	A&E		Burnham Amb Stn				
Unplanned Repair	19/01/2015	09:56	29/01/2015	08:00	264	Taunton	TN012073
02 Cab Assembly 1	fitted diesel sticker to fuel flap						
17 Tyres Replace	replaced all 7 tyres (inc spare) with winter tyres						
18 Wheels Check Torques	retorque and fit check links						
31 Charging System	Faulty Tail lift battery charger repaired by Jon coles for WAS warranty						
34 Lighting System	faulty n/s/r upper red outline marker replaced by was warranty						
55 Ramp	removed damaged bridge plate rub block						
55 Tail Lift	fitted new tail lift warning LED						
56 Comms Equipment	MDT upgraded by PCE						
85 Body Interior 1	replaced broken bio safe strap in side locker & scoop buckel strap						
85 Body Interior 2	made repare to bottom draw base center cupboard						
86 Doors	see notes						
87 - Stretchers/Chairs/Boards	Fitted stretcher charger						
87a - Medical Equipment Repair	Swapped mangar compressor mounting backplate						
PDI Inspection							
Breakdown	30/01/2015	15:59	30/01/2015	16:00	409	Taunton	TN012140
Breakdown	Gateway not working						
Unplanned Repair	09/02/2015	10:00	09/02/2015	14:03	1,549	Taunton	TN012198
52 Electrical Aux	Inv panic alarm going off by itself - stripped press strips & cleaned out swarf						
85 Body Interior 1	Electrical Auxs See email to Kev.						
86 Doors	Adj side door top catch microswitch						
Travel Time	Travel to & from B-o-S						
Breakdown	13/02/2015	06:46	25/02/2015	15:33	2,102	Taunton	TN012226
45 Engine 1	Merc 24 attended, unable to fix, being recovered to city west exeter						
Breakdown	Non-start						
Unplanned Repair	26/02/2015	02:00	26/02/2015	02:15	2,244	Taunton	TN012341

44 Add Ad Blue	topped up by crew						
SAFETY INSPECTION	04/03/2015	10:30	04/03/2015	14:02	3,263	Taunton	TN012351
18 Wheels Check Torques	o/s/f wing and n/s/f grill led's not flashing cleaned torch charger connections side door bearings noisy paper copy used by Lee Crisp (PCS)					Awaiting Warranty	
34 Emergency Lights							
52 Electrical Aux							
86 Doors							
Safety Inspection						Awaiting Warranty	
Vehicle Deep Clean	04/03/2015	13:14	05/03/2015	15:25	3,263	Taunton	TN012354
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	15/03/2015	01:00	15/03/2015	01:15	4,931	Taunton	TN012445
44 Add Ad Blue	topped up by crew						
Unplanned Repair	19/03/2015	18:00	19/03/2015	18:15	5,675	Taunton	TN012479
44 Add Ad Blue	topped up by crew						
Unplanned Repair	24/03/2015	11:00	24/03/2015	15:30	6,374	Taunton	TN012471
02 Windows/Glass	badly chipped windscreen replaced by mobile windscreens						
Unplanned Repair	05/04/2015	22:00	05/04/2015	22:30	7,991	Taunton	TN012575
45 Engine Ad Blue	Topped up by crew						
Unplanned Repair	13/04/2015	13:45	13/04/2015	14:00	9,645	Taunton	TN012586
45 Engine Ad Blue	Topped up						

Vehicle Deep Clean	16/04/2015	10:19	16/04/2015	15:01	10,154	Taunton	TN012608
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	17/04/2015	08:00	17/04/2015	13:00	10,154	Taunton	TN012622
18 Wheels Check Torques	o/s/f wing and n/s/f grill led's not flashing- repaired by Jon Coles replaced damaged PCR holder in rear, replaced both fire extinguishers side door bearings noisy- Replaced by Jon coles Replaced missing stretcher harness. parts non stock paper copy used by Lee Crisp (PCS)						
34 Emergency Lights							
85 Body Interior 1							
86 Doors							
87 Stretcher							
Safety Inspection							
Camera Installation	20/04/2015	14:28	21/04/2015	18:00	10,157	Taunton	TN012642
Camera Installation	CCTV fitted by Jon Coles						
Unplanned Repair	07/05/2015	14:31	07/05/2015	14:45	12,809	Taunton	TN012765
44 Add Ad Blue	topped up by crew						
Unplanned Repair	15/05/2015	05:30	15/05/2015	05:45	14,269	Taunton	TN012797
44 Add Ad Blue	topped up by crew						
SAFETY INSPECTION	26/05/2015	10:04	28/05/2015	09:45	15,930	Taunton	TN012843
02 Cab Assembly 1	fitted new touch battery and fitted spare holder refitted trim round bulkhead window replaced all tyres clean hubs and rims						
02 Windows/Glass							
17 Tyres Replace							
18 Wheels Check Torques	readjusted exhaust tail pipe to stop catching on ramp resecuired mud flap refitted vac splint door under 1st saloon seat						
43 Exhaust System 1							
71 Body Exterior 1							
85 Body Interior 1							

87 - Stretchers/Chairs/Boards supplied missing pedimate
Safety Inspection

Vehicle Deep Clean	27/05/2015	08:30	27/05/2015	15:33	15,930	Taunton	TN012855
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	25/05/2015	22:00	25/05/2015	22:30	15,875	Taunton	TN012862
44 Add Ad Blue	topped up by crew						
Unplanned Repair	05/06/2015	07:30	05/06/2015	07:45	17,301	Taunton	TN012936
44 Add Ad Blue	topped up by crew						
Unplanned Repair	22/06/2015	10:15	22/06/2015	10:30	20,211	Taunton	TN012979
45 Engine Oil Top Up	toppe up engine oil 2x ltrs						
Breakdown	26/06/2015	19:44	29/06/2015	15:10	20,211	Taunton	TN013000
Breakdown Decontaminated Travel Time	Needs deep clean emergency deep clean vomit on wall trolley and vac mattress collwected from BOS ref emergency clean						
Unplanned Repair	30/06/2015	08:00	30/06/2015	09:14	21,037	Taunton	TN013013
85 Body Interior 1	Refitted vac splint locker door - fitted larger headed screws						
SAFETY INSPECTION	09/07/2015	07:00	10/07/2015	09:32	22,504	Taunton	TN013057
02 Cab Assembly 1 18 Wheels Check Torques 34 Emergency Lights 56 Comms Equipment	replaced courtesy lamp bulb faulty o/s/f wing LED repaired by Jon Coles for WAS warranty resecurred MDT and radio aerial						

Safety Inspection	paper copy used						
92 - C Service							
Service C							
Tail Lift Annual Service	Statutory Inspection and Weight Test carried out by south west lifts						
Vehicle Deep Clean	08/07/2015	09:30	09/07/2015	09:40	22,504	Taunton	TN013063
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	29/07/2015	19:00	29/07/2015	19:15	26,158	Taunton	TN013169
44 Add Ad Blue	topped up by crew						
SAFETY INSPECTION	20/08/2015	09:00	20/08/2015	16:00	30,632	Taunton	TN013264
02 Windscreen Wipers	Inv washers inop - unblocked pump filter in tank Checklist Defect Inv n/s wing led inop - replaced faulty LED Topped up & cleaned crystals from neck & surrounding area Checklist Defect Side door seal split Awaiting Parts						
18 Wheels Check Torques							
34 Emergency Lights							
45 Engine Ad Blue							
86 Doors							
Safety Inspection							
Vehicle Deep Clean	21/08/2015	08:11	21/08/2015	13:47	30,633	Taunton	TN013271
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	24/08/2015	22:30	24/08/2015	22:45	30,799	Taunton	TN013296
34 Lights Bulb Replacement	n/s headlight bulb changed by lead para						
Unplanned Repair	03/09/2015	13:00	03/09/2015	13:30	32,262	Taunton	TN013336
02 Windscreen Wipers	SEE NOTES						

Unplanned Repair	11/09/2015	22:00	11/09/2015	22:15	33,827	Taunton	TN013391
44 Add Ad Blue	topped up by crew						
Unplanned Repair	23/09/2015	00:30	23/09/2015	00:45	35,993	Taunton	TN013491
44 Add Ad Blue	topped up by crew						
SAFETY INSPECTION	30/09/2015	08:00	01/10/2015	14:48	36,930	Taunton	TN013452
02 Cab Assembly 1	Replaced missing 'no smoking' sticker						
02 Windscreen Wipers	Replaced wiper blades						
03 Instruments & Sensors 1	Reset service indicator						
18 Wheels Check Torques							
45 Engine Ad Blue	Topped up						
71 Body External Steps	lubed side step rollers						
86 Door Lock	Adjusted rear door cables & linkages. Freed off & lubed various keylocks						
86 Doors	Replaced split side door seal						
Safety Inspection	electronic checklist not used - paper copy sent						
Vehicle Deep Clean	01/10/2015	09:06	01/10/2015	15:37	36,930	Taunton	TN013458
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	26/10/2015	01:00	26/10/2015	02:00	40,952	Taunton	TN013553
34 Lights Bulb Replacement	o/s h/light bulb replaced by lead para						
Unplanned Repair	11/11/2015	07:00	11/11/2015	07:15	43,322	Taunton	TN013624
44 Add Ad Blue	topped up by crew						

SAFETY INSPECTION	16/11/2015	12:00	19/11/2015	14:55	43,902	Taunton	TN013641
13 Brake Pads			Replaced worn front & rear pads				
17 Tyres Replace			Replaced all tyres (inc cleaning mating faces)				
18 Wheels Check Torques			inc extended roadtest as per policy				
24 Driveshaft 1			Removed plastic wrapping jammed in propshaft flange				
31 Charging System			Replaced broken charge skt cover				
33 Ignition System			Replaced key fob battery				
34 Emergency Lights			Faulty o/s grille light replaced by J.Coles for WAS				
34 Lights			Replaced n/s/f roof bar end cap seal				
45 Engine 1			Engine OIL WARNING - BELOW MIN - oil replaced as serviced				
45 Engine Ad Blue			Topped up & cleaned filler				
85 Body Interior 1			Replaced broken pull out work tray knob (inc removing broken part)				
Safety Inspection							
93 - D Service							
Service D							
MOT Pre Test							
Vehicle Deep Clean	18/11/2015	08:25	18/11/2015	14:10	43,902	Taunton	TN013648
Vehicle Deep Clean			Vehicle Deep Clean				
Unplanned Repair	24/11/2015	08:00	24/11/2015	16:00	45,033	Taunton	TN013678
11 Axle Rear			SEE NOTES				
Travel Time			drive to Burnham to investigate fault				
Unplanned Repair	28/11/2015	17:00	28/11/2015	17:15	45,897	Taunton	TN013713
44 Add Ad Blue			topped up by crew				
Unplanned Repair	04/12/2015	18:00	04/12/2015	18:15	47,264	Taunton	TN013786
44 Add Ad Blue			topped up by crew				
Breakdown	11/12/2015	22:12	14/12/2015	09:10	48,793	Taunton	TN013750

54 Horns	see notes						
Breakdown	Defective horn/siren						
Unplanned Repair	26/12/2015	21:30	26/12/2015	21:45	51,351	Taunton	TN013817
44 Add Ad Blue	topped up by crew						
SAFETY INSPECTION	29/12/2015	15:00	31/12/2015	15:49	51,965	Taunton	TN013813
18 Wheels Check Torques							
34 Emergency Lights	see notes						
34 Lights	see notes						
44 Add Ad Blue	add ad blue clean spills						
55 Tail Lift	see notes						
71 Body External Steps	lube side step						
85 Body Interior 1	resecure pcr holder						
85 Body Interior 2	fit dca and amy decals						
87 - Stretchers/Chairs/Boards	fit belts to stretcher						
Safety Inspection	paper copy used						
Travel Time	travel to a1 for mot						
MOT							
Gearbox Oil & Filter Change							
Breakdown	08/01/2016	20:51	15/01/2016	11:56	53,619	Taunton	TN013858
45 Engine 1	Engine loss of power / limp mode see notes						
Breakdown	None Starter						
BREAKDOWN	16/01/2016	21:45	20/01/2016	16:00	54,083	Taunton	TN013912
03 Instruments & Sensors 1	Checked fault codes using Xentry - various codes - sent veh to Merc-SEE NOTES						
45 Engine 1	Engine Limp mode? no power, Turbo?						

Unplanned Repair	21/01/2016	14:50	29/01/2016	08:21	54,235	Taunton	TN013935
45 Engine 1	sent to Merc exeter for warranty-SEE NOTES						
45 Engine 2	carry out diagnostic check for loss of power						
Unplanned Repair	30/01/2016	20:00	30/01/2016	20:15	54,616	Taunton	TN013988
44 Add Ad Blue	topped up by crew						
SAFETY INSPECTION	04/02/2016	08:00	09/02/2016	16:02	55,818	Taunton	TN014001
02 Windscreen Wipers	Replaced o/s washer jet						
18 Wheels Check Torques	inc extended roadtest as per policy						
52 Electrical Aux	Resecured aux wiring in n/s wing						
55 Tail Lift	See notes - repairs from service						
71 Body Exterior 1	Changed tyre pressure decals to correct pressure						
86 Doors Rear	Fitted strengthening plates to o/s/r door. Lubed & freed keylock & catches						
Safety Inspection							
Travel Time	Collected from B-o-S						
Wheel Studs & Nuts Replacement	Replaced all nuts & studs (inc cleaning all wheel & hub flange mating faces)						
Handbrake Cable Replacement	Replace all 3 handbrake cables						
Annual Air Con Service	Annual Air Condition Service - both systems						
Annual Heater Service	Annual Heater Service						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	04/02/2016	15:42	08/02/2016	12:14	55,818	Taunton	TN014004
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	17/02/2016	19:15	17/02/2016	19:30	57,616	Taunton	TN014068
34 Lights Bulb Replacement	o/s headlight bulb replaced by crew						
Unplanned Repair	18/02/2016	22:00	18/02/2016	22:15	57,909	Taunton	TN014069
34 Lights Bulb Replacement	n/s headlight bulb replaced by crew						

SAFETY INSPECTION	17/03/2016	10:15	18/03/2016	10:16	63,390	Taunton	TN014196
13 Handbrake			adjust handbrake shoes and cable				
18 Wheels Check Torques							
55 Tail Lift			fit new hose on ram and test				
85 Body Interior 1			replace strap in lucas locker				
86 Sliding Door			refit sliding door seal				
87 - Stretchers/Chairs/Boards			replace stretcher straps and mattress				
Safety Inspection			paper copy used by Chris Small				
Fit Throw Lines & SOP							
92 - C Service							
Service C							
Breakdown	30/03/2016	21:54	31/03/2016	10:51	65,717	Taunton	TN014256
54 Horns			see notes				
Breakdown			Intermittent horn fault affecting sirens.				
Breakdown	06/04/2016	19:10	07/04/2016	15:41	67,065	Taunton	TN014283
27 Transmission Automatic			Inv reported stuck in 2nd gear - see notes				
Breakdown			stuck in 2nd gear, just revs up to 3000 revs.				
SAFETY INSPECTION	28/04/2016	09:30	28/04/2016	15:00	70,510	Taunton	TN014397
02 Cab Assembly 1			Removed broken storage bin lock				
18 Wheels Check Torques							
54 Horns			Cleaned horn switch contacts in steering wheel				
71 Body Exterior 1			Resecured mudflap mount & spray supression				
71 Body Exterior 2			Replaced faded stickers				
Safety Inspection							
Install Saloon CCTV Camera							
85 Body Int Alcohol Gel Dispen supplied & fitted							

Unplanned Repair	23/05/2016	10:18	25/05/2016	13:01	75,150	Taunton	TN014508
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

45 Engine 1	Engine Intermittently loosing power- see notes
-------------	--

SAFETY INSPECTION	13/06/2016	09:00	17/06/2016	15:55	78,861	Taunton	TN014608
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	Replaced both OOD fire extinguishers
02 Cab Assembly 1	Replaced courtesy light bulb
03 Instruments & Sensors 1	Reset serv indicator
17 Tyres Replace	Replaced all 6 worn tyres (inc cleaning all mating surfaces)
18 Wheels Check Torques	inc extended roadtest as per policy
45 Engine 1	See notes - new ECU pins
86 Door Lock	Resecured side door catch covers
86 Doors Rear	Repaired broken o/s/r door stay pivot
Safety Inspection	
Reposition grab bag shelf	
Tail Lift Annual Service	Statutory Inspection and Weight Test done by SW Lifts
Tail Lift 6 Monthly Inspection	Statutory Inspection done by SW Lifts

Vehicle Deep Clean	13/06/2016	14:09	13/06/2016	14:12	78,661	Taunton	TN014613
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	13/06/2016	14:12	13/06/2016	14:15	78,861	Taunton	TN014614
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	13/06/2016	14:15	13/06/2016	14:18	78,861	Taunton	TN014615
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	13/06/2016	14:18	14/06/2016	11:28	78,861	Taunton	TN014616
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	18/06/2016	07:30	06/07/2016	14:09	79,284	Taunton	TN014636
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

45 Engine 1	Engine CONTINUING INTERMITTENT LOSS OF POWER-SEE NOTES
56 Comms Power Failure	see notes
71 Body Exterior 1	Replaced missing n/s/r roof corner cap & repaired rain deflector

SAFETY INSPECTION	22/07/2016	10:00	22/07/2016	16:32	82,479	Taunton	TN014789
02 Cab Assembly 2							
13 Brakes 1							
18 Wheels Check Torques							
45 Engine Ad Blue							
85 Body Interior 1							
89 Seats							
Safety Inspection							
93 - D Service							
Service D							

Unplanned Repair	27/07/2016	14:30	27/07/2016	14:51	83,049	Taunton	TN014811
02 Mirrors							

Vehicle Deep Clean	01/09/2016	10:00	01/09/2016	16:12	91,340	Taunton	TN014998
Vehicle Deep Clean							

SAFETY INSPECTION	02/09/2016	08:00	02/09/2016	15:58	91,340	Taunton	TN015004
13 Brakes 1							
16 Suspension 1							
16 Suspension 2							
18 Wheels Check Torques							
55 Tail Lift							
Safety Inspection							

Monitoring

Unplanned Repair	02/10/2016	20:00	02/10/2016	20:15	98,534	Taunton	TN015181
34 Lights Bulb Replacement							

Unplanned Repair	07/10/2016	10:15	07/10/2016	11:00	99,627	Taunton	TN015224
34 Emergency Lights	roof beacon 'detached' see email, replaced damaged airport light						
SAFETY INSPECTION	12/10/2016	13:30	14/10/2016	16:14	100,808	Taunton	TN015246
01 Heating 1	Replace aux heater exhaust pipe						
13 Brake Test	Carry out R.B.T						
13 Brakes 1	Replace rear brake pads and discs [clean hubs and wheel rims]						
16 Suspension 2	slight play n/s and o/s/f strut tops						Monitoring
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy						
86 Door Seals	Replace o/s door seal						
86 Doors	SEE NOTES						
Safety Inspection	Paper copy used by Chris Small						
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill						
92 - C Service							
Service C							
Gearbox Oil & Filter Change							
Vehicle Deep Clean	14/10/2016	08:00	14/10/2016	15:55	100,808	Taunton	TN015266
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/10/2016	11:15	20/10/2016	14:02	101,829	Taunton	TN015296
34 Lights Bulb Replacement	Electrical Auxs headlight bulb replaced by duty officer						
71 Body External Steps	Replace damaged side step						
Breakdown	04/11/2016	16:32	07/11/2016	14:29	104,842	Taunton	TN015385
Breakdown	issue with gearbox and engine, cant move. see notes						
Unplanned Repair	21/11/2016	00:30	28/11/2016	16:00	107,598	Taunton	TN015478
45 Engine 1	Engine limp mode x2 whilst on emergency transfer- see notes						

SAFETY INSPECTION	21/11/2016	10:00	23/11/2016	08:28	107,594	Taunton	TN015480
16 Suspension 2	slight play n/s and o/s/f strut tops					Monitoring	Awaiting Parts
17 Tyres	Replace n/s and o/s/f and o/s/r tyres [worn] clean hubs and rims						
17 Tyres Tracking	Body Exterior wheel balance / tracking out [check and adjust]						
18 Wheels Check Torques							
56 Comms Equipment	Fit new sat nav SDcard						
71 Body Exterior 1	Repair and refit rear mud flap o/s						
85 Body Interior 1	Repair grab bag locker hinge						
85 Body Interior 2	Repair pcr locker						
86 Door Lock	Side locker door lock [key] inop spinning						
Safety Inspection	Paper copy used by Chris Small						
MOT Pre Test							
Travel Time	Take vehicle for MOT						
MOT	wait at A1 for MOT						
Tail Lift 6 Monthly Inspection	Statutory Inspection SEE NOTES						
Vehicle Deep Clean	23/11/2016	08:00	23/11/2016	16:03	107,598	Taunton	TN015497
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	01/12/2016	02:01	05/12/2016	13:48	108,210	Taunton	TN015547
45 Engine 1	SEE NOTES						
85 Body Interior 1	Resecured drugs locker door						
Breakdown	Won't go out of first gear						
BREAKDOWN	24/12/2016	14:00	24/12/2016	16:00	112,316	Taunton	TN015697
17 Tyres Replace	ATS call out- replaced o/s/f tyre and cracked rim						
18 Wheels	cracked rim replaced						
Vehicle Deep Clean	04/01/2017	14:24	05/01/2017	12:23	114,198	Taunton	TN015743
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	05/01/2017	13:00	06/01/2017	15:55	114,198	Taunton	TN015756
-------------------	------------	-------	------------	-------	---------	---------	----------

02 Windscreen	Small chip in screen n/s	Monitoring
16 Suspension 2	slight play n/s and o/s/f strut tops	Monitoring
16 Suspension 3	Rear leaf springs slippers starting to split	Monitoring
17 Tyres	Replace n/s/f tyre puncture replace n/s/r tyres worn clean hubs and rims	
18 Wheels Check Torques	carry out extended test drive and retorque as per trust policy	
44 Add Ad Blue	Top up ad blue	
52 Electrical Aux	Reset service indicator	
55 Tail Lift	SEE NOTES	
86 Door Lock	Side locker door lock [key] inop spinning	Monitoring
86 Doors Rear	Rear door lock seized free off and lubricate	
Safety Inspection	Paper copy used by chris small	
Medical Device and Equip Chec		
Annual Heater Service	Annual Heater Service	
Handbrake Cable Replacement	Replace rear handbrake cables [not due at this time]	

Unplanned Repair	09/02/2017	17:57	10/02/2017	11:16	121,147	Taunton	TN015962
------------------	------------	-------	------------	-------	---------	---------	----------

01 Heating 1	saloon heater very noisy, replaced faulty motor and tested, ok
54 Horns	recurrent fault siren failing on /off- No fault found
54 Sirens	siren foot medal poor contact - see notes

SAFETY INSPECTION	22/02/2017	10:30	23/02/2017	16:41	123,575	Taunton	TN016027
-------------------	------------	-------	------------	-------	---------	---------	----------

01 Air Conditioning 1	Reposition saloon a/c pipes under vehicle fouling on h/brake cable	
02 Cab Assembly 1	Fit new interior light bulb	
02 Windscreen	Small chip in screen n/s	Monitoring
16 Suspension 1	Replace n/s and o/s/r anti roll bar link lower bushes	
16 Suspension 2	slight play n/s and o/s/f strut tops	Monitoring
16 Suspension 3	Rear leaf springs slippers starting to split	Monitoring
18 Wheels Check Torques		
34 Emergency Light System	Emg Warning Devices siren / bull horn SEE NOTES	
52 Electrical Aux	Reset service indicator	
71 Body Exterior 1	Refit n/s/f fog lamp trim	
86 Door Lock	Side locker door lock [key] inop spinning	Monitoring
Road Test	Carry out road test and R-B-T	
Safety Inspection	Paper copy used by Chris Small	
Annual Air Con Service	Annual Air Condition Service	

93 - D Service
Service D

Vehicle Deep Clean	23/02/2017	08:00	23/02/2017	15:46	123,575	Taunton	TN016033
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	06/03/2017	12:39	06/03/2017	14:59	125,214	Taunton	TN016086
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	low pressure on inner tyre replace n/s and o/s/r inner tyres
-----------	--

Vehicle Deep Clean	11/04/2017	13:20	11/04/2017	15:44	131,696	Taunton	TN016297
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	12/04/2017	08:30	13/04/2017	15:15	131,696	Taunton	TN016300
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	Replaced broken o/s mirror cover & glass	
02 Windscreen	Small chip in screen n/s	Monitoring
02 Windscreen Wipers	Replaced wiper blades	
16 Suspension 2	slight play n/s and o/s/f strut tops	Monitoring
16 Suspension 3	Rear leaf springs slippers starting to split	Monitoring
18 Wheels Check Torques		
54 Sirens	Replaced faulty bull horn foot pedal	
85 Body Interior 1	Resecured PRF holder	
86 Door Lock	Replaced saloon lock set (both doors seized) & adj rear door linkages	Awaiting Parts
Safety Inspection		

Unplanned Repair	08/05/2017	07:00	08/05/2017	08:55	135,365	Taunton	TN016442
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	replaced damaged o/s mirror arm and all components
------------	--

SAFETY INSPECTION	19/05/2017	11:30	26/05/2017	10:55	137,729	Taunton	TN016513
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	Replace cab and saloon fire extinguishers
------------------------------	---

02 Cab Assembly 1	Replace broken phone holder	
02 Cab Assembly 2	Refit cab to saloon seal	
02 Windscreen	Small chip in screen n/s	Monitoring
16 Suspension 2	n/s/f strut replaced by mercedes	
16 Suspension 3	Rear leaf springs slippers starting to split- replaced by mercedes	
18 Wheels Check Torques		
34 Lights Bulb Replacement	n/s dipped beam bulb replaced by duty officer overnight	
52 Electrical Aux	Reset service indicator	
71 Body Exterior 1	Battery locker key seized strip lock free off lube and refit	
71 Body Exterior 2	Side locker lock inop replace	
85 Body Interior 1	Resecure chair track locker hinge	
86 Door Lock	Replaced saloon lock set (both doors seized) & adj rear door linkages	
86 Doors	Doors back door faulty catch alarm sounds SEE NOTES	
89 Seats	passenger seat cover starting to split on the seam- replaced by mercedes	
Road Test	Carry out road test and R-B-T	
Safety Inspection	Paper copy used by Chris Small	
Tail Lift 6 Monthly Inspection	Statutory Inspection carried out by south west lifts	
Tail Lift Annual Service	Statutory Inspection and Weight Test carried out by south west lifts	

Vehicle Deep Clean	22/05/2017	08:00	22/05/2017	13:30	137,729	Taunton	TN016521
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	01/06/2017	12:28	09/06/2017	15:16	138,505	Taunton	TN016587
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	see notes
Breakdown	EM light on LOP power failing
Travel Time	

SAFETY INSPECTION	28/06/2017	09:45	29/06/2017	13:36	142,322	Taunton	TN016748
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	Fit cab bulk head expansion plug	
02 Windscreen	Small chip in screen n/s	Monitoring
17 Tyres	Replace o/s/r worn outer tyre [clean hub and rims]	
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R-B-T	
45 Engine 1	SEE NOTES	
71 Body Exterior 1	Fit n/s/f fog lamp grille	

71 Body Exterior 2 Replace incorrect address decal
 71 Body External Steps Small spliy in side step mudflap
 Safety Inspection Paper copy used by Chris Small
 MGS Gas Storage Modifications MGS Gas Storage Modifications
 92 - C Service
 Service C

Monitoring

Breakdown 26/07/2017 01:52 26/07/2017 02:00 148,731 Taunton TN016923

Breakdown collision with gate post

Unplanned Repair 28/07/2017 13:50 28/07/2017 15:27 148,972 Taunton TN016938

17 Tyres Replace Replace punctured o/s/r outer tyre clean rims and hub
 18 Wheels Retorque Carry out extended test drive and retorque as per trust policy
 34 Lights Bulb Replacement Replace n/s day running light bulb
 Replace Vehicle Fuel Card Replace Vehicle Fuel Card

Vehicle Deep Clean 02/08/2017 14:27 02/08/2017 14:30 149,784 Taunton TN016972

Vehicle Deep Clean Vehicle Deep Clean

Emergency Deep Clean 02/08/2017 14:30 03/08/2017 12:16 149,784 Taunton TN016973

Emergency Deep Clean

SAFETY INSPECTION 03/08/2017 13:30 07/08/2017 13:13 149,784 Taunton TN016982

02 Windscreen Small chip in screen n/s
 13 Brake Pads Replace worn rear disc pads
 13 Brakes 1 Replace front discs and pads
 17 Tyres Replace worn n/s/r inner and outer and o/s and n/s/f tyres [clean hubs and rims]
 17 Tyres Tracking Check and adjust tracking
 18 Wheels Check Torques Carry out extended test drive and retorque as per trust policy carry out RBT
 52 Electrical Aux Reset service indicator
 71 Body Exterior 1 Fit new rear mud flap guide rail
 71 Body External Steps Small split in side step mudflap
 Safety Inspection Paper copy used by Chris Small
 Gearbox Oil & Filter Change

Monitoring

Monitoring

Vehicle Deep Clean	14/08/2017	15:53	14/08/2017	15:58	149,784	Taunton	TN017039
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/08/2017	10:00	23/08/2017	11:05	153,178	Taunton	TN017104
17 Tyres Replace 18 Wheels Retorque	Replaced punctured n/s/r outer inc extended roadtest as per policy						
Vehicle Deep Clean	20/09/2017	11:30	21/09/2017	14:57	159,805	Taunton	TN017258
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/09/2017	14:01	22/09/2017	15:42	159,805	Taunton	TN017259
02 Windscreen 17 Tyres Replace 18 Wheels Check Torques 34 Lights Bulb Replacement 71 Body External Steps 85 Body Interior 1 86 Door Lock 86 Doors 86 Sliding Door Safety Inspection MOT Pre Test 93 - D Service Service D	Small chip in screen n/s Replaced worn o/s/r tyres inc extended roadtest as per policy Replaced n/s side light bulb Small split in side step mudflap Replaced 1x broken bag securing strap Inv rear door lock c/locking not locking - repaired linkage & lubed Lubed stiff side door runners Runner rail cover missing						Awaiting Parts
Breakdown	27/09/2017	21:49	02/10/2017	15:51	161,118	Taunton	TN017297
45 Engine 1 Breakdown	Engine Adblue full, adblue warning & EMS light active - see notes audible adblue & EML SEE NOTES						

Unplanned Repair	09/10/2017	13:00	09/10/2017	14:00	163,850	Taunton	TN017421
17 Tyres Replace 18 Wheels	replaced by ATS from Taunton's stock cracked wheel replaced						
Unplanned Repair	24/10/2017	10:45	24/10/2017	10:59	166,705	Taunton	TN017472
34 Lights Bulb Replacement	Replace o/s/f side light bulb						
Breakdown	27/10/2017	12:41	27/10/2017	14:53	167,525	Taunton	TN017498
17 Tyres Replace 18 Wheels Breakdown	ATS bridgwater call out - replaced n/s/f tyre n/s/f cracked wheel rim replaced Front nearside tyre flat						
Vehicle Deep Clean	30/10/2017	09:58	30/10/2017	16:00	168,394	Taunton	TN017507
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/10/2017	15:02	31/10/2017	17:30	168,394	Taunton	TN017510
02 Cab Assembly 1 03 Instruments & Sensors 1 18 Wheels Check Torques 55 Tail Lift 85 Body Interior 1 85 Body Interior 2 86 Sliding Door 89 Seats Safety Inspection Travel Time MOT Tail Lift 6 Monthly Inspection	Replaced courtesy light bulb Reset serv indicator Straightened bent handrail & Freed & lubed sticking drop handle carry chair mount insecure Replaced worn 2x O2 locker pins Replaced missing/damaged side door runner covers (inc body repairs) Resecured 2x arm rests. Lubed & freed stiff swivel locks test no - 536976554354 Statutory Inspection						

Unplanned Repair	17/11/2017	15:15	17/11/2017	16:42	172,797	Taunton	TN017634
71 Body External Steps	SEE NOTES					Monitoring	
Unplanned Repair	28/11/2017	14:15	28/11/2017	16:52	175,505	Taunton	TN017695
34 Lights Bulb Replacement	Replace n/s repeater lamp bulb						
SAFETY INSPECTION	06/12/2017	10:12	07/12/2017	16:35	177,586	Taunton	TN017738
01 Air Conditioning 1	SEE NOTES					Monitoring	
03 Instruments & Sensors 1	Reset service indicator						
13 Brakes 1	Replace rear brake pad anti rattle springs.Clean wheel rims and hubs.						
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R.B.T						
45 Engine 1	Oil leak SEE NOTES						
45 Engine 2	Replace cracked air intake pipe support bracket						
54 Sirens	Body Interior siren / horn becoming vague again.SEE NOTES						
56 Radio	Body Interior cab radio u/s						
71 Body Exterior 1	Replace damaged rear mudflap						
71 Body External Steps	SEE NOTES						
Safety Inspection	Paper copy used by Chris Small						
92 - C Service							
Service C							
Vehicle Deep Clean	07/12/2017	14:24	08/12/2017	15:58	177,596	Taunton	TN017753
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	13/12/2017	09:20	13/12/2017	09:38	178,893	Taunton	TN017785
34 Lights Bulb Replacement	Replace n/s headlamp bulb						
Breakdown	05/01/2018	01:29	05/01/2018	04:00	184,308	Taunton	TN017914
17 Tyres Replace	N/S/F punctured - replaced by ATS on b/down						

18 Wheels Breakdown	Replaced cracked wheel rim FNS tyre flat
------------------------	---

SAFETY INSPECTION	18/01/2018	14:00	22/01/2018	16:47	187,610	Taunton	TN017985
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	SEE NOTES	Awaiting Warranty
13 Brakes 1	Replace rear brake pads and discs clean hubs and rims.	
16 Suspension 1	Replace split front strut boots.	
17 Tyres	Replace 3 x worn tyres	
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R.B.T	
44 Add Ad Blue		
55 Tail Lift	Tail lift hand rail stiff in operation free off and lube.	
71 Body Exterior 1	SEE NOTES	
Road Test	SEE NOTES	
Safety Inspection	Paper copy used by Chris Small	
Wheel Hub Flanges Replaceme	Not done Vehicle still under warranty	Lack of Labour
Handbrake Cable Replacement	Replace rear handbrake cables. Not done vehicle still under warranty.	Awaiting Warranty
Annual Heater Service	Annual Heater Service	Lack of Labour
Annual Air Con Service	Annual Air Condition Service	Lack of Labour

Vehicle Deep Clean	22/01/2018	08:30	22/01/2018	13:00	187,617	Taunton	TN017997
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	04/02/2018	11:49	12/02/2018	14:20	191,216	Taunton	TN018081
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

15 Steering 1	Steering heavy
31 Battery Aux	Electrical Auxs ?alternator failure - see email
44 Add Ad Blue	Top up ad blue from tank
Breakdown	Alternator not charging replace alternator

Unplanned Repair	23/02/2018	08:45	23/02/2018	13:54	193,827	Taunton	TN018219
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Battery Aux	Tested & replaced faulty aux battery
44 Add Ad Blue	Topped up

56 Comms Equipment MDT Failure/Issue MDT powering down battery check required

Breakdown 02/03/2018 21:32 06/03/2018 14:27 195,255 Taunton TN018273

Breakdown Heater stopped working in front cab replace fan and resister

SAFETY INSPECTION 05/03/2018 08:40 06/03/2018 13:55 195,255 Taunton TN018276

01 Air Conditioning 1	SEE NOTES	Awaiting Parts
13 Brake Test	Carry out brake test	
18 Wheels Check Torques		
34 Lights	Replace osr marker light	
34 Lights Bulb Replacement	Replace osf marker light bulb	
86 Sliding Door	Replace sliding door roller bearings	
Annual Air Con Service	Annual Air Condition Service	
Annual Heater Service	Annual Heater Service	
Handbrake Cable Replacement	Replace rear handbrake cables.Not done vehicle still under warranty.	Monitoring
Medical Devices Check	Check battery health on mobi med 76% & 100%	
Road Test	Catty out road test	
Safety Inspection	Carry out safety inspection	
Wheel Hub Flanges Replaceme	Not done Vehicle still under warranty	Monitoring
93 - D Service		
Service D	Carry out D service	

Vehicle Deep Clean 05/03/2018 10:30 05/03/2018 15:30 195,255 Taunton TN018279

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair 23/03/2018 08:00 23/03/2018 08:49 199,810 Taunton TN018394

71 Body External Steps Side step sticking free off and lube
87a - Medical Equipment RepairReplace broken carry chair locking plunger

Unplanned Repair 02/04/2018 08:15 04/04/2018 17:01 202,064 Taunton TN018439

01 Heating 1	Saloon heater inop. SEE NOTES
02 Windscreen Wipers	Replace
16 Suspension 1	Knocking noise o/s/f suspension SEE NOTES
17 Tyres	O/S/R inner tyre flat replaced clean hub and rims
31 Charging System Battery	Battery / charging light.Replace chassis battery
71 Body External Steps	External step sticking. Clean and lube
86 Doors	Body Exterior door stay u/s - see email for other defects.SEE NOTES
89 Seatbelts	O/S cab seatbelt not retracting. Replaced
Road Test	Carry out extended test drive and retorque as per trust policy carry out R.B.T

Breakdown	15/04/2018	10:20	19/04/2018	13:17	205,078	Taunton	TN018502
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	high temp and burning smell.SEE JOB CARD TN018521
-----------	---

SAFETY INSPECTION	17/04/2018	11:00	19/04/2018	16:18	205,078	Taunton	TN018521
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	SEE NOTES	Monitoring
02 Cab Ass Fire Extinguisher	Replace cab and saloon fire extinguishers [date expired]	
13 Brake Pads	Replace worn front brake pads.Clean wheel rims and hubs.	
13 Handbrake	Adjust cable and shoes	
16 Suspension 1	Replace leaking n/s/r shock absorber.	
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R.B.T	
45 Engine 1	Fumes.Investigate fumes in cab.SEE NOTES	
85 Body Interior 1	Repair and resecure carry chair locker door.	
85 Body Interior 2	Replae broken grab bag locker strap	
86 Doors	Replace damaged scoop board locker door lock barrel.	
Handbrake Cable Replacement	Replace rear handbrake cables.Not done vehicle still under warranty.	
Safety Inspection	Paper copy used by Chris Small	
Wheel Hub Flanges Replaceme	Not done Vehicle still under warranty	
85 Body Int Alcohol Gel Dispen	Already fitted	
Fit Poster Holder	Fit Poster Holder	
Gearbox Oil & Filter Change		
Tail Lift 6 Monthly Inspection	Statutory Inspection. Slow close inop trace fault to mercury switch replaced	

Vehicle Deep Clean	19/04/2018	08:00	19/04/2018	15:56	205,078	Taunton	TN018530
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	23/04/2018	07:27	23/04/2018	17:11	205,966	Taunton	TN018544
17 Tyres Replace	O/S/F punctured tyre replaced by ATS						
18 Wheels	Cracked rim replaced						
Breakdown	ATS attended b/down 2x as only took tyre not built wheel & rim was cracked						
Unplanned Repair	25/04/2018	06:00	25/04/2018	08:33	206,367	Taunton	TN018566
34 Lights Bulb Replacement	H/light bulb replaced by Duty Officer (P.Lewis)						
Unplanned Repair	04/05/2018	09:38	04/05/2018	15:56	208,595	Taunton	TN018618
45 Engine 1	Vehicle reported in limp mode E.M.L light not on.SEE NOTES						
Breakdown	21/05/2018	08:09	22/05/2018	12:22	212,982	Taunton	TN018707
03 Instruments & Sensors 1	Inv EML on - found fault code for excess ash content in DPF, cleared codes						
34 Lights Bulb Replacement	Replaced o/s dip beam bulb						
43 Exhaust System 1	Cleaned DPF, regenerated & carried out teaching process. Roadtested						
Breakdown	Engine in restriction mode						
Breakdown	23/05/2018	07:57	23/05/2018	13:40	213,203	Taunton	TN018718
02 Mirrors	Repaired damaged mirror arm & replaced broken back cover						
Breakdown	O/S Wing Mirror damaged						
Unplanned Repair	25/05/2018	08:15	25/05/2018	08:36	213,821	Taunton	TN018730
45 Engine Ad Blue	Replaced missing ADBlue cap						
Breakdown	26/05/2018	23:52	28/05/2018	15:37	214,116	Taunton	TN018738
Breakdown	intermittant limp mode.SEE NOTES						
Breakdown	31/05/2018	04:27	06/06/2018	09:30	214,707	Taunton	TN018762
03 Instruments & Sensors 1	Inv limp mode - found fault code for Fuel rail pressure sensor fault. see notes						

41 Air Intake	Oil leak from air intake system seals in baffler unit replace seals
45 Engine 1	NS bank injectors chuffing replace injector seal and bolts
Breakdown	LIMP MODE, NO EML

SAFETY INSPECTION	04/06/2018	13:36	07/06/2018	16:01	214,735	Taunton	TN018788
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	SEE NOTES	Awaiting Parts
13 Brake Test	Carry out brake test	
16 Suspension 1	Replace rear anti roll bar bushes	
17 Tyres Replace	Replace nsf tyre	
18 Wheels Check Torques		
34 Lights	OS torch not working Replace torch	
34 Lights Bulb Replacement	Saloon light not working replace bulb	
43 Exhaust System 1	Replace exhaust tailpipe	
Medical Devices Check	Check mobi med battery health 69% &89% replace one battery	
Safety Inspection	Carry out safety inspection	
92 - C Service		
Service C	Carry out C Service	
Tail Lift Annual Service	Statutory Inspection and Weight Test	

Vehicle Deep Clean	05/06/2018	14:21	06/06/2018	12:10	214,735	Taunton	TN018803
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	18/06/2018	13:00	18/06/2018	13:20	217,014	Taunton	TN018900
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Replaced o/s side light bulb
----------------------------	------------------------------

SAFETY INSPECTION	05/07/2018	11:07	13/07/2018	15:12	220,910	Taunton	TN019033
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	SEE NOTES	
13 Brake Pads	Replace rear brake pads	
13 Brake Test	Carry out brake test	
16 Suspension 1	osr suspension buffer split	Monitoring
17 Tyres Replace	Rear tyres low replace	
18 Wheels Check Torques		
45 Engine 1	Minor oil leak from engine	Monitoring

45 Engine Oil Top Up	Top up engine oil						Monitoring
71 Body Exterior 1	Body Exterior damage to n/s wheelarch noted - ? how / when						
89 Seats	Resecure locking pin on attendant seat						
Medical Devices Check	Check battery health on mobi med 100% & 89%						
Safety Inspection	Carry out safety inspection						
Vehicle Deep Clean	09/07/2018	09:30	09/07/2018	15:39	220,910	Taunton	TN019048
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	31/07/2018	16:02	31/07/2018	18:06	225,485	Taunton	TN019216
Breakdown	tyre underinflated osr 205/75R16C Michelin Alpin						
Breakdown	01/08/2018	05:59	02/08/2018	13:00	225,600	Taunton	TN019217
27 Transmission Automatic Breakdown	Roadtested - NFF. Also vehicle used 3x shifts since reported fault - No reoccura intermit. not selecting gears						
Unplanned Repair	03/08/2018	14:00	03/08/2018	15:57	226,095	Taunton	TN019248
71 Body Exterior 1	Change call signs						
Unplanned Repair	07/08/2018	15:20	07/08/2018	15:41	226,518	Taunton	TN019266
45 Engine Oil Top Up							
SAFETY INSPECTION	16/08/2018	10:13	17/08/2018	15:52	227,254	Taunton	TN019309
16 Suspension 1	osr suspension buffer split						Monitoring
18 Wheels Check Torques	Carry out test drive and R.B.T						
42 Radiator	Refit insecure radiator couling						
43 Exhaust System 1	Resecure D.P.F bracket						
45 Engine 1	Minor oil leak from engine						
55 Tail Lift	Drill out broken bolts in tail lift guide mountings refit with new bolts						

71 Body Exterior 1	Body Exterior damage to n/s wheelarch noted - ? how / when					Monitoring	
71 Body External Steps	Replace side step mudflap						
85 Body Interior 1	Repair grab bag locker						
85 Body Interior 2	Chair track locker door insecure repair and resecure						
87 Oxygen System	Body Interior O2 regulator leaking.Repair carried out by M.D.T team						
Safety Inspection	Paper copy used by Chris Small						
Vehicle Deep Clean	16/08/2018	10:00	17/08/2018	15:35	227,254	Taunton	TN019311
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	22/08/2018	08:00	22/08/2018	10:41	227,524	Taunton	TN019336
86 Doors Rear	Replaced o/s/r door lower cable & handle - see notes						
Unplanned Repair	23/08/2018	12:55	23/08/2018	13:11	227,579	Taunton	TN019348
34 Lights Bulb Replacement	Replace n/s headlamp bulb						
Breakdown	03/09/2018	19:07	04/09/2018	09:39	228,972	Taunton	TN019410
34 Emergency Lights Breakdown	Replaced n/s blue light above door - knocked off n/S Blue light missing						
SAFETY INSPECTION	27/09/2018	10:30	28/09/2018	16:01	231,428	Taunton	TN019555
02 Cab Assembly 1	N/S window switch						
02 Windscreen Wipers	Replaced leaking washer check valve						
18 Wheels Check Torques	Carry out extended test drive and R.B.T						
34 Lights	Replace inop o/s/f side light bulb						
45 Engine 1	Minor oil leak from engine.SEE NOTES						
71 Body Exterior 1	Body Exterior damage to n/s wheelarch noted - ? how / when					Monitoring	
86 Doors	Remove rear door lock panel lube cables and test [stiff in operation]						
Safety Inspection	Paper copy used by Chris Small						
MOT Pre Test							
93 - D Service							
Service D							

Tail Lift 6 Monthly Inspection Statutory Inspection

Vehicle Deep Clean	28/09/2018	08:00	28/09/2018	15:17	231,428	Taunton	TN019557
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	08/10/2018	07:12	08/10/2018	07:58	232,924	Taunton	TN019619
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	Wasshers not working filter blocked remove bottle clean bottle and filter						
----------------------	---	--	--	--	--	--	--

Unplanned Repair	10/10/2018	07:05	10/10/2018	07:56	233,157	Taunton	TN019640
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	Windscreen washers u/s non return valve broken replace valve						
----------------------	--	--	--	--	--	--	--

Unplanned Repair	12/10/2018	08:00	12/10/2018	09:14	233,343	Taunton	TN019659
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Doors Rear	Repaired o/s/r door handle & linkage						
---------------	--------------------------------------	--	--	--	--	--	--

Unplanned Repair	15/10/2018	10:00	15/10/2018	13:53	233,644	Taunton	TN019672
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

15 Steering 1	Steering Heavy/noisy steering.SEE NOTES						
---------------	---	--	--	--	--	--	--

Breakdown	15/10/2018	23:49	17/10/2018	12:18	233,769	Taunton	TN019677
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	STEERING UNSERVICEABLE SEE NOTES						
-----------	----------------------------------	--	--	--	--	--	--

Breakdown	02/11/2018	01:53	02/11/2018	11:23	235,245	Taunton	TN019796
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Limp mode SEE NOTES						
-----------	---------------------	--	--	--	--	--	--

Unplanned Repair	05/11/2018	08:28	05/11/2018	12:30	235,319	Taunton	TN019802
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	engine management light on fault 19185 stored fuel sensor fault						
71 Body Exterior 1	Body Exterior damage to n/s wheelarch noted - ? how / when						

Vehicle Deep Clean	08/11/2018	13:00	09/11/2018	09:42	235,747	Taunton	TN019824
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	08/11/2018	14:08	13/11/2018	10:55	235,747	Taunton	TN019825
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	Resecure panel behind n/s seat cover for chargers]
02 Windscreen Wipers	Replace washer check valve
16 Suspension 1	Replace split o/s/r spring slippers
16 Suspension 2	Replace n/s/f suspension arm
18 Wheels Check Torques	Carry out extended test drive and retorque as per ctrust policy carry out R.B.T
44 Fuel System 1	Rail sensor fault - cleared
52 Electrical Aux	Repair damaged saloon genisys panel
55 Tail Lift	Hand rail damaged remove repair and refit
71 Body Exterior 1	Replace o/s/r lower corner
85 Body Interior 1	Replace damaged grab bag locker strap
86 Doors	Replace inop rear door lock motor
Safety Inspection	Paper copy used by Chris Small
Sealing of stretcher clamp	Sealing of stretcher clamp
Travel Time	
MOT	

Unplanned Repair	23/11/2018	07:00	23/11/2018	08:24	236,998	Taunton	TN019915
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	E/M light on SEE NOTES
-------------	------------------------

Unplanned Repair	07/12/2018	15:45	07/12/2018	16:00	239,091	Taunton	TN020017
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Replace inop o/s full beam bulb
----------------------------	---------------------------------

SAFETY INSPECTION	17/12/2018	13:41	19/12/2018	09:55	240,581	Taunton	TN020071
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 2	rear air con inoperative , see notes	
02 Cab Assembly 1	dash panel left of paper clip broken	
02 Cab Assembly 2	lower bag strap broken	
02 Windscreen	windscreen chipped	Monitoring
03 Instruments & Sensors 1	reset service indicator	

16 Suspension 1	slight play top strut					Monitoring	
17 Tyres Replace	replace offside front and offside rear inner						
18 Wheels Check Torques	carried out extended road test and brake test and re torque wheels						
34 Lights Bulb Replacement	N/S dip beam bulb replaced						
45 Engine Oil Top Up	top up engine oil level (1 litre)						
55 Tail Lift	1 x stretcher lock in tail lift siezed , see notes						
71 Body External Steps	side step not coming out fully						
86 Doors Rear	rear door lock barrel siezed						
89 Seats	both rear attendant seat base covers split					Monitoring	
Safety Inspection	carried out safety inspection						
Vehicle Deep Clean	18/12/2018	12:00	19/12/2018	14:44	240,581	Taunton	TN020081
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	04/01/2019	09:20	04/01/2019	11:31	244,661	Taunton	TN020167
54 Sirens	Inv siren inop - repaired wiring connector at siren unit						
Unplanned Repair	09/01/2019	15:00	09/01/2019	15:30	243,423	Taunton	TN020201
34 Emergency Lights	Replaced broken front roof bar n/s end cap						
Unplanned Repair	17/01/2019	09:28	17/01/2019	10:21	244,411	Taunton	TN020252
85 Body Interior 1	centre dash panel around radio broken , replaced dash panel						
Vehicle Deep Clean	28/01/2019	08:30	28/01/2019	14:00	245,896	Taunton	TN020321
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	29/01/2019	15:45	30/01/2019	08:17	245,948	Taunton	TN020339
02 Mirrors	attend to damaged nearside mirror						

SAFETY INSPECTION	30/01/2019	08:00	31/01/2019	16:01	245,999	Taunton	TN020340
01 Heating 1							
02 Windscreen Wipers							
13 Brakes 1							
17 Tyres							
18 Wheels Check Torques							
44 Add Ad Blue							
71 Body External Steps							
85 Body Interior 1							
Safety Inspection							
Fit 3rd Helmet Restraint							
Handbrake Cable Replacement							
Annual Air Con Service							
Annual Heater Service							
Unplanned Repair	11/03/2019	14:40	12/03/2019	06:44	250,558	Taunton	TN020589
02 Mirrors							
Vehicle Deep Clean	12/03/2019	08:30	12/03/2019	15:50	250,615	Taunton	TN020593
Vehicle Deep Clean							
SAFETY INSPECTION	12/03/2019	12:26	13/03/2019	15:52	250,615	Taunton	TN020594
13 Brake Test							
17 Tyres Replace							
18 Wheels Check Torques							
34 Lights Bulb Replacement							
55 Tail Lift							
Medical Devices Check							
Safety Inspection							
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection							
Gearbox Oil & Filter Change							

Unplanned Repair	18/03/2019	12:04	18/03/2019	12:07	251,302	Taunton	TN020627
02 Mirrors	Replace ns mirror glass						
Breakdown	22/03/2019	14:03	27/03/2019	15:56	251,958	Taunton	TN020656
45 Engine 1	invest loss of power pop noise , replaced turbo see notes attend to nearside injectors leaking all 3 replaced injectors seals , see notes LOUD POP, NOW HAS NO POWER, POSS TURBO , see notes						
45 Engine 2							
Breakdown							
Breakdown	02/04/2019	20:19	03/04/2019	09:20	252,946	Taunton	TN020720
86 Doors Rear	Repaired o/s/r door stay (sheared bolt) back door swings open - not secured						
Breakdown							
SAFETY INSPECTION	22/04/2019	08:26	22/04/2019	13:02	254,918	Taunton	TN020832
02 Cab Ass Fire Extinguisher	Replace fire extinguishers Carry out brake test Front stretcher wheel lock flap siezed Update sat nav Check battery health on mobi med 87% & 88% Carry out safety inspection Axle Oil Change						
13 Brake Test							
18 Wheels Check Torques							
55 Tail Lift							
56 Comms Equipment							
Medical Devices Check							
Safety Inspection							
Axle Oil Change							
Vehicle Deep Clean	01/05/2019	08:00	01/05/2019	15:41	256,570	Taunton	TN020900
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	10/05/2019	14:30	10/05/2019	15:17	257,748	Taunton	TN020958
31 Battery Chassis	Test and replace chassis battery Inv comms power failling - see notes						
56 Comms Power Failure							

Monitoring

BREAKDOWN	24/05/2019	15:23	28/05/2019	16:03	259,414	Taunton	TN021055
85 Body Interior 1	Replace damaged floor trim n/s						
Breakdown	P/Steering fault trace fault to pump replace and clean leaking oil.						
Road Test	Carry out extended road test						
SAFETY INSPECTION	03/06/2019	07:11	05/06/2019	09:23	260,097	Taunton	TN021097
13 Brake Test	Carry out brake test						
13 Brakes 1	Replace front brake discs and pads						
13 Brakes 2	Replace rear brake pads and adjust handbrake						
18 Wheels Check Torques							
34 Emergency Lights	NSF grill blue light not working replace light						
45 Engine 1	NSR injector blowing replace injector seal						
45 Engine Oil Top Up	Top up engine oil						
71 Body Exterior 1	Repair nsf top and bottom corners and nsr top and bottom corners						
86 Door Lock	Replace door lock surround on scoop door non stock parts						
86 Sliding Door	Replace side door center and top bearings						
Medical Devices Check	Check battery health on mobi med 85% & 88%						
Safety Inspection	Carry out safety inspection						
Vehicle Deep Clean	04/06/2019	08:00	04/06/2019	15:40	260,097	Taunton	TN021109
Vehicle Deep Clean	Vehicle Deep Clean						
Tail Lift 12M Service & Weight	12/06/2019	12:00	13/06/2019	13:47	260,957	Taunton	TN021180
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight - done by SWLifts						
Unplanned Repair	17/06/2019	07:01	17/06/2019	07:58	261,390	Taunton	TN021193
34 Lights	Replace os side indicator repeater						
Breakdown	17/06/2019	23:16	18/06/2019	07:14	261,486	Taunton	TN021208

Breakdown Vehicle in limp mode check vehicle found speed limiter left on

Vehicle Deep Clean 15/07/2019 08:00 15/07/2019 15:55 265,415 Taunton TN021394

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 15/07/2019 09:55 26/07/2019 15:15 265,415 Taunton TN021398

01 Air Conditioning 1 Compressor for saloon failed
 16 Suspension 1 Replace ns front and rear spring slippers
 17 Tyres Replace Replace osf and osr inner tyres
 18 Wheels Check Torques Carry out extended test drive and retorque as per trust policy carry out R.B.T
 27 Transmission Automatic oil top up
 45 Engine Oil Top Up Top up engine oil
 86 Sliding Door Replace side door bearings
 Safety Inspection Carry out safety inspection
 Pollen Filter Change Pollen Filter Change
 Fuel Filter Change Change Fuel Filter
 Air Filter Change Air Filter Change

Breakdown 07/08/2019 23:55 08/08/2019 10:58 266,993 Taunton TN021584

01 Air Conditioning 1 Air con leak from seal on compressor replace seal and regass
 43 Exhaust System 1 Bracket broken on DPF new parts on order Awaiting Parts
 71 Body External Steps Fault with motor replace motor with non stock parts
 Breakdown side step wont stay in

Unplanned Repair 28/08/2019 09:30 28/08/2019 11:57 270,189 Taunton TN021696

31 Battery Comms Comms powering down replace comms battery

SAFETY INSPECTION 29/08/2019 09:21 30/08/2019 11:24 270,457 Taunton TN021705

13 Brake Test Carry out brake test
 18 Wheels Check Torques
 34 Lights One saloon light not working Awaiting Parts
 43 Exhaust System 1 Bracket broken on DPF new parts on order

45 Engine Oil Top Up	Top up engine oil						
86 Sliding Door	Top bearings in sliding door noisy			Awaiting Parts			
Medical Devices Check	Check battery health on mobi med 97% & 95%						
Safety Inspection	Carry out safety inspection						
Tail Lift Inspection	Carry out tail lift inspection						
Vehicle Deep Clean	30/08/2019	08:30	30/08/2019	13:54	270,457	Taunton	TN021713
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	02/09/2019	10:00	02/09/2019	11:05	270,900	Taunton	TN021724
45 Engine 1	Inv EML on - replaced air mass sensor						
Unplanned Repair	10/09/2019	15:00	26/09/2019	16:01	271,735	Taunton	TN021796
71 Body Exterior 1	Rear panel/frame replaced by Autospray						
71 Body Exterior 2	Rear wheel arches replaced by Autospray						
85 Body Interior 1	Dekitted to go to bodyshop						
Breakdown	29/09/2019	20:59	30/09/2019	08:55	272,375	Taunton	TN021918
02 Mirrors	Replaced missing n/s mirror glass						
Breakdown	N/S Wing mirror						
Unplanned Repair	02/10/2019	14:45	02/10/2019	15:02	272,429	Taunton	TN021939
34 Lights	One saloon light not working			Awaiting Parts			
34 Lights Bulb Replacement	Replaced n/s dip beam bulb						
86 Sliding Door	Top bearings in sliding door noisy			Awaiting Parts			
SAFETY INSPECTION	07/10/2019	09:43	08/10/2019	10:12	273,508	Taunton	TN021965
02 Cab Assembly 1	floor mat drivers side split on edge			Monitoring			
03 Instruments & Sensors 1	reset service indicator						

13 Brake Test	carried out brake test , footbrake 44% handbrake 18%
17 Tyres Replace	replaced offside outer tyre
18 Wheels Check Torques	carried out road test and re torque 180nm osr
34 Lights	One saloon light not working
45 Engine Oil Top Up	topped up engine oil level
85 Body Interior 1	top bag strap broken
86 Doors	nearside front door wiring harness adrift at A post , see notes
86 Sliding Door	Top bearings in sliding door noisy
Safety Inspection	carried out safety inspection
Travel Time	collect DCA from ilminster

Vehicle Deep Clean	08/10/2019	10:30	08/10/2019	15:31	273,515	Taunton	TN021982
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	14/11/2019	10:52	14/11/2019	11:10	278,369	Taunton	TN022265
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine Ad Blue	Topped up
-------------------	-----------

SAFETY INSPECTION	18/11/2019	07:16	20/11/2019	08:54	278,940	Taunton	TN022288
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windows/Glass	Replace broken os window switch
02 Windscreen Wipers	Replace wiper blades
13 Brake Test	Carry out brake test
17 Tyres Replace	Replace nsf and both nsr tyres
18 Wheels Check Torques	
34 Lights	Replace broken osr fog light osr top side light and osr marker light
45 Engine Oil Top Up	Top up engine oil
86 Door Lock	Replace key battery
89 Seats	Replace seat base on attendant seats and refit locking pins
Safety Inspection	Carry out safety inspection
Travel Time	
MOT	
Brakes Replace Brake Fluid	Replace brake fluid
Tail Lift Inspection	Carry out tail lift inspection

Vehicle Deep Clean	18/11/2019	13:00	19/11/2019	12:29	278,940	Taunton	TN022300
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	27/11/2019	08:00	27/11/2019	10:06	280,008	Taunton	TN022374
34 Emergency Lights	Replaced smashed n/s/r side blue light						
71 Body Exterior 1	Replaced damaged n/s/f top corner						
SAFETY INSPECTION	31/12/2019	08:33	02/01/2020	13:31	284,883	Taunton	TN022639
02 Cab Ass Fire Extinguisher	Replace fire extinguishers						
13 Brake Test	Carry out brake test						
17 Tyres Replace	Replace osf tyre						
18 Wheels Check Torques							
34 Lights	Pod marker lights and side lights not working SEE NOTES						
55 Tail Lift	Refit tail lift guides and replace one tail lift light						
71 Body External Steps	Replace side step suppressor						
86 Door Lock	Replace outer barrel on scoop door lock						
Safety Inspection	Carry out safety inspection						
Travel Time	Collect vehicle from minehead						
Engine Change Oil & Filter	Carry out engine oil and filter change						
Replace Handbrake Cables	Not required cables in good condition						
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Vehicle Deep Clean	02/01/2020	10:30	02/01/2020	16:15	284,887	Taunton	TN022654
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	09/01/2020	07:00	09/01/2020	08:00	285,585	Taunton	TN022707
Camera Installation	Replace broken camera above sliding door						
Unplanned Repair	20/01/2020	08:00	21/01/2020	13:50	286,145	Taunton	TN022821
71 Body Exterior Roof	Replaced smashed skylight (inc fitting blast film)						

Unplanned Repair	22/01/2020	11:42	22/01/2020	12:38	287,059	Taunton	TN022828
34 Lights	Airport light knocked off replace light						
SAFETY INSPECTION	11/02/2020	09:06	11/02/2020	13:58	289,645	Taunton	TN022980
02 Cab Ass Fire Extinguisher	Replace fire extinguisher in saloon						
13 Brake Test	Carry out brake test						
18 Wheels Check Torques							
45 Engine Oil Top Up	Top up engine oil						
71 Body Exterior 1	Resecure bridgeplate guides						
71 Body External Steps	Step not deploying straighten and lubricate						
Medical Devices Check	Check battery health on mobi med 96% & 101%						
Safety Inspection	Carry out safety inspection						
Tail Lift Inspection	Carry out tail lift inspection						
Vehicle Deep Clean	17/02/2020	08:29	17/02/2020	16:45	290,247	Taunton	TN023026
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	27/02/2020	19:05	28/02/2020	07:21	291,678	Taunton	TN023129
34 Lights	Replace NS indicator repeater lense						
Breakdown	NS indicator repeater lense broken						
Unplanned Repair	04/03/2020	11:05	04/03/2020	11:07	292,674	Taunton	TN023170
34 Lights Bulb Replacement	Replace os daytime running light bulb						
Unplanned Repair	10/03/2020	10:30	10/03/2020	11:34	293,636	Taunton	TN023226
86 Doors Rear	Repaired o/s/r door stay						

Unplanned Repair	19/03/2020	11:00	19/03/2020	11:55	295,110	Taunton	TN023290
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body Exterior 1	attend to 2 x tail lift guide blocks pulled from body , see notes						
--------------------	---	--	--	--	--	--	--

SAFETY INSPECTION	24/03/2020	08:00	25/03/2020	16:00	295,740	Taunton	TN023331
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	Replace cab interior light bulb
03 Instruments & Sensors 1	Reset service indicator
13 Brakes 1	Replace rear brake discs and pads
16 Suspension 1	Replace worn rear spring eye bushes
17 Tyres	
18 Wheels Check Torques	Carry out extended test drive and retorque carry out R.B.T
27 Transmission Automatic	Replace front propshaft
55 Tail Lift	Tail lift hand rails seized strip free off and lube
71 Body Exterior 1	N/S/F fog lamp bezal insecure refit
85 Body Interior 1	Repair and resecure locker door below stretcher head seat
89 Seats	Saloon swival seats plungers seized free off and lube
Safety Inspection	

Vehicle Deep Clean	26/03/2020	09:15	27/03/2020	07:30	295,785	Taunton	TN023352
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	14/04/2020	12:00	14/04/2020	14:49	298,570	Taunton	TN023472
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Doors Rear	rear door stay broken , replaced rear door stay bar						
---------------	---	--	--	--	--	--	--

SAFETY INSPECTION	01/05/2020	07:09	01/05/2020	15:30	300,574	Taunton	TN023584
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	Replace cab interior light bulb	
02 Cab Assembly 2	Small split in floor mat o/s	Monitoring
13 Brakes 1	Replace worn brake pedal rubber	
18 Wheels Check Torques		
44 Add Ad Blue		
55 Tail Lift	1x hose replaced	

71 Body Exterior 1	Tail lift guide blocks insecure drill out broken bolts and refit
85 Body Interior 1	Chair track locker door insecure repair and resecure
86 Door Lock	Replace side locker door barrel
86 Doors Rear	Doors Restraining arm snapped
89 Seats	Saloon seat plunger nuts insecure resecure
Safety Inspection	
Tail Lift Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight

Vehicle Deep Clean	07/05/2020	08:00	07/05/2020	14:39	301,295	Taunton	TN023633
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	07/05/2020	13:00	07/05/2020	14:02	301,295	Taunton	TN023634
55 Tail Lift	2 x tail lift guards adrift from body work , see notes						
Unplanned Repair	09/05/2020	15:45	09/05/2020	16:05	301,651	Taunton	TN023642
44 Add Ad Blue	Topped up						
Unplanned Repair	13/05/2020	08:00	13/05/2020	08:34	302,267	Taunton	TN023667
42 Coolant System	Replace faulty radiator expansion bottle.						
Unplanned Repair	30/05/2020	10:37	30/05/2020	11:30	304,496	Taunton	TN023792
31 Battery Comms	Replaced faulty comms bty						
Breakdown	12/06/2020	21:30	15/06/2020	14:26	305,837	Taunton	TN023891
Breakdown	very strong smell under bonnet; VOR , see notes						
SAFETY INSPECTION	13/06/2020	07:12	15/06/2020	15:50	305,903	Taunton	TN023892

02 Cab Assembly 1	tool box cover / lid cracked broken	
02 Cab Assembly 2	Small split in floor mat o/s	
02 Windscreen	windscreen chipped	Monitoring
13 Brake Test	carried out brake test , footbrake 35% handbrake 12%	
16 Suspension 1	slight play in offside front shockabsorber	Monitoring
16 Suspension 2	play in both lower arm ball joints - within tolerance	Monitoring
16 Suspension 3	excessive play in rear anti roll bar bushes , replaced both bushes	
17 Tyres	replaced nsr,nsri,osro,nsf,osf	
18 Wheels	Replaced 1x cracked rim	
18 Wheels Check Torques	carried out extended road test and re-torque 180nm	
34 Lights Bulb Replacement	replaced n/s day running light bulb + n/s side light + headlamp os	
45 Engine 1	oil leak from air dozer	
45 Engine 2	injectors leaking 4 . see job TN023891	
45 Engine 3	turbo intake pipe bracket broken	
45 Engine Oil Top Up	topped up engine oil level 1.5 litres	
85 Body Interior 1	Replaced broken saloon clock	
85 Body Interior 2	locker door scoop strap u/s , replaced damaged strap	
86 Doors	locker door key spinning in lock	
89 Seats	drivers seat base cover holed , cushion holed . replaced both cover & cushion	
Medical Devices Check	mobimed batteries , 86% & 83%	
Medical Devices Repair	stylist pen missing from mobi med , fit new pen	
Safety Inspection	carried out safety inspection	

Vehicle Deep Clean	15/06/2020	08:00	15/06/2020	15:42	306,034	Taunton	TN023901
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	19/06/2020	12:30	19/06/2020	13:36	306,508	Taunton	TN023927
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	attend to damaged offside door mirror , see notes
71 Body Exterior 1	Body Exterior Driver wmirror broke by wall. Minor glass break

Unplanned Repair	25/06/2020	08:15	25/06/2020	08:56	307,331	Taunton	TN023970
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	replaced damaged offside front mirror motor test operation all ok	
02 Windscreen	windscreen chipped	Monitoring
16 Suspension 1	slight play in offside front shockabsorber	Monitoring
16 Suspension 2	play in both lower arm ball joints - within tolerance	Monitoring

Unplanned Repair	29/06/2020	07:00	29/06/2020	14:10	307,626	Taunton	TN024003
52 Electrical Aux 56 Comms Equipment	Reported E.P.C.R inop check cradle and power feed no faults Radio signal poor replace broken aerial						
Unplanned Repair	02/07/2020	09:00	02/07/2020	15:30	308,079	Taunton	TN024032
71 Body Exterior 1	Refit rear mudflap						
Unplanned Repair	06/07/2020	08:30	06/07/2020	09:18	308,778	Taunton	TN024059
02 Windscreen 16 Suspension 1 16 Suspension 2 85 Body Interior 1	windscreen chipped slight play in offside front shockabsorber play in both lower arm ball joints - within tolerance carry chair jammed in cradle , see notes						
Unplanned Repair	07/07/2020	11:00	07/07/2020	12:00	308,958	Taunton	TN024065
45 Engine 1 56 Comms Power Failure	EML on - driving ok - SEE NOTES Inv comms power failing - see notes						
Unplanned Repair	08/07/2020	07:55	08/07/2020	09:11	309,044	Taunton	TN024068
43 Exhaust System 1	Replaced faulty NOX sensor 1 - inc clearing codes & roadtest						
Breakdown	19/07/2020	22:08	20/07/2020	13:30	310,795	Taunton	TN024139
02 Windows/Glass 34 Emergency Lights 45 Engine 1 Breakdown Road Test	replaced broken nearside front window switch test all ok nearside rear sceen light knocked off , see notes attend to diesel leak EML on limp mode , read faults carried out extended road test						
Breakdown	21/07/2020	00:58	30/07/2020	15:51	310,876	Taunton	TN024151
001 Recover Vehicle 002 Major Unit Replace Eng	Vehicle Recovery to Mercedes van centre Taunton Engine replaced by Merc Taunton						

31 Battery Chassis	Tested & replaced chassis battery.
45 Engine 1	Injector blown out of head - bolt pulled out.
Breakdown	engine blown no power , see notes
Travel Time	Collection from Merc.

SAFETY INSPECTION	30/07/2020	11:49	31/07/2020	16:17	310,886	Taunton	TN024234
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	drivers torch inoperative	
02 Cab Assembly 2	drivers floor mat split	
16 Suspension 1	slight play in both front lower arm ball joints , within tolerance	Monitoring
16 Suspension 2	slight play in offside front shockabsorber	Monitoring
18 Wheels Check Torques		
34 Lights	Electrical Auxs FLOOD LIGHT	
43 Exhaust System 1	top bracket on dpf cracked on 1 side	Monitoring
44 Add Ad Blue	top up adblue from main tank	
44 Fuel System 1	Leak from fuel system. Clip on fuel line near starter not clipped together.	
45 Engine 1	Aux belt not alligned correctly on A/C pulley. Realligned.	
52 Electrical Aux	Replace cab interior light bulb	
86 Door Lock	Replace locker door lock barrel	
86 Doors	locker door lock spinning with key	
Safety Inspection		
Travel Time	Pick up vehicle from Mercedes van centre	
Engine Change Oil & Filter		
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card	
Tail Lift Inspection	carried out lift inspection	

Vehicle Deep Clean	31/07/2020	12:30	31/07/2020	15:37	310,895	Taunton	TN024243
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	01/08/2020	22:00	03/08/2020	14:42	310,930	Taunton	TN024247
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

42 Coolant System	Inv coolant loss - see notes
Breakdown	Coolant leak

Unplanned Repair	04/08/2020	07:00	04/08/2020	14:56	311,095	Taunton	TN024260
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

43 Exhaust System 1	Replaced NOx sensor 2, cleared codes & took to Merc for recoding D5
45 Engine Ad Blue	Inv Adblue system fault W/L on

Unplanned Repair	06/08/2020	12:00	06/08/2020	13:05	311,381	Taunton	TN024296
71 Body Exterior 1	Repaired & resecured 3x tail lift rubbing blocks						
Unplanned Repair	07/08/2020	13:00	07/08/2020	14:35	311,502	Taunton	TN024303
44 Add Ad Blue	Top up 10lts						
Unplanned Repair	10/08/2020	08:00	10/08/2020	15:10	311,861	Taunton	TN024306
17 Tyres	OSF tyre pressure low - cracked rim.						
18 Wheels							
18 Wheels Retorque	Carry out extended test drive and retorque						
Vehicle Deep Clean	09/09/2020	12:00	10/09/2020	12:06	316,545	Taunton	TN024520
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/09/2020	09:47	11/09/2020	10:03	316,545	Taunton	TN024529
02 Cab Assembly 1	drivers floor mat split					Monitoring	
13 Brake Test	carried out brake test , footbrake 46% handbrake 15%						
13 Brakes 1	front brake pads low , replaced front brake pads						
16 Suspension 1	slight play in both front lower arm ball joints , within tolerance					Monitoring	
16 Suspension 2	slight play in offside front shockabsorber					Monitoring	
18 Wheels Check Torques	carried out extended road test						
18 Wheels Retorque	carried out re-torque 180nm						
34 Lights	offside rear lamp dim , replaced lamp unit test all ok						
43 Exhaust System 1	top bracket on dpf cracked on 1 side					Monitoring	
71 Body Exterior Roof	roof hatch has a bolt missing						
Safety Inspection	carried out safety inspection						
Supply Sat Nav	updated sat nav to latest software version 5.30						
Fuel Filter Change	Change Fuel Filter, not required as replaced with new engine at 310,000 miles						
Air Filter Change	Air Filter Change ,not required as replaced with new engine at 310,000 miles						
Pollen Filter Change	Pollen Filter Change , CARRIED OUT						
Medical Devices Repair	09/09/2020	13:37	09/09/2020	13:44	316,545	MDT Taunton	TT000525

Decontaminated	Cleaned with clinell wipes
Defect Sheet Present No	
Defect Sheet Present Yes	
Medical Devices Repair	O2 leak from outlet port, new service kit fitted, please see notes

Unplanned Repair	16/09/2020	16:06	17/09/2020	14:38	317,182	Taunton	TN024584
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	drivers floor mat split	Monitoring
31 Battery Aux	Powerfailing - See Notes	
43 Exhaust System 1	top bracket on dpf cracked on 1 side	Monitoring
55 Tail Lift	Replace tail lift battery	

Unplanned Repair	18/09/2020	13:00	18/09/2020	16:10	317,521	Taunton	TN024601
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	drivers floor mat split	Monitoring
43 Exhaust System 1	top bracket on dpf cracked on 1 side	Monitoring
52 Electrical Aux	Earth issue - See notes	

Unplanned Repair	23/09/2020	13:55	23/09/2020	13:58	318,368	Taunton	TN024642
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Replace ns dip, main beam and os daytime running light bulbs
----------------------------	--

BREAKDOWN	29/09/2020	12:15	29/09/2020	13:30	319,293	Exeter	EX026829
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

44 Fuel System 1	fuel leak see notes
Travel Time	travel and return from westpoint show ground.

Breakdown	29/09/2020	13:01	01/10/2020	12:00	319,293	Taunton	TN024682
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Fuel leak
-----------	-----------

SAFETY INSPECTION	21/10/2020	12:14	23/10/2020	11:55	322,947	Taunton	TN024827
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	drivers floor mat split	Monitoring
02 Windscreen	windscreen chipped	Monitoring

03 Instruments & Sensors 1	RE-SET SERVICE INDICATOR - with texa						
16 Suspension 1	play in both front lower arm ball joints - within tolerance						Monitoring
18 Wheels Check Torques	CARRIED OUT EXTENDED ROAD TEST						
34 Emergency Lights	3 x led inoperative on nearside rear side blue light						Monitoring
34 Lights	nearside rear indicator lamp u/s						
43 Exhaust System 1	top bracket on dpf cracked on 1 side						Monitoring
45 Engine 1	cooling fan and cowling damaged - new required , see notes						
45 Engine Oil Top Up	topped up engine oil level						
55 Tail Lift	right lift rail bent , left rail siezed bearing picked up , see notes						
71 Body Exterior 1	2 x lift guards pulled out from body , see notes						
89 Seats	locking pin on rear attendant seat loose						
Medical Devices Check	mobimed batteries health 95% & 85%						
Safety Inspection	carried out safety inspection						
Travel Time	take vehicle to A1 MOT CENTRE						
Tail Lift Inspection	carried out loler inspection						
MOT	carried out mot test at A1 mot centre						
Vehicle Deep Clean	23/10/2020	11:00	23/10/2020	15:32	322,957	Taunton	TN024850
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	01/11/2020	11:30	01/11/2020	11:51	324,282	Taunton	TN024921
02 Cab Assembly 1	drivers floor mat split						Monitoring
02 Windscreen	windscreen chipped						Monitoring
16 Suspension 1	play in both front lower arm ball joints - within tolerance						Monitoring
34 Emergency Lights	3 x led inoperative on nearside rear side blue light						Monitoring
34 Lights Bulb Replacement	replaced offside front headlamp bulb						
43 Exhaust System 1	top bracket on dpf cracked on 1 side						Monitoring
Unplanned Repair	18/11/2020	11:15	18/11/2020	11:30	326,713	Taunton	TN025053
44 Add Ad Blue							
Unplanned Repair	23/11/2020	08:00	23/11/2020	09:32	327,579	Taunton	TN025092
55 Tail Lift	Adj. Rail bearings tight. Remove rail, clean and lubricate. Refit.						

56 Comms Equipment Reboot M.D.T and check battery voltages.

SAFETY INSPECTION **27/11/2020** **07:40** **30/11/2020** **12:11** **328,309** **Taunton** **TN025134**

02 Cab Ass Fire Extinguisher	fire extinguisher expired in cab	
02 Cab Assembly 1	drivers floor mat split	Monitoring
02 Windscreen	windscreen chipped	Monitoring
13 Brake Test	carried out brake test , footbrake 42% handbrake 19%	
13 Brakes 2	rear brakes low - removed wheels and will go too next safety inspection	Monitoring
16 Suspension 1	play in both front lower arm ball joints - within tolerance	Monitoring
17 Tyres Replace	replaced all 4 tyres inc cleaning up the hubs , keeping 3 part worn tyres back	
18 Wheels Check Torques	carried out extended road test	
18 Wheels Retorque	re-torque rear wheels 180nm	
34 Emergency Lights	3 x led inoperative on nearside rear side blue light	Monitoring
43 Exhaust System 1	top bracket on dpf cracked on 1 side	Monitoring
45 Engine Oil Top Up	topped up engine oil level	
71 Body Exterior 1	front bumper damaged nearside	Monitoring
71 Body Exterior 2	nearside rear corner cap damaged / holed , replaced cap and reflector	
85 Body Interior 1	saloon fire extinguisher expired	
85 Body Interior 2	coms radio phone holder in saloon adrift , re-secure holder	
85 Body Interior 3	cupboard door trim adrift in saloon - re-secure with screws all ok	
89 Seats	both rear and front attendant seat base release pin nuts loose	
Safety Inspection	carried out safety inspection	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change	

Vehicle Deep Clean **30/11/2020** **08:30** **30/11/2020** **15:12** **328,354** **Taunton** **TN025145**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **12/12/2020** **09:00** **12/12/2020** **14:59** **329,827** **Taunton** **TN025231**

34 Lights Inv n/s brake lights inop. Temp repaired to get working - fault with SAM unit

Unplanned Repair **15/12/2020** **08:00** **15/12/2020** **08:25** **330,032** **Taunton** **TN025254**

02 Cab Assembly 1	drivers floor mat split	Monitoring
02 Windscreen	windscreen chipped	Monitoring

13 Brakes 2	rear brakes low - removed wheels and will go too next safety inspection	Monitoring
16 Suspension 1	play in both front lower arm ball joints - within tolerance	Monitoring
33 Ignition System	replaced remote key blip battery	
34 Emergency Lights	3 x led inoperative on nearside rear side blue light	Monitoring
43 Exhaust System 1	top bracket on dpf cracked on 1 side	Monitoring
71 Body Exterior 1	front bumper damaged nearside	Monitoring

Unplanned Repair	23/12/2020	11:40	23/12/2020	13:24	331,618	Taunton	TN025315
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

42 Coolant System	Coolant light on expansion tank leaking replace tank
-------------------	--

Unplanned Repair	30/12/2020	13:45	30/12/2020	14:30	332,866	Taunton	TN025369
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Replaced n/s main beam bulb
----------------------------	-----------------------------

Unplanned Repair	02/01/2021	11:30	02/01/2021	12:03	333,359	Taunton	TN025393
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

55 Tail Lift	Straightened bent RH handrail. Freed & lubed sticking LH handrail drop feature
--------------	--

SAFETY INSPECTION	08/01/2021	08:34	11/01/2021	16:02	334,313	Taunton	TN025446
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	saloon fire extinguisher expired	
02 Cab Assembly 1	drivers floor mat split , requires new floor mat	Monitoring
02 Cab Assembly 2	tool box lid/cover broken - replaced glove box lid/cover	
02 Windscreen	windscreen chipped	Monitoring
03 Instruments & Sensors 1	reset service indicator with texa	
13 Brakes 1	Replace worn rear brake pads	
15 Steering 1	Replace leaking powersteering pump.	
16 Suspension 1	play in both front lower arm ball joints - within tolerance	Monitoring
18 Wheels Check Torques		
34 Emergency Lights	replaced offside front marker light	
34 Lights	attend too lights inoperative at rear - wiring fault see notes	
43 Exhaust System 1	top bracket on dpf cracked on 1 side	Monitoring
43 Exhaust System 2	replaced rear exhaust pipe and replaced front exhaust dpf clamp	
44 Add Ad Blue	top up adblue system	
55 Tail Lift	slow close inop & lights on when rear door open - Replace mercury switch.	
71 Body Exterior 1	front bumper damaged nearside	Monitoring

71 Body Exterior 2	rear mud flap insecure , resecure mudflap drilling new holes & new bolts
85 Body Interior 1	lower bag strap broken
85 Body Interior 3	Remove repair and refit chair track locker door
85 Body Interior Roof	skylight blind u/s - new blind required
89 Seatbelts	front swivel seat seatbelt insecure
89 Seats	swivel seat plunger nuts insecure
Medical Devices Check	mobimed battery health . 95% & 85%
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Engine Change Oil & Filter	
Tail Lift Inspection	

Vehicle Deep Clean	11/01/2021	08:00	11/01/2021	14:58	334,313	Taunton	TN025471
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	06/02/2021	07:13	07/02/2021	06:25	338,455	Taunton	TN025683
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Front offside tyre
-----------	--------------------

Unplanned Repair	07/02/2021	14:00	07/02/2021	14:41	338,594	Taunton	TN025702
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Tracking	Check and adjust tracking
87 - Stretchers/Chairs/Boards	Supply stretcher harness belts

Breakdown	09/02/2021	03:53	09/02/2021	14:29	338,978	Taunton	TN025715
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Charging System	Alternator not charging replace alternator
34 Emergency Lights	Repair wiring to grill lights one new light required
42 Coolant System	Replace leaking header tank
42 Radiator	Resecure radiator to front pannel
86 Sliding Door	Replace side door center bearings
Breakdown	Alternator light on

Unplanned Repair	10/02/2021	07:28	10/02/2021	08:28	339,043	Taunton	TN025723
34 Emergency Lights	Replace osf grill light						
Unplanned Repair	11/02/2021	08:00	11/02/2021	12:00	339,263	Taunton	TN025742
86 Door handle	Rear door external handle snapped. Replace.						
Unplanned Repair	14/02/2021	14:45	14/02/2021	15:00	339,521	Taunton	TN025768
34 Lights Bulb Replacement	Replace ns daytime running bulb						
SAFETY INSPECTION	19/02/2021	08:16	20/02/2021	08:13	339,929	Taunton	TN025796
02 Cab Assembly 1	drivers floor mat split , requires new floor mat					Monitoring	
02 Windscreen	windscreen chipped					Monitoring	
02 Windscreen Wipers	replaced wiper blades						
13 Brake Test	carried out brake test , footbrake 45% handbrake 25%						
13 Brakes 1	replaced brake pedal rubber.						
16 Suspension 1	play in both front lower arm ball joints - within tolerance					Monitoring	
18 Wheels Check Torques	carried out extended road test - recheck aux belt all ok						
24 Driveshaft 1	rear propshaft missing a grease nipple - fit a new grease nipple						
43 Exhaust System 1	top bracket on dpf cracked on 1 side					Monitoring	
45 Engine Oil Top Up	TOPPED UP ENGINE OIL LEVEL						
71 Body Exterior 1	front bumper damaged nearside					Monitoring	
71 Body Exterior 2	rear mud flap loose and bent , straighten and re-secure mudflap						
71 Body Exterior 3	big rear door rattling top catch worn replaced top catch						
71 Body Exterior Roof	roof blind in saloon u/s					Monitoring	
71 Body External Steps	side step sticking not fully deploying ,see notes						
86 Door handle	Replaced broken side door outer handle						
86 Doors	locker door lock spinning - outer barrel broken						
Aux drive belt change	a/c and fan belt damaged- incorrectly fitted - replaced belt and check alignment						
Safety Inspection	carried out safety inspection						
Vehicle Deep Clean	22/02/2021	08:00	22/02/2021	14:57	340,050	Taunton	TN025819
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	08/03/2021	07:01	08/03/2021	07:48	341,983	Taunton	TN025915
34 Lights	Daytime running lighjts not working SEE NOTES						
Unplanned Repair	12/03/2021	11:30	12/03/2021	12:05	342,575	Taunton	TN025959
02 Mirrors 86 Sliding Door	Replaced broken n/s mirror glass Lubed side door catches & rollers						
Unplanned Repair	18/03/2021	14:45	18/03/2021	15:45	343,814	Taunton	TN026014
86 Sliding Door	Inv side door inop - Adjusted linkage & cables						
SAFETY INSPECTION	02/04/2021	08:24	02/04/2021	14:52	346,349	Taunton	TN026125
13 Brake Test 13 Brakes 1 16 Suspension 1 18 Wheels Check Torques 34 Lights Bulb Replacement 55 Tail Lift 71 Body Exterior Roof 86 Doors Rear Safety Inspection Travel Time Tail Lift Inspection	Carry out brake test Adjust handbrake Refit nsr spring slipper unable to repalce no stock Replace cab interior light bulb Adjust tail lift rams strip and clean bearings on ns tail lift rail Replaced broken skylight blind Replaced top catch slam plate Carry out tail lift inspection Collect vehicle from bridgwater Carry out tail lift inspection						
Vehicle Deep Clean	04/04/2021	09:00	04/04/2021	17:41	346,587	Taunton	TN026134
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	08/04/2021	00:13	09/04/2021	14:43	347,100	Taunton	TN026155
56 Comms Equipment Breakdown	Check for not plotting carry out checks with control all ok MDT not plotting						

Unplanned Repair	19/04/2021	07:45	26/04/2021	15:36	348,054	Taunton	TN026225
45 Engine 1	Turbo replaced by Mercedes under warranty						
99 Diagnostic Test	Carry out daignostic test fault with boost control flap mercedes warranty						
Breakdown	Engine LIMP MODE VOR #499637						
Travel Time	collected from Mercedes						
Breakdown	12/05/2021	22:27	13/05/2021	02:00	351,172	Taunton	TN026410
Breakdown	limp mode						
SAFETY INSPECTION	20/05/2021	13:00	21/05/2021	15:06	352,373	Taunton	TN026470
01 Air Conditioning 1	air conditioning inoperative 18'c , no gas in system , see notes						
02 Cab Assembly 1	drivers floor mat split down the edge						
02 Windscreen	windscreen chipped						
13 Brake Test	carried out brake test . footbrake 32% handbrake 22%						
15 Steering 1	power steering fluid leak , pipe clip loose tighten up clip pipe secure						
16 Suspension 1	both front and rear offside rear spring slippers u/s , see notes						
17 Tyres Replace	replace both rear inner tyres						
18 Wheels Check Torques	carried out extended road test						
18 Wheels Retorque	carried out re-torque on rear wheels 180nm						
34 Emergency Lights	nearside end cap missing from roof bar lights						
34 Lights	n/s/r reverse light partly inop + n/s/r side blue light partly inop						
44 Add Ad Blue	top up adblue , 12 litres from stock						
45 Engine 1	air dozer seals leaking , replaced all air dozer seals						
45 Engine Oil Top Up	topped up engine oil level						
54 Horns	bull horn trim broken and has sharp edges -see notes						
71 Body Exterior 1	drivers door seal split						
71 Body Exterior 2	nearside front top end cap damaged / holed - replaced end cap						
71 Body External Steps	side step sticking , lubricate step						
85 Body Interior 1	scoop strap broken						
89 Seats	rear attendant seat base locking pin loose						
Safety Inspection	carried out safety inspection						

Vehicle Deep Clean	25/05/2021	08:30	25/05/2021	15:45	352,847	Taunton	TN026504
Vehicle Deep Clean	Vehicle Deep Clean						
Tail Lift 12M Service & Weight	27/05/2021	09:00	27/05/2021	12:30	353,068	Taunton	TN026702
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight - SWLifts						
Unplanned Repair	31/05/2021	06:54	31/05/2021	08:03	353,463	Taunton	TN026544
34 Emergency Lights	Blue grill lights not working check connections and reinitiate						
ACCIDENT	07/06/2021	11:03	24/06/2021	12:14	354,170	Taunton	TN026602
71 Body Exterior Acc Repair	Accident damage to os battery box to go to autospray						
SAFETY INSPECTION	30/06/2021	14:00	01/07/2021	13:12	355,063	Taunton	TN026776
02 Windscreen Wipers	Wiper linkage noisy replace linkage						
13 Brake Test	Carry out brake test						
18 Wheels Check Torques							
34 Lights	OS daytime running not working socket melted replace headlight						
86 Sliding Door	Replace center side door bearings						
Safety Inspection	Carry out safety inspection						
Tail Lift Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight carried out by south west lifts						
Unplanned Repair	07/07/2021	07:00	07/07/2021	07:32	355,664	Taunton	TN026823
86 Doors Rear	Rear door open warning adjust microswitch						
Vehicle Deep Clean	29/07/2021	09:15	29/07/2021	13:15	358,874	Dorchester	DC025568

Vehicle Deep Clean

Vehicle Deep Clean

SAFETY INSPECTION **12/08/2021** **08:25** **15/08/2021** **14:00** **360,132** **Dorchester** **DC025674**

01 Air Conditioning 1 adjuster u/s
 02 Cab Ass Fire Extinguisher replace fire ext
 02 Cab Assembly 1 foot plate damaged
 11 Axle Rear hub seal leaking
 13 Brakes 1 fronts worn
 13 Brakes 2 rears worn. telamar heat shield rubbing
 13 Handbrake Replace shoes
 16 Suspension 1 Struts and arms worn
 16 Suspension 2 ARB bushes worn
 18 Wheels no valve extensions on rear
 18 Wheels Check Torques
 34 Lights reverse light inop
 42 Radiator Radiator leaking
 45 Engine 1 Air box mounts u/s
 45 Engine Ad Blue top up
 55 Tail Lift replace 2x hoses
 71 Body External Steps side step sticking
 85 Body Interior 1 remove cables
 Safety Inspection
 Engine Change Oil & Filter
 Wheel Hub Flanges Replaceme

Vehicle Deep Clean **16/08/2021** **09:00** **16/08/2021** **14:00** **360,146** **Dorchester** **DC025699**

Vehicle Deep Clean

Vehicle Deep Clean

Breakdown **20/08/2021** **14:21** **21/08/2021** **10:21** **360,428** **Dorchester** **DC025740**

42 Coolant System
 Breakdown coolant leak-steering-smoke from engine

Unplanned Repair **30/08/2021** **10:30** **30/08/2021** **11:26** **361,576** **Dorchester** **DC025808**

34 Lights	N/S Indicators not working.....SEE NOTES
56 Comms Equipment	MDT power failing, reset and check batteries

Breakdown	06/09/2021	07:10	06/09/2021	13:45	362,572	Dorchester	DC025842
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	O/S wide angle mirror missing. Replace
45 Engine Ad Blue	System topped up with screen wash.See notes
Breakdown	put wrong liquid in adblue tank.
DEFCT01	Mirrors Wing mirror struck concealed wall in hedge.

Vehicle Deep Clean	21/09/2021	13:38	22/09/2021	11:00	364,040	Dorchester	DC025973
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	22/09/2021	11:55	23/09/2021	15:16	364,049	Dorchester	DC025988
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	OS mirror frame damaged
18 Wheels Check Torques	
34 Emergency Light System	upper front blue lights, NS inner not flashing, OS inner not working
34 Emergency Lights	NSR rectangular blue light @50%
34 Lights	NSR upper indicator, incorrect type
44 Add Ad Blue	top up
45 Engine 1	both engine mounts split
55 Tail Lift	guide rail seized
85 Body Interior 1	stratcher guide buffer damaged
Check Winter Pack	
Safety Inspection	
Tail Lift Inspection	

Breakdown	25/09/2021	19:40	27/09/2021	10:00	364,339	Dorchester	DC026012
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Doors Rear	Door open warning on.Catch fixings missing.Replace
Breakdown	back door not locking(warning); VOR
Travel Time	

Breakdown	02/10/2021	13:24	04/10/2021	08:23	364,805	Dorchester	DC026063
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown side step n/w & water leak; VOR

Breakdown 10/10/2021 08:57 13/10/2021 15:45 365,608 Dorchester DC026108

02 Glass / Windows window inop n/s.....switch u/s
Breakdown MDT screen black/frozen VOR
Travel Time

Unplanned Repair 17/10/2021 23:40 17/10/2021 23:55 366,048 Dorchester DC026158

34 Lights Bulb Replacement Headlamp bulb replaced by Bronze

SAFETY INSPECTION 04/11/2021 08:07 06/11/2021 11:30 369,750 Dorchester DC026280

02 Cab Ass Fire Extinguisher out of date fire ext.
03 Instruments & Sensors 1 EML and Service lights on
18 Wheels Check Torques
44 Fuel System 1 no fuel angel fitted
45 Engine 1 N/S engine mount bolt missing
45 Engine Ad Blue Cap missing, top up level
54 Reversing Systems Camera screen cracked.. requires replacement
85 Body Interior 1 catch cover damaged
86 Doors passenger door check strap broken
86 Doors Rear large rear door seal u/s
Safety Inspection
Travel Time
Wash Vehicle clean off before inspection/mot
Fuel Filter Change Change Fuel Filter
Air Filter Change Air Filter Change
Pollen Filter Change Pollen Filter Change
Brake Fluid Change Brake Fluid Change
MOT

Vehicle Deep Clean 05/11/2021 09:00 05/11/2021 12:18 369,744 Dorchester DC026300

Vehicle Deep Clean Vehicle Deep Clean

Breakdown	23/11/2021	09:34	23/11/2021	11:09	370,382	Dorchester	DC026408
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	FIRE SUPPRESSION WARNING						
-----------	--------------------------	--	--	--	--	--	--

Breakdown	11/12/2021	19:56	30/12/2021	13:44	374,352	Dorchester	DC026554
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers	Replace						
44 Add Ad Blue							
45 Engine 1	Faulty throttle pedal.ECU failed						
45 Engine Oil Top Up							
Breakdown	limp mode; ESP warning; VOR. See notes						
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							

Breakdown	14/12/2021	13:51	14/12/2021	15:08	374,352	Dorchester	DC026579
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	runs but not well						
-----------	-------------------	--	--	--	--	--	--

Vehicle Deep Clean	31/12/2021	08:30	31/12/2021	12:00	374,404	Dorchester	DC026722
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Breakdown	07/01/2022	14:08	07/01/2022	14:56	375,376	Dorchester	DC026791
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	REAR RAMP ALARM FAULT AND SIDE STEP						
-----------	-------------------------------------	--	--	--	--	--	--

Breakdown	10/01/2022	10:25	10/01/2022	13:40	376,866	Dorchester	DC026801
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	flat tyre front nearside						
-----------	--------------------------	--	--	--	--	--	--

BREAKDOWN	20/01/2022	07:23	20/01/2022	12:55	377,948	Dorchester	DC026875
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1	Body Interior Saloon heater not staying on
45 Engine 1	Engine intermittent EML
55 Tail Lift	Ramp/Lift/Tail Hoist tail lift alarming
85 Body Interior 1	luggage strap damaged

Breakdown	22/01/2022	09:56	24/01/2022	12:00	378,335	Dorchester	DC026906
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1	Blower motor inop,replace	
02 Cab Assembly 1	Cab mats required	
02 Cab Assembly 2	torch inop, pedal rubber split	
02 Windscreen Wipers	washers blocked	
17 Tyres	2x low	
18 Wheels	rim cracked	
34 Lights	O/S DRL not working. N/S side light	
43 Exhaust System 1	DPF Crack around welds By top bracket	Monitoring
45 Engine 1	EMI on,replace air mass meter	
45 Engine Ad Blue	top up	
55 Tail Lift	Stuck in slow close..NO PARTS.....	
71 Body Exterior 1	Rear flap loose	
86 Door Lock	Rear lock inop	
86 Door Seals	Replace door seals on rear	
86 Sliding Door	catch covers damaged	
Breakdown	heating not working/EML on	
Annual Air Con Service	Annual Air Condition Service	
Annual Heater Service	Annual Heater Service	
18 Wheels Check Torques		
Safety Inspection		

Vehicle Deep Clean	24/01/2022	15:49	25/01/2022	13:16	378,388	Dorchester	DC026926
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	31/01/2022	01:12	31/01/2022	08:52	379,300	Dorchester	DC026975
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Sliding Door	Outer door handle snapped off.Replace
-----------------	---------------------------------------

Breakdown side door handle snapped off

Unplanned Repair 07/02/2022 12:30 07/02/2022 12:45 379,800 Dorchester DC027032

45 Engine Ad Blue Replace missing AdBlue cap

COMMS.FAILURE CHECK09/02/2022 08:23 09/02/2022 12:48 381,131 Dorchester DC027043

MDT Failure/Issue M531 reported faulty, Halls electrical to sort

Breakdown 14/02/2022 19:57 15/02/2022 13:51 381,980 Dorchester DC027075

45 Engine 1 EML on limp mode
71 Body Exterior 1 NSR corner cap missing
Breakdown limp mode & Struggling to find gears

Breakdown 19/02/2022 21:10 25/02/2022 11:46 382,693 Dorchester DC027105

01 Air Conditioning 1 climate control fault picked up on TEXA, replace control unit
Breakdown iN IIMP MODE

Breakdown 04/03/2022 10:50 04/03/2022 12:00 383,717 Dorchester DC027182

Breakdown Flat

Breakdown 05/03/2022 16:46 14/03/2022 13:10 383,926 Dorchester DC027191

Breakdown limp mode; VOR

18 Wheels Check Torques
Safety Inspection
Travel Time

Engine Change Oil & Filter

Tail Lift Inspection Replace tilt sensor, straighten o/s gate

44 Add Ad Blue

17 Tyres Replace Replace n/s/r inner, been run flat

43 Exhaust System 1 DPF Crack around welds By top bracket

43 Exhaust System 2 CAT blocked, replace nox sensor, and tail pipe

02 Pipeline Annual Inspection	07/03/2022	11:00	07/03/2022	11:30	383,921	MDT Weymouth	DW000825
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - no faults						
Vehicle Deep Clean	15/03/2022	13:30	16/03/2022	13:19	383,951	Dorchester	DC027276
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	18/03/2022	15:17	19/03/2022	06:00	384,094	Dorchester	DC027304
Breakdown	MDT freezing/unable to book on; VOR						
Breakdown	23/03/2022	23:27	24/03/2022	14:55	384,420	Dorchester	DC027331
Breakdown	SIDE DOOR LOCK BROKE UNABLE TO ACCESS FROM OUTSIDE						
ACCIDENT	24/03/2022	18:16	28/03/2022	08:27	385,000	Dorchester	DC027343
Breakdown	Rear view camera is cracked						
Breakdown	20/04/2022	14:02	22/04/2022	07:58	388,328	Dorchester	DC027521
Breakdown	Seat adjuster broke						
Replace Handbrake Cables	Replace Handbrake Cables						
18 Wheels Check Torques							
Safety Inspection							
34 Lights	OSR yellow marker not working						
89 Seats	replace drivers seat back adjuster knob						
86 Doors	NS door window switch broken						
44 Add Ad Blue	top up						
45 Engine Oil Top Up	top up						
86 Doors Rear	bottom catch cover damaged						
86 Sliding Door	central locking not working						
85 Body Interior 1	bag cupboard strap broken						

13 Brake Pads	rears low
86 Door Lock	rear door barrel seized
55 Tail Lift	guide rail seized

Vehicle Deep Clean	25/04/2022	08:20	26/04/2022	13:00	388,415	Dorchester	DC027561
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	06/05/2022	08:27	06/05/2022	13:53	389,965	Dorchester	DC027618
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	nearside running light out
-----------	----------------------------

Breakdown	06/05/2022	17:30	09/05/2022	08:05	390,018	Dorchester	DC027621
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	defective AUX battery/not charging
31 Battery Aux	defective, not charging

Breakdown	12/05/2022	19:14	14/05/2022	09:41	390,505	Dorchester	DC027652
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Alternator is not charging
31 Battery Chassis	Battery u/s
31 Charging System	Alternator not charging
01 Air Conditioning 1	Adjuster u/s

Breakdown	22/05/2022	15:24	23/05/2022	14:19	391,100	Dorchester	DC027718
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	EPCR power check
-----------	------------------

Breakdown	29/05/2022	11:12	30/05/2022	06:31	393,086	Dorchester	DC027760
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Powerhood Broken
-----------	------------------

Breakdown	01/06/2022	07:20	01/06/2022	12:00	393,773	Dorchester	DC027785
Breakdown 02 Mirrors	N/S mirror glass broken n/s mirror glass						
Breakdown	05/06/2022	21:18	06/06/2022	12:07	394,839	Dorchester	DC027810
Breakdown	Sat nav wont stay on.Replace broken mount and faulty head						
SAFETY INSPECTION	09/06/2022	07:52	10/06/2022	08:11	395,246	Dorchester	DC027846
18 Wheels Check Torques							
Safety Inspection							
54 Reversing Systems	Other Reversing Camera cracked/distorted						
Tail Lift Inspection							
13 Brake Pads	fronts low						
18 Wheels	Flange/studs damage						
17 Tyres	rears low						
55 Tail Lift	LED not working/hand rail bent						
45 Engine Ad Blue	Top up						
34 Lights	n/s side light inop						
86 Doors Rear	Large door stay ripped out of floor						
71 Body Exterior 1	tail lift guides damaged						
45 Engine 1	Wiring harness loose and rubbing						
85 Body Interior 1	Torch docks damaged/insecure						
02 Windscreen Wipers	Blades poor						
Vehicle Deep Clean	10/06/2022	10:23	10/06/2022	16:36	395,260	Dorchester	DC027862
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	30/06/2022	13:07	01/07/2022	11:06	398,510	Dorchester	DC028004
Breakdown	Battery keeps losing power						
BREAKDOWN	04/07/2022	07:38	04/07/2022	10:35	398,995	Dorchester	DC028021

31 Battery Aux Ramp/Lift/Tail Hoist wont work without engine on. See notes
 87 Chairs Other carry Chair adjustment handle missing.Chair is ok
 Travel Time

Breakdown **08/07/2022** **18:06** **09/07/2022** **11:04** **399,900** **Dorchester** **DC028054**

Breakdown AC warm
 01 Air Conditioning 1 Cab A/C inop..
 01 Air Conditioning 2 Rear system inop
 Travel Time

SAFETY INSPECTION **11/07/2022** **13:00** **12/07/2022** **09:58** **399,900** **Dorchester** **DC028065**

18 Wheels Check Torques
 Safety Inspection
 31 Battery Comms battery reported to be draining imediately unplugged from charger
 86 Sliding Door key not operating central locking
 86 Doors Rear barrel lock seized
 16 Suspension 1 slipper pads starting to delaminate, parts on back order
 44 Add Ad Blue top up
 45 Engine Oil Top Up top up

Vehicle Deep Clean **12/07/2022** **13:51** **13/07/2022** **15:00** **399,900** **Dorchester** **DC028076**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **20/07/2022** **02:52** **20/07/2022** **09:04** **400,805** **Dorchester** **DC028116**

Breakdown Internal back door handle not working

Breakdown **28/07/2022** **22:28** **29/07/2022** **14:58** **401,457** **Dorchester** **DC028181**

Breakdown O/S headlight out

Breakdown	31/07/2022	06:37	01/08/2022	07:10	401,950	Dorchester	DC028192
Breakdown	Ramp not working all the time						
Unplanned Repair	09/08/2022	11:15	09/08/2022	12:10	403,208	Dorchester	DC028241
31 Battery Aux	all electrics dropping out						
Defect Repair	26/08/2022	09:21	26/08/2022	10:27	406,500	Dorchester	DC028337
02 Windscreen	Windscreen 2MM chip to O/S of mirror						
54 Reversing Systems	Other Reversing camera not working						
02 Cab Assembly 1	music radio buttons not working						
31 Battery Comms	Battery comms power failing when engine running						
Defect Repair	26/08/2022	10:31	26/08/2022	10:33	406,500	Dorchester	DC028338
31 Battery Comms	Battery/Charging Sys Power failing while engine running						
SAFETY INSPECTION	30/09/2022	14:56	30/09/2022	14:58	409,680	St Leonards	SL037682
18 Wheels Check Torques							
Safety Inspection							
SAFETY INSPECTION	30/09/2022	13:30	06/10/2022	11:00	409,850	St Leonards	SL037684
18 Wheels Check Torques							
Safety Inspection	PCS						
56 Radio	Body Interior music radio buttons now working						
86 Sliding Door	Doors Side door not locking						
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
Tail Lift Inspection							
Engine Change Oil & Filter							

Vehicle Deep Clean	13/10/2022	08:35	13/10/2022	08:36	409,850	St Leonards	SL037821
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	13/10/2022	08:36	13/10/2022	12:27	409,850	St Leonards	SL037822
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/10/2022	11:04	21/10/2022	11:56	412,331	St Leonards	SL037915
34 Lights 45 Engine Ad Blue	N/S main beam inop Top Up.						
Breakdown	05/11/2022	10:16	07/11/2022	06:16	413,900	Dorchester	DC028460
Breakdown	defective side door & side step						
Unplanned Repair	11/11/2022	07:00	11/11/2022	10:05	413,966	St Leonards	SL038086
34 Lights MOT	Body Exterior side light below the side door missing						
Breakdown	17/11/2022	13:26	17/11/2022	15:00	417,015	St Leonards	SL038137
Breakdown 86 Sliding Door	defective side door Replace upper and lower side door catch						
Breakdown	19/11/2022	18:56	20/11/2022	11:57	417,015	St Leonards	SL038166
Breakdown	side door opens while driving						
Breakdown	24/11/2022	20:37	25/11/2022	05:57	418,324	St Leonards	SL038224

Breakdown sidedoor keeps opening by itself

Breakdown 02/12/2022 11:31 02/12/2022 12:30 418,997 St Leonards SL038312

Breakdown manga charger. Repaired by MDT

Breakdown 06/12/2022 21:20 19/12/2022 14:00 419,589 St Leonards SL038363

Breakdown Tail hoist not locking VOR
55 Tail Lift Checked for not stowing. Cleaned to find cracked H-frame.VOR. SWL to repair.
71 Body Exterior 1 Tail lift.. SWL to Repair

SAFETY INSPECTION 16/12/2022 12:00 23/12/2022 11:23 419,589 St Leonards SL038505

18 Wheels Check Torques Checked. 180nm
Safety Inspection Repaired & Checked.
Tail Lift Inspection To be completed by S.W.L. Due to a cracked H Frame.
Pollen Filter Change Pollen Filter Change. Replaced.
Air Filter Change Air Filter Change. Replaced.
Fuel Filter Change Change Fuel Filter. Replaced.
45 Engine 1 Unit Non start. Due to being parked up with door open.
44 Add Ad Blue Top up unit 4L.
34 Emergency Light System Light bar partley working.Please supply intermitencia unit P/N 2006001
13 Brakes 1 Replace brake pads all round well under 50% ?????
52 Electrical Aux Replace u/s Torch
13 Brakes 2 Replace worn out peddle rubber.
44 Fuel System 1 Repair filler neck. Replace cap
85 Body Interior 1 Repair damaged Cab storage unit
45 Engine 2 Scan for fault codes Reset sevice light.
Wheel Hub Flanges ReplacemeReplace overdue wheel flanges [4]
17 Tyres 1x low

Vehicle Deep Clean 20/12/2022 06:00 21/12/2022 12:54 419,589 St Leonards SL038547

Vehicle Deep Clean Vehicle Deep Clean

Breakdown	26/12/2022	19:05	27/12/2022	06:00	419,758	St Leonards	SL038598
Breakdown	Tail light flickering. Top left					Monitoring	
Breakdown	26/12/2022	19:07	27/12/2022	06:00	419,758	St Leonards	SL038599
Breakdown	Horn not working sometimes. Doesn't set off siren					Monitoring	
Unplanned Repair	27/12/2022	11:30	28/12/2022	12:30	419,915	St Leonards	SL038603
54 Sirens	Siren inop					Monitoring	
54 Horns	Horn inop						
55 Tail Lift	Platform lights flashing when stowed (see notes)						
01 Heating 1	Cab heater temp stat fault						
BREAKDOWN	29/01/2023	05:57	29/01/2023	12:14	419,945	St Leonards	SL038943
34 Lights	Lighting System LIGHTS IN CAB AND BACK OF VEH OFF						
Breakdown	04/02/2023	17:12	05/02/2023	09:30	423,000	St Leonards	SL038989
Breakdown	Sirens Not Working						
54 Sirens	Test siren operation, all ok at time of test.						
Unplanned Repair	09/02/2023	11:15	09/02/2023	11:45	425,081	St Leonards	SL039058
34 Lights Bulb Replacement	O/S side repeater not working. Replaced bulb						
Breakdown	10/02/2023	09:48	10/02/2023	13:30	425,081	St Leonards	SL039070
Breakdown	FLAT TYRE						
Unplanned Repair	12/02/2023	11:04	12/02/2023	13:30	425,668	St Leonards	SL039087

45 Engine 1	EML LOP						
41 Air Intake	Air mass meter u/s						
Breakdown	13/02/2023	07:54	15/02/2023	07:05	425,796	St Leonards	SL039091
Breakdown	EML on. fault codes due to rich running. traced to faulty O2 sensor. replaced						
Travel Time							
45 Engine 1	O2 Sensor replace						
Unplanned Repair	08/03/2023	13:30	10/03/2023	14:00	428,887	St Leonards	SL039317
34 Lights	Rear lights flickering (see notes)						
71 Body Exterior 1	Rear mud flap missing. Plastic holder insecure. replaced rubber flap and holder.						
31 Battery Chassis	Chassis battery voltage low. tested battery. battery faulty. replace						
71 Body External Steps	Side step inop. cleaned and lubed step runners. step operating ok.						
52 Electrical Aux	side charger flap cover broken. replaced						
O2 Pipeline Annual Inspection	11/03/2023	09:46	11/03/2023	09:48	428,892	MDT Ferndown	TF002557
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found.						
Breakdown	26/03/2023	17:31	27/03/2023	15:47	432,344	St Leonards	SL039491
Breakdown	rear taillight intermittent (see notes)						
Vehicle Deep Clean	07/04/2023	06:00	09/04/2023	05:35	434,245	St Leonards	SL039622
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/04/2023	06:00	10/04/2023	14:09	434,425	St Leonards	SL039649
18 Wheels Check Torques	Checked.						
Safety Inspection	Inspected.						
34 Lights	Lighting System O/S side indicator Blown						
34 Lighting System	Lighting System n/s rear light not working						

71 Body Exterior 1	Body Exterior plastic trim hanging underneath						
34 Lights Bulb Replacement	Lighting System HEADLIGHT BULB OUT						
86 Door Lock	Rear door lock barrel siezed. Removed ,freed,lubbed,refitted.						
02 Cab Ass Fire Extinguisher	Out of date. Replaced x1.						
13 Brakes 1	Rear disc's & pads worn. Replaced.						
Wheel Hub Flanges Replaceme	Rears in poor condition. Replaced.						
17 Tyres	N/S/R/I&O,O/S/R/I low tread. Replaced x3.Cleaned rims.						
55 Tail Lift	Drop gate siezed, guide blocks adrift,tilt sensor n/w. Repaired. No sensor .					Monitoring	

BREAKDOWN	12/05/2023	11:55	12/05/2023	11:59	437,486	St Leonards	SL040098
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Door Lock	Vehicle auto locking when driving
--------------	-----------------------------------

SAFETY INSPECTION	19/05/2023	14:30	23/05/2023	08:23	438,126	St Leonards	SL040201
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
55 Tail Lift	Drop gate siezed, guide blocks adrift,tilt sensor n/w. Repaired. No sensor .
Tail Lift Inspection	Done.
Annual Air Con Service	Annual Air Condition Service. Replaced pipe ends @ drier.
Annual Heater Service	Annual Heater Service. Replaced exhaust.
85 Body Interior 1	Fit clips for AVP
89 Seats	Saloon seats locking pins loose. Adjusted.
34 Lighting System	Saloon interior lights n/w x2. Replaced tubes x2.
17 Tyres Replace	O/S/F nailed. Replaced.
15 Steering 1	N/S/F rack end worn. Replaced.
43 Exhaust System 1	tail pipe mounting broken. Replaced clamp and rubber cotton reel.

Vehicle Deep Clean	23/05/2023	09:00	24/05/2023	14:46	438,300	St Leonards	SL040237
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	28/05/2023	19:30	30/05/2023	06:00	439,550	St Leonards	SL040319
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Tail lift not working	Monitoring
-----------	-----------------------	------------

Unplanned Repair	03/06/2023	13:05	03/06/2023	13:43	439,589	St Leonards	SL040396
Breakdown	Tail lift not working						
Breakdown	19/06/2023	14:42	21/06/2023	15:47	441,591	St Leonards	SL040645
Breakdown	alternator belt snapped						
Unplanned Repair	23/06/2023	09:00	23/06/2023	12:15	441,596	St Leonards	SL040697
31 Battery Aux	Test and replace						
SAFETY INSPECTION	01/07/2023	08:16	01/07/2023	19:10	442,340	St Leonards	SL040813
18 Wheels Check Torques							
Safety Inspection							
Engine Change Oil & Filter							
Replace Handbrake Cables	Replace Handbrake Cables						
Tail Lift Inspection							
34 Lights	N/S/F upper marker light inop						
86 Sliding Door	Step light onot working/damaged						
89 Seats	O/S/F seat height adjuster missing						
Vehicle Deep Clean	04/07/2023	07:00	04/07/2023	11:00	442,340	St Leonards	SL040849
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	10/08/2023	06:00	10/08/2023	14:00	444,626	St Leonards	SL041469
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	11/08/2023	08:00	11/08/2023	14:00	444,626	St Leonards	SL041495
18 Wheels Check Torques							

Safety Inspection	
86 Doors Rear	DOORS SMALL REAR DOOR STAY BROKEN
Tail Lift Inspection	
87 Chairs	Chair handle adjuster broken
86 Sliding Door	Side door lower catch not locking over

Unplanned Repair	15/08/2023	10:00	15/08/2023	12:02	445,112	St Leonards	SL041538
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Sliding Door	Doors Side door insecure. replaced lower latch and sliding bearings. adjusted.
-----------------	--

Breakdown	19/09/2023	06:26	19/09/2023	14:00	447,198	St Leonards	SL041989
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Power steering gone	
15 Steering 1	Steering fault - Defect moved to inspection job card	Monitoring

Vehicle Deep Clean	21/09/2023	12:00	22/09/2023	08:00	447,198	St Leonards	SL042050
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	22/09/2023	10:30	24/09/2023	08:46	447,198	St Leonards	SL042056
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
15 Steering 1	Steering fault
Recall Notification	Mercedes airbag recall
16 Suspension 1	Rear anti roll bar bushes badly worn

Unplanned Repair	11/10/2023	11:30	11/10/2023	12:38	449,430	St Leonards	SL042312
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Power Failure	Comms power failing
------------------------	---------------------

Breakdown	13/10/2023	16:42	13/10/2023	17:48	449,620	St Leonards	SL042356
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	No power / Battery Check
-----------	--------------------------

Vehicle Deep Clean	31/10/2023	11:54	01/11/2023	09:00	450,710	St Leonards	SL042583
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	01/11/2023	08:00	03/11/2023	09:30	450,710	St Leonards	SL042598
18 Wheels Check Torques							
Safety Inspection							
MDT Failure/Issue	Electrical Auxs WIRING CHECK FOR MDT NFF						
86 Sliding Door	DOORS SIDE DOOR OPENS WHILST MOVING NFF						
31 Battery Chassis	Battery/Charging Sys Vechile not holding charge NFF						
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
MOT	Friday 08:00						
02 Cab Assembly 1	Replace helmet nets						
13 Brakes 1	Front brake pads worn low and discs Lipped. Replaced						
89 Seats	N/S seat base cover torn and frame cracked. Replaced						
Unplanned Repair	06/11/2023	07:50	06/11/2023	08:50	450,929	St Leonards	SL042670
45 Engine 1	EML						
Unplanned Repair	19/11/2023	11:49	19/11/2023	12:51	451,400	St Leonards	SL042846
55 Tail Lift	Rail siezed.						
Unplanned Repair	26/11/2023	13:30	09/01/2024	12:00	455,196	St Leonards	SL042941
27 Transmission Automatic	Clutch Juddering when changing gear - Merc Exeter to repair						
32 Starting System 1	Poor starting. Checked - starting ok after injector leak rectified.						
45 Engine 1	Fumes in cab. (see notes)						
002 Major Unit Replace Gearbo	Replaced by Merc Exeter						
Vehicle Deep Clean	09/01/2024	15:33	10/01/2024	13:30	455,311	St Leonards	SL043529
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	11/01/2024	06:00	12/01/2024	07:09	455,331	St Leonards	SL043546
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
45 Engine 1	Engine Amber EML						
01 Air Conditioning 1	A/C System Saloon Rain leaking through rear						
Tail Lift Inspection	Done.						
Brake Fluid Change	Brake Fluid Change						
02 Cab Assembly 1	Cubby knob missing. Replaced.						
34 Lights Bulb Replacement	N/S dip-beam n/w. Replaced bulb.						
34 Lights	N/S/F side marker n/w.Replaced.						
86 Door Lock	Scoop locker lock barrel n/w. Replaced.						
86 Door Hinges	Rear door hinges worn. Adjusted drop bolts top & bottom.					Monitoring	
86 Sliding Door	Central locking n/w. Checked wiring,repared earth. Replaced solenoid.						
86 Doors Rear	see notes.						
85 Body Interior 1	Large bottom drawer back broken. Repaired.						
89 Seats	Saloon seat arm rest adrift & locking pin loose. Tightened all.						
54 Reversing Systems	Rev camera n/w, Rev bleeper n/w.						
55 Tail Lift	Tilt sensor n/w. No Parts.					Monitoring	

SAFETY INSPECTION	23/01/2024	17:00	24/01/2024	15:30	455,748	St Leonards	SL043692
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
86 Door Hinges	Rear door hinges worn. Adjusted drop bolts top & bottom.					Monitoring	
55 Tail Lift	Tilt sensor n/w. No Parts.					Monitoring	
31 Charging System	Electrical Auxs ZOLL NOT CHARGING IN BRACKET.Checked OK.						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Axle Oil Change	Axle Oil Change. Done.						
Tail Lift Inspection							
02 Windscreen Wipers	N/S washer jet blocked. Replaced.						
86 Door Seals	Side door seal split. Replaced.						
11 Axle Rear	Noisey.					Monitoring	
86 Sliding Door	Top magnet u/s. Replaced.						

Vehicle Deep Clean	25/01/2024	15:17	26/01/2024	12:00	455,758	St Leonards	SL043723
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	27/02/2024	08:00	28/02/2024	14:27	457,855	St Leonards	SL044166
45 Engine 1 15 Steering 1 34 Lighting System	EML/LOP Vibration under 30mph Rear lighting fault						
02 Pipeline Annual Inspection	06/03/2024	12:20	06/03/2024	12:23	458,042	MDT Weymouth	DW001604
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
Unplanned Repair	04/03/2024	12:00	04/03/2024	14:00	458,041	St Leonards	SL044248
45 Engine 1 13 Brakes 1	EML on Brakes grinding						
SAFETY INSPECTION	09/03/2024	10:23	10/03/2024	12:27	458,042	St Leonards	SL044332
18 Wheels Check Torques Safety Inspection 56 Comms Equipment 45 Engine 1 17 Tyres 13 Brake Pads 16 Suspension 1 43 Exhaust System 1 71 Body Exterior 1 16 Suspension 2 85 Body Interior 1 02 Windscreen Wipers 85 Body Interior 2 86 Doors Rear	Comms Power Check Black screen on MDT it wont turn on Emg Warning Devices Amber EML with brakes grinding Rears 2x low Rears low Front struts have slight play. Tail Pipe Corroded, No parts No valve extensions fitted, No parts Rear Shocks U/S Fire Ext O.O.D Blades U/S Rear Shelf edge missing Fit Plate N/S Rear Door.						
Vehicle Deep Clean	11/03/2024	08:23	11/03/2024	12:09	458,078	St Leonards	SL044345
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	21/03/2024	06:00	21/03/2024	07:30	459,683	St Leonards	SL044512
56 Comms Power Failure 34 Lighting System	Electrical Auxs POWER KEEPS FAILING FOR MDT ETC Rear light flickering						
Unplanned Repair	29/03/2024	16:00	29/03/2024	17:00	459,801	St Leonards	SL044668
86 Doors	Doors Side door open beeping when not open						
BREAKDOWN	11/04/2024	13:00	11/04/2024	13:30	460,230	St Leonards	SL044894
44 Add Ad Blue							
Vehicle Deep Clean	20/04/2024	07:33	20/04/2024	14:01	460,699	St Leonards	SL044980
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	22/04/2024	06:34	22/04/2024	14:00	460,699	St Leonards	SL044992
18 Wheels Check Torques							
Safety Inspection							
86 Door Hinges	Rear door hinges worn. Adjusted drop bolts top & bottom.						
55 Tail Lift	Tilt sensor n/w. No Parts.						Monitoring
11 Axle Rear	Noisey. Diff pan corroding						Monitoring
85 Body Interior 1	Shelf angle rail broken. Replaced						
Man Handling Equipment Insp	Chair red button missing						
17 Tyres Replace	2X rear tyres replaced						
18 Wheels	Replace 1x wheel						
16 Suspension 1	Buffer pads torn.						
Breakdown	01/05/2024	02:16	01/05/2024	16:00	461,595	St Leonards	SL045113
Breakdown	amber EML						

Breakdown	11/05/2024	20:48	12/05/2024	12:03	462,614	St Leonards	SL045285
Breakdown	Red Brake warning. EIS communication fault. replaced key. all ok.						
Vehicle Deep Clean	31/05/2024	12:41	01/06/2024	10:22	463,229	St Leonards	SL045571
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	03/06/2024	05:03	05/06/2024	12:00	463,229	St Leonards	SL045596
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
Tail Lift Inspection	Done.						
Annual Heater Service	Annual Heater Service. Done.						
Annual Air Con Service	Annual Air Condition Service. Done.						
Engine Oil & Filter Change	Engine Oil & Filter Change. Done.						
55 Tail Lift	Tilt sensor n/w. Replaced. N/S drop gate u/s. Replaced 2nd hand.						
86 Doors Rear	Step light n/w. Replaced.						
86 Door Lock	Incorrect key on ring. Replaced lock set.						
17 Tyres	O/S/R valve extensions missing. Replaced.						
13 Calipers	N/S/F brake binding. Removed,cleaned,lubbed sliders.						
45 Engine 1	EML on. Checked, replaced cat temp sensor.						
BREAKDOWN	07/06/2024	06:51	07/06/2024	15:03	463,229	St Leonards	SL045652
13 Brakes 1	Brakes Poor. Replace telma relay box with good spare						
56 Comms Equipment	MDT inop NFF						
54 Reversing Systems	Reverse camera inop. NFF						
Unplanned Repair	22/06/2024	13:00	22/06/2024	14:00	464,366	St Leonards	SL045923
71 Body Exterior Acc Repair	Replace 2x damaged o/s blue LED's						

Breakdown	28/06/2024	17:25	29/06/2024	15:57	465,064	St Leonards	SL046040
Breakdown 15 Steering 1	MDT wont power on Play in steering column						
Unplanned Repair	01/07/2024	12:27	01/07/2024	18:00	465,064	St Leonards	SL046079
13 Brakes 1	Brakes poor.(SEE NOTES)						
Vehicle Deep Clean	11/07/2024	14:44	13/07/2024	13:17	465,253	St Leonards	SL046255
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	17/07/2024	07:00	18/07/2024	18:11	465,253	St Leonards	SL046351
18 Wheels Check Torques							
Safety Inspection							
55 Tail Lift	Tilt sensor n/w. No Parts.						
34 Emergency Light System	Lighting System n/s blue lights broken (two)						
71 Body Exterior 1	Body Exterior N/S blue light damage						
Tail Lift Annual Service	Ramp/Lift/Tail Hoist ramp barrier crushing carry chair						
11 Axle Rear	Noisy. Diff pan corroding						
Engine Change Oil & Filter							
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present						
Tail Lift Inspection							
Tail Lift 6 Monthly Inspection	Tail lift side rail stanctions excessively loose						
Pollen Filter Change	Pollen Filter Change						
Air Filter Change	Air Filter Change						
02 Windscreen Wipers	Windscreen washer jet hoses snapped & leaking						
Check Ferno Carry Chair Straps	Carry chair head rest adjuster knob missing						
87 - Stretchers/Chairs/Boards	Stretcher belts in wrong positions						
71 Body External Steps	N/S Side step not working						
13 Brake Test							
13 Handbrake	Cab handbrake travel becomming excessive						
85 Body Interior 1	Saloon locker 'LH2' broken						
43 Exhaust System 1	Exhaust D.P.F. pressure sensor insecure						

17 Tyres Replace 18 Wheels	O/S/R/O Tyre tread cut excessively through to cords / ply N/S/R/I Wheel rim 'dot-dash' type & excessively fatigued						
BREAKDOWN	20/07/2024	13:29	20/07/2024	13:31	465,415	St Leonards	SL046429
Breakdown 31 Battery Chassis	Emergency start button used to start vehicle Replace u/s battery						
Unplanned Repair	23/07/2024	11:23	23/07/2024	12:19	465,692	St Leonards	SL046474
31 Battery Comms	Battery U/S						
Vehicle Deep Clean	26/08/2024	10:18	27/08/2024	09:59	468,430	St Leonards	SL046982
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/08/2024	14:00	28/08/2024	15:17	468,430	St Leonards	SL047020
18 Wheels Check Torques Safety Inspection Tail Lift 12M Service & Weight Replace Handbrake Cables Tail Lift Inspection 02 Cab Assembly 1 86 Door Hinges 34 Lights Bulb Replacement 13 Handbrake 17 Tyres 54 Reversing Systems	Checked. Carried out inspection. Tail Lift 12M Service & Weight - DONE BY SWL Replace Handbrake Cables Drivers & passenger window switches broken. Replaced both. Rear door hinges worn. O/S headlight no pattern. Replaced bulb & adjusted. Adjuster siezed. Replaced. Valve extensions missing x3. Replaced. Beeper n/w. Repaired wiring, replaced beeper						
Breakdown	20/09/2024	17:48	21/09/2024	08:43	471,483	St Leonards	SL047399
Breakdown Road Test	LOP						

Vehicle Deep Clean	01/10/2024	15:54	02/10/2024	10:49	471,974	St Leonards	SL047548
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	04/10/2024	08:00	11/10/2024	15:00	471,974	St Leonards	SL047586
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
52 Electrical Aux	Electrical Auxs MDVS NOT RECEIVED LOG ON BY CONTROL
89 Seats	Other REAR SALOON SEAT NOT PIVOTING
Pollen Filter Change	Pollen Filter Change. Done.
Air Filter Change	Air Filter Change. Done.
Fuel Filter Change	Change Fuel Filter. Done.
19 Chassis 1	Front sub-frame damaged @ lower arm mounting. (See notes)
86 Door Lock	Scoop locker lock n/w on key. replaced housing.
17 Tyres Tracking	Carried out by SAS.
45 Engine Ad Blue	Replaced broken adblue filler neck.
15 Steering 1	Steering lock bolt missing. replaced bolt for steering lock

Breakdown	19/10/2024	10:50	19/10/2024	14:12	471,976	St Leonards	SL047845
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	flat tyre NSF
-----------	---------------

Breakdown	26/10/2024	22:53	27/10/2024	11:28	473,110	St Leonards	SL047969
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Flat Tyre
17 Tyres Replace	Tyre replaced by ATS - Aranged by OSD

Vehicle Deep Clean	15/11/2024	10:39	16/11/2024	07:47	474,409	St Leonards	SL048248
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	18/11/2024	09:30	19/11/2024	07:27	474,458	St Leonards	SL048281
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection Tail Lift Inspection MOT 45 Engine 1 13 Brake Pads 43 Exhaust System 1	Done 14.11.24. PASSED Replace 2x injector sealls. Replace front brake pads Tailpipe corroded and cracked. Replaced						
Med Devices Recall	18/11/2024	08:08	18/11/2024	08:11	474,436	MDT Ferndown	TF003849
Decontaminated Med Devices Recall	Cleaned with clinell wipes Carry out Mangar Compressor and charger dock upgrade.						
Unplanned Repair	24/11/2024	06:00	27/11/2024	07:30	475,072	St Leonards	SL048369
71 Body Exterior 1	Front top blue lights damaged						
Breakdown	01/12/2024	17:58	02/12/2024	07:00	475,290	St Leonards	SL048481
Breakdown	TAIL LIFT LIGHT FAULTY. Checked lift function, battery and lights. all ok.						
Unplanned Repair	09/12/2024	16:00	09/12/2024	16:15	478,124	St Leonards	SL048615
34 Emergency Lights	Top blue end cap damaged. Replaced						
Vehicle Deep Clean	28/12/2024	08:27	29/12/2024	08:16	478,150	St Leonards	SL048848
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	31/12/2024	07:00	31/12/2024	16:00	478,150	St Leonards	SL048878
Check MDVS for Update Safety Inspection 18 Wheels Check Torques	Check and Install MDVS windows update Carried out inspection. Checked.						

Road Test	
55 Tail Lift	O/S gate bent. Straightened.
16 Suspension 1	Rear spring pad split. Rep[laced.

Vehicle Deep Clean	10/02/2025	11:00	11/02/2025	09:16	485,642	St Leonards	SL049492
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	14/02/2025	13:17	18/02/2025	09:56	485,658	St Leonards	SL049559
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
Tail Lift Inspection	
Engine Change Oil & Filter	
34 Lights Bulb Replacement	N/S/F Side light bulb not working
34 Lights	N/S/F Indicator bulb flashing white
Gearbox Oil & Filter Change	Gear box filler cap missing
02 Cab Assembly 1	Cab passenger seat belt wrongly fitted
85 Body Interior 1	Saloon locker 'LH1' & 'LH2' hinges broken / removed
Check Ferno Carry Chair Straps	Carry chair strap wrongly fitted
02 Cab Ass Fire Extinguisher	Saloon fire extinguisher pin removed & seal snapped
87 Chairs	Carry chair roll pin missing
86 Doors Rear	O/S/R Door carry chair bracket seized & insecure
89 Seats	Saloon N/S/R seat base swivel pin insecure
87 Stretcher Harness Replaced	Stretcher velcros removed from frame
87 - Stretchers/Chairs/Boards	Stretcher hitch sleeve bushing broken
87 Stretcher	Stretcher wheel flat spotted & brake cams require adjusting
Air Filter Change	Air Filter Change
19 Chassis 1	Rear chassis wiring insecure
Aux drive belt change	Air conditioning belt tensioner snapped & bolt sheared in mount
13 Handbrake	Cab hand brake travel becomming excessive
16 Suspension 1	Rear anti-roll bar bushes lower drop links excessively worn
34 Lighting System	O/S/F Day time running light not working
56 Radio	G.P.S. Ariel missing from saloon roof
34 Emergency Light System	N/S/R Upper stop / tail light not working
13 Brake Test	
34 Emergency Lights	N/S/R Number plate L.E.D. broken

Unplanned Repair	21/03/2025	13:45	21/03/2025	15:36	487,160	St Leonards	SL050032
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Emergency Lights	Emg Warning Devices NS grille blue light out. Replaced with good spare
02 Mirrors	Near side wing mirror glass insecure. Replaced glass due to broken tabs

02 Pipeline Annual Inspection	27/03/2025	09:54	27/03/2025	09:56	487,742	MDT Ferndown	TF004064
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found.
-------------------------------	--

Vehicle Deep Clean	31/03/2025	07:30	01/04/2025	07:00	487,742	St Leonards	SL050137
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	03/04/2025	06:00	03/04/2025	16:00	487,742	St Leonards	SL050199
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
71 Body Exterior 1	Body Exterior tai light flashing- not bulb- wiring issue
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
Tail Lift Inspection	
85 Body Int Alcohol Gel Dispen	
34 Lights Bulb Replacement	OS Dip beam bulb nw. Replaced
45 Engine 1	Aux belt Frayed. Replaced
45 Engine 2	Injector 3 blowing by. Seal replaced
11 Axle Rear	Half shaft seal slight leak. Cleaned and resealed
13 Brake Pads	Rear brake pads worn low and NSR slider seized. Replaced
17 Tyres Replace	Nail in OSR tyre, Replaced osr tyres
Pollen Filter Change	Pollen Filter Change

Breakdown	06/04/2025	18:02	08/04/2025	06:17	487,904	St Leonards	SL050253
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	not keeping coolant at all; VOR at Blandford
42 Coolant System	Replace blown top radiator hose with one from decomissioned truck
Road Test	Bleed coolant system and road test

BREAKDOWN	10/04/2025	09:30	10/04/2025	10:48	487,990	St Leonards	SL050331
86 Door handle	N/S Side door handle snapped off						
BREAKDOWN	15/04/2025	08:30	15/04/2025	14:34	488,959	St Leonards	SL050398
34 Emergency Lights	N/S/F Dytime running light bulb not working						
02 Cab Assembly 1	N/S Cab torch ripped out of center consol mounts						
02 Mirrors	N/S/F Wing mirror accident damage						
Unplanned Repair	18/04/2025	12:00	20/04/2025	12:31	489,378	St Leonards	SL050466
71 Body Exterior Roof	Water leak from roof						
34 Lights	N/S/R lights flickering						
Unplanned Repair	30/04/2025	10:39	01/05/2025	08:00	490,118	St Leonards	SL050676
31 Charging System	Alternator u/s						
Unplanned Repair	05/05/2025	07:00	05/05/2025	08:36	490,820	St Leonards	SL050758
45 Engine 1	EML and juddering						
Breakdown	09/05/2025	22:15	10/05/2025	10:00	490,990	St Leonards	SL050862
Breakdown	RAMP BROKEN						
31 Battery Chassis	Test and replace						
Breakdown	10/05/2025	11:53	10/05/2025	12:52	490,990	St Leonards	SL050873
Breakdown	MDT powers down						
31 Battery Aux	Test & replaced Aux battery.						

Vehicle Deep Clean	18/05/2025	11:48	19/05/2025	13:44	492,246	St Leonards	SL051020
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/05/2025	15:53	20/05/2025	07:39	492,262	St Leonards	SL051038
Check MDVS for Update	Check and Install MDVS windows update. Done.						
Safety Inspection	Carried out inspection.						
18 Wheels Check Torques	Checked.						
Road Test	Done.						
86 Door handle	Doors Side door handle snapped off						
31 Charging System	Other Shoreline is not ejecting from DCA						
31 Charging System Battery	Battery/Charging Sys Red battery alternator warning						
34 Emergency Lights	N/S grill blue n/w. Replaced & rewired.						
44 Add Ad Blue	Topped 15Ltrs.						
85 Body Int Alcohol Gel Dispen	Removed old dispenser.						
55 Tail Lift	N/S drop gate loose. Removed & tightened post, refitted.						
Breakdown	01/06/2025	16:28	02/06/2025	08:59	493,395	St Leonards	SL051318
Breakdown	AUX battery low/ warning on						
31 Charging System	Alternator not charging. Checked, replaced alternator.						
01 Air Conditioning 1	REpair leaking pipes at compressor.						
Vehicle Deep Clean	10/06/2025	13:45	10/06/2025	15:48	493,395	St Leonards	SL051466
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	10/07/2025	14:00	10/07/2025	14:30	498,114	St Leonards	SL051986
01 Heating 1	Replace blower motor						
Decommission Vehicle	21/07/2025	15:17			498,130	St Leonards	SL052209

