

<b>WN63BYG</b>	<b>A&amp;E</b>		<b>Nailsea Amb Stn</b>				
<b>SAFETY INSPECTION</b>	<b>24/03/2015</b>	<b>10:30</b>	<b>24/03/2015</b>	<b>14:35</b>	<b>51,045</b>	<b>Taunton</b>	<b>TN012469</b>
18 Wheels Check Torques							
85 Body Interior 1							
87 Stretcher							
C Service							
Safety Inspection							
Seat swivel locking devices ch							
	replaced out of date rear fire extinguisher, front one req changing						Partially Completed
	replaced missing stretcher straps and full harness						
	paper copy used by Lee Crisp and Russel Pearec (PCS)						
	Check security of seat swivel locking devices						
<b>Unplanned Repair</b>	<b>08/04/2015</b>	<b>09:37</b>	<b>08/04/2015</b>	<b>09:52</b>	<b>52,431</b>	<b>Taunton</b>	<b>TN012556</b>
86 Doors							
	removed and repared rear door stay bar and straightened side rail						
<b>Unplanned Repair</b>	<b>17/12/2015</b>	<b>12:20</b>	<b>29/12/2015</b>	<b>16:11</b>	<b>87,944</b>	<b>Bristol</b>	<b>BL000189</b>
17 Tyres Replace							
	replace o/s/f tyre						
<b>BREAKDOWN</b>	<b>13/12/2015</b>	<b>08:03</b>	<b>13/12/2015</b>	<b>10:00</b>	<b>87,342</b>	<b>Bristol</b>	<b>BL000497</b>
44 Fuel System 1							
	Fuel filler cap u/s - AA assistance required.						
<b>Unplanned Repair</b>	<b>05/01/2016</b>	<b>19:28</b>	<b>06/01/2016</b>	<b>14:49</b>	<b>90,023</b>	<b>Bristol</b>	<b>BL000347</b>
55 Tail Lift							
18 Wheels Check Torques							
Safety Inspection							
Travel Time							
MOT							
Tail Lift Annual Service							
Tail Lift Inspection							
	Ramp/Lift/Tail Hoist tail lft bars bent						
	Statutory Inspection and Weight Test						
<b>Breakdown</b>	<b>28/01/2016</b>	<b>13:11</b>	<b>28/01/2016</b>	<b>15:00</b>	<b>92,774</b>	<b>Bristol</b>	<b>BL000657</b>

Breakdown	Hissing turbo						
<b>Vehicle Deep Clean</b>	<b>02/02/2016</b>	<b>01:36</b>	<b>02/02/2016</b>	<b>01:37</b>	<b>92,785</b>	<b>Bristol</b>	<b>BL000692</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Veh Deep Clean</b>	<b>02/02/2016</b>	<b>15:43</b>	<b>02/02/2016</b>	<b>15:43</b>	<b>92,774</b>	<b>Bristol</b>	<b>BL001238</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>15/02/2016</b>	<b>17:22</b>	<b>16/02/2016</b>	<b>14:00</b>	<b>94,326</b>	<b>Bristol</b>	<b>BL000844</b>
02 Cab Assembly 1	Body Interior ramp hit carry chair. Hand rail bent downward						
02 Cab Assembly 2							
13 Brake Pads	Body Interior cabinets are held together with estaplast.						
18 Wheels Check Torques	renewed rear pads						
42 Coolant System	viscous fan engaged full time.						
44 Fuel System 1	Body Exterior no fuel angel no fuel cap						Awaiting Warranty
45 Engine 2	Emg Warning Devices EML flashed on once then off again						
55 Tail Lift	toggle switches inop.						Awaiting Parts
Safety Inspection							
Tail Lift Inspection	lubricate and inspect.						
Gearbox Oil & Filter Change							
93 - D Service							
Service D							
Wheel Studs & Nuts Replaceme							
Wheel Hub Flanges Replaceme							
Annual Heater Service	Annual Heater Service						
Handbrake Cable Replacement	Replace rear handbrake cables						
<b>Breakdown</b>	<b>26/02/2016</b>	<b>14:00</b>	<b>01/03/2016</b>	<b>18:07</b>	<b>95,303</b>	<b>Bristol</b>	<b>BL001029</b>
Breakdown	vehicle juddered & stopped smell of oil						

<b>SAFETY INSPECTION</b>	<b>23/03/2016</b>	<b>07:09</b>	<b>23/03/2016</b>	<b>13:55</b>	<b>98,112</b>	<b>Bristol</b>	<b>BL001346</b>
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques  
Safety Inspection  
Tail Lift Inspection

<b>Unplanned Repair</b>	<b>18/04/2016</b>	<b>13:23</b>	<b>18/04/2016</b>	<b>14:08</b>	<b>100,493</b>	<b>Bristol</b>	<b>BL001639</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

42 Coolant System	viscous fan engaged full time.
55 Ramp	taillift bars badly damaged
55 Tail Lift	toggle switches inop.
86 Door handle	new side door handle

<b>Unplanned Repair</b>	<b>23/04/2016</b>	<b>18:00</b>	<b>23/04/2016</b>	<b>18:15</b>	<b>101,238</b>	<b>Taunton</b>	<b>TN014374</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	headlight bulb replaced by duty officer
----------------------------	---

<b>SAFETY INSPECTION</b>	<b>04/05/2016</b>	<b>10:02</b>	<b>05/05/2016</b>	<b>07:40</b>	<b>102,810</b>	<b>Bristol</b>	<b>BL001815</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques		
55 Tail Lift	lub lift and fit o/s hose	
71 Body Exterior 1	refit rear mudflap bracket	
71 Body Exterior 2	rear mudflap split,no stock.	Awaiting Parts
85 Body Interior 1	refit stairpro cupboard hinge strip	
85 Body Interior 2	Other Fuel gauge suspect.nff	
86 Door Seals	drivers door seal split,no stock.	Awaiting Parts
87a - Medical Equipment Repair	Medical Devices Stretcher does not have sholder straps.nff	
Safety Inspection		
UB Fire Suppression Service	not fitted	

<b>Veh Deep Clean</b>	<b>04/05/2016</b>	<b>21:15</b>	<b>05/05/2016</b>	<b>05:16</b>	<b>102,811</b>	<b>Bristol</b>	<b>BL001825</b>
-----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Defect Repair</b>	<b>09/05/2016</b>	<b>10:59</b>	<b>09/05/2016</b>	<b>11:08</b>	<b>103,383</b>	<b>Bristol</b>	<b>BL001856</b>
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

89 Seatbelts	srs light on dash carry fault test and replace o/s seat belt buckle
--------------	---

<b>Breakdown</b>	<b>18/05/2016</b>	<b>09:53</b>	<b>18/05/2016</b>	<b>11:37</b>	<b>104,336</b>	<b>Bristol</b>	<b>BL001981</b>
Breakdown	passenger mirror knocked off						
<b>Unplanned Repair</b>	<b>18/05/2016</b>	<b>11:42</b>	<b>20/05/2016</b>	<b>11:37</b>	<b>104,388</b>	<b>Bristol</b>	<b>BL001982</b>
02 Mirrors	new n\s\lf mirror old one broken off						
<b>Breakdown</b>	<b>04/06/2016</b>	<b>02:54</b>	<b>07/06/2016</b>	<b>20:55</b>	<b>104,388</b>	<b>Bristol</b>	<b>BL002168</b>
02 Cab Assembly 1	replaced cab torch						
02 Mirrors	replaced ns mirror back						
27 Transmission Automatic	trace oil leak change sump gasket						
45 Engine 1	See notes						
45 Engine 2	viscous fan perm engaged						
45 Engine Oil Top Up	topped up oil						
Breakdown	engine problem						
Road Test							
<b>SAFETY INSPECTION</b>	<b>29/06/2016</b>	<b>15:08</b>	<b>29/06/2016</b>	<b>19:15</b>	<b>109,883</b>	<b>Bristol</b>	<b>BL002455</b>
18 Wheels Check Torques							
87 - Stretchers/Chairs/Boards	service equipment						
Safety Inspection							
Tail Lift Inspection							
<b>Unplanned Repair</b>	<b>14/07/2016</b>	<b>18:28</b>	<b>14/07/2016</b>	<b>18:38</b>	<b>109,999</b>	<b>Bristol</b>	<b>BL002648</b>
33 Ignition System	new eis unit						
<b>Stretcher/Med Handling Repair</b>	<b>23/07/2016</b>	<b>11:42</b>	<b>23/07/2016</b>	<b>11:47</b>	<b>111,383</b>	<b>Bristol</b>	<b>BL002765</b>

87 - Stretchers/Chairs/Boards supply workshop spare stretcher.Serial no. 160141026.See notes.

<b>SAFETY INSPECTION</b>	<b>29/07/2016</b>	<b>07:00</b>	<b>29/07/2016</b>	<b>17:06</b>	<b>111,947</b>	<b>Bristol</b>	<b>BL002818</b>
18 Wheels Check Torques							
55 Tail Lift		lubrcate platform					
86 Door Seals		fit drivers door seal					
86 Doors Rear		fit door mod kit					
99 Diagnostic Test		carry out regen and clear codes					
Safety Inspection							
92 - C Service							
Service C							
<b>Unplanned Repair</b>	<b>28/07/2016</b>	<b>00:45</b>	<b>28/07/2016</b>	<b>01:00</b>	<b>111,774</b>	<b>Taunton</b>	<b>TN014813</b>
34 Lights Bulb Replacement		headlight bulb replaced by duty officer					
<b>Defect Repair</b>	<b>16/08/2016</b>	<b>16:03</b>	<b>16/08/2016</b>	<b>16:06</b>	<b>114,360</b>	<b>Bristol</b>	<b>BL003027</b>
71 Body Exterior 1		carry out various repairs to side step					
<b>Vehicle Deep Clean</b>	<b>16/08/2016</b>	<b>21:15</b>	<b>17/08/2016</b>	<b>02:30</b>	<b>114,361</b>	<b>Bristol</b>	<b>BL003032</b>
Vehicle Deep Clean		Vehicle Deep Clean					
<b>Unplanned Repair</b>	<b>30/08/2016</b>	<b>13:28</b>	<b>30/08/2016</b>	<b>13:34</b>	<b>116,255</b>	<b>Bristol</b>	<b>BL003159</b>
16 Suspension 1		Crew complained of rear suspension fault replace rear shock absorbers					
34 Lighting System		Clean connections on ns side indicator					
<b>SAFETY INSPECTION</b>	<b>14/09/2016</b>	<b>15:51</b>	<b>16/09/2016</b>	<b>14:45</b>	<b>118,345</b>	<b>Bristol</b>	<b>BL003358</b>
02 Windscreen		Top up washers					
13 Brakes 1		Replace front brake discs and pads					
13 Brakes 2		Replace rear brake discs and pads					

17 Tyres Replace	Replace all 4 rear tyres
18 Wheels Check Torques	
45 Engine Oil Top Up	Top up engine oil
55 Tail Lift	Replace os tail lift hand rail
85 Body Interior 1	Bin catches not working replace catches
Safety Inspection	Carry out safety inspection
Tail Lift Inspection	Carry out tail lift inspection

<b>Unplanned Repair</b>	<b>22/09/2016</b>	<b>15:04</b>	<b>22/09/2016</b>	<b>18:20</b>	<b>118,889</b>	<b>Bristol</b>	<b>BL003460</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

55 Tail Lift	tail lift remote cable broken / repaired remote cable and checked operation
71 Body External Steps	side step motor noisy / replaced side step motor and checked operation

<b>Breakdown</b>	<b>29/09/2016</b>	<b>20:10</b>	<b>29/09/2016</b>	<b>21:29</b>	<b>119,934</b>	<b>Bristol</b>	<b>BL003522</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	EML& loss of power carry out regeneration of particle filter
-----------	--

<b>Breakdown</b>	<b>15/10/2016</b>	<b>19:48</b>	<b>17/10/2016</b>	<b>12:05</b>	<b>121,390</b>	<b>Bristol</b>	<b>BL003718</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

03 Instruments & Sensors 1	carried out diagnostic test carry out regen and extended roadtest
45 Engine 1	cleaned engine after oil leak as dipstick was left out
Breakdown	Orange EML, Limp mode and slipping gears

<b>Vehicle Deep Clean</b>	<b>17/10/2016</b>	<b>21:15</b>	<b>18/10/2016</b>	<b>02:15</b>	<b>121,414</b>	<b>Bristol</b>	<b>BL003729</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>SAFETY INSPECTION</b>	<b>01/11/2016</b>	<b>08:21</b>	<b>01/11/2016</b>	<b>11:44</b>	<b>123,157</b>	<b>Bristol</b>	<b>BL003914</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen	Top up washers
18 Wheels Check Torques	
45 Engine Oil Top Up	Top up engine oil
Safety Inspection	Carry out safety inspection

Annual Air Con Service	Annual Air Condition Service
Remove Ventilator Brackets	Remove Ventilator Brackets and fitted
UB Fire Suppression Service	Not fitted to vehicle

<b>Vehicle Deep Clean</b>	<b>01/11/2016</b>	<b>12:30</b>	<b>01/11/2016</b>	<b>14:15</b>	<b>123,157</b>	<b>Bristol</b>	<b>BL003932</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

<b>Breakdown</b>	<b>15/11/2016</b>	<b>17:42</b>	<b>17/11/2016</b>	<b>13:28</b>	<b>124,572</b>	<b>Bristol</b>	<b>BL004097</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	LOP, poss gearbox issue, orange EML						
-----------	-------------------------------------	--	--	--	--	--	--

<b>SAFETY INSPECTION</b>	<b>29/11/2016</b>	<b>09:37</b>	<b>02/12/2016</b>	<b>07:23</b>	<b>124,572</b>	<b>Bristol</b>	<b>BL004302</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace	n\s\f tyre
18 Wheels Check Torques	
34 Emergency Lights	Electrical Auxs electrical faults, unable to use sirens
55 Tail Lift	Ramp/Lift/Tail Hoist side step vibrates 30 sec
87 - Stretchers/Chairs/Boards	Medical Devices incorrect lap straps on stretcher
87 Stretcher	Other 7402 leg strap for stretcher missing
87 Stretcher Harness Replaced	Med Equip & Devices side rail of stretcher broken
Safety Inspection	
Tail Lift Inspection	
Tail Lift Annual Service	Statutory Inspection and Weight Test
Travel Time	
MOT	
Annual Heater Service	Annual Heater Service
Handbrake Cable Replacement	Replace rear handbrake cables
93 - D Service	
Service D	
Fit Throw Lines & SOP	

<b>Unplanned Repair</b>	<b>12/12/2016</b>	<b>21:34</b>	<b>12/12/2016</b>	<b>21:37</b>	<b>124,788</b>	<b>Bristol</b>	<b>BL004497</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	replace o/s indicator bulb (wing)
----------------------------	-----------------------------------

<b>Breakdown</b>	<b>15/12/2016</b>	<b>02:39</b>	<b>19/12/2016</b>	<b>15:16</b>	<b>125,079</b>	<b>Bristol</b>	<b>BL004541</b>
Breakdown	back door not open adjust handle mechanisum needs new cable						
<b>Breakdown</b>	<b>28/12/2016</b>	<b>23:42</b>	<b>29/12/2016</b>	<b>18:15</b>	<b>125,997</b>	<b>Bristol</b>	<b>BL004759</b>
Breakdown	Red warning light - belt						
<b>Breakdown</b>	<b>02/01/2017</b>	<b>16:41</b>	<b>03/01/2017</b>	<b>22:05</b>	<b>125,999</b>	<b>Bristol</b>	<b>BL004812</b>
31 Charging System Breakdown	replaced faulty alternator and checked charge rate red battery light, chassis battery defect						
<b>SAFETY INSPECTION</b>	<b>03/01/2017</b>	<b>20:41</b>	<b>03/01/2017</b>	<b>22:06</b>	<b>126,000</b>	<b>Bristol</b>	<b>BL004840</b>
02 Cab Assembly 1	replaced os window control switch						
02 Windscreen	topped up screen wash						
16 Suspension 1	slight play in nsf and osf lower ball joints						
18 Wheels Check Torques							
55 Tail Lift	forced greasing through tail lift bushes						
85 Body Interior 1	repair kick bin						
Safety Inspection							
Medical Device and Equip Chec	checked suction unit ok for update						
<b>Vehicle Deep Clean</b>	<b>12/01/2017</b>	<b>07:56</b>	<b>12/01/2017</b>	<b>11:17</b>	<b>126,925</b>	<b>Bristol</b>	<b>BL004953</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>ACCIDENT</b>	<b>02/02/2017</b>	<b>16:42</b>	<b>02/02/2017</b>	<b>16:48</b>	<b>129,185</b>	<b>Bristol</b>	<b>BL005317</b>
34 Emergency Light System	replace n/s/f wing blue and surround						

Monitoring



<b>Unplanned Repair</b>	<b>06/02/2017</b>	<b>12:53</b>	<b>07/02/2017</b>	<b>16:37</b>	<b>129,963</b>	<b>Bristol</b>	<b>BL005360</b>
44 Fuel System 1 Breakdown	check out fuel fault with retun pipe blown off replace clip on pipe eml light, engine failure, leaking fuel						
<b>SAFETY INSPECTION</b>	<b>23/02/2017</b>	<b>15:46</b>	<b>23/02/2017</b>	<b>15:50</b>	<b>132,242</b>	<b>Bristol</b>	<b>BL005580</b>
02 Windscreen	Top up washers						
18 Wheels Check Torques							
45 Engine Oil Top Up	Top up engine oil						
Safety Inspection	Carry out safety inspection						
Tail Lift Inspection	Carry out tail lift inspection						
<b>Vehicle Deep Clean</b>	<b>23/02/2017</b>	<b>21:30</b>	<b>24/02/2017</b>	<b>00:40</b>	<b>132,242</b>	<b>Bristol</b>	<b>BL005587</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Breakdown</b>	<b>22/03/2017</b>	<b>14:12</b>	<b>22/03/2017</b>	<b>15:15</b>	<b>135,797</b>	<b>Bristol</b>	<b>BL005889</b>
86 Sliding Door Breakdown	crew reported side door not opening / checked operation no fault at present SIDE DOORS NOT CLOSING						
<b>Breakdown</b>	<b>25/03/2017</b>	<b>23:02</b>	<b>29/03/2017</b>	<b>16:54</b>	<b>136,388</b>	<b>Bristol</b>	<b>BL005938</b>
Breakdown	fail lift not working trace fault to poor connection in control unit						
<b>Unplanned Repair</b>	<b>30/03/2017</b>	<b>06:00</b>	<b>30/03/2017</b>	<b>06:15</b>	<b>136,434</b>	<b>Taunton</b>	<b>TN016231</b>
34 Lights Bulb Replacement	o/s headlight bulb replaced by duty officer						
<b>Unplanned Repair</b>	<b>03/04/2017</b>	<b>18:48</b>	<b>03/04/2017</b>	<b>20:09</b>	<b>136,666</b>	<b>Bristol</b>	<b>BL006024</b>
34 Lights	Other driver side indicator not working						
86 Sliding Door	new outter door handle and x3 screws missing lock housing						

<b>Vehicle Deep Clean</b>	<b>06/04/2017</b>	<b>01:00</b>	<b>06/04/2017</b>	<b>05:15</b>	<b>136,918</b>	<b>Bristol</b>	<b>BL006056</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>06/04/2017</b>	<b>07:30</b>	<b>06/04/2017</b>	<b>14:14</b>	<b>136,918</b>	<b>Bristol</b>	<b>BL006057</b>
02 Windscreen	top up wash fluid and replace cap						
17 Tyres	replace two tyres						
18 Wheels Check Torques							
34 Emergency Lights	replace O/S blue lens						
42 Coolant System	replace coolant bottle						
45 Engine Oil Top Up	top up engine oil						
71 Body Exterior 1	replace rear corner R/H/Lower and reflector						
85 Body Interior 1	re-secure torch charger						
Safety Inspection	carry out safety inspection						
UB Fire Suppression Service	not fitted						
<b>Unplanned Repair</b>	<b>07/04/2017</b>	<b>02:00</b>	<b>07/04/2017</b>	<b>02:15</b>	<b>137,064</b>	<b>Taunton</b>	<b>TN016276</b>
34 Lights Bulb Replacement	n/s main beam replaced by duty officer						
<b>Breakdown</b>	<b>06/05/2017</b>	<b>13:45</b>	<b>07/05/2017</b>	<b>15:09</b>	<b>140,681</b>	<b>Bristol</b>	<b>BL006400</b>
34 Emergency Light System	nsr scene light lens damaged / light working but no stock						Awaiting Parts
34 Emergency Lights	replaced nsr top blue lens and repaired wiring / replaced ns blue led						
Breakdown	top nsr corner blue lens and side Blue / scene lights hit by tree						
<b>Breakdown</b>	<b>10/05/2017</b>	<b>17:08</b>	<b>11/05/2017</b>	<b>15:54</b>	<b>140,924</b>	<b>Bristol</b>	<b>BL006448</b>
Breakdown	O/S side rail of tail lift snap off						
<b>Breakdown</b>	<b>27/05/2017</b>	<b>11:28</b>	<b>05/06/2017</b>	<b>13:19</b>	<b>142,595</b>	<b>Bristol</b>	<b>BL006640</b>
41 Turbo	check - turbo snapped Replace turbo						
Breakdown	ENGINE/TURBO						

<b>MGS Gas Storage Modifications</b>	<b>05/06/2017</b>	<b>08:30</b>	<b>05/06/2017</b>	<b>08:31</b>	<b>142,595</b>	<b>Bristol</b>	<b>BL006745</b>
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

MGS Gas Storage Modifications	MGS Gas Storage Modifications
-------------------------------	-------------------------------

<b>SAFETY INSPECTION</b>	<b>16/06/2017</b>	<b>14:47</b>	<b>17/06/2017</b>	<b>08:43</b>	<b>143,666</b>	<b>Bristol</b>	<b>BL006909</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen	Top up washers
13 Brakes 1	Replace brake pedal rubber
13 Brakes 2	Replace rear discs and pads
17 Tyres Replace	Replace 4 tyres
18 Wheels Check Torques	
34 Emergency Light System	nsr scene light lens damaged replace
Safety Inspection	Carry out safety inspection
Annual Air Con Service	Annual Air Condition Service
Tail Lift Inspection	Carry out tail lift inspection
Service C	Carry out C service
Gearbox Oil & Filter Change	Carry out gearbox oil and filter change

<b>Vehicle Deep Clean</b>	<b>17/06/2017</b>	<b>09:40</b>	<b>19/06/2017</b>	<b>08:23</b>	<b>143,667</b>	<b>Bristol</b>	<b>BL006914</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Breakdown</b>	<b>27/06/2017</b>	<b>01:54</b>	<b>28/06/2017</b>	<b>12:06</b>	<b>144,410</b>	<b>Bristol</b>	<b>BL007010</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	not take charge,engine off, down vehicle
-----------	--

<b>Breakdown</b>	<b>27/06/2017</b>	<b>12:00</b>	<b>28/06/2017</b>	<b>12:11</b>	<b>144,410</b>	<b>Bristol</b>	<b>BL007017</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	REMAINS DEPLOYED.
-----------	-------------------

<b>Unplanned Repair</b>	<b>28/06/2017</b>	<b>16:13</b>	<b>28/06/2017</b>	<b>18:24</b>	<b>144,410</b>	<b>Bristol</b>	<b>BL007043</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

55 Tail Lift	check out lift n\w n\ff at time of test
71 Body External Steps	lub and adjust side step

<b>Vehicle Deep Clean</b>	<b>27/07/2017</b>	<b>16:00</b>	<b>28/07/2017</b>	<b>21:20</b>	<b>148,152</b>	<b>Bristol</b>	<b>BL007477</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>28/07/2017</b>	<b>08:01</b>	<b>28/07/2017</b>	<b>13:27</b>	<b>148,152</b>	<b>Bristol</b>	<b>BL007479</b>
02 Cab Assembly 1	Other fumes inside vehicle. nff						
02 Windscreen	top up wash fluid						
18 Wheels Check Torques							
34 Lights	replace torch						
45 Engine 1	replace pollen filter						
71 Body Exterior 1	Body Exterior scuffs on side door hinges						
71 Body Exterior 2	replace rear mud flap						
Safety Inspection	carry out safety inspection						
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Tail Lift Inspection							
<b>Unplanned Repair</b>	<b>07/08/2017</b>	<b>10:31</b>	<b>07/08/2017</b>	<b>10:35</b>	<b>148,881</b>	<b>Bristol</b>	<b>BL007580</b>
02 Mirrors	replaced damaged os mirror parts						
<b>Unplanned Repair</b>	<b>19/08/2017</b>	<b>08:45</b>	<b>19/08/2017</b>	<b>08:51</b>	<b>150,822</b>	<b>Bristol</b>	<b>BL007705</b>
55 Tail Lift	tail lift sensor and plate damaged - repair and fit new sensor						
<b>Vehicle Deep Clean</b>	<b>08/09/2017</b>	<b>03:38</b>	<b>08/09/2017</b>	<b>12:12</b>	<b>153,332</b>	<b>Bristol</b>	<b>BL007919</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>08/09/2017</b>	<b>14:40</b>	<b>27/09/2017</b>	<b>11:18</b>	<b>153,333</b>	<b>Bristol</b>	<b>BL007937</b>
02 Windscreen	top up screenwash						
13 Brakes 1	replace front discs and pads						
18 Wheels Check Torques							
27 Transmission Automatic	remove and re-seal rear hubs						
34 Lights	no plate lights inop / checked wiring and carried out harness repair						
41 Turbo	REPLACE TURBO AND OIL COOLER - CITYWEST						

45 Engine 1	oil leak - citywest
45 Engine Oil Top Up	top up engine oil
55 Tail Lift	not closing fully - top up oil. free off hand rails
71 Body External Steps	replaced step motor and checked operation
85 Body Interior 1	replace kick bin catch
89 Seats	replace drivers seat cover
Safety Inspection	carry out safety inspection
UB Fire Suppression Service	

<b>Breakdown</b>	<b>06/10/2017</b>	<b>18:13</b>	<b>09/10/2017</b>	<b>07:34</b>	<b>153,962</b>	<b>Bristol</b>	<b>BL008320</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

15 Steering 1	check power steering fault and top up fluid level
45 Engine 1	eml on, carry out diagnostic checks, reset all oxy values, regen, all ok
Breakdown	eml & limp mode
Road Test	carried out roadtest

<b>SAFETY INSPECTION</b>	<b>18/10/2017</b>	<b>08:01</b>	<b>20/10/2017</b>	<b>13:10</b>	<b>154,995</b>	<b>Bristol</b>	<b>BL008449</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	renew carpet
02 Windscreen Wipers	renew wipers
13 Brakes 1	renew brake fluid
16 Suspension 1	renew rear link arm bushes
16 Suspension 2	renew front shockers
18 Wheels Check Torques	
34 Lighting System	Other rear number plate lights defect
34 Lights	renew n/s/r stop/tail lamp unit
44 Fuel System 1	renew fuel angel
44 Fuel System 2	renwe fuel tank
45 Engine 1	Engine EML
55 Tail Lift	Ramp/Lift/Tail Hoist Audible warning lift not sitting in right place
71 Body Exterior 1	RENEW FRONT BUMPER
71 Body External Steps	renew step stay supressor
85 Body Interior 1	repair to kick bin
86 Door Lock	repair to side and rear doors - not locking with key
89 Seats	repair to saloon seat base
Safety Inspection	
Tail Lift Annual Service	Statutory Inspection and Weight Test
Tail Lift Inspection	
Travel Time	

MOT

Annual Heater Service      Annual Heater Service  
Handbrake Cable Replacement Replace rear handbrake cables  
Annual Air Con Service      Annual Air Condition Service  
Wheel Hub Flanges Replacement renew front and rear flanges

<b>Breakdown</b>	<b>22/10/2017</b>	<b>18:49</b>	<b>23/10/2017</b>	<b>12:32</b>	<b>155,230</b>	<b>Bristol</b>	<b>BL008487</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	side door off hinges
-----------	----------------------

<b>Emergency Deep Clean</b>	<b>06/11/2017</b>	<b>12:37</b>	<b>06/11/2017</b>	<b>12:39</b>	<b>156,672</b>	<b>Bristol</b>	<b>BL008655</b>
-----------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Emergency Deep Clean
----------------------

<b>Breakdown</b>	<b>08/11/2017</b>	<b>14:48</b>	<b>20/11/2017</b>	<b>12:46</b>	<b>156,740</b>	<b>Bristol</b>	<b>BL008688</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	orange EML&fumes in cab
-----------	-------------------------

<b>Breakdown</b>	<b>14/11/2017</b>	<b>13:51</b>	<b>14/11/2017</b>	<b>19:27</b>	<b>156,740</b>	<b>Bristol</b>	<b>BL008755</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	fumes in cab replace grommet in engine bay
55 Tail Lift	carry out repair to tail lift handset
56 Comms Equipment	re fit radio into dashboard and carry out repair to speaker
Breakdown	Tail lift not releasing

<b>SAFETY INSPECTION</b>	<b>29/11/2017</b>	<b>07:01</b>	<b>30/11/2017</b>	<b>12:56</b>	<b>159,068</b>	<b>Bristol</b>	<b>BL008902</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Heating 1	replace pollen filter
02 Mirrors	replace o/s mirror shell
18 Wheels	clean corrosion from flanges and paint wheels
18 Wheels Check Torques	
45 Engine Oil Top Up	top up engine oil
85 Body Interior 1	replace cab torch
Safety Inspection	

<b>Vehicle Deep Clean</b>	<b>29/11/2017</b>	<b>13:29</b>	<b>29/11/2017</b>	<b>13:30</b>	<b>159,068</b>	<b>Bristol</b>	<b>BL008904</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Vehicle Deep Clean</b>	<b>29/11/2017</b>	<b>11:40</b>	<b>29/11/2017</b>	<b>21:00</b>	<b>159,068</b>	<b>Bristol</b>	<b>BL008905</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Breakdown</b>	<b>23/12/2017</b>	<b>06:08</b>	<b>23/12/2017</b>	<b>11:27</b>	<b>160,918</b>	<b>Bristol</b>	<b>BL009194</b>
34 Emergency Lights 56 Comms Equipment Breakdown	replaced smashed nsr top blue light and repaired roof fixings checked aux and comms battery checked terrafix / all ok at time of testing rear blue lights						
<b>SAFETY INSPECTION</b>	<b>08/01/2018</b>	<b>11:35</b>	<b>08/01/2018</b>	<b>15:20</b>	<b>162,310</b>	<b>Bristol</b>	<b>BL009343</b>
18 Wheels Check Torques 34 Lights Safety Inspection 93 - D Service Service D Tail Lift Inspection UB Fire Suppression Service	replace no plate lamp						
<b>Vehicle Deep Clean</b>	<b>08/01/2018</b>	<b>13:40</b>	<b>08/01/2018</b>	<b>21:00</b>	<b>162,310</b>	<b>Bristol</b>	<b>BL009347</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Breakdown</b>	<b>14/01/2018</b>	<b>12:52</b>	<b>15/01/2018</b>	<b>08:11</b>	<b>163,000</b>	<b>Bristol</b>	<b>BL009429</b>
Breakdown	base radio bracket unscrewed						
<b>Breakdown</b>	<b>07/02/2018</b>	<b>16:26</b>	<b>08/02/2018</b>	<b>13:41</b>	<b>164,281</b>	<b>Bristol</b>	<b>BL009743</b>
Breakdown	not holding charge						

<b>Vehicle Deep Clean</b>	<b>20/02/2018</b>	<b>07:06</b>	<b>20/02/2018</b>	<b>13:05</b>	<b>165,756</b>	<b>Bristol</b>	<b>BL009876</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>SAFETY INSPECTION</b>	<b>20/02/2018</b>	<b>08:09</b>	<b>21/02/2018</b>	<b>13:45</b>	<b>165,756</b>	<b>Bristol</b>	<b>BL009877</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	new front fire\ext
13 Brakes 2	refit new srevo pipe
16 Suspension 1	new front shocks
17 Tyres Replace	new front tyres x2
17 Tyres Tracking	
18 Wheels Check Torques	
18 Wheels Removal	clean hubs
31 Charging System Battery	battery locker lock broken (refit new lock)
34 Lights Bulb Replacement	new main bulb o's
55 Ramp	ramp bar damaged (repair and test all ok)
86 Door Hinges	bin door hinge
Safety Inspection	
85 Body Int Alcohol Gel Dispen	

<b>Unplanned Repair</b>	<b>27/02/2018</b>	<b>15:31</b>	<b>27/02/2018</b>	<b>21:42</b>	<b>165,955</b>	<b>Bristol</b>	<b>BL009978</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

16 Suspension 1	crew reported fault with suspension - no fault found
17 Tyres Replace	N/S/F tyre punctured - replace
27 Transmission Automatic	carry out gearbox service
44 Fuel System 1	other fuel angel missing replace fuel cap
45 Engine 1	juddering and loosing power - carry out diagnostics NFF
71 Body External Steps	Ramp/Lift/Tail Hoist side step very noisy - straighten and lubricate
87 Stretcher	Other stretcher wheels locked straight - carried out repair BL009977
Check Winter Pack	replace salt sticks
Road Test	carry out road test

<b>Unplanned Repair</b>	<b>13/03/2018</b>	<b>06:45</b>	<b>14/03/2018</b>	<b>08:43</b>	<b>167,104</b>	<b>Bristol</b>	<b>BL010155</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

15 Steering 1	noise from steering rack / new rack fitted
16 Suspension 1	checked noise from suspension / bottom arms reqd



Road Test	carried out road test						
<b>Unplanned Repair</b>	<b>23/03/2018</b>	<b>19:17</b>	<b>24/03/2018</b>	<b>19:50</b>	<b>168,408</b>	<b>Bristol</b>	<b>BL010285</b>
42 Coolant System	Radiator/Cooling Sys coolant light on / pressure tested system and topped up/ ok						
<b>SAFETY INSPECTION</b>	<b>27/03/2018</b>	<b>07:24</b>	<b>27/03/2018</b>	<b>13:31</b>	<b>168,601</b>	<b>Bristol</b>	<b>BL010310</b>
02 Windscreen	top up screenwash						
13 Brakes 1	replace rear pads						
17 Tyres Replace	replace 3 tyres						
18 Wheels Check Torques							
34 Lights Bulb Replacement	replace O/S sidelight bulb						
45 Engine Oil Top Up	top up engine oil						
55 Tail Lift	guard rail siezed - free off and lubricate						
85 Body Interior 1	carry out repair to kick bin						
Check Winter Pack	snow socks missing - no stock						
Safety Inspection	carry out safety inspection						
Fit Poster Holder	Fit Poster Holder						
Tail Lift Inspection	Carry out safety inspection						
<b>Vehicle Deep Clean</b>	<b>27/03/2018</b>	<b>16:00</b>	<b>27/03/2018</b>	<b>21:30</b>	<b>168,612</b>	<b>Bristol</b>	<b>BL010327</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Unplanned Repair</b>	<b>25/04/2018</b>	<b>14:01</b>	<b>26/04/2018</b>	<b>10:40</b>	<b>170,839</b>	<b>Bristol</b>	<b>BL010617</b>
31 Battery Aux	refit new battery						
45 Engine 1	hammer out injectors and refit new seals						
<b>SAFETY INSPECTION</b>	<b>08/05/2018</b>	<b>08:36</b>	<b>11/05/2018</b>	<b>15:40</b>	<b>171,628</b>	<b>Bristol</b>	<b>BL010745</b>
02 Windscreen	top up screenwash						
18 Wheels Check Torques							
18 Wheels Removal	remove and clean wheels and flanges outside						

Awaiting Parts

34 Emergency Light System	replace n/s/f blue lens
45 Engine Oil Top Up	top up engine oil
52 Electrical Aux	inverter not working
55 Tail Lift	free off siezed handrail
85 Body Interior 1	totch not charging - carry out repair
87 Stretcher	refit stretcher straps to correct locations
89 Seats	Other control knob broken on saloon seat - replaced
Safety Inspection	carry out safety inspection

<b>Vehicle Deep Clean</b>	<b>09/05/2018</b>	<b>08:30</b>	<b>10/05/2018</b>	<b>01:40</b>	<b>171,628</b>	<b>Bristol</b>	<b>BL010787</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>SAFETY INSPECTION</b>	<b>19/06/2018</b>	<b>21:25</b>	<b>20/06/2018</b>	<b>18:27</b>	<b>177,196</b>	<b>Bristol</b>	<b>BL011238</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen	top up screenwash
18 Wheels Check Torques	
18 Wheels Removal	remove and clean wheels and flanges
34 Lighting System	torch not working - replace torch and charger
41 Air Intake	replace air filter
45 Engine 1	Engine EML on - carry out diagnostics - regen and replaced air flow sensor
45 Engine Oil Top Up	top up engine oil
55 Tail Lift	hand rail siezed
85 Body Interior 1	kick bin not working
86 Doors Rear	rear door catch strike pins worn
87 Stretcher	straps missing
Road Test	carry out road test
Safety Inspection	carry out safety inspection
Tail Lift Inspection	carry out tail lift inspection

Awaiting Parts

<b>Vehicle Deep Clean</b>	<b>21/06/2018</b>	<b>12:47</b>	<b>21/06/2018</b>	<b>12:48</b>	<b>177,202</b>	<b>Bristol</b>	<b>BL011263</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Vehicle Deep Clean</b>	<b>01/08/2018</b>	<b>13:03</b>	<b>01/08/2018</b>	<b>22:30</b>	<b>180,308</b>	<b>Bristol</b>	<b>BL011702</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Service C 18000</b>	<b>01/08/2018</b>	<b>13:13</b>	<b>01/08/2018</b>	<b>15:00</b>	<b>180,308</b>	<b>Bristol</b>	<b>BL011703</b>
02 Windscreen	Topped up screenwash						
02 Windscreen Wipers	Replaced wiper blades						
18 Wheels Removal	Cleaned hubs and flanges						
C Service	Carried out C service						
18 Wheels Check Torques							
Safety Inspection	Carried out safety inspection						
<b>Breakdown</b>	<b>14/08/2018</b>	<b>06:16</b>	<b>14/08/2018</b>	<b>13:57</b>	<b>181,420</b>	<b>Bristol</b>	<b>BL011827</b>
86 Door Lock	resecured lock assy						
86 Sliding Door	sliding door warning coming on / adjusted micro switch						
Breakdown	02 Flow metre broken						
Road Test	road tested after work done						
<b>Defect Repair</b>	<b>01/09/2018</b>	<b>08:08</b>	<b>01/09/2018</b>	<b>08:14</b>	<b>182,904</b>	<b>Bristol</b>	<b>BL012001</b>
01 Heating 1	Radiator/Cooling Sys coolant light on dash,top up and test						
34 Lights	Lighting System d/s headlight out,replace bulb						
86 Door handle	Other unable to open side door,replace sliding door outer handle						
86 Doors Rear	free off sticking key barrel						
<b>Breakdown</b>	<b>02/09/2018</b>	<b>21:28</b>	<b>03/09/2018</b>	<b>07:58</b>	<b>182,968</b>	<b>Bristol</b>	<b>BL012015</b>
Breakdown	side door alarm constantly sounding.carry out repairs to door lock and adjust						
<b>SAFETY INSPECTION</b>	<b>11/09/2018</b>	<b>06:58</b>	<b>14/09/2018</b>	<b>10:19</b>	<b>183,559</b>	<b>Bristol</b>	<b>BL012096</b>
02 Windscreen Wipers	replace wiper blades						
18 Wheels Check Torques							
43 Exhaust System 1	replace tail pipe						
Safety Inspection							
UB Fire Suppression Service	not fitted to this vehicle						
Tail Lift Inspection							

Tail Lift Annual Service	Statutory Inspection and Weight Test						
Annual Heater Service	Annual Heater Service						
Handbrake Cable Replacement	Replace rear handbrake cables						
Annual Air Con Service	Annual Air Condition Service						
Travel Time							
MOT							
<b>Vehicle Deep Clean</b>	<b>11/09/2018</b>	<b>12:03</b>	<b>11/09/2018</b>	<b>20:30</b>	<b>183,559</b>	<b>Bristol</b>	<b>BL012100</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Unplanned Repair</b>	<b>24/09/2018</b>	<b>11:34</b>	<b>28/09/2018</b>	<b>06:49</b>	<b>184,928</b>	<b>Bristol</b>	<b>BL012248</b>
43 Exhaust System 1 99 Diagnostic Test	carried out DPF clean and regen eml light on						
<b>Defect Repair</b>	<b>08/10/2018</b>	<b>11:52</b>	<b>08/10/2018</b>	<b>11:56</b>	<b>185,534</b>	<b>Bristol</b>	<b>BL012373</b>
02 Mirrors	replace n/s mirror casings and glass						
<b>SAFETY INSPECTION</b>	<b>22/10/2018</b>	<b>16:14</b>	<b>22/10/2018</b>	<b>21:57</b>	<b>187,243</b>	<b>Bristol</b>	<b>BL012565</b>
02 Windscreen	Topped Up Screenwash						
18 Wheels Check Torques							
18 Wheels Removal	Clean All Hubs And Flanges						
Check Winter Pack							
Safety Inspection	Carried Out Safety Inspection						
Fit 3rd Helmet Restraint	Fitted 3rd Helmet Restraint in Cab						
Sealing of stretcher clamp	Sealed Both Stretcher Clamps						
<b>Vehicle Deep Clean</b>	<b>22/10/2018</b>	<b>16:00</b>	<b>23/10/2018</b>	<b>07:00</b>	<b>187,243</b>	<b>Bristol</b>	<b>BL012567</b>
Vehicle Deep Clean	Vehicle Deep Clean						

<b>Breakdown</b>	<b>06/11/2018</b>	<b>18:45</b>	<b>06/11/2018</b>	<b>19:00</b>	<b>188,095</b>	<b>Bristol</b>	<b>BL012701</b>
Breakdown	EML limp mode						
<b>BREAKDOWN</b>	<b>09/11/2018</b>	<b>10:01</b>	<b>10/11/2018</b>	<b>12:16</b>	<b>188,270</b>	<b>Bristol</b>	<b>BL012732</b>
34 Emergency Lights	renew n/s/r lamp						
45 Engine 1	EML On						
99 Diagnostic Test	Code Read - DPF Blocked - Carried Out Regen - Requires DPF Cleaner						
<b>Breakdown</b>	<b>20/11/2018</b>	<b>21:47</b>	<b>21/11/2018</b>	<b>00:30</b>	<b>189,103</b>	<b>Bristol</b>	<b>BL012844</b>
Breakdown	7402 N/S rear outer						
<b>SAFETY INSPECTION</b>	<b>04/12/2018</b>	<b>06:49</b>	<b>05/12/2018</b>	<b>09:35</b>	<b>190,659</b>	<b>Bristol</b>	<b>BL012970</b>
02 Mirrors	switch						
17 Tyres Replace							
18 Wheels Check Torques							
18 Wheels Removal	clean hubs						
45 Engine Oil Top Up							
86 Sliding Door	not openning from inside (strip down adjust and refit all ok)						
87 Chairs	rear seat lock looes refit						
Safety Inspection							
Tail Lift Inspection							
Gearbox Oil & Filter Change							
<b>Vehicle Deep Clean</b>	<b>04/12/2018</b>	<b>08:20</b>	<b>05/12/2018</b>	<b>03:10</b>	<b>190,660</b>	<b>Bristol</b>	<b>BL012979</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Breakdown</b>	<b>13/12/2018</b>	<b>20:42</b>	<b>14/12/2018</b>	<b>07:37</b>	<b>191,239</b>	<b>Bristol</b>	<b>BL013088</b>
Breakdown	7402 - loss of power - limp mode						

<b>BREAKDOWN</b>	<b>31/12/2018</b>	<b>10:58</b>	<b>31/12/2018</b>	<b>11:04</b>	<b>192,661</b>	<b>Bristol</b>	<b>BL013247</b>
71 Body External Steps	Step Bent And Rollers Worn - Straighten Step - Replaced Rollers And Lube						
<b>Breakdown</b>	<b>03/01/2019</b>	<b>15:33</b>	<b>03/01/2019</b>	<b>21:29</b>	<b>192,897</b>	<b>Bristol</b>	<b>BL013281</b>
99 Diagnostic Test Breakdown	Stripped And Checked All Injectors And Seals - All Ok Misfiring, Fumes In Cab						
<b>SAFETY INSPECTION</b>	<b>11/01/2019</b>	<b>16:21</b>	<b>15/01/2019</b>	<b>19:49</b>	<b>193,363</b>	<b>Bristol</b>	<b>BL013370</b>
02 Windows/Glass	top up washers						
17 Tyres	osr tyres need replacing						
18 Wheels Check Torques							
45 Engine 1	Engine occasional loss of power old defect						
45 Engine Oil Top Up							
85 Body Interior 1	Body Interior hinge on equip cbrd by sd door sticking out old defect						
89 Seats	seat pin replaced						
Check Winter Pack	replace salt sticks and snow socks						
Safety Inspection							
Wheel Hub Flanges Replacemewheel hubs have old tyre fitted never been changed							
<b>Vehicle Deep Clean</b>	<b>12/01/2019</b>	<b>07:00</b>	<b>12/01/2019</b>	<b>11:46</b>	<b>193,363</b>	<b>Bristol</b>	<b>BL013375</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>26/02/2019</b>	<b>11:34</b>	<b>27/02/2019</b>	<b>12:02</b>	<b>196,473</b>	<b>Bristol</b>	<b>BL013794</b>
02 Cab Ass Fire Extinguisher	Replaced Cab Assembly Fire Extinguisher						
02 Windscreen	Topped Up Screenwash						
16 Suspension 1	Replaced 2x Split Rear Spring Buffers						
18 Wheels Check Torques							
18 Wheels Removal	Cleaned All Hubs And Flanges						
34 Lighting System	Offside Stop/Tail Light Lens Damaged - Replaced Led Light Unit						
34 Lights	Offside Reverse Not Fully Working - Replaced Led Light Unit						
34 Lights Bulb Replacement	Offside Rear Fog Light Lens Damaged - Replaced Led Light Unit						
42 Coolant System	Thermostat Housing Leaking - Strip, Cleaned And Replaced Seal - All Ok						
85 Body Interior 1	Replaced Saloon Assembly Fire Extinguisher						
Safety Inspection	Carried Out Safety Inspection						

UB Fire Suppression Service Tail Lift Inspection 93 - D Service Service D	Carry Out Fire Suppression Service Carried Out Tail Lift Inspection Carried Out D Service						
<b>Vehicle Deep Clean</b>	<b>27/02/2019</b>	<b>09:47</b>	<b>27/02/2019</b>	<b>19:00</b>	<b>196,473</b>	<b>Bristol</b>	<b>BL013810</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Vehicle Deep Clean</b>	<b>10/04/2019</b>	<b>13:06</b>	<b>10/04/2019</b>	<b>23:59</b>	<b>200,513</b>	<b>Bristol</b>	<b>BL014187</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>11/04/2019</b>	<b>08:15</b>	<b>11/04/2019</b>	<b>15:07</b>	<b>200,813</b>	<b>Bristol</b>	<b>BL014194</b>
02 Windscreen 13 Brake Pads 13 Brakes 1 18 Wheels Check Torques 18 Wheels Removal 34 Lights Bulb Replacement Safety Inspection Tail Lift Inspection	Topped Up Screenwash Replaced Front Brake Pads Replaced And Bled Both Front Brake Calipers  Clean All Hubs And Flanges Nearside Front Side Light Blown Carry Out Safety Inspection Carry Out Tail Lift Inspection						
<b>Breakdown</b>	<b>29/05/2019</b>	<b>20:45</b>	<b>30/05/2019</b>	<b>10:23</b>	<b>204,616</b>	<b>Bristol</b>	<b>BL014630</b>
Breakdown	front near flat tyre						
<b>Vehicle Deep Clean</b>	<b>05/06/2019</b>	<b>10:16</b>	<b>05/06/2019</b>	<b>10:19</b>	<b>205,070</b>	<b>Bristol</b>	<b>BL014689</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>05/06/2019</b>	<b>11:07</b>	<b>06/06/2019</b>	<b>11:27</b>	<b>205,070</b>	<b>Bristol</b>	<b>BL014692</b>
18 Wheels Check Torques 43 Exhaust System 1 86 Doors	remove tail pipe and fit correctly replace sliding door bearings						

Safety Inspection	
Axle Oil Change	Axle Oil Change
UB Fire Supp 12mts Service	Service of fire suppression system, not fitted to this truck
Engine Change Oil & Filter	

<b>Breakdown</b>	<b>23/06/2019</b>	<b>16:49</b>	<b>27/06/2019</b>	<b>08:30</b>	<b>206,768</b>	<b>Bristol</b>	<b>BL014845</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Rear Wheels Grinding
-----------	----------------------

<b>SAFETY INSPECTION</b>	<b>27/06/2019</b>	<b>08:30</b>	<b>02/07/2019</b>	<b>14:57</b>	<b>206,771</b>	<b>Bristol</b>	<b>BL014894</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	located and repaired aircon leak and regassed
02 Cab Assembly 1	replaced cab torch
02 Cab Assembly 2	replaced cab fuse cover
02 Windscreen	topped up screen wash
13 Brake Pads	replaced rear pads
13 Brakes 1	repaired osf flexi hose and bled system
13 Calipers	replaced osr caliper and bled system
13 Discs	replaced rear discs
13 Handbrake	adjusted handbrake
18 Wheels Check Torques	
18 Wheels Removal	cleaned front and rear hubs
44 Fuel System 1	replaced fuel angel
55 Tail Lift	freed off seized hand rail
71 Body External Steps	replaced step mudflap
86 Sliding Door	replaced side door inner panel
89 Seats	adjusted saloon seats
Safety Inspection	
Wheel Hub Flanges Replacement	replaced rear flanges

<b>Vehicle Deep Clean</b>	<b>27/06/2019</b>	<b>16:00</b>	<b>27/06/2019</b>	<b>22:00</b>	<b>206,771</b>	<b>Bristol</b>	<b>BL014897</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Breakdown</b>	<b>06/07/2019</b>	<b>08:33</b>	<b>11/07/2019</b>	<b>11:01</b>	<b>207,181</b>	<b>Bristol</b>	<b>BL014957</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

27 Transmission Automatic	renew torque convertor
Breakdown	not selecting gears-wshop recovery to city west



<b>Breakdown</b>	<b>11/07/2019</b>	<b>18:42</b>	<b>18/07/2019</b>	<b>15:39</b>	<b>207,181</b>	<b>Bristol</b>	<b>BL015028</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	misfire and loss of power.carry tests found turbo blown						
-----------	---	--	--	--	--	--	--

<b>Breakdown</b>	<b>23/07/2019</b>	<b>12:14</b>	<b>23/07/2019</b>	<b>14:29</b>	<b>207,411</b>	<b>Bristol</b>	<b>BL015139</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Radio and MDT not powering up						
-----------	-------------------------------	--	--	--	--	--	--

<b>Vehicle Deep Clean</b>	<b>13/08/2019</b>	<b>20:00</b>	<b>14/08/2019</b>	<b>04:00</b>	<b>209,817</b>	<b>Bristol</b>	<b>BL015319</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

<b>SAFETY INSPECTION</b>	<b>16/08/2019</b>	<b>15:26</b>	<b>23/08/2019</b>	<b>08:00</b>	<b>209,818</b>	<b>Bristol</b>	<b>BL015346</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

002 Major Unit Replace Gearbore	renew gearbox
02 Windscreen	topped up screen wash
02 Windscreen Wipers	replaced wiper blades
17 Tyres Replace	replaced tyre
18 Wheels	cleaned and painted road wheels
18 Wheels Check Torques	
18 Wheels Removal	cleaned wheel hubs
27 Transmission Automatic	Gearbox lurching, overrevving,
34 Lighting System	replaced os headlight cover
45 Engine 1	replaced air box cover and pollen filter
52 Electrical Aux	replaced damaged shore line cover
71 Body Exterior 1	removed old signage
85 Body Interior 1	replaced bag straps
99 Diagnostic Test	checked for gearbox fault / dealer repair reqd
Safety Inspection	
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Replace Handbrake Cables	only inspection reqd
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Tail Lift Inspection	
Brakes Replace Brake Fluid	
MOT	
Axle Oil Change	Axle Oil Change

<b>Vehicle Deep Clean</b>	<b>30/09/2019</b>	<b>07:30</b>	<b>30/09/2019</b>	<b>12:44</b>	<b>211,963</b>	<b>Bristol</b>	<b>BL015687</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>01/10/2019</b>	<b>07:21</b>	<b>01/10/2019</b>	<b>11:26</b>	<b>211,963</b>	<b>Bristol</b>	<b>BL015695</b>
18 Wheels	clean and paint wheels						
18 Wheels Check Torques							
18 Wheels Removal	clean corrosion from flanges						
71 Body External Steps	repair side step mounting brackets						
85 Body Interior 1	replace cab torch						
Safety Inspection							
Tail Lift Inspection	straighten h/rail,repair wiring in h/set						
<b>Breakdown</b>	<b>19/10/2019</b>	<b>02:42</b>	<b>19/10/2019</b>	<b>08:54</b>	<b>213,356</b>	<b>Bristol</b>	<b>BL015871</b>
Breakdown	N/S headlight blown						
<b>Breakdown</b>	<b>01/11/2019</b>	<b>01:35</b>	<b>01/11/2019</b>	<b>08:40</b>	<b>214,608</b>	<b>Bristol</b>	<b>BL015976</b>
86 Sliding Door	reset side door handle and rechecked						
Breakdown	sidedoor outside lock broken						
<b>Breakdown</b>	<b>05/11/2019</b>	<b>18:24</b>	<b>06/11/2019</b>	<b>07:23</b>	<b>214,608</b>	<b>Bristol</b>	<b>BL016014</b>
34 Lighting System	Main Beam Stuck On - Found Switch Sticking - Removed, Cleaned And Refitted						
34 Lights Bulb Replacement	Replaced Offside Front Side Indicator Bulb						
Breakdown	Full Beam Headlight Always On						
<b>Vehicle Deep Clean</b>	<b>08/11/2019</b>	<b>20:30</b>	<b>11/11/2019</b>	<b>10:18</b>	<b>215,032</b>	<b>Bristol</b>	<b>BL016065</b>
Vehicle Deep Clean	Vehicle Deep Clean						

<b>SAFETY INSPECTION</b>	<b>09/11/2019</b>	<b>10:08</b>	<b>11/11/2019</b>	<b>11:32</b>	<b>215,032</b>	<b>Bristol</b>	<b>BL016068</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace	replace 4 rear tyres
18 Wheels Check Torques	
18 Wheels Removal	clean corrosion from flanges
34 Lights	replace broken number plate lamp and repair wiring
34 Lights Bulb Replacement	Lighting System Offside wing indicator not working.replace bulb
85 Body Interior 2	replace cuboard catch
87 Chairs	replace chair leg strap
87a - Medical Equipment Repair	Med Equip & Devices Strecher guard broken,repair as required
Safety Inspection	

<b>SAFETY INSPECTION</b>	<b>18/12/2019</b>	<b>21:23</b>	<b>19/12/2019</b>	<b>17:53</b>	<b>219,843</b>	<b>Bristol</b>	<b>BL016498</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	nsf mirror replaced
02 Windscreen Wipers	
18 Wheels Check Torques	
45 Engine Oil Top Up	
71 Body Exterior 1	refitted damaged weatherstrip to nearside door
85 Body Interior 1	stow cupboard been ripped off/reworked and modified
86 Doors Rear	stiff to open nsr door/ stripped down /reset and lubricated
Safety Inspection	

<b>Vehicle Deep Clean</b>	<b>18/12/2019</b>	<b>23:00</b>	<b>19/12/2019</b>	<b>04:30</b>	<b>219,843</b>	<b>Bristol</b>	<b>BL016501</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Breakdown</b>	<b>18/01/2020</b>	<b>22:41</b>	<b>24/01/2020</b>	<b>17:55</b>	<b>223,346</b>	<b>Bristol</b>	<b>BL016792</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	side step partially out&no heating
-----------	------------------------------------

<b>SAFETY INSPECTION</b>	<b>24/01/2020</b>	<b>14:51</b>	<b>28/01/2020</b>	<b>13:55</b>	<b>223,447</b>	<b>Bristol</b>	<b>BL016888</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Heating 1	saloon heater not working
02 Cab Assembly 1	replaced interior light bulb
02 Cab Assembly 2	replaced tool box cover
03 Instruments & Sensors 1	Other Odometer not regestering miles traveled

16 Suspension 1	replaced rear arb bushes
17 Tyres Replace	replaced worn nsf tyre
18 Wheels Check Torques	
18 Wheels Removal	cleaned all wheel hubs
34 Lighting System	replaced missing ns headlight cover / adjusted headlight aim
34 Lights Bulb Replacement	replaced ns headlight bulb
52 Electrical Aux	rectified aux charger not working
71 Body External Steps	side step not deploying / carried out repair to bent step / replaced rollers
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service / not fitted on vehicle
Tail Lift Inspection	

<b>Vehicle Deep Clean</b>	<b>27/01/2020</b>	<b>13:58</b>	<b>27/01/2020</b>	<b>14:00</b>	<b>223,447</b>	<b>Bristol</b>	<b>BL016904</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>SAFETY INSPECTION</b>	<b>06/03/2020</b>	<b>13:29</b>	<b>06/03/2020</b>	<b>13:30</b>	<b>225,434</b>	<b>Bristol</b>	<b>BL017475</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques
Safety Inspection

<b>Vehicle Deep Clean</b>	<b>12/03/2020</b>	<b>01:41</b>	<b>12/03/2020</b>	<b>12:03</b>	<b>226,593</b>	<b>Bristol</b>	<b>BL017341</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Unplanned Repair</b>	<b>11/04/2020</b>	<b>10:14</b>	<b>11/04/2020</b>	<b>12:12</b>	<b>228,956</b>	<b>Bristol</b>	<b>BL017736</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine Oil Top Up
----------------------

<b>Vehicle Deep Clean</b>	<b>17/04/2020</b>	<b>16:00</b>	<b>17/04/2020</b>	<b>21:00</b>	<b>230,274</b>	<b>Bristol</b>	<b>BL017808</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>SAFETY INSPECTION</b>	<b>17/04/2020</b>	<b>09:31</b>	<b>17/04/2020</b>	<b>16:00</b>	<b>230,273</b>	<b>Bristol</b>	<b>BL017831</b>
15 Steering 1	ABS SENSOR						
18 Wheels Check Torques							
71 Body External Steps	Other side step wont auto come out						
86 Doors	doors side door wont open from outside						
Safety Inspection							
Tail Lift Inspection							
<b>Breakdown</b>	<b>21/05/2020</b>	<b>13:08</b>	<b>21/05/2020</b>	<b>15:12</b>	<b>231,700</b>	<b>Bristol</b>	<b>BL018185</b>
71 Body External Steps	repair bent side step and lubricate						
Breakdown	side step wont come out						
<b>Vehicle Deep Clean</b>	<b>28/05/2020</b>	<b>21:00</b>	<b>29/05/2020</b>	<b>03:00</b>	<b>233,972</b>	<b>Bristol</b>	<b>BL018249</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>29/05/2020</b>	<b>07:10</b>	<b>30/05/2020</b>	<b>07:23</b>	<b>233,972</b>	<b>Bristol</b>	<b>BL018250</b>
01 Heating 1	air con not working						
02 Windscreen Wipers	replace wiper blades						
13 Brakes 1	replace front pads and discs						
13 Brakes 2	replace rear brake pads and discs						
18 Wheels Check Torques							
34 Lights	replace o/s fog light						
Safety Inspection							
Engine Change Oil & Filter							
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
UB Fire Supp 12mts Service	Service of fire supression system						
Wheel Hub Flanges Replaceme							
<b>Breakdown</b>	<b>13/06/2020</b>	<b>02:38</b>	<b>16/06/2020</b>	<b>08:40</b>	<b>236,558</b>	<b>Bristol</b>	<b>BL018390</b>
Breakdown	fan belt slipping/snapped; VOR						

<b>Unplanned Repair</b>	<b>22/06/2020</b>	<b>12:22</b>	<b>14/07/2020</b>	<b>07:58</b>	<b>237,661</b>	<b>Bristol</b>	<b>BL018519</b>
43 Exhaust System 1	renew DPF and brackets						
45 Engine 1	injectors leaking, renew all injectors						
45 Engine 2	sump leaking, removes gearbox and seal						
Engine Change Oil & Filter							
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
MOT							
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Axle Oil Change	Axle Oil Change						
<b>RE-ISSUE INSPECTION</b>	<b>16/07/2020</b>	<b>16:48</b>	<b>16/07/2020</b>	<b>16:54</b>	<b>238,564</b>	<b>Bristol</b>	<b>BL018692</b>
02 Windows/Glass							
17 Tyres Replace							
18 Wheels	wheel markers replaced						
18 Wheels Check Torques							
18 Wheels Removal	clean and re fit flanges						
86 Sliding Door	lower door catch repaired						
Re-Issue Inspection							
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
<b>Vehicle Deep Clean</b>	<b>17/07/2020</b>	<b>04:30</b>	<b>17/07/2020</b>	<b>13:05</b>	<b>238,564</b>	<b>Bristol</b>	<b>BL018699</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Unplanned Repair</b>	<b>27/07/2020</b>	<b>11:52</b>	<b>27/07/2020</b>	<b>12:06</b>	<b>239,483</b>	<b>Bristol</b>	<b>BL018790</b>
17 Tyres Replace	Nearside front tyre and all tyre pressurs						
34 Lights Bulb Replacement	Nearside front wing indicator						

<b>Unplanned Repair</b>	<b>16/08/2020</b>	<b>12:11</b>	<b>16/08/2020</b>	<b>12:15</b>	<b>241,309</b>	<b>Bristol</b>	<b>BL019011</b>
01 Air Conditioning 1	degas and regas system - all ok at time of test						
31 Battery Chassis	renew chassis battery						
45 Engine 1	carry out regen						
71 Body External Steps	repair to bent side step						
85 Body Interior 1	Engine smell of fuel in cab - no fault found						
<b>Vehicle Deep Clean</b>	<b>27/08/2020</b>	<b>21:00</b>	<b>28/08/2020</b>	<b>03:00</b>	<b>242,712</b>	<b>Bristol</b>	<b>BL019109</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>28/08/2020</b>	<b>10:03</b>	<b>09/09/2020</b>	<b>08:19</b>	<b>242,712</b>	<b>Bristol</b>	<b>BL019112</b>
02 Mirrors	nsf mirror replaced						
17 Tyres Replace	X 6						
18 Wheels Check Torques							
27 Transmission Automatic	Top up gearbox oil						
45 Engine 1	engine oil leak from big sump rear crank oil seal						
45 Engine 2	engine mounts need replacing						
45 Engine 3	Replace oil pick up and lower sump						
Safety Inspection							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Replace Handbrake Cables	Replace Handbrake Cables						
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
<b>Unplanned Repair</b>	<b>09/09/2020</b>	<b>17:16</b>	<b>09/09/2020</b>	<b>17:21</b>	<b>242,712</b>	<b>Bristol</b>	<b>BL019256</b>
31 Battery Aux	Replaced aux,tail lift and comms battery						
<b>ACCIDENT</b>	<b>12/09/2020</b>	<b>05:10</b>	<b>12/09/2020</b>	<b>06:41</b>	<b>243,227</b>	<b>Bristol</b>	<b>BL019278</b>
02 Mirrors	renew n/s mirror parts as listed						

<b>SAFETY INSPECTION</b>	<b>06/10/2020</b>	<b>08:37</b>	<b>06/10/2020</b>	<b>15:05</b>	<b>245,724</b>	<b>Bristol</b>	<b>BL019548</b>
02 Cab Ass Fire Extinguisher	Replace Cab Fire Extinguisher						
02 Windscreen	Top Up Screenwash						
02 Windscreen Wipers	Screenwash One Way Valve Broken and washer bottle blocked / cleaned out						
18 Wheels Check Torques	Torque All Wheel Nuts						
18 Wheels Removal	Clean All Hubs And Flanges						
Safety Inspection	Carry Out Safety Inspection						
Tail Lift Inspection	Carry Out Tail Lift Inspection And Repair						
<b>Breakdown</b>	<b>30/10/2020</b>	<b>07:37</b>	<b>30/10/2020</b>	<b>10:27</b>	<b>247,952</b>	<b>Bristol</b>	<b>BL019830</b>
Breakdown	reversing LEDs on near side out						
<b>Vehicle Deep Clean</b>	<b>17/11/2020</b>	<b>02:35</b>	<b>17/11/2020</b>	<b>15:13</b>	<b>249,569</b>	<b>Bristol</b>	<b>BL020033</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>18/11/2020</b>	<b>10:00</b>	<b>18/11/2020</b>	<b>15:25</b>	<b>249,569</b>	<b>Bristol</b>	<b>BL020048</b>
18 Wheels Check Torques							
Safety Inspection							
<b>Unplanned Repair</b>	<b>17/12/2020</b>	<b>21:56</b>	<b>17/12/2020</b>	<b>22:00</b>	<b>252,173</b>	<b>Bristol</b>	<b>BL020366</b>
02 Windscreen Wipers	Windscreen Winscreen washers not working - tank full/OLD DEFECT						
34 Lights	Nearside side repeater smashed off-refitted new						
34 Lights Bulb Replacement	Nearside headlamp bulb						
<b>Vehicle Deep Clean</b>	<b>23/12/2020</b>	<b>12:11</b>	<b>23/12/2020</b>	<b>20:00</b>	<b>254,977</b>	<b>Bristol</b>	<b>BL020447</b>
Vehicle Deep Clean	Vehicle Deep Clean						



<b>SAFETY INSPECTION</b>	<b>23/12/2020</b>	<b>14:27</b>	<b>23/12/2020</b>	<b>15:32</b>	<b>252,173</b>	<b>Bristol</b>	<b>BL020448</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windows/Glass							
17 Tyres Replace	x 4						
18 Wheels Check Torques							
34 Lights	nsr reverse light inope fit new						
42 Coolant System	top up coolant system						
45 Engine 1	alternator replaced						
45 Engine 2	injectors chuffing on os bank					Monitoring	
45 Engine Oil Top Up							
71 Body Exterior 1	osr light pod replaced and indicator lamp						
71 Body Exterior 2	outside temp sensor hanging down re route and re fit						
Safety Inspection							
Tail Lift Inspection							

<b>Breakdown</b>	<b>12/01/2021</b>	<b>05:48</b>	<b>12/01/2021</b>	<b>19:30</b>	<b>256,756</b>	<b>Bristol</b>	<b>BL020636</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brakes 1	checked brake system / traced fault to pad sensor wire / replaced sensor						
18 Wheels Retorque	carried out wheel torque						
34 Lighting System	adjusted headlight aim						
99 Diagnostic Test	carried out test / brake warning fault / repaired fault and cleared codes						
Breakdown	Orange Brake pads low warning						
Road Test	carried out road test						

<b>Breakdown</b>	<b>27/01/2021</b>	<b>02:58</b>	<b>27/01/2021</b>	<b>14:06</b>	<b>258,512</b>	<b>Bristol</b>	<b>BL020763</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	See Notes						
Breakdown	rear running lights on the left side of the truck						

<b>Unplanned Repair</b>	<b>03/02/2021</b>	<b>09:17</b>	<b>05/02/2021</b>	<b>07:19</b>	<b>258,903</b>	<b>Bristol</b>	<b>BL020862</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Emergency Lights	replaced ns blue led						
34 Lighting System	Lighting System tail lights flickering						
45 Engine 2	injectors chuffing on os bank						

<b>Vehicle Deep Clean</b>	<b>05/02/2021</b>	<b>00:16</b>	<b>05/02/2021</b>	<b>22:45</b>	<b>258,903</b>	<b>Bristol</b>	<b>BL020897</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>06/02/2021</b>	<b>08:06</b>	<b>06/02/2021</b>	<b>13:11</b>	<b>258,903</b>	<b>Bristol</b>	<b>BL020901</b>
16 Suspension 1	replace rear spring buffers						
18 Wheels Check Torques							
18 Wheels Removal	clean corrosion from flanges						
34 Emergency Lights	replace n/s/r top blue light cover,repair roof and fit new rivnuts						
45 Engine Oil Top Up	top up engine oil						
86 Doors	replace top door magnet						
87a - Medical Equipment Repair	replace stryker belts						
Safety Inspection							
Tail Lift Inspection							
MOT							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
<b>Breakdown</b>	<b>14/02/2021</b>	<b>12:57</b>	<b>14/02/2021</b>	<b>14:17</b>	<b>259,580</b>	<b>Bristol</b>	<b>BL020981</b>
Breakdown	coolant levels warning on - vehicle in service - level is ok but light is on						
<b>Unplanned Repair</b>	<b>15/02/2021</b>	<b>10:45</b>	<b>15/02/2021</b>	<b>11:17</b>	<b>259,615</b>	<b>Bristol</b>	<b>BL020991</b>
42 Coolant System	coolant light on / replaced coolant bottle and bled system						
<b>Breakdown</b>	<b>14/03/2021</b>	<b>13:19</b>	<b>15/03/2021</b>	<b>14:02</b>	<b>262,196</b>	<b>Bristol</b>	<b>BL021262</b>
55 Tail Lift	Replaced mercury switch						
Breakdown	Tail Lift Very Slow Up/Down						
<b>Breakdown</b>	<b>31/03/2021</b>	<b>18:25</b>	<b>02/04/2021</b>	<b>07:05</b>	<b>263,448</b>	<b>Bristol</b>	<b>BL021408</b>
13 Brakes 1	renew front pads						
13 Brakes 2	renew rear pads and handbrake shoes						
13 Handbrake	re fit handbrake cables onto shoes and adjust						
17 Tyres Replace	x 4						
27 Transmission Automatic	rear prop fitted advise on rear diff has play and slack shaft						
42 Coolant System	water pump						

99 Diagnostic Test  
Breakdown  
18 Wheels Check Torques  
Safety Inspection  
Brakes Replace Brake Fluid

telma working front brakes look low will need stripping due safety inspection  
brakes bound on-suspension on nearside front

**Vehicle Deep Clean**      **01/04/2021**      **19:45**      **02/04/2021**      **14:01**      **264,020**      **Bristol**      **BL021418**

Vehicle Deep Clean      Vehicle Deep Clean

**Unplanned Repair**      **09/04/2021**      **07:05**      **09/04/2021**      **09:15**      **264,652**      **Bristol**      **BL021487**

55 Tail Lift  
85 Body Interior 1  
89 Seats

Ramp/Lift/Tail Hoist open/close button not working Repaired control box  
other rear extractor fan not working Replaced fan  
Repaired saloon seat arm rest

**Unplanned Repair**      **19/04/2021**      **07:30**      **19/04/2021**      **08:00**      **265,420**      **Bristol**      **BL021583**

42 Coolant System  
87 Stretcher

topped up coolant after new bottle fitted  
replaced faulty battery

**Breakdown**      **11/05/2021**      **14:06**      **11/05/2021**      **15:19**      **269,288**      **Bristol**      **BL021853**

85 Body Interior 1  
Breakdown

CCTV check  
No Oil

**Vehicle Deep Clean**      **13/05/2021**      **21:28**      **14/05/2021**      **10:55**      **269,588**      **Bristol**      **BL021899**

Vehicle Deep Clean      Vehicle Deep Clean

**SAFETY INSPECTION**      **14/05/2021**      **15:00**      **14/05/2021**      **20:57**      **269,588**      **Bristol**      **BL021905**

02 Cab Ass Fire Extinguisher  
02 Cab Assembly 1  
02 Mirrors  
13 Handbrake  
18 Wheels Check Torques

replaced out of date extinguisher  
replaced tool box cover  
replaced ns blind spot mirror  
adjusted handbrake

18 Wheels Removal	clened all wheel hubs
43 Exhaust System 1	replaced taile pipe assy
55 Tail Lift	replaced handrail magnet and adjusted hand rail
86 Sliding Door	replaced female catch
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service / not fitted to vehicle
Engine Change Oil & Filter	

<b>Vehicle Deep Clean</b>	<b>14/06/2021</b>	<b>09:56</b>	<b>14/06/2021</b>	<b>09:57</b>	<b>270,787</b>	<b>Bristol</b>	<b>BL022460</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Vehicle Deep Clean</b>	<b>14/06/2021</b>	<b>09:58</b>	<b>14/06/2021</b>	<b>09:59</b>	<b>270,787</b>	<b>Bristol</b>	<b>BL022461</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>SAFETY INSPECTION</b>	<b>14/06/2021</b>	<b>15:37</b>	<b>14/06/2021</b>	<b>15:38</b>	<b>270,787</b>	<b>Bristol</b>	<b>BL022723</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques
Safety Inspection

<b>Unplanned Repair</b>	<b>23/06/2021</b>	<b>14:30</b>	<b>23/06/2021</b>	<b>15:35</b>	<b>272,506</b>	<b>Bristol</b>	<b>BL022335</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Door Lock	replaced rear door lock cover
86 Sliding Door	stripped side door and replaced broken outer handle assy

<b>Breakdown</b>	<b>26/06/2021</b>	<b>01:43</b>	<b>26/06/2021</b>	<b>07:17</b>	<b>272,694</b>	<b>Bristol</b>	<b>BL022367</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Headlight Out
-----------	---------------

<b>Breakdown</b>	<b>27/06/2021</b>	<b>13:04</b>	<b>28/06/2021</b>	<b>07:17</b>	<b>272,786</b>	<b>Bristol</b>	<b>BL022377</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	replaced damaged ns mirror parts
Breakdown	broken wing mirror

<b>MRO Refresh</b>	<b>11/07/2021</b>	<b>10:00</b>	<b>11/07/2021</b>	<b>10:45</b>	<b>273,704</b>	<b>Bristol</b>	<b>BL022538</b>
MRO Refresh							
<b>BREAKDOWN</b>	<b>19/07/2021</b>	<b>07:26</b>	<b>19/07/2021</b>	<b>07:31</b>	<b>274,241</b>	<b>Bristol</b>	<b>BL022601</b>
55 Tail Lift	Carry Out Repairs To Tail Lift Stow Sensor						
<b>Unplanned Repair</b>	<b>19/07/2021</b>	<b>15:11</b>	<b>19/07/2021</b>	<b>15:14</b>	<b>274,242</b>	<b>Bristol</b>	<b>BL022609</b>
01 Air Conditioning 1	Carried out nitrogen test, found taps loose, re-gas ok						
<b>Vehicle Deep Clean</b>	<b>26/07/2021</b>	<b>21:40</b>	<b>27/07/2021</b>	<b>10:46</b>	<b>274,712</b>	<b>Bristol</b>	<b>BL022803</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>29/07/2021</b>	<b>09:11</b>	<b>29/07/2021</b>	<b>16:16</b>	<b>274,712</b>	<b>Bristol</b>	<b>BL022838</b>
02 Mirrors	replace o/s mirror cover						
13 Brakes 1	replace front brake pads and discs						
16 Suspension 1	replace both front shocks						
18 Wheels Check Torques							
45 Engine Oil Top Up	top up engine oil						
85 Body Interior 1	tighten up piano hinges						
86 Doors	repair top door catch and replace cover						
Safety Inspection							
UB Fire Supp 12mts Service	Service of fire suppression system						
Tail Lift Inspection							
<b>Unplanned Repair</b>	<b>04/08/2021</b>	<b>21:09</b>	<b>04/08/2021</b>	<b>21:12</b>	<b>275,470</b>	<b>Bristol</b>	<b>BL022908</b>
15 Steering 1	steering wheel replaced						
99 Diagnostic Test	test found dpf fill level at 103% carry out dpf regen all ok but advise new dpf						
<b>Breakdown</b>	<b>06/08/2021</b>	<b>19:29</b>	<b>07/08/2021</b>	<b>06:32</b>	<b>275,818</b>	<b>Bristol</b>	<b>BL022939</b>
Breakdown	FLASHING YELLOW ENG MAN LIGHT LIMP MODE - In Use						

<b>Breakdown</b>	<b>10/08/2021</b>	<b>16:04</b>	<b>11/08/2021</b>	<b>12:06</b>	<b>276,148</b>	<b>Bristol</b>	<b>BL022969</b>
45 Engine 1	replace boost sensor cat temp sensor clean out particulate and regen						
86 Sliding Door	repair side door handle fault and reset lock,adjust cables and lube						
Breakdown	EML light on/Loss of power,carry out star tests						
Road Test	carry out long r/test						
<b>MRO Refresh</b>	<b>15/08/2021</b>	<b>11:13</b>	<b>15/08/2021</b>	<b>11:14</b>	<b>276,413</b>	<b>Bristol</b>	<b>BL023004</b>
MRO Refresh							
<b>Unplanned Repair</b>	<b>16/08/2021</b>	<b>09:04</b>	<b>16/08/2021</b>	<b>12:18</b>	<b>276,450</b>	<b>Bristol</b>	<b>BL023019</b>
71 Body Exterior 1	Removed graffiti from side of truck						
86 Door handle	Replaced side door outer handle						
<b>Breakdown</b>	<b>28/08/2021</b>	<b>15:02</b>	<b>29/08/2021</b>	<b>11:21</b>	<b>276,500</b>	<b>Bristol</b>	<b>BL023152</b>
Breakdown	coolant EML on dash-confirm mileage						
<b>MRO Refresh</b>	<b>29/08/2021</b>	<b>09:30</b>	<b>29/08/2021</b>	<b>10:00</b>	<b>277,387</b>	<b>Bristol</b>	<b>BL023157</b>
MRO Refresh							
<b>Breakdown</b>	<b>05/09/2021</b>	<b>14:59</b>	<b>06/09/2021</b>	<b>06:48</b>	<b>277,844</b>	<b>Bristol</b>	<b>BL023221</b>
Breakdown	defective driver's seat(can't be adjusted)						
<b>SAFETY INSPECTION</b>	<b>17/09/2021</b>	<b>07:53</b>	<b>18/09/2021</b>	<b>07:44</b>	<b>277,967</b>	<b>Bristol</b>	<b>BL023361</b>

02 Mirrors	replace n/s mirror cover
18 Wheels	clean corrosion from flanges
18 Wheels Check Torques	
31 Battery Aux	replace shore line cover
34 Lights	replace o/s and n/s front side light bulbs
34 Lights Bulb Replacement	repair n/s/f flasher lamp and resecure back to wing
41 Turbo	replace split turbo hose
42 Coolant System	replace radiator cap
45 Engine Oil Top Up	top up engine oil
71 Body Exterior 1	drill and refit back number plate to body
86 Sliding Door	replace sliding dorr centre hinge
Safety Inspection	
Tail Lift Inspection	straighten out bent hand rails, clean up corrosion and lube sliders
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Replace Handbrake Cables	Replace Handbrake Cables

<b>Vehicle Deep Clean</b>	<b>19/09/2021</b>	<b>07:00</b>	<b>20/09/2021</b>	<b>13:39</b>	<b>277,968</b>	<b>Bristol</b>	<b>BL023385</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Breakdown</b>	<b>13/10/2021</b>	<b>22:58</b>	<b>15/10/2021</b>	<b>22:33</b>	<b>280,070</b>	<b>Bristol</b>	<b>BL023691</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace	Replaced both front tyres
17 Tyres Tracking	Reset tracking
18 Wheels Check Torques	
32 Starting System 1	Replaced starter motor
42 Coolant System	Replaced radiator,coolant tank and cap.Thermostat and housing and fan cowel
Breakdown	7402 - non start
Install Saloon CCTV Camera	Fitted LED mod

<b>Vehicle Deep Clean</b>	<b>18/10/2021</b>	<b>07:40</b>	<b>18/10/2021</b>	<b>13:26</b>	<b>280,095</b>	<b>Bristol</b>	<b>BL023732</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>SAFETY INSPECTION</b>	<b>18/10/2021</b>	<b>09:27</b>	<b>19/10/2021</b>	<b>15:20</b>	<b>280,319</b>	<b>Bristol</b>	<b>BL023742</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	Topped up washers
13 Brakes 1	Replaced rear discs and pads
13 Brakes 2	Replaced handbrake shoes
18 Wheels Check Torques	
34 Lights Bulb Replacement	Nearside headlamp
43 Exhaust System 1	EGR cooler replaced at rygor
45 Engine Oil Top Up	
85 Body Interior 1	Replaced cab light bulb
86 Door Seals	Replaced offside
86 Doors	Replaced ns door wiring boot
Road Test	Carry Out Test After All Repair Work
Safety Inspection	

<b>BREAKDOWN</b>	<b>08/11/2021</b>	<b>08:21</b>	<b>08/11/2021</b>	<b>08:25</b>	<b>280,965</b>	<b>Bristol</b>	<b>BL023952</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

55 Tail Lift	Tail Lift Deployed Warning - Buffer Plate Bent - Carry Out Repair
--------------	---

<b>BREAKDOWN</b>	<b>17/12/2021</b>	<b>14:24</b>	<b>17/12/2021</b>	<b>14:29</b>	<b>283,190</b>	<b>Bristol</b>	<b>BL024419</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Sliding Door	Central Locking Not Working - Replace Locking Motor And Outer Handle
-----------------	--

<b>Vehicle Deep Clean</b>	<b>21/12/2021</b>	<b>19:00</b>	<b>22/12/2021</b>	<b>12:24</b>	<b>283,889</b>	<b>Bristol</b>	<b>BL024466</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>SAFETY INSPECTION</b>	<b>22/12/2021</b>	<b>14:27</b>	<b>22/12/2021</b>	<b>20:59</b>	<b>283,889</b>	<b>Bristol</b>	<b>BL024477</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Glass / Windows	Replace Damaged Offside Window Switch	
02 Windscreen	Top Up Screenwash	
16 Suspension 1	Movement In Both Front Lower Arms - Check On Next Service	Monitoring
16 Suspension 2	Movement In Both Front Shocks - Check On Next Service	Monitoring
18 Wheels Check Torques	Torque All Wheel Nuts	
18 Wheels Removal	Clean All Hubs And Flanges	
45 Engine 1	Engine Oil Leak - Looks Like Behind The Flywheel	Monitoring
Safety Inspection	Carry Out Safety Inspection	
UB Fire Supp 6mts Service	Carry Out UB Fire Supp 6mts Service	
Tail Lift Inspection	Carry Out Tail Lift Inspection	



<b>SAFETY INSPECTION</b>	<b>13/01/2022</b>	<b>07:35</b>	<b>26/01/2022</b>	<b>16:15</b>	<b>284,734</b>	<b>Bristol</b>	<b>BL024691</b>
02 Glass / Windows	Offside saloon window smashed						
02 Mirrors	replace n/s mirror glass						
02 Windscreen Wipers	replace wiper blades						
13 Brakes 1	unsized o/s/r caliper sliders refit back caliper						
13 Brakes 2	adjust hand brake shoes						
16 Suspension 1	replace rear a.r.b bushes						
17 Tyres Replace	replace three tyres on the rear						
18 Wheels Check Torques							
18 Wheels Removal	clean corrosion from hubs and flanges						
45 Engine Oil Top Up	top up engine oil						
55 Tail Lift	remove n/s hand rail clean tubes and bearings, grease up and refit back						
85 Body Interior 1	replace luggage strap						
86 Sliding Door	carried out repair to door lock housing and replaced lock and catches						
87 Stretcher	replace one belt and stryker batteries x 2						
Check Ferno Carry Chair Straps	replace straps						
MOT							
Safety Inspection							
<b>Vehicle Deep Clean</b>	<b>17/01/2022</b>	<b>07:30</b>	<b>18/01/2022</b>	<b>14:18</b>	<b>284,733</b>	<b>Bristol</b>	<b>BL024733</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Defect Repair</b>	<b>31/01/2022</b>	<b>12:53</b>	<b>31/01/2022</b>	<b>12:55</b>	<b>284,991</b>	<b>Bristol</b>	<b>BL024884</b>
71 Body External Steps	clean off road grime from step, straighten mounting and lube and reset step						
<b>BREAKDOWN</b>	<b>02/02/2022</b>	<b>19:44</b>	<b>02/02/2022</b>	<b>21:20</b>	<b>285,129</b>	<b>Bristol</b>	<b>BL024918</b>
86 Door handle	Carry Out Repairs And Adjustments To Side Door Outer Handle						
<b>SAFETY INSPECTION</b>	<b>26/02/2022</b>	<b>06:35</b>	<b>26/02/2022</b>	<b>12:35</b>	<b>286,122</b>	<b>Bristol</b>	<b>BL025201</b>

18 Wheels Check Torques  
 18 Wheels Removal  
 45 Engine Oil Top Up  
 Safety Inspection  
 Tail Lift Inspection

clean corrosion from hubs and flanges  
 top up oil

**Vehicle Deep Clean**      **28/02/2022**      **09:15**      **28/02/2022**      **12:22**      **286,123**      **Bristol**      **BL025223**

Vehicle Deep Clean      Vehicle Deep Clean

**Breakdown**      **05/03/2022**      **18:41**      **06/03/2022**      **10:25**      **286,548**      **Bristol**      **BL025275**

Breakdown  
 71 Body External Steps  
 33 Ignition System

side step deployed/not retracting; VOR  
 Replaced motor spindle  
 Replaced key battery

**Breakdown**      **28/03/2022**      **07:13**      **28/03/2022**      **09:33**      **287,385**      **Bristol**      **BL025496**

Breakdown  
 99 Diagnostic Test

Orange EML and high pitched sound  
 Carried out diag test, rest codes for boost pressure.sent out as lack of staff

**Unplanned Repair**      **08/04/2022**      **20:41**      **08/04/2022**      **20:45**      **287,829**      **Bristol**      **BL025615**

71 Body External Steps  
 52 Electrical Aux

Replaced side step  
 Wired in new step with modified relay.

**SAFETY INSPECTION**      **09/04/2022**      **06:32**      **10/04/2022**      **10:00**      **287,829**      **Bristol**      **BL025619**

18 Wheels Check Torques  
 Safety Inspection  
 Air Filter Change  
 Fuel Filter Change  
 Engine Change Oil & Filter  
 18 Wheels  
 Pollen Filter Change  
 34 Emergency Lights  
 85 Body Interior 1

Air Filter Change  
 Change Fuel Filter  
  
 clean all hubs and flanges from corrosion  
 Pollen Filter Change  
 remove front grille and replace broken blue led and refit and test  
 replace broken side door straps

89 Seatbelts	n/s seat belt fault srs light on replace belt clear codes,SRS LIGHT IS STILL ON
55 Tail Lift	straighten out bent handrails and clean and free of sticking sliders
86 Door Airbag	code read faults tested wiring found fault with broken wires repaired wiring

<b>Vehicle Deep Clean</b>	<b>11/04/2022</b>	<b>06:50</b>	<b>11/04/2022</b>	<b>11:26</b>	<b>287,829</b>	<b>Bristol</b>	<b>BL025631</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Breakdown</b>	<b>16/04/2022</b>	<b>09:53</b>	<b>17/04/2022</b>	<b>07:28</b>	<b>288,026</b>	<b>Bristol</b>	<b>BL025690</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Side Step Will not go in-STILL BEING USED
-----------	---

<b>02 Pipeline Annual Inspection</b>	<b>13/04/2022</b>	<b>13:52</b>	<b>13/04/2022</b>	<b>13:59</b>	<b>287,829</b>	<b>MDT Bristol</b>	<b>TB005984</b>
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - Parts/Cost - PLease see Notes
-------------------------------	---

<b>Defect Repair</b>	<b>07/05/2022</b>	<b>11:52</b>	<b>07/05/2022</b>	<b>11:54</b>	<b>289,014</b>	<b>Bristol</b>	<b>BL025876</b>
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body External Steps	carry out repairs to bent side step mounting brackets
86 Sliding Door	repair lower sliding door lock and adjust catches

<b>Breakdown</b>	<b>07/05/2022</b>	<b>11:55</b>	<b>08/05/2022</b>	<b>07:06</b>	<b>289,014</b>	<b>Bristol</b>	<b>BL025877</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Side step stck out
-----------	--------------------

<b>Breakdown</b>	<b>23/05/2022</b>	<b>18:27</b>	<b>25/05/2022</b>	<b>07:31</b>	<b>289,100</b>	<b>Bristol</b>	<b>BL026024</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	side step opens whilst driving without warning
-----------	--

<b>SAFETY INSPECTION</b>	<b>25/05/2022</b>	<b>07:24</b>	<b>25/05/2022</b>	<b>14:11</b>	<b>289,693</b>	<b>Bristol</b>	<b>BL026048</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	carry repairs to bent end plate
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
45 Engine Oil Top Up	top up engine oil
18 Wheels Removal	clean corrosion from hubs and flanges

71 Body External Steps	carry out repairs to side step						
<b>Vehicle Deep Clean</b>	<b>25/05/2022</b>	<b>16:30</b>	<b>25/05/2022</b>	<b>21:50</b>	<b>289,694</b>	<b>Bristol</b>	<b>BL026061</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Breakdown</b>	<b>27/05/2022</b>	<b>21:47</b>	<b>29/05/2022</b>	<b>12:36</b>	<b>289,749</b>	<b>Bristol</b>	<b>BL026073</b>
Breakdown 52 Electrical Aux	rejecting shoreline charge Distubution box RCD trip shorted replaced RCD and 110v relay						
<b>Unplanned Repair</b>	<b>02/06/2022</b>	<b>10:52</b>	<b>02/06/2022</b>	<b>10:55</b>	<b>289,792</b>	<b>Bristol</b>	<b>BL026120</b>
71 Body External Steps	Adjusted and modified sliding door for step fault						
<b>Breakdown</b>	<b>18/06/2022</b>	<b>13:38</b>	<b>19/06/2022</b>	<b>09:46</b>	<b>290,971</b>	<b>Bristol</b>	<b>BL026265</b>
Breakdown 45 Engine 1	Drive belt off,power steering failed&red Batt Replaced 2 idler wheels, fan bearing, belt tensioner and 2 belts						
<b>SAFETY INSPECTION</b>	<b>18/07/2022</b>	<b>06:30</b>	<b>21/07/2022</b>	<b>16:15</b>	<b>292,559</b>	<b>Bristol</b>	<b>BL026601</b>
18 Wheels Check Torques Safety Inspection 85 Body Interior 1 01 Air Conditioning 2 01 Air Conditioning 1 15 Steering 1 Road Test	Doors LINEN CUPBOARD DOOR FAULTY Body Interior AC system Cab /AC system Saloon not working Check For Air Con Not Working - Condenser Faulty Steering Oil Cooler Pipe Split - Replaced Pipe Carry Out Road Test						
<b>Vehicle Deep Clean</b>	<b>18/07/2022</b>	<b>16:30</b>	<b>18/07/2022</b>	<b>22:30</b>	<b>292,559</b>	<b>Bristol</b>	<b>BL026604</b>
Vehicle Deep Clean	Vehicle Deep Clean						

<b>Vehicle Deep Clean</b>	<b>15/08/2022</b>	<b>19:30</b>	<b>16/08/2022</b>	<b>08:14</b>	<b>294,014</b>	<b>Bristol</b>	<b>BL026912</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>16/08/2022</b>	<b>16:59</b>	<b>16/08/2022</b>	<b>17:26</b>	<b>293,221</b>	<b>Bristol</b>	<b>BL026917</b>
18 Wheels Check Torques	Torque All Wheel Nuts						
Safety Inspection	Carry Out Safety Inspection						
UB Fire Supp 12mts Service	Service of fire suppression system						
Tail Lift Inspection	Carry Out Tail Lift Inspection						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
02 Windscreen	Top Up Screenwash						
18 Wheels Removal	Clean All Hubs And Flanges						
16 Suspension 1	Movement In Front Lower Ball Joints						
45 Engine 1	Oil Leak From Rear Oil Seal And Sumps						
						Monitoring	
						Monitoring	
<b>ACCIDENT</b>	<b>27/08/2022</b>	<b>14:08</b>	<b>27/08/2022</b>	<b>14:10</b>	<b>294,537</b>	<b>Bristol</b>	<b>BL027015</b>
71 Body Exterior Acc Repair	nsf mirror damaged						
02 Mirrors	replace nsf mirror and angle mirror						
<b>Breakdown</b>	<b>01/09/2022</b>	<b>21:06</b>	<b>02/09/2022</b>	<b>10:10</b>	<b>294,926</b>	<b>Bristol</b>	<b>BL027061</b>
Breakdown	AirCon not working/strange noise						
01 Heating 1	Replaced blower motor and heater resistor						
34 Emergency Lights	Replaced airport light						
<b>BREAKDOWN</b>	<b>16/09/2022</b>	<b>16:45</b>	<b>16/09/2022</b>	<b>16:47</b>	<b>295,242</b>	<b>Bristol</b>	<b>BL027165</b>
71 Body External Steps	Side Step Keeps Deploying - Carry Out Repairs To Top Catch						
<b>Unplanned Repair</b>	<b>17/09/2022</b>	<b>12:39</b>	<b>17/09/2022</b>	<b>12:42</b>	<b>295,423</b>	<b>Bristol</b>	<b>BL027170</b>
71 Body External Steps	step sticking, reshape and repair						
34 Lights	replace n/s wing indicator bulb						

<b>Unplanned Repair</b>	<b>30/09/2022</b>	<b>11:08</b>	<b>30/09/2022</b>	<b>11:11</b>	<b>295,905</b>	<b>Bristol</b>	<b>BL027300</b>
34 Lights Bulb Replacement	replaced os headlight bulb						
<b>SAFETY INSPECTION</b>	<b>03/10/2022</b>	<b>06:30</b>	<b>05/10/2022</b>	<b>12:47</b>	<b>295,905</b>	<b>Bristol</b>	<b>BL027315</b>
18 Wheels Check Torques							
Safety Inspection							
Annual Heater Service	Annual Heater Service						
Replace Handbrake Cables	Replace Handbrake Cables						
45 Engine 1	EML on						
86 Door Seals	replace n/s and o/s						
02 Mirrors	replace parts as listed						
34 Lights	replace cab bulb						
Install Saloon CCTV Camera	replace lens						
85 Body Interior 1	replace scoop strap						
16 Suspension 1	replace front shockers and lower arms						
16 Suspension 2	replace rear spring buffers						
13 Brake Pads	replace front pads						
32 Starting System 1	replace battery						
02 Cab Ass Fire Extinguisher	replace extinguisher						
13 Brakes 2	fit new front pad sensors						
85 Body Interior 2	fit P Clips						
45 Engine 2	Replaced egr valve and programmed						
99 Diagnostic Test	Carried out diag, found egr valve sticking						
17 Tyres Tracking							
<b>Vehicle Deep Clean</b>	<b>06/10/2022</b>	<b>14:32</b>	<b>06/10/2022</b>	<b>14:33</b>	<b>295,905</b>	<b>Bristol</b>	<b>BL027368</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Breakdown</b>	<b>31/10/2022</b>	<b>15:53</b>	<b>31/10/2022</b>	<b>21:37</b>	<b>295,945</b>	<b>Bristol</b>	<b>BL027598</b>
Breakdown	EXHAUST FUMES IN CAB						
44 Fuel System 1	Stripped down number 2 and number 4 injectors, renewed seals						
<b>SAFETY INSPECTION</b>	<b>01/11/2022</b>	<b>06:30</b>	<b>03/11/2022</b>	<b>13:36</b>	<b>295,945</b>	<b>Bristol</b>	<b>BL027616</b>

18 Wheels Check Torques							
Safety Inspection							
86 Doors	Doors CENTRAL LOCKING NOT WORKING						
Tail Lift Inspection							
34 Lights	replace cab light bulb						
44 Fuel System 1	replace flap buffers						
71 Body External Steps	replace rollers						
34 Lighting System	replace rear lamp units						
71 Body Exterior 1	replace corner caps						
34 Emergency Lights	replace grille blue light						
85 Body Interior 1	repair kick bin in saloon						
17 Tyres Replace	replace n/s/f						
13 Brake Pads	replace rear pads						
89 Seats	replace front seat pad foam, cover and frame						
86 Door Lock	replace key battery						
<b>Vehicle Deep Clean</b>	<b>04/11/2022</b>	<b>10:40</b>	<b>07/11/2022</b>	<b>08:58</b>	<b>295,945</b>	<b>Bristol</b>	<b>BL027648</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>BREAKDOWN</b>	<b>10/11/2022</b>	<b>12:14</b>	<b>11/11/2022</b>	<b>07:15</b>	<b>297,973</b>	<b>Bristol</b>	<b>BL027724</b>
86 Doors Rear	Doors Back door has dropped. Pin unable to lift						
86 Door Hinges	Carry Out Repairs To Offside Rear Door Opening Mechanism						
<b>Unplanned Repair</b>	<b>30/11/2022</b>	<b>15:43</b>	<b>30/11/2022</b>	<b>15:44</b>	<b>299,172</b>	<b>Bristol</b>	<b>BL027920</b>
86 Doors Rear	adjust door cable and door hinges all ok						
<b>SAFETY INSPECTION</b>	<b>12/12/2022</b>	<b>17:20</b>	<b>13/12/2022</b>	<b>12:33</b>	<b>299,653</b>	<b>Bristol</b>	<b>BL028018</b>
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
34 Lights Bulb Replacement	Nearside headlamp						
45 Engine 1	Engine oil leak from sumps and oil filter housing but engine noisy, cleaned up						
Tail Lift Inspection							

MOT

Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

<b>Vehicle Deep Clean</b>	<b>13/12/2022</b>	<b>08:25</b>	<b>13/12/2022</b>	<b>20:00</b>	<b>299,657</b>	<b>Bristol</b>	<b>BL028028</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Breakdown</b>	<b>22/12/2022</b>	<b>03:15</b>	<b>20/01/2023</b>	<b>12:30</b>	<b>300,368</b>	<b>Bristol</b>	<b>BL028100</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	ALL EML lop non start
45 Engine 1	Carried out diag, found engine seized
002 Major Unit Replace Eng	
001 Recover Vehicle	AA will not recover until new year - planned for 03/01/2022

<b>SAFETY INSPECTION</b>	<b>23/01/2023</b>	<b>09:40</b>	<b>23/01/2023</b>	<b>12:56</b>	<b>300,368</b>	<b>Bristol</b>	<b>BL028503</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	Torque All Wheel Nuts
Safety Inspection	Carry Out Safety Inspection
45 Engine 1	ENGINE BLOWN - OLD DEFECT
02 Windscreen	Top Up Screenwash
18 Wheels Removal	Clean All Hubs And Flanges
56 Comms Equipment	Replace Front And Rear Genysis Panels With Refurbished Units
02 Cab Assembly 1	Replace Missing Hand Torch
56 Radio	Replace Faulty CAB Radio - Needs To Be Programmed By Mercedes

<b>Vehicle Deep Clean</b>	<b>22/01/2023</b>	<b>20:30</b>	<b>23/01/2023</b>	<b>08:40</b>	<b>300,368</b>	<b>Bristol</b>	<b>BL028519</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Breakdown</b>	<b>25/01/2023</b>	<b>07:31</b>	<b>25/01/2023</b>	<b>17:19</b>	<b>300,434</b>	<b>Bristol</b>	<b>BL028534</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	oil leak; VOR
43 Exhaust System 1	carry out dpf clean and carry out regen, clear fault codes
45 Engine Oil Top Up	change engine oil

<b>Defect Repair</b>	<b>06/02/2023</b>	<b>09:31</b>	<b>06/02/2023</b>	<b>09:34</b>	<b>301,064</b>	<b>Bristol</b>	<b>BL028715</b>
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------



31 Battery Aux                      Tested aux & comms battery for terrafix/radio not working, all ok, just charged

**Vehicle Deep Clean                      04/03/2023                      02:00                      04/03/2023                      05:00                      302,493                      Bristol                      BL029231**

Vehicle Deep Clean                      Vehicle Deep Clean

**02 Pipeline Annual Inspection                      04/03/2023                      13:16                      04/03/2023                      13:17                      302,494                      MDT Bristol                      TB007695**

02 Pipeline Annual Inspection                      Annual Inspection and Pressure Test - Tested by SB - Passed all Tests

**SAFETY INSPECTION                      06/03/2023                      15:11                      08/03/2023                      14:50                      302,494                      Bristol                      BL029277**

18 Wheels Check Torques

Safety Inspection

56 Comms Equipment

Comms Power Check MDT not powering up

52 Electrical Aux

Battery/Charging Sys battery charge cons low with starting problems

02 Cab Ass Fire Extinguisher

86 Doors Rear

OSR door stay bent no stock

Monitoring

85 Body Interior 1

rear kick bin not opening

85 Body Interior 2

saloon microphone replaced

85 Body Interior 3

repair interior door

34 Lights

OSF marker light replaced

02 Glass / Windows

top up washers

87 Stretcher

stretcher harnesses replaced repair override and replace tube

**Unplanned Repair                      25/03/2023                      06:34                      25/03/2023                      10:26                      303,463                      Bristol                      BL029627**

86 Doors Rear

OSR door stay bent no stock

86 Doors

Doors SLIDING DOOR UNABLE TO OPEN

18 Wheels

Wheels TORQUE WHEEL NUT SMASHED OFF

02 Cab Assembly 1

Other NORMAL RADIO NOT WORKING

17 Tyres Replace

Replaced both front tyres

**Unplanned Repair                      09/04/2023                      12:09                      09/04/2023                      12:11                      304,524                      Bristol                      BL029950**

33 Ignition System                      key fob damaged - swapped for spare key

**SAFETY INSPECTION      17/04/2023      07:22              17/04/2023      11:58              304,915      Bristol              BL030109**

18 Wheels Check Torques  
 Safety Inspection  
 45 Engine 1                      Emg Warning Devices Front Blue Light Out  
 86 Doors                      Doors back door unable to lock  
 Annual Air Con Service                      Annual Air Condition Service  
 Brake Fluid Change                      Brake Fluid Change  
 Engine Change Oil & Filter  
 Tail Lift Inspection  
 55 Tail Lift                      replace tilt switch  
 85 Body Interior 1                      replace towel holder

**Vehicle Deep Clean      18/04/2023      14:30              18/04/2023      22:45              304,935      Bristol              BL030170**

Vehicle Deep Clean                      Vehicle Deep Clean

**Breakdown              22/04/2023      08:43              22/04/2023      09:26              305,295      Bristol              BL030235**

Breakdown                      aux battery shutting down  
 31 Battery Aux                      Replaced aux battery

**Breakdown              22/04/2023      08:46              22/04/2023      09:28              305,295      Bristol              BL030236**

Breakdown                      reestablishing bar snapped off  
 86 Doors Rear                      Replaced offside door stay

**Breakdown              06/05/2023      23:04              07/05/2023      07:35              306,574      Bristol              BL030527**

Breakdown                      Query Battery Issue  
 31 Battery Chassis                      Replaced battery  
 99 Diagnostic Test                      Code read fault low voltage cleared codes road tested ok  
 71 Body Exterior 1                      Removed nearside door trim to remove dent in door stopping window working

<b>Breakdown</b>	<b>08/05/2023</b>	<b>12:43</b>	<b>08/05/2023</b>	<b>14:38</b>	<b>306,755</b>	<b>Bristol</b>	<b>BL030548</b>
Breakdown 86 Sliding Door	defective side door Refitted sliding door top catch						
<b>SAFETY INSPECTION</b>	<b>27/05/2023</b>	<b>08:46</b>	<b>27/05/2023</b>	<b>11:18</b>	<b>308,529</b>	<b>Bristol</b>	<b>BL030961</b>
18 Wheels Check Torques	Torque All Wheel Nuts						
Safety Inspection	Carry Out Safety Inspection						
86 Doors	Doors VERTICAL DENT WITH PAINT DAMAGE						
02 Windscreen	Top Up Screenwash						
18 Wheels Removal	Clean All Hubs And Flanges						
02 Cab Assembly 1	Replace Missing Hand Torch						
34 Lights Bulb Replacement	Interior Cab Light Not Working						
45 Engine Oil Top Up	Top Up Engine Oil Level						
<b>Vehicle Deep Clean</b>	<b>29/05/2023</b>	<b>09:00</b>	<b>30/05/2023</b>	<b>07:13</b>	<b>308,530</b>	<b>Bristol</b>	<b>BL030981</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Unplanned Repair</b>	<b>21/06/2023</b>	<b>09:12</b>	<b>21/06/2023</b>	<b>09:15</b>	<b>310,978</b>	<b>Bristol</b>	<b>BL031345</b>
89 Seats	Repaired offside front seat recline bar						
02 Windscreen	Topped up washers						
<b>Vehicle Deep Clean</b>	<b>13/07/2023</b>	<b>10:00</b>	<b>13/07/2023</b>	<b>14:20</b>	<b>312,880</b>	<b>Bristol</b>	<b>BL031731</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>14/07/2023</b>	<b>07:04</b>	<b>14/07/2023</b>	<b>10:42</b>	<b>312,912</b>	<b>Bristol</b>	<b>BL031732</b>
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Tail Lift Inspection							

17 Tyres Replace 45 Engine Oil Top Up	replace 4 rear tyres top up engine oil						
<b>Replace Vehicle Fuel Card</b>	<b>14/07/2023</b>	<b>08:39</b>	<b>14/07/2023</b>	<b>08:40</b>	<b>312,880</b>	<b>Bristol</b>	<b>BL031747</b>
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
<b>Breakdown</b>	<b>17/07/2023</b>	<b>18:33</b>	<b>18/07/2023</b>	<b>09:31</b>	<b>313,252</b>	<b>Bristol</b>	<b>BL031824</b>
Breakdown	Warning lights by reg plate not working vehicle in use					Monitoring	
<b>Breakdown</b>	<b>09/08/2023</b>	<b>08:06</b>	<b>09/08/2023</b>	<b>13:11</b>	<b>315,831</b>	<b>Bristol</b>	<b>BL032322</b>
Breakdown 34 Emergency Lights	Fumes in the cab - Found no fault other than fuel smell from filling up Replaced both grille lights and corroded wiring						
<b>ACCIDENT</b>	<b>21/08/2023</b>	<b>01:48</b>	<b>21/08/2023</b>	<b>17:53</b>	<b>316,864</b>	<b>Bristol</b>	<b>BL032552</b>
Breakdown 34 Lighting System	N/S Light Cluster Damage Replaced rear light holder						
<b>SAFETY INSPECTION</b>	<b>21/08/2023</b>	<b>12:08</b>	<b>21/08/2023</b>	<b>17:59</b>	<b>315,831</b>	<b>Bristol</b>	<b>BL032575</b>
18 Wheels Check Torques Safety Inspection Breakdown 52 Electrical Aux UB Fire Supp 12mts Service 34 Lighting System 45 Engine Oil Top Up 89 Seats	OLD DEFECT Warning lights by reg plate not working vehicle in use OLD DEFECT Electrical Auxs Two front grill (blue) lights are not working. Service of fire suppression system NOT FITTED Replaced O/S upper side light added 2l Replaced bulkhead seat base and clips						
<b>Recall Notification</b>	<b>21/08/2023</b>	<b>17:59</b>	<b>21/08/2023</b>	<b>18:00</b>	<b>316,879</b>	<b>Bristol</b>	<b>BL032593</b>
Recall Notification	AIRBAGS						

<b>Unplanned Repair</b>	<b>23/08/2023</b>	<b>07:45</b>	<b>23/08/2023</b>	<b>08:35</b>	<b>317,033</b>	<b>Bristol</b>	<b>BL032627</b>
71 Body External Steps	side step not working - investigate and carry out repair						
<b>Vehicle Deep Clean</b>	<b>24/08/2023</b>	<b>15:00</b>	<b>24/08/2023</b>	<b>18:00</b>	<b>317,034</b>	<b>Bristol</b>	<b>BL032663</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Breakdown</b>	<b>09/09/2023</b>	<b>17:19</b>	<b>10/09/2023</b>	<b>14:14</b>	<b>318,727</b>	<b>Bristol</b>	<b>BL033114</b>
Breakdown	defective stretcher IN USE					Monitoring	
<b>Unplanned Repair</b>	<b>22/09/2023</b>	<b>11:34</b>	<b>22/09/2023</b>	<b>15:26</b>	<b>319,000</b>	<b>Bristol</b>	<b>BL033503</b>
99 Diagnostic Test 13 Brakes 1	carried out diagnostics - rear right ABS sensor replaced check wiring to sensor - ABS sensor required - parts on order						
<b>Vehicle Deep Clean</b>	<b>02/10/2023</b>	<b>14:10</b>	<b>02/10/2023</b>	<b>19:15</b>	<b>321,362</b>	<b>Bristol</b>	<b>BL033841</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>04/10/2023</b>	<b>11:03</b>	<b>04/10/2023</b>	<b>16:48</b>	<b>321,362</b>	<b>Bristol</b>	<b>BL033893</b>
18 Wheels Check Torques							
Safety Inspection							
Breakdown	defective stretcher IN USE						
45 Engine 1	Emg Warning Devices 3 amber warnings on dash abs, esp warning n tyre old						
Tail Lift Inspection							
02 Windscreen	washers inop						
34 Emergency Lights	nsf scene light inop						
13 Brakes 1	front discs and pads						
85 Body Interior 1	micro phone x1						
85 Body Interior 2	invertor led and caps replaced						
85 Body Interior 3	rear door catch cover						
<b>Breakdown</b>	<b>05/10/2023</b>	<b>06:23</b>	<b>05/10/2023</b>	<b>12:26</b>	<b>321,473</b>	<b>Bristol</b>	<b>BL033898</b>

Breakdown	Non Starter NO FAULT FOUND						
<b>Breakdown</b>	<b>10/10/2023</b>	<b>01:07</b>	<b>10/10/2023</b>	<b>09:05</b>	<b>321,473</b>	<b>Bristol</b>	<b>BL034070</b>
Breakdown	red eml brake lights						
99 Diagnostic Test	test brakes and system found no faults						
<b>Unplanned Repair</b>	<b>13/10/2023</b>	<b>15:49</b>	<b>13/10/2023</b>	<b>15:51</b>	<b>322,222</b>	<b>Bristol</b>	<b>BL034168</b>
99 Diagnostic Test	crew reported esp warning carried out diagnostics and road test no fault found						
<b>Emergency Deep Clean</b>	<b>27/10/2023</b>	<b>07:15</b>	<b>27/10/2023</b>	<b>14:54</b>	<b>323,503</b>	<b>Bristol</b>	<b>BL034703</b>
Emergency Deep Clean							
<b>SAFETY INSPECTION</b>	<b>14/11/2023</b>	<b>07:12</b>	<b>14/11/2023</b>	<b>15:24</b>	<b>324,825</b>	<b>Bristol</b>	<b>BL035302</b>
18 Wheels Check Torques							
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
34 Emergency Light System	Replaced nsf scene light						
55 Tail Lift	Stripped nearside arm and re-built						
01 Heating 1	Replaced both saloon heat sensors						
85 Body Interior 1	Replaced cctv dvr and configured						
85 Body Interior Roof	Replaced skylight blind						
85 Body Interior 2	Replaced missing glove holder end stop						
33 Ignition System	Replaced old key with spare, 2 new keys on order						
<b>Vehicle Deep Clean</b>	<b>13/11/2023</b>	<b>14:00</b>	<b>13/11/2023</b>	<b>18:00</b>	<b>324,825</b>	<b>Bristol</b>	<b>BL035327</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>MOT EXPIRES</b>	<b>28/11/2023</b>	<b>12:20</b>	<b>01/12/2023</b>	<b>08:47</b>	<b>326,269</b>	<b>Bristol</b>	<b>BL035826</b>
MOT							

54 Warn Dev/System	Brakes RED BRAKE LIGHT/ABS AMBER OLD DEFECT
Tail Lift Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
55 Tail Lift	Main frame replaced by Alfa

<b>Annual Heater Service Att</b>	<b>07/12/2023</b>	<b>10:30</b>	<b>07/12/2023</b>	<b>11:55</b>	<b>326,690</b>	<b>Bristol</b>	<b>BL036110</b>
----------------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Annual Heater Service	Annual Heater Service
Heater Service	A/C System Saloon No heating in rear

<b>ACCIDENT</b>	<b>13/12/2023</b>	<b>10:20</b>	<b>13/12/2023</b>	<b>11:00</b>	<b>327,218</b>	<b>Bristol</b>	<b>BL036331</b>
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	NS mirror come out.
02 Mirrors	Replaced nearside mirror glass
55 Tail Lift	Replaced damaged tail lift handrail

<b>Breakdown</b>	<b>17/12/2023</b>	<b>19:03</b>	<b>17/12/2023</b>	<b>19:30</b>	<b>327,565</b>	<b>Bristol</b>	<b>BL036470</b>
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	headlight out
-----------	---------------

<b>Unplanned Repair</b>	<b>18/12/2023</b>	<b>06:44</b>	<b>18/12/2023</b>	<b>06:48</b>	<b>327,577</b>	<b>Bristol</b>	<b>BL036471</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Replaced offside head light by OO's
----------------------------	-------------------------------------

<b>Vehicle Deep Clean</b>	<b>08/01/2024</b>	<b>10:00</b>	<b>08/01/2024</b>	<b>13:30</b>	<b>329,652</b>	<b>Bristol</b>	<b>BL037326</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>SAFETY INSPECTION</b>	<b>09/01/2024</b>	<b>08:27</b>	<b>09/01/2024</b>	<b>09:42</b>	<b>329,652</b>	<b>Bristol</b>	<b>BL037353</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
85 Body Interior 1	Repaired kick bin

<b>Unplanned Repair</b>	<b>13/01/2024</b>	<b>07:08</b>	<b>13/01/2024</b>	<b>08:16</b>	<b>330,005</b>	<b>Bristol</b>	<b>BL037525</b>
86 Doors Rear	Doors Back door will not open replaced o/f door seal and 4 striker plates						
<b>Defect Repair</b>	<b>15/01/2024</b>	<b>09:49</b>	<b>15/01/2024</b>	<b>09:56</b>	<b>330,143</b>	<b>Bristol</b>	<b>BL037608</b>
86 Doors Rear	Replaced outer handle and modified internal locking plate Replaced centre arm bearings and cleaned track						
86 Sliding Door							
<b>SAFETY INSPECTION</b>	<b>05/02/2024</b>	<b>08:08</b>	<b>05/02/2024</b>	<b>16:28</b>	<b>332,033</b>	<b>Bristol</b>	<b>BL038345</b>
18 Wheels Check Torques	UB Fire Supp 6mts Service Pollen Filter Change Replaced cctv cupboard struts Replaced cab fire extinguisher Replaced rear discs and pads Replaced 2 x front and nsr inner						
Safety Inspection							
Engine Change Oil & Filter							
UB Fire Supp 6mts Service							
Pollen Filter Change							
85 Body Interior 1							
02 Cab Ass Fire Extinguisher							
13 Brakes 1							
17 Tyres Replace							
<b>Vehicle Deep Clean</b>	<b>07/02/2024</b>	<b>11:00</b>	<b>07/02/2024</b>	<b>14:20</b>	<b>332,033</b>	<b>Bristol</b>	<b>BL038429</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Unplanned Repair</b>	<b>17/02/2024</b>	<b>09:45</b>	<b>17/02/2024</b>	<b>09:55</b>	<b>332,760</b>	<b>Bristol</b>	<b>BL038777</b>
Breakdown	Engine Smell Of Diesel And Noise From Engine PLEASE SEE NOTES Carry Out Road Test - No Fault Found						
99 Diagnostic Test							
Road Test							
<b>O2 Pipeline Annual Inspection</b>	<b>02/03/2024</b>	<b>11:18</b>	<b>02/03/2024</b>	<b>11:23</b>	<b>333,677</b>	<b>MDT Bristol</b>	<b>TB009784</b>
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - Parts/Costs - Please see Notes						



<b>Vehicle Deep Clean</b>	<b>20/03/2024</b>	<b>14:05</b>	<b>20/03/2024</b>	<b>18:00</b>	<b>335,112</b>	<b>Bristol</b>	<b>BL039922</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>SAFETY INSPECTION</b>	<b>21/03/2024</b>	<b>11:08</b>	<b>21/03/2024</b>	<b>13:07</b>	<b>335,112</b>	<b>Bristol</b>	<b>BL039938</b>
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection	Ajusted end plate stops						
89 Seats	Saloon seat base ripped						
16 Suspension 1	Replaced Rear shcoks						
16 Suspension 2	Replaced rear spring slippers						
16 Suspension 3	Replaced Rear antiroll bar link arm bushes						
<b>Breakdown</b>	<b>04/04/2024</b>	<b>00:15</b>	<b>04/04/2024</b>	<b>08:42</b>	<b>336,463</b>	<b>Bristol</b>	<b>BL040383</b>
Breakdown	N/S Indicator Not Working,replace blown bulb						
<b>Breakdown</b>	<b>30/04/2024</b>	<b>02:29</b>	<b>02/05/2024</b>	<b>09:42</b>	<b>336,463</b>	<b>Bristol</b>	<b>BL041282</b>
Breakdown	Red battery warning,Smoke from bonnet.						
45 Engine 1	Replaced both AUX belts, tensioner and idlers						
15 Steering 1	Replaced power steering pump						
52 Electrical Aux	Replaced Alternator						
<b>SAFETY INSPECTION</b>	<b>03/05/2024</b>	<b>11:47</b>	<b>03/05/2024</b>	<b>17:54</b>	<b>337,098</b>	<b>Bristol</b>	<b>BL041397</b>
18 Wheels Check Torques	Torque All Wheel Nuts - 180NM #2						
Safety Inspection	Carry Out Safety Inspection						
Tail Lift Inspection	Carry Out Tail Lift Inspection						
02 Windscreen	Top Up Screenwash						
18 Wheels Removal	Clean All Hubs And Flanges						
89 Seats	Left Trim On Offside Front Seat Damaged - New Req'd						
<b>Defect Repair</b>	<b>04/05/2024</b>	<b>08:14</b>	<b>04/05/2024</b>	<b>08:16</b>	<b>337,160</b>	<b>Bristol</b>	<b>BL041434</b>
34 Lights Bulb Replacement	Nearside headlamp						

<b>Vehicle Deep Clean</b>	<b>04/05/2024</b>	<b>14:30</b>	<b>04/05/2024</b>	<b>16:30</b>	<b>337,160</b>	<b>Bristol</b>	<b>BL041453</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>ACCIDENT</b>	<b>25/05/2024</b>	<b>11:06</b>	<b>27/05/2024</b>	<b>09:25</b>	<b>337,170</b>	<b>Bristol</b>	<b>BL042190</b>
02 Mirrors	Mirrors n/s wing mirror glass portion smashed						
<b>SAFETY INSPECTION</b>	<b>19/06/2024</b>	<b>13:26</b>	<b>19/06/2024</b>	<b>16:36</b>	<b>342,873</b>	<b>Bristol</b>	<b>BL043019</b>
18 Wheels Check Torques	Torque All Wheel Nuts - 180NM #2						
Safety Inspection	Carry Out Safety Inspection						
Annual Air Con Service	Carry Out Annual Air Condition Service						
02 Windscreen	Top Up Screenwash						
18 Wheels Removal	Clean All Hubs And Flanges						
86 Doors Rear	Replace Missing Nearside Rear Door Lower Catch Cover						
55 Tail Lift	Replace Damaged Offside Safety Rail						
<b>Vehicle Deep Clean</b>	<b>19/06/2024</b>	<b>10:20</b>	<b>19/06/2024</b>	<b>13:30</b>	<b>342,873</b>	<b>Bristol</b>	<b>BL043077</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Breakdown</b>	<b>03/07/2024</b>	<b>04:40</b>	<b>03/07/2024</b>	<b>08:43</b>	<b>344,144</b>	<b>Bristol</b>	<b>BL043454</b>
Breakdown	O/S/R Body Damage,carry out repairs to o/s/r lower corner cap						
<b>Breakdown</b>	<b>17/08/2024</b>	<b>14:15</b>	<b>17/08/2024</b>	<b>15:40</b>	<b>349,133</b>	<b>Bristol</b>	<b>BL044962</b>
Breakdown	O/S rear inner has a nail in it						
17 Tyres Replace	Replaced Both O//R tyres						
18 Wheels Retorque	Torqued O/S/R only						

<b>Unplanned Repair</b>	<b>19/08/2024</b>	<b>14:19</b>	<b>19/08/2024</b>	<b>14:22</b>	<b>349,435</b>	<b>Bristol</b>	<b>BL045041</b>
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Install Saloon CCTV Camera	Pulled CCTV hard drive and formatted
----------------------------	--------------------------------------

<b>SAFETY INSPECTION</b>	<b>06/09/2024</b>	<b>07:51</b>	<b>07/09/2024</b>	<b>11:11</b>	<b>351,326</b>	<b>Bristol</b>	<b>BL045667</b>
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
87 Chairs	Med Equip & Devices One passenger chair defected, big hole on chair
55 Tail Lift	Ramp/Lift/Tail Hoist ramp jammed in closed position
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
Wheel Hub Flanges Replaceme	
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
UB Fire Supp 12mts Service	Service of fire supression system
Tail Lift Inspection	
86 Door Lock	Replaced rear door and locker door locks
02 Glass / Windows	Replaced offside switch
99 Diagnostic Test	Deleted codes from service
89 Seats	Replaced damaged offside height adjustment lever
86 Sliding Door	Replaced damaged top latch cover
02 Cab Ass Fire Extinguisher	Replaced both extinguishers
13 Brakes 1	Replaced front discs and pads
17 Tyres Replace	X 3
41 Air Intake	Replaced turbo intake pipe
45 Engine Oil Top Up	
87 Stretcher	Replaced battery

<b>Vehicle Deep Clean</b>	<b>07/09/2024</b>	<b>14:30</b>	<b>07/09/2024</b>	<b>17:45</b>	<b>351,326</b>	<b>Bristol</b>	<b>BL045718</b>
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

<b>Defect Repair</b>	<b>08/09/2024</b>	<b>09:37</b>	<b>08/09/2024</b>	<b>09:39</b>	<b>351,361</b>	<b>Bristol</b>	<b>BL045723</b>
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Offside headlamp
MDT Failure/Issue	Checked for operation of terrafix, all seems ok

<b>SAFETY INSPECTION</b>	<b>18/10/2024</b>	<b>12:45</b>	<b>18/10/2024</b>	<b>16:47</b>	<b>355,194</b>	<b>Bristol</b>	<b>BL047156</b>
18 Wheels Check Torques Safety Inspection 02 Windscreen 18 Wheels Removal							
<b>Vehicle Deep Clean</b>	<b>19/10/2024</b>	<b>12:15</b>	<b>19/10/2024</b>	<b>17:00</b>	<b>355,194</b>	<b>Bristol</b>	<b>BL047209</b>
Vehicle Deep Clean      Vehicle Deep Clean							
<b>BREAKDOWN</b>	<b>21/10/2024</b>	<b>18:04</b>	<b>21/10/2024</b>	<b>18:06</b>	<b>355,194</b>	<b>Bristol</b>	<b>BL047273</b>
99 Diagnostic Test      test system found soot content high 43 Exhaust System 1      carry out forced regen reset values possible new DPF on next return							
<b>Breakdown</b>	<b>30/10/2024</b>	<b>03:16</b>	<b>30/10/2024</b>	<b>09:05</b>	<b>355,788</b>	<b>Bristol</b>	<b>BL047560</b>
Breakdown      N/S Headlight 34 Lights Bulb Replacement      Replace Blown Nearside Headlight Bulb							
<b>Defect Repair</b>	<b>21/11/2024</b>	<b>10:11</b>	<b>21/11/2024</b>	<b>10:14</b>	<b>356,944</b>	<b>Bristol</b>	<b>BL048372</b>
01 Heating 1      A/C System Saloon no heating in saloon - OLD DEFECT 86 Sliding Door      Re-attached top latch and re-secured mounting plate to door							
<b>Unplanned Repair</b>	<b>24/11/2024</b>	<b>06:30</b>	<b>24/11/2024</b>	<b>08:27</b>	<b>358,059</b>	<b>Bristol</b>	<b>BL048475</b>
86 Sliding Door      Side Door Alarming - Replace Faulty Top Catch And Adjust Cables							
<b>SAFETY INSPECTION</b>	<b>29/11/2024</b>	<b>14:58</b>	<b>02/12/2024</b>	<b>17:00</b>	<b>358,414</b>	<b>Bristol</b>	<b>BL048690</b>
18 Wheels Check Torques Safety Inspection							

Replace Handbrake Cables	Replace Handbrake Cables						
Engine Change Oil & Filter							
Tail Lift Inspection							
MOT							
71 Body Exterior 1	Replaced call signs						
<b>Vehicle Deep Clean</b>	<b>30/11/2024</b>	<b>21:00</b>	<b>30/11/2024</b>	<b>23:59</b>	<b>358,414</b>	<b>Bristol</b>	<b>BL048741</b>
Vehicle Deep Clean	Vehicle Deep Clean						
<b>Unplanned Repair</b>	<b>04/12/2024</b>	<b>11:02</b>	<b>04/12/2024</b>	<b>11:05</b>	<b>358,415</b>	<b>Bristol</b>	<b>BL048875</b>
99 Diagnostic Test	Carry Out Fault Code Check For EML On - Low Voltage Codes Stored - Clear Codes						
<b>Breakdown</b>	<b>21/02/2025</b>	<b>19:43</b>	<b>24/02/2025</b>	<b>10:12</b>	<b>361,443</b>	<b>Bristol</b>	<b>BL051807</b>
Breakdown	multiple warning on dash ABS/Traction/Lane assist vehicle to attend workshops					Monitoring	
<b>RE-ISSUE INSPECTION</b>	<b>25/02/2025</b>	<b>16:18</b>	<b>27/02/2025</b>	<b>10:28</b>	<b>361,901</b>	<b>Bristol</b>	<b>BL051939</b>
Re-Issue Inspection							
Breakdown	multiple warning on dash ABS/Traction/Lane assist vehicle to attend workshops						
02 Mirrors	Body Exterior Knocked wing mirror off						
13 Brakes 1	abs fault NSF						
<b>SAFETY INSPECTION</b>	<b>27/02/2025</b>	<b>15:44</b>	<b>27/02/2025</b>	<b>17:25</b>	<b>361,487</b>	<b>Bristol</b>	<b>BL052015</b>
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
<b>Vehicle Deep Clean</b>	<b>27/02/2025</b>	<b>22:00</b>	<b>28/02/2025</b>	<b>00:00</b>	<b>361,901</b>	<b>Bristol</b>	<b>BL052037</b>
Vehicle Deep Clean	Vehicle Deep Clean						

<b>Decommission Vehicle</b>	<b>17/07/2025</b>	<b>08:00</b>		<b>364,588</b>	<b>Unallocated</b>	<b>Un001175</b>
Decommission vehicle	Decommission vehicle					