

VE64BHN	A&E	Wimborne Amb Stn					
PDI Inspection	28/01/2015	08:30	12/03/2015	11:38	140	Exeter	EX012292
02 Cab Assembly 1 PDI Inspection	dimensions on windscreen incorrect replaced,carry chair wont fit in cupboard						
BREAKDOWN	16/03/2015	15:43	17/03/2015	12:42	335	Exeter	EX012517
31 Charging System Battery	stretcher charger inop was and myself unable trace feed to aux socket notes						
Breakdown	17/03/2015	22:42	18/03/2015	14:23	429	Exeter	EX012523
01 Heating 1 56 Comms Equipment 56 Radio 87a - Medical Equipment Breakdown	blowing cold operator error cab speaker electrical shorting noise on right hand bend poor reception outdie of exeter Repaimobimed not powering up metering unit replaced Radio recep int						
Unplanned Repair	19/03/2015	10:29	19/03/2015	10:32	434	Exeter	EX012534
44 Add Ad Blue	leave 15 liters on station						
Breakdown	27/03/2015	22:11	31/03/2015	11:23	1,385	Exeter	EX012557
Breakdown	FAULT LIGHTS/SIRENS.NFF WATER LK REAR SAL. No discription to test NFF						
BREAKDOWN	01/04/2015	09:57	01/04/2015	20:30	1,386	Exeter	EX012574
31 Battery Comms 34 Emergency Light System 85 Body Interior 1 Travel Time	genesis power failing Blue lights intermittant when siren switched on Water ingress from rear saloon drop to exeter w/shop and wait drop back					Awaiting Warranty Awaiting Warranty	
SAFETY INSPECTION	03/04/2015	08:34	03/04/2015	12:02	1,781	Exeter	EX012598
18 Wheels Check Torques							

34 Emergency Light System	Blue lights intermittant when siren switched on						
85 Body Interior 1	Water ingress from rear saloon						
Safety Inspection							
Travel Time	collect and return to exeter amb station						
Breakdown	03/04/2015	22:38	10/04/2015	07:32	2,539	Exeter	EX012601
Breakdown	Mobi med not charging as unit faulty						
Breakdown	08/04/2015	20:59	09/04/2015	14:30	2,539	Exeter	EX012627
Breakdown	Mobimed not charging on veh						
Unplanned Repair	12/04/2015	12:28	12/04/2015	13:10	2,984	Exeter	EX012642
44 Add Ad Blue							
Unplanned Repair	22/04/2015	12:18	22/04/2015	12:20	4,038	Exeter	EX012701
44 Add Ad Blue							
Vehicle Deep Clean	18/05/2015	08:20	18/05/2015	12:13	8,590	Exeter	EX012855
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/05/2015	11:30	18/05/2015	13:54	8,509	Exeter	EX012857
18 Wheels Check Torques							
45 Engine 1	top up oil and adblue area cleaned off						
Safety Inspection							
Unplanned Repair	21/05/2015	14:29	27/05/2015	14:31	8,929	Exeter	EX012921
44 Add Ad Blue							

Vehicle Deep Clean	29/06/2015	09:00	29/06/2015	09:37	15,471	Exeter	EX013097
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	29/06/2015	09:00	30/06/2015	09:14	15,471	Exeter	EX013098
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/06/2015	14:42	01/07/2015	14:49	15,471	Exeter	EX013112
18 Wheels Check Torques 71 Body Exterior 1 Safety Inspection	damage to nsr front arch					Monitoring	
Unplanned Repair	03/07/2015	07:46	03/07/2015	07:50	15,471	Torquay	TO010717
45 Engine Ad Blue	Crew topped up Adblue						
Unplanned Repair	14/07/2015	08:06	14/07/2015	08:08	17,501	Exeter	EX013194
34 Lights Bulb Replacement	replaced headlight bulbs x 2						
SAFETY INSPECTION	10/08/2015	07:44	11/08/2015	11:10	22,256	Exeter	EX013352
13 Handbrake 17 Tyres Replace 18 Wheels Check Torques 55 Ramp 71 Body Exterior 1 86 Door Lock 89 Seats Safety Inspection 92 - C Service Service C	excessive travel replaced all rear tyres bridge plate guides refitted with bolts damage to nsr front arch Body Exterior Side door sticking adjusted lock cables and and lock adjuster brgs rough and grounchy richard humbfreys						
Vehicle Deep Clean	11/08/2015	08:30	11/08/2015	13:07	22,256	Exeter	EX013363

Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/08/2015	18:16	26/08/2015	08:58	24,298	Exeter	EX013447
71 Body Exterior 1 Breakdown	Repair and refit rear mudflap SIDE SKIRT/MUD FLAT O/SIDE LOOSE						
Breakdown	28/08/2015	09:05	28/08/2015	14:40	25,000	Exeter	EX013460
Breakdown	Fire supression system deployed NFF						Monitoring
SAFETY INSPECTION	21/09/2015	10:24	22/09/2015	09:04	28,344	Exeter	EX013572
17 Tyres Replace	replaaced both front tyres required Body Interior Electrical light above stretcher dripping water Statutory Inspection						
17 Tyres Tracking							
18 Wheels Check Torques							
85 Body Interior 1 Safety Inspection							
Tail Lift 6 Monthly Inspection							
Vehicle Deep Clean	22/09/2015	07:40	22/09/2015	13:00	28,344	Exeter	EX013578
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	05/10/2015	10:20	05/10/2015	11:47	30,490	Exeter	EX013651
55 Tail Lift	bridge plate seccuring bolt sheared off replaced bridge plate from NME temp repa						
SAFETY INSPECTION	02/11/2015	09:54	02/11/2015	14:52	35,134	Exeter	EX013819
02 Cab Assembly 1	Interior light inop REPLACED BULB cupboard door catch missing PARTS ORDERED Front pads low REPLACED O/S guard rail loose, drop down siezed REPAIRED						Awaiting Parts
02 Cab Assembly 2							
13 Brake Pads							
18 Wheels Check Torques							
55 Tail Lift							

85 Body Interior 1	stay bar holder missing from o/s, found in drawer REFITTED
85 Body Interior 2	Requires sticker mod DONE
85 Body Interior 3	Scoop locker strap broken REPLACED
87 Stretcher	Incorrect pedimate fitting FITTED NEW
89 Seats	Body Interior Both seats in rear VERY stiff to move in and out REPAIRED WARRANTY
Safety Inspection	

Vehicle Deep Clean	03/11/2015	06:45	03/11/2015	12:31	35,134	Exeter	EX013828
---------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	19/11/2015	22:14	23/11/2015	15:15	37,742	Exeter	EX013942
------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

Breakdown	REAR DOOR WON'T OPEN EXCEPT WITH FORCE - Notes					Awaiting Warranty	
-----------	--	--	--	--	--	-------------------	--

BREAKDOWN	27/11/2015	10:47	27/11/2015	12:00	38,189	Exeter	EX014044
------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

55 Tail Lift	gate handles seized out of warranty
--------------	-------------------------------------

SAFETY INSPECTION	14/12/2015	07:58	16/12/2015	12:30	39,752	Exeter	EX014085
--------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

13 Brakes 1	replaced rear discs and pads	
17 Tyres Replace	replaced both front and nsr inner tyre	
17 Tyres Tracking	carry out tracking	
18 Wheels Check Torques		
34 Lights	fog light damaged replaced	Awaiting Parts
71 Body Exterior 1	replaced bonnet as stay bracket requires welding and sent to autospray	
Safety Inspection		
MOT Pre Test		
93 - D Service		
Service D		
Travel Time		
MOT		

Vehicle Deep Clean	15/12/2015	08:35	15/12/2015	11:11	39,752	Exeter	EX014093
---------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	21/12/2015	13:30	23/12/2015	10:30	40,423	Exeter	EX014136
------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

Breakdown	MDT not communicating. Battery Check req						
-----------	--	--	--	--	--	--	--

Breakdown	04/01/2016	23:02	06/01/2016	14:35	43,686	Exeter	EX014215
------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

Breakdown	AMBER ENG MGMT						
-----------	----------------	--	--	--	--	--	--

SAFETY INSPECTION	25/01/2016	07:00	25/01/2016	15:13	45,957	Exeter	EX014331
--------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

18 Wheels Check Torques							
34 Emergency Light System	stretcher lamp LEDS inop done						
34 Lighting System	ns side marker damaged replaced lamp						
45 Engine Oil Top Up	1 ltr top up						
71 Body Exterior 1	ns damage and rear ramp bridge plate giudes damaged						
Safety Inspection							

Vehicle Deep Clean	25/01/2016	13:30	26/01/2016	08:49	45,957	Exeter	EX014338
---------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	29/01/2016	09:04	29/01/2016	09:06	46,099	Exeter	EX014366
-------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

34 Lights Bulb Replacement							
----------------------------	--	--	--	--	--	--	--

SAFETY INSPECTION	07/03/2016	08:20	09/03/2016	10:37	52,940	Exeter	EX014585
--------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

16 Suspension 1	Slight play in both front shocks MONITOR					Monitoring	
17 Tyres Replace	4 tyres on rear axle worn 3mm + road test						
18 Wheels Check Torques							
44 Fuel System 1	Fuel Angle damaged FITTED FUEL CAP						
87 Stretcher	Lap belts incorrect on stretcher FITTED NEW						
87a - Medical Equipment Repai	Mangor Charger plug damaged REPLACED UNIT SENT OLD UNIT FOR REPAIR IA						
Safety Inspection							

Gearbox Oil & Filter Change							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	07/03/2016	13:45	08/03/2016	11:18	52,940	Exeter	EX014590
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	16/03/2016	17:30	17/03/2016	14:08	54,207	Exeter	EX014640
71 Body External Steps Breakdown	Re-align step frame and reset motor limits side step will not deploy						
ACCIDENT	18/03/2016	07:00	18/03/2016	08:00	54,207	Exeter	EX014656
34 Emergency Lights	replaced damaged roof light						
Unplanned Repair	25/03/2016	07:30	25/03/2016	11:33	55,551	Exeter	EX014695
34 Lights 52 Electrical Aux	N/S/R sidelights and no. plate lights inop temp repair Lighting System rear light suspected fuse blown, OO aware						
Breakdown	27/03/2016	10:15	27/03/2016	10:31	55,926	Exeter	EX014700
34 Lighting System Breakdown	replaced headlight bulb Headlight bulb blown						
Breakdown	27/03/2016	11:22	29/03/2016	12:00	55,926	Exeter	EX014702
Breakdown	Rear light cluster fault						
Breakdown	03/04/2016	06:31	06/04/2016	11:50	56,710	Exeter	EX014738
34 Lighting System Breakdown	tailights inop top and bottom						

SAFETY INSPECTION	18/04/2016	07:17	18/04/2016	14:18	58,684	Exeter	EX014831
01 Air Conditioning 1	In Cab aircon inop WARRANTY					Monitoring	
13 Handbrake	Hand brake requires adjustment REPAIRED						
16 Suspension 1	Slight play in both front shocks and ball joints MONITOR					Monitoring	
18 Wheels Check Torques							
34 Emergency Light System	Airport light inop WARRANTY Claim submitted					Monitoring	
34 Lights	DRL O/S inop REPAIRED						
85 Body Interior 1	Pull knob missing from cupboard in cab repaired						
87 - Stretchers/Chairs/Boards	serviced stryker 141239284 and long board 33212 and tracks CT03142T						
87 Boards	Long board O/D						
87 Chairs	Chair and tracks O/D						
87 Stretcher	Stretcher O/D						
Safety Inspection							
92 - C Service							
Service C							
85 Body Int Alcohol Gel Dispen							
Fit Throw Lines & SOP							
Vehicle Deep Clean	19/04/2016	07:00	19/04/2016	14:13	58,684	Exeter	EX014848
Vehicle Deep Clean	Vehicle Deep Clean						
ACCIDENT	25/04/2016	11:00	25/04/2016	12:15	59,216	Exeter	EX014880
Travel Time	Travel to exeter station for vehicle collection						
02 Mirrors	Body Exterior Off side wing mirror, log 84 24/04/16 REPLACED						
Vehicle Deep Clean	31/05/2016	08:30	02/06/2016	13:21	64,706	Exeter	EX015073
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	31/05/2016	11:04	03/06/2016	14:51	64,706	Exeter	EX015074
01 Air Conditioning 1	Eberspacher A/C leak - WARRANTY Done					Awaiting Warranty	
02 Cab Ass Fire Extinguisher	Both cab and saloon fire extinguishers no service dates					Awaiting Parts	

02 Mirrors	Mirrors o/s wing mirror damage, going wrkshps						
13 Brakes 1	Front discs and pads worn - Replaced						
16 Suspension 1	Slight play in both front shocks and ball joints MONITOR					Awaiting Warranty	
17 Tyres	O/S/F tyre worn to 3mm - Replaced						
18 Wheels Check Torques							
34 Emergency Light System	Airport light inop WARRANTY Claim submitted						
34 Lighting System	O/S/R Number plate light broken - Repaired						
34 Lights	N/S/F dipped beam inop - Replaced						
43 Exhaust System 1	Exhaust tail pipe and monting badly bent - Replaced						
71 Body Exterior Acc Repair	Body damage to both rear arches, N/S/R locker door and step area					Awaiting Body Repair	
85 Body Interior 1	I.V. holder missing velcro straps - Replaced						
86 Doors	N/S/R door difficulty open inside and out - suspect cable adjustment rqd - Done						
86 Doors Rear	O/S/R door difficult to open, Door stay bar centre bolt snapped - DONE						
89 Seats	N/S/R saloon seat base split and detend pin loose - Repaired						
Safety Inspection							
UB Fire Suppression Service	Warning going off after serv. fitted new system						
Annual Air Con Service	Annual Air Condition Service - See NOTES						
Annual Heater Service	Annual Heater Service						
Wheel Studs & Nuts Replaceme							
Handbrake Cable Replacement	Replace rear handbrake cables						
Reposition grab bag shelf							

Breakdown	04/06/2016	06:22	04/06/2016	10:24	64,787	Exeter	EX015106
------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

18 Wheels	leaking rim replaced wheel and tyre
Breakdown	flat tyre near side front

BREAKDOWN	08/06/2016	13:00	08/06/2016	14:31	65,390	Exeter	EX015138
------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

86 Doors Rear	osr door dropped adjusted aprature
---------------	------------------------------------

Breakdown	10/06/2016	08:11	10/06/2016	14:58	65,651	Exeter	EX015152
------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

71 Body External Steps	Temp Repair WARRANTY CLAIM SUBMITTED	Awaiting Warranty
Breakdown	SIDE STEP MOTOR NOT CUTTING OUT	

Unplanned Repair	24/06/2016	08:45	24/06/2016	08:59	67,702	Exeter	EX015247
-------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

34 Lights	Electrical Auxs OS side turn signal not working REPAIRED
-----------	--

ACCIDENT	01/07/2016	09:45	20/07/2016	15:11	69,000	Exeter	EX015314
02 Windows/Glass	Other o/s side window smashed, VOR'd at Exeter.						
71 Body Exterior Acc Repair	Body damage to both rear arches, N/S/R locker door and step area						
Vehicle Deep Clean	11/07/2016	09:04	20/07/2016	12:49	68,972	Exeter	EX015362
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/07/2016	13:30	20/07/2016	15:08	69,015	Exeter	EX015416
02 Cab Ass Fire Extinguisher	Both cab and saloon fire extinguishers no service dates FITTED Slight play in both front shocks and ball joints MONITOR Monitoring Temp Repair WARRANTY CLAIM SUBMITTED-DONE Doors SIDE DOOR JAMMED REPAIRED						
16 Suspension 1							
18 Wheels Check Torques							
71 Body External Steps							
86 Sliding Door							
Safety Inspection							
Breakdown	04/08/2016	12:37	05/08/2016	14:38	70,841	Exeter	EX015502
45 Engine 1 Breakdown	Sent to City west SEE NOTES LOP Complete						
BREAKDOWN	15/08/2016	06:00	15/08/2016	09:12	72,336	Exeter	EX015558
86 Doors Install Saloon CCTV Camera	locker door handle snapped off Awaiting Warranty						
Unplanned Repair	17/08/2016	08:49	18/08/2016	08:58	72,728	Exeter	EX015585
17 Tyres Replace	osro tyre puncture						

SAFETY INSPECTION	22/08/2016	09:09	22/08/2016	14:55	73,236	Exeter	EX015605
02 Mirrors	N/S mirror back broken, sharpe edges exposed REPLACED FRAME AND BACK						
13 Brakes 1	hand brake travel to high READJUSTED						
16 Suspension 1	Slight play in both front shocks and ball joints MONITOR						Monitoring
16 Suspension 2	rear u/bolts loose plus spring moved, RE-ALIGNED RETORQUED						Monitoring
17 Tyres Replace	N/S/F tyre below 3mm, REPLACED						
18 Wheels Check Torques							
45 Engine 1	belt tensioner boot split slight sweat marks, MONITOR						Monitoring
55 Tail Lift	grab rail relaese handle bolts loose RETIGHENED SEE NOTES						Monitoring
56 Radio	hand held aireal broken FITTED NEW						
71 Body Exterior 1	long board top retainig bracket missing MONITER						Monitoring
85 Body Interior 1	bulk head window lock missing PARTS ORDERED JW 22.08.16						Awaiting Parts
85 Body Interior 2	response bag securing strap broken FITTED NEW						
85 Body Interior 3	carry chair retainig bracket bent REMOVED AND STRAINGTENED						
86 Door handle	Body Exterior Door handle broke. NFF						
86 Doors	locker door handle snapped off JOB COMPLETE						
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	23/08/2016	07:40	23/08/2016	12:09	73,236	Exeter	EX015617
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/09/2016	08:45	23/09/2016	09:15	78,250	Exeter	EX015877
71 Body Exterior 1	broken front number plate, REPLACE FRONT NUMBER PLATE						
Breakdown	25/09/2016	11:41	26/09/2016	08:04	78,613	Exeter	EX015884
86 Door Lock	bolts fallen out refitted and replaced cover and checked all ok						
Breakdown	SIDE DOOR JAMMED						
Vehicle Deep Clean	04/10/2016	07:45	04/10/2016	12:20	80,154	Exeter	EX015955

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	04/10/2016	13:41	06/10/2016	09:08	80,156	Exeter	EX015961

02 Cab Assembly 1	Both front armrests insecure - Re-secured	
02 Cab Assembly 2	Brake pedal rubber split	
02 Windscreen Wipers	Front wiper blades poor - Replaced	
13 Brakes 1	Replaced rear discs and pads	
16 Suspension 1	Slight play in both front shocks and ball joints MONITOR	Awaiting Warranty
16 Suspension 3	All Rear spring slipper pads splitting	
18 Wheels Check Torques		
45 Engine 1	belt tensioner boot split slight sweat marks, MONITOR	Awaiting Warranty
55 Ramp	Tail lift bridge plate guides insecure - Re-secured	
55 Tail Lift	grab rail release handle bolts loose RETIGHTENED SEE NOTES	
85 Body Interior 1	bulk head window lock missing PARTS ORDERED JW 22.08.16	Awaiting Parts
85 Body Interior 2	Maternity bag strap broken - Replaced	
86 Doors Rear	N/S/R door stay bar insecure - Re-secured	
89 Seatbelts	Untwisted Front saloon seatbelt	
89 Seats	Both N/S saloon seat detent pins insecure - Re-secured	
Safety Inspection		
93 - D Service		
Service D		
MOT Pre Test		

SAFETY INSPECTION	14/11/2016	08:00	18/11/2016	14:46	85,415	Exeter	EX016241
--------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

02 Mirrors	broken mirror back n/s, MIRROR BACK AND LENS REPLACED	
13 Handbrake	high hand brake travel, readjusted brake shoes	
16 Suspension 1	Slight play in both front shocks and ball joints, NOW WORN, WARRENTY	
16 Suspension 2	rear arb worn, WARRENTY	
17 Tyres Replace	rear tyres x3 worn, TYRES REPLACED AND FITTING FACES CLEANED	
18 Wheels Check Torques		
34 Emergency Lights	o/s/r top corner blue light holed, HOLE FILLED AND REPAIRED	
45 Engine 1	belt tensioner boot split slight sweat marks, NOW LEAKING, WARRENTY	
45 Engine 2	aux belt tensioner leaking, WARRENTY	
52 Electrical Aux	phone holder broken, HOLDER FOUND AND REPAIRED	
55 Tail Lift	tail lift handle bolt missing o/s, BOLT REPLACED AND LOCK TIGHTED	
71 Body External Steps	step edge broken, STEP EDGE REPLACED AND NEW DECAL APPLIED	
85 Body Interior 1	bulk head window lock missing, WINDOW LOCK REPLACED	
85 Body Interior 3	bio strap buckle cracked, AWP	Awaiting Parts
86 Door Lock	Doors when locking remotely one front doors doesn't lock NFF	

87 - Stretchers/Chairs/Boards	carry chair securing bracket broken, WARRENTY						Awaiting Parts
89 Seats	child seat base securing clip missing, AWP						
Check Winter Pack	winter pack checked and complete						
Safety Inspection							
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill, HOLES FILLED						
Travel Time							
MOT							
Vehicle Deep Clean	14/11/2016	10:54	14/11/2016	15:36	85,415	Exeter	EX016243
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	06/12/2016	07:21	06/12/2016	08:46	87,969	Exeter	EX016397
34 Lights Bulb Replacement	REPLACED NSF MAIN BULB REPLACED						
Breakdown	Headlight						
Vehicle Deep Clean	23/12/2016	07:00	23/12/2016	12:17	90,823	Exeter	EX016543
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/12/2016	09:23	23/12/2016	12:09	90,823	Exeter	EX016544
02 Cab Assembly 1	remove damaged shelf in cupboard sharp edges						
13 Handbrake	travel adjusted						
16 Suspension 1	lower link bushes slight play serviable						
18 Wheels Check Torques							
45 Engine 1	slight weep from tensioner						
85 Body Interior 3	bio strap buckle cracked replaced						
89 Seats	child seat base securing clip missing, AWP						
Safety Inspection							
Breakdown	31/01/2017	17:19	01/02/2017	08:34	97,207	Exeter	EX016821
Breakdown	SIREN not working , lights ok						

SAFETY INSPECTION	06/02/2017	08:14	08/02/2017	09:29	98,262	Exeter	EX016844
--------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

02 Cab Assembly 1	Front armrests insecure - Re-secured	
16 Suspension 1	lower arms slight play in swivel joints, MONITOR	Monitoring
16 Suspension 2	Both front struts have slight play in them. MONITOR	Monitoring
17 Tyres Replace	N/S/F, O/S/F, O/S/R OUTER tyres below 3mm, tyres replaced.	
18 Wheels Check Torques		
34 Lights	Lighting System osf running light u/s	
45 Engine 1	aux drive belt tensioner weeping fluid - Replaced	
55 Tail Lift	Bridge plate guide pulled out of body - Repaired	
71 Body Exterior 1	rear sprya surppresor insecure, resecured	
71 Body External Steps	step mud flap split, step mud flap replaced	
85 Body Interior 1	Carry chair bracket snapped and monting loose - Weld repair and re-secured	
85 Body Interior 2	Response bag trap broken - Replaced	
86 Door Lock	Rear door lock siezed - Repaired	
86 Doors Rear	O/S rear door stay bar bent - Straightened	
86 Sliding Door	Top lock mounting plate loose and cover broken	
89 Seats	Both rear swivel seat armrests and detend pin insecure - Re-secured	
Safety Inspection		
Medical Device and Equip Chec		
92 - C Service		
Service C		
Tail Lift 6 Monthly Inspection	Statutory Inspection	
Tail Lift Annual Service	Statutory Inspection and Weight Test	
Gearbox Oil & Filter Change		

Vehicle Deep Clean	07/02/2017	08:50	07/02/2017	12:01	98,262	Exeter	EX016859
---------------------------	-------------------	--------------	-------------------	--------------	---------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	20/03/2017	08:38	21/03/2017	08:40	104,233	Exeter	EX017157
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

16 Suspension 1	lower arms slight play in swivel joints, MONITOR	
16 Suspension 2	Both front struts have slight play in them. MONITOR	
16 Suspension 3	rear lower ARB worn, ARB replaced.	
18 Wheels Check Torques		
34 Lights	DRL inop, 2x bulbs replaced	
43 Exhaust System 1	heater exhaust broken, WARRENTY	Awaiting Warranty
55 Ramp	slow close and warning lights not working, WARRENTY	Awaiting Warranty
71 Body External Steps	step mud flap ripped, step mud flap replaced.	

Safety Inspection							
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
Vehicle Deep Clean	21/03/2017	07:00	21/03/2017	10:38	104,233	Exeter	EX017167
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	29/03/2017	11:00	29/03/2017	11:44	105,359	Exeter	EX017223
34 Lights Bulb Replacement	replaced h/ light bulb x 2 switch on DRLs as reported in op						
SAFETY INSPECTION	01/05/2017	08:24	04/05/2017	14:38	111,794	Exeter	EX017433
02 Cab Assembly 1	Cab centre console cupboard white button missing						
13 Brakes 1	Front discs and pads worn - Replaced						
16 Suspension 1	N/S/R spring front slipper pad split						
17 Tyres	N/S/R outer tyre worn - Replaced						
18 Wheels Check Torques							
43 Exhaust System 1	heater exhaust broken, WARRENTY - Done						
55 Ramp	slow close and warning lights not working, WARRENTY						
55 Tail Lift	Bridge plate guides ripped out of body and mounting plate ripped - Replaced						
71 Body Exterior Acc Repair	N/S of vehicle damaged (lower sill, side door and above wheel arch)						
86 Doors Rear	O/S/R door stay bent						
86 Sliding Door	Top lock cover damaged						
89 Seatbelts	N/S/R saloon seatbelt twisted - Untwisted						
Safety Inspection							
Travel Time	Collect from exe station						
Handbrake Cable Replacement	Replace rear handbrake cables						
Vehicle Deep Clean	03/05/2017	08:22	03/05/2017	11:32	111,794	Exeter	EX017453
Vehicle Deep Clean	Vehicle Deep Clean						
WAS Firetrace rework and	02/05/2017	10:18	02/05/2017	13:30	111,794	Exeter	EX017778
UB Fire Suppression Service	carried out by JC on 02/05/17						

Breakdown	07/06/2017	10:15	07/06/2017	13:18	116,465	Exeter	EX017696
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	tracking out - pulling lef see notes.						
-----------	---------------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	12/06/2017	07:41	13/06/2017	14:42	117,084	Exeter	EX017727
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

13 Brakes 1	rear discs and pads worn, disc and pads replaced						
16 Suspension 1	N/S/R spring front slipper pad split						
18 Wheels Check Torques							
34 Lights Bulb Replacement	DRL inop, bulb replaced.						
55 Ramp	slow close and warning lights not working, WARRENTY						
55 Tail Lift	Bridge plate guides ripped out of body and mounting plate ripped - Replaced						
71 Body Exterior Acc Repair	N/S of vehicle damaged (lower sill, side door and above wheel arch)						
71 Body External Steps	side step bent, step restraightend						
85 Body Interior 1	cab touch missing, touch replaced						
Safety Inspection							
MGS Gas Storage Modifications	MGS Gas Storage Modifications						
93 - D Service							
Service D							

Vehicle Deep Clean	13/06/2017	07:00	13/06/2017	11:39	117,084	Exeter	EX017738
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	19/06/2017	07:30	19/06/2017	08:22	118,060	Exeter	EX017790
-------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

01 Air Conditioning 1	Electrical Auxs Air conditioning ? saloon re-gassing.						Monitoring
02 Mirrors	Mirrors NSF blind spot mirror fallen out REPLACED						
34 Lighting System	indicator inop nsf wing						

Breakdown	05/07/2017	08:46	05/07/2017	14:53	120,335	Exeter	EX017909
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	Check batteries for power fail on coms						
-----------	--	--	--	--	--	--	--

Replace Vehicle Fuel Card	18/07/2017	11:57	18/07/2017	11:58	122,271	Exeter	EX017995
----------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
---------------------------	---------------------------

Vehicle Deep Clean	24/07/2017	07:30	24/07/2017	13:07	123,217	Exeter	EX018051
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	24/07/2017	01:55	25/07/2017	13:41	123,321	Exeter	EX018066
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

01 Air Conditioning 1	Electrical Auxs Air conditioning ? saloon re-gassing.
02 Cab Assembly 1	replaced locker knob
17 Tyres Replace	replaced osri/o and nsri
18 Wheels Check Torques	
34 Lights Bulb Replacement	cab light bulb replaced
Safety Inspection	
Tail Lift 6 Monthly Inspection	Statutory Inspection

Breakdown	15/08/2017	09:45	15/08/2017	12:00	126,778	Exeter	EX018254
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	LOP - EML on / will not reset
-----------	-------------------------------

BREAKDOWN	29/08/2017	08:16	29/08/2017	14:57	128,405	Exeter	EX018339
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

86 Door Lock	Sliding door handle very stiff to open SEE NOTES
86 Doors	Door warning sounding
86 Sliding Door	Top door ctach pulled away from door REPAIRED

Vehicle Deep Clean	04/09/2017	10:17	04/09/2017	14:52	128,780	Exeter	EX018379
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	04/09/2017	11:23	06/09/2017	08:59	128,780	Exeter	EX018380
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

16 Suspension 1	both front struts and swiveals worn, MONITOR	Monitoring
18 Wheels Check Torques		
34 Lights	cab light not working, BULB REPLACED	
34 Lights Bulb Replacement	head light bulb inop. bulb replaced	
45 Engine 1	belt tensioner leaking, warrenty repair mercedes	Awaiting Warranty
71 Body Exterior 1	fog light cover missing,	Awaiting Parts
85 Body Interior 1	bulkhead window catch missing, CATCH REPLACED	
85 Body Interior 2	MGS brackets incorrectly fitted by crew, recorrect system,	
86 Sliding Door	sliding door lock cover broken, RESECURED	
Safety Inspection		

Vehicle Deep Clean	16/10/2017	09:00	17/10/2017	09:04	134,729	Exeter	EX018658
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	17/10/2017	07:25	20/10/2017	08:37	134,729	Exeter	EX018664
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Windscreen Wipers	Wipers not clearing screen REPLACED	
15 Steering 1	P/steering leak from hose on X member and Reservoir hose	Awaiting Warranty
15 Steering 2	Play and noise from O/S rack WARRANTY	Awaiting Warranty
16 Suspension 1	both front struts and swiveals worn, MONITOR	Monitoring
17 Tyres Replace	N/S/R inner worn 3mm REPLACED	
18 Wheels	Corrosion around wheel nut holes REPLACED	
18 Wheels Check Torques		
44 Fuel System 1	Diesel leak showing on under side of engine WARRANTY	Awaiting Warranty
45 Engine 1	belt tensioner leaking, warrenty repair mercedes	
55 Tail Lift	O/S hand rail loose mounting REPAIRED	
71 Body Exterior 1	fog light cover missing,	
Safety Inspection		
MOT Pre Test		
92 - C Service		
Service C		

Breakdown	15/11/2017	10:45	15/11/2017	11:54	139,084	Exeter	EX018874
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

86 Doors	side door top lock collapsed and replaced bolts and cover
Breakdown	unable to open side door from outside

Vehicle Deep Clean	27/11/2017	07:25	27/11/2017	11:00	140,984	Exeter	EX018941
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/11/2017	12:15	28/11/2017	14:58	140,984	Exeter	EX018946
02 Cab Assembly 1	cab touch missing. torch replaced.						
02 Mirrors	n/s mirror broken. variouse parts replaced.						
15 Steering 1	P/steering leak from hose on X member and Reservoir hose, merc repaired						
15 Steering 2	Play and noise from O/S rack, merc completed, warrenty						
15 Steering 3	steering pipe clip broken, pipe clipp replaced.						
16 Suspension 1	both front struts and swiveals worn, MONITOR						
18 Wheels Check Torques							
34 Lighting System	o/s/f fog light cover rmissing.AWP						
34 Lights	n/s head light bulb u/s, bulb replaced						
44 Fuel System 1	Diesel leak showing on under side of engine, merc completed warrenty						
55 Tail Lift	bridge plate guides broken. bolts drilled out and replaced.						
71 Body Exterior 1	lower o/s/r reflector u/s. reflector replaced.						
85 Body Interior 1	side door inner lock cover insecure. SEE NOTES WARRENTY						
85 Body Interior 2	saloon roof fan inop.WARRENTY.						Awaiting Warranty
86 Door Seals	drivers door seal ripped.Door seal replaced.						
Safety Inspection							
Travel Time							
MOT							
BREAKDOWN	06/12/2017	13:00	07/12/2017	14:21	141,951	Exeter	EX019002
01 Heating 1	blower motor u/s checked reastate						
Breakdown	07/12/2017	14:15	07/12/2017	15:00	141,000	Exeter	EX019015
Breakdown	MDT wont turn on						
Unplanned Repair	14/12/2017	07:00	14/12/2017	07:30	142,973	Exeter	EX019062
34 Lights Bulb Replacement	replaced ind bulb						

Vehicle Deep Clean	09/01/2018	07:30	09/01/2018	13:03	147,052	Exeter	EX019208
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	09/01/2018	13:53	10/01/2018	12:19	147,052	Exeter	EX019215
02 Mirrors	o/s mirror broken, various parts replaced						
13 Brakes 1	hand brake comes up to high, readjust						
17 Tyres	2 X front totyres to trust limits,						
18 Wheels Check Torques							
34 Lights	number plate light not working. repair wiring						
34 Lights Bulb Replacement	o/s/f side light bulb inop.bulb replaced.						
55 Tail Lift	various tail lift faults, see notes						
71 Body Exterior 1	o/s/f fog light surround missing, new cover fitted						
71 Body Exterior 2	o/s wing decal coming off, refixed						
85 Body Interior 2	saloon roof fan inop.WARRENTY.						
Safety Inspection							
Defect Repair	12/01/2018	09:07	12/01/2018	09:12	147,235	Exeter	EX019234
71 Body External Steps	step not working, step damaged ,sraghten and rectify fault						
89 Seatbelts	drivers seat belt frayed, minor bubbling monitor						
Travel Time	collect vehicle from exeter, heavy traffic due to RTC.						
Tail Lift Annual Service	17/01/2018	09:03	17/01/2018	10:31	147,887	Exeter	EX019274
Tail Lift Annual Service	Statutory Inspection and Weight Test, SWTailifts Harvey						
Tail Lift 6 Monthly Inspection	Statutory Inspection SWTailifts Harvey						
Breakdown	30/01/2018	13:26	30/01/2018	15:15	149,396	Exeter	EX019370
Breakdown	Puncture						
Breakdown	06/02/2018	02:06	06/02/2018	12:21	150,292	Exeter	EX019415
31 Battery Comms	removed and checked all ok						

Breakdown MDT and radios powering down

Vehicle Deep Clean 20/02/2018 08:30 20/02/2018 13:04 152,433 Exeter EX019517

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 20/02/2018 14:11 27/02/2018 07:17 152,433 Exeter EX019528

02 Windscreen Wipers

13 Brakes 1 Replace front discs and pads

13 Brakes 2 Replace rear brake shoes, discs and pads

15 Steering 2 Small PAS oil leak

16 Suspension 1 Both lower ball joints have play MONITOR

16 Suspension 2 Both front struts have play MONITOR

17 Tyres Replace Replace 3 x tyres

18 Wheels Replace 2 x rims

18 Wheels Check Torques

34 Emergency Light System O/S side top front and rear blue strobes damaged

34 Lights O/S scene light has condensation in it MONITOR

42 Coolant System REPLACED AS WEAK

45 Engine 1 Rattle from cold startup (Timing chain) (DEALER)

55 Tail Lift Lift has damage to metal work MONITOR

71 Body Exterior 1 O/S and N/S lower front and rear corner covers broken

71 Body Exterior Roof O/S top corner plate holed

71 Body External Steps Poor action

85 Body Interior 1 Extraction fan not working

85 Body Interior 2 Saloon towel dispenser damaged. Cab centre console button broken and strut loose

85 Body Interior 3 Strap buckle broken on lower stowage sliding door scoop strap buckle broken

86 Doors Rear Lower lock cover insecure Chair stowage red handle cover missing

86 Sliding Door Sliding door arm spring and bearings required, Top latch cover broken

Safety Inspection

85 Body Int Alcohol Gel Dispen

93 - D Service

Service D

Gearbox Oil & Filter Change

Wheel Hub Flanges Replaceme

Handbrake Cable Replacement Replace rear handbrake cables

Unplanned Repair	05/04/2018	11:45	05/04/2018	11:53	158,160	Exeter	EX019791
-------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

31 Battery Comms	comms failing, test battery, comms battery failed test, battery replaced.						
------------------	---	--	--	--	--	--	--

Vehicle Deep Clean	09/04/2018	07:15	09/04/2018	10:37	158,947	Exeter	EX019806
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	13/04/2018	09:16	13/04/2018	13:30	159,688	Exeter	EX019855
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Assembly 1	Bulk head sliding window catch missing						
13 Brakes 1	Hand brake lever high (adjusted)						
17 Tyres Replace	Both front tyres replaced						
18 Wheels Balance & Alignment	Wheel alignment required						
18 Wheels Check Torques							
34 Emergency Lights	Torch getting hot on charger						
34 Lights Bulb Replacement	N/S/F side light and DRL light inop						
45 Engine Oil Top Up							
71 Body Exterior 1	Corner covers damaged N/S & O/S rear lower and O/S upper front O/S/R light pod						Monitoring
71 Body Exterior 2	Spray suppression torn MONITOR						Monitoring
86 Sliding Door	Bearings rough						
89 Seats	seat base replaced as ripped						
Safety Inspection							
Fit Poster Holder	Fit Poster Holder						
UB Fire Suppression Service							

BREAKDOWN	02/05/2018	07:03	03/05/2018	15:02	162,040	Exeter	EX019986
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

45 Engine 1	VISCOUS VAN SUPPORT DAMAGED AND BELT SHREDDED NOTES						Awaiting Parts
71 Body Exterior Acc Repair	Body Exterior damage to Siren housing						Awaiting Parts
Road Test							

Breakdown	13/05/2018	19:25	14/05/2018	14:32	163,468	Exeter	EX020065
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

31 Charging System Battery	Test and confirm alternator failed REPLACED						
Breakdown	SRS and ESP, alt lights on						

SAFETY INSPECTION	14/05/2018	09:45	15/05/2018	09:41	163,468	Exeter	EX020069
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

01 Air Conditioning 1	A/C condensor fan inop	Awaiting Parts
02 Cab Ass Fire Extinguisher	Fire suppression low but still in green MONITOR	Monitoring
02 Windows/Glass	Passager window switch missing REPLACED	
02 Windscreen Wipers	Washer cap missing	Awaiting Parts
18 Wheels Check Torques		
34 Lights	O/S/F fog light sorround missing REPLACED	
34 Lights Bulb Replacement	Interioir light inop REPLACED	
45 Engine 1	VISCOUS VAN SUPPORT DAMAGED AND BELT SHREDDDED NOTES	
45 Engine 2	Signs of oil leaking around inlet track	
45 Engine Ad Blue	Adblue warning on TOPPED UP	
56 Comms Fitment	NO voice warning in saloon REPIARED WIRING TO SPEAKER	
71 Body Exterior 2	Rear spray suppression torn REPLACED	
71 Body Exterior Acc Repair	Body Exterior damage to Siren housing	Awaiting Body Repair
71 Body External Steps	Mud flap torn REPLACED	
85 Body Interior 1	Centre console lock inop REPAIRED	
85 Body Interior 2	Cab speaker insecure REPAIRED SEE NOTES	
85 Body Interior 3	Saloon fan inop PARTS ORDERED	Awaiting Parts
87 Chairs	Track stowage cupboard stop damaged	
Safety Inspection		

Vehicle Deep Clean	15/05/2018	09:49	15/05/2018	13:45	163,468	Exeter	EX020076
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	22/05/2018	07:18	30/05/2018	08:26	164,332	Exeter	EX020130
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

01 Air Conditioning 1	A/C condensor fan inop	
41 Turbo	Blown turbo REPLACED BY MERC OF EXETER	
71 Body Exterior Acc Repair	Body Exterior damage to Siren housing	Monitoring
85 Body Interior 3	Saloon fan inop PARTS ORDERED	

SAFETY INSPECTION	28/06/2018	07:22	29/06/2018	07:33	168,296	Exeter	EX020377
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

15 Steering 1	minor weap on power steering hose. hose cleaned up and monitor.
18 Wheels Check Torques	
45 Engine 1	belt tensioner leaking
45 Engine Oil Top Up	Engine add 1L oil displayed, no leaks found

71 Body Exterior 1	3 X lower body corners smashed up.						
71 Body Exterior 2	fog light surround missing,						
Safety Inspection							
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	29/06/2018	07:32	29/06/2018	12:20	168,298	Exeter	EX020394
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	15/07/2018	23:11	16/07/2018	11:47	170,923	Exeter	EX020494
Breakdown	rear differential oil leak, SEE NOTES						
Road Test	road test vhlcle to check for leaks, no leaks present, level checked.						
Breakdown	26/07/2018	18:38	27/07/2018	11:57	172,663	Exeter	EX020564
01 Air Conditioning 1	reported cold then goes hot over 20 mph see notes						
56 Comms Power Failure	checked batteries and cbles all good sent to pce						
Breakdown	Powering down - battery check please						
SAFETY INSPECTION	07/08/2018	10:48	08/08/2018	13:28	173,934	Exeter	EX020627
02 Mirrors	Drivers mirror glass insecutre REPAIRED						
13 Brake Pads	Front pads required						
16 Suspension 1	O/S front ball joint required MONITOR N/S						Monitoring
16 Suspension 2	Play in both front struts						Monitoring
17 Tyres Replace	Replace all rear tyres and N/S/F SEE NOTES						
18 Wheels Check Torques							
34 Emergency Lights	Damage to N/S/R upper corner lens						Monitoring
34 Lights Bulb Replacement	DRL lights both bulbs replaced						
55 Tail Lift	Tail lift slow to operate and no lights working						
71 Body Exterior 1	O/S upper front corner damaged O/S rear wheel arch damaged						Monitoring
Safety Inspection							

Vehicle Deep Clean	08/08/2018	11:30	09/08/2018	11:20	173,934	Exeter	EX020636
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	04/09/2018	16:46	05/09/2018	11:25	176,332	Exeter	EX020808
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

13 Brakes 1 Breakdown	See notes for defects brakes locking up
--------------------------	--

Unplanned Repair	10/09/2018	11:00	10/09/2018	11:25	177,145	Exeter	EX020840
-------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

34 Lights Bulb Replacement	replaced DRL
----------------------------	--------------

Breakdown	16/09/2018	12:27	17/09/2018	10:19	178,110	Exeter	EX020875
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

31 Battery Chassis Breakdown	battery u/s replaced no elecs at scene , restarted via emerg start
---------------------------------	---

SAFETY INSPECTION	17/09/2018	14:20	18/09/2018	14:14	178,115	Exeter	EX020889
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Ass Fire Extinguisher	both fire extinguishers out of date NO STOCK	Awaiting Parts
13 Handbrake	excessive travel REPAIRED	
16 Suspension 1	N/S lower ball joint lift measured 1.5mm MONITOR	Monitoring
16 Suspension 2	Play in both front struts MONITOR	Monitoring
17 Tyres Tracking	N/S/F scrubbing outer edge RESET TRACKING	
18 Wheels Check Torques		
34 Emergency Lights	Damage to N/S/R upper corner lens MONITOR	Monitoring
45 Engine 1	Engine EML, NO LOP NO FAULT FOUND	
55 Tail Lift	slow down inop and lights on SEE NOTES	Lack of Labour
56 Comms Equipment	other Airwave aerial missing from roof of vehicle NOFAULT FOUND	
71 Body Exterior 1	O/S upper front corner damaged O/S rear wheel arch damaged MONITOR	Monitoring
85 Body Interior 1	centre console surround cracked REPLACED	
87 Chairs	carry chair bracket cracked PARTS ORDERED	Awaiting Parts
89 Seatbelts	O/SF seat belt U/S REPLACED	
89 Seats	rear swivel seat locking mech loose REPAIRED	
Safety Inspection		

MOT Pre Test

Vehicle Deep Clean	18/09/2018	10:21	18/09/2018	13:57	178,115	Exeter	EX020898
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	22/09/2018	10:33	25/09/2018	14:27	178,419	Exeter	EX020915
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

43 Exhaust System 1	carry out dpf clean and road test and regen
43 Exhaust System 2	wont teach in due to temp sensor failed teach in repeat regen and road test
Breakdown	EML AND BURNING FROM ENGINE

Unplanned Repair	26/09/2018	14:20	26/09/2018	14:22	178,661	Exeter	EX020938
-------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Assembly 1	voice warning going off due to temperture	Monitoring
-------------------	---	------------

Unplanned Repair	01/10/2018	13:30	01/10/2018	13:54	179,646	Exeter	EX020966
-------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

86 Door Lock	voice warning going off at speed found lock insecure replaced screws
--------------	--

Breakdown	01/10/2018	17:39	01/10/2018	19:00	179,000	Exeter	EX020968
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	flat tyre n/s front; rim damaged as well
-----------	--

Breakdown	03/10/2018	09:42	03/10/2018	13:32	179,967	Exeter	EX020996
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

56 Comms Equipment	aireal missing on roof, aireal replaced
86 Sliding Door	sliding door not sliding back fully, marker pen stuck in runer, pen removed
87 - Stretchers/Chairs/Boards	chair removed by crew, chair replaced
Breakdown	side door u/s
Supply Sat Nav	sat no low battery screen warning, PCE

BREAKDOWN	16/10/2018	08:37	16/10/2018	08:48	181,558	Exeter	EX021072
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

31 Battery Aux	Battery/Charging Sys MDT SLOW battery ok
56 Comms Equipment	MDT Failure/Issue MDT not connecting to satnav unable to upgrade
86 Doors	Body Exterior SD VOICE KEEPS GOING.removed adjusted and replaced cover

Breakdown	19/10/2018	19:18	22/10/2018	08:13	182,128	Exeter	EX021108
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Mirrors	replaced mirror glass at exeter stn
Breakdown	N/S mirror glass cracked

SAFETY INSPECTION	29/10/2018	08:43	31/10/2018	12:42	183,448	Exeter	EX021149
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Ass Fire Extinguisher	both fire extinguishers out of date NO STOCK
02 Cab Assembly 1	voice warning going off due to temperture PARTS ORDERED 30.10.18 JD
02 Windscreen Wipers	Fornt wiper not clearing screen
16 Suspension 1	N/S lower ball joint lift measured 1.5mm REPLACED
16 Suspension 2	Play in both front struts MONITOR
16 Suspension 3	N/S/R spring eye bush low in saddle REPLACED N/S and O/S
17 Tyres Replace	O/S/R inner tyre worn 3mm REPLACED
17 Tyres Tracking	Tracked after suspenion defects
18 Wheels	Wheel replaced pitted
18 Wheels Check Torques	
34 Emergency Lights	Damage to N/S/R upper corner lens MONITOR
43 Exhaust System 1	Exhaust manifold bolt loose
45 Engine 1	N/S engine mount split
55 Tail Lift	slow down inop and lights on SEE NOTES
71 Body Exterior 1	O/S upper front corner damaged O/S rear wheel arch damaged MONITOR
71 Body Exterior 2	O/S/R lower corner damage sharpe edges, Fornt bumper step damaged REPLACED
71 Body External Steps	Step mud flap torn REPLACED
85 Body Interior 1	Torch missing REPLACED
87 Chairs	carry chair bracket cracked PARTS ORDERED
Safety Inspection	
Sealing of stretcher clamp	Sealing of stretcher clamp
Travel Time	
MOT	

Vehicle Deep Clean	30/10/2018	11:45	30/10/2018	13:57	183,448	Exeter	EX021158
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Wash Vehicle	31/10/2018	07:30	31/10/2018	14:50	183,448	Exeter	EX021165
---------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Wash Vehicle	
--------------	--

Unplanned Repair	12/11/2018	13:00	12/11/2018	13:45	185,299	Exeter	EX021238
56 Comms Equipment	no power to sat nav remove check power refit connector in rear						
BREAKDOWN	19/11/2018	08:24	19/11/2018	10:58	186,075	Exeter	EX021281
31 Battery Comms 56 Comms Equipment	Tested battery passed MDT screen not powering on						
Breakdown	25/11/2018	11:58	26/11/2018	09:30	186,783	Exeter	EX021324
Breakdown MDT Failure/Issue	Serial External power failure replaced missing aerial checked power source and battery						
Vehicle Deep Clean	10/12/2018	07:20	10/12/2018	14:03	188,640	Exeter	EX021421
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/12/2018	11:52	12/12/2018	14:21	188,640	Exeter	EX021424
02 Cab Ass Fire Extinguisher	Fire trace disconnected, both F/E Out ser date						
13 Brake Pads	Rear pads low REPLACED						
16 Suspension 1	O/S slipper pads split						
18 Wheels Check Torques							
34 Emergency Lights	Water ingress into O/S scene light						Monitoring
34 Lighting System	Large crease in N/S/R top blue light						
34 Lights	Incorrect main beam pattern N/S						
45 Engine 1	Oil over engine, DIP STICK LEFT OUT						
45 Engine 2	Rattle from timing chain when engine started from cold						
45 Engine 3	Oil leak from boost silencer seal						
56 Comms Equipment	Other sat nav not working						
71 Body Exterior 1	Accident damage around vehicle SEE NOTES						
71 Body External Steps	Side step not dplying						
85 Body Interior 1	Centre console cabinet unable to lock REPAIRED LOCK AND ADJUSTED						
85 Body Interior 2	Track cupboard door stop pulled from frame						
85 Body Interior 3	Clock symbols very dim FITTED NEW						

86 Door Lock	Unable to override rear door lock C/L	REPLACED COMPLETE LOCK SET
Safety Inspection		
93 - D Service		
Service D		
Tail Lift 6 Monthly Inspection	Statutory Inspection	
Tail Lift Annual Service	Statutory Inspection and Weight Test	
UB Fire Suppression Service	NEW UNIT FITTED	

Unplanned Repair	03/01/2019	10:46	03/01/2019	10:48	191,757	Exeter	EX021554
-------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Mirrors	smashed n/s mirror surround, various parts replaced.
------------	--

Breakdown	18/01/2019	09:51	11/02/2019	08:28	193,987	Exeter	EX021654
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

41 Turbo	veins starting to crack up
43 Exhaust System 1	egr bolt missing causing high pitched whistle
Breakdown	Gone into limp mode

SAFETY INSPECTION	11/02/2019	08:28	12/02/2019	08:23	194,039	Exeter	EX021809
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

18 Wheels Check Torques	
34 Emergency Lights	Water ingress into O/S scene light
34 Lights	o/s/f fog light unit insecure, temp repair carried out, unit ordered
road test	extended road test to bed in brakes
Safety Inspection	
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab

Vehicle Deep Clean	11/02/2019	08:00	11/02/2019	10:55	194,039	Exeter	EX021810
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	28/02/2019	17:19	01/03/2019	07:50	196,100	Exeter	EX021947
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	R/N/S OUTER.
-----------	--------------

Vehicle Deep Clean	05/03/2019	07:15	05/03/2019	10:43	197,552	Exeter	EX021962
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/03/2019	06:00	07/03/2019	08:10	197,564	Exeter	EX021971
02 Cab Ass Fire Extinguisher	Fire suppression alarm going off. sensor cleaned out, fault rectified						
18 Wheels	N/S/R Wheel nut markers missing.re check torques replace markers						
18 Wheels Check Torques							
43 Exhaust System 1	Exhaust tail pipe erroded. tail pipe replaced						
55 Tail Lift	side to side play in hand rails, resecure and adust stops.						
71 Body Exterior 1	SEE NOTES X 3 FAULTS						
85 Body Interior 1	Bio strap broken, strap replaced						
86 Door Seals	N/S/F door seal ripped, door seal replaced						
MDT Failure/Issue	MDT braket insecure, replace missing screws						
Safety Inspection							
Breakdown	05/04/2019	11:11	05/04/2019	13:32	201,709	Exeter	EX022167
86 Door Hinges	Top roller bolt snapped, REPAIRED SEE NOTES						
Breakdown	Side door off hinge						
SAFETY INSPECTION	15/04/2019	08:37	15/04/2019	14:37	203,417	Exeter	EX022215
02 Cab Assembly 1	cab light inop. cab light bulb replaced						
17 Tyres Replace	o/s/f tyre scrubbing out on inner edge, tyre replaced						
18 Wheels Check Torques							
45 Engine 1	oil leak from turbo silencer, remove clean and prpoerly refit turbo silencer						
Safety Inspection							
Axle Oil Change	Change oil of Axle						
Replace Handbrake Cables	Replace Handbrake Cables						
Vehicle Deep Clean	16/04/2019	12:22	16/04/2019	14:33	203,419	Exeter	EX022240
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	22/04/2019	06:41	22/04/2019	07:26	204,040	Exeter	EX022258
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	fire suppression warning on, make up bypass plug, new system to be ordered					Partially Completed
-----------	--	--	--	--	--	---------------------

Breakdown	29/04/2019	18:43	30/04/2019	09:53	204,040	Exeter	EX022314
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

86 Door handle	Side door handle snapped REPLACED Drill out screw for cover					
86 Doors Rear	Rear door stay snapped off, REPLACED Drill old unit out					
Breakdown	BACK DOOR ROD SNAPPED OFF SIDE DOOR NOT OPENING					

Breakdown	14/05/2019	06:59	14/05/2019	11:09	206,947	Exeter	EX022418
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	50p size chip in drivers line of sight					
-----------	--	--	--	--	--	--

Breakdown	16/05/2019	09:43	07/06/2019	08:37	207,070	Exeter	EX022456
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

45 Engine 1	excessive oil around turbo enging wont crank or move with bar					
Breakdown	Engine failure excessive oil around turbo SEIZED ENGINE					

Vehicle Deep Clean	07/06/2019	09:28	07/06/2019	13:29	207,121	Exeter	EX022600
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean					
--------------------	--------------------	--	--	--	--	--

SAFETY INSPECTION	10/06/2019	07:28	12/06/2019	15:00	207,121	Exeter	EX022607
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

15 Steering 1	Power steering hoses damp MONITOR					
16 Suspension 1	Slight play in O/S/F shock MONITOR					
17 Tyres Replace	O/S/R inner flat, N/S/F tyre worn 3mm REPLACED					
18 Wheels Check Torques						
34 Emergency Lights	Slaight damage to both rear top coner lights MONITOR					
34 Lighting System	O/S secne cracked water ingress					
54 Warn Dev/System	N/S camera above side door water ingress REPAIREd					
55 Tail Lift	Wheel wedge seized STRIPPED FREED CLEANED REPAIRED					
56 Comms Fitment	Saloon mic missing PARTS Ordered					Awaiting Parts

71 Body Exterior 1	Bridge plate guides pulled from body	REPAIRED
71 Body External Steps	Step U/S, Mud flap torn	REPLACED
85 Body Interior 2	White board insecure	REPAIRED
86 Doors Rear	O/S/R door stay pulled from mounting	REPLACED
Breakdown	fire suppression warning on, make up bypass plug, new system to be ordered	
Safety Inspection		
Engine Change Oil & Filter	LINKED ONLY ENGINE REPLACED	
Tail Lift Inspection		

Breakdown	19/06/2019	13:34	19/06/2019	14:30	208,147	Exeter	EX022683
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	N/S/F Grill Light Blue Broken	Awaiting Parts
-----------	-------------------------------	----------------

Unplanned Repair	24/06/2019	07:00	24/06/2019	09:54	208,156	Exeter	EX022700
-------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Ass Fire Extinguisher	Other fire suppressant warning pressure ok on gauge slightly down	and NFF
34 Emergency Light System	replaced inop nsf grill oval blue lamp assy and replaced plug	

Breakdown	02/07/2019	00:05	02/07/2019	09:05	209,247	Exeter	EX022751
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	Red fire suppressant light on	REPAIRED SEE NOTES
-----------	-------------------------------	--------------------

Vehicle Deep Clean	08/07/2019	08:10	08/07/2019	13:57	210,375	Exeter	EX022802
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	09/07/2019	09:31	09/07/2019	14:36	210,415	Exeter	EX022817
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Assembly 1	cab center console ram insecure, resecure	
16 Suspension 1	Rear lower anti roll bar bushes worn	
18 Wheels Check Torques		
44 Fuel System 1	fuel filter clip not holding, clip replaced	
52 Electrical Aux	Emg Warning Devices Fire Suppressant System warning, clean sensor	
56 Comms Fitment	Saloon mic missing, mic replaced	Parts ordered in store
Breakdown	N/S/F Grill Light Blue Broken, already rectified	

MDT Failure/Issue Safety Inspection	MDT screen blurry, PCE DEALING						
Unplanned Repair	02/08/2019	14:17	02/08/2019	14:21	214,505	Exeter	EX023016
02 Mirrors	N/S door mirrors damaged - replaced mirror glass top and bottom						
Defect Repair	06/08/2019	06:56	06/08/2019	11:24	214,505	Exeter	EX023025
31 Battery Chassis 45 Engine 1 Road Test	Replaced Emg Warning Devices Amber EML SEE NOTES Extended road test,						
Vehicle Deep Clean	20/08/2019	07:30	20/08/2019	11:10	217,804	Exeter	EX023133
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/08/2019	11:21	21/08/2019	14:57	217,804	Exeter	EX023134
01 Heating 1 13 Brakes 1 18 Wheels Check Torques 45 Engine 1 56 Comms Fitment 71 Body Exterior 1 85 Body Interior 1 Safety Inspection Annual Air Con Service Annual Heater Service Tail Lift Inspection	heater exhaust split.exhaust replaced Hand brake travel to high, adjust shoes and cable brive belt tensioner weaping/leaking Saloon mic missing, mic replaced bridge plate guide insecure, resecure and repair bag storage bio strap broken,bio atrap replaced Annual Air Condition Service, see notes for fault Annual Heater Service						
Breakdown	11/09/2019	11:16	12/09/2019	14:22	221,173	Exeter	EX023331
32 Starting System 1 Breakdown	Vehicle not starting SEE NOTES Will Not Start						

Unplanned Repair	18/10/2019	10:55	18/10/2019	11:03	222,173	Exeter	EX023682
-------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Mirrors	mirror glass broken, mirror glass replaced
15 Steering 1	reports of heavy steering, no loss of fluid or leaks, road tested fine, no fault
42 Coolant System	coolant level low, no leaks found topped up with fluid

SAFETY INSPECTION	21/10/2019	12:11	25/10/2019	14:27	222,173	Exeter	EX023691
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

13 Brake Pads	All brake pads worn REPLACED	
13 Brake Test		
13 Discs	All disks worn REPLACED	
16 Suspension 1	N.S.F spring slipper starting to split MONITOR	Monitoring
16 Suspension 2	O.S.R Shock absorber weeping MONITOR	Monitoring
17 Tyres Replace	N.S.R tyres on 3 mm REPLACED	
18 Wheels Check Torques		
52 Electrical Aux	O/S/F window switch damaged REPLACED	
71 Body Exterior 1	Step mudflap starting to tear MONITOR	Monitoring
Check Vehicle Call Signs	Remove and fit new call signs 3804	
Safety Inspection		
Pollen Filter Change	Pollen Filter Change	
Fuel Filter Change	Change Fuel Filter	
Air Filter Change	Air Filter Change	
MOT		

SAFETY INSPECTION	07/11/2019	13:09	08/11/2019	11:36	222,464	Exeter	EX023870
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Ass Fire Extinguisher	2 X fire extinguishers O.O.D, replaced
02 Mirrors	drivers side mirror insecure, repaired and resecured
16 Suspension 1	spring slippers x 2 u/s n/s/r, replace both spring slippers
18 Wheels Check Torques	
45 Engine 1	pollen filter missing, pollen filter replaced
55 Tail Lift	o/s/r tail lift hand rail inop, south west lifts repaired
71 Body Exterior 1	insecure rear spray suppressor, rescrew loose bolts
71 Body Exterior 2	document holder starting to brake away, glue and screw back together
71 Body External Steps	split step mud flap, replace mud flap, seized bolts cut off, new fitted
85 Body Interior 1	insecure rear seat arm rest, repair and resecure

Safety Inspection
 UB Fire Supp 6mts Service UB Fire Supp 6mts Service
 Brakes Replace Brake Fluid
 Tail Lift Inspection
 Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight, carried out by south west lifts

Vehicle Deep Clean **08/11/2019** **08:39** **08/11/2019** **08:40** **222,464** **Exeter** **EX023873**

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean **08/11/2019** **08:41** **08/11/2019** **14:36** **222,464** **Exeter** **EX023874**

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN **05/12/2019** **11:00** **05/12/2019** **13:53** **224,605** **Exeter** **EX024089**

42 Coolant System Other coolant level warning light REPLACED EXPANSION BOTTLE

Breakdown **11/12/2019** **09:19** **11/12/2019** **10:58** **225,874** **Exeter** **EX024135**

31 Battery Comms Breakdown checked battery all ok advised contact logistics and inform PCE
 MDT Screen Freezing/Battery Check

Breakdown **18/12/2019** **11:58** **19/12/2019** **07:15** **227,493** **Exeter** **EX024200**

55 Tail Lift Breakdown Taunton rectified
 tail lift audio warning on

Vehicle Deep Clean **27/12/2019** **10:00** **31/12/2019** **10:20** **229,247** **Exeter** **EX024262**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **27/12/2019** **11:15** **30/12/2019** **13:46** **229,247** **Exeter** **EX024265**

13 Handbrake brakes require adjusting, adjust brakes

17 Tyres Replace	o/s/r/o tyre has a screw in it plus wheel cracked, tyre replaced
17 Tyres Tracking	tracking out, adjust tracking
18 Wheels Check Torques	
32 Starting System 1	starting fault key fob, self rectified, no fault found
34 Lighting System	blue light control panel not fully illuminating, MONITOR
71 Body Exterior 1	insecure spray surpressor, RESECURE
71 Body External Steps	side step noisy under operation, clean and lubricate
85 Body Interior 1	saloon clock insecure, RESECURE
Road Test	extended road test,
Safety Inspection	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change

Breakdown	02/01/2020	08:11	03/01/2020	11:34	229,521	Exeter	EX024293
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

13 Brakes 1	ESP warning light on
Breakdown	amber ESP warning light on, see notes

Breakdown	29/01/2020	17:09	04/02/2020	14:55	234,070	Exeter	EX024553
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

13 Brakes 1	squeal as stopping
15 Steering 1	reported to be heavy
45 Engine 2	smell in cab bulkhead grommet split replaced.
45 Engine Oil Top Up	intermittent level light on
Breakdown	oil waring light, solid power steering.smell in cab (replaced bulkhead grommet)

SAFETY INSPECTION	03/02/2020	07:21	03/02/2020	13:14	234,070	Exeter	EX024577
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

13 Brakes 1	Hnad brake travel high, adjust cable.	
18 Wheels Check Torques		
34 Lights	o/s side light inop, bulb replaced	
55 Tail Lift	tail lift o/s amber light inop, light unit replaced	
71 Body Exterior 1	front ambulance plastic cab screen cover split, MONITOR	Monitoring
86 Sliding Door	sliding door top pin female broken, female repalced	
Safety Inspection		
Engine Change Oil & Filter		
Tail Lift Inspection		

Vehicle Deep Clean	03/02/2020	10:48	04/02/2020	09:27	234,070	Exeter	EX024589
--------------------	------------	-------	------------	-------	---------	--------	----------

BREAKDOWN	13/02/2020	07:11	19/02/2020	12:10	234,970	Exeter	EX024708
-----------	------------	-------	------------	-------	---------	--------	----------

Vehicle Deep Clean	18/03/2020	11:00	18/03/2020	13:22	240,710	Exeter	EX024995
--------------------	------------	-------	------------	-------	---------	--------	----------

SAFETY INSPECTION	20/03/2020	10:55	24/03/2020	08:25	240,710	Exeter	EX025013
-------------------	------------	-------	------------	-------	---------	--------	----------

Breakdown	03/04/2020	12:19	03/04/2020	15:24	242,233	Exeter	EX025141
-----------	------------	-------	------------	-------	---------	--------	----------

Unplanned Repair	03/04/2020	14:49	03/04/2020	14:51	242,285	Exeter	EX025143
34 Lights	Headlight bulb inop - REPLACED BULB						
Unplanned Repair	15/04/2020	15:39	15/04/2020	15:41	243,610	Exeter	EX025279
55 Tail Lift	O/S handrail pulled off - refit and adjust						
Vehicle Deep Clean	27/04/2020	07:45	27/04/2020	13:39	245,289	Exeter	EX025422
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/04/2020	15:50	28/04/2020	14:31	245,289	Exeter	EX025432
01 Air Conditioning 1	Saloon condensor fan noisy, frame work rusted MONITOR						
18 Wheels Check Torques							
34 Lights	see notes						
71 Body Exterior 1	front ambulance plastic cab screen cover split, MONITOR						
85 Body Interior 1	Drugs cupboard screws pulled from hinge - replace screws						
85 Body Interior 2	Roof blind pulled from runners - removed and parts ordered						Awaiting Parts
86 Door Seals	door seal bottom rear o/s u/s, door seal cleaned out and replaced						
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
UB Fire Supp 12mts Service	Service of fire supression system						
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge - awaitng jacktone						Awaiting Parts
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Tail Lift Inspection	SEE NOTES						
Breakdown	07/06/2020	20:32	08/06/2020	08:49	251,435	Exeter	EX025762
Breakdown	washers stopped working						Monitoring
SAFETY INSPECTION	08/06/2020	08:49	09/06/2020	13:00	251,504	Exeter	EX025764
17 Tyres Replace	N/S/R inner worn 3mm REPLACED						
18 Wheels Check Torques							

43 Exhaust System 1	Mounting loose REPAIRED						
52 Electrical Aux	Torch dim when battery changed and not charging REPLACED						
55 Tail Lift	N/S hand rail worn on guide brg Parts ordered JD 09-06-20					Awaiting Parts	
71 Body Exterior 1	Autoeje3ct cover damaged REPLACED						
85 Body Interior 2	Roof blind pulled from runners - removed and parts ordered					Monitoring	
86 Door Lock	Side door not catching on second catch REPAIRED						
86 Doors Rear	Doors rear door stay broken						
Breakdown	washers stopped working						
Safety Inspection							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge - awaitng jacktone					Monitoring	
Vehicle Deep Clean	09/06/2020	07:20	09/06/2020	13:51	251,435	Exeter	EX025773
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	03/07/2020	17:55	04/07/2020	15:00	251,504	Exeter	EX026061
15 Steering 1	power steerin fault ? reported M/B attending						
BREAKDOWN	06/07/2020	09:05	06/07/2020	09:32	251,990	Exeter	EX026069
15 Steering 1	Steering power steering faulty? REPAIRED BY MERC EXETER						
86 Door Lock	Doors verbal warning for doors when the door is closed, REPAIRED						
SAFETY INSPECTION	22/07/2020	07:55	22/07/2020	15:06	258,784	Exeter	EX026194
13 Brake Pads	Rear pads worn - REPLACED						
17 Tyres Replace	Rear outter tyres worn to 3mm - swap worn tyres to N/S/R and fit news to O/S/R						
18 Wheels Check Torques							
34 Emergency Lights	N/S/R blue light corner lens damaged - repair light plate and replace lens						
45 Engine 1	Oil leak from aux tentioner area						
55 Ramp	hand rails insecure, bridge plate guides loose, resecure compoments						
Safety Inspection							
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card					Awaiting Parts	
Engine Change Oil & Filter							
Tail Lift Inspection							

Vehicle Deep Clean	23/07/2020	07:38	23/07/2020	07:41	258,789	Exeter	EX026201
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Replace Vehicle Fuel Card Vehicle Deep Clean	Replace Vehicle Fuel Card Vehicle Deep Clean
---	---

Breakdown	07/08/2020	19:13	10/08/2020	07:58	261,244	Exeter	EX026348
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown Road Test	CRACKED WHEEL RIM, dented wheel and holed tyre rep;laced
------------------------	--

BREAKDOWN	14/08/2020	07:00	14/08/2020	14:31	261,555	Exeter	EX026400
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

34 Lighting System 44 Fuel System 1 56 Radio	REPLACED DAMAGED O/S FOG LAMP LEVEL FULL GAUGE LOW REPLACED ADBLUE TANK CAB MUSIC RADIO INOP	Awaiting Parts
--	--	----------------

Unplanned Repair	17/08/2020	12:29	17/08/2020	12:33	261,600	Exeter	EX026417
-------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

33 Ignition System 86 Door Lock	key fob replaced Replace key fob
------------------------------------	-------------------------------------

SAFETY INSPECTION	07/09/2020	08:13	08/09/2020	07:16	264,740	Exeter	EX026587
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

01 Heating 1 13 Brake Test 16 Suspension 1 16 Suspension 2 18 Wheels Check Torques 44 Fuel System 1 56 Radio 85 Body Interior 1 85 Body Interior 2 87a - Medical Equipment Repair Road Test Safety Inspection	Blower inop - REPLACED N/S/R Spring slipper split REPLACED Rear ARBs worn REPLACED ~Fit solo fuel cap CAB MUSIC RADIO INOP - RECTIFIED CCTV gas strut wont hold - REPLACED Phone holder damaged - REMOVED Oxygen valve cracked - REPLACED BY KB
--	--

Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service - 271g off R134a gas used

Breakdown	13/09/2020	17:33	14/09/2020	15:30	265,513	Exeter	EX026648
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Assembly 1	Other Fumes in cab, N.F.F.
02 Windows/Glass	Washer jets inop, repaired split pipe.
02 Windscreen Wipers	Other Washer jets blocked, repaired.
Breakdown	EML light on and Add Blue Light, N.F.F.

ACCIDENT	03/10/2020	18:26	09/10/2020	13:55	269,543	Exeter	EX026890
-----------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

45 Engine 1	removed DPF sensor failed REPALCED also pressure hose replaced split on remova	Awaiting Parts
71 Body Exterior 1	GLASS O/S SALOON OUTER CREACKED REPLACED BY NMW	
71 Body Exterior Acc Repair	nsr top corner damage and nsf wing and bumper damager unable to open door fully	Awaiting Body Repair
Breakdown	N/S rear blue Knocked off AUTOSPRAY REPLACED	

SAFETY INSPECTION	15/10/2020	08:32	16/10/2020	14:33	270,279	Exeter	EX026983
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Ass Fire Extinguisher	Both extinguishers replaced with new in date canisters	
13 Brake Pads	Front pads worn - Replaced pads and check disk thickness- serviceable	
16 Suspension 1	N/S/F Strut has play and a split dust boo, Replace strut unit and adjust camber	
17 Tyres Replace	Both front tyres worn on outter edges - Replaced front tyres and tracked vehicle	
17 Tyres Tracking	Track vehicle and adjust camber after strut replacement and tyre wear	
18 Wheels Check Torques		
45 Engine 1	Oil leak - Cleaned engine off and road test + Tentioneer worn - replaced tentione	
55 Tail Lift	Lift hose split to cords SWL REPLACED FORM SWAST STOCK	
71 Body Exterior 1	Rear spray supressor insecure due to crack in mount - temp repair with new screw	
71 Body Exterior 2	O/S/F Fog surround missing - Unable to order - Cannot contact merc	Awaiting Parts
71 Body Exterior Acc Repair	nsr top corner damage and nsf wing and bumper damage - Repaired previously	
71 Body External Steps	Side step mudflap torn - REPLACED mudflap with new unit	
85 Body Interior 1	SEE NOTES	Awaiting Parts
85 Body Interior Roof	Roof blind damaged and no longer useable - New unit required	Monitoring
87 Med Handling Equip Inspect	ECPR charging cradle damaged at base - New unit fitted NON STOCK	
87 Stretcher	Spare stryker battery missing - new unit fitted Y192720	
Safety Inspection		
Air Filter Change	Air Filter Change	

Fuel Filter Change	Change Fuel Filter						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service -Requires jacktone replacement - Awaiting parts						Awaiting Parts
Tail Lift Inspection							
Pollen Filter Change	Pollen Filter Change						
MOT							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight - Carried out by Harvey SWL						
Engine Change Oil & Filter							

Vehicle Deep Clean	17/11/2020	13:00	17/11/2020	14:30	276,746	Exeter	EX027293
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	26/11/2020	09:42	27/11/2020	14:46	278,280	Exeter	EX027365
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

01 Air Conditioning 1	A/C in cab not operating - check system - low on gas - Charged with 800g r134a						
02 Cab Ass Fire Extinguisher	Saloon fire extinguisher expired - REPLACED						
13 Brakes 1	rear brake shoes and discs and pads worn ---- Replaced						
13 Handbrake	Adjust travel post road test						
17 Tyres	O/S/R/I tyre low on air - check for leaks or punctures - non found						
18 Wheels Check Torques							
34 Emergency Lights	O/S/R Blue corner light damages - holed on bottom of unit - MONITOR						Monitoring
34 Lights	N/S/R fog light LEDs below 50% REPLACED						
45 Engine 1	Engine oil leak - possible sump gasket CLEAN and road test MONITOR						Monitoring
71 Body Exterior 2	O/S/F Fog surround missing REPLACED						
71 Body External Steps	Step sticking on deployment - lube and work - operating smoothly						
85 Body Interior 1	SEE NOTES						
85 Body Interior Roof	Roof blind damaged and no longer useable - New unit required						
Road Test	Extended road test to bed in new brakes						
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service -Requires jacktone replacement - Awaiting parts						Awaiting Parts

BREAKDOWN	10/12/2020	11:45	10/12/2020	12:28	280,420	Exeter	EX027500
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

71 Body External Steps	side step inop, clean off mud and replace faulty deployment ram						
------------------------	---	--	--	--	--	--	--

Breakdown	23/12/2020	12:27	23/12/2020	15:30	282,885	Exeter	EX027636
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	Off rear inner tyre flat
-----------	--------------------------

Breakdown	23/12/2020	15:32	24/12/2020	11:34	282,885	Exeter	EX027639
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

17 Tyres Replace	REPLACED O/S/R/O + N/S/R TYRES WITH DIRECTIONALS
18 Wheels	O/S/R/O Rim cracked - REPLACED WITH NEW RIM
Breakdown	ATS say rim cracked, can change
Road Test	

SAFETY INSPECTION	11/01/2021	07:24	11/01/2021	15:00	285,683	Exeter	EX027777
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

16 Suspension 1	remove osf strut and replaced missing boot	
18 Wheels Check Torques		
34 Emergency Light System	torch missing REPLACED	
34 Emergency Lights	O/S/R Blue corner light damages - holed on bottom of unit - MONITOR bck ordered	Awaiting Parts
43 Exhaust System 1	DPF brcket insecure resure and reposition	
45 Engine 1	Engine oil leak - possible sump gasket CLEAN and road test MONITOR	Monitoring
55 Tail Lift	refit os handrail	
86 Doors	replaced sliding door lower magnet	
Safety Inspection		
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service -Requires jacktone replacement - Awaiting parts	Awaiting Parts
Tail Lift Inspection		

Vehicle Deep Clean	12/01/2021	07:14	12/01/2021	10:57	285,683	Exeter	EX027790
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	06/02/2021	17:57	08/02/2021	08:21	289,216	Exeter	EX028007
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Breakdown	nearside mirror casing slightly damaged OPERATIONAL	Monitoring
-----------	---	------------

BREAKDOWN	09/02/2021	13:05	09/02/2021	14:08	289,521	Exeter	EX028037
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

01 Heating 1	heater inop REPAIRED BLOWER MOTOR U/S
02 Mirrors	Back and surround damaged - replaced

Vehicle Deep Clean	15/02/2021	07:20	15/02/2021	09:54	290,213	Exeter	EX028073
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/02/2021	07:36	18/02/2021	14:29	290,442	Exeter	EX028100
02 Mirrors	N/S mirror back and frame damaged - REPLACED						
16 Suspension 1	O/S/R Spring slipper split - REPLACED						
18 Wheels Check Torques							
34 Emergency Lights	O/S/R Blue corner light damages - holed on bottom of unit - MONITOR bck ordered					Awaiting Parts	
42 Coolant System	Rad slightly insecure - Secure rad						
45 Engine 1	Engine oil leak from gasket - Remove sump, Remove old sealant and renew sealant						
45 Engine 2	Engine O/S mount split - and tensioner REPLACED						
55 Tail Lift	Tail lift multiple defects SEE NOTES						
Breakdown	nearside mirror casing damaged - REPLACED						
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service -Requires jacktone replacement - Awaiting parts					Awaiting Parts	
Engine Change Oil & Filter							
Unplanned Repair	16/03/2021	09:00	16/03/2021	09:31	295,012	Exeter	EX028321
34 Lights Bulb Replacement	N/S/F headlamp bulb inop REPLACED						
86 Door Lock	Central locking inop - Key fob battery flat REPLACED						
Breakdown	16/03/2021	19:18	18/03/2021	08:46	295,154	Exeter	EX028332
45 Engine 1	EML on spoke to driver 18/02/21 reported no EML last 2 days, not active						
Breakdown	nearside dip beam out, recurring issue, finger print on bulb, bulb repalced						
Breakdown	16/03/2021	19:19	17/03/2021	08:09	295,154	Exeter	EX028333
Breakdown	nearside dip beam out, recurring issue, linked to EX028332					Monitoring	
SAFETY INSPECTION	31/03/2021	08:23	01/04/2021	11:51	297,008	Exeter	EX028465
02 Cab Assembly 1	SEE NOTES FOR FAULTS						

16 Suspension 1	spring slippers front of rear springs split.
18 Wheels Check Torques	
27 Transmission Automatic	prop center bearing braking up. center bearing replaced
45 Engine 1	SEE NOTES FOR FAULTS
71 Body Exterior 1	SEE NOTES FOR FAULTS
Road Test	
Safety Inspection	
Tail Lift Inspection	SEE NOTES FOR FAULTS
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service, Awaiting jactone replacement.
Replace Handbrake Cables	Replace Handbrake Cables

Vehicle Deep Clean	31/03/2021	09:41	01/04/2021	13:24	297,008	Exeter	EX028467
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	13/04/2021	09:09	13/04/2021	14:00	299,091	Exeter	EX028639
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

55 Tail Lift	UNABLE TO RAISE LIFT OFF GROUND swl ATTENDED REPLACED MOTOR
--------------	---

BREAKDOWN	22/04/2021	07:30	22/04/2021	11:35	300,327	Exeter	EX028643
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

45 Engine 1	Engine Amber engine light on, SEE NOTES
-------------	---

SAFETY INSPECTION	11/05/2021	08:34	12/05/2021	12:59	304,256	Exeter	EX028787
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

13 Handbrake	handbrake travel high adjusted by Jules	
17 Tyres Replace	O/S/R/O tyre punctured	
18 Wheels Check Torques		
34 Emergency Lights	O/S/R Corner blue light holed at back and taped monitor	Monitoring
45 Engine 1	Engine oil leak from dipstick tube replaced seal in sump	
56 Comms Fitment	replaced damaged mic and cover rear of saloon	
86 Door Seals	rear door bottom seal damaged - no stock	Monitoring
87 Stretcher	Stretcher spare battery wont charge - REPLACED Y192743	
Safety Inspection		
Throttle Pedal Check	Throttle Pedal Check insecure secured bolts	
UB Fire Supp 12mts Service	Service of fire supression system	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change	

Vehicle Deep Clean	12/05/2021	11:10	13/05/2021	14:31	304,260	Exeter	EX028798
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	13/05/2021	21:49	18/05/2021	10:29	304,345	Exeter	EX028806
45 Engine 1	engine oil temperature sensor incorrect signal - SEE NOTES					Awaiting Parts	
45 Engine 2	sent to dealer confirmed oil temp sensor, advised part of level sensor which we						
Breakdown	red EML on						
02 Pipeline Annual Inspection	03/06/2021	10:34	03/06/2021	10:37	306,106	MDT Taunton	TT001217
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
Vehicle Deep Clean	02/07/2021	09:38	02/07/2021	14:00	306,371	St Leonards	SL033671
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/07/2021	09:00	16/07/2021	08:00	306,371	St Leonards	SL033699
01 Air Conditioning 1	Clean out intake box. Replace contaminanted Filter.					Monitoring	
01 Air Conditioning 2	Fan motor u/s above rear axle - Paul Dunford (Espar) to repair						
02 Windscreen Wipers	Replace worn out wipers.						
13 Brake Test	Telma broken up. Replaced						
13 Brakes 1	Replace worn out peddle rubber.						
13 Brakes 2	Replace F/Disc & Pads.						
15 Steering 1	Replace both Drag link ends.						
16 Suspension 1	Replace both F/Lower arms. Worn out. 6mm play.						
16 Suspension 2	Replace both F/Struts Play in O/S.						
17 Tyres	Replace both F/Tyres. Due to incorrect Trak						
18 Wheels Check Torques	Done						
34 Emergency Lights	O/S/R Corner blue light holed at back and taped monitor						
44 Add Ad Blue	Top up unit 16L. Replace damaged cap						
45 Engine 1	engine oil temperature sensor incorrect signal - SEE NOTES. E.C.U connection.						
86 Door Seals	rear door bottom seal damaged - no stock						
Safety Inspection	Done.						

Wheel Hub Flanges ReplacemeReplace F/Flanges.
Tail Lift Inspection Done.

Breakdown **19/07/2021** **09:20** **20/07/2021** **09:00** **306,442** **St Leonards** **SL033841**

02 Windscreen Windscreen smashed - Mobile windscreens to replace
Breakdown cracke windscreen in places

Vehicle Deep Clean **10/08/2021** **07:25** **10/08/2021** **11:00** **308,678** **St Leonards** **SL034079**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **10/08/2021** **13:00** **12/08/2021** **15:00** **308,678** **St Leonards** **SL034091**

01 Air Conditioning 2 Fan motor u/s above rear axle - Paul Dunford (Espar) to repair
02 Windscreen Refit all screen panel work not fitted by window company
02 Windscreen Wipers Replace pipe work & One way valve
13 Brakes 1 Replace Rear Pads & Rear Calibers.
18 Wheels Check Torques Checked
34 Lights Bulb Replacement Replace F/Runing lights.
44 Add Ad Blue Top up unit 3L
52 Electrical Aux Replace damaged n/s window switch
71 Body Exterior 1 Repair Bonnet
85 Body Interior 1 Replace F/Flooring.
86 Door Lock Lube all locks Replace battery lock
Safety Inspection Checked
Wheel Hub Flanges ReplacemeReplace rears

Unplanned Repair **24/08/2021** **13:00** **24/08/2021** **14:00** **310,049** **St Leonards** **SL034201**

02 Mirrors Replace n/s mirror glass
Travel Time Travel to Wimborne

Vehicle Deep Clean **22/09/2021** **08:36** **22/09/2021** **12:30** **313,956** **St Leonards** **SL034419**

Vehicle Deep Clean		Vehicle Deep Clean					
SAFETY INSPECTION	23/09/2021	06:30	24/09/2021	10:00	313,956	St Leonards	SL034429
02 Windscreen Wipers	washer jet adrift. secured.						
18 Wheels Check Torques	Checked.						
34 Lighting System	Replace o/s headlight						
45 Engine 1	oil leak.washed & monitor.						
86 Door Lock	central locking n/w. replaced battery in key.						
Safety Inspection	Carried out inspection.						
Tail Lift Inspection	Done. Replaced LED.						
Monitoring							
SAFETY INSPECTION	27/10/2021	06:00	29/10/2021	11:00	317,248	St Leonards	SL034770
02 Cab Ass Fire Extinguisher	Out of date x2. Replaced x2.						
17 Tyres Replace	N/S/R/I&O low tread,rim's in poor condition. Replaced tyres & rim's.						
18 Wheels Check Torques	Checked.						
45 Engine 1	oil leak.washed & monitor.						
55 Tail Lift	O/S gate loose. Tightened.						
86 Doors Rear	O/S stay broken. Replaced.						
Safety Inspection	Carried out inspection.						
Annual Air Con Service	Annual Air Condition Service. Done.W.A.S side n/w.						
Annual Heater Service	Annual Heater Service. Done.						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service. Done.						
MOT	Monitoring						
Vehicle Deep Clean	28/10/2021	11:49	28/10/2021	15:00	317,248	St Leonards	SL034801
Vehicle Deep Clean		Vehicle Deep Clean					
Unplanned Repair	18/11/2021	09:00	25/11/2021	12:00	317,300	St Leonards	SL034996
31 Charging System	Battery warning light on - Merc of Exeter to repair						
45 Engine 1	Oil leak - Merc of Exeter to repair						
Breakdown	19/11/2021	06:42	19/11/2021	06:42	317,300	St Leonards	SL035006
Breakdown		workshops requested recovery					

Breakdown	04/12/2021	17:44	06/12/2021	07:16	320,450	St Leonards	SL035148
86 Sliding Door Breakdown	Outer handle broken. Replaced. Outside door handle broken						
Breakdown	07/12/2021	13:49	08/12/2021	08:00	320,481	St Leonards	SL035176
Breakdown	MDT wont turn on						
SAFETY INSPECTION	15/12/2021	14:00	16/12/2021	14:20	321,460	Dorchester	DC026598
13 Brakes 1	TELMA heatshield rubbing						
15 Steering 1	power stg reservoir pipe leaking						
16 Suspension 1	replace 1 rear slipper pads						
16 Suspension 2	replace rear ARB link bottom bushes						
18 Wheels Check Torques							
44 Add Ad Blue	top up						
45 Engine 1							
45 Engine 2	slight leak at Right side of sump						
56 Comms Equipment	microphones loose						
85 Body Interior 1	stretcherguide buffer damaged						
85 Body Interior Roof	skylight blind damaged						
Safety Inspection							
Travel Time	collect from dorchester						
Engine Change Oil & Filter							
Brake Fluid Change	Brake Fluid Change						
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
Tail Lift Inspection							
Vehicle Deep Clean	15/12/2021	07:29	15/12/2021	11:00	321,427	St Leonards	SL035233
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	01/01/2022	03:04	01/01/2022	06:00	322,552	St Leonards	SL035354
Breakdown	flat tyre rear nearside inner						
Breakdown	05/01/2022	17:28	06/01/2022	06:00	323,061	St Leonards	SL035396
Breakdown	stretcher malfunctioning						Monitoring
Unplanned Repair	14/01/2022	07:31	14/01/2022	07:33	324,249	St Leonards	SL035462
Supply Sat Nav	Sat-Nav screen frozen. Supply & fit replacment.						
Breakdown	20/01/2022	15:57	21/01/2022	06:15	324,923	St Leonards	SL035531
Breakdown	MDT NOT WORKING BUT WORKS ON ANOTHER VEHICLE						Monitoring
Unplanned Repair	25/01/2022	06:45	25/01/2022	07:00	325,781	St Leonards	SL035558
34 Lights Bulb Replacement	Replace n/s headlight bulb						
Breakdown	25/01/2022	22:30	26/01/2022	10:47	325,782	St Leonards	SL035566
13 Brakes 1	Brake warning light on						
27 Transmission Automatic	Gearbox fault?						
31 Charging System	Battery warning light on.Set uo Texa. Replaced ignition key.Road tested OK.						
34 Lights	Reported headlight fault (See log book)						
Breakdown	battery red warning/gearbox/ headlight						
SAFETY INSPECTION	02/02/2022	06:00	14/02/2022	12:30	326,819	St Leonards	SL035642
01 Heating 1	Saloon heater exhaust end cap missing. Replaced.						
02 Cab Assembly 1	Interior light n/w. Replaced bulb.						
13 Handbrake	Cable adjuster siezed. Removed,free,lubed,refitted.						

17 Tyres Replace	N/S/F &O/S/R/I low tread.Cleaned rim's & flanges, Replaced.
18 Wheels Check Torques	Checked.
34 Lighting System	O/S Scene light n/w. Repaired wiring.
42 Coolant System	Coolant leak (Radiator). Merc of Exeter
43 Exhaust System 1	Exhaust manifold studs loose and DPF flexi pipe cracked - Merc of Exeter
45 Engine 1	Engine oil leak - Merc of Exeter
54 Sirens	Bull horn int inop and siren int inop using steering wheel button
55 Tail Lift	O/S hand rail drop mech u/s,temp repaired.Roll stop flap siezed.no parts.
86 Doors Rear	Replace rear door stay mount
86 Sliding Door	Rollers siezed. Replaced.
Breakdown	MDT NOT WORKING BUT WORKS ON ANOTHER VEHICLE
Safety Inspection	Carried out inspection.
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service.NOT DONE,SYSTEM DISCONNECTED.
Pollen Filter Change	Pollen Filter Change. Done.

02 Pipeline Annual Inspection	12/02/2022	08:43	14/02/2022	08:45	326,913	MDT Ferndown	TF001784
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test
-------------------------------	-------------------------------------

Vehicle Deep Clean	14/02/2022	06:52	14/02/2022	11:00	326,913	St Leonards	SL035735
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

COMMS.FAILURE CHECK	23/02/2022	09:15	23/02/2022	09:30	327,963	St Leonards	SL035829
----------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

MDT Failure/Issue	Carry out reboot
-------------------	------------------

Breakdown	08/03/2022	09:20	08/03/2022	12:00	329,445	St Leonards	SL035933
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	R/O/S Puncture
-----------	----------------

Breakdown	19/03/2022	21:38	21/03/2022	06:00	330,491	St Leonards	SL036001
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	MDT keeps powering down; VOR						
Breakdown	20/03/2022	10:15	01/04/2022	09:00	330,524	St Leonards	SL036002
Breakdown	MDT not powering up						
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
52 Electrical Aux	CCTV inop						
45 Engine Ad Blue	Top Up						
55 Tail Lift	Hand rails siezed,						
43 Exhaust System 1	Tail pie rotted						
45 Engine 1	Major oil leak, just been repaired by dealer (back to exeter)						
Breakdown	22/03/2022	11:05	22/03/2022	11:50	330,524	St Leonards	SL036028
Breakdown	request from workshops to convey to dealership						
Vehicle Deep Clean	05/04/2022	07:57	05/04/2022	07:59	330,524	St Leonards	SL036135
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	05/04/2022	08:00	05/04/2022	11:00	330,524	St Leonards	SL036136
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	07/04/2022	17:16	08/04/2022	08:30	330,721	St Leonards	SL036165
Breakdown	Powering down						
							Monitoring
Breakdown	29/04/2022	06:10	29/04/2022	07:15	334,111	St Leonards	SL036361
Breakdown	MDT no pwer - RE set MDT, ok.						
Breakdown	30/04/2022	12:06	03/05/2022	06:30	334,295	St Leonards	SL036368
Breakdown	MDT not powering on; VOR						

Tail Lift 12M Service & Weight	10/05/2022	10:00	13/05/2022	13:00	335,032	St Leonards	SL036556
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Vehicle Deep Clean	16/05/2022	07:20	16/05/2022	10:00	335,032	St Leonards	SL036560
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	16/05/2022	13:00	16/05/2022	13:00	335,032	St Leonards	SL036572
18 Wheels Check Torques Safety Inspection							
SAFETY INSPECTION	16/05/2022	13:00	22/06/2022	15:00	335,066	St Leonards	SL036573
18 Wheels Check Torques Safety Inspection Replace Handbrake Cables 31 Battery Aux 56 Comms Power Failure 54 Sirens 45 Engine 1 17 Tyres Replace 27 Transmission Automatic 001 Recover Vehicle	Checked. Carried out inspection. Replace Handbrake Cables. Done.Removed siezed adjuster,free & refit. Test Aux battery Siren intermittantly inop. Siren switch required? Oil leak. Merc of Exeter to repair O/S/F tyre worn inner edge. Replaced. Unable to select gears - Merc of Exeter to repair Vehicle Recovery						
Breakdown	18/05/2022	06:18	18/05/2022	06:18	335,066	St Leonards	SL036587
Breakdown	OIL LEAK						
Unplanned Repair	07/07/2022	10:45	07/07/2022	11:23	336,188	St Leonards	SL037045
56 Comms Power Failure							

Vehicle Deep Clean	19/07/2022	07:23	19/07/2022	10:30	337,683	St Leonards	SL037133
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	29/07/2022	10:30	25/08/2022	15:00	337,683	St Leonards	SL037215
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
UB Fire Supp 12mts Service	Service of fire supression system
Tail Lift Inspection	Done.
45 Engine Ad Blue	AD blue warning light on
42 Coolant System	Overheating - Red coolant warning light. See Notes.
45 Engine 1	Engine oil leak. Sandown Merc to repair
55 Tail Lift	O/S gate legs loose. Flap wieght missing. Tightened. Fitted wieght.

Unplanned Repair	12/09/2022	10:00	13/09/2022	15:00	339,156	St Leonards	SL037506
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Equipment	MDT inop - Logistics to arrange repair
--------------------	--

Breakdown	24/09/2022	13:49	26/09/2022	06:06	340,488	St Leonards	SL037630
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	flat tyre rear nearside inner
-----------	-------------------------------

Vehicle Deep Clean	27/09/2022	13:16	27/09/2022	13:18	340,621	St Leonards	SL037650
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	27/09/2022	13:18	29/09/2022	07:43	340,621	St Leonards	SL037651
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	29/09/2022	07:43	29/09/2022	07:44	340,633	St Leonards	SL037674
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

SAFETY INSPECTION	29/09/2022	07:44	03/10/2022	15:00	340,633	St Leonards	SL037675
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

56 Comms Equipment

Electrical Auxs KEEPS POWERING DOWN

Tail Lift Inspection

MOT

MOT 14:00 03.09.2022 @ Ferndown comm

55 Tail Lift

Tank corroded

Monitoring

03 Instruments & Sensors 1

Fire trace bypassed no stock

Monitoring

01 Air Conditioning 1

Condensor frame corroded...all working

Monitoring

ACCIDENT	11/10/2022	06:00	11/10/2022	10:03	341,340	St Leonards	SL037788
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors

O/S mirror glass smashed, renewed glass & surround.

Unplanned Repair	18/10/2022	11:30	20/10/2022	09:30	342,219	St Leonards	SL037879
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Power Failure

Comms power failing with engine running - Logistics

31 Battery Comms

86 Sliding Door

Side door handle stuck out

Unplanned Repair	26/10/2022	08:00	26/10/2022	09:00	342,554	St Leonards	SL037953
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Equipment

MDT n/w, reset.

44 Add Ad Blue

added 10l.

Breakdown	20/11/2022	07:52	21/11/2022	05:30	345,436	St Leonards	SL038167
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown

side door handle

Monitoring

Breakdown	03/12/2022	10:42	04/12/2022	11:02	347,329	St Leonards	SL038323
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	broken side door handle
-----------	-------------------------

Vehicle Deep Clean	29/12/2022	12:47	29/12/2022	12:50	350,192	St Leonards	SL038632
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	29/12/2022	12:50	30/12/2022	08:00	350,192	St Leonards	SL038633
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	31/12/2022	12:31	31/12/2022	12:33	350,195	St Leonards	SL038656
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	31/12/2022	12:33	03/01/2023	15:00	350,195	St Leonards	SL038657
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

55 Tail Lift	Tank corroded	Monitoring
03 Instruments & Sensors 1	Fire trace bypassed no stock	Monitoring
01 Air Conditioning 1	Condensor frame corroded...all working	Monitoring
Breakdown	side door handle. NFF	
86 Sliding Door	Doors SIDE SLIDING DOOR HANDLE BROKEN NFF	
Wheel Hub Flanges Replaceme		
Tail Lift Inspection		
Engine Change Oil & Filter		
13 Brake Pads	Front Brake discs and pads	
13 Brakes 1	Rear Brake Discs and pads	
17 Tyres Replace	Rear Tyres Replaced	
89 Seats	Passenger seat cover cut and frame cracked, rear saloon seat arm rest broken	
89 Seatbelts	passenger seatbelt frayed	
34 Emergency Light System	N/S/R Blue light not working	
34 Lights	O/S/F Fog light not working	
56 Comms Equipment	Cab speaker insecure	
02 Cab Assembly 1	Genysis unit not lighting up	
02 Cab Assembly 2	Center console button and latch missing	

Unplanned Repair	11/02/2023	08:00	11/02/2023	09:00	352,140	St Leonards	SL039075
85 Body Interior 1	Rear Cupboard Draw railings broken- New railings fitted						
Unplanned Repair	25/02/2023	12:00	25/02/2023	14:00	353,127	St Leonards	SL039216
17 Tyres Replace	Replace n/s/r inner tyre						
02 Pipeline Annual Inspection	30/03/2023	13:43	30/03/2023	13:44	354,508	MDT Ferndown	TF002617
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found						
SAFETY INSPECTION	03/04/2023	09:00	06/04/2023	12:00	354,508	St Leonards	SL039575
18 Wheels Check Torques							
Safety Inspection							
55 Tail Lift	Tail lift lights not working. faulty tilt switch. (no stock)					Monitoring	
03 Instruments & Sensors 1	Fire trace low pressure. fitted Jactone system						
01 Air Conditioning 1	Condensor frame corroded...all working					Monitoring	
71 Body Exterior 2	Body Exterior ABOVE WINDSCREEN E OF THE AMBULANCE SIGN SMASHED					Monitoring	
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Tail Lift Inspection							
34 Lights Bulb Replacement	osf wing repeater bulb blown. replace						
34 Lights	nsr reverse and tail light water ingress. both fron upper markers u/s. replace						
86 Doors Rear	NSR door split in lower corner. fit reinforce plate						
86 Sliding Door	Sliding door lower latch cover missing. fit new cover and sticker						
45 Engine 1	Aux belt tensioner seized. replaced						
16 Suspension 1	Rear spring buffers split x2. replaced						
45 Engine 2	NS engine mount split. replaced						
89 Seats	Drivers seat lumbar inop. replaced seat backrest with part from vor vehicle.						
13 Handbrake	Handbrake excess travel. check cables. adjust cables and shoes.						
27 Transmission Automatic	Replace rear gearbox mount						
Vehicle Deep Clean	04/04/2023	06:00	04/04/2023	16:00	354,508	St Leonards	SL039583

Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	11/04/2023	13:00	13/04/2023	09:09	354,652	St Leonards	SL039682
45 Engine Ad Blue 45 Engine 1	Ad blue warning light on dash - Andy Boyt to repair (F/Comms) Replace NOX sensors. Teach in new sensors, clear codes and road test. all ok.						
SAFETY INSPECTION	14/04/2023	05:36	14/04/2023	08:30	354,662	St Leonards	SL039716
18 Wheels Check Torques Safety Inspection							
Vehicle Deep Clean	14/04/2023	05:38	14/04/2023	09:00	354,662	St Leonards	SL039717
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	21/05/2023	16:49	22/05/2023	05:34	359,711	St Leonards	SL040218
Breakdown	no sirens						
SAFETY INSPECTION	29/05/2023	08:00	31/05/2023	14:00	360,092	St Leonards	SL040322
18 Wheels Check Torques Safety Inspection							
55 Tail Lift	Tail lift lights not working. faulty tilt switch. (no stock)						
01 Air Conditioning 1	Condensor frame corroded...all working						
71 Body Exterior 2	Body Exterior ABOVE WINDSCREEN E OF THE AMBULANCE SIGN SMASHED						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Tail Lift Inspection							
02 Windscreen Wipers	Wiper blades worn						
34 Lights Bulb Replacement	N/S/F Side light bulb not working.						
41 Air Intake	Intake system oil leak due to bad sealing.						
56 Comms Equipment	Saloon intercom cring smashed.						
85 Body Interior 1	Fit clips for saloon MVP.						
87 Stretcher Harness Replaced	Stretcher belts removed from main cott frame.						
86 Doors	N/S Side door catch covering loose.						
17 Tyres Replace	N/S/R/I Tyre tread feathered.						

85 Body Interior 2	Saloon locker seal broken.						
16 Suspension 1	Rear leaf spring rear most spring eye bushes worn & have excessive lift / play.						
Vehicle Deep Clean	30/05/2023	14:07	31/05/2023	12:26	360,098	St Leonards	SL040346
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	31/05/2023	15:00	01/06/2023	12:13	360,098	St Leonards	SL040366
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Breakdown	03/06/2023	11:32	03/06/2023	13:43	360,284	St Leonards	SL040394
Breakdown	MDT keeps turning off no power						
Unplanned Repair	22/06/2023	09:53	22/06/2023	10:58	361,208	St Leonards	SL040687
56 Comms Equipment	Power fail						
Unplanned Repair	26/06/2023	15:30	26/06/2023	15:45	363,103	St Leonards	SL040739
45 Engine Oil Top Up	Top up						
Replace Vehicle Fuel Card	07/07/2023	18:00	07/07/2023	18:10	364,120	St Leonards	SL040917
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
SAFETY INSPECTION	10/07/2023	07:00	10/07/2023	14:05	365,051	St Leonards	SL040969
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
31 Battery Chassis	Chassis battery weak						
Camera Installation	Fault with CCTV - Hard drive not reconised						
87 Stretcher Harness Replaced	Middle lap belt damaged						

Vehicle Deep Clean	11/07/2023	06:00	11/07/2023	13:30	365,051	St Leonards	SL040990
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	12/07/2023	20:42	13/07/2023	15:15	365,124	St Leonards	SL041044
Breakdown	Losing power in back of truck						
Breakdown	17/07/2023	22:43	19/07/2023	07:30	365,760	St Leonards	SL041117
Breakdown	limp mode (see notes)						
Breakdown	11/08/2023	00:38	11/08/2023	06:30	367,873	St Leonards	SL041491
Breakdown	O/S/F Deflating						
Unplanned Repair	12/08/2023	06:00	12/08/2023	17:00	367,873	St Leonards	SL041504
17 Tyres 18 Wheels	O/S/F Tyre puncture Rim u/s						
Vehicle Deep Clean	15/08/2023	10:24	15/08/2023	14:00	368,199	St Leonards	SL041536
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/08/2023	07:26	18/08/2023	14:51	368,199	St Leonards	SL041577
18 Wheels Check Torques Safety Inspection Replace Handbrake Cables Tail Lift Inspection 55 Tail Lift 34 Lights 34 Lights Bulb Replacement 02 Cab Ass Fire Extinguisher 45 Engine 1	Replace Handbrake Cables Rail insecure. Resecure rail. OS scene light not working. OS alley lights not working. Both bulbs blown Both fire extinguishes short dates. Replaced Aux belt running on wrong part of a/c compressor. Adjusted, squeal gone						

Unplanned Repair	15/09/2023	15:47	15/09/2023	15:49	370,336	St Leonards	SL041950
56 Comms Equipment	Comm batt replaced						
Vehicle Deep Clean	26/09/2023	10:07	26/09/2023	15:49	370,899	St Leonards	SL042100
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	02/10/2023	06:00	05/10/2023	08:35	370,899	St Leonards	SL042155
18 Wheels Check Torques							
Safety Inspection							
Recall Notification	Mercedes airbag recall						
MOT							
15 Steering 1	Replace worn steering wheel						
86 Door Lock	Manual door lock not working drivers door. Reattach and adjust rod						
16 Suspension 1	Replace 2x torn buffer pads						
13 Brake Pads	Front brake pads worn below 50%, Replaced						
11 Axle Rear	Replace corroded rear axle cover and gasket. Oil replaced.						
Unplanned Repair	09/10/2023	06:45	09/10/2023	08:01	371,268	St Leonards	SL042265
71 Body External Steps	Step Inop						
Unplanned Repair	30/10/2023	11:00	30/10/2023	11:15	373,344	St Leonards	SL042563
02 Mirrors	Replace damaged n/s mirror glass						
Vehicle Deep Clean	07/11/2023	13:00	08/11/2023	15:37	374,302	St Leonards	SL042703

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/11/2023	14:16	09/11/2023	06:54	374,407	St Leonards	SL042719
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 12mts Service	Service of fire suppression system						
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
Tail Lift Inspection							
Pollen Filter Change	Pollen Filter Change						
Engine Change Oil & Filter							
02 Glass / Windows	O/S window switch incomplete						
Breakdown	17/12/2023	15:51	18/12/2023	07:27	376,698	St Leonards	SL043231
Breakdown	Red battery warning light						
45 Engine 1	Belts come off.						
Vehicle Deep Clean	19/12/2023	13:43	20/12/2023	10:20	376,745	St Leonards	SL043252
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	21/12/2023	14:00	22/12/2023	10:40	376,745	St Leonards	SL043287
18 Wheels Check Torques							
Safety Inspection							
85 Body Interior 1	Comms locker Lock damaged..parts ordered						
13 Handbrake	Hand brake has long travel						
86 Sliding Door	Sliding door hard to open						
Breakdown	17/01/2024	21:44	19/01/2024	07:38	377,478	St Leonards	SL043634
Breakdown	Lights and sirens intermittent						
Unplanned Repair	28/01/2024	13:40	28/01/2024	14:09	377,687	St Leonards	SL043754

54 Sirens No audio on sirens. replaced siren and repaired bull horn pedal switch.

SAFETY INSPECTION 04/02/2024 10:00 05/02/2024 14:00 378,969 St Leonards SL043829

18 Wheels Check Torques
 Safety Inspection
 56 Comms Equipment Radio & Comm System Sat nav not working. NFF
 01 Air Conditioning 1 A/C System Saloon temp in rear not working with burning cable smell. NFF
 45 Engine 1 Injector blowing by
 45 Engine 2 Resenator seals leaking oil.
 45 Engine 3 Oil leak from vac pump.
 16 Suspension 1 Rear anti roll bar bushes worn. Replaced
 85 Body Interior 1 230v leds missing and broken. Replaced
 15 Steering 1 Play from n/s/f joint and track rod end. Replaced
 17 Tyres Replace NSF Tyre worn Replaced
 42 Coolant System Coolant temp sensor seal leaking. Replaced

Vehicle Deep Clean 06/02/2024 11:54 07/02/2024 09:25 379,000 St Leonards SL043864

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 18/02/2024 07:31 18/02/2024 11:30 379,500 St Leonards SL044024

Breakdown Puncture

Breakdown 29/02/2024 09:55 29/02/2024 14:16 381,261 St Leonards SL044201

Breakdown WATER IN FUEL. Drained fuel tank, replaced fuel filter. cleared fault codes.

02 Pipeline Annual Inspection 15/03/2024 13:23 15/03/2024 13:25 383,284 MDT Ferndown TF003323

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - No faults found.

SAFETY INSPECTION	18/03/2024	07:00	26/03/2024	17:32	383,321	St Leonards	SL044457
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

01 Air Conditioning 1 A/C System Saloon temp in rear not working with burning cable smell

Brake Fluid Change Brake Fluid Change

Tail Lift 12M Service & Weight Carry out inspection

Tail Lift Inspection Tail lift bolt missing

55 Tail Lift Tail lift side rails loose

34 Lights N/S/R Number plate LED broken

17 Tyres N/S/R/O Tyre wall cut through to cords

87 Stretcher Stretcher belts removed from main cott frame

87 - Stretchers/Chairs/Boards Stretcher side wing catch not working

43 Exhaust System 1 Exhaust D.P.F. Pressure sensor pipes split & insecure

13 Handbrake Cab hand brake travel becomming excessive

41 Air Intake Air intake pipes insecure

16 Suspension 1 Rear shock absorbers leaking

02 Cab Assembly 1 Cab passenger window switch broken

54 Sirens Front siren housing insecure

13 Brake Test Carry out

Vehicle Deep Clean	20/03/2024	11:26	21/03/2024	09:08	383,320	St Leonards	SL044499
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	10/04/2024	04:58	12/04/2024	06:19	385,324	St Leonards	SL044825
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown Aux drive belts broken apart and come off pulleys. Crank pulley seal leaking oil

45 Engine 1 Replace crank pulley seal. Replace 2x belts.

Vehicle Deep Clean	24/04/2024	08:45	24/04/2024	16:00	386,835	St Leonards	SL045031
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	27/04/2024	06:00	28/04/2024	07:28	386,835	St Leonards	SL045057
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques Checked.

Safety Inspection Carried out inspection.

Tail Lift Inspection Done.

Auto G/box Oil & Filter Change Auto G/box Oil & Filter Change. Done.Cleaned sealer from faces.

Wheel Hub Flanges ReplacemeReplaced rears.

13 Brakes 1 Rear disc's & pads worn. Replaced.
 13 Handbrake Cable adjuster siezed. Replaced.
 17 Tyres Replace Both O/S/R tyres low tread. Replaced x2.
 02 Cab Assembly 1 Arm rests loose. Secured.
 02 Cab Assembly 2 Interior light n/w. Adjusted contacts.
 44 Add Ad Blue Topped 10 Ltrs.
 71 Body Exterior 1 Bonnet soundproofing adrift. Resecured.

Unplanned Repair	09/05/2024	10:41	13/05/2024	10:00	386,835	St Leonards	SL045248
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windscreen Windscreen Damaged

Unplanned Repair	19/05/2024	11:49	21/05/2024	12:30	386,950	St Leonards	SL045386
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1 EML on. Vehicle Key Faulty, parts ordered.

Vehicle Deep Clean	11/06/2024	13:30	12/06/2024	08:44	389,456	St Leonards	SL045717
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	13/06/2024	07:00	14/06/2024	09:38	389,456	St Leonards	SL045748
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques Checked.
 Safety Inspection
 UB Fire Supp 6mts Service UB Fire Supp 6mts Service
 Annual Heater Service Annual Heater Service
 Annual Air Con Service Annual Air Condition Service
 Tail Lift Inspection
 Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight
 71 Body Exterior 1 Damaged caused by corrosion around o/s/r lower hinge
 43 Exhaust System 1 Heater exhaust split, Replaced.

Monitoring

Unplanned Repair	15/07/2024	06:27	15/07/2024	17:01	391,700	St Leonards	SL046321
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

52 Electrical Aux	Not Charging. Auto eject broken. Replaced						
-------------------	---	--	--	--	--	--	--

Vehicle Deep Clean	22/07/2024	13:25	23/07/2024	10:15	392,001	St Leonards	SL046452
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	24/07/2024	17:04	02/08/2024	15:44	392,001	St Leonards	SL046527
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
56 Comms Power Failure	MDT Failure/Issue MDT keeps power fails						
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present						
Tail Lift Inspection	Done.						
34 Lights Bulb Replacement	N/S dip beam n/w. Replaced bulb.						
02 Cab Assembly 1	Interior light n/w. Replaced bulb.						
85 Body Interior 1	Cupboard strap broken. Replaced.						
17 Tyres Replace	N/S/R/I tyre low tread. Replaced.						
45 Engine 1	Oil & coolant leakig in V. (Sandown)						
02 Cab Ass Fire Extinguisher	Out of date x2. Replaced x2.						

Unplanned Repair	07/08/2024	05:30	07/08/2024	16:47	392,715	St Leonards	SL046705
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	Fumes in cab. Replaced elbow to turbo bolts x3 due to incorrect bolts fitted.						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						

Unplanned Repair	13/08/2024	15:00	14/08/2024	12:19	393,591	St Leonards	SL046794
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

01 Air Conditioning 1	No air con in saloon. - Replaced. rear condensor, hoses and drier.						
01 Air Conditioning 2	Serviced cab ac system. working ok.						
02 Windscreen Wipers	Washer jets y piece broken. replaced						

Unplanned Repair	19/08/2024	09:00	19/08/2024	09:15	394,242	St Leonards	SL046868
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors Replace n/s mirror glass

Vehicle Deep Clean 02/09/2024 10:02 03/09/2024 09:39 395,980 St Leonards SL047124

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 04/09/2024 10:30 05/09/2024 10:48 395,980 St Leonards SL047158

18 Wheels Check Torques	Checked.	
Safety Inspection	Carried out inspection.	
71 Body Exterior 1	Damaged caused by corrosion around o/s/r lower hinge.Lift in N/S.	Monitoring
56 Comms Power Failure	MDT Failure/Issue MDT keeps power fails	
86 Sliding Door	Rollers siezed. Replaced.	
17 Tyres Replace	O/S/F low tread. Replaced.	

SAFETY INSPECTION 13/10/2024 11:00 24/10/2024 10:23 398,319 St Leonards SL047728

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
71 Body Exterior 1	Damaged caused by corrosion around o/s/r lower hinge.Lift in N/S.
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	Done.
MOT	Tuesday 15th @ 11:15
Engine Change Oil & Filter	Done.
02 Windscreen Wipers	O/S washer jet blocked. Replaced.
02 Cab Assembly 1	Cubby box knob missi8ng. Replaced.
45 Engine 2	Oil leak in V still. see previous job card.
71 Body Exterior 2	Panel above windscreen broken.
13 Discs	Front disc's worn.
17 Tyres	O/S/R extension valve missing. Replaced.

Vehicle Deep Clean 24/10/2024 15:00 25/10/2024 15:06 398,372 St Leonards SL047950

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair 25/10/2024 08:00 25/10/2024 09:00 398,372 St Leonards SL047960

UB Fire Supp Repair Re route fire suppression system

Vehicle Deep Clean 20/11/2024 11:00 21/11/2024 07:00 399,773 St Leonards SL048326

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 21/11/2024 15:00 25/11/2024 16:40 399,773 St Leonards SL048337

18 Wheels Check Torques
 Safety Inspection
 Tail Lift Inspection
 87 - Stretchers/Chairs/Boards Stretcher belts wrongly fitted
 87 Chairs Carry chair brackets broken
 86 Doors Rear O/S/R Inner door accident damage / sharp edges
 54 Sirens O/S/F Siren unit surround insecure
 13 Handbrake Cab handbrake travel becoming excessive
 13 Brakes 1 Front brakes pads thicknesses low, sensors worn & brakes discs badly lipped
 16 Suspension 1 Front shockabsorbers badly worn & top mount bushes have excessive lift
 13 Brake Test
 55 Tail Lift Tail lift fuse wiring fault

Med Devices Recall 20/11/2024 07:31 21/11/2024 07:34 398,372 MDT Ferndown TF003853

Decontaminated Cleaned with clinell wipes
 Med Devices Recall Upgraded Mangar compressor and charger on vehicle.

Breakdown 01/01/2025 05:59 01/01/2025 05:59 405,233 St Leonards SL048895

Breakdown Intermittent LOP Monitoring

Breakdown 01/01/2025 06:00 01/01/2025 06:00 405,233 St Leonards SL048896

Breakdown Clutch or gearbox slipping Monitoring

SAFETY INSPECTION 04/01/2025 06:00 04/01/2025 16:00 405,233 St Leonards SL048941

Check MDVS for Update Check and Install MDVS windows update
 Safety Inspection Carried out inspection.
 18 Wheels Check Torques Checked.

Road Test	
Breakdown	Clutch or gearbox slipping
45 Engine 1	Engine Intermittent limp mode. EGR valve sticking. replaced.
34 Lighting System	Lighting System Plastic cover of OS indicator. See notes.
41 Air Intake	Leaking @ metal pipe/resinator. Replaced pipe & seals.
34 Lights	O/S headlight blanking plug missing. Replaced.
45 Engine Oil Top Up	Topped 1Ltr.
34 Emergency Lights	Both N/S & O/S front body blues insecure. Secured.
02 Cab Assembly 1	Drivers window switch broken.Replaced.
34 Lights Bulb Replacement	N/S number plate light broken. Replaced.

Vehicle Deep Clean	05/01/2025	14:00	06/01/2025	15:36	405,282	St Leonards	SL048957
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	19/02/2025	14:54	20/02/2025	14:08	411,872	St Leonards	SL049624
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	24/02/2025	14:47	26/02/2025	10:00	411,872	St Leonards	SL049676
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
UB Fire Supp 12mts Service	Service of fire supression system
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	
34 Lights	Front sidelight bulbs replaced - nsr fog light replaced.
16 Suspension 1	Rear lower drop link bushes worn. replaced
16 Suspension 2	Rear spring buffers worn x2 - replaced.
71 Body Exterior 1	nsr reflector replaced - tail lift bridge plate guides & mudflap resecured.
17 Tyres Replace	NSF Tyre replaced.
85 Body Interior 1	Cupboard and doors repairs.
02 Cab Assembly 1	Gear shift selector lever bolts fallen out. stripped dash and refitted bolts.
45 Engine 1	No 4&6 injectors leaking at seals. removed, cleaned and refitted with new seal.
13 Brakes 1	NSF lower caliper slider stiff. removed, cleaned and regreased.

Unplanned Repair	27/02/2025	09:00	27/02/2025	09:35	412,024	St Leonards	SL049714
02 Mirrors	N/S mirror damaged. -Replaced whole mirror assembly.						
Unplanned Repair	06/03/2025	13:58	06/03/2025	14:00	412,707	St Leonards	SL049808
71 Body External Steps	Step warning not going off when step deployed.						
Unplanned Repair	13/03/2025	12:00	13/03/2025	13:26	413,682	St Leonards	SL049918
71 Body External Steps 55 Tail Lift	Side step deploying while driving Tail lift deployed warning while driving						
Unplanned Repair	24/03/2025	12:00	24/03/2025	13:15	415,056	St Leonards	SL050061
01 Heating 1	Saloon heater not working						
Unplanned Repair	29/03/2025	06:00	30/03/2025	08:33	415,691	St Leonards	SL050118
01 Heating 1	Saloon heater not working. Replaced both climate sensors						
O2 Pipeline Annual Inspection	08/04/2025	11:58	08/04/2025	11:59	416,374	MDT Weymouth	DW002239
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
Vehicle Deep Clean	09/04/2025	06:00	09/04/2025	10:00	416,374	St Leonards	SL050310
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	12/04/2025	06:00	13/04/2025	16:00	416,374	St Leonards	SL050350
Check MDVS for Update Safety Inspection 18 Wheels Check Torques	Check and Install MDVS windows update						

Road Test							
71 Body External Steps	Doors side step deploying spontaneously. Adjust door catches						
Axle Oil Change	Axle Oil Change						
Tail Lift Inspection							
85 Body Int Alcohol Gel Dispen							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
01 Heating 1	Heater inop - Replace control unit and sensor						
13 Brake Pads	Rear pads low						Monitoring
01 Air Conditioning 1	Secure aircon condenser above rear axle						
17 Tyres Replace	Replace n/s/r/o tyre - Worn to 3mm						
85 Body Interior 1	Replace damaged saloon retaining strap						

Breakdown	28/04/2025	17:13	29/04/2025	10:00	417,467	St Leonards	SL050638
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Fire suppression system deployed						
31 Battery Chassis	Chassis battery U/S Replaced						

SAFETY INSPECTION	24/05/2025	06:00	24/05/2025	11:40	421,002	St Leonards	SL051150
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update							
Safety Inspection	Carried out inspection.							
18 Wheels Check Torques	Checked.							
Road Test	Done.							
13 Brake Pads	Rear pads low. Checked ,still OK.						Monitoring	
43 Exhaust System 1	Hole in tail pipe.Monitor.JS.							
34 Emergency Lights	O/S grill blue not strobing. Replaced 2nd hand.							
15 Steering 1	PAS pipe clip broken. Replaced.							
71 Body Exterior Roof	Cracked/holed over cab							

Vehicle Deep Clean	26/05/2025	16:35	27/05/2025	10:17	421,033	St Leonards	SL051215
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Breakdown	13/06/2025	05:07	14/06/2025	11:51	422,480	St Leonards	SL051514
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	steering making noise, power steering gone
15 Steering 1	Replaced power steering pump and checked steering rack. All ok
Road Test	

BREAKDOWN	22/07/2025	07:45	22/07/2025	08:02	426,212	St Leonards	SL052220
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine Oil Top Up	Engine oil low
----------------------	----------------

Unplanned Repair	04/08/2025	12:00	04/08/2025	12:36	427,446	St Leonards	SL052485
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

87a - Medical Equipment Repair	EPCR not working
--------------------------------	------------------