

VE64BHY	A&E		Minehead Amb Stn				
PDI Inspection	02/02/2015	10:00	20/03/2015	14:29	112	Taunton	TN012153
17 Tyres PDI Inspection	ATS to fit Winter tyres x7						
SAFETY INSPECTION	31/03/2015	14:36	31/03/2015	14:41	1,763	Taunton	TN012511
18 Wheels Check Torques Safety Inspection Vehicle Deep Clean	Not done as veh only been on road 1 week from new (A. Sanders authorised) Vehicle Deep Clean not done as veh only been used 1 week from new						
Unplanned Repair	03/04/2015	13:40	03/04/2015	13:44	2,110	Taunton	TN012539
44 Add Ad Blue	filled adblue containers 10ltrs						
Unplanned Repair	09/04/2015	22:30	09/04/2015	22:45	3,629	Taunton	TN012625
44 Add Ad Blue	topped up by crew						
Unplanned Repair	15/04/2015	02:00	15/04/2015	02:15	4,538	Taunton	TN012626
44 Add Ad Blue	topped up by crew						
Unplanned Repair	18/04/2015	20:15	18/04/2015	20:30	5,427	Taunton	TN012673
44 Add Ad Blue	topped up by crew						
Unplanned Repair	20/04/2015	15:11	20/04/2015	15:18	6,094	Taunton	TN012645
44 Add Ad Blue	topped up adblue 15ltrs						
Unplanned Repair	22/04/2015	13:00	22/04/2015	13:15	6,562	Taunton	TN012676

44 Fuel System 1	removed fuel angel
86 Doors	Side door magnetic grip not catching, adjusted

Unplanned Repair	28/04/2015	09:32	28/04/2015	09:45	7,934	Taunton	TN012745
-------------------------	-------------------	--------------	-------------------	--------------	--------------	----------------	-----------------

44 Add Ad Blue	topped up by crew
----------------	-------------------

Unplanned Repair	09/05/2015	11:30	09/05/2015	11:45	10,372	Taunton	TN012779
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

44 Add Ad Blue	topped up by crew
----------------	-------------------

Vehicle Deep Clean	12/05/2015	09:30	12/05/2015	14:21	10,997	Taunton	TN012776
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	12/05/2015	14:00	13/05/2015	11:17	10,997	Taunton	TN012786
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques	
34 Emergency Light System	replaced damaged n/s/r top blue lens cover
87 - Stretchers/Chairs/Boards	Body Interior Stretcher wheel locking, unable to steer
87 Stretcher	repaired castor lock on stretcher
Safety Inspection	paper copy used by Lee Crisp (PCS)

Unplanned Repair	15/05/2015	15:05	15/05/2015	15:38	11,163	Taunton	TN012800
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

52 Electrical Aux	Cleaned out swarf from saloon roof panic strip as alarm going by itself
-------------------	---

Unplanned Repair	28/05/2015	08:30	28/05/2015	08:45	13,836	Taunton	TN012885
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

44 Add Ad Blue	topped up by crew
----------------	-------------------

Unplanned Repair	02/06/2015	13:00	02/06/2015	13:15	15,349	Taunton	TN012900
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

44 Add Ad Blue	topped up by crew						
Unplanned Repair	12/06/2015	18:00	12/06/2015	18:15	17,908	Taunton	TN012960
44 Add Ad Blue	topped up on 2 occasions by the crew						
SAFETY INSPECTION	23/06/2015	10:24	23/06/2015	15:53	20,686	Taunton	TN012987
18 Wheels Check Torques 89 Seats Safety Inspection 92 - C Service Service C	replaced rear saloon seat bearings & adjusted front saloon seat						
Unplanned Repair	04/07/2015	21:00	04/07/2015	21:01	23,150	Taunton	TN013089
45 Engine Ad Blue	Topped up by crew (empties collected & refilled at Taunton)						
ACCIDENT	28/07/2015	07:00	28/07/2015	09:16	28,447	Taunton	TN013152
71 Body Exterior Acc Repair	N/S sliding door and lower surround + NS wheelarch-SEE NOTES						
Unplanned Repair	29/07/2015	08:00	29/07/2015	08:15	28,566	Taunton	TN013160
44 Add Ad Blue	topped up by crew						
SAFETY INSPECTION	04/08/2015	08:30	05/08/2015	12:30	30,003	Taunton	TN013185
03 Instruments & Sensors 1 13 Handbrake 17 Tyres Replace 18 Wheels Check Torques 43 Exhaust System 1	Reset service indicator Adjusted h/brake Replaced all 6 worn rear tyres (inc cleaning hub faces) inc extended roadtest as per policy Repositioned tail pipe						

45 Engine Ad Blue	Topped up & cleaned up area of filler (dried & crystallized spillages)						
71 Body Exterior 1	Cleaned bitumin from o/s of body inc blue light lenses & cctv cover						
86 Doors	Adj & lubed rear door mechanism for inner handle						
87 - Stretchers/Chairs/Boards	Swapped ferno pedimate for stryker type						
89 Seats	Lubed, freed & adjusted swivel seat locks & bearings						
Safety Inspection	paper copy used						
Vehicle Deep Clean	05/08/2015	09:10	05/08/2015	09:13	30,013	Taunton	TN013191
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	05/08/2015	09:14	05/08/2015	16:01	30,013	Taunton	TN013192
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	10/08/2015	09:16	10/08/2015	15:00	31,183	Taunton	TN013212
Breakdown	N/S/R Puncture						
Unplanned Repair	12/08/2015	20:30	12/08/2015	20:45	31,788	Taunton	TN013330
44 Add Ad Blue	topped up by crews						
Unplanned Repair	19/08/2015	00:30	19/08/2015	00:45	33,148	Taunton	TN013258
34 Lights Bulb Replacement	o/s headlight bulb replaced by duty officer						
Unplanned Repair	26/08/2015	13:10	26/08/2015	13:25	34,847	Taunton	TN013299
02 Mirrors	replaced n/s mirror glass						
Breakdown	06/09/2015	20:39	06/09/2015	22:00	37,441	Taunton	TN013339
34 Lights Bulb Replacement	AA attended and replaced bulb						
Breakdown	N/S headlight out. AA to go minehead st.						

SAFETY INSPECTION	16/09/2015	09:18	17/09/2015	15:50	40,058	Taunton	TN013389
13 Brakes 1	Replaced worn front discs & pads & rear pads						
18 Wheels Check Torques	inc extended roadtest						
45 Engine Ad Blue	Topped up						
85 Body Interior 1	Replaced broken scoop securing strap (buckle smashed)						
Safety Inspection							
93 - D Service	done inc indicator reset						
Service D							
Tail Lift Annual Service	Statutory Inspection and Weight Test done by SW Lifts						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Unplanned Repair	21/09/2015	09:30	21/09/2015	09:45	41,109	Taunton	TN013409
02 Mirrors	Replaced missing o/s mirror glass						
Unplanned Repair	26/09/2015	18:00	26/09/2015	18:15	42,289	Taunton	TN013487
44 Add Ad Blue	topped up by crew						
Unplanned Repair	05/10/2015	13:00	08/10/2015	13:23	44,417	Taunton	TN013477
34 Lights	replaced smashed n/s/f indicator repeater lamp						
45 Engine 1	Inv EML on & limp mode - see notes						
SAFETY INSPECTION	27/10/2015	13:00	29/10/2015	15:15	48,625	Taunton	TN013566
13 Handbrake	Adjusted handbrake						
18 Wheels Check Torques							
71 Body Exterior 1	Temp repair to accident damage (n/s/f body corner & n/s/r wheel arch)						
71 Body Exterior 2	Repaired & straightened tail lift rubbing blocks						
86 Door Lock	Locker door keylock u/s						
86 Doors	Adjusted rear door linkage for outer handle. Secured side door catch cover						
87 Stretcher	Replaced 1x missing chest strap (old stock part)						

Awaiting Warranty

89 Seats	Swivel seat bearings getting rough					Awaiting Warranty	
Safety Inspection	Paper copy used						
Gearbox Oil & Filter Change							
Vehicle Deep Clean	28/10/2015	10:08	28/10/2015	10:10	48,625	Taunton	TN013571
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	28/10/2015	10:10	29/10/2015	09:24	48,625	Taunton	TN013572
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/11/2015	22:00	08/11/2015	22:15	49,992	Taunton	TN013623
44 Add Ad Blue	topped up by crew						
SAFETY INSPECTION	10/12/2015	13:58	14/12/2015	16:00	57,213	Taunton	TN013740
03 Instruments & Sensors 1	Reset service indicator						
17 Tyres	replace n,s and o,s front wheels,tyres clean hubs						
18 Wheels Check Torques	inc extended roadtest as per policy						
52 Electrical Aux	Both front 12v cigarette sockets inop					Awaiting Warranty	
54 Reversing Systems	Rev camera inop - red fault light on cctv unit					Awaiting Warranty	
55 Tail Lift	Freed off, cleaned & lubed stuck tail lift drop handles						
85 Body Interior 1	Replaced both OOD fire extinguishers						
85 Body Interior 2	fit dca decals in cab and saloon						
85 Body Interior 3	Replaced broken scoop securing strap						
86 Door Lock	Locker door keylock u/s					Awaiting Warranty	
89 Seats	Swivel seat bearings getting rough					Awaiting Warranty	
Safety Inspection	paper copy used						
MOT Pre Test							
92 - C Service							
Service C							
Travel Time							
MOT							

Unplanned Repair	28/12/2015	01:30	28/12/2015	01:45	60,367	Taunton	TN013804
34 Lights Bulb Replacement	n/s main beam bulb replaced by duty officer						
Breakdown	31/12/2015	04:19	31/12/2015	06:00	61,142	Taunton	TN013818
17 Tyres Replace 18 Wheels Breakdown	ATS call out, replaced n/s/f tyre and cracked rim replaced n/s/f cracked rim, rim supplied FOC by workshops Puncture						
Unplanned Repair	01/01/2016	01:00	01/01/2016	01:30	61,332	Taunton	TN013826
34 Lights Bulb Replacement	headlight bulb replaced by Duty officer						
SAFETY INSPECTION	19/01/2016	10:00	20/01/2016	13:28	65,613	Taunton	TN013925
17 Tyres Replace 18 Wheels Check Torques 43 Exhaust System 1 52 Electrical Aux 54 Reversing Systems 86 Door Lock 86 Doors Rear 86 Sliding Door 89 Seats Safety Inspection	Replaced all 4 worn rear tyres inc cleaning all mating faces inc extended roadtest as per policy Replaced missing exh heat sheild securing clips (inc straightening & refitting) Both front 12v cigarette sockets inop Rev camera inop - red fault light on cctv unit Locker door keylock u/s freed off & lubed keylock Removed & re-shaped side door top magnet mounting arm SEE NOTES					Awaiting Warranty Awaiting Warranty Awaiting Warranty Awaiting Warranty	
Unplanned Repair	25/01/2016	08:00	25/01/2016	16:17	66,294	Taunton	TN013948
55 Tail Lift	Bridging plate securing pin & insert missing - replaced by SW Lifts						
Unplanned Repair	11/02/2016	11:45	11/02/2016	12:34	70,398	Taunton	TN014038
02 Mirrors 02 Windscreen Wipers 03 Instruments & Sensors 1	Replaced broken n/s mirror glass Replaced smearing wiper blades Reset service indicator						

Unplanned Repair	19/02/2016	14:00	19/02/2016	14:29	72,233	Taunton	TN014074
34 Emergency Lights 34 Lights	replace n/s rear corner light Body Exterior RNS blue light missing. found at end of shift						
Unplanned Repair	22/02/2016	13:00	22/02/2016	13:36	72,963	Taunton	TN014082
02 Cab Assembly 1 56 Comms Equipment	replaced cab courtesy light bulb checked and replaced missing radio aerial						
SAFETY INSPECTION	02/03/2016	11:31	03/03/2016	17:30	74,572	Taunton	TN014123
18 Wheels Check Torques							
34 Emergency Lights	N/S/F blue corner lens broken					Awaiting Parts	
52 Electrical Aux	Both front 12v cigarette sockets repaired by J.Coles for WAS						
54 Reversing Systems	Rev camera inop					Awaiting Parts	
55 Tail Lift	See notes						
85 Body Interior 1	Resecured cupboard hinges						
86 Door Lock	Faulty Locker door keylock replaced by J.Coles for WAS						
86 Doors	Straightened bent o/s/r door stay						
86 Doors Rear	Rear door handle linkage repaired by J.Coles for WAS						
86 Sliding Door	Side door bearings replaced by J.Coles under warranty for WAS						
Camera Upgrade	Front cctv camera inop - cable faulty					Awaiting Parts	
Safety Inspection							
Install Saloon CCTV Camera	Done by J.Coles						
93 - D Service							
Service D							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	01/03/2016	12:00	02/03/2016	14:40	74,572	Taunton	TN014125
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	13/03/2016	22:30	13/03/2016	22:45	77,074	Taunton	TN014166

34 Lights Bulb Replacement n/s headlight bulb replaced by duty officer

Unplanned Repair 25/03/2016 14:41 25/03/2016 15:20 79,921 Taunton TN014243

34 Lights Inv intermittent o/s indicator fault - cleaned arc'd bulb holder contact & bent

SAFETY INSPECTION 12/04/2016 11:00 15/04/2016 16:00 84,018 Taunton TN014311

13 Handbrake adjust handbrake shoes
 17 Tyres Replace replace front tyres worn
 18 Wheels replaced cracked n/s/r/i wheel rim
 18 Wheels Check Torques carry out extended test drive as per trust policy and retorque
 34 Emergency Light System see notes
 34 Emergency Lights N/S/F blue corner lens broken
 34 Lights Bulb Replacement replace n/s full beam bulb
 52 Electrical Aux reset service indicator
 54 Reversing Systems Rev camera inop
 55 Tail Lift free up seized guide rails, and adjust ram.
 85 Body Interior 1 see notes
 Camera Upgrade Front cctv camera inop - cable faulty
 Safety Inspection paper copy used by Chris Small
 85 Body Int Alcohol Gel Dispen fit gel dispenser
 Wheel Studs & Nuts Replacemsee notes
 Handbrake Cable ReplacementReplace rear handbrake cables
 UB Fire Suppression Service carry out fire suppression service
 Annual Heater Service Annual Heater Service
 Annual Air Con Service Annual Air Condition Service [dual system]
 Fit Throw Lines & SOP supply throw lines

Monitoring

Vehicle Deep Clean 14/04/2016 15:14 14/04/2016 15:17 84,016 Taunton TN014328

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean 14/04/2016 15:17 14/04/2016 15:19 84,017 Taunton TN014329

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean 14/04/2016 15:19 15/04/2016 15:39 84,018 Taunton TN014330

Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	17/05/2016	07:00	17/05/2016	09:38	90,328	Taunton	TN014488
34 Lights 55 Tail Lift	INTERMITANT FAULT ON NEARSIDE WING INDICATOR-replaced bulb						
SAFETY INSPECTION	26/05/2016	07:44	27/05/2016	17:00	92,699	Taunton	TN014521
13 Discs 16 Suspension 1 17 Tyres Replace 18 Wheels Check Torques 71 Body Exterior Acc Repair 85 Body Interior 1 89 Seats Annual Heater Service Safety Inspection 92 - C Service Service C	Replaced worn front & rear discs & pads Replaced both n/s/r spring slipper pads Replaced 3x worn rear tyres inc cleaning all mating faces Repaired acc dam to n/s/r wheel arch Resecured saloon microphone Lubed & freed sticking saloon seat plunger Annual Heater Service						
Unplanned Repair	03/06/2016	09:45	03/06/2016	11:21	93,170	Taunton	TN014557
34 Emergency Lights	repair n/s/r corner blue light fittings and fit light [unit missing]						
Vehicle Deep Clean	06/06/2016	09:00	06/06/2016	15:13	93,229	Taunton	TN014565
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	27/06/2016	15:30	01/07/2016	16:03	98,507	Taunton	TN014667
34 Emergency Lights	Replaced missing o/s/r blue corner lens & LED unit						

SAFETY INSPECTION	30/06/2016	09:00	01/07/2016	16:05	98,507	Taunton	TN014682
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Cab Assembly 1	Repaired cab storage bin
02 Cab Assembly 2	Replaced stickers in windscreen (w/screen replaced)
02 Windscreen	Chipped windscreen replaced by Mobile windscreens
03 Instruments & Sensors 1	Reset service indicator
18 Wheels Check Torques	
34 Lights	Repaired corroded wiring to no plate light
86 Sliding Door	Reshaped side door top magnet arm & resecured catch cover
87 Stretcher Harness Replaced	Repaired harness chest strap
Safety Inspection	filter & washer booked out as not booked last time
Reposition grab bag shelf	
Gearbox Oil & Filter Change	

Unplanned Repair	07/07/2016	08:30	07/07/2016	08:48	99,977	Taunton	TN014713
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

86 Doors	replaced battery in remote key fob
----------	------------------------------------

Unplanned Repair	13/07/2016	15:15	13/07/2016	15:30	101,551	Taunton	TN014749
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	o/s headlight bulb replaced by duty officer
----------------------------	---

Unplanned Repair	19/07/2016	08:40	19/07/2016	08:56	103,064	Taunton	TN014774
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	Replaced broken n/s mirror glass
------------	----------------------------------

SAFETY INSPECTION	16/08/2016	09:55	19/08/2016	16:41	109,489	Taunton	TN014906
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Saloon air con inop-SEE NOTES
02 Cab Ass Fire Extinguisher	New fire extinguisher fitted in cab and saloon
02 Cab Assembly 1	Supply new torch [1 missing]
13 Handbrake	adjust handbrake shoes and cables
16 Suspension 1	n/s/f strut worn
16 Suspension 2	o/s/r spring pads split
17 Tyres Replace	Replace n/s/f and n/s/r tyres [worn] clean hubs and rims

18 Wheels Check Torques							
34 Lights Bulb Replacement	replace n/s day running light bulb						
45 Engine Ad Blue	clean ad blue filler						
52 Electrical Aux	reset service indicator						
86 Door Lock	free off seized rear door lock						
89 Seats	Both swival seat bearings slight noise						Awaiting Warranty
Safety Inspection	paper copy used by Chris Small						
Tail Lift 6 Monthly Inspection	Statutory Inspection carried out by south west lifts						
93 - D Service							
Service D							
Tail Lift Annual Service	Statutory Inspection and Weight Test carried out by south west lifts						

Unplanned Repair	01/09/2016	22:45	01/09/2016	23:00	112,447	Taunton	TN015005
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	n/s headlight bulb replaced by duty officer						
----------------------------	---	--	--	--	--	--	--

Unplanned Repair	19/09/2016	07:00	19/09/2016	07:15	116,371	Taunton	TN015087
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	replaced missing o/s mirror glass						
------------	-----------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	29/09/2016	12:44	30/09/2016	10:55	118,898	Taunton	TN015165
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace	Replaced worn o/s/f & o/s/r tyres						
18 Wheels Check Torques	inc extended roadtest as per policy						
34 Lights	N/S/F roof marker partially inop						Awaiting Parts
52 Electrical Aux	Fire supression warning going off						Awaiting Warranty
85 Body Interior 3	Removed kit/equip as req'd - veh going to bodyshop						
86 Sliding Door	Side door seal split						Awaiting Parts
89 Seats	Both swival seat bearings slight noise						
Safety Inspection							

ACCIDENT	30/09/2016	10:30	07/10/2016	16:00	118,898	Taunton	TN015175
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights	N/S/F roof marker partially inop						
44 Add Ad Blue	Topped up adblue						
52 Electrical Aux	Modified wiring to prevent fire supression warning fault						
71 Body Exterior 3	Dekitted for going to bodyshop						

71 Body Exterior Acc Repair
86 Sliding Door Replaced side door seal

Vehicle Deep Clean **10/10/2016** **08:00** **10/10/2016** **16:00** **119,053** **Taunton** **TN015231**

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean **10/10/2016** **15:59** **10/10/2016** **16:00** **119,053** **Taunton** **TN015239**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **31/10/2016** **08:00** **31/10/2016** **08:30** **123,209** **Taunton** **TN015353**

45 Engine Oil Top Up check oil and top up [top up washer fluid]

Vehicle Deep Clean **09/11/2016** **11:00** **09/11/2016** **16:00** **125,036** **Taunton** **TN015408**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **10/11/2016** **07:00** **11/11/2016** **15:00** **125,036** **Taunton** **TN015416**

13 Brake Pads Replaced worn front pads
18 Wheels Check Torques
86 Doors Rear Lubed & freed off rear keylock
86 Sliding Door Straightened side door top magnet mount arm
Safety Inspection
Remove Ventilator Brackets Remove Ventilator Brackets and Fill
MOT Pre Test
Travel Time
MOT
92 - C Service
Service C

SAFETY INSPECTION **21/12/2016** **11:00** **22/12/2016** **16:00** **133,853** **Taunton** **TN015670**

01 Air Conditioning 1	Fan on a/c condenser for saloon inop	Awaiting Warranty					
01 Heating 1	Replace aux heater exhaust pipe [split]						
02 Cab Assembly 1	Refit cab to saloon window seal						
13 Brake Test	Carry out R/B/T						
13 Handbrake	Adjust handbrake shoes and cable						
18 Wheels Check Torques							
34 Lights Bulb Replacement	Replace n/s/f side light bulb						
45 Engine Ad Blue	Clean Ad blue filler						
52 Electrical Aux	Reset service indicator						
55 Tail Lift	SEE NOTES						
71 Body Exterior 1	Side locker scoop board strap broken replace	Awaiting Warranty					
85 Body Interior 1	Repair hinge on locker below stretcher head seat						
86 Door Lock	Rear external door lock seized free off and lubricate						
86 Doors	Side locker door lock key inop						
87a - Medical Equipment Repair	Replace damaged mangar pump charger						
89 Seats	Both saloon swival seats slight wear in bearings						
Road Test	Carry out road test						
Safety Inspection	Paper copy used by Chris Small						
Vehicle Deep Clean	22/12/2016	08:00	22/12/2016	14:03	133,853	Taunton	TN015676
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	16/01/2017	07:00	16/01/2017	13:20	138,550	Taunton	TN015825
15 Steering 1	checked and adjusted tracking						
17 Tyres Replace	Tyres NSF tyre bald outer edge.replaced tyre						
Vehicle Deep Clean	01/02/2017	12:00	02/02/2017	09:48	142,036	Taunton	TN015912
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	02/02/2017	10:30	03/02/2017	16:06	142,036	Taunton	TN015917
01 Air Conditioning 1	Fan on a/c condenser for saloon inop	Awaiting Warranty					
02 Cab Assembly 1	Replace interior light bulb						
13 Brakes 1	replace rear brake pads [clean rims and hubs]						
16 Suspension 1	Replace n/s/r lower ARB bush [worn]						
17 Tyres	Replace n/s/r tyres [worn]						

18 Wheels Check Torques	Carry out extended test drive as per trust policy retorque and RBT	
27 Transmission Automatic	Centre propshaft mounting rubber starting to split	Monitoring
45 Engine 1	Slight oil leak replace o ring and seal on manifold intake	
52 Electrical Aux	Reset service indicator	
86 Doors	Side locker door lock key inop	Awaiting Warranty
86 Doors Rear	O/S door delaminating	Monitoring
89 Seats	Both saloon swival seats slight wear in bearings	Awaiting Warranty
Safety Inspection	Paper copy used by Chris Small	
Medical Device and Equip Chec		
93 - D Service		
Service D		
Tail Lift 6 Monthly Inspection	Statutory Inspection	

Breakdown	13/02/2017	02:09	14/02/2017	14:46	143,784	Taunton	TN015973
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

56 Comms Equipment	see notes
Breakdown	MDT not powering up

Unplanned Repair	21/02/2017	03:00	21/02/2017	03:30	144,651	Taunton	TN016013
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	N/S/F h/light bulb replaced by DO
----------------------------	-----------------------------------

Unplanned Repair	21/02/2017	10:00	21/02/2017	10:35	144,703	Taunton	TN016015
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lighting System	Electrical Auxs Offside indicator lens\casing broken
34 Lights	Electrical Auxs Offside indicator lens\casing broken

Unplanned Repair	23/02/2017	22:00	23/02/2017	22:30	145,268	Taunton	TN016043
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	O/S h/light bulb replaced by DO
----------------------------	---------------------------------

Unplanned Repair	06/03/2017	12:00	06/03/2017	13:00	147,686	Taunton	TN016087
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body External Steps	SEE NOTES
------------------------	-----------

Breakdown	08/03/2017	22:40	15/03/2017	11:00	148,248	Taunton	TN016104
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1 Breakdown	SEE NOTES limp mode						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep						

56 Comms Equipment SEE NOTES
Breakdown MDT wont turn on, AUX battery?

SAFETY INSPECTION 01/05/2017 08:00 05/05/2017 09:37 156,146 Taunton TN016413

01 Air Conditioning 1	Fan on a/c condenser for saloon replaced by Hickleys for WAS	
16 Suspension 1	Replaced 2x rear A/R bar link bushes	
17 Tyres Replace	Replaced worn n/s/r tyres	
18 Wheels Check Torques	inc extended roadtest as per policy	
27 Transmission Automatic	Centre propshaft mounting rubber starting to split	Monitoring
34 Lighting System	Found & refitted missing N/S h/light back cover	
34 Lights	Amber side marker lights inop (temp repair by J.Coles to make roadworthy)	Awaiting Warranty
43 Exhaust System 1	Replaced corroded tail pipe	
85 Body Interior 1	Resecured saloon mics	
86 Door Lock	Rear door lock seized	Awaiting Warranty
86 Doors	Side locker door lock key inop	Awaiting Warranty
86 Doors Rear	O/S door delaminating	Awaiting Warranty
86 Sliding Door	Straightened bent top magnet arm. Side door rollers getting noisy	
Safety Inspection		
WAS Firetrace rework & Service	Done by J.Coles for WAS	
Handbrake Cable Replacement	Replace rear handbrake cables - not done as veh under warranty still	
UB Fire Suppression Service	Done by J.Coles for WAS	
Annual Heater Service	Annual Heater Service	
Annual Air Con Service	Annual Air Condition Service inc both belts	

Vehicle Deep Clean 02/05/2017 09:00 02/05/2017 13:24 156,146 Taunton TN016419

Vehicle Deep Clean Vehicle Deep Clean

ACCIDENT 23/05/2017 14:46 14/06/2017 08:28 160,505 Taunton TN016531

71 Body Exterior Acc Repair n/s/f wing, door and bonnet repaired by Autospray

Vehicle Deep Clean 13/06/2017 14:38 14/06/2017 15:59 160,591 Taunton TN016656

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	14/06/2017	08:28	16/06/2017	16:05	160,591	Taunton	TN016658
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	Replace bulkhead expansion plug	
13 Handbrake	Adjust handbrake shoes and cable	
15 Steering 1	SEE NOTES	
18 Wheels Check Torques		
27 Transmission Automatic	Centre propshaft mounting rubber starting to split	Awaiting Warranty
34 Lights	Amber side marker lights inop (temp repair by J.Coles to make roadworthy)	Monitoring
45 Engine Ad Blue	Clean ad blue filler neck	
55 Tail Lift	SEE NOTES	Awaiting Warranty
71 Body Exterior 1	Replace address decal on side door	
71 Body Exterior 2	Adjust tail lift ram and stops	
85 Body Interior 1	Replace grab bag middle strap	
86 Door Lock	Rear door lock seized .Replaced by J.Coles	
86 Door Seals	Replace damaged n/s door seal	
86 Doors	Side locker door lock key inop.Replaced by J.Coles	
86 Doors Rear	O/S door delaminating	Monitoring
86 Sliding Door	Slight roughness external bearings	Monitoring
89 Seats	Rear swival seat bearing slight roughness	Monitoring
Safety Inspection	Paper copy used by Chris Small	
MGS Gas Storage Modifications	MGS Gas Storage Modifications	
92 - C Service		
Service C		

Unplanned Repair	28/06/2017	07:00	28/06/2017	11:30	162,750	Taunton	TN016747
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

56 Comms Equipment	MDT powers down, pce atteneded and replaced faulty parts
56 Comms Fitment	Check unable to contact control via mainset radio- replaced aerial
71 Body External Steps	side step noisy when coming out- motor repleced by jon coles under warranty

Breakdown	02/07/2017	22:04	02/07/2017	23:45	163,828	Taunton	TN016776
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace	ATS Call out- replaced n/s/r/o tyre
Breakdown	Puncture

Breakdown	18/07/2017	05:36	25/07/2017	16:05	166,713	Taunton	TN016876
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Retorque	Retorque front wheels						
45 Engine 1	SEE NOTES						
71 Body Exterior 1 Breakdown	Carry out temp repair to n/s/r wheel arch limp mode						
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/07/2017	09:00	18/07/2017	14:00	166,713	Taunton	TN016879
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/07/2017	13:30	20/07/2017	13:41	166,713	Taunton	TN016883
02 Cab Ass Fire Extinguisher	Replace cab and saloon dates expired						
13 Brakes 1	SEE NOTES						
17 Tyres Replace	Replace worn n/s/f tyre clean hub and rim						
18 Wheels Check Torques							
27 Transmission Automatic	Centre propshaft mounting rubber starting to split- repaired by mercedes						
34 Emergency Lights	Body Exterior nearside blue light, broken after getting caught SEE NOTES						
34 Lighting System	N/S/F 1x marker light led inop						Monitoring
34 Lights	Amber side marker lights inop (temp repair by J.Coles to make roadworthy)						Awaiting Warranty
52 Electrical Aux	Fit n/s electric window switch						
55 Tail Lift	SEE NOTES						
85 Body Interior 1	Repair chair track locker hinge						
86 Doors Rear	O/S door delaminating						Awaiting Warranty
86 Sliding Door	Slight roughness external bearings						Awaiting Warranty
87 - Stretchers/Chairs/Boards	Remove damaged carry chair mounting bracket repair and refit						
89 Seats	Rear swival seat bearing slight roughness						Awaiting Warranty
Safety Inspection	Paper copy used by Chris Small						
Tail Lift 6 Monthly Inspection	Statutory Inspection carried out by south west lifts						
Tail Lift Annual Service	Statutory Inspection and Weight Test carried out by south west lifts						
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Unplanned Repair	07/08/2017	08:30	07/08/2017	09:00	168,139	Taunton	TN016992
45 Engine Oil Top Up	Topped up 1.5 ltr						
Unplanned Repair	23/08/2017	07:45	23/08/2017	08:02	170,749	Taunton	TN017100
02 Mirrors	Mirrors shattered Blind spot mirror, van hit- replaced mirror glass						

SAFETY INSPECTION	30/08/2017	11:00	01/09/2017	16:24	172,064	Taunton	TN017154
01 Heating 1	Replace cracked aux heater exhaust pipe						
02 Mirrors	Repair and replace damaged o/s mirror						
13 Brakes 1	Replace front discs and pads						
13 Brakes 2	Replace rear discs and pads						
17 Tyres	Replace n/s/r worn inner tyre						
17 Tyres Tracking	Carry out steering geometry check and adjustment						
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R-B-T						
34 Lighting System	N/S/F 1x marker light led inop						Monitoring
34 Lights	Amber side marker lights inop (temp repair by J.Coles to make roadworthy)						
45 Engine 1	Oil leak from engine						Awaiting Warranty
55 Tail Lift	Sliding rails seized free off and lube						
86 Door Seals	Replace o/s split door seal						
86 Doors	Replace cracked internal door panel						
86 Doors Rear	O/S door delaminating						Awaiting Warranty
86 Sliding Door	Slight roughness external bearings						Awaiting Warranty
89 Seats	Rear swival seat bearing slight roughness						Awaiting Warranty
Safety Inspection	Paper copy used by Chris Small						
Vehicle Deep Clean	01/09/2017	08:00	01/09/2017	15:50	172,064	Taunton	TN017163
Vehicle Deep Clean	Vehicle Deep Clean						
ACCIDENT	01/09/2017	16:25	07/09/2017	14:22	172,064	Taunton	TN017169
71 Body Exterior Acc Repair	n/s body damage repaired by Autospray						
Unplanned Repair	07/09/2017	14:22	12/09/2017	18:00	172,064	Taunton	TN017209
34 Lighting System	N/S/F 1x marker light led inop						Awaiting Warranty
45 Engine 1	Oil leak from engine, leaking turbo hose replaced by mercedes of exeter						
86 Doors	carry bracket for chair on rear door broken						Awaiting Warranty
86 Doors Rear	O/S door delaminating						Monitoring
86 Sliding Door	Side door bearings replaced by Jon coles						
89 Seats	Rear swival seat bearings replaced by jon coles						

Vehicle Deep Clean	11/10/2017	11:30	12/10/2017	11:36	178,017	Taunton	TN017375
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	12/10/2017	11:46	16/10/2017	15:02	178,017	Taunton	TN017384
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Calipers	Replaced o/s/f caliper (bleed nipple seized sheared off)	
17 Tyres Replace	Replaced worn o/s/f tyre	
18 Wheels Check Torques		
34 Emergency Lights	Replaced broken o/s/f side blue light	
34 Lighting System	N/S/F 1x marker light led inop	Monitoring
86 Doors Rear	O/S door delaminating	Monitoring
Safety Inspection		
MOT Pre Test		
Travel Time		
MOT	test no - 548697969131	
93 - D Service		
Service D		

Breakdown	30/10/2017	14:31	01/11/2017	16:00	180,765	Taunton	TN017509
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Charging System	checked and found alternator faulty SEE NOTES
Breakdown	alternator warning light/ battery

SAFETY INSPECTION	20/11/2017	11:30	21/11/2017	14:23	184,697	Taunton	TN017640
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres	Replace o/s/r tyres 1x puncture 1x worn clean hub and rims	
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R-B-T	
34 Lighting System	N/S/F 1x marker light led inop	Monitoring
45 Engine Ad Blue	Clean Ad blue filler.	
52 Electrical Aux	Inverter inop,check all connections John Coles contacted awaiting warranty.	Awaiting Warranty
55 Tail Lift	Hand rails seized free off and lube.	
71 Body Exterior 1	Battery locker lock inop seized remove lock free off and lube refit lock	
85 Body Interior 1	Chair track locker hinge insecure repair and resecure	
86 Doors	Large rear door stay swival bolt broken remove drill out bolt and replace	
86 Doors Rear	O/S door delaminating	Awaiting Warranty
Safety Inspection	Paper copy used by Chris Small	

Vehicle Deep Clean	21/11/2017	08:30	21/11/2017	13:42	184,697	Taunton	TN017643
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	30/11/2017	22:00	30/11/2017	23:00	186,886	Taunton	TN017709
34 Lights Bulb Replacement	Headlight bulb replaced by DO (Rich Cockin)						
Breakdown	03/12/2017	10:46	04/12/2017	14:02	187,542	Taunton	TN017717
17 Tyres Replace Breakdown	Punctured n/s/f replaced by ATS (cracked rim - tyre worn to 3mm) N/S front puncture ? 205/75R16C						
Unplanned Repair	18/12/2017	12:00	18/12/2017	12:20	191,245	Taunton	TN017818
02 Mirrors	Replaced broken n/s mirror glass						
Unplanned Repair	19/12/2017	00:01	19/12/2017	01:00	191,294	Taunton	TN017827
34 Lights Bulb Replacement	N/S dip bulb replaced by lead para (Aaron)						
Unplanned Repair	21/12/2017	13:45	21/12/2017	13:58	192,113	Taunton	TN017842
45 Engine Oil Top Up							
Unplanned Repair	27/12/2017	11:20	27/12/2017	11:37	193,606	Taunton	TN017861
45 Engine Oil Top Up	Topped up 0.5 ltr						
SAFETY INSPECTION	09/01/2018	10:00	11/01/2018	17:25	197,001	Taunton	TN017931
03 Instruments & Sensors 1 17 Tyres	Reset service indicator Replace n/s/r worn tyres and o/s/r outer punctured tyre.clean hubs and rims.						

18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R.B.T
27 Transmission Automatic	Replace rear prop shaft [worn UJ]
34 Lighting System	N/S/F 1x marker light led inop
34 Lights	Replace damaged o/s marker light
45 Engine Ad Blue	Clean Ad blue filler
52 Electrical Aux	Inverter inop,check all connections John Coles contacted awaiting warranty.
86 Doors Rear	O/S door delaminatin.Make and fit temp support plates to door.
89 Seats	Swival seat [front] arm rest insecure locking bolt missing replaced.
Safety Inspection	Paper copy used by Chris Small
Tail Lift 6 Monthly Inspection	Statutory Inspection.Hand rails seized free off and lube
92 - C Service	
Service C	
Gearbox Oil & Filter Change	

Vehicle Deep Clean	11/01/2018	09:00	11/01/2018	15:11	197,011	Taunton	TN017943
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	14/02/2018	13:00	16/02/2018	07:47	203,430	Taunton	TN018154
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	15/02/2018	09:36	19/02/2018	15:54	203,430	Taunton	TN018159
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brake Test	Carry out brake test	
16 Suspension 1	All 4 rear suspension buffers split replace	
16 Suspension 2	OSF strut boot split replace boot	
18 Wheels Check Torques		
34 Emergency Light System	Replace airport light on roof	
34 Emergency Lights	Both top rear blue lights cracked secured with tape	Monitoring
34 Lighting System	NSF top side light 50% working replace light	
34 Lights	OS platform light not working replace light	
44 Add Ad Blue	Top up ad blue from tank	
55 Tail Lift	See notes	Awaiting Parts
71 Body Exterior 1	Bridge plate guide bars broken repair	
71 Body External Steps	Side step edge strip broken replace	
86 Doors Rear	Carry out modification to osr door	
86 Sliding Door	Top magnet not engaging adjust magnet	
Medical Devices Check	Check battery health on mobi med 95% & 100%	
Road Test	Carry out road test	
Safety Inspection	Carry out safety inspection	

Unplanned Repair	15/02/2018	09:38	15/02/2018	15:34	203,430	Taunton	TN018160
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Battery Aux	Inverter fault wirining repair carried ou by john coles under warranty
----------------	--

SAFETY INSPECTION	26/03/2018	08:30	27/03/2018	16:03	209,417	Taunton	TN018402
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	Replaced broken n/s mirror cover
02 Windscreen	Cracked windscreen replaced by National mobile windscreens
03 Instruments & Sensors 1	Reset serv ind
17 Tyres Replace	Replaced worn front tyres inc cleaning faces
18 Wheels Check Torques	
34 Emergency Lights	Both top rear blue lights cracked secured with tape
34 Lights	Correctly refitted o/s/f fog light & dip beam bulbs (inc removing fire trace ext
34 Lights Bulb Replacement	Replaced o/s side light bulb
45 Engine 1	Replaced broken aux belt tensioner
55 Tail Lift	Replaced broken handpump & bent pipe
71 Body External Steps	Fitted side step decals
85 Body Interior 1	Replaced damaged o/s/r upper cupboard shelf edging
Safety Inspection	
85 Body Int Alcohol Gel Dispen	Already fitted
Fit Poster Holder	Fit Poster Holder

Vehicle Deep Clean	26/03/2018	13:00	27/03/2018	15:30	209,417	Taunton	TN018405
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	10/04/2018	12:00	10/04/2018	12:20	212,356	Taunton	TN018472
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	Replaced missing n/s mirror glass
------------	-----------------------------------

Unplanned Repair	26/04/2018	16:50	26/04/2018	17:04	214,631	Taunton	TN018579
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine Oil Top Up

Vehicle Deep Clean	21/05/2018	13:00	22/05/2018	13:58	219,322	Taunton	TN018711
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	22/05/2018	08:00	25/05/2018	09:49	219,323	Taunton	TN018713
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	Replace damaged n/s washer jet connector
03 Instruments & Sensors 1	Reset service indicator
13 Brakes 1	REAR BRAKES
13 Brakes 2	Front brakes.Replace worn front discs and pads
15 Steering 1	Replace worn n/s inner steering joint
16 Suspension 1	Replace worn o/s/f shock absorber
16 Suspension 2	Replace worn n/s and o/s/f lower suspension arms
17 Tyres Tracking	Check tracking and adjust
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R.B.T
45 Engine Ad Blue	Clean Ad blue filler
71 Body Exterior 1	Body Exterior legs below ramp damaged -low uneven ground.SEE NOTES
71 Body Exterior 2	Repair damaged to body n/s/f and repaint.
89 Seats	Saloon swival seat plunger lock nut insecure,secure
Safety Inspection	Paper copy used by Chris Small
Wheel Hub Flanges Replaceme	
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service.Twin system.
UB Fire Suppression Service	
Handbrake Cable Replacement	Replace rear handbrake cables
93 - D Service	
Service D	

Unplanned Repair	04/06/2018	08:00	05/06/2018	15:03	220,410	Taunton	TN018782
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	Engine yellow warning light, intermittent.SEE NOTES
-------------	---

Unplanned Repair	11/06/2018	07:50	11/06/2018	08:32	221,179	Taunton	TN018829
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights	Replaced faulty o/s bulb holder & bulb
45 Engine Oil Top Up	topped up 0.5 ltr

Breakdown	24/06/2018	13:48	27/06/2018	10:46	223,283	Taunton	TN018942
45 Engine 1 Breakdown	Injector chuffing replace injector seal on number 4 cylinder lack of power; turbo not working see notes						
SAFETY INSPECTION	26/06/2018	08:38	27/06/2018	10:48	223,283	Taunton	TN018954
02 Cab Ass Fire Extinguisher	Replace fire extinguishers						
13 Brake Test	Carry out brake test						
18 Wheels Check Torques							
44 Add Ad Blue	Top up ad blue from tank						
56 Comms Equipment	Aerial broken on roof replace						
86 Sliding Door	Top door magnet not touching adjust magnet						
Medical Devices Check	Check battery health on mobi med 95% & 91%						
Safety Inspection	Carry out safety inspection						
Vehicle Deep Clean	27/06/2018	11:30	28/06/2018	12:00	223,288	Taunton	TN018968
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/07/2018	11:30	20/07/2018	12:10	227,773	Taunton	TN019146
45 Engine Ad Blue	Replaced missing cap & cleaned filler neck						
45 Engine Oil Top Up	Topped up 1ltr						
Breakdown	21/07/2018	11:44	24/07/2018	17:17	227,973	Taunton	TN019149
Breakdown	In Limp mode ?turbo.SEE NOTES						
SAFETY INSPECTION	30/07/2018	08:00	01/08/2018	09:15	228,285	Taunton	TN019201
02 Cab Assembly 1	Replace n/s cab torch battery						
03 Instruments & Sensors 1	Reset service indicator						
13 Handbrake	Adjust handbrake shoes and cable						
17 Tyres	Replace worn rear tyres clean hubs and rims						
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R.B.T						
44 Add Ad Blue							
85 Body Interior 1	Carry chair mounting point damaged remove repair and refit.						
86 Doors	Side door lock covers insecure, resecure.						

Safety Inspection Tail Lift 6 Monthly Inspection Tail Lift Annual Service	Paper copy used by Chris Small Statutory Inspection Statutory Inspection and Weight Test						
Vehicle Deep Clean	31/07/2018	11:30	31/07/2018	15:54	228,285	Taunton	TN019215
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	15/08/2018	11:20	16/08/2018	15:56	234,551	Taunton	TN019306
31 Battery Aux Breakdown	Tail lift battery failed replace battery eml & limp mode.SEE NOTES						
Unplanned Repair	17/08/2018	16:01	20/08/2018	16:38	234,572	Taunton	TN019320
27 Transmission Automatic 45 Engine 1	SEE NOTES						
Breakdown	24/08/2018	21:12	27/08/2018	08:35	234,572	Taunton	TN019359
02 Windscreen Wipers Breakdown	Replaced worn wiper blades n/s wiper blade perished						
Vehicle Deep Clean	10/09/2018	11:00	11/09/2018	13:00	233,577	Taunton	TN019448
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	11/09/2018	08:00	11/09/2018	16:24	233,577	Taunton	TN019463
17 Tyres Replace 18 Wheels Check Torques 86 Doors 86 Sliding Door 89 Seatbelts Safety Inspection MOT Pre Test	Replaced both worn front tyres inc extended roadtest as per policy Replaced broken dvrs door window switch panel Replaced noisy & worn side door centre bearings Drivers seatbelt slightly worn on edge - part ordered - on back order with apprentice						Awaiting Parts

Unplanned Repair	21/09/2018	11:10	21/09/2018	11:45	234,792	Taunton	TN019529
56 Comms Equipment	Inv satnav power issues - See notes						
Unplanned Repair	25/09/2018	08:15	25/09/2018	08:38	235,323	Taunton	TN019539
34 Lights Bulb Replacement	Replace n/s h/lamp bulb						
Unplanned Repair	01/10/2018	05:00	01/10/2018	05:40	236,291	Taunton	TN019573
34 Lights Bulb Replacement	H/light bulb replaced by OO						
Unplanned Repair	05/10/2018	12:00	05/10/2018	12:20	237,038	Taunton	TN019613
02 Mirrors	Replaced broken o/s mirror glass						
Unplanned Repair	09/10/2018	13:00	09/10/2018	13:56	237,625	Taunton	TN019638
45 Engine 1	Reported engine cutting out SEE NOTES						
Unplanned Repair	18/10/2018	08:43	18/10/2018	09:03	239,393	Taunton	TN019697
45 Engine Oil Top Up	Top up engine oil						
SAFETY INSPECTION	22/10/2018	11:22	23/10/2018	15:32	240,285	Taunton	TN019719
02 Cab Assembly 1	replace interior lamp bulb						
18 Wheels Check Torques							
86 Door Lock	replaced siezed rear door key lock and outer barrel						
89 Seatbelts	replaced damaged offside seat belt						
89 Seats	Replace rear attendants seat base						

Safety Inspection	Carry out safety inspection						
92 - C Service	Carry out C service						
Service C							
Travel Time							
MOT	test no - 477896597147						
Vehicle Deep Clean	23/10/2018	11:00	23/10/2018	15:45	240,285	Taunton	TN019734
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	14/11/2018	09:00	14/11/2018	09:46	244,513	Taunton	TN019859
34 Lights Bulb Replacement	Replace o/s headlamp bulb [dip beam]						
71 Body Exterior 1	Body Exterior Step is jamming and not deploying						
71 Body External Steps	Side step not deploying lube and test						
Unplanned Repair	19/11/2018	08:17	30/11/2018	14:36	244,976	Taunton	TN019886
45 Engine 1	Engine Engine cutting out.Gears slipping. SEE NOTES						
71 Body External Steps	Side step warning all the time repair switch on side step						
SAFETY INSPECTION	29/11/2018	07:10	30/11/2018	12:12	244,976	Taunton	TN019951
13 Brake Test	Carry out brake test						
16 Suspension 1	Replace rear anti roll bar bushes						
18 Wheels Check Torques							
86 Sliding Door	Sliding door top magnet not touching adjust						
Medical Devices Check	Check battery health on mobi med 96% & 97%						
Safety Inspection	Carry out safety inspection						
Sealing of stretcher clamp	Sealing of stretcher clamp						
Gearbox Oil & Filter Change	Carry out gearbox oil and filter change						
Vehicle Deep Clean	30/11/2018	08:50	03/12/2018	15:42	244,976	Taunton	TN019961
Vehicle Deep Clean	Vehicle Deep Clean						

ACCIDENT	03/12/2018	07:23	03/12/2018	11:51	244,976	Taunton	TN019969
34 Lights 71 Body Exterior Acc Repair	Replace ns headlight and adjust accident damage to nsf to go to body shop						Awaiting Body Repair
Unplanned Repair	05/12/2018	14:44	05/12/2018	15:34	245,279	Taunton	TN019992
71 Body External Steps	SEE NOTES						
BREAKDOWN	07/12/2018	15:23	11/12/2018	13:58	245,631	Taunton	TN020016
01 Heating 1 45 Engine 1 71 Body Exterior 1 71 Body External Steps	Heater not working test heater unbale to fault E.M.L light on power loss SEE NOTES Replace nsr bottom corner Side step not coming out staighthen step and lubricate						
Unplanned Repair	17/12/2018	07:14	17/12/2018	13:15	245,927	Taunton	TN020063
01 Heating 1	Rear heater intermitant , see notes						
Unplanned Repair	07/01/2019	11:30	07/01/2019	12:09	250,311	Taunton	TN020178
45 Engine Oil Top Up 86 Door Lock	Topped up 1ltr (non stock) Inv c/locking tempermental - replaced key fob battery						
SAFETY INSPECTION	14/01/2019	11:37	15/01/2019	15:43	251,354	Taunton	TN020223
02 Cab Assembly 1 02 Cab Assembly 2 18 Wheels Check Torques 34 Emergency Lights 34 Lights 45 Engine Oil Top Up 55 Tail Lift 71 Body Exterior Acc Repair 71 Body External Steps	centre cab cupboard lid adrift centre dash panel broken around radio carried out brake test and road test top left side blue light damaged and inoperative nearside fog lamp cover missing top up engine oil level lights and slow close inoperative , see notes accident damage to nsf to go to body shop side step only coming out half way						Awaiting Parts Awaiting Parts

89 Seats	rear attendant seat base cover split						Monitoring
Safety Inspection	carried out safety inspection						
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab						
Tail Lift 6 Monthly Inspection	Statutory Inspection carried out						
Vehicle Deep Clean	14/01/2019	10:00	15/01/2019	08:47	251,354	Taunton	TN020224
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	21/02/2019	08:00	22/02/2019	15:46	258,422	Taunton	TN020483
02 Cab Assembly 1	Replace inop cab interior light bulb						
02 Cab Assembly 2	centre dash panel broken around radio.Replaced						
03 Instruments & Sensors 1	Reset service indicator check for fault codes						
13 Brakes 1	Replace front discs pads						
13 Brakes 2	Replace worn rear disc pads						
16 Suspension 1	Replace worn rear spring eye bushes						
17 Tyres	Replace worn rear tyres						
18 Wheels Check Torques	Carry out extended test drive and retorque as per trust policy carry out R.B.T						
34 Emergency Lights	O/S/F blue lights above cab 1xinop					Monitoring	
34 Lights	nearside fog lamp cover missing						
71 Body Exterior 1	Repair n/s/f upper corner						
71 Body External Steps	Side step sticking free off lube and test						
89 Seats	rear attendant seat base cover split						
Safety Inspection	Paper copy used by Chris Small						
93 - D Service							
Service D							
Vehicle Deep Clean	25/02/2019	08:00	25/02/2019	15:00	258,432	Taunton	TN020503
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	09/03/2019	15:29	11/03/2019	08:00	260,805	Taunton	TN020577
Breakdown	wing mirror casing needs tightening						

Unplanned Repair	27/03/2019	11:00	27/03/2019	12:10	264,401	Taunton	TN020681
54 Sirens	Inv siren inop - replaced faulty siren unit						
Breakdown	27/03/2019	18:38	29/03/2019	15:18	264,600	Taunton	TN020686
Breakdown	Replaced broken skylight glass & handles (inc cleaning & blastfilm)						
Vehicle Deep Clean	08/04/2019	11:00	08/04/2019	15:42	267,021	Taunton	TN020746
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	09/04/2019	11:10	11/04/2019	08:29	267,021	Taunton	TN020756
02 Mirrors	nearside mirror damaged , replaced front and rear covers						
17 Tyres Replace	replaced nearside and offside tyres						
18 Wheels Check Torques	carried out extended road test & retorque front wheels 180nm						
34 Emergency Lights	O/S/F blue lights above cab 1xinop						Monitoring
34 Lights	nearside front fog lamp cover missing						
44 Add Ad Blue	top up add blue , main tank						
45 Engine Oil Top Up	top up engine oil level						
71 Body External Steps	step sticking and high viz sticker missing , clean step and fit new decal						
85 Body Interior 1	bag shelf strap broken , replaced strap						
86 Door Lock	rear door lock inoperative with key						
86 Sliding Door	centre door bearings noisy						
Safety Inspection	carried out safety inspection						
UB Fire Suppression Service	carried out fire suppression service all ok						
Annual Heater Service	Annual Heater Service , see notes						
Annual Air Con Service	Annual Air Condition Service carried out						
Breakdown	22/04/2019	04:25	23/04/2019	13:27	269,360	Taunton	TN020830
45 Engine 1	Carry out diagnostic test SEE NOTES						
Breakdown	limp mode						
Travel Time	Collect parts from exeter						
Breakdown	26/04/2019	11:48	26/04/2019	12:00	270,003	Taunton	TN020876

Breakdown	Paint scratch N/S/R						
Unplanned Repair	13/05/2019	09:36	13/05/2019	15:58	273,171	Taunton	TN020969
34 Emergency Lights 45 Engine 1	O/S/F blue lights above cab 1xinop attend to vehicle cutting out . fuel rail sensor fault stored.SEE NOTES					Monitoring	
Vehicle Deep Clean	22/05/2019	11:00	22/05/2019	15:45	274,379	Taunton	TN021037
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/05/2019	08:38	24/05/2019	13:38	274,379	Taunton	TN021039
02 Cab Ass Fire Extinguisher 02 Mirrors 02 Windscreen 13 Brake Test 13 Brakes 1 15 Steering 1 16 Suspension 1 18 Wheels Check Torques 31 Battery Chassis 34 Emergency Lights 34 Lights 43 Exhaust System 1 55 Tail Lift 71 Body Exterior 1 85 Body Interior 1 86 Doors Safety Inspection Travel Time Axle Oil Change Replace Handbrake Cables Engine Change Oil & Filter	cab and saloon extinguishers expired , replaced both extinguishers offside door mirror damaged , replaced front and back covers chipped zone B carried out brake test nearside front caliper siezed , see notes slight play in steering rack arm nearside rear spring buffer split Replace chassis battery O/S/F blue lights above cab 1xinop nearside front fog lamp cover missing rear tail pipe corroded and holed decals missing from tail lift NSF LOWER CAP AND NSR LOWER CAP DAMAGED. see notes scoop strap damaged locker door lock spins new barrel required carried out safety inspection deliver DCA back to minehead and bring back 4501 Axle Oil Change , carried out 23.5.19 2.5 litres of oil Replace Handbrake Cables carried out oil and filter change					Monitoring Monitoring Monitoring Awaiting Parts Monitoring	
Unplanned Repair	30/05/2019	15:15	30/05/2019	16:19	275,239	Taunton	TN021086

02 Windscreen	chipped zone B					Monitoring	
17 Tyres Replace	Replaced o/s/r inner punctured tyre						
18 Wheels Retorque	Carry out extended test drive and retorque as per trust policy						
43 Exhaust System 1	Replaced tail pipe						
Unplanned Repair	18/06/2019	06:31	18/06/2019	06:33	278,984	Taunton	TN021209
34 Lights Bulb Replacement	Headlight bulb replaced by oo						
Breakdown	28/06/2019	11:52	28/06/2019	15:00	281,204	Taunton	TN021282
001 Recover Vehicle Breakdown	Vehicle Recovery , from wellington road taunton noise&smell.heavy steering.battery&coolant msg						
SAFETY INSPECTION	01/07/2019	08:00	04/07/2019	16:07	281,206	Taunton	TN021290
01 Air Conditioning 1	Air con compressor siezed replace compressor belt and pulleys						
02 Windscreen	chipped zone B						
13 Brake Test	Carry out brake test						
18 Wheels Check Torques							
34 Lights Bulb Replacement	Replace interior cab light bulb						
86 Sliding Door	Adjust to magnet						
Medical Devices Check	Check battery health on mobi med 83% & 95%						
Safety Inspection	Carry out safety inspection						
Tail Lift Inspection	Done by SWLIfts						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight done by SWLIfts						
Vehicle Deep Clean	03/07/2019	08:39	03/07/2019	15:04	281,206	Taunton	TN021314
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/07/2019	08:20	08/07/2019	10:07	281,478	Taunton	TN021342
42 Coolant System	Coolant light on replace bottle						

BREAKDOWN	12/07/2019	13:32	12/07/2019	15:18	282,212	Taunton	TN021389
86 Doors Rear	ATTEND TO NEARSIDE REAR DOOR STAY BROKEN						
Unplanned Repair	23/07/2019	09:15	23/07/2019	10:01	284,311	Taunton	TN021461
34 Lights Bulb Replacement	Replaced o/s day running bulb						
87 Oxygen System	Inv O2 leak - found demand valve to be leaking - replaced						
Unplanned Repair	26/07/2019	07:45	26/07/2019	08:08	284,812	Taunton	TN021483
45 Engine Oil Top Up	Body Exterior Nearside /passenger door (bottom of)						
71 Body Exterior 1							
Breakdown	03/08/2019	16:44	05/08/2019	08:11	286,158	Taunton	TN021540
Breakdown	offside rear outer 205/75/r16c 113/111r replaced by ATS						
Vehicle Deep Clean	12/08/2019	11:00	13/08/2019	11:23	287,651	Taunton	TN021606
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/08/2019	09:28	14/08/2019	09:56	287,651	Taunton	TN021616
02 Mirrors	offside mirror damaged						
03 Instruments & Sensors 1	service light on , reset with texa						
13 Brake Test	carried out brake test , footbrake 43% handbrake 13% new rear brakes						
13 Brakes 2	rear pads low discs worn , replaced rear discs and pads						
15 Steering 1	slight play in inner rack arm						Monitoring
17 Tyres Replace	replaced inner and outer nearside rear tyres						
18 Wheels Check Torques	carried out extended road test and re torque 180nm both rears						
34 Emergency Lights	both top rear corner blue lights loose held on with tape see notes						
34 Lights	offside marker light inoperative , nearside fog lamp cover missing						
44 Add Ad Blue	top up adblue from main tank						
45 Engine Oil Top Up	topped up engine oil level . 1.5litres						
87 Stretcher	mattress split/holed , no new mattress in stock replace next safety						Awaiting Parts
Safety Inspection	carried out safety inspection						

Breakdown	17/08/2019	16:48	20/08/2019	13:35	288,226	Taunton	TN021639
17 Tyres	Replace punctured o/s/r outer tyre						
Breakdown	noise above 50mph from near side.SEE NOTES						
Travel Time	Deliver vehicle to minehead station						
Unplanned Repair	13/09/2019	15:00	13/09/2019	15:31	292,166	Taunton	TN021819
02 Mirrors	replaced nearside mirror backing and mirror glass						
SAFETY INSPECTION	23/09/2019	12:00	27/09/2019	15:48	293,917	Taunton	TN021880
01 Air Conditioning 1	Saloon A/C inop SEE NOTES						
01 Air Conditioning 2	Condenser fan for saloon seized parts ordered						Awaiting Parts
02 Mirrors	Replace ns mirror glass						
13 Brakes 1	Replace worn front discs and pads						
15 Steering 1	slight play in inner rack arm						
16 Suspension 1	Replace n/s/r spring slipper						
16 Suspension 2	Lift in n/s and o/s/f lower ball joints within tolerance						Monitoring
17 Tyres	Replace punctured o/s/r outer tyre. And worn n/s/f						
18 Wheels Check Torques	Carry out extended test drive as per trust policy carry out R.B.T						
27 Transmission Automatic	Replace propshaft centre mounting						
34 Emergency Light System	O/S/F blue light overcab 25% inop						Monitoring
34 Emergency Lights	Repair and resecure n/s/r blue corner light						
34 Lights	Replace damaged o/s side marker light						
43 Exhaust System 1	Replace cracked turbo to exhaust elbow						
44 Add Ad Blue							
45 Engine 1	Replace cracked E.G.R pipe						
45 Engine 2	Replace aux belt tensioner and belt						
55 Tail Lift	SEE NOTES						Monitoring
71 Body Exterior 1	Replace missing n/s/f missing fog lamp bezel						
71 Body External Steps	Lube sticking side step						
85 Body Interior 1	Replace damaged grab bag locker strap						
85 Body Interior 2	Carry chair mounting bracket damaged remove repair and refit						
85 Body Interior Roof	Sky light blind deteriorated						Monitoring
87 Stretcher	mattress split/holed , no new mattress in stock replace next safety						
Safety Inspection							
Pollen Filter Change	Pollen Filter Change						

Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Vehicle Deep Clean	25/09/2019	08:00	25/09/2019	15:57	293,917	Taunton	TN021898
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	16/10/2019	15:45	16/10/2019	16:08	297,499	Taunton	TN022042
52 Electrical Aux	Replace damaged shore line socket cover						
Vehicle Deep Clean	04/11/2019	10:45	04/11/2019	15:40	300,989	Taunton	TN022166
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	04/11/2019	11:48	07/11/2019	11:16	300,989	Taunton	TN022168
01 Air Conditioning 2	Condenser fan for saloon seized parts ordered						
03 Instruments & Sensors 1	reset service indicator with texa						
13 Brake Test	carried out brake test . footbrake 44% handbrake 16%						
16 Suspension 2	Lift in n/s and o/s/f lower ball joints within tolerance, see notes					Monitoring	
17 Tyres Replace	replaced offside front tyre						
18 Wheels Check Torques	carried out extended road test and retorque 180nm						
34 Emergency Light System	O/S/F blue light overcab 25% inop					Monitoring	
34 Lights	nearside front fog lamp cover missing again					Monitoring	
34 Lights Bulb Replacement	offside side light dim , replace bulb						
55 Tail Lift	SEE NOTES					Monitoring	
71 Body Exterior 1	bodywork damage below fuel filler .					Monitoring	
71 Body External Steps	side step sticking , lubricate side step and retest operation all ok						
85 Body Interior 1	drivers floor mat has a small split in it					Monitoring	
85 Body Interior Roof	Sky light blind deteriorated					Monitoring	
86 Sliding Door	centre door bearings noisy , replaced bearings						
89 Seats	nearside front seat arm rest loose , tighten bolt all ok						
Safety Inspection	carried out safety inspection						
Travel Time	take DCA to A 1 mot centre						
Engine Change Oil & Filter	carried out oil and filter change						
Brakes Replace Brake Fluid	brake fluid checked all ok not required this time						

MOT

SAFETY INSPECTION	16/12/2019	10:50	17/12/2019	15:27	308,515	Taunton	TN022507
02 Cab Assembly 1	drivers torch missing , FIT NEW TORCH FROM NON STOCK						
02 Cab Assembly 2	drivers door seal broken / split . replaced door seal						
02 Windscreen Wipers	not clearing screen , replaced front wiper blades						
13 Brake Test	carried out brake test . footbrake 38% handbrake 21%						
13 Brakes 1	brake pedal rubber worn						
16 Suspension 1	slight play in offside front shockabsorber						Monitoring
16 Suspension 2	Lift in n/s and o/s/f lower ball joints within tolerance, see notes						Monitoring
17 Tyres Replace	replaced both worn rear inner tyres						
18 Wheels Check Torques	carried out extended road test and re torque 180nm						
34 Emergency Light System	O/S/F blue light overcab 25% inop						Monitoring
34 Lights	nearside front fog lamp cover missing again						Monitoring
44 Add Ad Blue	top up ad blue from main tank						
45 Engine Oil Top Up	top up engine oil level						
55 Tail Lift	SEE NOTES						
71 Body Exterior 1	bodywork damage below fuel filler .						Monitoring
85 Body Interior 1	drivers floor mat has a small split in it						Monitoring
85 Body Interior Roof	Sky light blind deteriorated						Monitoring
86 Doors Rear	rear door lock inoperative with key. excessive play in top catch see notes						
86 Sliding Door	sliding door lock inoperative with key						
89 Seats	front attendant seat lower bearings u/s . see notes						
Check seat belt anchor points	nearside front seat belt frayed u/s new required						
Check Vehilce Call Signs	front white call sign coming adrift						
Medical Devices Check	mobimed batteries . 66% & 87% . replaced no1 battery						
Safety Inspection	carried out safety inspection						
Tail Lift Inspection	carried out loler inspection						
Vehicle Deep Clean	17/12/2019	11:40	18/12/2019	16:07	308,515	Taunton	TN022515
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	19/12/2019	18:09	20/12/2019	06:44	308,669	Taunton	TN022546
Breakdown	Off side rear hole rear corner cap replace at next safety						Awaiting Body Repair

Unplanned Repair	24/12/2019	15:00	24/12/2019	15:44	309,509	Taunton	TN022599
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Battery Chassis	attend to charging fault message on dash.Replace faulty chassis battery						
--------------------	---	--	--	--	--	--	--

SAFETY INSPECTION	27/01/2020	14:40	30/01/2020	11:51	315,339	Taunton	TN022867
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brake Test	carried out brake test , footbrake 45% handbrake 18%						
16 Suspension 1	slight play in offside front shockabsorber						Monitoring
16 Suspension 2	Lift in n/s and o/s/f lower ball joints within tolerance, see notes						Monitoring
18 Wheels Check Torques	carried out road test						
34 Emergency Light System	O/S/F blue light overcab 25% inop						Monitoring
34 Lights	nearside front fog lamp cover missing again						Monitoring
44 Add Ad Blue	top up adblue from main tank						
45 Engine Oil Top Up	topped up engine oil level . 1litre						
52 Electrical Aux	230v . pin bent over in socket , straighten pin test charging all ok						
55 Tail Lift	both side rails siezed , free of rails and lubricate						
71 Body Exterior 1	bodywork damage below fuel filler .						Monitoring
71 Body Exterior 2	both rear lower corner caps damaged , see notes						
71 Body External Steps	side step sticking in , straighten bar under step and lubricate step test ok						
85 Body Interior 1	drivers floor mat has a small split in it						Monitoring
85 Body Interior 2	infection control cupboard door struts not holding new required						Monitoring
85 Body Interior Roof	Sky light blind deteriorated						Monitoring
86 Doors Rear	door lock inoperative with key , and top catch required. see notes						
86 Sliding Door	top catch cover on sliding door damaged new required, not releasing inside						
Medical Devices Check	mobimed batteries . 99% & 80%						
Safety Inspection	carried out safety inspection						

Vehicle Deep Clean	29/01/2020	08:30	29/01/2020	15:32	315,339	Taunton	TN022880
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	03/02/2020	06:54	03/02/2020	07:53	315,893	Taunton	TN022909
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Headlight bulb replaced by oo						
----------------------------	-------------------------------	--	--	--	--	--	--

Unplanned Repair	05/02/2020	08:31	05/02/2020	08:34	316,128	Taunton	TN022938
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Headlight bulb replaced by oo						
----------------------------	-------------------------------	--	--	--	--	--	--

Breakdown	08/02/2020	21:45	10/02/2020	09:45	316,128	Taunton	TN022970
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Deep clean - due to Coronavirus SEE emergency deep clean TN022973						
-----------	---	--	--	--	--	--	--

Emergency Deep Clean	10/02/2020	09:15	10/02/2020	14:03	316,631	Taunton	TN022973
-----------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Emergency Deep Clean							
----------------------	--	--	--	--	--	--	--

Unplanned Repair	20/02/2020	14:30	26/02/2020	10:00	318,212	Taunton	TN023071
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

03 Instruments & Sensors 1	Inv Brake forscce distribution, ABS, ESP & EML lights on - SEE NOTES						
31 Battery Comms	Tested & replaced faulty comms bty & reset comms						
33 Ignition System	Mercedes replaced & coded new ign switch & 1x key (c/locking fault)						
Travel Time	take vehicle to merc taunton for repairs & collected						

SAFETY INSPECTION	09/03/2020	08:00	13/03/2020	15:45	319,931	Taunton	TN023199
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Replace rear a/c condenser and fan.Replace						
02 Cab Assembly 1	Replace interior light bulb						
03 Instruments & Sensors 1	Reset service indicator						
13 Brakes 1	Replace worn brake pads						
16 Suspension 1	slight play in offside front shockabsorber						
16 Suspension 2	Lift in n/s and o/s/f lower ball joints within tolerance, see notes						
17 Tyres	Replace worn o/s/r outer tyre						
18 Wheels Check Torques							
34 Emergency Light System	O/S/F blue light overcab 25% inop						
34 Lights	nearside front fog lamp cover replaced						
45 Engine 1	Replace leaking injector seals						
45 Engine 2	Investigate noise from front of engine SEE NOTES						
45 Engine 3	Noise from engine tappets? will monitor						
52 Electrical Aux	Replace shoreline charger cover						
71 Body Exterior 1	bodywork damage below fuel filler .						
71 Body Exterior 2	Replace side step mudflap						
71 Body External Steps	Replace worn side step motor						
85 Body Interior 1	drivers floor mat has a small split in it						
85 Body Interior 2	infection control cupboard door struts not holding new required						
85 Body Interior 3	Replace inop door step light						

Monitoring

85 Body Interior Roof Sky light blind deteriorated
86 Door Seals Replace rear door seals
Safety Inspection
Auto G/box Oil & Filter Change Auto G/box Oil & Filter Change
Tail Lift Inspection
UB Fire Supp 6mts Service UB Fire Supp 6mts Service

Vehicle Deep Clean 13/03/2020 09:45 13/03/2020 16:00 319,941 Taunton TN023252

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair 18/03/2020 15:50 19/03/2020 11:30 320,687 Taunton TN023287

45 Engine 1 attend to engine management light on ,see note

BREAKDOWN 28/03/2020 12:30 30/03/2020 09:03 321,977 Taunton TN023369

45 Engine 1 Viscous fan come adrift refit and tighten
Travel Time Call out travel to minehead and back

Unplanned Repair 08/04/2020 13:30 08/04/2020 14:50 323,878 Taunton TN023447

71 Body External Steps attend to step not deploying , lubricate step and test all ok
86 Sliding Door attend too sliding door stiff too open , see notes

Breakdown 08/04/2020 18:38 09/04/2020 12:31 323,905 Taunton TN023449

001 Recover Vehicle Travel to M/head, pushed in & secured step. Recovered back to Taunton
71 Body External Steps Inv side step not retracting - replaced motor
Breakdown side step not retracting; VOR

SAFETY INSPECTION 15/04/2020 07:00 17/04/2020 15:11 324,356 Taunton TN023474

02 Mirrors Replace n/s mirror glass
03 Instruments & Sensors 1 Carry out diagnostics test clear codes and reset service indicator

13 Handbrake	Adjust handbrake shoes and cable	
17 Tyres	Replace worn tyres n/s f 2x n/s/r clean hubs and rims	
18 Wheels Check Torques	Carry out extended test drive and retorque	
45 Engine 1	SEE NOTES	
45 Engine 3	Noise from engine tappets? will monitor	Monitoring
54 Sirens	Bull horn inop replace switch non stock part	
55 Tail Lift	Fit new mercury switch	
71 Body Exterior 1	Repair o/s/r lower corner replace cap and reflector	
71 Body Exterior 3	Tail lift guide blocks insecure remove drill out bolts replace nutserts refit	
85 Body Interior 1	Chair track locker insecure repaired	
86 Doors Rear	Replace large rear door stay bar	
89 Seats	Saloon swivel seats plunger nuts insecure adjust and resecure	
Safety Inspection		
Annual Air Con Service	Annual Air Condition Service	
Annual Heater Service	Annual Heater Service	
UB Fire Supp 12mts Service	Service of fire suppression system	
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test	
Engine Change Oil & Filter		

Vehicle Deep Clean	17/04/2020	07:07	17/04/2020	14:18	324,366	Taunton	TN023484
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	30/04/2020	07:15	01/05/2020	14:45	326,375	Taunton	TN023581
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

001 Recover Vehicle	Travel to M/Head, connect bty pack to give additional power & drove back
01 Heating 1	Inv cab blowers stuck on hot air regardless of temp switch position see notes
31 Charging System	Replaced faulty alternator (done by SB - assessed by PF) inc discussions
71 Body External Steps	Lubricated sticking side step
Breakdown	Alternator W/L on
Road Test	carried out extended road test

BREAKDOWN	23/05/2020	08:27	23/05/2020	10:13	329,881	Taunton	TN023741
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

42 Coolant System	Engine coolant low warning light on - see eng activity
45 Engine 1	attend to coolant light on , see notes
Road Test	carried out extended road test , 10 miles all ok level all correct no light on

SAFETY INSPECTION	29/05/2020	09:18	01/06/2020	14:17	330,244	Taunton	TN023778
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	cab and saloon fire extinguisher expired , replaced both extinguishers	
02 Cab Assembly 1	tool box cover cracked	
02 Cab Assembly 2	floor mat split on edge (offside)	Monitoring
13 Brake Test	carried out brake test footbrake 42% handbrake 23 %	
16 Suspension 1	slight play in both front shockabsorbers	Monitoring
16 Suspension 2	replaced both rear anti roll bar bushes	
17 Tyres Replace	replaced offside front tyre	
18 Wheels Check Torques	carried out extended extended road test ref non start	
32 Starting System 1	attend to non start , see notes	
44 Add Ad Blue	topped up adblue	
45 Engine 1	replaced intake pipe bracket	
45 Engine 3	Noise from engine tappets? will monitor	Monitoring
45 Engine Oil Top Up	topped up engine oil level	
52 Electrical Aux	right hand scene light on genysis panel doesnt light up	Monitoring
55 Tail Lift	safety rails loose ,see notes	
71 Body Exterior 1	nearside front lower end cap damaged	Monitoring
86 Doors Rear	key inoperative in door lock , lsee notes	
Medical Devices Check	mobimed batteries , 95% & 78%	
Safety Inspection	carried out safety inspection	
Replace Handbrake Cables	checked all ok not required this time	
Tail Lift Inspection	carried out loler inspection	

Vehicle Deep Clean	02/06/2020	08:30	02/06/2020	14:18	330,259	Taunton	TN023815
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	03/06/2020	15:00	03/06/2020	16:44	330,380	Taunton	TN023830
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1

Unplanned Repair	05/06/2020	14:00	19/06/2020	10:00	330,466	Taunton	TN023847
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

002 Major Unit Replace Eng	Engine replaced by Merc van centre Taunton
42 Coolant System	
45 Engine 1	Engine replaced by Merc van centre Taunton - see notes
Travel Time	Deliver to Mercedes.collect from dealers

Unplanned Repair	08/07/2020	11:00	08/07/2020	12:16	334,020	Taunton	TN024075
34 Emergency Lights	Replaced damaged o/s/r corner blue light						
SAFETY INSPECTION	15/07/2020	12:00	17/07/2020	16:47	335,451	Taunton	TN024115
02 Cab Assembly 1	Replace cab interior light bulb						
02 Cab Assembly 2	floor mat split on edge (offside)						
16 Suspension 1	slight play in both front shockabsorbers						
17 Tyres	Replace worn o/s/r inner tyre						
18 Wheels Check Torques	Carry out extended test drive and retorque						
34 Emergency Light System	Resecure n/s/r corner blue light						
34 Emergency Lights	Repair n/s wing blue light insecure						
34 Lighting System	N/S grill led inop clean connections and test all ok						
52 Electrical Aux	right hand scene light on genysis panel doesnt light up						
55 Tail Lift	Hand rails seized free off and lube						
71 Body Exterior 1	nearside front lower end cap damaged						
71 Body External Steps	External step sticking free off and lube						
86 Door Lock	Replace ignition key battery						
86 Doors	Rear door lock inop remove panel lube and refit						
89 Seats	Resecure swival seat plunger nuts						
Safety Inspection							
Vehicle Deep Clean	15/07/2020	13:49	16/07/2020	15:45	335,451	Taunton	TN024117
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	28/07/2020	10:00	28/07/2020	15:44	337,173	Taunton	TN024213
34 Lights Bulb Replacement	Replace NS main beam						
Breakdown	29/07/2020	12:27	30/07/2020	09:14	337,436	Taunton	TN024222
Breakdown	Ramp will not raise.Replaced leaking hose top up oil and test all ok.						

Breakdown	03/08/2020	22:19	04/08/2020	13:35	337,436	Taunton	TN024259
56 Comms Power Failure Breakdown	Inv power fail of MDT & radio - back up bty failed - PCE contacted. no MDT POWER OR VMT						
Vehicle Deep Clean	21/08/2020	11:00	21/08/2020	15:34	341,293	Taunton	TN024400
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	21/08/2020	14:00	24/08/2020	13:49	341,293	Taunton	TN024405
13 Brakes 1	O/S/F brake binding on slides free off and lube.						
17 Tyres	Replace worn o/s/r outer tyre						
18 Wheels Check Torques	Carry out extended test drive and retorque						
44 Add Ad Blue							
45 Engine 1	Replace aux belt tensioner						
71 Body Exterior 1	Tail lift guide blocks insecure drill out broken bolt replace and resecure.						
71 Body External Steps	Free off and lube side step						
85 Body Interior 1	Replace struts in infection control locker door.						
85 Body Interior 2	Resecure swivel seat plunger nuts						
Safety Inspection							
Medical Devices Repair	21/08/2020	12:47	21/08/2020	12:54	341,293	MDT Taunton	TT000510
Decontaminated	Cleaned with clinell wipes						
Defect Sheet Present No							
Defect Sheet Present Yes							
Medical Devices Repair	O2 leak from outlet port, new service kit fitted lot no 45429						
Tail Lift 12M Service & Weight	27/08/2020	11:19	27/08/2020	13:30	341,293	Taunton	TN024456
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight done by SWLIfts						
Tail Lift Inspection							
Breakdown	01/10/2020	19:26	02/10/2020	11:06	347,667	Taunton	TN024702
34 Lights Bulb Replacement	replaced offside front day running light bulb						

Breakdown O/S Wing mirror and casing broken , see notes

Vehicle Deep Clean 07/10/2020 10:30 07/10/2020 15:38 348,639 Taunton TN024743

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 08/10/2020 13:00 13/10/2020 09:30 348,639 Taunton TN024754

02 Cab Assembly 1	drivers floor mat split	Monitoring
02 Windscreen	windscreen chipped	Monitoring
02 Windscreen Wipers	wipers not clearing screen , replaced wiper blades	
03 Instruments & Sensors 1	re-set service indicator with texa	
13 Brakes 1	front pads low , replaced front discs and pads	
16 Suspension 1	nearside front shockabsorber boot split	
16 Suspension 2	slight play in both front lower arm ball joints - within tolerance	Monitoring
16 Suspension 3	slight play in nearside front shockabsorber	Monitoring
17 Tyres Replace	replaced worn nearside tyre , inc cleaning of hub	
18 Wheels Check Torques	carried out extended road test	
18 Wheels Retorque	re-torque front wheels 180nm	
34 Lights Bulb Replacement	replaced offside day running light bulb	
44 Add Ad Blue	top up adblue from main tank	
55 Tail Lift	warning message tail lift deployed , see notes	
71 Body Exterior 1	damage under passengers door on sill	Monitoring
71 Body Exterior 2	left lower front saloon end cap damaged + top cap damaged	
71 Body External Steps	side step inoperative only coming out half way , lubricate step all ok	
86 Sliding Door	door stiff too open , centre and top bearings + not touching top magnet	
Safety Inspection	carried out safety inspection	
Supply Sat Nav	updated sat nav software too latest version 5.30	
Travel Time	take vehicle for mot test	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card , linked too clear	
Air Filter Change	Air Filter Change , replaced air filter	
Fuel Filter Change	Change Fuel Filter , replaced fuel filter	
Pollen Filter Change	Pollen Filter Change , replaced pollen filter	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service , carried out all ok	
MOT	carried out mot test at A1 mot centre	
Engine Change Oil & Filter	carried out oil and filter change	

Unplanned Repair 26/10/2020 07:00 26/10/2020 07:53 350,237 Taunton TN024852

34 Lights Bulb Replacement	Replace os daytime running and ns side light bulb						
42 Coolant System	Top up coolant						
45 Engine Oil Top Up	Top up engine oil						
Unplanned Repair	26/10/2020	11:39	26/10/2020	13:13	350,297	Taunton	TN024856
34 Lights	bulbholder in os headlight burnt out replace os headlight						
Breakdown	31/10/2020	08:05	01/11/2020	09:30	350,593	Taunton	TN024912
Breakdown	ESP & alternator lights on , see notes						
Unplanned Repair	03/11/2020	10:12	03/11/2020	12:22	350,795	Taunton	TN024938
17 Tyres Replace	Replace all 4 rear tyres						
45 Engine 1	Noise from engine noisey viscous fan replace fan and test						
Unplanned Repair	13/11/2020	09:37	13/11/2020	13:34	352,059	Taunton	TN025012
31 Battery Chassis	Chassis battery failed and not holding charge replace battery						
31 Battery Comms	Comms battery reading 0 volts on genysis display SEE NOTES						
Breakdown	Check for non start/charging fault						
SAFETY INSPECTION	16/11/2020	08:52	18/11/2020	13:11	352,211	Taunton	TN025021
13 Brake Test	Carry out brake test						
18 Wheels Check Torques							
34 Lights Bulb Replacement	Replace nsf side light bulb and cab interior bulb						
43 Exhaust System 1	DPF bracket broken and hole in dpf replace dpf						
85 Body Interior 1	Replace broken line strapp in scoop cupboard						
86 Door Lock	Replace key battery						
Medical Devices Check	Check batteries on mobi med 100% & 91%						
Safety Inspection	Carry out safety inspection						
Tail Lift Inspection	Carry out tail lift inspection						
Vehicle Deep Clean	16/11/2020	14:00	17/11/2020	13:11	352,211	Taunton	TN025034

Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	26/12/2020	12:00	28/12/2020	11:35	358,968	Taunton	TN025333
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/12/2020	07:00	27/12/2020	15:06	358,968	Taunton	TN025336
03 Instruments & Sensors 1	Reset service indicator check for fault codes						
13 Brake Pads	Replaced worn rear pads inc cleaning faces & lubing sliders						
17 Tyres	Replace worn front tyres.						
18 Wheels Check Torques	Carry out extended test drive and retorque carry out R.B.T						
34 Emergency Lights	Replaced faulty o/s/r side blue LED light						
34 Lights Bulb Replacement	Replaced n/s side light bulb						
71 Body Exterior 1	Resecured rear mudflap mount						
71 Body Exterior 2	Resecured arch liners to front bumper						
71 Body External Steps	Lubed & freed off sticking side step						
Safety Inspection							
Unplanned Repair	04/01/2021	12:44	04/01/2021	13:46	360,320	Taunton	TN025415
11 Axle Rear	Investigate noise from rear unable to reproduce or hear noise						
Unplanned Repair	11/01/2021	12:40	11/01/2021	14:50	361,686	Taunton	TN025469
33 Ignition System	key remote blip inoperative - replaced battery test all ok						
71 Body External Steps	side step not deploying fully - lubricate step re-test all ok						
86 Sliding Door	sliding door not opening correctly see notes						
ACCIDENT	25/01/2021	13:27	26/01/2021	16:16	364,730	Taunton	TN025579
02 Windows/Glass	os pod window smashed						
Travel Time	Take to bodyshop & window installer for replacement of broken side window						

Unplanned Repair	30/01/2021	12:27	30/01/2021	14:36	365,611	Taunton	TN025624
02 Mirrors	Replace os and ns mirror glasses						
17 Tyres Replace	Puncture osr inner tyre replace tyre						
86 Door Lock	Replace key battery						
Vehicle Deep Clean	06/02/2021	10:14	07/02/2021	07:40	366,162	Glastonbury Workshop	GW020425
SAFETY INSPECTION	04/02/2021	08:30	08/02/2021	15:52	366,162	Taunton	TN025665
01 Air Conditioning 1	Saloon a/c evaporator inop SEE NOTES						
13 Brakes 1	Adjust park brake						
13 Brakes 2	Telma rubbing, remove plate and space out.						
18 Wheels Check Torques							
34 Emergency Lights	Resecure damaged n/s/r corner blue light [no new parts]						
34 Lights	Replace NSR fog light						
45 Engine Oil Top Up	Top up 1.5ltr						
52 Electrical Aux	Replace ign key battery						
71 Body Exterior 1	Body damage - See notes						
71 Body External Steps	Lubricate side step						
85 Body Interior 1	CCTV fault. Plug in diagnostics and reformat HDD						
85 Body Interior 2	Resecure swivel seat plunger nuts. Carry chair catch see notes.						
85 Body Interior 3	Resecure tracker locker door jamb. Realign front locker door.						
86 Door Lock	Rear door barrel seized - replaced.						
86 Sliding Door	Replace external bearings, straighten upper magnet, resecure lower catch cover.						
Safety Inspection							
Tail Lift Inspection	N.S hand rail seized strip free off lube and refit						
Vehicle Deep Clean	08/02/2021	09:18	08/02/2021	13:28	366,162	Taunton	TN025704
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	19/02/2021	13:00	19/02/2021	15:30	367,949	Taunton	TN025807

02 Windscreen Wipers	unblock washer jet/pipes
52 Electrical Aux	Investigate comms. Reboot and all working.
86 Door Lock	Replace key battery

SAFETY INSPECTION	22/03/2021	08:00	24/03/2021	12:00	373,298	Taunton	TN026039
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Saloon a/c evaporator fan seized new parts to be ordered	Awaiting Parts
02 Cab Ass Fire Extinguisher	Replace Cab and saloon.	
03 Instruments & Sensors 1	Reset service indicator and clear stored fault codes	
13 Brakes 1	Replace worn front brake pads free off and replace n/s/f caliper slides.	
18 Wheels Check Torques		
34 Emergency Lights	Replace broken nsr top blue light (carry out repair to mounting points]	
45 Engine 1	Oil leak SEE NOTES	
52 Electrical Aux	Replace o/s window switch	
71 Body Exterior 1	NS cab pod alloy support insecure. Reattach.	
71 Body External Steps	Replace 1x roller clean and lube.	
86 Door Lock	Replace key battery	
86 Sliding Door	Realign top magnet	
Safety Inspection		
Engine Change Oil & Filter		

Vehicle Deep Clean	23/03/2021	13:00	24/03/2021	15:47	373,298	Taunton	TN026049
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	02/04/2021	14:00	03/04/2021	14:31	373,989	Taunton	TN026132
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	Mirrors O/S mirror cracked
13 Brakes 1	Inv ABS w/l on - see notes
86 Door Lock	Replaced key fob battery
99 Diagnostic Test	Reconfigure vci on xentry after collectiong from mercedes
Travel Time	Collect parts from exeter

Unplanned Repair	05/04/2021	13:00	07/04/2021	15:31	374,068	Taunton	TN026136
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brakes 1	A.B.S WARNING LIGHT ON
18 Wheels Retorque	Carry out extended test drive and retorque.

Unplanned Repair	22/04/2021	14:55	22/04/2021	16:05	377,159	Taunton	TN026260
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Door handle	Replaced broken side door handle & adjusted mech as req'd						
----------------	---	--	--	--	--	--	--

SAFETY INSPECTION	05/05/2021	11:06	07/05/2021	16:06	379,705	Taunton	TN026348
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Saloon a/c evaporator fan seized new parts to be ordered	
02 Cab Assembly 1	tool box cover / lid broken	
02 Cab Assembly 2	passengers window switch broken	
02 Mirrors	Body Exterior Left wing mirror broken from connecting to a hedge	
02 Windscreen Wipers	wipers not clearing screen , replaced wiper blades	
13 Brake Test	carried out brake test . footbrake 50% handbrake 27%	
13 Brakes 2	rear pads low , replaced rear discs and pads	
18 Wheels Check Torques	carried out 10mile road test and re-torque of rear wheels	
18 Wheels Retorque	re-torque rear wheels 180nm	
34 Emergency Lights	1 x led in right side of roof bar inoperative	Monitoring
44 Add Ad Blue		
45 Engine Oil Top Up	topped up engine oil level	
71 Body External Steps	side step not deploying fully , lubricate step	
85 Body Interior 1	bottom draw broken back adrift , removed draw and carry out repairs	
85 Body Interior 2	rear attendant seat locking pin loose in base , re-secure locking pin	
85 Body Interior 3	oxygen bottle door catches worn on bottom , replaced catches	
86 Doors Rear	rear door not opening from inside top or bottom - adjustment of cables required	
86 Sliding Door	top magnet not touching door mount + top catch broken	
Install Saloon CCTV Camera	cctv checked all ok no faults	
Medical Devices Repair	epcr cradle broken	
Safety Inspection	carried out safety inspection	
Supply Sat Nav	update sat nav	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service , linked to clear	
UB Fire Supp 12mts Service	Service of fire supression system , carried out all ok	
Annual Heater Service	Annual Heater Service , carried out see notes	
Annual Air Con Service	Annual Air Condition Service , carried out kit used from non stock	
Tail Lift Inspection	carried out loler inspection	

Unplanned Repair	14/05/2021	07:50	14/05/2021	08:02	380,487	Taunton	TN026421
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement replaced nearside front headlamp bulb

Unplanned Repair **02/06/2021** **09:00** **02/06/2021** **10:05** **383,799** **Taunton** **TN026572**

34 Lights Bulb Replacement Replace OS dipped beam.

Unplanned Repair **03/06/2021** **11:55** **03/06/2021** **13:30** **383,885** **Taunton** **TN026585**

31 Battery Aux Inv t/lift battery low - see notes - sensor fault

SAFETY INSPECTION **18/06/2021** **11:33** **21/06/2021** **14:46** **386,489** **Taunton** **TN026700**

13 Brake Test Carry out brake test
 16 Suspension 1 Replace rear anti roll bar bushes
 17 Tyres Replace Replace both front tyres
 18 Wheels Check Torques
 34 Lights Bulb Replacement Replace osf side light bulb
 45 Engine Oil Top Up Top up engine oil
 54 Sirens Bull horn not working repair bull horn switch
 55 Tail Lift Free off and lubricate stretcher lock and ns rail
 71 Body External Steps Side step not deploying starighten and lubricate
 86 Door Lock Replace female side door catches
 86 Sliding Door Adjust top door magnet
 Safety Inspection Carry out safety inspection
 Replace Handbrake Cables Not required in good condition

Vehicle Deep Clean **21/06/2021** **15:15** **23/06/2021** **13:30** **386,491** **Taunton** **TN026718**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **05/07/2021** **09:54** **05/07/2021** **14:09** **388,364** **Taunton** **TN026807**

42 Coolant System Replace leaking radiator
 Breakdown Engine keeps losing coolant fluid

Unplanned Repair	07/07/2021	08:00	07/07/2021	15:37	388,690	Taunton	TN028632
17 Tyres Replace	o/s/f punctured tyre replaced by ATS						
Breakdown	22/07/2021	23:33	23/07/2021	13:23	392,579	Taunton	TN026964
Breakdown	side step not deploying operation being used by crew						
Unplanned Repair	27/07/2021	13:15	27/07/2021	13:47	393,254	Taunton	TN027014
71 Body External Steps	Side step damage SEE NOTES						
Vehicle Deep Clean	28/07/2021	08:17	28/07/2021	15:04	393,301	Taunton	TN027023
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	28/07/2021	14:24	30/07/2021	11:55	393,301	Taunton	TN027031
13 Brake Test	Carry out brake test						
18 Wheels Check Torques							
45 Engine Oil Top Up	Top up engine oil						
52 Electrical Aux	Replace broken 240v socket						
71 Body Exterior 1	Replace damaged nsf bottom corner						
71 Body Exterior 2	Replace side step suppressor						
71 Body External Steps	Replace side step after being hit						
Safety Inspection	Carry out safety inspection						
Pollen Filter Change	Pollen Filter Change						
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
Tail Lift 12M Service & Weight	02/08/2021	09:30	02/08/2021	15:43	393,624	Taunton	TN027132
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight done by SWLifts						
Tail Lift Inspection							

Unplanned Repair	27/08/2021	07:00	27/08/2021	07:52	398,257	Taunton	TN027262
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Sliding Door	Side door wont open or shut remove foreign object and test ok
-----------------	---

SAFETY INSPECTION	08/09/2021	12:00	13/09/2021	15:55	399,971	Taunton	TN027357
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	drivers seat cover and cushion u/s - removed seat and replaced cover and cushion
13 Brakes 1	Replace front discs and pads and rear pads. Also OSF hub and abs sensor.
13 Brakes 2	Telma appeared to be rubbing see notes.
15 Steering 1	Power steering pump leaking - replace.
15 Steering 2	Steering rack leaking - replace.
16 Suspension 1	Excessive play in both lower arm ball joints - replace.
16 Suspension 2	Excessive play in both front shock absorbers - replace.
17 Tyres Replace	Replaced all 4 rear tyres due to low tread.
17 Tyres Tracking	Check alignment.
18 Wheels Check Torques	Carry out extended road test.
18 Wheels Retorque	
45 Engine 1	Replace broken air induction pipe affixing bracket.
54 Sirens	bull horn inoperative - see notes
71 Body Exterior 1	repair offside rear wheel arch
85 Body Interior 1	Swap out CCTV HDD.
85 Body Interior 2	Swivel seat area mic surround damaged. Swap with item from N/S.
86 Sliding Door	reposition top magnet position as not touching
Safety Inspection	
Engine Change Oil & Filter	
Fuel Filter Change	Change Fuel Filter
Air Filter Change	Air Filter Change

Vehicle Deep Clean	14/09/2021	08:45	14/09/2021	15:27	399,979	Taunton	TN027383
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	13/10/2021	09:00	13/10/2021	09:15	402,083	St Leonards	SL034660
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

44 Add Ad Blue	Top up Ad blue
----------------	----------------

Vehicle Deep Clean	25/10/2021	07:29	25/10/2021	11:00	402,842	St Leonards	SL034750
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	26/10/2021	09:00	29/10/2021	10:00	402,842	St Leonards	SL034762
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

01 Heating 1	Replace saloon heater exhaust	
02 Windscreen Wipers	Replaced	
15 Steering 1	Tighten loose track rod end nut	
16 Suspension 1	Tighten loose front sub frame bolts and replace susp arms	
17 Tyres	Tyres PUNCTURED TYRE DRIVERS FRONT	
18 Wheels Check Torques		
34 Emergency Lights	Replace n/s/f blue light cover	
34 Lighting System	Replace 2x front top marker lights ans scene light	
45 Engine 1	Replace belt tensioner	
71 Body Exterior 1	Damage to n/s sill and n/s/r wheel arch damaged	Monitoring
86 Doors	Replace saloon door seal	
86 Doors Rear	Secure rear door grab handle	
86 Sliding Door	Adjsut side door catches and cables	
Safety Inspection		
Tail Lift Inspection		
MOT		

Breakdown	15/11/2021	14:14	16/11/2021	06:00	403,454	St Leonards	SL034957
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	FIRE SUPPRESSION SYSTEM DEPLOYED ENG MAN WARNING	Monitoring
-----------	--	------------

Breakdown	21/11/2021	16:55	22/11/2021	07:00	403,990	St Leonards	SL035022
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

32 Starting System 1	Starting fault? Check batteries. Replace chassis battery
Breakdown	battery issue

Vehicle Deep Clean	06/12/2021	09:29	06/12/2021	13:11	404,487	St Leonards	SL035160
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	06/12/2021	07:00	08/12/2021	15:00	404,590	St Leonards	SL035169
18 Wheels Check Torques							
71 Body Exterior 1 Breakdown	Damage to n/s sill and n/s/r wheel arch damaged FIRE SUPPRESSION SYSTEM DEPLOYED ENG MAN WARNING						
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Brake Fluid Change	Brake Fluid Change						
Unplanned Repair	29/12/2021	10:45	29/12/2021	11:45	405,343	St Leonards	SL035325
01 Heating 1	Cab heater inop. Replace motor						
Vehicle Deep Clean	26/01/2022	08:02	26/01/2022	10:00	406,658	St Leonards	SL035572
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/01/2022	10:00	27/01/2022	12:00	406,658	St Leonards	SL035573
02 Cab Ass Fire Extinguisher	Out of date x2. Replaced x2.						
02 Cab Assembly 1	Cubby box catch missing. Replaced.						
16 Suspension 1	Rear spring buffer pads torn x2. Replaced.						
17 Tyres Replace	N/S/F tyre wearing outer edge. Replaced.						
17 Tyres Tracking	Reset tracking.						
18 Wheels Check Torques	Checked.						
55 Tail Lift	O/S Hand rail bent.N/S rail twisted. Repaired both.						
71 Body External Steps	Body Exterior REAR STEP ALTHOUGH NO DAMAGE RECORDED						
Safety Inspection	Carried out inspection.						
Tail Lift Inspection	Done.						
O2 Pipeline Annual Inspection	18/02/2022	10:21	18/02/2022	10:27	407,720	MDT Ferndown	TF001806
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
87 Oxygen System	Repair - replaced 2x kinked O2 connection probes.						

Unplanned Repair	21/02/2022	09:45	21/02/2022	10:49	407,748	St Leonards	SL035798
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights	N/S headlight n/w. Replaced bulb.
87 Stretcher	Put back in service with no stretcher battery!!.. Battery taken from 9814

SAFETY INSPECTION	21/03/2022	05:00	21/03/2022	15:00	409,408	St Leonards	SL036004
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked
Safety Inspection	Checked.
Tail Lift Inspection	Inspected
89 Seats	Repair saloon seats
44 Add Ad Blue	Fill up Add Blue 9L
71 Body External Steps	Lube up unit Repair Damaged side.
34 Emergency Lights	Repair bull horn

Vehicle Deep Clean	22/03/2022	08:07	23/03/2022	08:33	409,414	St Leonards	SL036024
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	06/05/2022	20:28	09/05/2022	06:00	414,337	St Leonards	SL036448
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Side door handle stuck out & unable to open door	Monitoring
-----------	--	------------

SAFETY INSPECTION	09/05/2022	07:00	09/05/2022	07:00	414,337	St Leonards	SL036458
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	

SAFETY INSPECTION	09/05/2022	07:00	13/05/2022	15:00	414,337	St Leonards	SL036459
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Breakdown	Side door handle stuck out & unable to open door
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
UB Fire Supp 12mts Service	Service of fire supression system
02 Windscreen Wipers	

44 Add Ad Blue
 13 Brakes 1
 34 Emergency Light System Fit new gen panel. as old one was Damaged.
 86 Sliding Door
 34 Lights Bulb Replacement

ACCIDENT	10/05/2022	07:00	10/05/2022	15:00	414,337	St Leonards	SL036478
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior Acc Repair N/S Ext Damage to side door Runners Hinges Body covers x More.

Vehicle Deep Clean	13/05/2022	07:00	13/05/2022	07:00	414,337	St Leonards	SL036545
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean	13/05/2022	07:00	13/05/2022	12:00	414,337	St Leonards	SL036546
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair	24/05/2022	07:00	24/05/2022	07:30	415,197	St Leonards	SL036652
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Sliding Door Body Exterior Side step going in and out while driving - Replace catch.

SAFETY INSPECTION	18/07/2022	09:00	21/07/2022	15:00	419,285	St Leonards	SL037126
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked
Safety Inspection	Checked
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	Checked
44 Add Ad Blue	Add Blue warning light on.
34 Lights	Replace o/s/f runing light.
34 Emergency Lights	Replace o/s search light.
13 Brakes 1	Replace worn out handbrake shoes. Full kit.
13 Brakes 2	Replace worn out Rear Dics & Pads.
11 Axle Rear	Replace worn out Rear Wheel bearings
Wheel Hub Flanges Replaceme	Fitted
17 Tyres Replace	Replace damaged O/S/F Tyre
45 Engine 1	LOP. Drile out Exhaust manifold Replace broken studs.
13 Brake Pads	F/Pads getting low replace next S/l. J.S

ACCIDENT	18/07/2022	13:30	21/07/2022	15:00	419,285	St Leonards	SL037129
71 Body Exterior Acc Repair Damage to N/S B post Inner seal. Outer seal. Door X More. Bodyshop Req							
Vehicle Deep Clean	21/07/2022	13:43	22/07/2022	11:00	419,285	St Leonards	SL037160
Vehicle Deep Clean Vehicle Deep Clean							
Breakdown	26/07/2022	19:56	09/08/2022	10:00	419,489	St Leonards	SL037190
Breakdown Brakes Spongy 13 Brakes 1 Brake fault							
Breakdown	14/08/2022	11:31	15/08/2022	15:00	420,118	St Leonards	SL037315
Breakdown Non start 32 Starting System 1 Non start							
Unplanned Repair	25/08/2022	13:30	25/08/2022	14:30	421,107	St Leonards	SL037383
31 Battery Chassis Test and replace							
Vehicle Deep Clean	20/09/2022	09:47	20/09/2022	09:51	423,336	St Leonards	SL037582
Vehicle Deep Clean Vehicle Deep Clean							
Vehicle Deep Clean	20/09/2022	09:52	21/09/2022	11:17	423,337	St Leonards	SL037585
Vehicle Deep Clean Vehicle Deep Clean							
SAFETY INSPECTION	21/09/2022	09:00	21/09/2022	09:01	423,338	St Leonards	SL037601
18 Wheels Check Torques Safety Inspection							

SAFETY INSPECTION	21/09/2022	09:05	22/09/2022	15:00	423,338	St Leonards	SL037602
18 Wheels Check Torques	Checked.						
Safety Inspection	Checked						
Engine Change Oil & Filter	Changed						
Tail Lift Inspection	Inspected						
44 Add Ad Blue	Top up unit 11L						
45 Engine 1	Oil Leak to rear of Engine. Clean off oil Fit new induction pipe.						
52 Electrical Aux	Replace battery on stret						
56 Comms Equipment	Replace damaged N/S Mic						
13 Brake Pads	Replace F/Pads.						
71 Body External Steps	step slow						
BREAKDOWN	11/10/2022	09:30	11/10/2022	10:30	424,081	St Leonards	SL037797
86 Sliding Door	DOOR NOT OPENING, cables come loose , adjusted & secured.						
SAFETY INSPECTION	01/11/2022	10:00	03/11/2022	16:00	425,284	St Leonards	SL037996
18 Wheels Check Torques							
Safety Inspection							
MOT							
27 Transmission Automatic	fit new prop shaft						
Vehicle Deep Clean	03/11/2022	09:00	04/11/2022	08:00	425,284	St Leonards	SL038023
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	07/11/2022	11:25	07/11/2022	11:59	425,663	St Leonards	SL038049
34 Lights Bulb Replacement	Replace headlamp bulb and sidelight bulb						
ACCIDENT	20/11/2022	00:00	21/11/2022	09:00	426,947	St Leonards	SL038175

71 Body Exterior Acc Repair Replace damaged front number plate

Breakdown	15/12/2022	18:59	16/12/2022	10:00	428,500	St Leonards	SL038496
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	SatNav not powering on	Monitoring
Supply Sat Nav	Sat nav inop	
01 Heating 1	Saloon heater inop	

Unplanned Repair	20/12/2022	13:15	20/12/2022	14:15	428,971	St Leonards	SL038542
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Sliding Door	Side door not opening from outside. adjusted handle mech and adjust cables.
-----------------	---

Unplanned Repair	23/02/2023	10:00	23/02/2023	11:00	434,583	St Leonards	SL039185
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Doors Rear	stay damaged, removed repaired & refitted
---------------	---

Unplanned Repair	24/02/2023	14:00	27/02/2023	12:00	434,851	St Leonards	SL039205
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

27 Transmission Automatic	Replace gearbox mount
---------------------------	-----------------------

Breakdown	17/03/2023	05:44	17/03/2023	14:26	436,824	St Leonards	SL039400
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	wouldnt start
-----------	---------------

SAFETY INSPECTION	20/03/2023	11:30	23/03/2023	13:26	437,163	St Leonards	SL039419
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
86 Doors Rear	Doors REAR TAIL LIFT DOOR STAY BROKEN
Tail Lift Inspection	Done.
86 Door Lock	Rear door lock barrell siezed. Replaced vehicle lock set.
71 Body Exterior 2	Bull horn cover broken. Replaced.
02 Cab Assembly 1	Cubby box knob missing. Replaced.

34 Lights	N/S/F sidelight n/w. Replaced bulb.
34 Emergency Lights	N/S front scene light n/w. Replaced.
44 Fuel System 1	Leak from filter bleed pipe.Replaced.
02 Cab Assembly 2	Dash broken @ sat-nav mounting.Replaced (2nd hand parts).
Install Saloon CCTV Camera	cctv n/w, Formatted hard drive. Checked OK.
45 Engine 1	Injector seals leaking. Replaced x6.
55 Tail Lift	Tilt sensor n/w. Replaced.

02 Pipeline Annual Inspection	24/03/2023	12:39	24/03/2023	12:40	437,169	MDT Ferndown	TF002590
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - No faults found.

SAFETY INSPECTION	03/05/2023	15:00	05/05/2023	18:00	439,415	St Leonards	SL039998
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
71 Body Exterior 1	Siren external surround loose. replace x2 clips.						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Tail Lift Inspection							
13 Brakes 1	Front brakes worn. Replaced						
16 Suspension 1	Rear spring eye bushes worn and drop link bushes worn.						
45 Engine 1	Fan belt tensioner leaking oil. replaced						
34 Lights	OS Side marker u/s. replaced						
86 Sliding Door	Sliding door upper magnet torn. replaced.- wiring broken, rewire side door.						
43 Exhaust System 1	Tailpipe corroded. replaced tail pipe section.						
19 Chassis 1	step and rear mudflap loose. resecured						
89 Seats	Rear attendant seat bearings loose. retightened						
85 Body Interior 1	Fit Pclips for avp						
86 Doors Rear	Rear door hinges have play (monitor)					Monitoring	
19 Chassis 2	Vibration cause from front prop uj u/s. replaced						
19 Chassis 3	Telma rubbing causing noise when driving. no parts, to be ordered. (monitor)					Monitoring	
71 Body Exterior 2	ns tail light led out. no parts. (monitor)					Monitoring	
UB Fire Supp 12mts Service	Service of fire supression system						
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						

Vehicle Deep Clean	08/05/2023	07:00	08/05/2023	15:17	439,415	St Leonards	SL040036
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean	17/06/2023	14:03	18/06/2023	12:24	441,901	St Leonards	SL040612
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/06/2023	05:41	22/06/2023	13:19	441,901	St Leonards	SL040628
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Tail Lift Inspection	Done.						
Replace Handbrake Cables	Replace Handbrake Cables						
56 Comms Equipment	Roof aerial missing. Replaced.						
86 Door Lock	Scoop locker lock n/w.Replaced barrell housing.						
86 Doors Rear	Lower locking rod n/w.Ordered parts.						Awaiting Parts
34 Lights	N/S/R light pod broken. Replaced.						
Breakdown	05/07/2023	16:50	06/07/2023	05:04	443,075	St Leonards	SL040880
Breakdown	N/S TOP REAR B/L FLICKERING						
Replace Vehicle Fuel Card	11/07/2023	15:34	11/07/2023	15:34	443,702	St Leonards	SL041013
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Unplanned Repair	11/07/2023	15:00	11/07/2023	15:30	443,702	St Leonards	SL041014
31 Battery Comms	Comms battery 0.0 volts. (see notes)						
Unplanned Repair	12/07/2023	10:15	12/07/2023	10:44	443,783	St Leonards	SL041024
31 Battery Chassis	Test and replace						

Vehicle Deep Clean	27/07/2023	08:30	27/07/2023	15:00	445,050	St Leonards	SL041293
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	28/07/2023	10:00	29/07/2023	13:12	445,050	St Leonards	SL041308
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
19 Chassis 3	Telma rubbing causing noise when driving. no parts, to be ordered. (monitor)
71 Body Exterior 2	ns tail light led out. no parts. (monitor)
86 Doors Rear	Lower locking rod n/w.Ordered parts.
Pollen Filter Change	Pollen Filter Change
02 Glass / Windows	Passanger window switch broken
55 Tail Lift	Carry out inspection.
33 Ignition System	E.M.L. Illuminated on dashboard display system.
34 Emergency Lights	N/S/R Top 360 blue LED smashed.
34 Lights Bulb Replacement	O/S/F Side light bulb not working.

Unplanned Repair	21/08/2023	06:00	21/08/2023	11:01	445,168	St Leonards	SL041619
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Charging System	Battery/Charging Sys CHASSIS BATTERY FAULT
Travel Time	Travel to bournemouth hospital to look at tail lift stuck out.
55 Tail Lift	Tail lift not stowing. Managed to stow til lift, Power issue with tail lift.

Breakdown	28/08/2023	06:23	28/08/2023	18:36	447,429	St Leonards	SL041709
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Belt hangin from under the vehicle near the bonnet
-----------	--

Vehicle Deep Clean	04/09/2023	15:14	05/09/2023	10:00	447,429	St Leonards	SL041824
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	05/09/2023	16:00	06/09/2023	10:39	447,429	St Leonards	SL041834
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection
Tail Lift Inspection

Engine Change Oil & Filter	
Recall Notification	Mercedes airbag recall
02 Cab Assembly 1	Steering wheel in poor condition.

Breakdown	02/10/2023	19:49	03/10/2023	10:00	447,429	St Leonards	SL042172
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	EML & Limp mode (see notes)
86 Door Lock	Central locking inop - Replace key fob

SAFETY INSPECTION	19/10/2023	15:00	24/10/2023	20:48	455,245	St Leonards	SL042435
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
MOT	
Pollen Filter Change	Pollen Filter Change
24 Driveshaft 1	Both rear half shafts leaking. Cleaned and resealed.
13 Brake Pads	Rear brake pads worn. replaced
17 Tyres Replace	Both front tyres worn, replaced
85 Body Interior 1	Skylight blind missing. Replaced
86 Doors Rear	Large rear door bottom door lock pin sticking. Cleaned and freed

Vehicle Deep Clean	21/10/2023	09:00	22/10/2023	08:00	455,245	St Leonards	SL042458
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	16/11/2023	11:30	16/11/2023	11:45	457,191	St Leonards	SL042820
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights Bulb Replacement	Replace headlight bulb
----------------------------	------------------------

Unplanned Repair	22/11/2023	08:45	22/11/2023	12:40	457,651	St Leonards	SL042883
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	step u/s
------------------------	----------

BREAKDOWN	22/11/2023	14:20	22/11/2023	16:45	457,191	St Leonards	SL042896
Breakdown	SIDE STEP BROKEN						
BREAKDOWN	23/11/2023	08:38	23/11/2023	08:53	457,770	St Leonards	SL042905
13 Brakes 1 71 Body External Steps	ESP warning light on N/S Side step broken & requires replacing.						
Vehicle Deep Clean	28/11/2023	11:54	29/11/2023	08:30	458,209	St Leonards	SL042959
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	29/11/2023	11:00	29/11/2023	17:19	458,209	St Leonards	SL042969
18 Wheels Check Torques Safety Inspection Tail Lift Inspection 86 Door Seals 86 Sliding Door 13 Handbrake 34 Lights	Sliding door seal incomplete and damaged Lower catch not latching N/S Hand brake noise N/S side/stop light full of water and not all working						
BREAKDOWN	03/12/2023	14:38	04/12/2023	12:33	458,300	St Leonards	SL043032
13 Brakes 1	TELMA u/s						
Unplanned Repair	15/12/2023	15:00	18/12/2023	15:16	459,090	St Leonards	SL043217
11 Axle Front	O/S/F wheel bearing u/s						
Breakdown	28/12/2023	18:52	29/12/2023	13:37	459,711	St Leonards	SL043353
Breakdown Travel Time	Camber '+' overadjusted on osf wheel. adjusted camber to correct position. Travel to weymouth station, inspect veh and bring back to vmu.						

Vehicle Deep Clean	08/01/2024	07:06	08/01/2024	11:30	461,268	St Leonards	SL043507
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	09/01/2024	14:30	10/01/2024	14:11	461,268	St Leonards	SL043528
18 Wheels Check Torques							
Safety Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Brake Fluid Change	Brake Fluid Change						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
17 Tyres	n/s/r Inner tyre and o/s/r outer tyre below limit						
16 Suspension 1	Both N/S/R and O/S/R Front spring buffers split						
86 Sliding Door	Sliding door runner bearing siezed						
31 Battery Comms	Comms battery old and weak						
86 Doors Rear	Rear door hard to open/sticking						
02 Cab Assembly 1	Steering wheel to one side						
Unplanned Repair	01/02/2024	15:00	02/02/2024	08:00	462,993	St Leonards	SL043806
01 Air Conditioning 1	Air con compressor u/s						
Vehicle Deep Clean	26/02/2024	10:07	26/02/2024	13:14	463,779	St Leonards	SL044148
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/02/2024	11:00	28/02/2024	14:28	463,779	St Leonards	SL044174
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
Tail Lift Inspection	Done.						
13 Brakes 1	Front disc's & pads worn. Replaced.						
16 Suspension 1	Front shocks worn. Replaced.						
15 Steering 1	Lower ball joints worn. Replaced.						
44 Fuel System 1	Cap broken. Replaced.						
44 Fuel System 2	Oil leak from HPP. Removed, cleaned, replaced seal & bolts & refitted.						

86 Door Lock	Side door lock n/w on key. Replaced barrel.
Install Saloon CCTV Camera	Front camera n/w. Investigate to find lead u/s.
34 Lighting System	O/S scene light smashed. Replaced.
86 Doors Rear	Locking rods n/w. Removed, repaired, refitted.
17 Tyres Tracking	Re-set tracking.

02 Pipeline Annual Inspection	01/03/2024	11:33	01/03/2024	11:34	463,819	MDT Ferndown	TF003288
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test
-------------------------------	-------------------------------------

AVP Check	04/03/2024	11:49	04/03/2024	14:00	463,820	St Leonards	SL044247
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check
--------------------	---------------------

AVP Check	05/03/2024	10:16	05/03/2024	10:19	463,865	St Leonards	SL044265
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check
--------------------	---------------------

AVP Check	06/03/2024	08:45	06/03/2024	10:15	463,921	St Leonards	SL044285
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check
--------------------	---------------------

AVP Check	07/03/2024	07:30	07/03/2024	09:00	464,021	St Leonards	SL044299
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check
--------------------	---------------------

AVP Check	08/03/2024	08:30	08/03/2024	09:45	464,116	St Leonards	SL044316
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check
--------------------	---------------------

Breakdown	13/03/2024	18:50	15/03/2024	09:30	464,271	St Leonards	SL044399
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Loss of power, headlights, sirens, indicators
Travel Time	Travel to Weymouth
33 Ignition System	Replace key fob

Breakdown	24/03/2024	18:00	25/03/2024	10:55	465,519	St Leonards	SL044567
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	defective stretcher(broken handle)						
-----------	------------------------------------	--	--	--	--	--	--

Vehicle Deep Clean	02/04/2024	14:21	03/04/2024	10:28	466,665	St Leonards	SL044720
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	08/04/2024	06:22	09/04/2024	12:00	466,665	St Leonards	SL044801
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
Engine Change Oil & Filter							
13 Handbrake	Adjusted shoes and cables.						
01 Air Conditioning 1	Saloon AC condenser fan seized. replaced whole condenser assembly.						
85 Body Interior 1	240v socket led's damaged. replaced led lens. -underseat locker door resecured.						
16 Suspension 1	Rear anti roll bar drop link bushes worn. replaced bushes.						
13 Brakes 1	Both rear caliper lower sliders stiff. remove and regreased (no stock parts)						
71 Body Exterior 1	Tail lift bridge plate guides insecure on body. resecured x3.						
02 Cab Assembly 1	Dash trim broken causing switch panel and sat nav insecure. replaced dash trim.						
34 Lights	OSF Fog light damaged. replaced - front sidelight bulbs replaced.						
55 Tail Lift	Lift magnet braket broken/corroded. replaced. -adjusted rams and frame stops.						
86 Doors Rear	Excessive play in rear door hinges. - Monitor.					Monitoring	
86 Doors	Adjusted top and bottom latch pins or large rear door.						

BREAKDOWN	08/05/2024	11:00	09/05/2024	10:41	469,938	St Leonards	SL045246
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

87 - Stretchers/Chairs/Boards	Stretcher side wing handle snapped						
-------------------------------	------------------------------------	--	--	--	--	--	--

Vehicle Deep Clean	16/05/2024	07:06	16/05/2024	09:36	470,507	St Leonards	SL045340
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	18/05/2024	06:00	19/05/2024	12:04	470,507	St Leonards	SL045373
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
 Safety Inspection
 86 Doors Rear Excessive play in rear door hinges. - Monitor.
 71 Body Exterior 1 Body Exterior O/S Rear low back corner reflector came off
 31 Battery Chassis Battery/Charging Sys dca battery shutting down
 Auto G/box Oil & Filter Change Auto G/box Oil & Filter Change
 34 Lighting System O/S indicator lense damaged
 85 Body Interior 1 center consol button missing
 71 Body Exterior 2 damage to N/S of fropnt bumper
 02 Windscreen Wipers Wiper blades split

Unplanned Repair **11/06/2024** **11:00** **11/06/2024** **13:00** **473,025** **St Leonards** **SL045721**

31 Battery Aux See Notes.

Vehicle Deep Clean **03/07/2024** **12:49** **04/07/2024** **10:25** **473,763** **St Leonards** **SL046120**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **05/07/2024** **06:15** **05/07/2024** **16:57** **473,763** **St Leonards** **SL046142**

18 Wheels Check Torques
 Safety Inspection
 Annual Air Con Service Annual Air Condition Service
 Annual Heater Service Annual Heater Service
 UB Fire Supp 12mts Service Service of fire supression system
 Tail Lift Inspection
 Check and Fit P-Clips Check for the presence of P-Clips and fit if not present
 34 Lights Bulb Replacement Replace n/s running light bulb
 02 Glass / Windows Replace o/s window switch
 17 Tyres Replace Replace 12x front tyres/wheel - Tyres worn

Breakdown **10/07/2024** **20:57** **12/07/2024** **06:00** **473,763** **St Leonards** **SL046247**

Breakdown O/S REAR OUTSIDE OF TWIN

Vehicle Deep Clean	06/08/2024	16:08	07/08/2024	13:20	477,882	St Leonards	SL046704
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	12/08/2024	06:00	13/08/2024	06:42	477,882	St Leonards	SL046762
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
34 Lights	NSF DRL and NS side repeater bulbs blown.- replaced bulbs
Axle Oil Change	Axle Oil Change
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service - Replacement required. - No stock
Tail Lift Inspection	
13 Handbrake	Adjust.
55 Tail Lift	-Tilt switch faulty. replaced. -Hand rails loose- Retightened.
42 Coolant System	Coolant leak from temp sensor. replaced sensor and cleaned coolant.
16 Suspension 1	NSR Spring buffer torn. replaced buffer.
13 Brakes 1	NSR Caliper slider seized. replaced sldier kit.
17 Tyres	OSF Tyre replaced.
86 Sliding Door	Sliding door upper latch pulled out from door. refitted latch.
54 Sirens	Bull horn pedal inop. adjused spring in pedal.

Unplanned Repair	28/08/2024	12:35	28/08/2024	13:41	479,460	St Leonards	SL047038
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

55 Tail Lift	N/S gate stuck down. Removed sheared roll pin & fit new.
--------------	--

SAFETY INSPECTION	21/09/2024	07:15	23/09/2024	12:32	479,460	St Leonards	SL047402
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Annual Service	
Pollen Filter Change	Pollen Filter Change
Tail Lift Inspection	Tail lift not deploying
17 Tyres Replace	N/S/R/I Tyre blow out
87 - Stretchers/Chairs/Boards	Stretcher belts in wrong positions
87 Chairs	Carry chair roll pins loose

87 Stretcher	Stretcher wheel yolk insecure
13 Brake Test	
02 Cab Assembly 1	Cab M.D.V.S. Screen barckets loose & rattling
02 Cab Assembly 2	Cab passenger window switch broken
55 Tail Lift	Tail lift side rails insecure
13 Brakes 1	Rear brake pads & brake discs excessively low & worn
13 Brakes 2	O/S/R Brake caliper sliders excessively seized in hub

Vehicle Deep Clean	23/09/2024	06:44	23/09/2024	13:45	481,208	St Leonards	SL047426
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Med Devices Recall	23/09/2024	13:35	23/09/2024	13:37	481,208	MDT Ferndown	TF003770
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

Decontaminated	Cleaned with clinell wipes
Med Devices Recall	Upgraded the Mangar Compressor and charging dock.

Unplanned Repair	17/10/2024	14:37	17/10/2024	14:40	482,984	St Leonards	SL047813
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

44 Add Ad Blue	Top up Adblue
----------------	---------------

SAFETY INSPECTION	30/10/2024	07:00	31/10/2024	15:11	484,188	St Leonards	SL048013
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	-Corrosion on all frames and reservoir. -Power pack cover damaged - No stock
MOT	DONE
15 Steering 1	Power steering pump leaking oil. -Replaced pump
34 Lights	NSR Lower indicator led's out. replaced led's.
34 Emergency Lights	NSR Upper corner blue light lens damaged. replaced lens.
86 Sliding Door	Lower magnet replaced. -Upper latch cover replaced.
17 Tyres Replace	NSR outer tyre punctured. replaced tyre.
13 Brake Pads	Front pads worn. replaced pads.
55 Tail Lift	Lift ram return line leak. replaced pipe.
02 Windscreen Wipers	Wiper arms worn. replaced arms and blades.
27 Transmission Automatic	Lower cooler pipe bracket missing - Replaced bracket to resecure cooler pipes.
UB Fire Supp Replace	Replacement of UB Fire Suppression System

16 Suspension 2 45 Engine 1	Rear roll bar link bushes worn. replaced bushes. Injector no6 leaking at seal. cleaned and replaced seal.						
Vehicle Deep Clean	01/11/2024	16:00	02/11/2024	14:38	484,196	St Leonards	SL048054
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	15/12/2024	10:45	16/12/2024	08:08	488,600	St Leonards	SL048676
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	17/12/2024	10:00	18/12/2024	08:43	488,600	St Leonards	SL048703
18 Wheels Check Torques Safety Inspection Road Test 71 Body Exterior Acc Repair 42 Coolant System 45 Engine 1 45 Engine Oil Top Up 34 Emergency Lights Accident 34 Emergency Light System 86 Doors Rear 02 Cab Ass Fire Extinguisher 44 Add Ad Blue 55 Tail Lift	Checked. Carried out inspection. N/S rear low back corner reflector come out.Replaced corner capping & reflector. Engine Amber coolant warning.Cowling adrift. Secured cowling. EML on. Cleared faults. Fan speed, Intermitant nox sensor (Bank 1). Topped 1Ltr. O/S/f top blue adrift. Secured. Blue light over side door knocked off.Cill damaged at B post.Replaced light. O/S/R top blue lens cracked at rear mounting..Monitor. Not closing correctly. Safety strap missing. Topped 5Ltrs. Resevior bracket bent. Monitor.O/S hand rail loose.Tightened.						
						Monitoring	
						Monitoring	
Vehicle Deep Clean	29/01/2025	11:45	30/01/2025	09:59	492,097	St Leonards	SL049321
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	01/02/2025	06:00	01/02/2025	16:00	492,097	St Leonards	SL049367
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 34 Emergency Light System	Check and Install MDVS windows update O/S/R top blue lens cracked at rear mounting..Monitor.						

55 Tail Lift	Resevior bracket bent. Monitor.O/S hand rail loose.Tightened.
Tail Lift Inspection	
Engine Change Oil & Filter	
Pollen Filter Change	Pollen Filter Change

BREAKDOWN	09/02/2025	09:30	09/02/2025	11:43	492,564	St Leonards	SL049477
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	CEL on. Driving ok
01 Heating 1	Saloon heater not working

Vehicle Deep Clean	17/03/2025	06:00	17/03/2025	15:29	494,464	St Leonards	SL049957
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	19/03/2025	08:14	19/03/2025	15:17	494,464	St Leonards	SL049992
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
01 Heating 1	NO HEATING NFF
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Pollen Filter Change	Pollen Filter Change
71 Body Exterior 1	Battery box O/S Corroded, Team Leader aware told to monitor
	Monitoring

Breakdown	22/03/2025	19:16	23/03/2025	09:17	495,136	St Leonards	SL050046
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Diesel smell in the truck, and smoke from exhaust
34 Lights Bulb Replacement	N/S DRL bulb blown
Road Test	Carry out extended road test

02 Pipeline Annual Inspection	19/03/2025	13:24	19/03/2025	13:26	494,895	MDT Ferndown	TF004016
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test
-------------------------------	-------------------------------------

Unplanned Repair	17/04/2025	06:00	22/04/2025	10:00	497,503	St Leonards	SL050431
02 Windscreen	Windscreen Crack in windscreen						
Unplanned Repair	26/04/2025	06:00	27/04/2025	09:47	497,986	St Leonards	SL050611
71 Body Exterior 1 55 Tail Lift	Battery box O/S Corroded, Team Leader aware told to monitor Ramp/Lift/Tail Hoist wobbly tail lift. Repaired grab rail.					Monitoring	
SAFETY INSPECTION	07/05/2025	10:00	07/05/2025	16:00	498,394	St Leonards	SL050801
Check MDVS for Update	Check and Install MDVS windows update. Done.						
Safety Inspection	Carried out inspection.						
18 Wheels Check Torques	Checked.						
Road Test							
71 Body Exterior 1	Battery box O/S Corroded, Team Leader aware told to monitor						
85 Body Int Alcohol Gel Dispen	Replaced.						
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
Tail Lift Inspection	Done.						
01 Heating 1	Saloon heater smoking. Replaced inlet pipe. Repaired sheared bolt & loose nutser						
54 Warn Dev/System	Bull horn n/w. repaired switch.						
Vehicle Deep Clean	13/05/2025	10:16	13/05/2025	15:40	498,421	St Leonards	SL050922
Vehicle Deep Clean	Vehicle Deep Clean						
Decommission Vehicle	21/07/2025	15:22			499,527	St Leonards	SL052210