

Vehicle Detail	BN11ZSW	TOYOTA	HI-LUX 4X4 DIESEL	No
Date	Odo	Job Type	Description	
28/08/2025		0 RFL	RFL Sept 2025	
21/08/2024		0 RFL	RFL Aug 2024	
30/08/2023		0 RFL	RFL Sept 2023	
22/02/2023		0 COLLECTION & DELIVERY	Collection & Delivery	
22/02/2023		0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test	
22/02/2023		0 SERV/SAFETY INS (+ TEST FEE)	S2 SERVICE	
23/08/2022		0 RFL	RFL Aug 2022	
14/02/2022	51,410	REPAIRS TO FUEL SYSTEM	R&R Air Filter Element	
14/02/2022	51,410	REPAIRS TO ELECTRICS/BATTERY	stoplamp inop on os	
14/02/2022	51,410	COLLECTION & DELIVERY	Collection & Delivery	
14/02/2022	51,410	SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test	
14/02/2022	51,410	SERV/SAFETY INS (+ TEST FEE)	S1 SERVICE	
14/02/2022	51,410	REPAIRS TO BODY (NON ACCIDENT)	R&R Wiper Blades	
14/02/2022	51,410	REPAIRS TO BODY (NON ACCIDENT)	nsf wheelarch liner panel insecure rubbing ty	
14/02/2022	51,410	REPAIRS TO FUEL SYSTEM	Fuel Filter	
07/09/2021		0 RFL	RFL AUG 2021	
01/03/2021	47,040	TYRES	Wheel Balance	
01/03/2021	47,040	TYRES	Disposal of Tyre Casing	
01/03/2021	47,040	TYRES	Disposal of Tyre Casing	
01/03/2021	47,040	TYRES	Wheel Balance	
01/03/2021	47,040	TYRES	Tyre Valve Inner Repair	
01/03/2021	47,040	TYRES	Change Tyre	
01/03/2021	47,040	TYRES	Wheel Balance	
01/03/2021	47,040	TYRES	Change Tyre	
01/03/2021	47,040	TYRES	Change Tyre	
01/03/2021	47,040	TYRES	Tyre Valve Inner Repair	
01/03/2021	47,040	TYRES	Change Tyre	
01/03/2021	47,040	TYRES	Tyre Valve Inner Repair	
01/03/2021	47,040	TYRES	Wheel Balance	
01/03/2021	47,040	TYRES	Disposal of Tyre Casing	
01/03/2021	47,040	TYRES	Tyre Valve Inner Repair	
01/03/2021	47,040	TYRES	Disposal of Tyre Casing	
11/02/2021	47,040	REPAIRS TO BODY (NON ACCIDENT)	truckman top weather seal detached and tail g	
11/02/2021	47,040	SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test	
11/02/2021	47,040	REPAIRS TO ENGINE, EXHAUST	auxilliary belt showing wear and tensioner pu	
11/02/2021	47,040	REPAIRS TO BRAKES	Brake Fluid Change	
11/02/2021	47,040	SERV/SAFETY INS (+ TEST FEE)	S10 SERVICE	
11/02/2021	47,040	REPAIRS TO ENGINE, EXHAUST	Engine Timing Belt/Timing Chain	
11/02/2021	47,040	SERV/SAFETY INS (+ TEST FEE)	THERE IS A SQUEAKING NOISE COME FROM THE FAN	
11/02/2021	47,040	COLLECTION & DELIVERY	Collection & Delivery	
01/03/2019		0 RFL	RFL February 2019	
15/02/2018		0 RFL	RFL NE MAR 18	
25/01/2018		0 SERV/SAFETY INS (+ TEST FEE)	S7 SERVICE	
25/01/2018		0 REPAIRS TO BODY (NON ACCIDENT)	EA0517 Vehicle condition report recall end date =30-SEP-2018	
25/01/2018		0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test	
25/01/2018		0 REPAIRS TO ENGINE, EXHAUST	DEF0117 Vehicle Description Audit recall end date =30-APR-2018	

