

Transaction date	Fleet No	Invoice No	Registration	Detail	Odometer/Hrs run	Total net	Total VAT	Total cost	
03-Oct-17	NR030064	74354376	CX66GPY	Tyre worn out, NSF 1mm left, fit 1856515TESAVP - Parts		Æ83.81	Æ16.76	Æ100.57	
03-Oct-17	NR030064	74354376	CX66GPY	Tyre worn out, OSF 1mm left, fit 1856515TESAVP - Parts		Æ83.81	Æ16.76	Æ100.57	
03-Oct-17	NR030064	74354376	CX66GPY	Tyres - Environmental Disposal,NSF - Parts		Æ1.06	Æ0.21	Æ1.27	
03-Oct-17	NR030064	74354376	CX66GPY	Tyres - Environmental Disposal,OSF - Parts		Æ84.07	Æ16.81	Æ100.88	
10-Oct-17	NR030064	74354378	CX66GPY	Manufacturer Service - Time Based - Labour		Æ100.75	Æ20.15	Æ120.90	
10-Oct-17	NR030064	74354376	CX66GPY	Manufacturer Service - Time Based - Parts		Æ62.04	Æ12.41	Æ74.45	
01-Aug-18	NR030064	74600110	CX66GPY			Æ16.93	Æ3.39	Æ20.32	
23-Oct-18	NR030064	74667385	CX66GPY	Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade/s - Parts		Æ18.50	Æ3.70	Æ22.20	
23-Oct-18	NR030064	74667385	CX66GPY	Manufacturer Service - Distance Based - Labour 21000 kms/mixs Service		Æ75.00	Æ15.00	Æ90.00	
23-Oct-18	NR030064	74667385	CX66GPY	Manufacturer Service - Distance Based - Parts 21000 kms/mixs Service		Æ88.30	Æ17.66	Æ105.96	
20-Nov-18	NR030064	74693046	CX66GPY	Tyres - Environmental Disposal,OSF - Parts		Æ84.07	Æ16.81	Æ100.88	
20-Nov-18	NR030064	74693046	CX66GPY	Tyre worn out, NSF 0mm left, fit 1856515TESAVP - Parts		Æ84.07	Æ16.81	Æ100.88	
20-Nov-18	NR030064	74693046	CX66GPY	Tyres - Environmental Disposal,NSR - Parts		Æ1.10	Æ0.22	Æ1.32	
20-Nov-18	NR030064	74693046	CX66GPY	Tyres - Environmental Disposal,OSF - Parts		Æ1.10	Æ0.22	Æ1.32	
20-Nov-18	NR030064	74693046	CX66GPY	Tyres - Environmental Disposal,OSR - Parts		Æ1.10	Æ0.22	Æ1.32	
20-Nov-18	NR030064	74693046	CX66GPY	Wheel Alignment,NSF - Parts		Æ25.98	Æ5.20	Æ31.18	
26-Nov-18	NR030064	74707414	CX66GPY	Disc - Remove & Refit, Disc (incl. pads) - front (pair) - Parts 164550226 10158966,DISC_ACT.1		Æ143.18	Æ29.64	Æ172.82	
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: MINOR PUNCTURE REPAIR - VAN, Position: 8, 4, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TOD		1	Æ10.20	Æ2.04	Æ12.24
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: New Tyre, Position: A 1, 1856515MICHELPRIMACYXL92T, MICHELIN, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TRE		1	Æ76.51	Æ15.30	Æ91.81
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: Removed Tyre, Position: A 1, 1856515MICHELPRIMACYXL92T, MICHELIN, Removal Reason: Tyre - Worn Out, Tread: 2mm, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DR		1	Æ0.00	Æ0.00	Æ0.00
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: A 1, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY		1	Æ4.01	Æ0.80	Æ4.81
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: A 4, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY		1	Æ4.01	Æ0.80	Æ4.81
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: B 4, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY		1	Æ1.00	Æ0.20	Æ1.20
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: Tyres - Environmental Disposal, Position: A 4, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY		1	Æ1.80	Æ0.36	Æ2.16
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: WHEEL BALANCED - VAN, Position: A 1, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/0		1	Æ5.01	Æ1.00	Æ6.01
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: WHEEL BALANCED - VAN, Position: A 4, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/0		1	Æ5.01	Æ1.00	Æ6.01
12-Jun-20	NR030064	INV0009866	CX66GPY	Recharge Recharge For: WHEEL BALANCED - VAN, Position: B 4, Location: DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/06 AM, Rchg From Inv: TA12072020 Authorised By:JOHNATHAN EBENISER Location:DRIVING IN TO CROSS TYRES & AUTO PART OF TUF TREAD PONTYBEREM TODAY 12/0		1	Æ5.01	Æ1.00	Æ6.01
21-Sep-20	NR030064	MAINTINV0172518	CX66GPY	Recharge Recharge For: MINOR PUNCTURE REPAIR - CAR, Position: B 4, Location: Booking:ATS Bridgend, Rchg From Inv: U114235214		51897	Æ10.20	Æ2.04	Æ12.24
21-Sep-20	NR030064	MAINTINV0172518	CX66GPY	Recharge Recharge For: Standard Wheel Balance, Position: B 4, Location: Booking:ATS Bridgend, Rchg From Inv: U114235214		51897	Æ5.01	Æ1.00	Æ6.01
21-Sep-20	NR030064	MAINTINV0172518	CX66GPY	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 4, Location: Booking:ATS Bridgend, Rchg From Inv: U114235214		51897	Æ2.85	Æ0.57	Æ3.42
24-Sep-20	NR030064	INV00137064	CX66GPY	Recharge Recharge For: MOT - Class IV Cars (Up To 8 Passenger Seats), Rchg From Inv: 61681 Worn		52106	Æ154.00	Æ30.80	Æ184.80
24-Sep-20	NR030064	INV00137064	CX66GPY	Recharge Front Shock Absorber - Remove & Refit, Strut assy/suspension unit (pair) (Front Susp.), Rchg From Inv: 61681 Worn		52106	Æ125.60	Æ25.12	Æ150.72
09-Oct-20	NR030064	MAINTINV0172518	CX66GPY	Recharge Wash/Wipe Systems - Remove & Refit, Windscreen wiper - motor, Rchg From Inv: 61827		52291	Æ236.23	Æ47.25	Æ283.48
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: New Tyre, Position: B 4, 1856515MND4TX, MICHELIN, Tread: 8mm, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ81.11	Æ16.22	Æ97.33
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: Removed Tyre, Position: B 4, 1856515MND4TX, MICHELIN, Removal Reason: Tyre - Tread Damage, Tread: 4.3mm, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ10.00	Æ2.00	Æ12.00
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: B 4, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ11.10	Æ2.22	Æ13.32
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: Standard Wheel Balance, Position: B 4, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ5.01	Æ1.00	Æ6.01
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 4, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ2.85	Æ0.57	Æ3.42
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: New Tyre, Position: B 1, 1856515MND4TX, MICHELIN, Tread: 8mm, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ81.10	Æ16.22	Æ97.32
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: Removed Tyre, Position: B 1, 1856515MND4TX, MICHELIN, Removal Reason: Tyre - Worn Out, Tread: 2mm, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ10.00	Æ2.00	Æ12.00
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: B 1, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ11.10	Æ2.22	Æ13.32
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: Standard Wheel Balance, Position: B 1, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ5.01	Æ1.00	Æ6.01
23-Aug-21	NR030064	MAINTINV0639500	CX66GPY	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 1, Location: Booking-National Tyres BRIDGEND(014), Rchg From Inv: U114438672		61127	Æ2.85	Æ0.57	Æ3.42
30-Sep-21	NR030064	MAINTINV0683554	CX66GPY	Recharge Recharge For: MOT - Class IV Cars (Up To 8 Passenger Seats), Rchg From Inv: 64095		62805	Æ54.85	Æ10.97	Æ65.82
30-Sep-21	NR030064	MAINTINV0683554	CX66GPY	Recharge MOT - Pre Insp - LCV - HCVS Bespoke Event, Rchg From Inv: 64095		62805	Æ69.00	Æ13.80	Æ82.80
30-Sep-21	NR030064	MAINTINV0683554	CX66GPY	Recharge Injection - Remove & Refit, Glow plugs (all), Rchg From Inv: 64095		62803	Æ75.60	Æ15.12	Æ90.72
30-Sep-21	NR030064	MAINTINV0683554	CX66GPY	Recharge Service - Annual - HCVS Bespoke Event, Rchg From Inv: 64095		62803	Æ131.23	Æ26.25	Æ157.48
11-Mar-22	NR030064	MAINTINV1007894	CX66GPY	Recharge Recharge For: New Tyre, Position: A 1, 1856515MICHELROSSLIMATEPLUSXL92T, MICHELIN, Location: DRIVE IN TO BRIDGEND TUES 9:00AM, Rchg From Inv: U114593501 Authorised By:ALLYN HAWKES Location:DRIVE IN TO BRIDGEND TUES 9:00AM		69253	Æ83.00	Æ16.60	Æ99.60
11-Mar-22	NR030064	MAINTINV1007894	CX66GPY	Recharge Recharge For: New Tyre, Position: A 4, 1856515MICHELROSSLIMATEPLUSXL92T, MICHELIN, Location: DRIVE IN TO BRIDGEND TUES 9:00AM, Rchg From Inv: U114593501 Authorised By:ALLYN HAWKES Location:DRIVE IN TO BRIDGEND TUES 9:00AM		69253	Æ103.00	Æ20.60	Æ123.60
11-Mar-22	NR030064	MAINTINV1007894	CX66GPY	Recharge Recharge For: Removed Tyre, Position: A 1, 1856515MICHELROSSLIMATEPLUSXL92T, MICHELIN, Removal Reason: Tyre - Worn Out, Tread: 2mm, Location: DRIVE IN TO BRIDGEND TUES 9:00AM, Rchg From Inv: U114593501 Authorised By:ALLYN HAWKES Location:DRIVE IN TO BRIDGEND TUES 9:00AM		69253	Æ11.10	Æ2.22	Æ13.32
11-Mar-22	NR030064	MAINTINV1007894	CX66GPY	Recharge Recharge For: Standard Wheel Balance, Position: A 1, 1856515MICHELROSSLIMATEPLUSXL92T, MICHELIN, Removal Reason: Tyre - Worn Out, Tread: 2mm, Location: DRIVE IN TO BRIDGEND TUES 9:00AM, Rchg From Inv: U114593501 Authorised By:ALLYN HAWKES Location:DRIVE IN TO BRIDGEND TUES 9:00AM		69253	Æ11.10	Æ2.22	Æ13.32
11-Mar-22	NR030064	MAINTINV1007894	CX66GPY	Recharge Recharge For: Tyres - Environmental Disposal, Position: A 4, Location: DRIVE IN TO BRIDGEND TUES 9:00AM, Rchg From Inv: U114593501 Authorised By:ALLYN HAWKES Location:DRIVE IN TO BRIDGEND TUES 9:00AM		69253	Æ1.10	Æ0.22	Æ1.32
11-Mar-22	NR030064	MAINTINV1007894	CX66GPY	Recharge Recharge For: Tyres - Environmental Disposal, Position: A 1, Location: DRIVE IN TO BRIDGEND TUES 9:00AM, Rchg From Inv: U114593501 Authorised By:ALLYN HAWKES Location:DRIVE IN TO BRIDGEND TUES 9:00AM		69253	Æ1.10	Æ0.22	Æ1.32
05-Apr-22	NR030064	INV0963285	CX66GPY	Recharge Check, Braking System Fault Diagnosis - Check, ABS - fault diagnosis, Rchg From Inv: 65202 Customer states knocking noise			Æ34.50	Æ6.90	Æ41.40
29-Sep-22	NR030064	MAINTINV1244914	CX66GPY	Recharge Routine MOT - Pre Insp - LCV, Rchg From Inv: 155913		77252	Æ45.00	Æ9.00	Æ54.00
29-Sep-22	NR030064	MAINTINV1244914	CX66GPY	Recharge Routine MOT, Rchg From Inv: 155913		77252	Æ45.00	Æ9.00	Æ54.00
29-Sep-22	NR030064	MAINTINV1244914	CX66GPY	Recharge Routine Service, Rchg From Inv: 155913		77252	Æ180.00	Æ36.00	Æ216.00
26-Oct-22	NR030064	INV01295872	CX66GPY	Recharge Remove & Refit Rear OS Lamps exterior (rear) - number plate bulb right, Rchg From Inv: 156801		83790	Æ64.99	Æ12.99	Æ77.98
26-Oct-22	NR030064	INV01295872	CX66GPY	Recharge Remove & Refit Front N/S Arm (Front Susp.) - lower assy/wishbone left, Rchg From Inv: 156801		83790	Æ105.00	Æ21.00	Æ126.00
26-Oct-22	NR030064	INV01295872	CX66GPY	Recharge Remove & Refit Rear Shock absorber/damper (pair) (Rear Susp.), Rchg From Inv: 156801		83790	Æ140.00	Æ28.00	Æ168.00
12-Dec-22	NR030064	INV01389639	CX66GPY	Recharge Routine, Other Unspecified Work - Routine, Breakdown, Rchg From Inv: 1024885 12/12/2022:15-5ULLANELLI SA14 6		80210	Æ87.24	Æ17.45	Æ104.69
16-Jan-23	NR030064	INV01389639	CX66GPY	Recharge Remove & Refit, Water Pump - Remove & Refit, Water pump, Rchg From Inv: 087616 leaking		81444	Æ119.95	Æ23.99	Æ143.94
16-Jan-23	NR030064	INV01389639	CX66GPY	Recharge Remove & Refit, Alternator/Charging Circuit - Remove & Refit, Charging circuit - alternator/dynamo, Rchg From Inv: 087616 advised by Novuna alternator r		81444	Æ315.99	Æ63.20	Æ379.19
16-Jan-23	NR030064	INV01389639	CX66GPY	Recharge Remove & Refit, Battery - Remove & Refit, Charging circuit - battery, Rchg From Inv: 087616 cell down, alternator getting		81444	Æ124.30	Æ29.66	Æ153.96
16-Jan-23	NR030064	INV01389639	CX66GPY	Recharge Remove & Refit, Engine Assembly - Remove & Refit, Auxiliary drive belt (poly/belt), Rchg From Inv: 087616 routine		81444	Æ56.18	Æ11.24	Æ67.42
10-Mar-23	NR030064	INV01488029	CX66GPY	Recharge Check Checks - Check, Investigations & Report, Rchg From Inv: 089113 rear doors and clunking		83790	Æ22.50	Æ4.50	Æ27.00
10-Mar-23	NR030064	INV01488029	CX66GPY	Recharge Remove & Refit, Door (Rear) - Remove & Refit, Door (rear) - lock assy left, Rchg From Inv: 089113 lock damaged possibly due to f		83790	Æ263.70	Æ52.74	Æ316.44
10-Mar-23	NR030064	INV01488029	CX66GPY	Recharge Remove & Refit, Front Anti-Roll Bar - Remove & Refit, Anti-roll/stabiliser link (Front Susp.) right, Rchg From Inv: 089113 bush worn		83790	Æ28.31	Æ5.66	Æ33.97
10-Mar-23	NR030064	INV01488029	CX66GPY	Recharge Remove & Refit, Front Shock Absorber - Remove & Refit, Shock absorber/damper (one) (Front Susp.) right, Rchg From Inv: 089113		83790	Æ71.45	Æ14.29	Æ85.74
10-Mar-23	NR030064	INV01488029	CX66GPY	Recharge Remove & Refit, Front Shock Absorber - Remove & Refit, Strut assy/suspension unit (one) (Front Susp.) left, Rchg From Inv: 089113 noise when driving		83790	Æ162.96	Æ32.59	Æ195.55
10-Mar-23	NR030064	INV01488029	CX66GPY	Recharge Remove & Refit, Front Shock Absorber - Remove & Refit, Strut top bearing (Front Susp.) right, Rchg From Inv: 089113 coil spring snapped		83790	Æ124.44	Æ24.89	Æ149.33
10-Mar-23	NR030064	INV01488029	CX66GPY	Recharge Recharge For: Annual - Novuna Bespoke Event, Rchg From Inv: 089113		83790	Æ60.75	Æ12.15	Æ72.90
19-Sep-23	NR030064	INV01828805	CX66GPY	Recharge Recharge For: New Tyre, Position: A 1, 1856515MICHELROSSLIMATEPLUSXL92T, MICHELIN, Location: Civic LdUnit14b Kemys Way Enterprise Park Swansea Enterprise Park Kemys Way Lansamlet Swansea SA6 8QF // WED 20/09 BEFORE 12PM, Rchg From Inv: U114952225 Authorised By:PAUL CIVIC Location:Civic L		93096	Æ102.55	Æ20.51	Æ123.06
19-Sep-23	NR030064	INV01828805	CX66GPY	Recharge Recharge For: New Tyre, Position: A 4, 1856515MICHELROSSLIMATEPLUSXL92T, MICHELIN, Location: Civic LdUnit14b Kemys Way Enterprise Park Swansea Enterprise Park Kemys Way Lansamlet Swansea SA6 8QF // WED 20/09 BEFORE 12PM, Rchg From Inv: U114952225 Authorised By:PAUL CIVIC Location:Civic L		93096	Æ110.25	Æ22.05	Æ132.30
19-Sep-23	NR030064	INV01828805	CX66GPY	Recharge Recharge For: R/RESP R/SIDE VAN NORMAL HRS, Location: Civic LdUnit 14b Kemys Way Enterprise Park Swansea Enterprise Park Kemys Way Lansamlet Swansea SA6 8QF // W					

23-Sep-24	NR030064	MAINTINV02371868	CX66GPY	Recharge Remove & Refit, Bonnet - Remove & Refit, Bonnet - lock assy, Rchg From Inv: 102786 siezed not operating	106238	ÄE46.75	ÄE9.35	ÄE56.10
23-Sep-24	NR030064	MAINTINV02371868	CX66GPY	Recharge handle broken, Rchg From Inv: 102786 handle broken	106238	ÄE37.10	ÄE7.42	ÄE44.52
23-Sep-24	NR030064	MAINTINV02371868	CX66GPY	Recharge Remove & Refit, Linings (Pads & Shoes) - Remove & Refit, Brake shoes - rear (axle set), Rchg From Inv: 102786 osr adjuster seized,PAD_ACT.2.	106238	ÄE165.15	ÄE33.03	ÄE198.18
23-Sep-24	NR030064	MAINTINV02371868	CX66GPY	Recharge Remove & Refit, Lamps - Remove & Refit, Lamps exterior (rear) - brake light bulb right, Rchg From Inv: 102786 bulb blown	106238	ÄE10.34	ÄE2.07	ÄE12.41
23-Sep-24	NR030064	MAINTINV02371868	CX66GPY	Recharge Remove & Refit, Lamps - Remove & Refit, Lamps exterior (rear) - number plate bulb left, Rchg From Inv: 102786 bulb blown	106238	ÄE10.34	ÄE2.07	ÄE12.41
23-Sep-24	NR030064	MAINTINV02371868	CX66GPY	Recharge Remove & Refit, Front Arms (Upper & Lower) - Remove & Refit, Arm (Front Susp.) - upper assy/wishbone left, Rchg From Inv: 102786 noisy and play	106238	ÄE98.68	ÄE19.74	ÄE118.42
23-Sep-24	NR030064	MAINTINV02371868	CX66GPY	Recharge Remove & Refit, Front Shock Absorber - Remove & Refit, Strut top bearing (Front Susp.) left, Rchg From Inv: 102786 play and noise	106238	ÄE90.59	ÄE18.12	ÄE108.71
23-Sep-24	NR030064	MAINTINV02371868	CX66GPY	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 102786 bonnet not opening, gain acces	106238	ÄE22.50	ÄE4.50	ÄE27.00
23-Sep-24	NR030064	MAINTINV02371868	CX66GPY	Recharge Check, Checks - Check, Pre-check - Government Vehicle Test, Rchg From Inv: 102786 pre mot	106238	ÄE45.00	ÄE9.00	ÄE54.00
22-Nov-24	NR030064	INV02477144	CX66GPY	Recharge Remove & Refit, Heater Motor - Remove & Refit, Heater motor, Rchg From Inv: 273/9026662	107623	ÄE151.04	ÄE30.21	ÄE181.25
10-Feb-25	NR030064	MAINTINV02616775	CX66GPY	Recharge Remove & Refit, Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake), Rchg From Inv: 2288303	108322	ÄE7.00	ÄE1.40	ÄE8.40
10-Feb-25	NR030064	MAINTINV02616775	CX66GPY	Recharge Remove & Refit, Air Cleaner - Remove & Refit, Air cleaner/filter - assy, Rchg From Inv: 2288303	108322	ÄE10.94	ÄE1.19	ÄE12.13
10-Feb-25	NR030064	MAINTINV02616775	CX66GPY	Recharge Routine, Service - Annual - Novuna Bespoke Event, Rchg From Inv: 2288303	108322	ÄE115.32	ÄE23.06	ÄE138.38
19-Mar-25	NR030064	MAINTINV02668863	CX66GPY	Recharge Check, Engine Management Fault Diagnosis - Check, Engine management - read fault codes, Rchg From Inv: 2324955 EML light on dash check engine	108622	ÄE24.75	ÄE4.95	ÄE29.70
19-Mar-25	NR030064	MAINTINV02668863	CX66GPY	Recharge Remove & Refit, All Exhaust Components - Remove & Refit, Exhaust gas pressure sensor, Rchg From Inv: 2324955 Downstream Exhaust Temp Sensor	108622	ÄE329.03	ÄE65.81	ÄE394.84
19-Mar-25	NR030064	MAINTINV02668863	CX66GPY	Recharge Repair, Exhaust Gas Analysis - Repair, Regeneration of Particulate Filter(s), Rchg From Inv: 2324955	108622	ÄE49.50	ÄE9.90	ÄE59.40
19-Mar-25	NR030064	MAINTINV02668863	CX66GPY	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 2324955 Initial investigation has iden	108622	ÄE49.50	ÄE9.90	ÄE59.40
22-Sep-25	NR030064	MAINTINV02992719	CX66GPY	Recharge Routine, MOT - Class IV Cars (Up To 8 Passenger Seats), Rchg From Inv: s21982	110372	ÄE54.85	ÄE0.00	ÄE54.85
22-Sep-25	NR030064	MAINTINV02992719	CX66GPY	Recharge Routine, MOT - Pre Insp - LCV - Novuna Bespoke Event, Rchg From Inv: s21982	110372	ÄE90.00	ÄE16.00	ÄE96.00
22-Sep-25	NR030064	MAINTINV02992719	CX66GPY	Recharge Remove & Refit, Lamps - Remove & Refit, Lamps exterior - headlamp lens, Rchg From Inv: s21982 Headlamp Polishing / Restorati	110372	ÄE55.80	ÄE11.16	ÄE66.96
Report Total:								ÄE10,278.82