

WT17NYP	HART		NBOC				
PDI Inspection	09/08/2017	14:17	09/08/2017	18:00	97	Bristol	BL007615
PDI Inspection Replace Vehicle Fuel Card	carry out PDI Replace Vehicle Fuel Card						
SAFETY INSPECTION	23/08/2017	12:46	23/08/2017	13:01	213	Bristol	BL007743
18 Wheels 18 Wheels Check Torques 71 Body Exterior 1 Safety Inspection	4 x wheels and tyres ordered against for stock, ref S.A livery - supplied by autospray						
Unplanned Repair	12/09/2017	09:52	12/09/2017	09:56	1,837	Bristol	BL007974
86 Doors Rear	REAR DOOR HINGE SIEZED - FREED OFF AND LUBRICATED						
SAFETY INSPECTION	06/10/2017	13:24	09/10/2017	08:25	4,311	Bristol	BL008310
02 Windscreen 18 Wheels Check Torques 45 Engine Oil Top Up Safety Inspection	top up screenwash top up engine oil carry out safety inspection						
Unplanned Repair	02/11/2017	10:25	02/11/2017	10:30	6,654	Bristol	BL008625
17 Tyres Replace	replace x4 tyres						
SAFETY INSPECTION	16/11/2017	17:34	17/11/2017	12:24	6,931	Bristol	BL008786
18 Wheels Check Torques Safety Inspection							

Breakdown	11/12/2017	18:40	11/12/2017	21:31	7,250	Bristol	BL009036
Breakdown	Puncture nsf and nsr tyre replace tyres						
Unplanned Repair	20/12/2017	21:01	20/12/2017	21:02	9,433	Bristol	BL009151
34 Lights Bulb Replacement	replace O/S repeater bulb						
SAFETY INSPECTION	28/12/2017	20:23	28/12/2017	20:27	10,061	Bristol	BL009233
02 Windscreen	Top up washers						
18 Wheels Check Torques							
Safety Inspection	Carry out safety inspection						
Breakdown	02/01/2018	09:33	03/01/2018	13:40	10,331	Bristol	BL009276
Breakdown	Large Crack in Windscreen						
SAFETY INSPECTION	06/02/2018	18:13	06/02/2018	21:53	12,596	Bristol	BL009727
02 Windscreen	topped up screen wash						
13 Brake Pads	replaced front pads						
18 Wheels Check Torques							
45 Engine Oil Top Up	topped up engine oil						
86 Doors Rear	freed off stiff os rear door						
Road Test	carried out road test after brake work						
Safety Inspection							
Unplanned Repair	27/02/2018	19:51	27/02/2018	19:52	13,995	Bristol	BL009980

89 Seatbelts	check seatbelts mountings - all ok						
Unplanned Repair	27/02/2018	22:01	27/02/2018	22:03	14,004	Bristol	BL009986
Check Winter Pack	x2 snow socks						
Unplanned Repair	01/03/2018	11:14	01/03/2018	11:17	14,115	Bristol	BL010005
02 Windscreen	supply HART screen wash						
Breakdown	02/03/2018	21:08	08/03/2018	08:07	14,120	Bristol	BL010030
Breakdown	passenger side bottom 10inch crack						
SAFETY INSPECTION	19/03/2018	15:44	19/03/2018	20:00	14,531	Bristol	BL010219
13 Brake Pads	renew rear pads						
17 Tyres Replace	renew tyres						
18 Wheels Check Torques							
Safety Inspection							
92 - C Service							
Breakdown	04/05/2018	06:44	04/05/2018	14:33	17,366	Bristol	BL010726
Breakdown	O/S rear punture 215/60R17C						
SAFETY INSPECTION	08/05/2018	12:32	09/05/2018	08:12	17,556	Bristol	BL010756
18 Wheels Check Torques							
Safety Inspection							
Check seat belt anchor points	Check Seat belt anchor points						
Annual Air Con Service	Annual Air Condition Service						
SAFETY INSPECTION	19/06/2018	12:10	19/06/2018	19:13	19,854	Bristol	BL011236

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION **24/07/2018** **09:02** **26/07/2018** **11:45** **23,789** **Bristol** **BL011611**

13 Brakes 1 replace front disc pads
17 Tyres Replace replace 3 tyres
18 Wheels Check Torques
45 Engine 1 investigate fumes into cab,,exhaust blow found on engine,under warranty
Safety Inspection

SAFETY INSPECTION **14/09/2018** **15:02** **19/09/2018** **09:40** **27,945** **Bristol** **BL012154**

02 Windscreen Topped Up Screenwash
17 Tyres Replace renew tyre
18 Wheels replace damaged wheel rim
18 Wheels Check Torques
Safety Inspection Carried Out Safety Inspection

SAFETY INSPECTION **18/10/2018** **12:32** **18/10/2018** **12:39** **30,199** **Bristol** **BL012516**

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION **28/11/2018** **08:54** **03/12/2018** **10:39** **33,584** **Bristol** **BL012918**

13 Brakes 1 replace front pads and discs
13 Brakes 2 replace rear brake pads
17 Tyres Replace replace four tyres
18 Wheels Check Torques
45 Engine Oil Top Up top up engine oil
Safety Inspection

SAFETY INSPECTION	15/01/2019	13:22	16/01/2019	21:41	37,392	Bristol	BL013395
02 Windscreen	Topped Up Screenwash						
17 Tyres Replace	Replaced Both Front Tyres						
18 Wheels Check Torques							
31 Charging System Battery	Battery/Charging Sys tripping out when plugged into shoreline						
Safety Inspection							
93 - D Service							
Service D							
SAFETY INSPECTION	19/02/2019	11:26	20/02/2019	07:38	38,005	Bristol	BL013733
18 Wheels Check Torques							
Safety Inspection							
Breakdown	08/04/2019	11:41	08/04/2019	15:00	41,862	Bristol	BL014162
Breakdown	Rear O/S punture						
Unplanned Repair	24/04/2019	12:10	24/04/2019	12:13	43,606	Bristol	BL014311
45 Engine Oil Top Up							
SAFETY INSPECTION	16/05/2019	09:27	16/05/2019	09:28	43,606	Bristol	BL014524
18 Wheels Check Torques							
Safety Inspection							
Breakdown	07/06/2019	19:35	07/06/2019	21:10	47,069	Bristol	BL014713
Breakdown	flat near rear tyre						

SAFETY INSPECTION	10/06/2019	12:17	12/06/2019	11:10	47,104	Bristol	BL014723
13 Brakes 1	replace front brake pads and discs						
13 Brakes 2	replace rear pads and discs						
18 Wheels Check Torques							
45 Engine Oil Top Up	top up engine oil						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
SAFETY INSPECTION	24/06/2019	11:12	24/06/2019	11:13	47,109	Bristol	BL014849
18 Wheels Check Torques							
Safety Inspection							
SAFETY INSPECTION	16/08/2019	11:20	16/08/2019	12:23	51,003	Bristol	BL015343
17 Tyres Replace	replace both front tyres						
18 Wheels Check Torques							
45 Engine Oil Top Up	top up engine oil						
Safety Inspection							
SAFETY INSPECTION	12/09/2019	14:25	13/09/2019	07:47	52,286	Bristol	BL015562
18 Wheels Check Torques							
34 Lights	both number plate lights n/w,replace both bulbs						
86 Doors	straighten out bottom sliding door runner and lube						
Safety Inspection							
BREAKDOWN	03/10/2019	12:09	03/10/2019	12:13	53,334	Bristol	BL015722
42 Coolant System	Coolant Warning Light On - Topped Up Coolant Level						

SAFETY INSPECTION	15/11/2019	09:29	18/11/2019	09:37	56,287	Bristol	BL016158
02 Windows/Glass							
13 Brakes 1		front pads replaced					
18 Wheels Check Torques							
45 Engine Oil Top Up							
Safety Inspection							
SAFETY INSPECTION	23/12/2019	12:25	27/12/2019	08:01	57,004	Bristol	BL016553
16 Suspension 1							
18 Wheels Check Torques							
52 Electrical Aux		Battery/Charging Sys EPCR not charging in docking station					
71 Body Exterior 1		body panels replaced					
Safety Inspection							
SAFETY INSPECTION	24/01/2020	11:29	24/01/2020	11:29	59,168	Bristol	BL017028
18 Wheels Check Torques							
Safety Inspection							
Vehicle Deep Clean		Vehicle Deep Clean					
Breakdown	03/02/2020	19:30	03/02/2020	21:05	61,106	Bristol	BL016985
Breakdown		passenger side windscreen cracked					
Unplanned Repair	13/03/2020	08:30	13/03/2020	09:05	62,837	Bristol	BL017355
44 Add Ad Blue		topped up adblue					
45 Engine Oil Top Up		topped up engine oil					
SAFETY INSPECTION	25/03/2020	09:38	02/04/2020	08:41	64,016	Bristol	BL017458

13 Brakes 1	replace front brake pads
13 Brakes 2	replace rear brake pads
17 Tyres Replace	replace front tyres
18 Wheels Check Torques	
31 Battery Chassis	replace chassis battery
45 Engine Oil Top Up	top up engine oil
Safety Inspection	
Travel Time	
MOT	

SAFETY INSPECTION	14/04/2020	18:20	14/04/2020	18:25	64,389	Bristol	BL017773
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windows/Glass							
17 Tyres Replace							
18 Wheels Check Torques							
45 Engine 1	has slight engine oil leak from front crank seal					Monitoring	
Brake Fluid Change	Brake Fluid Change						
Safety Inspection							
92 - C Service							
Annual Air Con Service	Annual Air Condition Service						

SAFETY INSPECTION	20/05/2020	14:15	20/05/2020	14:19	65,547	Bristol	BL018164
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windows/Glass	
18 Wheels Check Torques	
45 Engine 1	has slight engine oil leak from front crank seal
Medical Devices Repair	oxygen bottle holding unit removed and repaired
Safety Inspection	

Unplanned Repair	01/07/2020	12:25	01/07/2020	12:27	65,549	Bristol	BL018548
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

17 Tyres Replace	call out and replace punture
------------------	------------------------------

SAFETY INSPECTION	20/07/2020	12:59	20/07/2020	13:06	69,033	Bristol	BL018728
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

15 Steering 1	top up fluid
17 Tyres Replace	replace damaged tyres
18 Wheels Check Torques	
42 Coolant System	pressure test system - no leaks found - replace cap
Safety Inspection	

SAFETY INSPECTION	20/08/2020	13:43	24/09/2020	19:55	71,400	Bristol	BL019054
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windows/Glass	
13 Brakes 1	front discs and pads replaced
18 Wheels Check Torques	
31 Battery Aux	Replaced aux battery
42 Coolant System	top up coolant
45 Engine 1	flywheel rattling on auto box
45 Engine Oil Top Up	
71 Body Exterior 1	rear reg plate lamps inop full of water
Safety Inspection	

Awaiting Warranty

SAFETY INSPECTION	24/09/2020	19:56	29/09/2020	07:50	71,410	Bristol	BL019417
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

17 Tyres Replace	renew x 2
18 Wheels Check Torques	
34 Lights	Lighting System Rear number plate lights out
71 Body Exterior 1	rear reg plate lamps inop full of water
Safety Inspection	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card

Awaiting Parts

Unplanned Repair	20/10/2020	12:26	20/10/2020	12:30	71,548	Bristol	BL019739
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

31 Battery Aux	test battery found faulty fit new and test system all ok re seal battery box
----------------	--

SAFETY INSPECTION	11/11/2020	16:19	11/11/2020	18:39	72,747	Bristol	BL019971
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	Top Up Screenwash
18 Wheels Check Torques	Torque All Wheel Nuts

34 Lights	Rear Number Plate Lights Out - OLD DEFECT
34 Lights Bulb Replacement	Int Lights Not Working
44 Add Ad Blue	Top Up Ad-Blue
85 Body Interior 1	Centre Console Push Button Missing
Safety Inspection	Carry Out Safety Inspection

Breakdown	09/12/2020	19:57	10/12/2020	21:34	73,980	Bristol	BL020288
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown	Knocking noise steering
-----------	-------------------------

SAFETY INSPECTION	10/12/2020	21:30	10/12/2020	21:33	74,240	Bristol	BL020302
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	Top Up Screenwash
15 Steering 1	Knocking From Steering - Unable To Fault
18 Wheels Check Torques	Torque All Wheel Nuts
Safety Inspection	Carry Out Safety Inspection

Breakdown	23/01/2021	20:04	28/01/2021	09:11	74,776	Bristol	BL020736
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

13 Brake Pads	Replace Front Brake Pads
13 Brakes 1	Replace Seized Nearside Front Brake Caliper
13 Discs	Replace Front Brake Discs
17 Tyres Tracking	Check And Adjust Tracking
18 Wheels Check Torques	Front Wheels Only
Breakdown	steering off centre; front wheel
Road Test	

SAFETY INSPECTION	22/02/2021	19:15	23/02/2021	08:12	74,776	Bristol	BL021063
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques	
45 Engine Oil Top Up	top up engine oil
87a - Medical Equipment Repair	Med Equip & Devices EPCR dock not charging tablet
Safety Inspection	

Unplanned Repair	28/02/2021	09:23	02/03/2021	08:04	75,012	Bristol	BL021105
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

17 Tyres Replace	Both front tyres
94 - Cambelt	Replaced cambelt kit and water pump
99 Diagnostic Test	Tested for coolant loss found water pump to be leaking
Road Test	

SAFETY INSPECTION	18/03/2021	22:48	23/03/2021	07:19	75,650	Bristol	BL021311
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

16 Suspension 1	osf shock absorber leaking missed on mot advise as a pair	Awaiting Parts
16 Suspension 2	front anti roll bar d bushes have play causing knocking missed on mot	Awaiting Parts
18 Wheels Check Torques		
27 Transmission Manual	osf transfer box shaft seal leaking	Awaiting Parts
Safety Inspection		
Annual Air Con Service	Annual Air Condition Service	
Travel Time		
MOT		

Unplanned Repair	05/05/2021	16:08	05/05/2021	16:19	79,303	Bristol	BL021774
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

45 Engine Oil Top Up	
Travel Time	To nboc to top up oil was below min

SAFETY INSPECTION	05/05/2021	19:10	09/05/2021	09:35	79,311	Bristol	BL021776
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windows/Glass	
18 Wheels Check Torques	
42 Coolant System	top up coolant
Install Saloon CCTV Camera	cctv inop/ chased wiring,found wiring and fuse burnt, renewed and re-tested
Safety Inspection	

Breakdown	29/05/2021	06:36	30/05/2021	07:47	80,250	Bristol	BL022082
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

56 Comms Equipment	terrafix to fix
Breakdown	Terrafix not logging - transmtion failure

Breakdown	01/06/2021	08:20	01/06/2021	09:48	80,876	Bristol	BL022097
17 Tyres Replace Breakdown	ats to carry out breakdown offside rear 215/60r17c 104/102H						
SAFETY INSPECTION	26/06/2021	11:35	26/06/2021	11:46	82,490	Bristol	BL022370
13 Brakes 1 18 Wheels Check Torques 45 Engine Oil Top Up Safety Inspection	replace rear pads and discs top engine oil						
Unplanned Repair	23/07/2021	17:29	23/07/2021	17:45	82,531	Bristol	BL022765
31 Battery Aux 99 Diagnostic Test	test for no aux power test battery at fault						
Breakdown	23/07/2021	20:54	25/07/2021	07:25	83,800	Bristol	BL022767
Breakdown	flat tyre rear nearside						
Unplanned Repair	26/07/2021	08:13	26/07/2021	15:35	83,900	Bristol	BL022784
31 Battery Chassis 99 Diagnostic Test	chassis battery failed non start						
SAFETY INSPECTION	01/09/2021	09:28	04/09/2021	07:49	84,824	Bristol	BL023185
01 Air Conditioning 1 13 Brakes 1 17 Tyres Replace 18 Wheels Check Torques 31 Battery Chassis 45 Engine 1	front discs and pads x2 front remove front end replace radiator and alternator						

Safety Inspection
 94 - Cambelt
 Replace Cambelt
 93 - D Service
 Service D

SAFETY INSPECTION **14/10/2021** **10:45** **14/10/2021** **10:46** **86,779** **Bristol** **BL023698**

18 Wheels Check Torques
 Safety Inspection

SAFETY INSPECTION **14/10/2021** **10:46** **14/10/2021** **13:47** **86,779** **Bristol** **BL023699**

02 Windscreen	Top Up Screenwash	
18 Wheels Check Torques	Torque All Wheel Nuts	
86 Door Seals	Both Side Door Seals Damaged - New Required	Monitoring
Safety Inspection	Carry Out Safety Inspection	

SAFETY INSPECTION **27/11/2021** **07:00** **27/11/2021** **11:49** **89,031** **Bristol** **BL024172**

18 Wheels Check Torques	
18 Wheels Removal	clean corrosion from flanges
31 Battery Aux	replace shore line cover
45 Engine Ad Blue	top up ad blue
45 Engine Oil Top Up	top up engine oil
71 Body Exterior 1	repair bent exhaust heat sheild and repair plastic under tray
86 Door Seals	Both Side Door Seals Damaged - New Required
Safety Inspection	

BREAKDOWN **29/12/2021** **11:11** **25/01/2022** **13:26** **89,910** **Bristol** **BL024530**

42 Coolant System	Losing coolant internally
-------------------	---------------------------

SAFETY INSPECTION **25/01/2022** **13:26** **25/01/2022** **13:37** **89,975** **Bristol** **BL024825**

02 Glass / Windows	top up washers
18 Wheels Check Torques	
31 Battery Aux	shoreline and charge aux
Safety Inspection	

Unplanned Repair	08/02/2022	18:43	15/02/2022	12:59	90,093	Bristol	BL024985
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

42 Coolant System	Losing coolant, back at heritage vw
-------------------	-------------------------------------

SAFETY INSPECTION	15/02/2022	17:55	17/02/2022	11:10	90,105	Bristol	BL025084
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	Top Up Screenwash
18 Wheels Check Torques	Torque All Wheel Nuts
Safety Inspection	Carry Out Safety Inspection
Annual Air Con Service	Carry Out Annual Air Condition Service
Travel Time	
MOT	

SAFETY INSPECTION	05/04/2022	15:51	05/04/2022	15:51	91,382	Bristol	BL025582
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	10/05/2022	17:26	10/05/2022	19:20	92,481	Bristol	BL025895
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques	Torque All Wheel Nuts
Safety Inspection	Carry Out Safety Inspection
02 Windscreen	Top Up Screenwash
44 Add Ad Blue	Top Up Ad Blue

SAFETY INSPECTION	21/06/2022	08:57	23/06/2022	15:55	93,678	Bristol	BL026294
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques

Safety Inspection
 27 Transmission Automatic
 13 Brakes 1
 45 Engine Oil Top Up
 02 Glass / Windows

Gear selector fault, cannot remove key from ignition
 front pads and discs replaced

SAFETY INSPECTION **15/08/2022** **14:02** **15/08/2022** **14:10** **97,988** **Bristol** **BL026905**

18 Wheels Check Torques
 Safety Inspection
 17 Tyres Replace 2 x Front

Unplanned Repair **15/09/2022** **09:35** **15/09/2022** **11:41** **100,020** **Bristol** **BL027152**

45 Engine Oil Top Up

SAFETY INSPECTION **19/10/2022** **08:25** **19/10/2022** **08:25** **102,460** **Bristol** **BL027479**

18 Wheels Check Torques
 Safety Inspection

SAFETY INSPECTION **19/10/2022** **15:51** **19/10/2022** **21:30** **102,460** **Bristol** **BL027490**

18 Wheels Check Torques
 Safety Inspection
 92 - C Service
 02 Windscreen Wipers replace
 02 Glass / Windows replace o/s switch
 13 Brakes 1 front pads
 13 Brakes 2 rear pads and discs
 17 Tyres Replace front tyres replaced
 31 Battery Aux replace aux battery

BREAKDOWN **28/10/2022** **07:00** **28/10/2022** **09:20** **102,460** **Bristol** **BL027572**

17 Tyres Replace	puncture						
Breakdown	23/11/2022	15:21	24/11/2022	14:42	102,460	Bristol	BL027861
Breakdown	Flat tyre						
Breakdown	26/11/2022	19:32	29/11/2022	10:20	103,525	Bristol	BL027886
Breakdown 31 Battery Aux	Blue lights/Genesis Not Working Replace Faulty Aux Battery						
SAFETY INSPECTION	29/11/2022	10:23	29/11/2022	14:34	103,700	Bristol	BL027905
18 Wheels Check Torques Safety Inspection 45 Engine Oil Top Up 02 Windscreen	Torque All Wheel Nuts Carry Out Safety Inspection Low Oil Warning Light - Dip Stick Is Dry - Old Defect Top Up Screenwash						
SAFETY INSPECTION	12/01/2023	10:05	12/01/2023	10:50	108,219	Bristol	BL028322
18 Wheels Check Torques Safety Inspection 71 Body Exterior 1 45 Engine Oil Top Up	Undertray damaged, req's ordering.						
Defect Repair	29/01/2023	09:24	29/01/2023	11:12	109,489	Bristol	BL028589
52 Electrical Aux 31 Charging System	Cairred out aux battery tests, all ok, charging on shoreline Replaced votronics charger						
MOT	08/02/2023	11:00	08/02/2023	15:49	109,665	Bristol	BL028759
MOT							

Travel Time
17 Tyres Replace

x 3

SAFETY INSPECTION **08/03/2023** **07:30** **08/03/2023** **09:24** **110,270** **Bristol** **BL029309**

18 Wheels Check Torques
Safety Inspection
45 Engine Oil Top Up top up engine oil

Unplanned Repair **11/04/2023** **09:05** **11/04/2023** **12:16** **113,508** **Bristol** **BL029984**

45 Engine Oil Top Up top up engine oil

SAFETY INSPECTION **13/04/2023** **08:48** **13/04/2023** **10:00** **113,588** **Bristol** **BL030017**

18 Wheels Check Torques
Safety Inspection
17 Tyres Replace 2 x Fronts
44 Add Ad Blue
45 Engine Oil Top Up

BREAKDOWN **17/05/2023** **13:30** **28/12/2023** **17:01** **115,485** **Bristol** **BL030745**

99 Diagnostic Test test underboost turbos possibly failed requires dealer due to time space

SAFETY INSPECTION **28/12/2023** **17:05** **28/12/2023** **17:08** **115,488** **Bristol** **BL036905**

18 Wheels Check Torques
Safety Inspection
Replace Vehicle Fuel Card Replace Vehicle Fuel Card
45 Engine 1 re check vw work
02 Glass / Windows

Unplanned Repair	01/01/2024	12:00	01/01/2024	18:26	115,488	Bristol	BL037060
34 Lights Bulb Replacement 85 Body Interior 1	Replaced offside brake light and side light Refitted inner roof cover						
Unplanned Repair	10/01/2024	11:58	10/01/2024	12:11	115,488	Bristol	BL037413
02 Windscreen Wipers 86 Doors 86 Sliding Door	Replaced blades Door warning on O/S door seal damaged door contact switch damaged by seal						
Unplanned Repair	15/01/2024	07:41	15/01/2024	07:45	115,488	Bristol	BL037603
86 Sliding Door	Requires offside sliding door seal and contacts parts in stock						Parts ordered in store
Unplanned Repair	19/01/2024	09:47	20/01/2024	08:58	115,488	Bristol	BL037767
86 Sliding Door 16 Suspension 1	Requires offside sliding door seal and contacts parts in stock Replaced PC Repaired nearside link						
Breakdown	06/02/2024	23:44	07/02/2024	09:23	116,000	Bristol	BL038381
Breakdown	Puncture						
SAFETY INSPECTION	09/02/2024	10:00	09/02/2024	10:11	116,838	Bristol	BL038498
18 Wheels Check Torques Safety Inspection MOT Travel Time							
Unplanned Repair	03/03/2024	13:21	03/03/2024	13:24	116,838	Bristol	BL039288
45 Engine Oil Top Up							

Unplanned Repair	05/03/2024	10:24	05/03/2024	10:33	118,003	Bristol	BL039356
13 Brakes 1	Replace Worn Front Brake Discs And Pads						
13 Brakes 2	Replace Worn Rear Brake Discs And Pads						
45 Engine Oil Top Up	Top Up Engine Oil Level						
SAFETY INSPECTION	19/03/2024	17:56	19/03/2024	18:42	122,449	Bristol	BL039876
18 Wheels Check Torques							
Safety Inspection							
56 Comms Equipment	Other handheld radio Ariel need replacing - OLD DEFECT						
45 Engine Oil Top Up							
Annual Air Con Service	Annual Air Condition Service						
SAFETY INSPECTION	22/04/2024	17:47	24/04/2024	14:55	125,033	Bristol	BL041020
18 Wheels Check Torques	Torque All Wheel Nuts - 180NM - #2						
Safety Inspection	Carry Out Safety Inspection						
Annual Air Con Service	Carry Out Annual Air Condition Service						
93 - D Service	Carry Out D Service						
Service D							
02 Windscreen	Top Up Screenwash						
17 Tyres Replace	Replace Worn Nearside Front Tyre						
16 Suspension 1	Replace Worn/Corroded Rear Shocks						
71 Body Exterior 1	Nearside Front Wheel Arch Liner Damaged						
71 Body Exterior 2	Front - Rear Under Trays Damaged/Missing						
SAFETY INSPECTION	03/06/2024	11:20	03/06/2024	11:22	128,282	Bristol	BL042489
18 Wheels Check Torques							
Safety Inspection							
45 Engine 1	front egr pipe leaking causing underboost parts to be ordered from tps					Awaiting Parts	
02 Glass / Windows							
Unplanned Repair	05/06/2024	08:09	05/06/2024	09:00	128,309	Bristol	BL042519
45 Engine 1	front egr pipe leaking causing underboost parts to be ordered from tps						

45 Engine 2	Replaced leaking egr pipe seal						
Breakdown	10/06/2024	16:15	11/06/2024	10:28	128,797	Bristol	BL042719
Breakdown 17 Tyres	O/S rear Tyre blow out ATS CARRIED OUT						
SAFETY INSPECTION	23/07/2024	08:45	23/07/2024	13:21	130,963	Bristol	BL044092
18 Wheels Check Torques Safety Inspection 13 Brake Pads 17 Tyres Replace 45 Engine Oil Top Up Install Saloon CCTV Camera	Replaced fronts Replaced nsf (damaged) osf (worn) nsr (worn) Re-formatted hard drive						
SAFETY INSPECTION	28/08/2024	12:26	28/08/2024	15:33	133,231	Bristol	BL045348
18 Wheels Check Torques Safety Inspection 45 Engine Ad Blue 31 Battery Aux	top up adblue check charging rate all ok battery tests ok blue lights not cutting out						
Unplanned Repair	02/09/2024	16:04	02/09/2024	16:07	133,400	Bristol	BL045532
31 Battery Aux 52 Electrical Aux	replace aux battery diagnose fault with charging issue requires further diagnostics						
Unplanned Repair	29/09/2024	10:57	15/10/2024	18:10	133,400	Bristol	BL046496
33 Ignition System 18 Wheels Check Torques Safety Inspection	Both keys require replacement						

71 Body Exterior 1	nsr wheel arch corroded
02 Glass / Windows	clear osf washer jet

Decommission Vehicle	20/02/2025	09:00	134,816	Unallocated	Un001159
-----------------------------	-------------------	--------------	----------------	--------------------	-----------------

Decommission vehicle	Decommission vehicle
----------------------	----------------------