

WM64JXB	A&E	Bodmin Amb Stn					
PDI Inspection	23/03/2015	11:00	10/04/2015	10:59	235	Redruth	RE017357
44 Add Ad Blue PDI Inspection	Supply AdBlue & dispencer						
Breakdown	23/04/2015	10:11	24/04/2015	11:21	1,817	Launceston	LA008230
03 Instruments & Sensors 1 Breakdown	Panic strip fault Electricks att. osr banging noise Merc 24 att. Rear anti roll bracket bolt secured						
Defect Repair	23/04/2015	09:19	23/04/2015	15:30	1,817	Launceston	LA008234
16 Suspension 1	At low speed banging from R/O/S wheels. Repaired with mercedes warranty						
Defect Repair	23/04/2015	09:20	27/04/2015	08:41	1,817	Launceston	LA008235
85 Body Interior 1	Panic alarm intermitent operation in patient area Warranty sent						Awaiting Warranty
Defect Repair	30/04/2015	09:10	30/04/2015	14:06	3,077	Launceston	LA008250
44 Fuel System 1	Body Exterior Fuel filler cap broken. Removed fuel angel & fitted Merc cap						
Defect Repair	30/04/2015	16:00	01/05/2015	09:28	3,077	Launceston	LA008253
44 Add Ad Blue	Supplied 20 Litres to Bodmin station						
Vehicle Deep Clean	05/05/2015	11:40	06/05/2015	11:29	4,114	Launceston	LA008265
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	05/05/2015	11:56	06/05/2015	11:52	4,114	Launceston	LA008266
18 Wheels Check Torques 44 Add Ad Blue 85 Body Interior 1	Top up ad blue. Panic alarm intermitent operation in patient area Warranty sent						

Safety Inspection

Unplanned Repair	29/05/2015	08:44	29/05/2015	09:01	4,570	Launceston	LA008334
-------------------------	-------------------	--------------	-------------------	--------------	--------------	-------------------	-----------------

45 Engine Ad Blue	supplied ad blue
-------------------	------------------

BREAKDOWN	12/06/2015	20:22	12/06/2015	22:30	14,843	Launceston	LA008509
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

001 Recover Vehicle	Vehicle Recovery
---------------------	------------------

Vehicle Deep Clean	16/06/2015	07:05	17/06/2015	09:57	15,493	Launceston	LA008374
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	16/06/2015	14:17	17/06/2015	14:30	15,493	Launceston	LA008379
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

18 Wheels Check Torques	
44 Add Ad Blue	
45 Engine Oil Top Up	
54 Warn Dev/System	Checklist Defect Speakers refitted & fault located with panic alarm. See notes
71 Body External Steps	Checklist Defect Straightened and repaired side step
87 Stretcher	Checklist Defect Supplied Stryker version of Pedi-mate. refitted harness
Safety Inspection	

Breakdown	01/07/2015	13:42	01/07/2015	15:43	18,575	Launceston	LA008420
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

15 Steering 1	Checked steering & suspension. NFF. ATS checked tracking
17 Tyres Replace	Replaced NSF tyre with part worn Continental
Breakdown	Front offside tyre tracking and low

Defect Repair	03/07/2015	13:59	03/07/2015	14:17	19,250	Launceston	LA008426
----------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

44 Add Ad Blue	Fill up add blue tank
----------------	-----------------------

Unplanned Repair	08/07/2015	13:30	08/07/2015	15:58	20,595	Redruth	RE017875
54 Warn Dev/System	Remove panic alarm strip , remove metal swarf from drilling, all ok.						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean</							

Unplanned Repair	16/09/2015	14:26	16/09/2015	14:34	40,368	Derriford	DE018896
02 Mirrors	refitted os motor and renewed mirrors						
Defect Repair	12/10/2015	08:15	12/10/2015	09:48	47,705	Launceston	LA008691
87 - Stretchers/Chairs/Boards	Body Interior Stretcher clamp not working properly, see notes.						
SAFETY INSPECTION	19/10/2015	13:10	20/10/2015	17:00	51,417	Launceston	LA008705
13 Brake Pads	Checklist Defect Front and rear brake pads replaced. Replace n/s/r inner tyre. Checklist Defect N/s/r inner wheel cracked. Side step not working, repair slight damage, now working.						
17 Tyres Replace							
18 Wheels							
18 Wheels Check Torques							
71 Body External Steps							
Safety Inspection							
93 - D Service							
Service D							
Gearbox Oil & Filter Change							
Vehicle Deep Clean	19/10/2015	14:46	21/10/2015	14:28	51,417	Launceston	LA008706
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	02/12/2015	11:47	03/12/2015	05:59	63,046	Derriford	DE019227
18 Wheels Check Torques	front body lights not working warranty straightened tail lift end cap Call sign number not fitted repaired tail lift sliders repaired attendants seat slider adjuster						
34 Lights							
55 Ramp							
71 Body Exterior 1							
71 Body Exterior 2							
89 Seats							
Safety Inspection							

Vehicle Deep Clean	03/12/2015	12:16	03/12/2015	15:28	63,071	Launceston	LA008788
Vehicle Deep Clean	Vehicle Deep Clean Not complete Lack of time (needed).						
Unplanned Repair	29/12/2015	15:44	29/12/2015	15:48	70,697	Launceston	LA008853
17 Tyres Replace	Both N/S/R tyres replaced by ATS						
Vehicle Deep Clean	11/01/2016	14:35	13/01/2016	07:27	74,894	Launceston	LA008864
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	11/01/2016	14:52	13/01/2016	12:55	74,894	Launceston	LA008865
18 Wheels Check Torques							
34 Lights Bulb Replacement	interior light not working. replace bulb.						
86 Doors	Rear door difficult to open from inside. remove panel and adjust cables.						
Safety Inspection							
MOT Pre Test							
92 - C Service							
Service C							
Travel Time							
MOT							
BREAKDOWN	08/02/2016	08:10	08/02/2016	13:36	81,597	Launceston	LA008930
86 Doors Rear	Reinforcing plates fitted by Autospray						
Vehicle Deep Clean	22/02/2016	07:32	23/02/2016	13:31	81,598	Launceston	LA008966
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	22/02/2016	08:05	24/02/2016	13:15	81,598	Launceston	LA008968
17 Tyres Replace	Both front and osr tyres renewed						

18 Wheels Check Torques							
86 Sliding Door	Side door rolloers noisy. Warranty sent						Awaiting Warranty
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Wheel Studs & Nuts Replaceme							
Handbrake Cable Replacement	Replace rear handbrake cables						
Tail Lift 6 Monthly Inspection	Statutory Inspection						

Unplanned Repair	08/03/2016	10:00	08/03/2016	11:45	83,577	Redruth	RE019047
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windows/Glass	O/S cabin glass shattered whilst driving NEW ORDERED						Awaiting Parts
------------------	--	--	--	--	--	--	----------------

Defect Repair	30/03/2016	12:17	31/03/2016	12:19	90,186	Launceston	LA009075
----------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

03 Instruments & Sensors 1	Engine management light on. Repaired by Marcedes warranty						
----------------------------	---	--	--	--	--	--	--

Vehicle Deep Clean	12/04/2016	08:46	14/04/2016	12:05	93,461	Launceston	LA009099
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	12/04/2016	16:02	14/04/2016	10:14	93,461	Launceston	LA009104
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

02 Windows/Glass	o.s. saloon glass replaced by Nat. Windscreens						
34 Lighting System	Electrical Auxs auto-leveling u/s. Lights stuck in position 3.						Awaiting Warranty
43 Exhaust System 1	Tailpipe mount bracket repaired						
UB Fire Suppression Service	Unable to free up extinguisher contents						
85 Body Int Alcohol Gel Dispen							
Fit Throw Lines & SOP							
93 - D Service							
Service D							

Unplanned Repair	22/04/2016	09:35	25/04/2016	13:30	95,056	Launceston	LA009133
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

44 Fuel System 1	fuel return pipe to filter leaking parts ordered, wrong parts sent. see notes.
Road Test	Extended road test.

Unplanned Vehicle Clean	09/05/2016	07:36	09/05/2016	14:32	97,933	Launceston	LA009172
--------------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean Saloon only.
--------------------	---------------------------------

Vehicle Deep Clean	19/05/2016	14:05	20/05/2016	14:20	100,956	Launceston	LA009206
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean NOT COMPLETE OF TIME/ LABOUR.
--------------------	--

SAFETY INSPECTION	19/05/2016	14:40	23/05/2016	09:40	100,956	Launceston	LA009207
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windows/Glass	O/S cabin glass shattered whilst driving NEW ORDERED	
17 Tyres Fit Winter	Replaced worn NSR tyres with winter tyres	
18 Wheels Check Torques		
34 Lighting System	Electrical Auxs auto-leveling u/s. Lights stuck in position 3. Repaired	
34 Lights	Repaired wiring to OSR amber marker lamp & replaced both damaged front contours	
34 Lights Bulb Replacement	Replaced cab interior light bulb	
86 Sliding Door	Side door rolloers noisy. Warranty sent	Awaiting Warranty
87 Stretcher	Replaced 2 x belts	
Check Vehilce Call Signs	Check vehilce call signs are fitted and correct	
Safety Inspection		
Gearbox Oil & Filter Change		

SAFETY INSPECTION	30/06/2016	10:27	01/07/2016	12:47	110,596	Launceston	LA009298
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher	2x extinguishers renewed	
02 Cab Assembly 1	n.s. mirror back renewed	
13 Brake Pads	Rear pads renewed	
18 Wheels Check Torques		
43 Exhaust System 1	Reposition tailpipe	
55 Tail Lift	Bridge plate guide secured	
71 Body Exterior 1	O>S damage to battery locker door and wheel arch.	Monitoring
71 Body External Steps	Side step freed off.	
85 Body Interior 1	Body Interior Saloon emergency window. pull strip stretched NFF	
86 Sliding Door	Side door rolloers noisy. Warranty sent	Awaiting Warranty

Safety Inspection
92 - C Service
Service C
Reposition grab bag shelf

Vehicle Deep Clean 30/06/2016 10:52 01/07/2016 07:36 110,596 Launceston LA009299

Vehicle Deep Clean Vehicle Deep Clean Saloon Only lack of labour/time.

SAFETY INSPECTION 09/08/2016 10:00 10/08/2016 10:44 121,920 Launceston LA009393

13 Brake Pads	Renew front discs & pads	
16 Suspension 1	Play in front struts	Awaiting Warranty
17 Tyres Replace	OSR tyres renewed	
18 Wheels Check Torques		
55 Tail Lift	Refit bridge plate guide	
71 Body Exterior 1	O>S damage to battery locker door and wheel arch.	Monitoring
86 Sliding Door	Side door rolloers noisy. Warranty sent	Awaiting Warranty
Safety Inspection		
Tail Lift 6 Monthly Inspection	Statutory Inspection	

Vehicle Deep Clean 09/08/2016 14:01 10/08/2016 14:44 121,920 Launceston LA009395

Vehicle Deep Clean Vehicle Deep Clean

Defect Repair 23/08/2016 12:23 23/08/2016 13:23 124,954 Launceston LA009423

17 Tyres Replace Renew front tyres

Defect Repair 08/09/2016 11:59 08/09/2016 14:18 129,643 Redruth RE019897

18 Wheels Balance & Alignmen	ATS balanced both front wheels	
34 Lights Bulb Replacement	Replaced NSF main beam bulb	
71 Body Exterior 1	Body Exterior front bumper ding from RTC, loose wheel arch pin	Awaiting Body Repair

BREAKDOWN	16/09/2016	08:30	16/09/2016	15:01	131,983	Launceston	LA009488
56 Comms Equipment 71 Body External Steps	Repaired via P.C.E over the phone.(Sat nav) Side step not working, now freed up and working.						
Vehicle Deep Clean	19/09/2016	07:11	19/09/2016	15:04	131,983	Launceston	LA009489
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/09/2016	15:22	21/09/2016	13:39	131,994	Launceston	LA009500
16 Suspension 1 17 Tyres Replace 18 Wheels Check Torques 71 Body Exterior Roof 86 Sliding Door Safety Inspection 93 - D Service Service D	Play in front struts NSR tyres renewed No blast film on skylight Side door rolloers noisey. Warranty sent					Monitoring Monitoring Monitoring	
Breakdown	02/10/2016	05:59	03/10/2016	10:27	132,496	Launceston	LA009535
Breakdown	says Fire Trace Fault, to be looked at next inspection.						
Breakdown	03/10/2016	07:51	03/10/2016	10:26	132,851	Launceston	LA009537
Breakdown	BURNING SMELL IN CAB ?? ELEC ?? . No fault found.						
Vehicle Deep Clean	01/11/2016	14:13	02/11/2016	17:00	141,344	Launceston	LA009614
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	02/11/2016	08:44	04/11/2016	13:08	141,344	Launceston	LA009616
13 Brakes 1 16 Suspension 1 18 Wheels Check Torques	Replace brake pedal rubber. Play in front struts					Awaiting Warranty	

34 Emergency Lights	N/s/f wing blue light missing.	
45 Engine 1	AUX belt tensioner worn (warranty) City West to replace 03/11/16	
54 Reversing Systems	Rear camera bracket damaged.	
55 Ramp	O/s ramp side arm adjusting pin missing.	
71 Body Exterior Roof	No blast film on skylight	
71 Body External Steps	Step alarm sounding, adjust side door catch.	
86 Sliding Door	Side door rolloers noisy. Warranty sent	Awaiting Warranty
Safety Inspection		
Travel Time	Travel to City West for warranty work.	
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill	
MOT Pre Test		

Breakdown	21/11/2016	22:50	22/11/2016	08:50	143,375	Launceston	LA009681
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Fire suppression system warning. Awaiting warranty. Ok to use the vehicle
-----------	---

SAFETY INSPECTION	12/12/2016	10:47	15/12/2016	08:12	150,569	Launceston	LA009744
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher	Fire trace warning sounding off	Awaiting Warranty
13 Brake Pads	renewed rear discs and pads	
16 Suspension 1	Play in front struts Front struts replaced under warranty mercedes of plymouth	
16 Suspension 2	rear spring slippers adrift Replaced under warranty by Mercedes of Plymouth	
18 Wheels Check Torques		
45 Engine 1	See notes	
71 Body Exterior 1	various body damage requiring bodyshop visit	Awaiting Body Repair
86 Sliding Door	Side door rolloers noisy. Warranty sent	
Safety Inspection		
Supply Sat Nav	upgraded	
Travel Time		
MOT	Done by mercedes of plymouth	
92 - C Service		
Service C		
Gearbox Oil & Filter Change		

Vehicle Deep Clean	12/12/2016	10:54	14/12/2016	09:43	150,569	Launceston	LA009745
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean Not Finished gone Derriford Warranty work.
--------------------	---

BREAKDOWN	04/01/2017	08:29	09/01/2017	09:54	156,447	Redruth	RE020512
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

001 Recover Vehicle	Vehicle Recovery
03 Instruments & Sensors 1	EML on and sudden loss of power
41 Turbo	Turbo disintegrated. Turbo, pipes and intercooler replaced by City West

Tail Lift Annual Service	11/01/2017	12:39	12/01/2017	07:30	156,577	Launceston	LA009842
---------------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	Renewed os dipped beam bulb
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by south west lifts P/O 151145138
Tail Lift 6 Monthly Inspection	Statutory Inspection
Install Saloon CCTV Camera	Already done

Vehicle Deep Clean	23/01/2017	13:24	26/01/2017	13:52	159,041	Launceston	LA009882
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean no Exterior wash could not get at washbay.
--------------------	---

SAFETY INSPECTION	24/01/2017	07:56	26/01/2017	14:01	159,041	Launceston	LA009883
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher	Fire trace warning sounding off
02 Cab Assembly 1	repaired cab storage cupboard
18 Wheels Check Torques	
71 Body Exterior 1	various body damage requiring bodyshop visit
71 Body External Steps	straightened and repaired side step
89 Seats	refitted and tightened swivel seat pins
Safety Inspection	
Medical Device and Equip Chec	

BREAKDOWN	03/02/2017	08:44	03/02/2017	13:00	161,235	Launceston	LA009920
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	NSF replaced @ Bodmin station by ATS St Austell
------------------	---

Breakdown	12/02/2017	22:46	13/02/2017	00:00	164,620	Launceston	LA009943
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	flat						
Breakdown	12/02/2017	22:46	13/02/2017	08:28	164,620	Launceston	LA009944
17 Tyres Replace Breakdown	Tyre replaced by ATS tyre flat						
Breakdown	13/02/2017	03:19	13/02/2017	04:50	164,718	Launceston	LA009945
17 Tyres Replace Breakdown	Both n/s/r tyres replaced by ATS flat rear passengers tyres						
Breakdown	15/02/2017	13:07	15/02/2017	16:30	165,780	Launceston	LA009960
17 Tyres Replace Breakdown	O/s/f tyre replaced by ATS flat tyre osf 205/75 R16C						
Breakdown	26/02/2017	21:45	03/03/2017	13:45	168,819	Launceston	LA009995
001 Recover Vehicle 02 Mirrors 13 Brakes 1 24 Driveshaft 1 Breakdown Travel Time	Vehicle Recovery - AA OS mirror shell renewed Handbrake cable & bracket replaced by City west roache P/O 151148596 Propshaft supplied to Roche gearbox gone						
Vehicle Deep Clean	06/03/2017	08:35	07/03/2017	14:00	168,921	Launceston	LA010028
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/03/2017	11:03	07/03/2017	12:57	168,921	Launceston	LA010029
02 Cab Assembly 1 03 Instruments & Sensors 1 17 Tyres Replace 18 Wheels Check Torques 71 Body Exterior 1 71 Body External Steps 85 Body Interior 1	renewed 1x missing torch low coolant level showing on dash topped up renewed worn osri tyre various body damage renewed osr corner straightened side step vaccum matteress door ripped off						
						Awaiting Body Repair	
						Awaiting Parts	

Safety Inspection
 UB Fire Suppression Service
 Handbrake Cable Replacement Not done due to vehicle age
 93 - D Service
 Service D

MRO Refresh	11/04/2017	14:21	11/04/2017	14:51	177,044	Launceston	LA010152
--------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

MRO Refresh

MRO Refresh	12/04/2017	09:16	12/04/2017	12:47	177,045	Launceston	LA010154
--------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

MRO Refresh

Breakdown	18/04/2017	00:23	19/04/2017	11:04	177,654	Launceston	LA010159
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1 Breakdown	Cab blower motor replaced by City West Comms Air Conn and Demister vehicle @ city west roche						
---------------------------	---	--	--	--	--	--	--

Defect Repair	17/04/2017	09:02	17/04/2017	13:24	177,654	Redruth	RE021082
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

55 Tail Lift 86 Doors Rear	Refitted plastic tail lift bridge plate guides Doors stay bar has sheared off. Removed and replaced broken bolt						
-------------------------------	--	--	--	--	--	--	--

Vehicle Deep Clean	24/04/2017	07:57	26/04/2017	10:57	177,754	Launceston	LA010177
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	24/04/2017	08:22	27/04/2017	10:07	177,754	Launceston	LA010178
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques 34 Lights Bulb Replacement 71 Body Exterior 1 71 Body Exterior 2 85 Body Interior 1 Safety Inspection Annual Heater Service	Day running light bulb renewed various body damage renewed osr corner NSF fog light surround renewed vaccum matteress door ripped off, renewed Annual Heater Service						
---	--	--	--	--	--	--	--

Annual Air Con Service

Annual Air Condition Service

Unplanned Repair	04/05/2017	11:15	04/05/2017	11:35	178,990	Derriford	DE021952
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Mirrors	Replaced o/s mirror cover						
------------	---------------------------	--	--	--	--	--	--

Breakdown	03/05/2017	19:40	03/05/2017	22:00	177,993	Launceston	LA010213
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace Breakdown	O/s/r inner tyre replaced by ATS OSR inner flat tyre 205/75 R16						
-------------------------------	--	--	--	--	--	--	--

Unplanned Repair	12/05/2017	14:30	12/05/2017	15:10	182,552	Derriford	DE022001
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Windscreen Wipers 34 Lights	Replaced wiper blades Repair faulty connection to o/s side repeator						
-----------------------------------	--	--	--	--	--	--	--

BREAKDOWN	25/05/2017	09:28	25/05/2017	09:30	182,552	Launceston	LA010286
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	OSF tyre renewed by ATS Redruth, cracked rim, Wheel supplied by Launceston						
------------------	--	--	--	--	--	--	--

Vehicle Deep Clean	30/05/2017	09:28	01/06/2017	08:17	184,593	Launceston	LA010302
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	30/05/2017	09:37	31/05/2017	09:18	184,593	Launceston	LA010303
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	renewed front pads						
16 Suspension 1	slight play rear roll bar link bushes						Monitoring
18 Wheels Check Torques							
71 Body Exterior 1	various body damage						Awaiting Body Repair
85 Body Interior 1	repaired cupboard shuts						
Safety Inspection							

Defect Repair	19/06/2017	07:53	22/06/2017	12:03	192,278	Launceston	LA010381
34 Emergency Lights	Emg Warning Devices Top Rear NS Corner Blue Light missing - Notes					Awaiting Parts	
34 Lights	Electrical Auxs Headlight dipped beam not correctly adjusted						
55 Tail Lift	Body Exterior tail lift breaching plate bolt sheared off - Repaired SWL						
MGS Gas Storage Modifications	MGS Gas Storage Modifications						
Breakdown	08/07/2017	10:56	10/07/2017	07:36	196,670	Launceston	LA010458
Breakdown	Indicators not working						
Unplanned Repair	05/07/2017	11:00	05/07/2017	11:23	195,768	Redruth	RE021581
45 Engine Oil Top Up	Top up oil. 2.5 lts, oil light on.						
SAFETY INSPECTION	11/07/2017	08:04	21/07/2017	11:38	197,420	Launceston	LA010465
01 Air Conditioning 1	Rattle coming from A/C compressor					Awaiting Warranty	
01 Heating 1	Heater exhaust cracked						
02 Cab Ass Fire Extinguisher	Both fire extinguishers out of date - Replaced						
02 Cab Assembly 1	Both front seat armrests insecure - Resecured						
02 Cab Assembly 2	Centre console white button missing - Replaced						
15 Steering 1	Slight play in O/S/F rack end						
16 Suspension 1	slight play rear roll bar link bushes					Awaiting Warranty	
16 Suspension 2	Both front lower arm ball joints have slight play					Awaiting Warranty	
17 Tyres	Both O/S/R, N/S/R/O and N/S/F tyres worn - Replaced					Awaiting Warranty	
18 Wheels Check Torques							
34 Emergency Lights	Emg Warning Devices Top Rear NS Corner Blue Light missing - Notes					Awaiting Warranty	
34 Lights	N/S/F fog light inop and surround missing - Repaired and replaced						
54 Reversing Systems	Reverse camera, bracket and mounting plate all missing						
55 Tail Lift	Bridge plate guides mounting plate ripped						
71 Body Exterior 1	various body damage - Photographed and reported						
71 Body Exterior 2	Rear spray supressor mounting plate insecure						
71 Body Exterior 3	Front number plate damaged						
85 Body Interior 1	Carry chair bracket cracked						
85 Body Interior 2	Cupboard below front saloon seat latch ripped off						
85 Body Interior 3	Medical gases cupboard handle ripped off						
86 Door Blinds	Side door blind broken					Awaiting Warranty	
89 Seats	Both N/S/R saloon swivel seat bearings rough					Awaiting Warranty	

Safety Inspection
 92 - C Service
 Service C
 Tail Lift 6 Monthly Inspection Statutory Inspection

Vehicle Deep Clean 11/07/2017 12:20 21/07/2017 15:00 197,420 Launceston LA010466

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 20/08/2017 10:46 25/08/2017 12:39 205,303 Launceston LA010604

34 Lighting System Emg Warning Devices indicator bulb OS wing - Repaired at city west
 34 Lights OS repeater lens broken _ New required - Repaired at city west
 42 Coolant System Water pump leaking ??? - Repaired at city west
 42 Radiator Engine LEAKING COOLANT, ? WATER PUMP - Repaired at city west
 Breakdown Coolant leak - Repaired at city west

SAFETY INSPECTION 24/08/2017 11:55 25/08/2017 12:35 205,303 Launceston LA010618

01 Air Conditioning 1 Rattle coming from A/C compressor - Espar repaired
 01 Heating 1 Heater exhaust cracked - Espar repaired
 15 Steering 1 Slight play in O/S/F rack end Awaiting Warranty
 16 Suspension 1 slight play rear roll bar link bushes Awaiting Warranty
 16 Suspension 2 Both front lower arm ball joints have slight play Awaiting Warranty
 18 Wheels Check Torques
 34 Lights O/S/F sidelight inop - Replaced
 85 Body Interior 1 Carry chair bracket cracked Awaiting Warranty
 86 Door Blinds Side door blind broken Awaiting Warranty
 86 Sliding Door Bearings rough Awaiting Warranty
 89 Seats Both N/S/R saloon swivel seat bearings rough Awaiting Warranty
 Safety Inspection
 Travel Time Collect from mercedes Roach
 Replace Vehicle Fuel Card Replace Vehicle Fuel Card
 Gearbox Oil & Filter Change

Defect Repair 05/09/2017 08:50 05/09/2017 09:25 207,869 Redruth RE021985

34 Emergency Lights Lighting System N/S top side blue light not working. Knocked off. Replaced light

Vehicle Deep Clean	03/10/2017	09:43	04/10/2017	13:12	215,004	Launceston	LA010753
Vehicle Deep Clean	Vehicle Deep Clean No powerwash its broken.						
SAFETY INSPECTION	03/10/2017	14:08	06/10/2017	10:58	215,004	Launceston	LA010754
02 Mirrors	O/S/F mirror damaged - Replaced						
13 Brakes 1	Rear brake pads low - To be replaced at dealer						
15 Steering 1	Slight play in O/S/F rack end						
16 Suspension 1	slight play rear roll bar link bushes						
16 Suspension 2	Both front lower arm ball joints have slight play						
17 Tyres	N/S/R inner tyre worn to 3mm - Replaced						
18 Wheels Check Torques							
45 Engine 1	Engine surge intermittent						
55 Tail Lift	Bridge plate guides insecure - Re-secured						
71 Body External Steps	Step has been hit - Straightened bent mounts and lubricated - All OK						
85 Body Interior 1	Carry chair bracket cracked - Replaced by Ben						
86 Door Blinds	Side door blind broken - Ben has ordered part						
86 Sliding Door	Bearings rough - Replaced by Ben						
89 Seatbelts	N/S/F saloon swivel seat seatbelt renewed						
89 Seats	Both N/S/R saloon swivel seat bearings rough - Replaced by Ben						
Safety Inspection							
93 - D Service							
Service D							
Vehicle Deep Clean	05/10/2017	14:34	05/10/2017	14:37	215,004	Launceston	LA010768
Vehicle Deep Clean	Vehicle Deep Clean done 3/10/17 la010753.						
Breakdown	19/10/2017	23:55	24/10/2017	14:41	217,589	Launceston	LA010811
31 Charging System Breakdown	Alternator U/S. Sent to Mercedes of Truro for repair battery light on dash						
SAFETY INSPECTION	14/11/2017	09:38	17/11/2017	10:16	221,855	Launceston	LA010915
16 Suspension 1	Front lower arms have excessive play - Replaced						

Awaiting Warranty

16 Suspension 2 Both front shock absorbers have excessive play - Replaced
 17 Tyres O/S/F and O/S/R inner tyres worn to 3mm - Replaced
 17 Tyres Tracking Check camber angle after fitting new shocks
 18 Wheels Check Torques
 34 Lighting System N/S/F fog light surround missing - Replaced
 34 Lights N/S/R number plate light insecure - Repaired
 34 Lights Bulb Replacement N/S/R top sidelight (red) only 50% working - Replaced
 71 Body External Steps Side step sticking - Lubricated and freed rollers
 86 Door Blinds Side door blind broken - Ben has ordered part
 Safety Inspection
 MOT Pre Test
 Travel Time
 MOT
 92 - C Service
 Service C

Vehicle Deep Clean	14/11/2017	09:52	17/11/2017	14:11	221,885	Launceston	LA010917
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	23/11/2017	10:39	23/11/2017	10:41	222,782	Launceston	LA010951
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	Crew reported step coming out while driving - Check operation and road test NFF
------------------------	---

Unplanned Repair	27/11/2017	12:08	27/11/2017	14:16	222,782	Redruth	RE022544
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body Exterior 1	Replace rear mud flap.
71 Body External Steps	Free-up side step.

Breakdown	15/12/2017	12:24	15/12/2017	14:00	228,778	Launceston	LA011034
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	N/S/F Tread - Spoke to OO, ATS to attend at Bodmin
-----------	--

Breakdown	15/12/2017	15:05	18/12/2017	09:19	228,778	Launceston	LA011039
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Bald Tyre
-----------	-----------

Breakdown	25/12/2017	09:05	27/12/2017	08:00	231,235	Launceston	LA011073
71 Body External Steps Breakdown	Side-step u/s. SatNav faulty						
BREAKDOWN	27/12/2017	08:00	28/12/2017	14:04	231,235	Redruth	RE022749
71 Body External Steps Supply Sat Nav	Side step u/s. New step now fitted. Sat nav u/s P.C.E to repair.						
SAFETY INSPECTION	09/01/2018	13:24	10/01/2018	14:58	234,070	Derriford	DE023432
02 Cab Assembly 1	Torch replaced						
02 Windscreen Wipers	wiper blades renewed						
16 Suspension 1	rear spring slipper pads u/s						
17 Tyres	valve extensions fitted to rear tyres						
17 Tyres Replace	NSR tyres renewed						
18 Wheels Check Torques							
31 Battery Comms	free off and open battery locker						
43 Exhaust System 1	Tail pipe renewed						
44 Fuel System 1	fuel angel loose no seal fitted cap changed						
55 Ramp	guide runners adrift.renewed lift pipe						
71 Body Exterior 1	Nearside camera dome smashed						
71 Body Exterior 2	nsf front arch liner damaged						
71 Body Exterior 3	NSF lower corner damaged						
71 Body External Steps	Straightened and repaired side step						
85 Body Interior 1	Bulkhead grommet renewed						
86 Door Blinds	side door blind u/s						
86 Door Seals	Offside cab door seal renewed						
86 Doors Rear	nearside rear door frame repaired						
86 Sliding Door	Side door rollers renewed						
87 Oxygen System	system service out of date air flows out of date						
89 Seats	Attendants seat adjuster bar missing						
Safety Inspection							
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by south west lifts P/O 151164922						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	11/01/2018	11:57	12/01/2018	06:00	234,070	Derriford	DE023453

Awaiting Warranty

Awaiting Parts
Awaiting Parts
Monitoring

Awaiting Parts

Monitoring
Awaiting Parts

Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	13/01/2018	13:29	16/01/2018	13:47	234,070	Launceston	LA011118
Breakdown	F/N/S LOW PRESS						
Unplanned Repair	19/01/2018	12:00	19/01/2018	15:23	235,150	Derriford	DE023501
02 Mirrors	Replaced o/s mirror glass						
Breakdown	22/01/2018	15:51	26/01/2018	14:35	237,073	Launceston	LA011150
Breakdown	Puncture						
Defect Repair	01/02/2018	09:00	01/02/2018	09:43	239,266	Redruth	RE022986
71 Body External Steps	Side step permanently deployed electrical fault. Checked & spaced door switch						
Breakdown	04/02/2018	18:39	05/02/2018	09:41	240,019	Launceston	LA011196
Breakdown	front O/S						
BREAKDOWN	19/02/2018	07:52	22/02/2018	10:57	242,351	Launceston	LA011246
17 Tyres 24 Driveshaft 1	Tyres Front off side tyre inside showing bare metal. - Checked All OK Engine Loud engine noise, when excelerating - Replaced prop on safety						
SAFETY INSPECTION	19/02/2018	08:24	23/02/2018	11:16	242,351	Launceston	LA011247
01 Heating 1 02 Cab Assembly 1 02 Cab Assembly 2 02 Mirrors	Cab Blowers inop - Replaced rear stat N/S/F seat armrest insecure - Re-secured Bulkhead window catch twisted - Re-secured Both front mirror glasses insecure - Both mirror arms replaced						

13 Brakes 1	Front discs and pads worn - Replaced (slider seized)	
13 Brakes 2	Rear discs and pads worn - Replaced	
15 Steering 1	Steering rack has play - Replaced	
16 Suspension 1	rear spring slipper pads u/s - Replaced all 4	
17 Tyres Tracking	Tracked vehicle twice due to ESP fault	
18 Wheels Check Torques		
24 Driveshaft 1	Centre propshaft rear bearings worn - Replaced prop	
34 Lighting System	N/S/R fog light damaged, O/S/R reverse light LED's inop - Replaced lights	
34 Lights	N/S torch inop - Replaced Torch	
34 Lights Bulb Replacement	Both front sidelights inop - Replaced	
55 Ramp	O/S tail lift gate seized in upper position - Sevicable	Monitoring
55 Tail Lift	N/S platform light inop and Bridge plate guides pulled out of body - Resecured	
71 Body Exterior 1	Nearside camera dome smashed	Awaiting Body Repair
71 Body Exterior 2	nsf front arch liner damaged - Replaced	
71 Body Exterior 3	N/S/F fog light surround missing	
85 Body Interior 1	Vacuum mattress cupboard pulling away from hinges - Re-secured longer screws	
86 Door Blinds	side door blind u/s - Ben WAS repaired (with help)	
86 Door Lock	Side door wont lock/unlock on key, Central locking working	Monitoring
86 Doors	O/S/R door stay bar bent and T/L hitting carry chair - Replaced door stay	
86 Doors Rear	Rear door not latching on bottom catch - NOTES	
86 Sliding Door	Side door panel cracked and door difficult to open from outside - NOTES	
87 Oxygen System	system service out of date air flows out of date	Monitoring
89 Seats	Attendants seat adjuster bar missing - Replaced	
Road Test	Carry out road tests before and after tracking steering angle/ESP fault	
Safety Inspection		
85 Body Int Alcohol Gel Dispen		
93 - D Service		
Service D		
UB Fire Suppression Service		
Handbrake Cable Replacement	Replace rear handbrake cables	
Wheel Hub Flanges Replaceme		

Vehicle Deep Clean	21/02/2018	14:11	23/02/2018	10:17	242,352	Launceston	LA011255
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	01/03/2018	10:00	01/03/2018	10:32	243,272	Redruth	RE023170
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Doors Rear	Doors rear door stop bolt broken in winds. replaced broken bolt
---------------	---

Emergency Deep Clean	14/03/2018	10:39	15/03/2018	13:00	246,663	Launceston	LA011319	
Emergency Deep Clean								
Breakdown	16/03/2018	13:08	20/03/2018	08:46	248,924	Launceston	LA011327	
Breakdown	flat tyre front driver's side							
Vehicle Deep Clean	21/03/2018	10:38	23/03/2018	14:52	248,924	Launceston	LA011338	
Vehicle Deep Clean	Vehicle Deep Clean EDC Done Only a week ago.							
SAFETY INSPECTION	21/03/2018	08:52	23/03/2018	13:59	248,924	Launceston	LA011341	
02 Cab Assembly 1	Phone cradle broken					Monitoring		
02 Cab Assembly 2	Centre console cuboard insecure - resecured							
02 Mirrors	o/s mirror frame and shell cracked - Replaced							
13 Handbrake	Front handbrake cable wearing from contact with chassis							
15 Steering 1	Excess toe out o/s/f wheel - tracked							
18 Wheels Check Torques								
55 Ramp	O/S tail lift gate siezed in upper position, both bearings worn - Sevicable							
71 Body Exterior 1	Nearside camera dome smashed							
85 Body Interior 1	Drugs cuboard door insecure - resecured							
85 Body Interior 2	Saloon white board insecure - Resecured							
86 Door Lock	Side door wont lock/unlock on key, Central locking working							
86 Sliding Door	Side door magnet stay bent - straightened							
87 Oxygen System	system service out of date air flows out of date							
89 Seats	Rear facing seat rail adjustment bar fallen off - re-fitted							
Safety Inspection								
BREAKDOWN	24/03/2018	04:40	26/03/2018	10:31	248,924	Redruth	RE023329	
86 Sliding Door	side door opening over 50mph. Checked & replaced loose/broken top catch. Adjuste							
Breakdown	17/04/2018	07:14	19/04/2018	09:37	255,748	Launceston	LA011434	
17 Tyres Replace	ATS attending with new rim and tyre							
Breakdown	front O/S tyre puncture - Cracked wheel Ordered							

Vehicle Deep Clean	30/04/2018	09:25	01/05/2018	14:33	258,833	Launceston	LA011473
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/04/2018	09:36	01/05/2018	11:36	258,833	Launceston	LA011474
02 Cab Assembly 1	Phone cradle broken - New required PCE?					Monitoring	
02 Cab Assembly 2	N/S/F armrest insecure - Re-secured						
17 Tyres	Both O/S/R tyres and N/S/F tyre worn below 3mm						
18 Wheels Check Torques							
85 Body Interior 1	Bulkhead window catch insecure - Re-secured						
89 Seatbelts	N/S/F saloon seatbelt anchor/detend pin arm insecure - Re-secured						
89 Seats	Front rear facing saloon seat adjuster bar insecure - Re-secured						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Fit Poster Holder	Fit Poster Holder						
Gearbox Oil & Filter Change							
92 - C Service							
Service C							
Breakdown	08/05/2018	16:25	16/05/2018	13:22	259,587	Launceston	LA011513
27 Transmission Automatic							
Breakdown	Auto gear selector not selecting drive - Sent to dealer						
Breakdown							
Breakdown	26/05/2018	18:32	26/05/2018	21:41	263,559	Launceston	LA011563
18 Wheels							
Breakdown	N/S/R inner wheel cracked 225/75 R16C Michelin os inner flat						
Breakdown							
ACCIDENT	27/05/2018	11:51	12/06/2018	08:20	264,867	Launceston	LA011564
Breakdown	body damage to offside - collision with property - Repaired at Autospray						

Vehicle Deep Clean	11/06/2018	09:19	13/06/2018	11:50	264,867	Launceston	LA011601
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	11/06/2018	09:19	11/06/2018	15:29	264,867	Launceston	LA011602
02 Cab Assembly 1	Phone cradle broken - New required PCE?						
02 Cab Assembly 2	Drivers hand torch dim, despite charge - battery replaced						
02 Windscreen Wipers	Screenwash low - topped up						
13 Handbrake	Handbrake req. adjustment - adjusted						
16 Suspension 1	Rear leaf springs out of alignment - servicable						
17 Tyres Replace	n/s/r tyres worn - replaced						
18 Wheels Check Torques							
24 Driveshaft 1	o/s/r outer driveshaft oil seal leaking - repaired						
24 Driveshaft 2	Propshaft centre bearing bush cracked - servicable						
34 Lighting System	n/s front marker 50% working - wiring repaired and LED unit replaced						
34 Lights	n/s front fog light surround missing - servicable						
34 Lights Bulb Replacement	o/s running light u/s - replaced						
45 Engine 1	Oil leak from boost hose - monitoring						
45 Engine Oil Top Up	Oil low - Topped up 0.6ltrs						
55 Ramp	Free off and lube O/S gate and top-up Lift oil						
56 Comms Equipment	MDT screen insecure - re-secured						
85 Body Interior 1	Saloon white board pen holders insecure - re-secured						
86 Sliding Door	Upper magnet bent, lower magnet missing - upper straightened						
89 Seats	Saloon rear facing seat rail bar fallen off - repaired						
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Breakdown	19/06/2018	22:09	21/06/2018	08:15	265,300	Launceston	LA011639
02 Windows/Glass Breakdown	O/s body window glass shattered See notes Cab window shattered drivers side					Awaiting Parts	
MRO Refresh	05/07/2018	11:02	06/07/2018	14:00	268,160	Derriford	DE024582
MRO Refresh							

Breakdown	03/07/2018	12:59	04/07/2018	07:19	268,102	Launceston	LA011691
Breakdown	all electrics failed on vehicle						
Breakdown	03/07/2018	17:07	24/07/2018	11:58	268,160	Launceston	LA011693
02 Mirrors	o/s/ mirror glass broken - replaced						
31 Battery Chassis	Internal short in new battery after on charge all night - Replaced faulty batt.						
32 Starting System 1	Starter Motor Short Circuit - starter replaced						
43 Exhaust System 1	DPF Ash Content High - Tunap Regeneration Performed						
45 Engine 1	EML Illuminated - Glow Plug Circuit Open See notes						
45 Engine 2	Injector seals leaking on both banks						
Breakdown	loss of power whilst driving, no voltage at battery						
Unplanned Repair	03/07/2018	08:03	03/07/2018	09:40	266,666	Launceston	LA011707
02 Windows/Glass	O/s body window glass shattered Replaced by National windscreens						
SAFETY INSPECTION	23/07/2018	07:05	27/07/2018	12:47	268,160	Derriford	DE024684
01 Air Conditioning 1	Air con compressor & pipe connection replaced by Espar P/O 151174851						
02 Cab Ass Fire Extinguisher	Replace cab & saloon fire extinguishers						
13 Handbrake	Adjust h/brake cables						
18 Wheels	Replace o/s/r outer wheel cracking on stud holes						
18 Wheels Check Torques							
31 Charging System	Chassis battery not charging on drop down See notes						
41 Air Intake	Turbo to intercooler pipe insecure Straighten bent support bracket						
71 Body Exterior 1	Replace missing o/s/r reflector						
87 Stretcher	Resecure stretcher clamp retaining bolt						
Safety Inspection							
Vehicle Deep Clean	25/07/2018	05:45	25/07/2018	09:54	268,160	Derriford	DE024702
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	01/08/2018	21:01	02/08/2018	07:54	268,200	Launceston	LA011782
Breakdown	1100scraped wheelarch&cracked orange light - Servicable spoke to OO						

Breakdown	06/08/2018	16:07	06/08/2018	16:16	269,988	Launceston	LA011791
Breakdown	TURBO/FUEL ISSUE. Repaired at Redruth WS						
BREAKDOWN	07/08/2018	15:40	08/08/2018	12:19	270,137	Launceston	LA011795
01 Air Conditioning 1	Air con compressor & pipe connection replaced by Espar Turbo impeller starting to show signs of wear Carried out DPF Re-gen Engine MIL illuminated LIMP mode Road tested with scanner connected for live data						Monitoring
41 Turbo							
43 Exhaust System 1							
45 Engine 1							
Road Test							
BREAKDOWN	08/08/2018	15:36	08/08/2018	15:41	270,152	Launceston	LA011801
41 Turbo	Turbo impeller starting to show signs of wear Engine wont rev over 3000 rpm - Boost pipe loose (see notes)						Monitoring
45 Engine 1							
Defect Repair	09/08/2018	07:00	30/08/2018	10:16	270,224	Launceston	LA011803
002 Major Unit Replace Eng	Mercedes of Truro replaced engine A/C system has a leak - Mercedes unable to re-gas Engine In limp mode and engine smoking - ?Exhaust Manifold						Monitoring
01 Air Conditioning 1							
45 Engine 1							
Unplanned Repair	06/08/2018	14:00	06/08/2018	16:17	269,988	Redruth	RE024246
41 Air Intake	Replaced broken O rings in intake pipes Removed heat sheild and checked DPF pipes to Turbo & joint. All tight & ok Fumes in the cab. Checked & found leakage in air intake from turbo - intercooler						
43 Exhaust System 1							
45 Engine 1							
SAFETY INSPECTION	06/09/2018	08:00	06/09/2018	16:25	271,869	Launceston	LA011867
01 Air Conditioning 1	A/C system has a leak - Mercedes unable to re-gas - Espar repaired leak Receiver dryer hose spit / leaking oil - replaced by espar. o/s saloon window rubber seperated >50% - re-sealed Play in rear anti-roll bar bushes - servicable						Monitoring
01 Air Conditioning 2							
02 Windows/Glass							
16 Suspension 1							
18 Wheels Check Torques	Driveshaft centre bearing worn - replaced Rear gearbox mount worn - slight vibration in 4th gear at 2500-3000rpm						Monitoring
24 Driveshaft 1							
27 Transmission Automatic							

34 Lighting System	n/s/r side marker damaged and wiring corroded - replaced	
41 Turbo	Turbo impeller starting to show signs of wear - New engine fitted	
45 Engine 1	Small oil leak from the front n/s/f engine	Monitoring
55 Ramp	Gate bearings worn and gates req. adjustment - adjusted	Monitoring
71 Body Exterior 1	o/s upper bodywork damage towards the rear	Monitoring
71 Body Exterior 2	Rear spray supressor has slight movment - currently servicable	Monitoring
85 Body Interior 1	Gloves dispensossor taped up - repaired	
89 Seats	Rear facing seat rake adjuster fallen off - replaced	
Safety Inspection		
MOT Pre Test		

Vehicle Deep Clean	07/09/2018	06:58	07/09/2018	14:46	271,869	Launceston	LA011868
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	17/09/2018	03:03	17/09/2018	10:04	274,031	Launceston	LA011896
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	limp mode, no warning lights - Carried out diagnostics - No Errors in mem - OK
-----------	--

Vehicle Deep Clean	15/10/2018	09:11	17/10/2018	16:02	281,539	Launceston	LA012016
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	15/10/2018	10:00	17/10/2018	15:55	281,539	Launceston	LA012017
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	Passengers window switch broken	
11 Axle Rear	n/s/r wheel bearing noisy??	
13 Brakes 1	Rear pads worn - replaced	
13 Brakes 2	Front brakes have 36% in-balance - n/s slider seized - replaced	
13 Handbrake	Handbrake shoes replaced, cracked, friction material missing.	
15 Steering 1	Play in steering both side ?inner track arms	
16 Suspension 1	Play in rear anti-roll bar bushes - servicable	Monitoring
16 Suspension 2	Leaf springs out of alignment	Monitoring
18 Wheels Check Torques		
24 Driveshaft 1	Centre prop mount split - replaced 4 weeks ago!	Monitoring
27 Transmission Automatic	Rear gearbox mount worn - slight vibration in 4th gear at 2500-3000rpm	
34 Emergency Lights	o/s/r upper blues, 2xLED's out - servicable	Monitoring
45 Engine 1	Small oil leak from the front n/s/f engine	
52 Electrical Aux	Emg Warning Devices No sirens	

54 Reversing Systems	No Reversing Horn						
54 Sirens	Electrical Auxs cab siren LED button not lit						
55 Ramp	Gate bearings worn and gates req. adjustment - adjusted						
71 Body Exterior 1	o/s upper bodywork damage towards the rear					Awaiting Body Repair	
71 Body Exterior 2	Rear spray supressor has slight movment - currently servicable					Monitoring	
71 Body Exterior 3	n/s/f lower body corner damage						
71 Body Exterior Roof	Skylight seal hanging off - repaired						
71 Body External Steps	Spray supressor starting to split					Monitoring	
86 Sliding Door	Top door stay mount broken						
89 Seats	Rear facing saloon seat rake adj. fallen off - repaired						
Safety Inspection							
93 - D Service							
Service D							

BREAKDOWN	17/10/2018	12:29	05/11/2018	08:11	281,539	Launceston	LA012024
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

15 Steering 1	Play in either both inner track arms or rack, rack replaced 02/2018
27 Transmission Automatic	Vibration at 2500-3000rpm
45 Engine 1	Engine / Turbo Leaking Oil, Recent New Engine

Breakdown	06/11/2018	18:42	27/11/2018	07:40	281,798	Launceston	LA012076
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

002 Major Unit Replace Axle	Rear axle unservicable - Mercedes Benz of Truro Replaced
Breakdown	Crew think gearbox gone
Travel Time	
MOT	M/B Truro to carry out MOT - Done

Vehicle Deep Clean	26/11/2018	12:08	27/11/2018	14:41	281,844	Launceston	LA012122
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	27/11/2018	10:08	30/11/2018	08:34	281,844	Launceston	LA012124
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	Curtosy light on all the time, can be manually turned off	Monitoring
13 Brakes 1	36% imbalance front wheels - wheels removed / examined - no fault	
15 Steering 1	Play in both inner track arms - replaced	
16 Suspension 1	Play in rear anti-roll bar bushes - servicable	
16 Suspension 2	Leaf springs out of alignment	
17 Tyres Replace	o/s/f tyre worn - replaced	

17 Tyres Tracking	Tracking Req. - Tracked
18 Wheels Check Torques	
24 Driveshaft 1	Centre prop mount split - replaced 4 weeks ago!
27 Transmission Automatic	Vibration at 40mph, recently seen by Merc. still present
34 Emergency Lights	o/s/r upper blues, 2xLED's out - servicable
55 Ramp	Slow close potentiometer not working
71 Body Exterior 1	o/s upper bodywork damage towards the rear
71 Body Exterior 2	Rear spray supressor has slight movment - repaired
71 Body Exterior 3	n/s wheel arch damage
71 Body External Steps	Spray supressor starting to split
85 Body Interior 1	White board insecure - repaired
Safety Inspection	
Sealing of stretcher clamp	Sealing of stretcher clamp
Tail Lift 6 Monthly Inspection	Statutory Inspection

Breakdown	02/01/2019	12:21	03/01/2019	08:15	289,410	Launceston	LA012211
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	back door stay bar broken					Monitoring	
-----------	---------------------------	--	--	--	--	------------	--

Breakdown	02/01/2019	12:23	03/01/2019	08:15	289,410	Launceston	LA012212
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	tear in front near tyre						
-----------	-------------------------	--	--	--	--	--	--

Vehicle Deep Clean	08/01/2019	09:24	10/01/2019	14:42	291,050	Launceston	LA012222
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	08/01/2019	09:29	10/01/2019	14:59	291,050	Launceston	LA012223
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	Curtosy light on all the time, can be manually turned off						
02 Mirrors	N/S/F mirror broken - Replaced						
02 Windscreen Wipers	Front wipers poor - Replaced						
18 Wheels Check Torques							
34 Lights	Electrical Auxs O/S driving light u/s - Replaced						
45 Engine 1	Slight engine oil leak - Cleaned down and monitor					Monitoring	
45 Engine Oil Top Up							
56 Comms Equipment	Other MDT not tracking						
71 Body Exterior 1	Bonnet catch broken - Replaced						
85 Body Interior 1	MGS cupboard door wont open - Repaired						

86 Doors Rear	Body Interior right hand rear door stay bottom bolt broken - Replaced
86 Sliding Door	Side door top magnet bent - Repaired
Breakdown	back door stay bar broken - Replaced
Safety Inspection	
Tail Lift Annual Service	Statutory Inspection and Weight Test

Breakdown	26/01/2019	14:12	07/02/2019	14:56	291,050	Launceston	LA012272
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1 Breakdown	Suspect EGR pipe on rear of engine - M/B to investigate (warranty) total loss of power						
--------------------------	---	--	--	--	--	--	--

Breakdown	09/02/2019	21:05	11/02/2019	09:01	291,064	Launceston	LA012307
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Engine managment light on (Amber) - NOTES						
-----------	---	--	--	--	--	--	--

Breakdown	15/02/2019	22:36	18/02/2019	07:43	291,067	Launceston	LA012325
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Rear heater not working - will pick up on safety						
-----------	--	--	--	--	--	--	--

SAFETY INSPECTION	18/02/2019	07:44	22/02/2019	13:20	291,067	Launceston	LA012326
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1	Heater Exhaust Damaged 4x holes - replaced	
01 Heating 2	Heater not working - Commutator high resistance - diagnosed/replaced	
02 Cab Assembly 1	Satnav mount fractured - servicable	Monitoring
02 Cab Assembly 2	Phone holder broken, has sharp edges - removed	
13 Brakes 1	Front pads at 50%	Monitoring
16 Suspension 1	Rear leaf springs slightly out of alignment	Monitoring
18 Wheels Check Torques		
24 Driveshaft 1	Prop, centre bearing split again (3x ~12 weeks) - replaced	
34 Emergency Lights	o/s/r upper blue light has 1x LED out	Monitoring
45 Engine 1	Slight engine oil leak - Cleaned down and monitor	
45 Engine 2	Bonnet pull seized - Free'd and lubricated	
55 Ramp	Mercury wiring stretched around rams - re-routed, gates req. adjustment	
71 Body Exterior 1	o/s/r lower corner reflector fallen off - replaced	
71 Body Exterior 2	n/s CCTV camera smashed	Monitoring

71 Body Exterior 3	Accident damage to o/s upper saloon - Fleet informed						
71 Body External Steps	Side step not fully deploying - Free'd and lubricated						
85 Body Interior 1	o/s Saloon mic missing						Monitoring
86 Sliding Door	Upper door stay mount bent out of shape - re-shaped						
87 Oxygen System	O2 pressure alarm only verbally warns, siren u/s						Monitoring
89 Seatbelts	Front side facing seatbelt fastener insecure - re-secured						
89 Seats	Rear facing seat rake missing						Monitoring
Safety Inspection	Actual Mileage: 296,751						
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab						
Handbrake Cable Replacement	Replace rear handbrake cables						
UB Fire Suppression Service							
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
Vehicle Deep Clean	19/02/2019	08:01	21/02/2019	13:01	291,067	Launceston	LA012330
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	01/03/2019	08:52	01/03/2019	15:48	291,067	Launceston	LA012353
41 Air Intake	Tighten pipe to air fliter, replaced air mass sensor from WX17HKE new ordered.						
Breakdown	Limp Mode, vehicle brought to Redruth workshop by Bodmin crew..						
Road Test	Put Star on vehicle and road test etc.						
BREAKDOWN	12/03/2019	14:00	14/03/2019	09:51	297,000	Redruth	RE025733
34 Lights	New indicator repeater ordered. Replaced repeater & bulb						
41 Air Intake	Replaced another MAFF sensor (taken from WX17CYL) crew needed the vehicle						
41 Turbo	Pipe "O" ring split, plastic box cracked and hose oily. See notes						
99 Diagnostic Test	Checked for faults - MAFF sensor again?						
Road Test	Extended road tests. NEW MAF SENSOR FITTED TO WX17CYL						
Breakdown	31/03/2019	16:57	03/04/2019	07:26	297,000	Launceston	LA012433
Breakdown	NOT STARTING, ALT WNG LIGHT ON						

SAFETY INSPECTION	01/04/2019	12:19	04/04/2019	15:39	297,000	Launceston	LA012436
02 Cab Assembly 1	Satnav mount fractured - servicable					Monitoring	
02 Cab Assembly 2	Centre console lock assembly fallen off, glove box light on all the time						
13 Brakes 1	Front pads worn						
13 Brakes 2	Brake pedal rubber worn						
13 Handbrake	Handbrake req. adjustment						
16 Suspension 1	Rear leaf springs slightly out of alignment					Monitoring	
16 Suspension 2	Rear shock boots starting to corrode					Monitoring	
16 Suspension 3	Rear drop links and spring eye bushes worn						
17 Tyres Replace	All four rear tyres at trust limit						
18 Wheels Check Torques							
24 Driveshaft 1	Propshaft centre bearing worn - Replaced propshaft (remove and refit X2)						
34 Emergency Lights	o/s/r upper blue light has 2x LED's out					Monitoring	
34 Lighting System	Front fog light damaged, mount broken - replaced						
34 Lights	n/s/f upper marker light 50%						
45 Engine 1	Engine MIL illuminated, ??PSM Module fault						
45 Engine 2	n/s engine oil leak ? power steering pump - NOTES						
45 Engine 3	Rear oil leak, ?crank oil seal / oil cooler					Monitoring	
55 Tail Lift	Tilt ram hose leaking oil, reservoir leaking oil						
71 Body Exterior 1	n/s front bumper hanging off						
71 Body Exterior 2	n/s CCTV camera smashed					Monitoring	
71 Body Exterior 3	Both front body corners damaged, bonnet release tight, rear reflector insecure						
71 Body External Steps	spray supressor starting to split					Monitoring	
85 Body Interior 1	o/s Saloon mic missing					Monitoring	
86 Sliding Door	Window sill fallen out, upper stay bent						
87 Oxygen System	O2 pressure alarm only verbally warns, siren u/s					Monitoring	
89 Seats	Rear facing seat rake missing						
Safety Inspection							
92 - C Service							
Service C							
Vehicle Deep Clean	02/04/2019	08:05	05/04/2019	08:30	297,500	Launceston	LA012439
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	15/04/2019	09:36	15/04/2019	09:41	302,869	Launceston	LA012468
02 Cab Assembly 1	Satnav mount fractured - servicable					Monitoring	
16 Suspension 1	Rear leaf springs slightly out of alignment					Monitoring	
16 Suspension 2	Rear shock boots starting to corrode					Monitoring	

34 Emergency Lights	o/s/r upper blue light has 2x LED's out	Monitoring
45 Engine 3	Rear oil leak, ?crank oil seal / oil cooler	Monitoring
52 Electrical Aux	Vehicle wouldnt start, lost power to genesis panel - NOTES	
71 Body Exterior 2	n/s CCTV camera smashed	Monitoring
71 Body External Steps	spray supressor starting to split	Monitoring
85 Body Interior 1	o/s Saloon mic missing	Monitoring
87 Oxygen System	O2 pressure alarm only verbally warns	

BREAKDOWN	19/04/2019	07:18	19/04/2019	09:47	305,000	Launceston	LA012482
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

31 Charging System Battery	Chassis battery 10.4vdc, 100% charge, 72% health - battery replaced
45 Engine 1	NOX Sensor signal un-detectable - (see notes)
99 Diagnostic Test	Constantly power failing, now wont start - Faulty chassis battery

BREAKDOWN	07/05/2019	07:27	07/05/2019	11:05	313,993	Launceston	LA012505
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Emergency Lights	O/S/R corner blue light smashed off - Replaced
45 Engine 1	EML Illuminated - NOX sensor sporadic fault - Cleared down and road tested - OK

SAFETY INSPECTION	13/05/2019	10:19	24/05/2019	14:52	314,696	Launceston	LA012514
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	Satnav mount fractured - servicable
02 Cab Assembly 2	Glove box light permanently illuminated
16 Suspension 1	Rear leaf springs slightly out of alignment
16 Suspension 2	Rear shock boots starting to corrode
18 Wheels Check Torques	
34 Emergency Lights	o/s/r upper blue light has 2x LED's out
34 Lights	o/s/f fog light damaged - Replaced
43 Exhaust System 1	DPF Mounting Bolt Loose - Tightened
45 Engine 1	Engine Engine warning light on - NOX sensor fault NOTES
45 Engine 2	SCR AdBlue Fault - Metering Fault (see notes)
45 Engine 3	Rear oil leak, ?crank oil seal / oil cooler
54 Sirens	Emg Warning Devices Siren not working - replaced
55 Tail Lift	Oil evident around t/l pump / reservoir
71 Body Exterior 1	o/s/f upper corner damaged
71 Body Exterior 2	n/s CCTV camera smashed
71 Body Exterior 3	n/s/f lower body corner damaged
71 Body External Steps	spray supressor starting to split
85 Body Interior 1	o/s Saloon mic missing

86 Doors Rear	Large rear door dropped, top lock not always catching
86 Sliding Door	Window seal hanging out - repaired
89 Seats	Rear facing seat rake missing - replaced
Safety Inspection	
Axle Oil Change	Axle Oil Change
Pollen Filter Change	Pollen Filter Change
Fuel Filter Change	Change Fuel Filter
Air Filter Change	Air Filter Change
Tail Lift Inspection	And Repairs

Vehicle Deep Clean	14/05/2019	09:00	16/05/2019	10:42	314,696	Launceston	LA012518
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	04/07/2019	11:37	09/07/2019	13:28	317,713	Dorchester	DC020464
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	adjuster u/s
18 Wheels Check Torques	
45 Engine Ad Blue	top up
45 Engine Oil Top Up	top up
85 Body Interior 1	fire ext out of date
85 Body Interior 2	saloon mic missing
86 Door Lock	Lock set required
86 Sliding Door	requires adjustment
Safety Inspection	

Vehicle Deep Clean	08/07/2019	10:30	09/07/2019	11:46	317,721	Dorchester	DC020478
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	05/08/2019	08:00	05/08/2019	08:01	318,200	Dorchester	DC020613
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	VEHICLE ONLY BEEN USED FOR A WEEK SINCE LAST INSPECTION/CLEAN
Vehicle Deep Clean	Vehicle Deep Clean

Breakdown	13/08/2019	10:57	13/08/2019	14:06	318,200	Dorchester	DC020656
Breakdown	SPLIT TYRE -passenger side front						
Breakdown	16/08/2019	23:02	16/08/2019	23:17	320,146	Dorchester	DC020678
Breakdown	demister not working						
Breakdown	16/08/2019	23:04	19/08/2019	12:11	320,155	Dorchester	DC020679
01 Heating 1	Blower inop,trace to siezed motor						
55 Tail Lift	guide rail loose						
86 Doors	rear door bar bent						
Breakdown	DEMISTER not working						
Travel Time							
Unplanned Repair	02/09/2019	14:00	02/09/2019	14:28	322,231	Dorchester	DC020775
45 Engine Oil Top Up							
BREAKDOWN	08/09/2019	08:30	09/09/2019	06:30	322,947	Dorchester	DC020813
86 Sliding Door	Doors Side door handle broken						
Travel Time	To wareham and return						
SAFETY INSPECTION	09/09/2019	06:30	10/09/2019	07:02	323,107	Dorchester	DC020815
02 Windows/Glass	rubber seal adrift/ screen wash cap u/s						
13 Brake Pads	All low						
13 Discs	Front worn						
17 Tyres	2x Tyres low						
18 Wheels	O/S/R wheel rim cracked						
18 Wheels Check Torques							
45 Engine Ad Blue	top up						
56 Comms Equipment	MDT Failure/Issue No power to the MDT						
71 Body Exterior 1	bonnet catch required adjustment						
85 Body Interior 1	Gas cupboard latch u/s						
86 Sliding Door	Bearings rough						

87 Stretcher Safety Inspection UB Fire Supp 6mts Service Tail Lift Inspection	Battery missing UB Fire Supp 6mts Service						
Vehicle Deep Clean	10/09/2019	11:00	11/09/2019	08:45	323,120	Dorchester	DC020825
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	24/09/2019	13:30	25/09/2019	14:59	323,883	Dorchester	DC020896
56 Comms Fitment 56 Comms Power Failure	MDT froze out, Aerial missing Comms Power Check Comms power check required please						
Breakdown	12/10/2019	08:29	12/10/2019	11:00	327,268	Dorchester	DC021013
Breakdown Travel Time	key not turning engine over						
Defect Repair	15/10/2019	13:47	15/10/2019	13:58	327,918	MDT Ferndown	TF000159
87 Oxygen System	Repair to O2 system in Oxygen cupboard. Replaced O2 probes.						
SAFETY INSPECTION	21/10/2019	11:30	22/10/2019	14:03	329,138	Dorchester	DC021067
02 Windows/Glass 02 Windscreen 02 Windscreen Wipers 03 Instruments & Sensors 1 13 Handbrake 16 Suspension 1 17 Tyres 18 Wheels Check Torques 44 Fuel System 1 45 Engine Ad Blue	Windscreen 10p size chip - National windscreens called Screen cracked.National windscreens to replace bottle top missing Service light on adjust Front struts and arms have play all rear low no fuel angel fitted top up						

45 Engine Oil Top Up top up
 55 Tail Lift Handrails bent, lights and slow close not working correctly
 85 Body Interior 1 gas cupboard broken again
 Safety Inspection
 MOT
 Brakes Replace Brake Fluid

Vehicle Deep Clean 22/10/2019 10:40 24/10/2019 08:38 329,154 Dorchester DC021075

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 02/11/2019 16:15 04/11/2019 06:47 330,847 Dorchester DC021135

Breakdown
 Travel Time passanger's window malfunction

Unplanned Repair 05/11/2019 12:30 06/11/2019 06:53 331,262 Dorchester DC021151

45 Engine Ad Blue
 71 Body Exterior 1 Crew unable to open bonnet

Breakdown 10/11/2019 19:25 11/11/2019 09:45 332,283 Dorchester DC021182

71 Body External Steps Secure damaged step.
 Breakdown side step damaged
 Travel Time

SAFETY INSPECTION 02/12/2019 08:30 03/12/2019 10:32 335,934 Dorchester DC021316

02 Cab Ass Fire Extinguisher replace fire extinguisher
 16 Suspension 1 replace rear spring slipper pads
 17 Tyres Replace replace NSF tyre
 18 Wheels Check Torques torque up
 44 Add Ad Blue top up
 71 Body Exterior 1 OSR lower corner cap damaged

85 Body Interior 1 refit front saloon seat adjuster bar
 86 Doors Rear OS rear door upper bolt not engaging lock
 Check Winter Pack check pack
 Safety Inspection
 Engine Change Oil & Filter
 Auto G/box Oil & Filter Change Auto G/box Oil & Filter Change
 Tail Lift Inspection inspection

Vehicle Deep Clean 04/12/2019 09:09 04/12/2019 14:07 335,947 Dorchester DC021337

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 13/01/2020 06:30 15/01/2020 13:35 341,686 Dorchester DC021582

01 Heating 1 Body Interior Cab temp cntrl hot or cold no medium
 13 Brakes 1 Telamr heat shield rubbing
 17 Tyres o/s/r outter flat
 18 Wheels Check Torques
 43 Exhaust System 1 rubbers missing tailpipe corroded
 45 Engine Ad Blue top up
 45 Engine Oil Top Up top up
 52 Electrical Aux Electrical Auxs Sure line NOT being auto ejected wen engine start
 55 Tail Lift Ramp/Lift/Tail Hoist Alarms 'deployed' when accelerating
 71 Body Exterior 1 tailift guides loose
 86 Doors Doors Side saloon door getting diff to open
 87 - Stretchers/Chairs/Boards Body Interior Trolley clamp, diff to release stretcher
 Safety Inspection
 Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Vehicle Deep Clean 14/01/2020 10:14 14/01/2020 12:19 341,685 Dorchester DC021593

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair 17/01/2020 11:30 17/01/2020 12:35 341,793 Dorchester DC021615

85 Body Interior 1 Crew reported unable to close large draw at bulkhead.See notes Awaiting Parts

ACCIDENT 03/02/2020 07:30 12/02/2020 09:20 344,220 Dorchester DC021721

71 Body Exterior Acc Repair Front end damage from deer strike

02 Pipeline Annual Inspection **12/02/2020** **11:30** **12/02/2020** **12:00** **341,793** **MDT Weymouth** **DW000165**

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - no faults

SAFETY INSPECTION **24/02/2020** **09:38** **25/02/2020** **10:33** **346,005** **Dorchester** **DC021863**

13 Brakes 1 rears low
 17 Tyres n/s/f tyre low
 18 Wheels Check Torques
 45 Engine Ad Blue top up
 45 Engine Oil Top Up top up
 55 Tail Lift guides damaged, alaram sounding
 85 Body Interior 1 Crew reported unable to close large draw at bulkhead. See notes
 Safety Inspection
 Annual Air Con Service Annual Air Condition Service
 Annual Heater Service Annual Heater Service
 Replace Handbrake Cables Replace Handbrake Cables
 Tail Lift Inspection
 UB Fire Supp 12mts Service Service of fire suppression system

Vehicle Deep Clean **25/02/2020** **10:12** **25/02/2020** **14:52** **346,017** **Dorchester** **DC021870**

Vehicle Deep Clean Vehicle Deep Clean

Defect Repair **01/03/2020** **09:00** **01/03/2020** **10:51** **347,026** **Dorchester** **DC021903**

45 Engine 1 other Amber EML
 Travel Time wareham return

Breakdown **01/03/2020** **14:05** **01/03/2020** **14:06** **347,020** **Dorchester** **DC021904**

Breakdown amber EML/noise from engine

Unplanned Repair	08/03/2020	07:22	09/03/2020	07:28	348,115	Dorchester	DC021953
34 Lights Bulb Replacement Travel Time	O/S repeater n/w. Replaced bulb. To and from Wareham Stn.						
Unplanned Repair	09/03/2020	14:30	09/03/2020	15:15	348,115	Dorchester	DC021963
13 Brakes 1 34 Lights	ABS faultCheck fault,replace n/s/f ABS sensor Lighting System right side indicator stalk not working						
Breakdown	04/04/2020	21:44	07/04/2020	12:00	352,000	Dorchester	DC022102
01 Heating 1 13 Brakes 1 13 Brakes 2 17 Tyres 18 Wheels 31 Battery Chassis 32 Starting System 1 45 Engine 1 45 Engine Ad Blue 45 Engine Oil Top Up 54 Reversing Systems Breakdown Travel Time 18 Wheels Check Torques Safety Inspection UB Fire Supp 6mts Service Tail Lift Inspection	Replace stepper motor long pedal TELMAR u/s Rears low x1 puncture Crack rim bat u/s Starter motor u/s damaged A/C adjuster u/s top up top up rev alarm u/s ABS amber warning light UB Fire Supp 6mts Service						
Unplanned Repair	01/04/2020	08:55	01/04/2020	09:37	351,102	St Leonards	SL029474
17 Tyres Replace	n/s/r outer puncture?						
Vehicle Deep Clean	07/04/2020	10:00	08/04/2020	08:00	352,000	Dorchester	DC022118
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	18/05/2020	09:12	18/05/2020	15:30	355,738	Dorchester	DC022393
02 Cab Assembly 1	sat nav bracket broken						
02 Windscreen Wipers	washers blocked						
13 Brake Pads	Front low						
16 Suspension 1	ARB links worn						
17 Tyres	front tyres low						
18 Wheels Check Torques							
34 Lights	fog light n/w						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
56 Comms Equipment	EPCR not on vehicle for inspection						
71 Body Exterior 1	wheel arch liner loose rubbing						
85 Body Interior 1	fire ext out of date						
85 Body Interior 2	Other Internal CCTV turning itself on						
86 Sliding Door	catch covers broken						
Safety Inspection							
Vehicle Deep Clean	19/05/2020	09:31	19/05/2020	14:00	355,747	Dorchester	DC022401
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	09/06/2020	22:28	12/06/2020	08:11	358,591	Dorchester	DC022571
Breakdown	VMT Aerial missing						
Breakdown	19/06/2020	16:22	20/06/2020	09:16	359,617	Dorchester	DC022639
18 Wheels	n/s/f rim cracked.Wheel and tyre replaced.carry out retorque						
Breakdown	N/S/F Puncture						
SAFETY INSPECTION	28/06/2020	07:30	28/06/2020	14:58	360,675	Dorchester	DC022684
02 Windscreen Wipers	blades split						
03 Instruments & Sensors 1	service light on						
18 Wheels Check Torques							

34 Lights	top marker light n/w o/s
42 Coolant System	weak mixture of coolant
45 Engine Ad Blue	top up
55 Tail Lift	Slow close not working
56 Comms Equipment	Aerial missing
85 Body Interior 1	Saloon fire ext o/o/d
86 Sliding Door	top magnet not holding
Safety Inspection	
Engine Change Oil & Filter	

Vehicle Deep Clean	29/06/2020	09:00	30/06/2020	13:30	360,688	Dorchester	DC022697
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Emergency Deep Clean	06/07/2020	08:00	06/07/2020	14:36	361,499	Dorchester	DC022748
-----------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Emergency Deep Clean

SAFETY INSPECTION	12/08/2020	09:13	14/08/2020	13:59	366,570	Dorchester	DC023021
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
44 Add Ad Blue	top up
44 Fuel System 1	Leak off pipe leaking.Replace
45 Engine Oil Top Up	top up
56 Comms Equipment	saloon microphone loose
85 Body Interior 1	passenger torch missing
86 Sliding Door	door magnet bracket bent
87 Stretcher	Med Equip & Devices stretcher/battery issue
89 Seats	saloon seat armrests loose
Safety Inspection	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
Pollen Filter Change	Pollen Filter Change
Tail Lift Inspection	inspection

Vehicle Deep Clean	14/08/2020	13:59	17/08/2020	12:02	366,580	Dorchester	DC023049
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	20/08/2020	13:01	20/08/2020	14:26	366,971	Dorchester	DC023093
Breakdown	Sidestep keeps going in/out						
Breakdown	20/08/2020	13:01	20/08/2020	14:27	366,971	Dorchester	DC023094
Breakdown	Sidestep keeps going in/out						
Unplanned Repair	21/08/2020	08:30	21/08/2020	09:36	367,104	Dorchester	DC023101
02 Mirrors 56 Comms Equipment travel time	replace NS mirror swap hard drive travel to and from dorchester						
ACCIDENT	02/09/2020	11:00	02/09/2020	12:43	368,432	Dorchester	DC023182
71 Body Exterior Acc Repair Travel Time	Check vehicle carry out temp repair to keep vehicle in service					Awaiting Body Repair	
SAFETY INSPECTION	18/09/2020	15:00	24/09/2020	12:39	371,037	Dorchester	DC023307
01 Air Conditioning 1 02 Windscreen Wipers 11 Axle Rear 13 Brakes 1 13 Brakes 2 16 Suspension 1 16 Suspension 2 17 Tyres 18 Wheels 18 Wheels Check Torques 34 Emergency Lights 43 Exhaust System 1 45 Engine 1 45 Engine Ad Blue 45 Engine Oil Top Up	Not working washers n/w, blades smeary N/S/R hub seal leaking Front calipers siezed Rears worn Stuts and arms worn Rear shock absorbers u/s All low, swap to cross climates rim damage 2x N/S/R top blue lens damaged exhaust has come of mounts, has been hit EML on top up top up						

56 Comms Equipment	EPCR cradle broken , but charging ok. PCE to repair
71 Body Exterior Acc Repair	Check vehicle carry out temp repair to keep vehicle in service
85 Body Interior 1	Foot plate in cab u/s
85 Body Interior 2	replace storage drawer runners
86 Sliding Door	top magnet bent
Safety Inspection	
Travel Time	
MOT	

Vehicle Deep Clean	22/09/2020	11:30	22/09/2020	14:30	371,032	Dorchester	DC023329
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	07/10/2020	11:35	07/10/2020	11:51	373,263	Dorchester	DC023440
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Ad Blue

Breakdown	13/10/2020	14:49	14/10/2020	12:43	373,263	Dorchester	DC023479
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

54 Warn Dev/System Breakdown	fire supression warning light coming on crack in windscreen
------------------------------	---

Unplanned Repair	20/10/2020	13:45	20/10/2020	14:26	375,041	Dorchester	DC023525
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	replace DLR bulb
45 Engine Oil Top Up	top up

Breakdown	21/10/2020	23:52	22/10/2020	12:52	375,258	Dorchester	DC023535
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps Breakdown	side step broken
----------------------------------	------------------

Breakdown	23/10/2020	16:44	24/10/2020	07:25	375,305	Dorchester	DC023551
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Non start
-----------	-----------

SAFETY INSPECTION	02/11/2020	09:00	04/11/2020	08:10	376,713	Dorchester	DC023601
01 Air Conditioning 1	A/C not working, Condensor damaged						
03 Instruments & Sensors 1	EML on, Service light on						
13 Handbrake	Adjustment required						
18 Wheels Check Torques							
34 Lights	O/S/R marker light out						
45 Engine Ad Blue	Top up						
55 Tail Lift	Rail bent						
56 Comms Equipment	EPCR cradle Damaged						
71 Body Exterior Acc Repair	Front end still damaged from RTC.. Body shop required						
85 Body Interior 1	Linen cupboard damaged						
86 Doors	Top Magnet bent						
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	04/11/2020	08:40	04/11/2020	13:50	376,727	Dorchester	DC023624
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	06/11/2020	03:25	06/11/2020	14:24	376,854	Dorchester	DC023646
Breakdown	O/S headlight Blown						
Breakdown	07/12/2020	20:11	13/12/2020	07:00	381,606	Dorchester	DC023854
02 Windscreen	small chip in centre						
02 Windscreen Wipers	blades split washers blocked						
03 Instruments & Sensors 1	EML on, service light on						
13 Brakes 1	Reported spongey						
13 Brakes 2	Replace pads all round, TELMAR not working						
17 Tyres	fronts worn						
34 Lights	o/s side light inop, n/s/r marker light n/w						
45 Engine Ad Blue	top up						
54 Reversing Systems	Reverse bleeper inop.						
55 Tail Lift	bolt missing from catch						
71 Body External Steps	side step comes out						
85 Body Interior 1	microphone damaged						

85 Body Interior 2	Gas cupboard catch u/s
86 Door Lock	Central locking faulty
Breakdown	Battery not charging on vehicle
Road Test	
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
18 Wheels Check Torques	
Safety Inspection	

Vehicle Deep Clean	14/12/2020	09:00	14/12/2020	13:15	381,631	Dorchester	DC023900
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	28/12/2020	07:00	28/12/2020	09:30	384,410	St Leonards	SL031970
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Side step u/s. Remove mud lube up runners.
86 Door Lock	Mags not holding door. Bent mag brackets
86 Sliding Door	Unable to open seized up rollers.

Breakdown	16/01/2021	13:06	18/01/2021	13:00	387,000	Dorchester	DC024137
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers	no washer fluid	
34 Lights	Body Exterior N/S reflector cracked Accident	
45 Engine 1	EML on Nox sensors required	Monitoring
45 Engine Ad Blue	top up	
45 Engine Oil Top Up	top up	
55 Tail Lift	Warning going off,gaurd rails bent,electrical fault	
71 Body Exterior 1	tailift guides damaged	
Breakdown	Ramp deployed alarm sounding when not	

SAFETY INSPECTION	26/01/2021	10:14	27/01/2021	08:40	387,894	Dorchester	DC024218
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher	cab extinguisher OOD	
02 Windscreen	small chip in centre	
15 Steering 1	Slight play in n/s inner rack end	Monitoring

17 Tyres	Rears low
18 Wheels Check Torques	
34 Lights Bulb Replacement	interior bulb blown
44 Add Ad Blue	top up
45 Engine 1	EML on Nox sensors required...DONE
45 Engine 2	Boost hose damaged,
55 Tail Lift	Leak on Hose o/s
71 Body Exterior Acc Repair	Front end still damaged from RTC.. Body shop required
85 Body Interior 1	saloon microphones loose
86 Doors Rear	barrel lock seized (replace all cylinders)
86 Sliding Door	top magnet bracket bent
Safety Inspection	
Engine Change Oil & Filter	

Vehicle Deep Clean	27/01/2021	09:50	27/01/2021	14:10	387,905	Dorchester	DC024226
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Tail Lift 12M Service & Weight	28/01/2021	09:00	28/01/2021	11:25	387,930	Dorchester	DC024236
---	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

55 Tail Lift	Hose leaking,hand rail rail loose,hand pump siezed...Not done on service
71 Body Exterior 1	Slow close/tilt switch inop..not done on service either....no parts.
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Tail Lift Inspection	

Breakdown	05/02/2021	01:55	05/02/2021	14:31	389,021	Dorchester	DC024291
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	FRONT LEFT TYRE SMOKING
-----------	-------------------------

Unplanned Repair	04/03/2021	12:15	04/03/2021	12:49	391,581	Dorchester	DC024502
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	Doors N/S WING MIRROR DAMAGED
------------	-------------------------------

SAFETY INSPECTION	08/03/2021	09:00	09/03/2021	14:00	392,992	Dorchester	DC024516
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

15 Steering 1	Slight play in n/s inner rack end
17 Tyres	Front low

17 Tyres Tracking	Tracking Required	Monitoring
18 Wheels Check Torques		
45 Engine Ad Blue		
45 Engine Oil Top Up		
55 Tail Lift	tilt switch inop	
86 Sliding Door	Realign top door magnet	
Safety Inspection		
Wheel Hub Flanges Replaceme		
Replace Handbrake Cables	Replace Handbrake Cables	
Annual Heater Service	Annual Heater Service	
Annual Air Con Service	Annual Air Condition Service	
UB Fire Supp 12mts Service	Service of fire supression system	

Vehicle Deep Clean	09/03/2021	12:31	10/03/2021	09:50	393,003	Dorchester	DC024530
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Medical Devices Repair	14/04/2021	09:30	14/04/2021	11:00	397,020	MDT Weymouth	DW000522
-------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

Decontaminated	Cleaned with clinell wipes
Defect Sheet Present No	
Defect Sheet Present Yes	
Medical Devices Repair	see notes

SAFETY INSPECTION	19/04/2021	08:00	20/04/2021	14:44	397,609	Dorchester	DC024792
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windows/Glass	Driver window switch u/s
02 Windscreen Wipers	washers blocked
17 Tyres	N/S/F tyre low on edge, tracking to be done
17 Tyres Tracking	Tracking Required
18 Wheels Check Torques	
34 Lighting System	N/S/R fog inop
34 Lights	o/s DRL out
45 Engine Ad Blue	top up
45 Engine Oil Top Up	top up
71 Body Exterior Acc Repair	Front end still damaged from RTC, body shop required
86 Sliding Door	top plunger damaged
Safety Inspection	
Travel Time	

Tail Lift Inspection

Vehicle Deep Clean	20/04/2021	08:17	20/04/2021	12:59	397,617	Dorchester	DC024804
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	28/05/2021	14:00	28/05/2021	14:21	403,484	Dorchester	DC025128
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Oil Top Up

Breakdown	29/05/2021	16:27	31/05/2021	13:46	403,680	Dorchester	DC025129
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	Torch missing	
02 Windscreen	Small chip in middle	
02 Windscreen Wipers	Blades u/s	
13 Handbrake	Adjust	
16 Suspension 1	ARB links worn	
34 Lights	marker light damaged o/s	
52 Electrical Aux	CCTV inop	
55 Tail Lift	rails siezed	
71 Body Exterior 1	Body Exterior HIT POST BACK BUMPER REFLECTOR OFF	Monitoring
71 Body Exterior Acc Repair	Front end still damaged from RTC, Autospray to repair	Monitoring
85 Body Interior 1	saloon fire ext out of date	
86 Doors Rear	Play in large door top hinge	Monitoring
Breakdown	Comms Battery Not Holding Charge	
Travel Time		
18 Wheels Check Torques		
Safety Inspection		
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service	

Vehicle Deep Clean	01/06/2021	09:00	01/06/2021	14:25	403,744	Dorchester	DC025146
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body Exterior 1	Body Exterior HIT POST BACK BUMPER REFLECTOR OFF	Monitoring
71 Body Exterior Acc Repair	Front end still damaged from RTC, Autospray to repair	Monitoring
86 Doors Rear	Play in large door top hinge	Monitoring
Vehicle Deep Clean	Vehicle Deep Clean	

Breakdown	05/06/2021	21:45	07/06/2021	14:56	403,803	Dorchester	DC025175
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown 5801- clicking noise from steering

Unplanned Repair 02/07/2021 12:10 02/07/2021 12:45 407,956 Dorchester DC025381

31 Battery Aux Tail lift battery reported failing

Breakdown 11/07/2021 14:28 11/07/2021 16:19 409,035 Dorchester DC025419

Breakdown NSR outer burst 205/75 R16C 110/108R C/Climate

SAFETY INSPECTION 12/07/2021 09:49 14/07/2021 14:04 409,035 Dorchester DC025423

02 Windscreen Wipers	Blades poor	
03 Instruments & Sensors 1	Service Light on	
13 Brakes 1	Rears worn	
13 Handbrake	Shoes worn out	
15 Steering 1	Power steering pump weeping from front seal	Monitoring
18 Wheels	No Valve ext fitted on n/s wheels	
18 Wheels Check Torques		
34 Emergency Lights	N/S Wing Blue Inop	
34 Lights	N/S headlight n/w	
42 Radiator	Radiator leaking	
43 Exhaust System 1	Tail pipe damaged, exhaust has been hit and moved	
45 Engine Ad Blue	Top Up	
54 Reversing Systems	Camera inop	
71 Body Exterior 1	Body Exterior HIT POST BACK BUMPER REFLECTOR OFF	Monitoring
71 Body Exterior 2	Rear flap loose	
71 Body Exterior Acc Repair	Front end still damaged from RTC, Autospray to repair..from 02.09.2020	Monitoring
85 Body Interior 1	Sky Light has been left open, saloon and stretcher wet	
85 Body Interior 2	Saloon fire ext out of date	
86 Doors Rear	Play in large door top hinge	Monitoring
86 Sliding Door	Bearing rough/magnet bent	
89 Seats	Driver seat swab u/s	
Safety Inspection		
Tail Lift Inspection		

Vehicle Deep Clean 14/07/2021 14:08 15/07/2021 12:15 409,170 Dorchester DC025450

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair	06/08/2021	08:30	06/08/2021	09:06	413,101	Dorchester	DC025626
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Sliding Door	Does Not Stay Open						
-----------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	23/08/2021	07:51	25/08/2021	08:30	414,179	Dorchester	DC025756
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	Electrical Auxs Saloon AC blows warm air regardless of settings						
02 Windscreen Wipers	washer blocked						
13 Brakes 1	Telma noisy,fit recon unit						
15 Steering 1	Power steering pump weeping from front seal					Awaiting Parts	
17 Tyres	3x low						
18 Wheels Check Torques							
24 Driveshaft 1	Front prop rear u/j siezed.Replace shaft						
33 Ignition System	Key Damaged						
45 Engine 1	Injectors blowing						
45 Engine 2							
45 Engine Ad Blue	Top up						
54 Reversing Systems	reverse bleeper, ticking/noisey						
71 Body Exterior 1	Body Exterior HIT POST BACK BUMPER REFLECTOR OFF						
71 Body Exterior 2	front number plate damaged/ red paint the same as the bins in Wareham yard						
71 Body Exterior Acc Repair	Front end still damaged from RTC, Autospray to repair..from 02.09.2020					Monitoring	
85 Body Interior 1	microphone loose						
85 Body Interior 2	linen cupboard catches loose						
86 Doors Rear	Play in large door top hinge						
86 Sliding Door	magnet bent again						
Safety Inspection							
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
Engine Change Oil & Filter							
Pollen Filter Change	Pollen Filter Change						
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						

Vehicle Deep Clean	25/08/2021	11:30	26/08/2021	11:22	414,198	Dorchester	DC025780
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	07/09/2021	12:45	07/09/2021	13:00	416,086	Dorchester	DC025855
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Sliding Door	Door open warning going off,check fault.Top catch bracket bent.Straighten						
-----------------	---	--	--	--	--	--	--

SAFETY INSPECTION	05/10/2021	08:00	07/10/2021	14:36	419,685	Dorchester	DC026070
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher	extinguisher OOD
13 Brake Pads	front pads low
15 Steering 1	Power steering pump weeping from front seal
15 Steering 2	top up reservoir
16 Suspension 1	2 slipper pads split
17 Tyres Replace	OSR inner has nail in sidewall
18 Wheels Check Torques	
34 Emergency Lights	OSF wing blue light not flashing
34 Lights Bulb Replacement	OS headlight out
44 Add Ad Blue	top up
45 Engine 1	NS engine mount split
45 Engine Oil Top Up	top up
55 Tail Lift	guide rails seized and OS light dull
71 Body Exterior 1	NSR corner cap and reflector damaged
71 Body Exterior Acc Repair	Front end still damaged from RTC, Autospray to repair..from 02.09.2020
85 Body Interior 1	stratcher guide buffer damaged
Safety Inspection	
Tail Lift Inspection	
MOT	

Vehicle Deep Clean	06/10/2021	14:15	07/10/2021	11:17	419,700	Dorchester	DC026090
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

BREAKDOWN	25/10/2021	07:31	25/10/2021	11:22	421,215	Dorchester	DC026203
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

55 Tail Lift	Tail lift deployed going off						
86 Sliding Door	Reported faulty,magnet not holding. Straighten bracket						

Breakdown	04/11/2021	02:16	04/11/2021	05:30	422,496	Dorchester	DC026279
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Off front tyre flat						
SAFETY INSPECTION	15/11/2021	08:22	15/11/2021	13:59	423,785	Dorchester	DC026352
18 Wheels Check Torques							
43 Exhaust System 1	reposition exhaust and replace missing rear mounts						
44 Add Ad Blue	top up						
71 Body Exterior 1	rear mudflap loose						
85 Body Interior 1	bag cupboard strap damaged NO PARTS						
Safety Inspection							
Brake Fluid Change	Brake Fluid Change						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Vehicle Deep Clean	15/11/2021	14:32	16/11/2021	14:52	423,800	Dorchester	DC026367
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	29/12/2021	09:47	30/12/2021	07:38	429,443	Dorchester	DC026705
17 Tyres Replace	Front tyres worn						
18 Wheels Check Torques							
45 Engine Oil Top Up							
85 Body Interior 1	Saloon microphone missing						Awaiting Parts
86 Doors Rear	Locking system inop						
Safety Inspection							
Tail Lift Inspection	Handrail siezed						
Vehicle Deep Clean	30/12/2021	10:00	30/12/2021	15:45	429,457	Dorchester	DC026717
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	31/12/2021	16:32	03/01/2022	08:40	429,602	Dorchester	DC026730
86 Doors Rear	both catches not locking in the closed position						
Breakdown	Rear door will not stay closed						

Breakdown	13/01/2022	18:27	14/01/2022	07:55	429,741	Dorchester	DC026827
55 Tail Lift	Ramp/Lift/Tail Hoist constant tail lift deployed warning						
86 Sliding Door	Body Exterior Side door not holding on magnet,dangerous on hills						
Breakdown	BACK DOOR INSECURE						
Travel Time							
Unplanned Repair	24/01/2022	14:30	24/01/2022	14:45	429,851	Dorchester	DC026931
02 Cab Ass Fire Extinguisher	Replaced.Used at RTC						
Breakdown	02/02/2022	18:03	03/02/2022	08:20	432,862	Dorchester	DC027008
Breakdown	both headlights out; VOR						
Unplanned Repair	03/02/2022	10:50	03/02/2022	11:09	432,907	Dorchester	DC027014
34 Lights	Both headlamps inop.Replace both bulbs						
COMMS.FAILURE CHECK	04/02/2022	08:50	04/02/2022	09:05	433,000	Dorchester	DC027018
MDT Failure/Issue	Carry out reboot						
SAFETY INSPECTION	07/02/2022	07:31	08/02/2022	13:43	433,305	Dorchester	DC027024
13 Brake Pads	rears low						
13 Handbrake	adjust						
15 Steering 1	steering reservoir hose leaking						
17 Tyres Replace	NSR out has screw in it						
18 Wheels Check Torques							
44 Add Ad Blue	top up						
45 Engine Oil Top Up	top up						
71 Body Exterior 1	front grille and bonnet damaged						
85 Body Interior 1	Saloon microphone missing and 1 loose						
85 Body Interior 2	cab centre consol loose						
85 Body Interior 3	bag cupboard strap broken						
86 Door Lock	rear door barrel seized						

Safety Inspection
 Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Vehicle Deep Clean **09/02/2022** **08:58** **09/02/2022** **14:09** **433,319** **Dorchester** **DC027045**

Vehicle Deep Clean Vehicle Deep Clean

ACCIDENT **17/02/2022** **09:47** **24/02/2022** **09:22** **434,168** **Dorchester** **DC027092**

71 Body Exterior Acc Repair bonnet and grille damaged

Unplanned Repair **08/03/2022** **10:45** **08/03/2022** **11:14** **436,046** **Dorchester** **DC027208**

16 Suspension 1 Noise reported from o/s/f. See notes Monitoring

02 Pipeline Annual Inspection **12/03/2022** **10:30** **12/03/2022** **11:00** **436,521** **MDT Weymouth** **DW000836**

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - no faults

SAFETY INSPECTION **21/03/2022** **08:45** **22/03/2022** **09:05** **437,392** **Dorchester** **DC027313**

18 Wheels Check Torques
 Safety Inspection
 16 Suspension 1 Noise reported from o/s/f. See notes
 Annual Heater Service Annual Heater Service
 Replace Handbrake Cables Replace Handbrake Cables
 UB Fire Supp 12mts Service Service of fire suppression system
 Tail Lift Inspection
 02 Windscreen Wipers replace blades
 44 Add Ad Blue top up
 45 Engine Oil Top Up top up
 13 Brake Pads replace front pads and discs
 86 Doors Rear door barrel seized
 85 Body Interior 1 bag cupboard strap broken
 16 Suspension 2 slight play in OS wishbone ball joint

Vehicle Deep Clean	22/03/2022	11:15	23/03/2022	11:33	437,407	Dorchester	DC027321
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	27/04/2022	16:41	04/05/2022	07:24	441,908	Dorchester	DC027582
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Diesel fumes in cab
43 Exhaust System 1	DPF cracked
Annual Air Con Service	Annual Air Condition Service
Engine Change Oil & Filter	
18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
86 Doors Rear	NS barrel siezed
44 Add Ad Blue	top up
42 Coolant System	top up
55 Tail Lift	NS light at 33%, guide rails seized
17 Tyres Replace	both NSR low
16 Suspension 1	2 slipper pads delaminating
45 Engine 1	to book filter
86 Sliding Door	magnet bracket bent

Vehicle Deep Clean	04/05/2022	09:30	04/05/2022	15:25	441,944	Dorchester	DC027608
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	07/06/2022	11:30	07/06/2022	11:44	445,544	Dorchester	DC027821
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers	Washers inop.Flush out bottle and clean filter
----------------------	--

ACCIDENT	08/06/2022	16:30	10/06/2022	15:00	445,746	Dorchester	DC027847
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	Fumes reported in cab
71 Body Exterior Acc Repair	Emg Warning Devices O/S blues cracked & scene light removed

SAFETY INSPECTION	13/06/2022	08:00	13/06/2022	13:50	445,753	Dorchester	DC027877
18 Wheels Check Torques							
Safety Inspection							
86 Sliding Door			Body Exterior Sliding door not staying open				
45 Engine 1			Engine Loud groaning noise turning right				
02 Windscreen			2 small chips in windscreen				
71 Body External Steps			rear step starting to rot				
Tail Lift Inspection							
34 Emergency Lights			Both OS upper rectangular blue lights and surrounds damaged				
44 Add Ad Blue			top up				
55 Tail Lift			missing bolt on handrail lock, both rails stiff				
02 Windscreen Wipers			blades worn				
02 Cab Assembly 1			passenger footplate damaged				
16 Suspension 1			1 slipper pad delaminated				
Vehicle Deep Clean	14/06/2022	12:00	15/06/2022	16:07	445,766	Dorchester	DC027894
Vehicle Deep Clean			Vehicle Deep Clean				
Unplanned Repair	16/06/2022	12:30	16/06/2022	13:34	445,774	Dorchester	DC027910
34 Emergency Lights			replace damaged OSR upper led & surround & OSR corner blue lens				
Breakdown	22/06/2022	19:01	23/06/2022	12:30	446,592	Dorchester	DC027958
Breakdown			Will not deploy				
55 Tail Lift			Reported will not deploy. NFF				
Unplanned Repair	12/07/2022	12:00	12/07/2022	13:32	448,720	Dorchester	DC028075
02 Windscreen Wipers			washers blocked				
Breakdown	14/07/2022	04:42	14/07/2022	09:57	449,089	Dorchester	DC028087
Breakdown			Engine fumes coming into cab				

Breakdown	04/08/2022	19:48	05/08/2022	13:23	451,200	Dorchester	DC028211
Breakdown	NSR wheelarch						
Breakdown	07/08/2022	21:46	08/08/2022	07:42	452,099	Dorchester	DC028227
Breakdown	O/S/F Indicator						
SAFETY INSPECTION	08/08/2022	14:00	10/08/2022	09:14	452,128	Dorchester	DC028238
18 Wheels Check Torques							
Safety Inspection							
45 Engine 1	fumes in cab						
Pollen Filter Change	Pollen Filter Change						
44 Add Ad Blue	top up						
45 Engine Oil Top Up	top up						
01 Air Conditioning 1	recharge system						
55 Tail Lift	magnet bracket rotted out						
17 Tyres Replace	OSR outer worn						
Vehicle Deep Clean	10/08/2022	08:14	10/08/2022	15:01	452,142	Dorchester	DC028248
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	19/08/2022	08:30	19/08/2022	11:19	452,500	Dorchester	DC028306
52 Electrical Aux	Radio & Comm System Aerial Missing						
Breakdown	03/09/2022	02:16	13/09/2022	12:51	454,756	Dorchester	DC028370
Breakdown	strong diesel fumes in the cab; VOR						
SAFETY INSPECTION	20/10/2022	08:00	20/10/2022	08:00	459,792	St Leonards	SL037900
18 Wheels Check Torques							

Safety Inspection

SAFETY INSPECTION	20/10/2022	08:00	01/11/2022	15:00	459,792	St Leonards	SL037901
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

86 Sliding Door Doors Side door not locking open

Tail Lift Inspection

MOT

52 Electrical Aux replace both 230v green led lights in saloon

17 Tyres replace front tyres

13 Handbrake adjust rear handbrake

85 Body Interior 1 replace cctv cabinet gas struts

71 Body Exterior 1 replace storage strap in exterior side compartment

16 Suspension 1 replace both front lower suspension arms

15 Steering 1 replace o/s/f inner rack end and outer track rod

31 Battery Chassis replace chassis battery

13 Brake Pads brake pads low more than 50% remaining

Monitoring

02 Cab Ass Fire Extinguisher replace Saloon and cabin fire extinguishers

31 Battery Comms investigate warning message of 0v

31 Charging System Investigate squeal from belts at idle

45 Engine 1

Vehicle Deep Clean	31/10/2022	13:35	31/10/2022	13:36	459,792	St Leonards	SL037990
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean	31/10/2022	13:37	01/11/2022	14:30	459,792	St Leonards	SL037991
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

Breakdown	11/11/2022	06:45	18/11/2022	10:00	461,178	Dorchester	DC028466
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown LOP

41 Turbo Replace Turbo and exhaust temp sensor

Breakdown	20/11/2022	13:37	21/11/2022	05:30	461,203	St Leonards	SL038170
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Sidestep not holding weight of person					Monitoring
-----------	---------------------------------------	--	--	--	--	------------

Unplanned Repair	18/01/2023	13:06	18/01/2023	14:30	469,000	St Leonards	SL038827
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windscreen Wipers 45 Engine Oil Top Up	washers inop. traced to blocked filter. unblocked filter. topped up					
--	---	--	--	--	--	--

SAFETY INSPECTION	03/02/2023	11:45	09/02/2023	15:30	469,783	St Leonards	SL038976
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
89 Seats	Other Passenger side chair back adjuster knob broken. Replaced.
02 Windscreen Wipers	Windscreen Washer not spraying
Tail Lift Inspection	Done.
Air Filter Change	Air Filter Change. Done.
Fuel Filter Change	Change Fuel Filter. Done.
Pollen Filter Change	Pollen Filter Change. Done.
13 Brakes 2	Rear pads & disc's worn. Replaced.
Wheel Hub Flanges Replaceme	Front & Rear's in poor condition. Replaced.
41 Turbo	Impeller damaged.Replaced turbo,oil & filter.
13 Brakes 1	Front disc's & pads worn. Replaced.
71 Body Exterior 1	Rear spray flap bracket broken.Removed.Replaced.
86 Door Lock	Siezed,replaced barrels on rear,scoop & side doors.
86 Doors	Scoop locker n/w on key. Repaired.
55 Tail Lift	O/S gate siezed in down position. Freed and lub'ed.
71 Body External Steps	Side step roller missing,bracket bent.Straightened.
34 Lights	Side step light n/w. Replaced.

Vehicle Deep Clean	08/02/2023	12:09	09/02/2023	13:00	469,783	St Leonards	SL039041
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	12/02/2023	18:28	13/02/2023	08:00	469,880	St Leonards	SL039090
Breakdown 99 Diagnostic Test	ABS warning light on. (see notes)						
Breakdown	14/02/2023	15:43	17/03/2023	05:21	469,960	St Leonards	SL039105
Breakdown 45 Engine 1 002 Major Unit Replace Eng	went bang smoking Suspect engine failure Rygor westbury to repair Replaced by Rygor Westbury						
02 Pipeline Annual Inspection	13/04/2023	13:01	13/04/2023	13:04	472,865	MDT Weymouth	DW001199
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
SAFETY INSPECTION	10/04/2023	14:00	13/04/2023	10:11	474,037	St Leonards	SL039665
18 Wheels Check Torques Safety Inspection 02 Cab Assembly 1 02 Windscreen Wipers Engine Change Oil & Filter Tail Lift Inspection Replace Handbrake Cables 34 Emergency Lights 86 Doors Rear 71 Body External Steps 55 Tail Lift 13 Brakes 1 45 Engine 1 16 Suspension 1 16 Suspension 2 15 Steering 1 34 Lights 19 Chassis 1 17 Tyres Tracking	NS Window switch broken. brake pedal rubber worn. replaced Wiper linkage noisy. lubricated. operating ok. MONITOR Replace Handbrake Cables. Freed off seized adjuster mechanism. NS Scene light damaged/water ingress. Replaced scene light. Rear door lower latch worn. replaced latch, lubed and adjusted all door cables. Step roller bush missing. replaced bush and lubricated step. (non stock part) Tail lift hand rails excessive movement and droppers seized. adjusted & Lubed Rear brake caliper sliders seized. removed freed off and lubricated. O/S Engine mount split. replaced mount. Rear anti roll bar drop link lower bushes worn. replaced bushes Front shock absorbers excessive play in upper mounts. replaced shocks, OSF track rod play in inner joint. replaced joint and end. OS side marker damaged and o/s no plate light dim. replaced both OSF wheel bearing excessive play. replaced hub assembly SAS to track (F/Comms)						
Vehicle Deep Clean	13/04/2023	16:00	14/04/2023	13:45	474,069	St Leonards	SL039714
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	25/04/2023	02:00	26/04/2023	05:20	475,035	St Leonards	SL039881
Breakdown	o/s headlight out						
34 Lights	O/S headlight u/s.. Parts ordered				Monitoring		
Unplanned Repair	27/04/2023	15:00	27/04/2023	17:08	475,255	St Leonards	SL039921
31 Charging System	Alternator U/S						
Unplanned Repair	08/05/2023	06:40	09/05/2023	14:00	475,842	St Leonards	SL040035
56 Comms Equipment	MDT not working - Repair arranged by OSD						
SAFETY INSPECTION	25/05/2023	08:27	25/05/2023	17:12	475,990	St Leonards	SL040263
18 Wheels Check Torques							
Safety Inspection							
02 Windscreen Wipers	Wiper linkage noisy. lubricated. operating ok. MONITOR						
34 Lights	O/S headlight u/s.. Parts ordered						
56 Comms Power Failure	MDT Failure/Issue MDT COMMS CHECK						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
UB Fire Supp 12mts Service	Service of fire supression system						
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
Vehicle Deep Clean	26/05/2023	11:58	27/05/2023	16:13	475,990	St Leonards	SL040286
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	28/05/2023	18:50	29/05/2023	06:00	476,744	St Leonards	SL040318
Breakdown	punctuire						

Unplanned Repair	07/06/2023	13:00	07/06/2023	14:00	478,265	St Leonards	SL040458
45 Engine 1	Replace EGR valve						
Unplanned Repair	01/07/2023	09:14	01/07/2023	09:18	480,185	St Leonards	SL040815
45 Engine Ad Blue 02 Windscreen Wipers	Top up Linkage worn, Parts ordered					Monitoring	
Breakdown	02/07/2023	16:24	03/07/2023	07:06	480,358	St Leonards	SL040821
Breakdown	side door magnet broken						
Replace Vehicle Fuel Card	06/07/2023	14:50	06/07/2023	14:51	480,378	St Leonards	SL040900
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
SAFETY INSPECTION	08/07/2023	06:00	10/07/2023	08:00	480,379	St Leonards	SL040937
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
02 Windscreen Wipers	Linkage worn, Parts ordered						
56 Comms Equipment	MDT Failure/Issue Terrafix powering down						
Tail Lift Inspection	Done.						
86 Sliding Door	Top magnet adrift. Resecured.						
89 Seatbelts	Saloon seat belt stalk loose. Tightened.						
02 Glass / Windows	Emergency window release rubber adrift.						
56 Comms Fitment	Mic's in saloon loose too wall. Secured.						
55 Tail Lift	Roll flaps siezed. Replaced x2.						
01 Heating 1	Saloon heater exhaust split. Replaced.						
Install Saloon CCTV Camera	Alarm light on. Checked, Formatted.						
44 Add Ad Blue	Tank fill level incorrect. (see notes)					Monitoring	
24 Driveshaft 1	Graese nipple missing from prop. Replaced.						
Vehicle Deep Clean	10/07/2023	15:00	11/07/2023	09:57	480,379	St Leonards	SL040987
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	04/08/2023	11:30	04/08/2023	11:45	481,358	St Leonards	SL041394
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Emergency Light System	Replace cab Genisys switch panel
---------------------------	----------------------------------

Vehicle Deep Clean	14/08/2023	06:18	14/08/2023	13:30	481,368	St Leonards	SL041512
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	16/08/2023	07:00	16/08/2023	16:08	481,368	St Leonards	SL041546
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
44 Add Ad Blue	Tank fill level incorrect. (see notes) Replaced tank, filled and reset values.
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Tail Lift Inspection	
86 Sliding Door	Sliding door upper latch loose and magnet worn. resecured and replaced
15 Steering 1	NSF Track rod end boot split. replaced end.
16 Suspension 1	Rear os spring buffers split. replaced x2.
13 Handbrake	Adjusted shoes and cable.

Unplanned Repair	21/09/2023	07:16	21/09/2023	07:39	487,113	St Leonards	SL042031
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

44 Add Ad Blue	Topped up adblue.
71 Body External Steps	Step not deploying. lubricated moving parts on step. operating ok.

Vehicle Deep Clean	25/09/2023	12:32	25/09/2023	17:14	487,113	St Leonards	SL042087
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	27/09/2023	07:36	02/10/2023	17:00	487,113	St Leonards	SL042116
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
MOT	

Tail Lift Inspection	
Recall Notification	Merc air bag recall
Pollen Filter Change	Pollen Filter Change
Fuel tank check	Fuel tank wet & filler neck leak
87 Stretcher	Stretcher belts wrongly fitted.
02 Windscreen Wipers	Windscreen washer jets not working.
16 Suspension 1	Front shock absorber top mounts have excessive play
02 Cab Assembly 1	Cab throttle pedal bolt snapped.
55 Tail Lift	Tail lift bridge plate bolt missing.
56 Comms Power Failure	Comms battery supply intermittent.
03 Instruments & Sensors 1	E.M.L. Illuminated on dashboard display
Tail Lift Annual Service	Tail lift hand pump controls seized.
13 Brake Test	Carry out brake test.
34 Lighting System	Carry out headlight alignment

Unplanned Repair	02/10/2023	17:30	03/10/2023	16:00	487,113	St Leonards	SL042171
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Power Failure	MDT not turning on - SSS to repair
------------------------	------------------------------------

Unplanned Repair	12/10/2023	12:18	12/10/2023	12:58	489,000	St Leonards	SL042324
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Chassis	Replace battery
--------------------	-----------------

Unplanned Repair	16/10/2023	11:45	17/10/2023	14:00	490,211	St Leonards	SL042391
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Equipment	MDT Failure/Issue Not sending messages to Control. Not working
44 Add Ad Blue	Top up Ad blue

Vehicle Deep Clean	06/11/2023	13:30	07/11/2023	11:00	491,145	St Leonards	SL042692
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/11/2023	13:00	08/11/2023	08:28	491,145	St Leonards	SL042704
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
-------------------------	----------

Safety Inspection	Carried out inspection.	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change. Done.	
17 Tyres Replace	O/S/R/O tyre nailed. Replaced.	
02 Cab Assembly 1	Drivers window switch broken. Replaced.	
34 Lights Bulb Replacement	N/S running light n/w. Replaced bulb.	
02 Cab Ass Fire Extinguisher	Out of date. Replaced x1.	
55 Tail Lift	Wedge support bolt siezed,washer adrift. SWL to repair.Monitor.	Monitoring
02 Glass / Windows	Rear door window rubber adrift. Secured.	

Breakdown	16/12/2023	14:53	17/12/2023	06:21	493,400	St Leonards	SL043226
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	stretcher straps wrong
-----------	------------------------

Vehicle Deep Clean	18/12/2023	06:47	18/12/2023	10:13	493,400	St Leonards	SL043235
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	19/12/2023	07:30	20/12/2023	15:08	493,400	St Leonards	SL043247
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
85 Body Interior 1	Large Bottom draw faulty, vac mattress door faulty. Repaired
86 Sliding Door	Not holding open. Magnet not making contact repositioned,
Brake Fluid Change	Brake Fluid Change
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
13 Brake Pads	Brake pads worn low. Replaced
71 Body Exterior 1	Shoreline autoeject cover missing. Replaced
17 Tyres	1x front tyre and 1x N/S/R tyre worn low. Replace bith tyres and move to front
31 Charging System	not charging

ACCIDENT	02/01/2024	05:53	02/01/2024	08:15	496,495	St Leonards	SL043411
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	N/S/R
-----------	-------

SAFETY INSPECTION	03/02/2024	10:00	04/02/2024	11:16	498,337	St Leonards	SL043821
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

55 Tail Lift

Wedge support bolt siezed, washer adrift. SWL to repair. Monitor.

Monitoring

56 Comms Equipment

Comms Power Check No sat nav NFF

Tail Lift 12M Service & Weight

Tail Lift 12M Service & Weight. DONE BY SWL

Tail Lift Inspection

DONE BY SWL

71 Body External Steps

Side step sticking. Roller badly worn. Replace cleaned and greased

34 Emergency Lights

N/S/R corner blue light smashed. Replaced and repaired mounting area.

13 Brake Pads

Rear brake pads worn low. Replaced

17 Tyres Replace

Nail in O/S/R/outer tyre

86 Doors Rear

Rear door alarm sounding. Adjusted sensor

Vehicle Deep Clean	06/02/2024	07:21	06/02/2024	13:23	498,368	St Leonards	SL043857
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean

Vehicle Deep Clean

Vehicle Deep Clean	13/03/2024	15:22	14/03/2024	12:04	503,270	St Leonards	SL044397
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean

Vehicle Deep Clean

SAFETY INSPECTION	15/03/2024	07:18	18/03/2024	16:00	503,270	St Leonards	SL044426
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

56 Comms Power Failure

Comms Power Check MDT not receiving jobs NFF

Engine Change Oil & Filter

Tail Lift Inspection

Inspected

02 Glass / Windows

window switch broken passenger side. Replaced

02 Windscreen Wipers

Wiper arm realligned

71 Body External Steps

Sliding door step not fully deploying. Replaced strut

Pollen Filter Change

Pollen Filter contaminated. Replaced

85 Body Interior 1

Floor matts missing. Replaced

16 Suspension 1

Buffer pads torn N/S. Replaced

85 Body Interior 2

Tool kit cover cracked. Replaced

43 Exhaust System 1

Exhaust tip broken off. Replaced

O2 Pipeline Annual Inspection	15/03/2024	10:42	16/03/2024	10:45	503,270	MDT Ferndown	TF003328
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

O2 Pipeline Annual Inspection Annual Inspection and Pressure Test - replaced 1 x port seal kit (lot53887)

Unplanned Repair	15/04/2024	09:00	16/04/2024	16:52	506,798	St Leonards	SL044932
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Doors Rear renewed o/s\r door stay

Vehicle Deep Clean	28/04/2024	09:09	29/04/2024	09:41	507,714	St Leonards	SL045067
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	29/04/2024	10:00	30/04/2024	13:28	507,714	St Leonards	SL045087
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

56 Radio Radio & Comm System Handheld battery charger not working

34 Lights Body Exterior Near side build side light

86 Door Seals N/S door seal split

13 Discs Front discs below limits

34 Lights Bulb Replacement O/S Dipped beam not working

55 Tail Lift Side rail not locking into place

Vehicle Deep Clean	06/06/2024	15:30	07/06/2024	15:03	510,787	St Leonards	SL045648
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	08/06/2024	13:30	09/06/2024	13:36	510,787	St Leonards	SL045686
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

Replace Handbrake Cables Replace Handbrake Cables

02 Cab Assembly 1 Torch n/w. Replaced battery.

44 Add Ad Blue Topped 10Ltrs.

45 Engine 1 EML on. Replaced cat temp sensor & adapt wiring as multi-plug missing.

34 Lights N/S number plate light n/w. Checked & replaced/rewire loom.

86 Door Lock Wrong key for locks. Find replacment key.

45 Engine 2	Inlet piping leaking. Replaced seals.
55 Tail Lift	Replaced missing roll-pin.

Unplanned Repair	17/06/2024	07:28	17/06/2024	07:33	512,044	St Leonards	SL045807
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	EML/LOP
34 Emergency Lights	Headlight n.w

BREAKDOWN	29/06/2024	09:00	29/06/2024	14:19	513,045	St Leonards	SL046049
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

44 Add Ad Blue

Unplanned Repair	18/07/2024	08:00	18/07/2024	13:00	516,471	St Leonards	SL046444
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

85 Body Interior 1	water in between inner & outer body skins O\S\F corner. see notes
--------------------	---

Vehicle Deep Clean	24/07/2024	10:30	24/07/2024	16:08	516,526	St Leonards	SL046506
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	25/07/2024	17:08	30/07/2024	11:38	516,526	St Leonards	SL046555
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 12mts Service	Service of fire suppression system
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
Tail Lift Inspection	
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Axle Oil Change	Axle Oil Change
Pollen Filter Change	Pollen Filter Change
13 Brakes 1	Crew report long travel on brake pedal. Checked and bled brake system
02 Cab Assembly 1	Steering wheel worn. replaced - console lid loose. resecured.
34 Lights	NSR Upper indicator led's inop. replaced light.

86 Sliding Door	(SEE NOTES)
86 Doors Rear	Upper latch cover broken. replaced with sticker.
85 Body Interior 1	Equipment straps broken. replaced and locker doors loose. resecured.
13 Handbrake	Adjusted shoes and cables.
Brake Fluid Change	Brake Fluid Change
16 Suspension 1	Rear anti roll bar drop link bushes worn. replaced x4 bushes.
16 Suspension 2	Front shock absorbers play in upper mounts. replaced shocks and bolts.
17 Tyres Replace	All tyres worn. replaced.
55 Tail Lift	Tilt switch faulty. replaced switch.
13 Brakes 2	Earth cable lugs on telma broken. replaced cable lugs.
45 Engine 1	Both engine belt tensioners worn. replace both.
01 Air Conditioning 1	Saloon ac system condenser fan seized. replaced condenser unit and lines.
02 Windscreen Wipers	Wiper system excessively noisy and worn. replaced linkage system and arms.

Breakdown	08/08/2024	07:45	09/08/2024	16:00	517,236	St Leonards	SL046713
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	gears not changing						
-----------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	28/08/2024	08:00	29/08/2024	14:28	518,545	St Leonards	SL047037
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
24 Driveshaft 1	Gearbox Won't Move In Any Gear. repaired previously.
MOT	Done.. Carried out 27th at Ferndown Comm
31 Battery Chassis	Battery u/s due to heater fault. replaced battery
01 Air Conditioning 1	Investigate blower fault. Heater resistor faulty.
85 Body Interior 1	Saloon top drawer bottom broken. repaired drawer.
27 Transmission Automatic	Transmission mount perished. replaced mount
43 Exhaust System 1	Rear tailpipe rubber hanger perished. replaced using spare parts.
41 Air Intake	Intake pipe on n/s broken at mount. replaced pipe/seals and cleaned.

Vehicle Deep Clean	29/08/2024	07:00	29/08/2024	14:55	519,303	St Leonards	SL047055
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Vehicle Deep Clean	08/10/2024	15:33	09/10/2024	11:21	521,976	St Leonards	SL047647
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/10/2024	06:00	10/10/2024	15:00	522,092	St Leonards	SL047666
18 Wheels Check Torques							
Safety Inspection							
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
Engine Change Oil & Filter	Replace Oil and Filter						
Pollen Filter Change	Pollen Filter Change						
Tail Lift Inspection							
85 Body Interior 1	Rear cupboard gas strut leaking oil. replaced						
89 Seats	Rear saloon swivel seat bearings worn. replaced bearings.						
13 Brakes 1	Telma inop. removed control box, cleaned & adjusted all contacts. tested ok						
Unplanned Repair	18/10/2024	09:58	18/10/2024	11:32	523,504	St Leonards	SL047828
86 Door handle	Rear outside door handle snapped						
ACCIDENT	13/11/2024	05:00	13/11/2024	08:30	527,759	St Leonards	SL048202
34 Emergency Lights	Lighting System Blue bar rear on the left hand side is damaged						
SAFETY INSPECTION	19/11/2024	07:00	19/11/2024	17:02	527,789	St Leonards	SL048297
18 Wheels Check Torques							
Safety Inspection							
86 Sliding Door	Doors side door handle snapped off. Previous repair						
17 Tyres Replace	Nail in OSR inner tyre. Replaced						
13 Brake Pads	Replace front and rear brake pads						
89 Seats	Rear swivel seat plunger seized. Replaced plunger						
Vehicle Deep Clean	20/11/2024	07:19	20/11/2024	13:00	527,799	St Leonards	SL048312
Vehicle Deep Clean	Vehicle Deep Clean						

Tail Lift 12M Service & Weight	20/11/2024	08:00	20/11/2024	11:43	527,799	St Leonards	SL048324
Tail Lift 12M Service & Weight Tail Lift Inspection							
Unplanned Repair	01/12/2024	11:15	02/12/2024	10:16	527,844	St Leonards	SL048477
54 Sirens	Siren inop						
Unplanned Repair	03/12/2024	07:25	13/12/2024	12:05	529,032	St Leonards	SL048500
UB Fire Supp Repair 56 Comms Equipment 31 Battery Aux	Fire suppression audio warning. Repair multiplug wiring No power to MDVS Test and replace						
Unplanned Repair	25/12/2024	06:00	25/12/2024	09:00	529,032	St Leonards	SL048821
71 Body Exterior 1	Body Exterior Crushed number plate, damage to the bumper						
Vehicle Deep Clean	02/01/2025	07:45	02/01/2025	13:00	531,268	St Leonards	SL048916
Vehicle Deep Clean	Vehicle Deep Clean						
Med Devices Recall	02/01/2025	10:20	02/01/2025	10:23	531,268	MDT Ferndown	TF003901
Decontaminated Med Devices Recall	Cleaned with clinell wipes Upgrade Mangar bracket and compressor to Airflo 24						
SAFETY INSPECTION	07/01/2025	16:12	08/01/2025	11:45	531,268	St Leonards	SL049004
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 52 Electrical Aux	Check and Install MDVS windows update.Done. Carried out insp[ection]. Checked. Electrical Auxs comms wiring and FSU sensor check						

Tail Lift Inspection	Done.	
44 Add Ad Blue	Topped 15Ltrs.	
02 Cab Assembly 1	Interior light n/w. Replaced bulb.	
45 Engine Oil Top Up	Topped 1Ltr	
71 Body Exterior 1	Front number plate smashed.	
71 Body External Steps	Rear step holed. Monitor.	Monitoring
Install Saloon CCTV Camera	CCTV alarm on. Checked & formatted.	

Unplanned Repair	13/02/2025	10:00	13/02/2025	14:21	535,316	St Leonards	SL049536
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Equipment	Roof aerial missing. Replaced
31 Charging System	Shoreline auto eject not ejecting. Cleaned and greased ejector.

Vehicle Deep Clean	19/02/2025	10:39	20/02/2025	11:00	536,161	St Leonards	SL049620
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	21/02/2025	17:00	24/02/2025	09:45	536,161	St Leonards	SL049657
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
71 Body External Steps	Rear step holed. Monitor.
Tail Lift Inspection	
02 Cab Assembly 1	Cab seat belt frayed
86 Sliding Door	N/S side door upper magnet check strap bent
13 Brake Test	
03 Instruments & Sensors 1	E.M.L. Illuminated on dash
13 Brakes 1	Front brakes due next service. John aware
13 Brakes 2	Rear brakes due next service. John aware

Breakdown	23/03/2025	16:27	24/03/2025	08:11	540,150	St Leonards	SL050053
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	steering clunking when turning
17 Tyres Replace	NSF Tyre replaced.

Unplanned Repair	01/04/2025	12:15	01/04/2025	12:44	541,246	St Leonards	SL050166
02 Mirrors	O/S mirror broken. Replaced glass.						
Vehicle Deep Clean	06/04/2025	12:00	08/04/2025	09:00	541,614	St Leonards	SL050250
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	09/04/2025	06:00	10/04/2025	10:40	541,614	St Leonards	SL050313
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
Wheel Hub Flanges Replaceme							
Tail Lift Inspection							
85 Body Int Alcohol Gel Dispen							
13 Brake Test							
02 Cab Assembly 1	Cab gearstick gaitor pulled out						
85 Body Interior 1	Saloon N/S/F seat base swivel pin loose						
85 Body Interior 2	Saloon N/S/R seat belt buckle bolt loose						
87 - Stretchers/Chairs/Boards	Stretcher belts in wrong positions						
O2 Pipeline Annual Inspection	07/04/2025	11:29	07/04/2025	11:30	541,614	MDT Ferndown	TF004096
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - Passed all tests.						
Emergency Deep Clean	16/05/2025	16:30	16/05/2025	20:37	546,989	St Leonards	SL051003
Emergency Deep Clean							
SAFETY INSPECTION	23/05/2025	06:43	23/05/2025	13:24	546,989	St Leonards	SL051125

Check MDVS for Update	Check and Install MDVS windows update.Done.	
Safety Inspection	Carried out inspection.	
18 Wheels Check Torques	Checked.	
Road Test	Done.	
02 Cab Assembly 1	Interior light n/w. Replaced bulb.	
89 Seats	Drivers seat back adjuster n/w. Monitor JS	Monitoring
44 Add Ad Blue	Topped 10Ltrs.	
02 Cab Assembly 2	Passenger window switch broken. Replaced.	
85 Body Interior 1	Cupboard strap broken. Replaced.	
71 Body Exterior 1	N/S/R lower corner capping smashed. Replaced.	
86 Door Lock	Scoopp locker key n/w. Replaced housing.	
34 Emergency Lights	Airport light n/w. Monitor JS.	Monitoring
56 Radio	Roof aerial missing. Replaced.	
13 Brakes 1	Front pads & disc's worn. Monitor JS.	Monitoring
17 Tyres Replace	O/S/F tyre worn on edge. Replaced.	
85 Body Int Alcohol Gel Dispen	Replaced.	
85 Body Interior 2	Roof panic strip n/w. Repaired wiring.	
02 Glass / Windows	N/S saloon window rubber adrift. Refitted.	

Vehicle Deep Clean	26/05/2025	13:21	26/05/2025	15:11	547,693	St Leonards	SL051207
Vehicle Deep Clean	Vehicle Deep Clean						