

WM64JWY	A&E		Newton Abbot Amb Stn				
PDI Inspection	04/04/2015	08:34	07/04/2015	09:27	176	Derriford	DE018126
71 Body Exterior 1 PDI Inspection	Skylight blast film fitted by Autospray p/o 151107468						
Unplanned Repair	05/05/2015	14:06	05/05/2015	14:11	2,259	Torquay	TO010530
45 Engine Ad Blue	Crew topped up						
SAFETY INSPECTION	11/05/2015	09:20	12/05/2015	06:57	3,817	Torquay	TO010547
13 Handbrake 18 Wheels Check Torques 87 - Stretchers/Chairs/Boards Safety Inspection	Checklist Defect Adjust H/brake Checklist Defect Service Scoop						
Vehicle Deep Clean	11/05/2015	12:29	11/05/2015	14:26	3,817	Torquay	TO010549
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	14/05/2015	13:00	14/05/2015	13:28	3,817	Torquay	TO010565
45 Engine Ad Blue	Crew topped up adblue						
Unplanned Repair	26/05/2015	08:03	26/05/2015	08:05	5,697	Torquay	TO010596
45 Engine Ad Blue	Crew topped up Adblue						
Unplanned Repair	11/06/2015	07:55	11/06/2015	08:06	8,152	Torquay	TO010657
45 Engine Ad Blue	Crew topped up adblue						

Unplanned Repair	16/06/2015	08:00	16/06/2015	09:11	9,188	Torquay	TO010667
16 Suspension 1	road tested,identified noise tightened rear arb link bolts all ok						
Unplanned Repair	22/06/2015	08:10	22/06/2015	08:12	9,906	Torquay	TO010682
45 Engine Ad Blue	Crew topped up adblue						
Vehicle Deep Clean	23/06/2015	08:10	23/06/2015	15:00	10,174	Torquay	TO010690
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/06/2015	15:19	24/06/2015	10:43	10,174	Torquay	TO010692
18 Wheels Check Torques Safety Inspection							
Unplanned Repair	03/07/2015	07:50	03/07/2015	07:54	11,418	Torquay	TO010718
45 Engine Ad Blue	Crewtopped up Adblue						
Unplanned Repair	08/07/2015	14:05	08/07/2015	14:07	12,373	Torquay	TO010738
44 Add Ad Blue							
Unplanned Repair	13/07/2015	12:05	13/07/2015	12:19	13,440	Torquay	TO010753
44 Add Ad Blue							
BREAKDOWN	27/07/2015	09:43	27/07/2015	09:47	15,876	Torquay	TO010805
17 Tyres Replace	Replaced N/S/F tyre due to smooth on outer edge						

71 Body External Steps	Side step been hit, bent back up as temp repair - new step required					Monitoring	
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	05/08/2015	07:10	05/08/2015	13:20	17,054	Torquay	TO010846
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	10/08/2015	14:17	12/08/2015	08:01	17,526	Torquay	TO010861
54 Warn Dev/System	Panic alarm constantly going and tail lift deployed going when pulling away					Awaiting Body Repair	
71 Body External Steps	Side step has been hit hard and will not deploy.						
SAFETY INSPECTION	12/08/2015	07:58	12/08/2015	11:46	17,536	Torquay	TO010867
03 Instruments & Sensors 1	Emg Warning Devices Panic alarm going off intermittently - Repaired					Awaiting Body Repair	
18 Wheels Check Torques							
54 Warn Dev/System	Emg Warning Devices Tail lift deployed warning on constantly - WAS repaired						
55 Tail Lift	Tail lift rams adjusted						
71 Body External Steps	Side step been hit, bent back up as temp repair - new step required -						
89 Seats	Rear swivel seat detend pin adjustment						
Safety Inspection							
92 - C Service							
Service C							
BREAKDOWN	02/09/2015	09:08	02/09/2015	09:28	20,317	Torquay	TO010925
45 Engine 1	Power loss up hills no EML on						
BREAKDOWN	03/09/2015	07:04	10/09/2015	09:32	20,330	Torquay	TO010928
45 Engine 1	Vehicle has loss of power and sticks in 2nd gear						
SAFETY INSPECTION	10/09/2015	12:00	10/09/2015	14:44	20,369	Torquay	TO010960
13 Brake Pads	Checklist Defect Front pads low Deffered until 14/09					Monitoring	
17 Tyres	Checklist Defect Frt 5mm RR3.5-4mm Defered until 14/09					Monitoring	

17 Tyres Replace	Checklist Defect 4 tyres across rear axle getting low	DEFFERED UNTIL 14/09	Monitoring
18 Wheels Check Torques			
45 Engine 1	Engine Will not go up hills- very low power	WARRANTY REPAIR CITY WEST	
71 Body Exterior 1	Checklist Defect Accident damage down N/S		Awaiting Body Repair
71 Body Exterior Acc Repair	Electrical Auxs Side step does not deploy correctly		
71 Body External Steps	Side step been hit, bent back up as temp repair - new step required -		Awaiting Parts
Safety Inspection			

Tail Lift 6 Monthly Inspection	25/09/2015	14:44	25/09/2015	15:30	20,964	Torquay	TO011012
---------------------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Tail Lift 6 Monthly Inspection Statutory Inspection Done by south swet lifts P/O 151116907

Vehicle Deep Clean	29/09/2015	08:57	30/09/2015	13:00	22,968	Torquay	TO011014
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

Defect Repair	29/09/2015	13:48	30/09/2015	09:21	22,968	Torquay	TO011015
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

13 Brake Pads	Checklist Defect Front pads low	REPLACED	
17 Tyres	Checklist Defect Frt 5mm RR3.5-4mm	RELACED ATS	
17 Tyres Replace	Checklist Defect 4 tyres across rear axle getting low	REPLACED BY ATS	
71 Body Exterior 1	Checklist Defect Accident damage down N/S		Awaiting Body Repair
71 Body Exterior Acc Repair	Electrical Auxs Side step does not deploy correctly	TEMP REPAIR	Awaiting Body Repair

Defect Repair	12/10/2015	09:21	12/10/2015	09:59	24,530	Torquay	TO011054
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

71 Body External Steps limp mode/engine man light + step fault notes

BREAKDOWN	12/10/2015	09:25	15/10/2015	14:09	24,530	Torquay	TO011055
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

45 Engine 1 Intermitant limp mode ?? WTY

Unplanned Repair	15/10/2015	13:59	15/10/2015	14:03	24,571	Torquay	TO011072
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

34 Lights Bulb Replacement	replaced o/s head light bulb	
71 Body External Steps	Side step been hit, bent back up as temp repair - new step required - notes	

Unplanned Repair	20/10/2015	08:01	22/10/2015	16:07	25,325	Torquay	TO011083
45 Engine 1	EML light on +						
SAFETY INSPECTION	23/10/2015	09:43	23/10/2015	15:00	25,361	Torquay	TO011098
18 Wheels Check Torques							
45 Engine Oil Top Up	topped up engine oil level 1.5ltrs						
71 Body Exterior Acc Repair	made temp repare to n\s rear wheel arch						
Safety Inspection							
Vehicle Deep Clean	23/10/2015	11:20	23/10/2015	14:15	25,361	Torquay	TO011099
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	02/11/2015	16:43	03/11/2015	10:04	26,223	Torquay	TO011137
Breakdown	2 Bold tyres taking toi ATS, ATS checked no action required tyres all ok!!						
Breakdown	15/11/2015	07:41	17/11/2015	12:06	28,006	Torquay	TO011177
Breakdown	Worn on outer edge (conti) Requested tyre From ATS Poss on fault??						
Unplanned Repair	16/11/2015	08:54	16/11/2015	08:58	28,006	Torquay	TO011179
34 Lights Bulb Replacement	OO replaced head light bulb n\s put back in safe						
BREAKDOWN	01/12/2015	08:12	03/12/2015	16:00	30,024	Torquay	TO011241
45 Engine 1	Engine Vehicle went into limp mode WTY merc Ex notes						
Breakdown	05/12/2015	14:09	09/12/2015	15:05	30,381	Torquay	TO011256
45 Engine 1	Limp mode WTY going back to merc Been fixed ??						
Breakdown	WHILST DRIVING LOSS OF POWER (LIMP MODE)						

SAFETY INSPECTION	10/12/2015	08:32	11/12/2015	12:16	30,423	Torquay	TO011271
02 Cab Assembly 1			fitted new adjueter knob to drivers seat				
17 Tyres			had ATS Fit part worn to n\s\				
18 Wheels Check Torques							
71 Body Exterior 1			made repair to broken front bumper foot step				
85 Body Interior 1			replaced form holder and repaired other one				
86 Doors			adjusted rear door cables and catch, sticking				
87 Stretcher Harness Replaced			replaced harness and x1 lap belt				
Safety Inspection							
Vehicle Deep Clean	10/12/2015	09:11	11/12/2015	09:14	30,423	Torquay	TO011277
Vehicle Deep Clean			Vehicle Deep Clean				
Unplanned Repair	17/12/2015	12:03	17/12/2015	12:06	31,160	Torquay	TO011295
87 - Stretchers/Chairs/Boards			replaced missing pole				
Unplanned Repair	15/01/2016	08:18	15/01/2016	08:34	35,688	Torquay	TO011392
34 Lights Bulb Replacement			replaced head light bulb				
SAFETY INSPECTION	18/01/2016	11:13	19/01/2016	16:00	36,298	Torquay	TO011399
02 Cab Assembly 1			replaced pedal rubber				
13 Brakes 1			replaced rear brake pads				
18 Wheels Check Torques							
85 Body Interior 1			ordered new knob for cab box and catch for bulkhead glass			Awaiting Parts	
86 Sliding Door			Ordered new panel for silding door			Awaiting Parts	
87 Stretcher			replace pedemate				
Safety Inspection							
MOT Pre Test							
Travel Time							

MOT							
93 - D Service	see notes						
Service D							
Vehicle Deep Clean	19/01/2016	12:34	20/01/2016	10:51	36,298	Torquay	TO011408
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	22/01/2016	15:50	22/01/2016	16:26	36,619	Torquay	TO011424
86 Doors	adjusted cables inside ,side door unable to open from inside just						
Unplanned Repair	10/02/2016	08:09	10/02/2016	08:13	39,496	Torquay	TO011474
34 Lights Bulb Replacement	replaced head light bulb used by oo,s						
SAFETY INSPECTION	29/02/2016	08:22	01/03/2016	14:44	42,849	Torquay	TO011531
02 Cab Ass Fire Extinguisher	replaced both fire extinguishers						
18 Wheels Check Torques							
45 Engine Oil Top Up	topped up oil level 0.5ltr						
71 Body External W&T Repair	made repir to n\s rear wheel arch						
85 Body Interior 1	knob for cab box and catch for bulkhead glass replaced both						
86 Doors	rescuiired side door inner window panel screws missing also refitted seal						
86 Sliding Door	Ordered new panel for silding door fitted new panel						
89 Seats	tightened saloon seat arms + WYT on first saet bearings noisy						Awaiting Warranty
Safety Inspection							
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	01/03/2016	08:05	01/03/2016	14:05	42,849	Torquay	TO011537
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	28/03/2016	19:58	30/03/2016	09:16	46,793	Torquay	TO011617
17 Tyres	ATS replaced tyres x2						

Breakdown	R/N/S PARTIAL FLAT						
Unplanned Repair	01/04/2016	09:40	01/04/2016	15:24	47,045	Torquay	TO011636
34 Lights Bulb Replacement	replaced head light bulb fitted by OO's						
Unplanned Repair	07/04/2016	13:21	07/04/2016	14:59	48,277	Torquay	TO011666
17 Tyres	ATS fitted two part worns to both front wheels						
SAFETY INSPECTION	11/04/2016	08:33	12/04/2016	08:16	48,277	Torquay	TO011675
02 Cab Assembly 1	replaced torch battery						
17 Tyres	replaced o/s\l r tyres						
18 Wheels Check Torques							
34 Lights Bulb Replacement	put spare bulb in glove box						
45 Engine Oil Top Up	topprd up engine oil level 1.5 ltrs						
52 Electrical Aux	speaker broken in cab x2						
Safety Inspection	Awaiting Parts						
85 Body Int Alcohol Gel Dispen							
Fit Throw Lines & SOP							
Wheel Studs & Nuts Replaceme							
Handbrake Cable Replacement							
UB Fire Suppression Service							
Vehicle Deep Clean	12/04/2016	08:46	13/04/2016	07:16	48,279	Torquay	TO011679
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/05/2016	11:31	24/05/2016	11:44	54,931	Torquay	TO011812
13 Brakes 1	replaced front pads and discs and sensors						
18 Wheels Check Torques							
44 Fuel System 1	replaced fuel cap						
52 Electrical Aux	speaker broken in cab x2 replaced speakers and changed volume knob						
Safety Inspection							
Gearbox Oil & Filter Change							

92 - C Service
Service C

Vehicle Deep Clean	24/05/2016	09:51	25/05/2016	13:43	54,931	Torquay	TO011815
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	04/07/2016	09:11	04/07/2016	15:26	60,873	Torquay	TO011924
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques	
71 Body Exterior 1	repaired bumper step,replaced number plate refitted siren cover
Safety Inspection	
Annual Heater Service	Annual Heater Service
Reposition grab bag shelf	

Install Saloon CCTV Camera	04/07/2016	15:28	06/07/2016	13:48	60,873	Torquay	TO011929
-----------------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

89 Seats	tightened saloon seat arms + WYT on first saet bearings noisy
Install Saloon CCTV Camera	

Vehicle Deep Clean	05/07/2016	09:00	05/07/2016	13:54	60,873	Torquay	TO011933
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	18/07/2016	12:52	18/07/2016	12:55	62,960	Torquay	TO011976
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

31 Charging System	240V charging inop - Traced fault to tripped switch and loose plug pass. seat.
--------------------	--

BREAKDOWN	22/07/2016	08:56	22/07/2016	09:32	63,587	Torquay	TO011991
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

71 Body External Steps	Side step has been hit and damaged - Bent back to shape as best as could
86 Doors Rear	N/S/R door stay snapped - Replaced door stay mounting block

Defect Repair	04/08/2016	08:39	04/08/2016	08:44	65,628	Torquay	TO012031
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

86 Sliding Door	Doors Side doo magnet not holding door open adjusted bracket	
87 Chairs	Body Interior Carry chair catch not working adjusted Ordered new bracket	Awaiting Parts

SAFETY INSPECTION	15/08/2016	08:35	16/08/2016	08:38	67,305	Torquay	TO012058		
13 Brakes 1	replaced rear pads and discs								
17 Tyres	replaced all tyres								
18 Wheels Check Torques									
43 Exhaust System 1	replaced cotton reel on exhaust mount								
Safety Inspection									
Annual Air Con Service	Annual Air Condition Service								
Tail Lift 6 Monthly Inspection	Statutory Inspection								
Vehicle Deep Clean	15/08/2016	14:22	16/08/2016	13:21	67,305	Torquay	TO012065		
Vehicle Deep Clean	Vehicle Deep Clean								
Defect Repair	19/09/2016	12:02	23/09/2016	07:20	72,198	Torquay	TO012192		
03 Instruments & Sensors 1	Emg Warning Devices fire suppression pressure low audible warning SEE NOTES					Awaiting Parts			
SAFETY INSPECTION	27/09/2016	10:00	12/10/2016	15:20	73,383	Torquay	TO012228		
03 Instruments & Sensors 1	Emg Warning Devices fire suppression pressure low audible warning SEE NOTES								
16 Suspension 1	Slipper pads split on rear spring WARRANTY								
17 Tyres Replace	O/S/R outer tyre nailed MERC TO REPLACE WHEN WHEEL OFF								
18 Wheels Check Torques									
24 Driveshaft 1	Major oil leak from input seal on diff WARRANTY								
34 Lights	replaced rear fog light								
34 Lights Bulb Replacement	repl;aced bulb in glove box								
71 Body Exterior 1	Checklist Defect Accident damage down N/S SENT TO BODYSHOP					Awaiting Body Repair			
71 Body Exterior Acc Repair	Electrical Auxs Side step does not deploy correctly TEMP REPAIR BODYSHOP								
85 Body Interior 1	Scoop stowage buckle cracked PARTS ORDERED								
85 Body Interior 2	Scoop upper shelf stowage strap missing buckle PARTS Ordered								
87 Chairs	Body Interior Carry chair catch not working adjusted Ordered new bracket								
Safety Inspection									
93 - D Service	Merc Exeter completing vehicle side of D service								
Service D									

Vehicle Deep Clean	27/09/2016	13:13	28/09/2016	09:43	73,383	Torquay	TO012230
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/10/2016	14:08	20/10/2016	14:21	74,817	Torquay	TO012338
34 Lights Bulb Replacement	replaced day running bulb o\s						
SAFETY INSPECTION	07/11/2016	08:26	07/11/2016	13:36	77,466	Torquay	TO012405
02 Cab Assembly 1	fitted new floor mats						
02 Cab Assembly 2	resequired cab center cupboard stay rams						
16 Suspension 1	replaced rear spring packer o\s\r rear						
18 Wheels Check Torques							
45 Engine Oil Top Up	topped up oil level .5ltr						
52 Electrical Aux	removed sat anv gracket and repaired						
86 Doors	Ordered side door upper plunger kit						Awaiting Parts
86 Sliding Door	straightened side door top magnet bracket						
Safety Inspection							
Supply Snow Sox to Vehicle	replaced snow sox						
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill						
Vehicle Deep Clean	07/11/2016	11:40	08/11/2016	11:50	77,466	Torquay	TO012412
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	17/11/2016	09:45	18/11/2016	14:41	79,004	Torquay	TO012461
86 Doors Rear	O/S/R door stay centre bolt snapped - Raised warranty form						Awaiting Warranty
Unplanned Repair	24/11/2016	09:15	24/11/2016	10:40	79,892	Torquay	TO012492
86 Doors Rear	replaced bolt in o\s\r rear door stay bar						

SAFETY INSPECTION	19/12/2016	10:14	20/12/2016	15:07	84,170	Torquay	TO012610
13 Brake Pads	replaced front pads and sensors						
18 Wheels Check Torques							
45 Engine Oil Top Up	topped up oil level 1ltr						
86 Doors	Ordered side door upper plunger kit						
Safety Inspection							
MOT Pre Test							
Travel Time							
MOT							
Vehicle Deep Clean	19/12/2016	13:24	20/12/2016	13:55	84,170	Torquay	TO012613
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/01/2017	09:48	31/01/2017	14:37	90,681	Torquay	TO012798
02 Cab Ass Fire Extinguisher	replaced both cab and body extinguisher						
17 Tyres	ATS fitted part worn on n\s\l						
18 Wheels Check Torques							
45 Engine 1	replaced a\c belt tentioner						
Safety Inspection							
Medical Device and Equip Chec							
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	31/01/2017	06:45	31/01/2017	13:11	90,681	Torquay	TO012806
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	05/02/2017	15:33	06/02/2017	12:05	91,396	Torquay	TO012833
55 Tail Lift	Hyd leak from tail lift SWL WARRANTY						
Breakdown	rear ramp not go back						

Unplanned Repair	08/03/2017	12:07	08/03/2017	13:36	96,290	Torquay	TO012976
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

34 Lights Bulb Replacement	replaced o/slf side light bulb
----------------------------	--------------------------------

SAFETY INSPECTION	13/03/2017	07:57	14/03/2017	09:51	97,245	Torquay	TO012984
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

13 Brake Pads	replaced rear pads
17 Tyres	replaced all tyres
18 Wheels	replaced damgaed check link
18 Wheels Check Torques	
34 Lights Bulb Replacement	replaced spare bulb in glove box
86 Sliding Door	straightened side door top magnet bracket
Safety Inspection	
Annual Heater Service	Annual Heater Service
Handbrake Cable Replacement	Replace rear handbrake cables not due still under WTY
UB Fire Suppression Service	not done rework required
Annual Air Con Service	Annual Air Condition Service

Vehicle Deep Clean	14/03/2017	08:33	14/03/2017	14:06	97,245	Torquay	TO012992
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	16/03/2017	09:53	21/03/2017	15:12	97,451	Torquay	TO013007
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

45 Engine 1	EML light on exhaust sensor fault
-------------	-----------------------------------

Unplanned Repair	28/03/2017	08:01	28/03/2017	08:05	98,602	Torquay	TO013044
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

34 Lights Bulb Replacement	replaced light that oo's changed
----------------------------	----------------------------------

SAFETY INSPECTION	25/04/2017	08:36	28/04/2017	07:57	103,230	Torquay	TO013158
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
34 Lights Bulb Replacement	replaced missing bulb in glove box
86 Sliding Door	straightened side door top magnet bracket
Safety Inspection	

WAS Firetrace rework & Service Been carried out 27/04/17
Gearbox Oil & Filter Change

Vehicle Deep Clean	26/04/2017	07:11	26/04/2017	14:08	103,230	Torquay	TO013168
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	12/05/2017	08:47	12/05/2017	15:03	105,416	Torquay	TO013234
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Doors	Side door lower bearings tight - Raised form	Awaiting Warranty
86 Sliding Door	Side door not opening from outside - Repaired NOTES	

Unplanned Repair	16/05/2017	09:01	16/05/2017	09:07	106,053	Torquay	TO013248
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Battery Comms	Replaced batt
56 Comms Power Failure	Checked system found unsteady voltage on comms batt REPLACED SEE NOTES

BREAKDOWN	19/05/2017	14:54	24/05/2017	15:16	106,551	Torquay	TO013266
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	EML light on, cutting out and difficult to start
-------------	--

SAFETY INSPECTION	06/06/2017	08:12	07/06/2017	08:17	108,797	Torquay	TO013336
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
86 Doors	replaced passenger door window switch
86 Sliding Door	straightened top magnet bracket
Safety Inspection	
93 - D Service	
Service D	

Vehicle Deep Clean	07/06/2017	07:38	07/06/2017	13:51	108,797	Torquay	TO013344
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	26/06/2017	08:00	26/06/2017	15:53	111,505	Torquay	TO013417
86 Doors	Doors Saloon side door will not stay open.						
86 Sliding Door	Doors Saloon side door won't open from outside.						
MGS Gas Storage Modifications	30/06/2017	08:11	30/06/2017	08:18	111,863	Torquay	TO013447
MGS Gas Storage Modifications	MGS Gas Storage Modifications						
Unplanned Repair	30/06/2017	13:54	30/06/2017	15:27	111,957	Torquay	TO013457
02 Mirrors	replaced n\s mirror glass						
SAFETY INSPECTION	17/07/2017	08:40	18/07/2017	14:04	114,932	Torquay	TO013534
02 Cab Assembly 1	replaced knob on center cupboard in cab						
13 Brakes 1	replaced front pads and discs and sensors						
18 Wheels Check Torques							
55 Ramp	stuck on slow close and no LEDS on platform						
56 Comms Equipment	replaced mounting bracket for sat nav on dash						
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Vehicle Deep Clean	18/07/2017	07:19	18/07/2017	11:51	114,932	Torquay	TO013540
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	28/07/2017	14:43	28/07/2017	15:24	116,341	Torquay	TO013599
86 Doors	adjusted side door cables to allow entry from outside						
BREAKDOWN	31/07/2017	08:00	31/07/2017	16:37	116,545	Torquay	TO013602
55 Ramp	Body Exterior Offside ramp hand-rail bent notes						
86 Sliding Door	Body Exterior Side door will not open notes						

BREAKDOWN	01/08/2017	08:06	01/08/2017	11:46	116,571	Torquay	TO013608
86 Sliding Door	side door needs fine adjustment						
BREAKDOWN	18/08/2017	08:03	18/08/2017	14:45	119,436	Torquay	TO013697
02 Windows/Glass	Body Exterior Rear nearside saloon window broken.						
SAFETY INSPECTION	29/08/2017	09:35	31/08/2017	13:22	121,084	Torquay	TO013736
01 Air Conditioning 1	rear condenser fan blowing fuses needs WTY repair					Awaiting Warranty	
02 Cab Assembly 1	tightened sat nav mounting bracket on dash						
11 Axle Rear	replaced x2 anti roll bushes lower						
13 Brakes 1	replaced rear discs and pads						
17 Tyres	replaced all tyres						
18 Wheels Check Torques							
31 Battery Chassis	replaced chassis battery						
71 Body External W&T Repair	replaced n\s lf lower corner cap and sprayed in scratches down side						
86 Sliding Door	straightened side door bracket and reglued bump cover						
Safety Inspection							
Vehicle Deep Clean	30/08/2017	07:38	30/08/2017	13:52	121,084	Torquay	TO013741
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	11/09/2017	07:13	14/09/2017	15:30	122,930	Torquay	TO013798
01 Air Conditioning 1	rear condenser fan blowing fuses needs WTY repair						
16 Suspension 1	Other ?shock absorber warn						
71 Body Exterior 1	Checklist Defect Accident damage down N/S SENT TO BODYSHOP						
86 Doors	Side door lower bearings tight - Raised form						
86 Doors Rear	O/S/R door stay centre bolt snapped - Raised warranty form						
Road Test							

Unplanned Repair	02/10/2017	13:24	02/10/2017	14:52	126,023	Torquay	TO013909
02 Mirrors	replaced mirror glass n\s						
SAFETY INSPECTION	09/10/2017	08:26	10/10/2017	14:57	127,063	Torquay	TO013937
01 Heating 1	heater exhaust pipe broken WTY ESpar done made repare to cab center cupboard						
02 Cab Assembly 1							
18 Wheels Check Torques							
52 Electrical Aux	replaced auto eject cover made repare to ramp guides x2 and reseaired straightened side door magnet bracket						
55 Ramp							
86 Sliding Door							
Safety Inspection							
92 - C Service							
Service C							
Vehicle Deep Clean	10/10/2017	08:40	10/10/2017	14:13	127,063	Torquay	TO013947
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	31/10/2017	10:20	01/11/2017	11:31	130,354	Torquay	TO014031
17 Tyres	ATS to replaced tyre two(rear driver side) tyres flat						
Breakdown							
BREAKDOWN	06/11/2017	08:45	10/11/2017	12:16	131,155	Torquay	TO014060
31 Charging System	Alternator light on WTY						
Defect Repair	17/11/2017	07:00	17/11/2017	07:59	132,192	Torquay	TO014112
71 Body External Steps	Body Exterior Side step damaged. Not working						
SAFETY INSPECTION	17/11/2017	08:18	21/11/2017	15:20	132,192	Torquay	TO014113

16 Suspension 1	Slight lift in both front ball joints MONITOR
18 Wheels Check Torques	
45 Engine 1	Engine oil leaks SEE NOTES
55 Tail Lift	O/S hand rail loose and bent
71 Body Exterior 1	Bridge plate guides insecure REPAIRED
85 Body Interior 1	Track cupboard door stop insecure secured
86 Sliding Door	Door stop bent REPAIRED
Safety Inspection	
MOT Pre Test	
Travel Time	
MOT	

Vehicle Deep Clean	20/11/2017	10:37	20/11/2017	14:28	132,192	Torquay	TO014122
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	08/12/2017	18:14	13/12/2017	10:19	134,034	Torquay	TO014220
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1 Breakdown	EML light on gone to MERC EX limp mode
--------------------------	---

Emergency Deep Clean	15/12/2017	09:37	15/12/2017	11:45	134,368	Torquay	TO014249
-----------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Emergency Deep Clean	
----------------------	--

Unplanned Repair	29/12/2017	13:25	29/12/2017	13:29	136,924	Torquay	TO014311
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	replaced wiper blades
----------------------	-----------------------

Vehicle Deep Clean	03/01/2018	08:24	04/01/2018	11:22	137,882	Torquay	TO014322
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	03/01/2018	12:22	03/01/2018	12:25	137,616	Torquay	TO014323
34 Lights Bulb Replacement	replaced bulb in glove box						
SAFETY INSPECTION	04/01/2018	09:12	05/01/2018	15:21	137,882	Torquay	TO014330
02 Cab Ass Fire Extinguisher	replaced cab and body fire extinguishers						
18 Wheels Check Torques							
24 Driveshaft 1	replaced rear prop short						
45 Engine Oil Top Up	topped up oil level 1ltr						
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Unplanned Repair	15/01/2018	09:07	15/01/2018	12:00	138,602	Torquay	TO014379
34 Lights Bulb Replacement	replacde bulb in glove box						
Vehicle Deep Clean	13/02/2018	07:06	14/02/2018	13:08	144,184	Torquay	TO014525
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/02/2018	08:37	13/02/2018	15:54	144,184	Torquay	TO014526
17 Tyres	replaced n\s\f						
18 Wheels Check Torques							
52 Electrical Aux	replaced gronit						
55 Ramp	replace led on ramp stake safety rall and freed						
85 Body Interior 1	reflex edging on door						
85 Body Interior 2	replace strap non cupboard						
Safety Inspection							
85 Body Int Alcohol Gel Dispen							
93 - D Service							
Service D							
Unplanned Repair	19/02/2018	10:38	19/02/2018	14:15	144,657	Torquay	TO014551

34 Lights Bulb Replacement sid lights replaced

Unplanned Repair **21/02/2018** **10:57** **21/02/2018** **11:02** **144,657** **Torquay** **TO014560**

34 Lights Bulb Replacement replaced head light bulb and inderactor bulb

Unplanned Repair **23/02/2018** **09:34** **23/02/2018** **12:03** **145,263** **Torquay** **TO014576**

01 Heating 1 Body Interior heater not working investergate reset

Defect Repair **19/03/2018** **12:05** **19/03/2018** **12:10** **148,720** **Torquay** **TO014694**

01 Heating 1 Electrical Auxs Saloon Heater not working
Annual Heater Service Annual Heater Service

SAFETY INSPECTION **29/03/2018** **14:25** **03/04/2018** **08:32** **150,353** **Torquay** **TO014745**

02 Cab Assembly 1 cab cupboard hinge adrif resecured
13 Brake Pads replaced front and rear pads and sensors
17 Tyres replaced o\s\f and n\s\r tyres
18 Wheels Check Torques
34 Lights replaced both ady running lights
45 Engine 1 replaced gromit in bulk head
52 Electrical Aux resecured wiring to patsient unit
86 Doors tightened side door lock assembly and adjusted
86 Sliding Door straightened side door top magnet bracket
89 Seats tightened salloon seat arms x2
Safety Inspection
Supply Snow Sox to Vehicle fitted new snow sox
Fit Poster Holder Fit Poster Holder
Wheel Hub Flanges Replaceme
Handbrake Cable ReplacementReplace rear handbrake cables
UB Fire Suppression Service

BREAKDOWN **29/04/2018** **06:16** **07/05/2018** **12:17** **154,854** **Torquay** **TO014886**

45 Engine 1 Turbo failed

Breakdown loud bang and loss of power
 Gearbox Oil & Filter Change merc doing wile in with them

SAFETY INSPECTION 14/05/2018 08:47 15/05/2018 09:30 156,607 Torquay TO014951

11 Axle Front	Lift in ball joints	Monitoring
17 Tyres Replace	OSR tyres renewed	
18 Wheels Check Torques		
34 Emergency Light System	NS wing strobe renewed	
43 Exhaust System 1	Reposition tailpipe	
71 Body Exterior 1	Spray supression insecure	
71 Body External Steps	Side step freed pff	
Safety Inspection		
Annual Air Con Service	Annual Air Condition Service	

Vehicle Deep Clean 15/05/2018 10:06 15/05/2018 10:08 156,607 Torquay TO014953

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean 15/05/2018 10:09 15/05/2018 14:28 156,607 Torquay TO014954

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN 29/05/2018 07:40 29/05/2018 12:16 157,285 Torquay TO015002

56 Comms Equipment Satnav will not power up WARRANTY PCE DONE

Unplanned Repair 31/05/2018 11:35 01/06/2018 12:29 157,431 Torquay TO015024

56 Comms Equipment MDT not powering up PCE to look at

Unplanned Repair 13/06/2018 13:28 13/06/2018 15:25 158,984 Torquay TO015084

02 Mirrors replaced broken mirror parts

SAFETY INSPECTION	20/06/2018	13:10	22/06/2018	15:00	160,260	Torquay	TO015111
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	replaced fire exting in body
13 Brakes 1	replaced brake pedal rubber
18 Wheels Check Torques	
45 Engine Oil Top Up	topped up engine oil level 1.5ltrs
86 Doors Rear	replaced rear door stay bar block
Safety Inspection	
Tail Lift 6 Monthly Inspection	Statutory Inspection fitted new telescopic arm o\s

Vehicle Deep Clean	21/06/2018	09:00	21/06/2018	14:32	160,260	Torquay	TO015117
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	18/07/2018	09:15	18/07/2018	16:09	165,032	Torquay	TO015221
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Doors	Doors outside locker door, handle broke, and adjust cables
----------	--

SAFETY INSPECTION	31/07/2018	11:15	01/08/2018	11:17	167,378	Torquay	TO015272
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	replaced torch battery x1
02 Mirrors	replaced broken parts on both mirrors
17 Tyres	replaced n\s\l and n\s\r tyres x3
18 Wheels Check Torques	
31 Charging System Battery	traced and retified drop dwn charging fault
34 Lights Bulb Replacement	replaced o\s wing indercator bulb + head light bulb in glove box
71 Body External Steps	removed and adjusted side step support bracket
86 Sliding Door	adgusted side door height and tightened side door lock assembly
Safety Inspection	
92 - C Service	
Service C	
MOT Pre Test	

Vehicle Deep Clean	01/08/2018	14:44	02/08/2018	08:44	167,378	Torquay	TO015277
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

ACCIDENT	29/08/2018	10:17	14/09/2018	13:19	171,584	Torquay	TO015413
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body Exterior Acc Repair	right side glass panel smashed and side boby damage
-----------------------------	---

SAFETY INSPECTION	14/09/2018	09:39	20/09/2018	15:52	171,669	Derriford	DE025021
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Mirrors	renewed ns backing
11 Axle Front	Lift in ball joints
18 Wheels Check Torques	
34 Lights Bulb Replacement	renewed nsf side light bulb
43 Exhaust System 1	tail pipe renewed
86 Door Seals	renewed osf
Safety Inspection	
Travel Time	
MOT	Done by A J Motors P/O 151176766

Vehicle Deep Clean	21/09/2018	08:31	21/09/2018	12:05	171,682	Derriford	DE025066
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	04/10/2018	12:21	05/10/2018	14:59	173,189	Torquay	TO015565
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	replaced bulb in glove box
----------------------------	----------------------------

SAFETY INSPECTION	23/10/2018	07:22	24/10/2018	08:50	176,875	Torquay	TO015648
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	Centre console held on by 1 screw and asque
02 Cab Assembly 2	GPS holding snapped on dash. Dash fascia broken.
13 Brake Pads	Carrier sliders siezed. strip and free up
13 Brakes 1	front disc and pad replacement
13 Brakes 2	rear discs and pads replacement
15 Steering 1	O/S track rod very minor play - MONITOR
17 Tyres Replace	O/S rear tyres to be replaced
18 Wheels Check Torques	
45 Engine 1	Intercooler to turbo pipe oil leak - MONITOR

55 Tail Lift	Lift guides broken x 2						
71 Body Exterior 1	N/S fog surround missing - AWAITING PARTS-						
71 Body Exterior 2	Replace n/s fog surround						
85 Body Interior 1	NEB securing strap broken						
Safety Inspection							
Vehicle Deep Clean	25/10/2018	14:19	25/10/2018	14:21	176,875	Torquay	TO015667
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	16/11/2018	08:18	16/11/2018	08:21	177,138	Torquay	TO015752
34 Lights Bulb Replacement	Adding blown headlight bulb as part						
BREAKDOWN	23/11/2018	12:17	23/11/2018	13:10	180,827	Torquay	TO015795
34 Emergency Lights	Quadflash light unit damaged. Replaced and crimped on terminals.						
Unplanned Repair	26/11/2018	09:17	26/11/2018	10:39	181,383	Torquay	TO015801
86 Sliding Door	adjust door mechanism						
Breakdown	01/12/2018	22:27	03/12/2018	09:57	182,025	Torquay	TO015834
Breakdown	FIRE SUPP UNIT PREVENTING START. checked all ok ???						
SAFETY INSPECTION	03/12/2018	08:11	04/12/2018	12:13	182,105	Torquay	TO015836
17 Tyres	nail in n/s r outer.						
18 Wheels Check Torques							
34 Lights Bulb Replacement	missing spare bulb and sidelight out						
45 Engine 1	small leak from egr area						
45 Engine Oil Top Up							
71 Body Exterior 2	slight play in N/S lower ball joint						
71 Body External Steps	small mudflap torn						

85 Body Interior 1	in cab central cupboard hinges not attached.
85 Body Interior 2	
85 Body Interior 3	
86 Door Lock	slide door magnet bracket loose
86 Sliding Door	runners lubricated
89 Seatbelts	saloon seat 2 anchor for seatbelt loose
89 Seats	saloon rear facing seat clips to stow away child restraints broken. sharp.
MDT Failure/Issue	coming away from dash. dismantle fascia and bolt back inplace
Safety Inspection	
Sealing of stretcher clamp	Sealing of stretcher clamp
Tail Lift 6 Monthly Inspection	Statutory Inspection
Tail Lift Annual Service	Statutory Inspection and Weight Test

Vehicle Deep Clean	03/12/2018	13:54	04/12/2018	14:16	182,105	Torquay	TO015840
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	24/12/2018	08:44	24/12/2018	13:28	184,634	Torquay	TO015947
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	Electrical Auxs Elec fault & repeated audible warning notes
-------------	---

Unplanned Repair	31/12/2018	14:06	10/01/2019	14:17	185,665	Torquay	TO015972
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	engine fault. gone to dealer checked over and codes
71 Body External Steps	external step not correctly deploying and getting stuck.

SAFETY INSPECTION	10/01/2019	07:56	11/01/2019	07:17	185,710	Torquay	TO016018
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	passenger torch not charging. Gently adjusted pins
02 Windows/Glass	sliding door window seal coming away from window approx 40%. resecured
17 Tyres	replaced o/s\f tyre
18 Wheels Check Torques	
34 Lights	sidelight fallen out of holder. retrieve and replace. headlight bulb insecure.
34 Lights Bulb Replacement	replace spare bulb
55 Tail Lift	o/s handrail stiff on stanchion and loose at base
86 Doors Rear	door stay bar very bent
86 Sliding Door	upper latch cover loose. adjusted and tightened

Safety Inspection Fit 3rd Helmet Restraint 93 - D Service Service D	Fit 3rd Helmet Restraint in Cab						
Vehicle Deep Clean	11/01/2019	08:20	11/01/2019	13:51	185,710	Torquay	TO016025
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	14/01/2019	08:41	14/01/2019	08:47	185,948	Torquay	TO016032
71 Body External Steps	Body Exterior side step u/s. REPAIRED						
Breakdown	24/01/2019	07:23	24/01/2019	09:54	187,110	Torquay	TO016094
71 Body External Steps Breakdown	made repair to step after hitting rock side step half deploying						
Breakdown	29/01/2019	11:42	29/01/2019	13:58	187,664	Torquay	TO016110
45 Engine 1 Breakdown	engine fault. scanned for codes. NOTE Engine warning light						
Unplanned Repair	04/02/2019	09:58	04/02/2019	14:52	187,865	Torquay	TO016130
33 Ignition System	replaced battery in key fob						
Unplanned Repair	05/02/2019	15:28	06/02/2019	08:40	188,027	Torquay	TO016141
31 Battery Chassis	INTERMITTANT BATTERY FAULT replaced chassis battery						
BREAKDOWN	12/02/2019	18:21	15/02/2019	07:56	188,919	Torquay	TO016161

45 Engine 1 Breakdown	checked and found multiple codes multiple faults going to Merc EX amber EML
--------------------------	--

Vehicle Deep Clean	26/02/2019	08:57	26/02/2019	13:14	190,928	Torquay	TO016221
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	27/02/2019	07:13	28/02/2019	14:38	190,928	Torquay	TO016226
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

15 Steering 1	Steering Rack upper seal allowing fluid leak
15 Steering 2	both lower arm ball joints req replacement - AWAIT PARTS
17 Tyres Replace	2 x tyres replaced
18 Wheels Check Torques	
34 Emergency Lights	O/S upper quad flash blue inop
34 Lights	N/S wing mount indicator broken.
42 Coolant System	expansion bottle replaced
55 Tail Lift	bridge guides loose - TIGHTENED
56 Comms Equipment	fist radio wires damaged. AWAIT PCE for repair
85 Body Interior 1	cupboard interior plastic trim broke - sharp edge. FILED FLAT AND SMOOTH
86 Doors Rear	door hinge pin notchy when door is opened - LUBRICATED
86 Sliding Door	top magnet stay bent - STRAIGHTENED
Medical Devices Service	ecs battery 1 on 32% - REPLACED
Safety Inspection	

SAFETY INSPECTION	04/04/2019	09:13	10/04/2019	15:03	196,201	Torquay	TO016410
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	expiration date up	
02 Cab Assembly 1	driver torch not charging	
13 Handbrake	o/s wheel cylinder 8mm adjustment siezed	
16 Suspension 1	both lower ball joints need replacing. Merc doing	Done
17 Tyres Replace	nail in osr inner tyre - replace 2 to keep treads matched depth	
18 Wheels Check Torques		
34 Lights	both sidelight inop	
41 Turbo	turbo leaking oil- merc warranty poss breather issue got to keek eye on it	Monitoring
45 Engine Oil Top Up	oil low	
71 Body External W&T Repair	Body Exterior Rear wheel arch damage	
86 Doors Rear	play in rear door bottom hinge	Monitoring
86 Sliding Door	top magnet does not secure door.	
87a - Medical Equipment Repairecs	battery 2 below 70%	

89 Seats
 Safety Inspection
 UB Fire Suppression Service

saloon seat 2 lock does not engage automaticly

Vehicle Deep Clean	04/04/2019	09:18	04/04/2019	11:58	196,201	Torquay	TO016411
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	15/04/2019	15:25	16/04/2019	08:18	196,873	Torquay	TO016467
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	replaced washer check valve
----------------------	-----------------------------

Unplanned Repair	14/05/2019	13:23	14/05/2019	15:50	201,368	Torquay	TO016585
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

89 Seats	seat swivel pin fallen off and roll pin missing.
----------	--

Unplanned Repair	17/05/2019	11:49	17/05/2019	11:59	201,921	Torquay	TO016598
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors 54 Reversing Systems	replace compete arm inc mirror and casings rear camera bent into body
------------------------------------	--

Vehicle Deep Clean	20/05/2019	08:20	20/05/2019	14:11	202,337	Torquay	TO016603
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	20/05/2019	14:55	23/05/2019	15:25	202,337	Torquay	TO016611
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brake Pads	replace front and rear pads
16 Suspension 1	replace both rear spring eye bushes
16 Suspension 2	replace both rear A. R. B
16 Suspension 3	replace o/s susp packer
18 Wheels Check Torques	
86 Doors	replaced passenger side window switch
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
Annual Heater Service	Annual Heater Service
Axle Oil Change	Axle Oil Change

Engine Change Oil & Filter DONE
Tail Lift Inspection DONE

Unplanned Repair 24/05/2019 15:08 24/05/2019 15:47 202,355 Torquay TO016628

13 Brakes 1 brake warning on dash. Recently had brake D+P. NOTE

ACCIDENT 13/06/2019 09:29 19/06/2019 08:06 205,193 Torquay TO016713

02 Windows/Glass other side rear window broken ordered glass

BREAKDOWN 01/07/2019 09:29 05/07/2019 12:29 207,723 Torquay TO016787

45 Engine 1 Engine rattel and leaking water

SAFETY INSPECTION 04/07/2019 15:43 05/07/2019 15:07 207,749 Torquay TO016815

02 Cab Ass Fire Extinguisher replaced body fire exting date up
17 Tyres replaced n\s\l f tyre
18 Wheels Check Torques
71 Body External Steps straightened side step under suport bar
71 Body External W&T Repair made repair and sprayed around side door and rear top blue light
86 Sliding Door straightened side door magnet bracket
Safety Inspection

Vehicle Deep Clean 08/07/2019 07:30 08/07/2019 13:27 207,806 Torquay TO016823

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair 11/07/2019 12:36 11/07/2019 15:25 208,212 Torquay TO016850

45 Engine 1 aux belt adrift removed broken belt and replaced checked all pullys ok?

Breakdown 12/07/2019 16:59 15/07/2019 08:51 208,403 Torquay TO016864

Breakdown not plotting - out of area

BREAKDOWN	02/08/2019	13:17	06/08/2019	10:02	211,414	Torquay	TO016969
42 Coolant System	Viscous fan fallen off Ordered New						
BREAKDOWN	12/08/2019	14:16	12/08/2019	15:59	212,289	Torquay	TO017001
52 Electrical Aux	solid yellow eml - SRS red						
SAFETY INSPECTION	14/08/2019	09:52	15/08/2019	09:17	212,614	Torquay	TO017007
13 Handbrake	no reserve travel on handbrake lever						
18 Wheels Check Torques							
34 Lights	sidelight missing from headlight unit.						
34 Lights Bulb Replacement	spare bulb missing						
45 Engine Oil Top Up	require top up						
52 Electrical Aux	EML on dash						
55 Tail Lift	bridge guides loose						
71 Body Exterior 1	o/s rear arch damage						
71 Body External Steps	small mudflap missing						
89 Seats	saloon seat 2 swivel release pin loose - req tightening						
MOT							
Safety Inspection							
Travel Time							
Tail Lift Inspection							
Brakes Replace Brake Fluid							
Vehicle Deep Clean	14/08/2019	12:09	15/08/2019	11:33	212,614	Torquay	TO017008
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	18/09/2019	15:08	19/09/2019	15:17	217,825	Torquay	TO017166
87 Stretcher	replaced stretcher battery						

Vehicle Deep Clean	24/09/2019	09:55	24/09/2019	13:28	218,782	Torquay	TO017183
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	25/09/2019	07:22	27/09/2019	12:25	218,782	Torquay	TO017187
02 Cab Ass Fire Extinguisher	replaced fire trace system after leak						
13 Brakes 1	brake fluid low						
13 Brakes 2	n/s f wheel very stiff. dismantle corner to determin cause.						
17 Tyres Replace	O/S F AND REAR AXLE TYRES ON 3MM						
18 Wheels Check Torques							
31 Battery Aux	key fob battery to be changed						
45 Engine 1	screenwash cap missing						
45 Engine Oil Top Up	oil on minimum mark						
52 Electrical Aux	crime prevention audible warning cont sounding NOTE						
55 Ramp	bridge guides loose						
55 Tail Lift	o/s handrail unable to be locked in the up position. ram also loose						
71 Body Exterior 1	multiple areas of body damage						
85 Body Interior 1	saloon storage cupboard strap broken						
85 Body Interior 2	lucas cupboard becoming detached from carcass						
86 Doors	sliding door very difficult to open from inside						
86 Sliding Door	top magnet bent						
89 Seatbelts	saloon seat 2 anchor point loose						
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
BREAKDOWN	27/09/2019	19:16	03/10/2019	10:46	218,920	Torquay	TO017207
42 Coolant System	radiator leak Merc to do						
Breakdown	big hole in radiator ; leaking						
Unplanned Repair	04/10/2019	12:20	04/10/2019	14:21	219,124	Torquay	TO017237
02 Cab Ass Fire Extinguisher	replaced and rewired fire trace pressure sensor						

Unplanned Repair	11/10/2019	11:13	11/10/2019	14:48	220,337	Torquay	TO017271
34 Lights 71 Body External Steps 89 Seats	tightened conections on n\s day running light removed and straightened step under support bar and refitted removed broken swivel locking pin and replaced kit						
Unplanned Repair	31/10/2019	11:40	31/10/2019	11:45	222,550	Torquay	TO017362
34 Lights Bulb Replacement	replace spare bulb in glovebox						
Breakdown	03/11/2019	15:48	04/11/2019	11:37	223,901	Torquay	TO017376
Breakdown	Drivers wing mirror cracked Doing on service 4-11-19						
SAFETY INSPECTION	04/11/2019	07:58	04/11/2019	14:43	223,907	Torquay	TO017377
02 Cab Assembly 1 02 Mirrors 13 Brake Pads 13 Brakes 1 13 Discs 13 Handbrake 16 Suspension 1 18 Wheels Check Torques 34 Emergency Lights 34 Lights 34 Lights Bulb Replacement 45 Engine Oil Top Up 85 Body Interior 1 85 Body Interior 2 Safety Inspection Tail Lift Inspection Tail Lift 12M Service & Weight	cab storage box button stuck down o/s big mirror smashed rear pads over 50% worn brake pedal smooth rear discs worn and lipped when replacing discs noticed n/s handbrake leading shoe very worn o/s r and n/s f packers on leaf springs 50% missing off each headlight spare bulb missing o/s sidelight not able to be seen in lamp - fallen out/back ? n/s sidelight inop compact track door jam coming away from carcass top magnet bent/not contactiong stay block Tail Lift 12M Service & Weight						
Vehicle Deep Clean	05/11/2019	08:38	05/11/2019	11:20	223,907	Torquay	TO017383
Vehicle Deep Clean	Vehicle Deep Clean						

BREAKDOWN	20/11/2019	05:21	20/11/2019	09:40	224,500	Torquay	TO017437
Breakdown Supply Sat Nav	SatNav failure replaced sat nav old one packed up supplied fitted and set up						
Unplanned Repair	20/11/2019	13:21	20/11/2019	13:24	225,836	Torquay	TO017443
34 Lights Bulb Replacement	replaced n\s wing indercator bulb						
BREAKDOWN	03/12/2019	11:31	03/12/2019	11:49	227,541	Torquay	TO017525
32 Starting System 1 56 Comms Power Failure 71 Body External Steps	crew saying vehicle start is hessitant crew saying MDT keeps booking off. step req attention, mishaped						
Vehicle Deep Clean	13/12/2019	08:49	13/12/2019	13:29	228,937	Torquay	TO017592
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/12/2019	14:35	17/12/2019	14:41	228,937	Torquay	TO017597
02 Mirrors 02 Windscreen Wipers 15 Steering 1 18 Wheels Check Torques 34 Lights 55 Ramp 55 Tail Lift 71 Body Exterior 1 71 Body External Steps 86 Sliding Door 89 Seats Safety Inspection Engine Change Oil & Filter Auto G/box Oil & Filter Change	o/s mirror frame broken req replacement camber adjustment req n/s + o/s (tyres wearing heavy outer edges) day light running bulb inop o/s handrail up/down slide function siezed bridge guides loose x 3 Body Exterior minor damage to REAR BODYWORK DRIVERS SIDE side step warning going off replaced step motor top magnet bent saloon seat 2 swivel pin assy loose						

Unplanned Repair	09/01/2020	08:06	09/01/2020	09:31	230,220	Torquay	TO017701
89 Seats	sliding assy jammed and lever broken off						
Vehicle Deep Clean	30/01/2020	09:14	30/01/2020	13:35	233,011	Torquay	TO017808
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/01/2020	15:12	31/01/2020	14:08	233,011	Torquay	TO017813
13 Brake Pads	replace front pads						
13 Discs	replaced front discs						
13 Handbrake	no reserve travel on handbrake						
16 Suspension 1	both A.R.B req replacement						
18 Wheels Check Torques							
34 Emergency Lights	n/s r upper blue light loose						
34 Lights Bulb Replacement	o/s high beam inop						
45 Engine Oil Top Up	top up required						
52 Electrical Aux	service light on						
71 Body Exterior 1	siren missing surround clips						
71 Body Exterior 2	arch trim missing fastners						
71 Body External Steps	side step crunchy						
89 Seats	driver seat cover torn, pad damaged						
Safety Inspection							
Tail Lift Inspection							
BREAKDOWN	02/02/2020	10:36	03/02/2020	15:10	233,100	Torquay	TO017818
Breakdown	central locking not working						
Unplanned Repair	03/02/2020	08:55	03/02/2020	15:03	233,199	Torquay	TO017825
17 Tyres	ATS to replace both front						
BREAKDOWN	03/02/2020	08:34	05/02/2020	15:05	233,199	Torquay	TO017838
17 Tyres Replace	replaced 1 punctured tyre with C/C tyre. matched across axle. so 2 were fitted						

BREAKDOWN	05/02/2020	07:42	05/02/2020	09:16	233,416	Torquay	TO017839
17 Tyres Replace	replace tyre NOTE.						
18 Wheels	replace cracked rim						
18 Wheels Retorque							
31 Battery Aux	replaced keyfob battery						
BREAKDOWN	10/02/2020	09:05	12/02/2020	15:52	234,116	Torquay	TO017865
15 Steering 1	steering rack leak						
33 Ignition System	replaced key battery						
45 Engine 1	Missfire and knocking ??!!						
Unplanned Repair	20/02/2020	13:41	20/02/2020	13:45	235,118	Torquay	TO017920
31 Battery Aux	aux battery showing 10.2 V on genysis						
86 Sliding Door	side door rollers competely siezed and digging a groove into runner						
Unplanned Repair	26/02/2020	12:35	26/02/2020	15:45	236,344	Torquay	TO017946
86 Door handle	replaced side door handle and adjusted cables and lock						
86 Sliding Door	replaced side door top mounting bracket with spare parts left over						
Unplanned Repair	06/03/2020	15:32	06/03/2020	15:36	237,029	Torquay	TO018003
17 Tyres	ats fitting x2 tyres n\s\r at ats depot						
Breakdown	07/03/2020	06:10	11/03/2020	13:51	237,086	Torquay	TO018004
Breakdown	F/N/S Puncture						
SAFETY INSPECTION	16/03/2020	13:24	17/03/2020	16:23	237,953	Torquay	TO018027

02 Cab Ass Fire Extinguisher cab extinguisher out of date
 02 Cab Assembly 1 in cab storage missing knob
 02 Windows/Glass n/s window switch missing button
 18 Wheels Check Torques
 45 Engine Oil Top Up top up req
 71 Body Exterior 1 small spray suppression missing
 86 Door Lock rear door (small) top lock stiff
 86 Door Seals side door window rubber hanging off. 50% loose
 86 Sliding Door top magnet bent
 87a - Medical Equipment Repair epcr cradle charging pins bent
 89 Seatbelts jany armrest loose
 89 Seats seat 1 armrest loose
 Safety Inspection

Vehicle Deep Clean	18/03/2020	09:51	18/03/2020	13:36	237,953	Torquay	TO018038
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	01/04/2020	08:26	01/04/2020	08:28	238,969	Torquay	TO018106
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Sliding Door	Doors Jammed. Top catch misaligned. - REPAIRED
-----------------	--

Unplanned Repair	02/04/2020	14:34	02/04/2020	15:49	239,029	Torquay	TO018117
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

85 Body Interior 1	checked for cctv warning removed swalf from roof strip and side buttons
--------------------	---

BREAKDOWN	06/04/2020	10:09	06/04/2020	15:15	239,337	Torquay	TO018136
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Water leaking into body on to seating checked Espar doing work
-----------------------	--

Unplanned Repair	07/04/2020	11:08	08/04/2020	07:20	239,351	Torquay	TO018148
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Sliding Door	door require adjustment - REPAIRED
-----------------	------------------------------------

BREAKDOWN	13/04/2020	08:21	13/04/2020	09:26	239,843	Torquay	TO018175
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Sliding Door	made repair to side door top lock and plate
-----------------	---

Breakdown	14/04/2020	22:39	15/04/2020	13:28	240,010	Torquay	TO018187
87a - Medical Equipment Repair	carried out checks and replaced patient unit charger BCV-1						
Breakdown	Various charging unit U/S/Battery check Req						
Unplanned Repair	16/04/2020	11:45	16/04/2020	15:29	240,077	Torquay	TO018199
Supply Sat Nav	checked for sat nav fault fitted spare						
Defect Repair	19/04/2020	13:36	19/04/2020	13:39	240,366	Torquay	TO018211
02 Mirrors	Mirrors N/S mirror cracked - replaced						
SAFETY INSPECTION	21/04/2020	09:58	24/04/2020	14:10	240,496	Torquay	TO018219
02 Cab Ass Fire Extinguisher	saloon extinguisher out of date - REPLACED						
17 Tyres Replace	OSR tyres 3mm - REPLACED						
18 Wheels	N/S rear wheel missing XTR - REPLACED WITH SPARE						
18 Wheels Check Torques							
56 Comms Equipment	aerial broken -REPLACED						
85 Body Interior 1	safe cupboard piano hinge coming away from carcass - REPAIRED						
85 Body Interior 2	patient control cupboard not closing - REMOVED OBJECTS BEHIND DRAWER						
86 Door Lock	locker door lock key static - WRIGGLED FREE						
86 Sliding Door	top magnet bent - ADJUSTED						
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
UB Fire Supp 12mts Service	Service of fire supression system						
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
Tail Lift Inspection							
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
Replace Handbrake Cables	Replace Handbrake Cables						
Vehicle Deep Clean	23/04/2020	11:17	24/04/2020	14:10	240,496	Torquay	TO018226
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	02/06/2020	08:03	03/06/2020	12:24	244,159	Torquay	TO018408
01 Air Conditioning 1	saloon A/C fan very noisy - bearings gone?					Monitoring	
02 Cab Assembly 1							
18 Wheels Check Torques	passenger window switch broken						
34 Lights Bulb Replacement							
45 Engine 1	spare bulb used						
45 Engine 2							
45 Engine Oil Top Up	Both engine mountings require replaceing					Monitoring	
71 Body Exterior 1							
71 Body Exterior 2	oil leak to ffront of EGR body - MON						
71 Body External Steps							
86 Door Hinges	top up req						
86 Door Lock							
86 Sliding Door	large spray suppression missing						
Medical Devices Check							
Safety Inspection	replaced bracked for reverse camera						
	step noisy - missing roller - replaced with spare and lubricated						
	side door top hinge pulling away from door						
	small door lock inop						
	top magnet de-magnetised						
	deep scratches on EPCR					Monitoring	
Vehicle Deep Clean	03/06/2020	07:42	03/06/2020	11:16	244,169	Torquay	TO018410
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/06/2020	10:01	08/06/2020	11:44	244,866	Torquay	TO018446
34 Lights	cleaned and adjusted o/s indercator lamp bulb holder						
Breakdown	20/06/2020	21:55	25/06/2020	09:27	246,371	Torquay	TO018521
Breakdown	power failing whenever engine turned off						
BREAKDOWN	12/07/2020	17:41	13/07/2020	12:37	249,088	Torquay	TO018590
31 Battery Comms	Coms battery fault replaced battery after checks						
Breakdown							
	Not charging from shoreline. check aerals						
Vehicle Deep Clean	13/07/2020	11:43	14/07/2020	13:55	249,088	Torquay	TO018593

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/07/2020	12:31	15/07/2020	15:52	249,088	Torquay	TO018595
02 Cab Assembly 1	knob and cupboard lose and missing						
13 Brake Pads	replaced rear pads						
18 Wheels Check Torques							
31 Charging System Battery	not charging off drop down traced fault to super auto ejc replaced all ok						
34 Lights	DRL fault replaced both bulbs ,blown and turned sysyem back on						
45 Engine Oil Top Up	topped up oil level 1.5 ltrs						
71 Body External Steps	step edge adrift removed cleaned and painted						
Safety Inspection							
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Tail Lift Inspection							
MOT							
Unplanned Repair	23/07/2020	10:51	23/07/2020	10:54	249,742	Torquay	TO018649
34 Lights Bulb Replacement	replaced bulb in glove box						
Unplanned Repair	04/08/2020	14:30	04/08/2020	16:03	251,769	Torquay	TO018705
34 Lights	removed and cleaned contacts on wing indercator and refitted						
BREAKDOWN	07/08/2020	10:30	07/08/2020	15:37	252,204	Torquay	TO018728
31 Charging System	Alternator warning light on REPLACED UNIT						
45 Engine 1	Engine oil leaks around alternator/ intercooler/ throttle body CLEANED MONITOR						
Unplanned Repair	11/08/2020	11:40	11/08/2020	11:42	252,925	Torquay	TO018746
Supply Sat Nav	carred out check as to Y sat nav not ploting						
BREAKDOWN	13/08/2020	14:40	24/08/2020	12:30	252,952	Torquay	TO018760
02 Mirrors	Mirror glass smashed REPLACED						
45 Engine 1	Poss turbo/timing chain						

45 Engine 2 oil leak to ffront of EGR body - MON

SAFETY INSPECTION **24/08/2020** **14:34** **28/08/2020** **16:00** **253,270** **Torquay** **TO018793**

01 Air Conditioning 1 saloon A/C fan very noisy - bearings gone?
 15 Steering 1 Pump damp MONITOR
 16 Suspension 1 U blots loose both sides REPAIRED
 18 Wheels Check Torques
 34 Lighting System Right wing ind inop REPAIRED FITTING
 52 Electrical Aux 240v led cracked/pushed through MONITOR NO STOCK
 71 Body Exterior 1 Rear spray supression insecure REPAIRED
 71 Body External Steps Side step not deploying REPAIRED
 86 Sliding Door Side door alarm inop REPAIRED
 Medical Devices Check deep scratches on EPCR
 Safety Inspection
 Engine Change Oil & Filter NEW engine fitted

Vehicle Deep Clean **25/08/2020** **16:00** **27/08/2020** **13:56** **253,270** **Torquay** **TO018794**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **04/09/2020** **10:45** **04/09/2020** **10:49** **253,941** **Torquay** **TO018836**

34 Lights Bulb Replacement Other side indicator bulb out replaced both wing bulbs

ACCIDENT **26/09/2020** **13:45** **06/11/2020** **15:42** **257,614** **Torquay** **TO018937**

17 Tyres supply wheel and tyre to be able to move at compound

Vehicle Deep Clean **06/11/2020** **14:36** **09/11/2020** **11:04** **257,742** **Torquay** **TO019155**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **06/11/2020** **15:45** **06/11/2020** **15:46** **257,742** **Torquay** **TO019156**

18 Wheels Check Torques
Safety Inspection

linked over due

SAFETY INSPECTION **06/11/2020** **15:46** **11/11/2020** **14:02** **257,742** **Torquay** **TO019157**

02 Cab Assembly 1 replaced dash surround around radio
02 Cab Assembly 2 replaced passenger foot plate cover and suport & tightened cupboard hinge
17 Tyres Replace nsf tyre 3mm, keep osf on shelf for spare
18 Wheels wheel rim cracked
18 Wheels Check Torques
43 Exhaust System 1 temp sensor burnt on exhaust
52 Electrical Aux 240v inverter faulty
86 Sliding Door side door magnet bracket bent straightened
87a - Medical Equipment Repaireplaced EPCR battery no 1
Safety Inspection
Tail Lift Inspection
UB Fire Supp 6mts Service UB Fire Supp 6mts Service

Unplanned Repair **11/11/2020** **14:36** **12/11/2020** **07:16** **257,746** **Torquay** **TO019183**

MDT Failure/Issue not turning on - NOTES

Vehicle Deep Clean **18/11/2020** **06:00** **18/11/2020** **11:52** **258,836** **Torquay** **TO019225**

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN **04/12/2020** **14:05** **11/12/2020** **08:49** **261,069** **Torquay** **TO019323**

55 Ramp suspect ramp motor failed SWL looking at

SAFETY INSPECTION **05/01/2021** **08:01** **06/01/2021** **14:33** **264,121** **Torquay** **TO019506**

02 Cab Assembly 1 storafge box hinge not affixed - RESECURED
02 Cab Assembly 2 torch missing - NO PARTS Awaiting Parts
02 Windscreen driver window switch broken - REPLACED

02 Windscreen Wipers	require replacement - REPLACED
13 Brakes 1	os rear pads missing shims - DISMANTLED AND REPLACED WITH SPARES
16 Suspension 1	both A.R.B worn - REPLACED
17 Tyres Replace	rear tyres below trust limit - REPLACED WITH C/C + CHANGED PRESSURE MARKERS
18 Wheels Check Torques	
34 Emergency Lights	OS SCENE LIGHT INOP - REPLACED
34 Lights	os front amber marker marker inop - REPLACED
34 Lights Bulb Replacement	spare bulb - REPLACED
71 Body External Steps	small mud flap torn badly - REPLACED
85 Body Interior 1	dressings cupboard strap broken - RESECURED
86 Door Hinges	side door wiring holder broken free from door - RESECURED
86 Sliding Door	door inop from outside - REPAIRED
Safety Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight 6mth done contractor not available

Vehicle Deep Clean	06/01/2021	07:37	06/01/2021	13:50	264,121	Torquay	TO019515
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	06/02/2021	09:21	06/02/2021	09:45	267,728	Torquay	TO019708
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Sliding Door	side door lock jammed - NOTE
-----------------	------------------------------

Defect Repair	06/02/2021	09:24	06/02/2021	09:45	267,728	Torquay	TO019709
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	ns big mirror cracked - REPLACED
31 Battery Chassis	Electrical Auxs constant power fail - NOTE

Defect Repair	06/02/2021	09:28	08/02/2021	13:57	267,728	Torquay	TO019710
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lighting System	Other rear brake light out - NOTE traced fault in main lume repaired
--------------------	--

Vehicle Deep Clean	09/02/2021	07:53	09/02/2021	13:24	267,728	Torquay	TO019725
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	09/02/2021	13:46	10/02/2021	12:04	267,728	Torquay	TO019731
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	cab extinguisher date up - REPLACED
------------------------------	-------------------------------------

02 Cab Assembly 1	driver torch missing - NO PARTS						
02 Cab Assembly 2	cab storage box hinge bent - REPAIRED						
02 Windscreen Wipers	ordered new wiper linkage						
13 Brake Pads	rear pads below 50% - REPLACED						
18 Wheels Check Torques							
34 Lights Bulb Replacement	NS DRL inop - REPLACED BULB						
86 Sliding Door	side door roller bearings tight - LUBRICATED						
Safety Inspection							
Tail Lift Inspection							
Fuel Filter Change	Change Fuel Filter - Linked in, new engine only done 15k miles new engine						
Air Filter Change	Air Filter Change						
Pollen Filter Change	Pollen Filter Change						
Breakdown	10/02/2021	20:01	11/02/2021	09:20	267,733	Torquay	TO019736
52 Electrical Aux Breakdown	carried out checks and reset all ok Cannot turn on electrics on in the back						
Defect Repair	18/02/2021	08:30	18/02/2021	15:19	268,554	Torquay	TO019773
13 Handbrake	checked for hand brake not holding found shoe broken replaced kit + adjusted						
Unplanned Repair	23/02/2021	09:51	23/02/2021	12:31	269,097	Torquay	TO019793
MDT Failure/Issue	controll report - sat nav not plotting NOTE						
Unplanned Repair	04/03/2021	06:56	04/03/2021	07:22	269,979	Torquay	TO019838
71 Body External Steps	NOTE						
BREAKDOWN	08/03/2021	14:10	08/03/2021	14:27	270,432	Torquay	TO019864
02 Cab Assembly 1	in cab storage box completely broken - REPAIRED see note						
13 Brakes 1							

Vehicle Deep Clean	25/03/2021	07:04	26/03/2021	12:10	272,699	Torquay	TO019939
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	26/03/2021	15:59	29/03/2021	07:37	272,700	Torquay	TO019957
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	storage button missing - REPLACED	
02 Windscreen	os washer jet broken - REPLACED	
02 Windscreen Wipers	wiper blades req replace - REPLACED	
13 Brakes 1	front disk and pads under trust requirement - REPLACED SET	
18 Wheels Check Torques		
34 Emergency Lights	NSF white marker light inop - REPLACED	
34 Lights	os R amber marker broken - REPLACED ROTTEN WIRES + LIGHT UNIT	
43 Exhaust System 1	hole in exhaust tail pipe - REPLACED	
55 Ramp	bridge guides through bolts pulled through guide - REPLACED W/SPARE GUIDE x 2	
71 Body Exterior 1	os arch damage - REPAIRED	
85 Body Interior 1	handles to saloon on bag storage loose - TIGHTENED	
85 Body Interior 2	240v sockets missing front plates, green lights damaged - NO PARTS	Monitoring
85 Body Interior 3	dressings cupboard strap broken - REPAIRED	
86 Sliding Door	top magnet bent - REPOSITIONED	
87 - Stretchers/Chairs/Boards	battery bad - REPLACED	
89 Seats	seat armrest broken - REPLACED WITH NEW	
Safety Inspection		
Tail Lift Inspection		
Replace Handbrake Cables	Replace Handbrake Cables	

BREAKDOWN	31/03/2021	10:01	06/04/2021	15:13	273,046	Torquay	TO019978
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

16 Suspension 1	Merc to replaced n\s\l shocker knocking
43 Exhaust System 1	DPF droken and sooty around turbo

SAFETY INSPECTION	05/05/2021	08:00	07/05/2021	16:00	273,455	St Leonards	SL033161
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	Replace N/S Damaged Mirror	
13 Brakes 1	Replasca worn out peddle rubber.	
16 Suspension 1	N/S/F Lower arm play. Not yet at M/B 3.5mm limit.	Monitoring
17 Tyres	Remove R/ Wheels Replace XTV X 2	

18 Wheels Check Torques	Checked.						
34 Lights	Replace damaged O/S/F Indecator lens						
44 Add Ad Blue	Top up unit 7L						
52 Electrical Aux	Replace missing Torch.						
55 Tail Lift	Repair damaged Gates.						
71 Body Exterior 1	Remove call sign left on bonnet						
85 Body Interior 1	Floor matts in poor con but not yet holed					Monitoring	
85 Body Interior 2	240v sockets missing front plates, green lights damaged - NO PARTS						
86 Door Seals	Replace O/S/F Door seal.						
86 Doors	Drivers door stiff to open from insideas new seal fitted.					Monitoring	
86 Doors Rear	Repair floor supports for R/Door Stays. Pulled away from floor.						
Safety Inspection	Checked.						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
Vehicle Deep Clean	07/05/2021	08:00	07/05/2021	15:00	273,455	St Leonards	SL033189
Vehicle Deep Clean	Vehicle Deep Clean						
02 Pipeline Annual Inspection	06/05/2021	11:14	06/05/2021	11:16	273,455	MDT Ferndown	TF001193
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - passed all tests.						
Unplanned Repair	11/05/2021	08:30	11/05/2021	10:00	273,469	St Leonards	SL033216
86 Sliding Door	Side door not openingRemove key from damaged lock Req new lock & Key.					Monitoring	
Breakdown	11/05/2021	14:11	12/05/2021	06:00	273,485	St Leonards	SL033223
Breakdown	Side Door Constant open alarm					Monitoring	
Unplanned Repair	12/05/2021	12:15	14/05/2021	12:00	273,588	St Leonards	SL033236
86 Door Lock	Side door audio warning sounding						
86 Doors	Drivers door stiff to open from insideas new seal fitted.					Monitoring	
86 Sliding Door	Side door not openingRemove key from damaged lock Req new lock & Key.					Monitoring	

Breakdown	17/05/2021	18:26	18/05/2021	12:30	273,681	St Leonards	SL033265
Breakdown	Side door handle outside broken					Monitoring	
Unplanned Repair	04/06/2021	09:20	04/06/2021	09:42	275,753	Dorchester	DC025170
44 Add Ad Blue							
Unplanned Repair	09/06/2021	10:00	09/06/2021	11:00	276,414	St Leonards	SL033487
01 Air Conditioning 1	Cab aircon inop - New compressor on order.					Monitoring	
SAFETY INSPECTION	14/06/2021	06:00	16/06/2021	16:00	276,570	St Leonards	SL033507
01 Air Conditioning 1	Fit new compressor. Trace wiring fault. to break in loom						
02 Windscreen Wipers	Replace both units.						
13 Brakes 1	Replace Rear Disc & Pads & Calibers.						
16 Suspension 1	N/S/F Lower arm play. Not yet at M/B 3.5mm limit.					Monitoring	
18 Wheels Check Torques	Checked.						
44 Add Ad Blue	Top up unit 9L						
71 Body Exterior 1	Body Interior vent above airway leaks rain. SEAL SKY LIGHT.						
85 Body Interior 1	Floor matts in poor con but not yet holed. Replace both units.						
86 Doors	Drivers door stiff to open from inside as new seal fitted. Adjust Stryter						
86 Sliding Door	Fit new Up & Down catches. & More. Req new lock & Key.						
Breakdown	Side door handle outside broken. Also replace door rollers.						
Safety Inspection	Checked.						
Wheel Hub Flanges Replaceme	Replace Rear Flanges.						
Tail Lift Inspection	Repair both damaged handrails. platform & More.						
Vehicle Deep Clean	17/06/2021	08:59	17/06/2021	12:30	276,570	St Leonards	SL033551
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	29/06/2021	20:05	30/06/2021	06:00	276,976	St Leonards	SL033644

Breakdown	side step malfunctioning				Monitoring		
Unplanned Repair	05/07/2021	10:15	05/07/2021	10:45	277,638	St Leonards	SL033686
71 Body External Steps	Lub and straighten side step						
Breakdown	09/07/2021	23:19	12/07/2021	09:00	278,164	St Leonards	SL033750
86 Sliding Door Breakdown	Side door audio warning sounding. Repair door wiring Side door alarm constant						
SAFETY INSPECTION	02/08/2021	07:00	03/08/2021	14:00	279,912	St Leonards	SL033983
02 Cab Assembly 1	Passenger window switch broken. Replaced.						
02 Cab Assembly 2	Interior light n/w. Replaced bulb.						
02 Mirrors	N/S mirror surround broken. Replaced.						
02 Windscreen Wipers	Washers n/w.						
16 Suspension 1	N/S/F Lower arm play. Not yet at M/B 3.5mm limit.						
16 Suspension 2	Rear spring seperator block split. Replaced.						
18 Wheels Check Torques	Checked.						
34 Lights	N/S running light n/w. Replaced bulb.						
86 Door Lock	Rear door barrel siezed. Replaced lock set.						
87 Chairs	Med Equip & Devices carry chair damaged at track connector						
Breakdown	side step malfunctioning						
Safety Inspection	Carried out inspection.						
MOT							
Vehicle Deep Clean	04/08/2021	07:00	04/08/2021	12:30	279,912	St Leonards	SL034012
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	03/09/2021	14:06	06/09/2021	07:58	282,540	St Leonards	SL034290
01 Heating 1	Cab blower n/w. Rep[laced.						
Breakdown	ventilation/heater not working; VOR						

Vehicle Deep Clean	20/09/2021	07:28	20/09/2021	11:30	283,695	St Leonards	SL034385
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/09/2021	12:00	22/09/2021	12:30	283,695	St Leonards	SL034396
02 Windscreen Wipers	Replace both worn out units.Clean out tank. Replace one way valve						
18 Wheels Check Torques	Checked						
34 Lighting System	Replace Damaged N/S Headlight.						
34 Lights Bulb Replacement	Replace O/S Runing light.						
44 Add Ad Blue	Top up unit 14L						
87a - Medical Equipment Repair	Body Interior Stretcher locking mechanism stuck						
Safety Inspection	Checked						
Engine Change Oil & Filter	Done.						
Breakdown	03/10/2021	11:28	04/10/2021	09:00	285,036	St Leonards	SL034534
32 Starting System 1 Breakdown	Non start. Replace starter motor None Starter						
BREAKDOWN	22/10/2021	11:14	22/10/2021	15:00	286,559	St Leonards	SL034743
71 Body External Steps	Repair Damage to side step						
Vehicle Deep Clean	28/10/2021	09:47	28/10/2021	12:00	286,840	St Leonards	SL034793
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	29/10/2021	06:00	01/11/2021	15:00	286,840	St Leonards	SL034809
18 Wheels Check Torques							
Safety Inspection							
Brake Fluid Change	Brake Fluid Change						
Tail Lift Inspection							

Breakdown	02/12/2021	20:26	03/12/2021	08:00	288,000	St Leonards	SL035138
Breakdown	side door - a key stuck/jammed in lock					Monitoring	
Breakdown	03/12/2021	17:07	06/12/2021	07:12	288,100	St Leonards	SL035146
Breakdown	key broken off in side door						
Unplanned Repair	10/12/2021	09:04	10/12/2021	09:06	289,789	St Leonards	SL035200
71 Body External Steps	Side step deploying.Adjust top catch.						
SAFETY INSPECTION	14/12/2021	06:00	15/12/2021	12:00	290,339	St Leonards	SL035216
18 Wheels Check Torques							
33 Ignition System	Replace key						
34 Emergency Lights	n\sf wing blue light n\w, repaired wiring.						
71 Body Exterior 1	Body Exterior IMPACT WITH TP - NO VEHICLE DAMAGE RECORDED						
86 Sliding Door	Doors side door unable to access from outside, renew lock & key						
Breakdown	side door - a key stuck/jammed in lock						
Safety Inspection							
UB Fire Supp 12mts Service	Service of fire supression system						
UB Fire Supp 6mts Service	jactone sys on veh, servied, rerout & secure pipe, rectified leak at gauge regas						
Tail Lift Inspection	ins, freed off some grease points, renewed platform n\s warning light						
Vehicle Deep Clean	15/12/2021	10:57	16/12/2021	07:15	290,339	St Leonards	SL035239
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	30/12/2021	21:47	31/12/2021	12:30	293,000	St Leonards	SL035340
55 Tail Lift	Clean up hand control contacts						
Breakdown	tail lift intermittent; VOR						

Breakdown	05/01/2022	20:06	06/01/2022	06:00	294,110	St Leonards	SL035397
Breakdown	AirCon malfunctioning					Monitoring	
Breakdown	18/01/2022	16:27	19/01/2022	06:30	294,110	St Leonards	SL035498
86 Sliding Door Breakdown	Adjust side door magnet and cable Sidedoor magnet not holding door						
Vehicle Deep Clean	25/01/2022	07:12	25/01/2022	11:00	294,119	St Leonards	SL035559
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/01/2022	06:00	26/01/2022	15:00	294,119	St Leonards	SL035567
02 Cab Ass Fire Extinguisher 02 Windscreen Wipers 18 Wheels Check Torques 85 Body Interior 1 Breakdown Safety Inspection Tail Lift 12M Service & Weight	date exp replaced, cleaned washers, secured cupboard door. AirCon malfunctioning Tail Lift 12M Service & Weight					Monitoring	
Unplanned Repair	02/02/2022	06:00	02/02/2022	07:00	294,120	St Leonards	SL035640
85 Body Interior 1 87 Stretcher	Body Interior Trolley cot securing latch broken Stretcher clamp u/s						
Breakdown	16/02/2022	02:52	17/02/2022	15:00	295,130	St Leonards	SL035760
34 Lights Breakdown	Rear lights inop Re-wire all rear lights. Replace loom. Replace 3 Light units N/S Tail Light Out					Monitoring	
O2 Pipeline Annual Inspection	17/02/2022	10:04	17/02/2022	10:05	295,130	MDT Ferndown	TF001801

02 Pipeline Annual Inspection Annual Inspection and Pressure Test

Unplanned Repair **03/03/2022** **11:15** **04/03/2022** **10:30** **295,722** **St Leonards** **SL035878**

45 Engine 1 Lack of power. Set up Texa and replace nox sensor, Road test, ok.

Unplanned Repair **08/03/2022** **13:00** **08/03/2022** **14:00** **295,967** **St Leonards** **SL035937**

86 Doors Rear Doors rear door stay broken - Replaced

Breakdown **15/03/2022** **03:45** **15/03/2022** **06:15** **296,693** **St Leonards** **SL035968**

Breakdown heavy smoke from exhaust Monitoring

Vehicle Deep Clean **16/03/2022** **09:34** **17/03/2022** **08:30** **296,856** **St Leonards** **SL035987**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **21/03/2022** **06:24** **22/03/2022** **09:42** **296,857** **St Leonards** **SL036003**

18 Wheels Check Torques	Checked.	
Safety Inspection	Carried out inspection.	
Breakdown	heavy smoke from exhaust	
71 Body Exterior 1	Body Exterior hit wall. wheel arch scratched	Monitoring
71 Body Exterior 2	Body Exterior O/S wheel arch scratched	Monitoring
Tail Lift Inspection	Done. Free off siezed o/s gate & flap.	
Replace Handbrake Cables	Replace Handbrake Cables. Done.	
86 Sliding Door	Rollers siezed. Replaced all.	
85 Body Interior 1	Linnen cupboard door broken @ hinge side.NO PARTS.	Monitoring
85 Body Interior 2	White board broken.NO PARTS.	Monitoring
55 Tail Lift	O/S Gate stuck down. Flaps stuck up.	
16 Suspension 1	Rear spring seperators split. Replaced x2.	
16 Suspension 2	N/S lower ball joint worn. Monitor (would still pass MOT)	

Unplanned Repair	08/04/2022	07:00	11/04/2022	15:00	298,011	St Leonards	SL036166
34 Lights	Brake lights inop						
Unplanned Repair	18/04/2022	09:21	18/04/2022	09:50	298,727	St Leonards	SL036216
86 Door Lock	Side door handle stuck out. Repaired.						
Breakdown	19/04/2022	18:00	20/04/2022	09:00	298,829	St Leonards	SL036233
Breakdown	Water coming through roof onto electrics					Monitoring	
Unplanned Repair	22/04/2022	08:03	22/04/2022	08:30	299,149	St Leonards	SL036264
Supply Sat Nav	Sat-Nav n/w. Replaced. Checked aerals,OK. Still not finding satalites						
Breakdown	30/04/2022	19:33	03/05/2022	08:30	299,806	St Leonards	SL036369
Breakdown	Key Fob wont unlock					Monitoring	
SAFETY INSPECTION	12/05/2022	06:00	12/05/2022	06:00	300,635	St Leonards	SL036526
18 Wheels Check Torques Safety Inspection							
SAFETY INSPECTION	12/05/2022	06:00	26/05/2022	12:00	300,635	St Leonards	SL036527
18 Wheels Check Torques	Checked						
Safety Inspection	Checked						
71 Body Exterior 1	Body Exterior hit wall. wheel arch scratched					Monitoring	
71 Body Exterior 2	Body Exterior O/S wheel arch scratched					Monitoring	
85 Body Interior 1	Linnen cupboard door broken @ hinge side Repaired.						
85 Body Interior 2	White board broken. Replaced.						
Breakdown	Key Fob wont unlock						
34 Lights	Lighting System N/S indicator						
Annual Heater Service	Annual Heater Service						

Annual Air Con Service	Annual Air Condition Service. New compressor fitted.
44 Add Ad Blue	Top up unit 19.5L
45 Engine 1	No Oil. Fill unit 3L
45 Engine 2	Reset service light.
13 Brakes 1	Replace peddle rubber
85 Body Interior 3	Fit floor matts correctly
52 Electrical Aux	Fit 4 New LED 240v lights.
02 Mirrors	Fit new O/S mirror as old one Damaged.
56 Comms Equipment	Replace damaged Mic.
Wear & Tear Repair	Replace damaged locker straps.
33 Ignition System	Supply 2x key fobs
86 Sliding Door	Repair damaged side door runner
13 Brakes 2	Adjust handbrake
34 Lighting System	Replace o/s stop/tail and ind lamp
55 Tail Lift	Replace gate

ACCIDENT	12/05/2022	09:49	25/05/2022	09:44	300,635	St Leonards	SL036536
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	Replace unreported damage to O/S Mirror. Replace mirror
55 Tail Lift	Replace damaged O/S Handrail as been closed up with rail still up. bend in two.
85 Body Interior 1	Replace frame work to rear storage unit as door been ripped off.
56 Comms Equipment	Replace saloon mic as been rip off.
85 Body Interior 2	Replace locker straps as been closed in side door.
71 Body External Steps	Side step protection flap ripped off.
71 Body Exterior 1	O/S Rear wheel arch damaged need replacement Arch.

Vehicle Deep Clean	17/05/2022	13:52	17/05/2022	13:53	300,635	St Leonards	SL036584
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	17/05/2022	13:53	18/05/2022	11:15	300,635	St Leonards	SL036586
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	06/06/2022	06:00	06/06/2022	07:23	301,436	St Leonards	SL036757
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Supply Sat Nav	Sat nav inop. Replaced.
----------------	-------------------------

BREAKDOWN	13/06/2022	07:45	13/06/2022	08:15	302,273	St Leonards	SL036815
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Indicator Bulb replacement by Jack						
-----------	------------------------------------	--	--	--	--	--	--

Breakdown	12/07/2022	20:00	13/07/2022	06:19	305,058	St Leonards	SL037097
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	No aircon both sides	Monitoring
45 Engine Ad Blue	Light on.....top up level	

Vehicle Deep Clean	19/07/2022	10:39	19/07/2022	14:00	305,599	St Leonards	SL037138
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	26/07/2022	07:00	28/07/2022	10:00	305,599	St Leonards	SL037180
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
71 Body Exterior 1	Body Exterior hit wall. wheel arch scratched
71 Body Exterior 2	Body Exterior O/S wheel arch scratched
Breakdown	No aircon both sides
71 Body Exterior Acc Repair	Damage to .Tail lift. O/S/R tail lights . Light panel. O/S lower cap. O/S panelw
Tail Lift Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
MOT	
01 Air Conditioning 1	Air con in saloon now working. Air Con in cab has hole in dash coil.
44 Add Ad Blue	Top up unit 9.2L
02 Windscreen Wipers	Clean out washer bottle Replace jets & Check valve
34 Lighting System	Repair N/S/F wing indecator. Bad Earth.
86 Sliding Door	Repair damaged mag brakets
16 Suspension 1	Replace both F/Lower arm as worn out more than 3.5mm
13 Brakes 1	Replace R/Pads. Renzo Repaired Good Job.
13 Brakes 2	Replace F/Disc & Pads.
Wheel Hub Flanges Replaceme	Front Hub Flanges Only , Rear Hub Flanges cleaned (rears on back order)

ACCIDENT	26/07/2022	08:40	28/07/2022	08:00	305,599	St Leonards	SL037183
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior Acc Repair Damage to Tail Lift. O/S/R light cluster. Light support Panel.O/S/R wheel arch.

Unplanned Repair 02/08/2022 10:00 02/08/2022 11:30 306,015 St Leonards SL037231

31 Battery Aux Replaced

Unplanned Repair 25/08/2022 07:30 30/08/2022 10:00 307,340 St Leonards SL037376

01 Air Conditioning 1 Air con inop Hickley to repair
01 Air Conditioning 2 Hole in Air con compressor
Travel Time To Weymouth & Return

Vehicle Deep Clean 06/10/2022 07:26 06/10/2022 07:27 311,095 St Leonards SL037723

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean 06/10/2022 07:27 06/10/2022 12:30 311,095 St Leonards SL037724

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 07/10/2022 11:30 07/10/2022 11:30 311,095 St Leonards SL037762

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION 07/10/2022 11:30 12/10/2022 13:17 311,095 St Leonards SL037763

18 Wheels Check Torques Checked
Safety Inspection Checked
Wheel Hub Flanges ReplacemeOnly Fitted Rears As F/ flanges just be replaced
Auto G/box Oil & Filter Change Auto G/box Oil & Filter Change. Unable to book out Fluids as incorrect stock
Tail Lift Inspection To be Inspected & Repaired by S.W.L as leaking tank. Replacement needed Monitoring
02 Windscreen Wipers Remove washer bottle clean out and Re-fit.
17 Tyres Replace Replace 5 Tyres
71 Body External W&T Repair Clean up all 6 Wheels
52 Electrical Aux Replace damaged 240v sure line socket.

Unplanned Repair	13/10/2022	13:30	13/10/2022	14:00	311,097	St Leonards	SL037842
56 Comms Equipment	MDT touch screen u/s - OSS to repair						
Breakdown	28/10/2022	02:50	28/10/2022	06:30	313,366	St Leonards	SL037972
Breakdown	brake lights not working						
Unplanned Repair	09/11/2022	09:30	11/11/2022	10:09	313,701	St Leonards	SL038066
15 Steering 1 89 Seats 13 Handbrake 71 Body External Steps 01 Air Conditioning 1	Out of alignment Base and backs worn No reserve travel Side step sticking compressor squeaking.						
ACCIDENT	16/11/2022	19:04	17/11/2022	07:00	313,866	St Leonards	SL038122
Breakdown	Ramp Damage					Monitoring	
BREAKDOWN	15/12/2022	09:30	15/12/2022	11:00	317,201	St Leonards	SL038490
71 Body Exterior 1 34 Lights 17 Tyres Replace	Side Step Only Partially deploying- Fault Rectified Interior Light not working- New bulb fitted O/S/R Tyres replaced- Punctured						
Breakdown	18/12/2022	03:35	18/12/2022	08:00	317,500	St Leonards	SL038517
Breakdown 45 Engine 1	burning smell in the cabin; VOR Re-gen in progress. Power steering low. intake leak to inlet pipe.						

Unplanned Repair	09/02/2023	09:30	09/02/2023	10:30	322,055	St Leonards	SL039054
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

17 Tyres Tracking	Tracking to do	Monitoring
18 Wheels	Front wheels out of balance. Front tyres replaced	

Unplanned Repair	06/03/2023	16:01	06/03/2023	16:20	322,953	St Leonards	SL039300
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Side step not deploying. Temp repair to step. All working
------------------------	---

SAFETY INSPECTION	24/03/2023	06:30	27/03/2023	16:10	324,133	St Leonards	SL039470
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
17 Tyres Tracking	Tracking to do
71 Body External Steps	side step not deploying. cleaned and lubricated runners. operating ok.
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
Pollen Filter Change	Pollen Filter Change
Tail Lift Inspection	
02 Cab Assembly 1	Cab interior light bulb blown. replaced
02 Cab Ass Fire Extinguisher	oth fire extinguishers out of date. replaced
85 Body Interior 1	locker strap broken. replace
16 Suspension 1	Rear spring buffers worn x2 and roll bar drop link bushes worn x3. replace
11 Axle Rear	Rear axle oil low. topped up (spare oil used)
13 Brakes 1	Nsf caliper slider seized. freed off and lubricated.
55 Tail Lift	(SEE NOTES)
13 Brake Pads	nsr outer pad friction material breaking apart. replaced rear brake pads.
86 Doors Rear	nsr door split in lower corner. fitted reinforce plate to door
86 Sliding Door	sliding door earth wire broken. replaced wire
42 Coolant System	Coolant reservoir leaking. replaced reservoir and cap.
Aux drive belt change	Drive belt split. replaced belt
27 Transmission Automatic	Rear transmission mount worn. replace
24 Driveshaft 1	Prop centre bearing and rear uj worn. replace
Travel Time	Road test

02 Pipeline Annual Inspection	23/03/2023	13:44	23/03/2023	13:47	324,133	MDT Ferndown	TF002589
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - replaced 1x Outlet port.
-------------------------------	--

Vehicle Deep Clean	29/03/2023	08:45	30/03/2023	10:19	324,133	St Leonards	SL039523
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/04/2023	12:12	21/04/2023	12:14	325,514	St Leonards	SL039832
45 Engine Ad Blue	AdBlue fault. topped up level and reset values using texa. light reset. all ok.						
SAFETY INSPECTION	01/05/2023	08:00	01/05/2023	14:36	326,250	St Leonards	SL039956
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
UB Fire Supp 12mts Service	Service of fire suppression system						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Replace Handbrake Cables	Replace Handbrake Cables						
Tail Lift Inspection	Done.						
85 Body Interior 1	Fit P clips for AVP						
34 Lights	O/S headlamp rear cover missing. Replaced.						
Vehicle Deep Clean	02/05/2023	10:45	03/05/2023	11:00	326,250	St Leonards	SL039973
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	13/06/2023	10:25	13/06/2023	15:00	331,206	St Leonards	SL040536
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/06/2023	07:00	14/06/2023	14:45	331,206	St Leonards	SL040547
18 Wheels Check Torques							
Safety Inspection							
86 Door Lock	Doors Side door magnetic catch u/s. Cab doors self lock						
45 Engine 1	engine AD BLU MAL FUNCTION LIMP MODE						
85 Body Interior 1	Microphone damage						

85 Body Interior 2	Sky light damaged
86 Doors	Rear Door light u/s
34 Lights	side light inop
15 Steering 1	Steering wheel replaced
17 Tyres	Fronts low
43 Exhaust System 1	CAT blocked
13 Brake Pads	Replace front pads

Breakdown	01/07/2023	08:06	01/07/2023	19:10	331,500	St Leonards	SL040812
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Accident damage
-----------	-----------------

Replace Vehicle Fuel Card	07/07/2023	18:00	07/07/2023	18:00	331,500	St Leonards	SL040918
----------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
---------------------------	---------------------------

Vehicle Deep Clean	24/07/2023	13:30	25/07/2023	10:34	337,235	St Leonards	SL041239
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	25/07/2023	10:30	27/07/2023	14:15	337,235	St Leonards	SL041255
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
MOT	
Tail Lift Inspection	
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
13 Handbrake	Adjust shoes and cables.
16 Suspension 1	Front shock absorbers play in upper mounts. replace both and bolts.
45 Engine 1	Coolant pump bearings noisy. new required
01 Air Conditioning 1	Rear AC condensor corroded and fan seized. replaced unit and unions.
45 Engine 2	Air box intake pipe to turbo leaking. replaced pipe and cleaned.
02 Cab Assembly 1	NS Window switch broken. replace.
34 Lights	No plate light inop. replace x1 light
86 Sliding Door	Sliding door wiring broken. repair wiring.

86 Doors Rear 13 Brakes 1	Rear door hinge nsr lower worn. Monitor Telma rubbing. operating ok. Monitor.	Monitoring
------------------------------	--	------------

SAFETY INSPECTION	02/09/2023	11:33	03/09/2023	08:00	339,696	St Leonards	SL041789
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques Safety Inspection 86 Doors Rear Engine Change Oil & Filter 55 Tail Lift	Checked. Carried out inspection. Rear door hinge nsr lower worn. Monitor Done. Tilt sensor n/w. Replaced.	Monitoring
---	---	------------

Vehicle Deep Clean	04/09/2023	10:30	04/09/2023	15:00	339,696	St Leonards	SL041813
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	24/09/2023	12:42	24/09/2023	12:45	342,170	St Leonards	SL042079
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

03 Instruments & Sensors 1	OTHER FIRE SUPPRESSION SYSTEM ALARM
----------------------------	-------------------------------------

Breakdown	27/09/2023	01:04	27/09/2023	05:29	342,667	St Leonards	SL042110
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	N/S Indicator Out
-----------	-------------------

Vehicle Deep Clean	14/10/2023	07:00	15/10/2023	07:30	345,505	St Leonards	SL042370
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	15/10/2023	08:00	15/10/2023	13:17	345,360	St Leonards	SL042382
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques Safety Inspection 86 Doors Rear 34 Lighting System	Checked. Carried out inspection. Rear door hinge nsr lower worn. Monitor Lighting System casing damage rear lights. Replaced.
---	--

Recall Notification	Mercedes airbag recall. Done.						
Unplanned Repair	17/10/2023	06:00	18/10/2023	10:00	345,539	St Leonards	SL042398
13 Brakes 1 13 Handbrake	Replace Telma Check and adjust as required						
Vehicle Deep Clean	25/11/2023	07:30	26/11/2023	14:00	347,213	St Leonards	SL042927
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/11/2023	10:00	27/11/2023	16:00	347,213	St Leonards	SL042945
18 Wheels Check Torques Safety Inspection 34 Lights 34 Lighting System Tail Lift Inspection UB Fire Supp 6mts Service 17 Tyres	Lighting System n/s indicator has a wiring issue Body Exterior casing damage to rear lights UB Fire Supp 6mts Service Nail in O/S/R inner tyre						
Breakdown	30/12/2023	11:39	30/12/2023	13:02	350,443	St Leonards	SL043378
Breakdown	Steering pulling left hand side						
Vehicle Deep Clean	05/01/2024	11:32	05/01/2024	18:00	351,016	St Leonards	SL043477
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/01/2024	06:00	08/01/2024	16:00	351,016	St Leonards	SL043503
18 Wheels Check Torques Safety Inspection	Checked. Carried out inspection.						

34 Lighting System	Lighting System Indicator, Genysis panel in saloon u/s.NO PARTS.
31 Charging System	Electrical Auxs EPCR CHARGING DOCK NOT WORKING
Brake Fluid Change	Brake Fluid Change
Tail Lift Inspection	Done.
55 Tail Lift	Trolley stop plate siezed. Replaced.
34 Lights Bulb Replacement	O/S headlight no pattern. Replaced bulb & adjusted.
Install Saloon CCTV Camera	N/W.Checked & Replaced camera & dome.

SAFETY INSPECTION	22/02/2024	14:30	23/02/2024	14:48	358,764	St Leonards	SL044102
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
71 Body Exterior Acc Repair	Body Exterior O/S/R Scuff					Monitoring	
44 Fuel System 1	Fuel cap missing. Replaced.						
34 Emergency Lights	N/S wing blue n/w. Repaired. O/S/F roof blue 50% n/w.					Monitoring	
85 Body Interior 1	Genysis panel in saloon smashed to bits!Swapped from other vehicle.						
02 Cab Ass Fire Extinguisher	Out of date. Replaced.						
54 Sirens	Bull horn cover broken. Replaced.						
13 Brakes 1	Front disc's worn. Replaced.						
Wheel Hub Flanges Replaceme	Poor condition. Replaced.						
17 Tyres Replace	O/S/R/O low tread. Replaced.						
13 Brakes 2	Rear pads low. Replaced disc's & pads.						
13 Calipers	front bleed nipples sheared, replaced calipers.						
86 Door Lock	Rear lock n/w. Removed ,cleaned,lubbed,refitted.						

Vehicle Deep Clean	25/02/2024	07:31	25/02/2024	14:45	358,769	St Leonards	SL044129
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	15/03/2024	16:13	15/03/2024	16:25	361,201	St Leonards	SL044432
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

55 Tail Lift	Tail lift battery u/s
--------------	-----------------------

Unplanned Repair	21/03/2024	16:15	21/03/2024	17:14	361,201	St Leonards	SL044530
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

54 Sirens Siren inop. Replaced faulty siren unit.

Vehicle Deep Clean 01/04/2024 09:56 01/04/2024 12:58 361,876 St Leonards SL044693

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 01/04/2024 14:00 02/04/2024 10:43 361,876 St Leonards SL044706

18 Wheels Check Torques

Safety Inspection

71 Body Exterior Acc Repair

34 Emergency Lights

86 Door Lock

34 Lights

01 Air Conditioning 1

71 Body Exterior 1

16 Suspension 1

Body Exterior O/S/R Scuff

O/S/F roof blue 50% n/w.

Locker door lock jammed

N/S?f side light not working

pollen filter in poor condition

N/S/R body end cap damaged

both rear leaf spring rear buffer split

Monitoring

Monitoring

Emergency Deep Clean 05/04/2024 09:44 05/04/2024 11:58 362,383 St Leonards SL044776

Emergency Deep Clean

Unplanned Repair 12/04/2024 11:00 12/04/2024 12:00 363,282 St Leonards SL044864

02 Windscreen Wipers

Washers inop

Breakdown 12/04/2024 21:59 14/04/2024 06:14 363,402 St Leonards SL044875

Breakdown

31 Battery Aux

load shedding

Aux battery u/s

BREAKDOWN 11/04/2024 13:30 11/04/2024 14:00 362,384 St Leonards SL044895

MDT Failure/Issue

Breakdown 22/04/2024 08:55 22/04/2024 10:00 364,983 St Leonards SL044995

Breakdown 02 Windscreen Wipers	side step coming out-unable to keep in Washers not working. bottle filter blocked. Replaced washed out						
Breakdown	23/04/2024	10:02	24/04/2024	15:18	365,195	St Leonards	SL045014
Breakdown 31 Charging System	unable to charge from shoreling Shoreline not charging - Look at inspection Awaiting Parts						
Unplanned Repair	01/05/2024	09:00	01/05/2024	15:03	366,096	St Leonards	SL045125
02 Mirrors	replaced n\s glass & secured cover.						
Unplanned Repair	02/05/2024	08:30	02/05/2024	09:07	366,405	St Leonards	SL045135
02 Mirrors 31 Charging System	N/S wing mirror smashed. Replaced Shoreline not charging. Repaired						
Breakdown	05/05/2024	15:58	06/05/2024	15:37	366,864	St Leonards	SL045182
Breakdown	red battery/ alternator warning						
02 Pipeline Annual Inspection	06/05/2024	11:06	06/05/2024	11:07	366,887	MDT Ferndown	TF003483
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found.						
Vehicle Deep Clean	14/05/2024	10:59	14/05/2024	15:47	367,722	St Leonards	SL045319
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	16/05/2024	11:30	17/05/2024	11:53	367,722	St Leonards	SL045346
18 Wheels Check Torques Safety Inspection 71 Body Exterior Acc Repair 34 Emergency Lights 31 Charging System Tail Lift Inspection	Body Exterior O/S/R Scuff O/S/F roof blue 50% n/w. Shoreline not charging - Look at inspection. NFF Inspected					Monitoring Monitoring	

Engine Change Oil & Filter							
24 Driveshaft 1			Rear propshaft U/S. Replaced				
55 Tail Lift			Replace perished pipe.				
17 Tyres Replace			Replace both front tyres and nsr tyres. Replace 1x rim				
34 Lights			Front marker light 50% of leds working. No stock			Monitoring	

Breakdown	23/06/2024	15:23	23/06/2024	17:00	372,561	St Leonards	SL045932
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	OSF tyre got a sharp screw on tyre leads puncture						
-----------	---	--	--	--	--	--	--

Vehicle Deep Clean	25/06/2024	13:42	26/06/2024	09:31	372,843	St Leonards	SL045967
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	28/06/2024	07:00	07/07/2024	14:00	372,843	St Leonards	SL046024
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
71 Body Exterior Acc Repair			Body Exterior O/S/R Scuff				
34 Emergency Lights			O/S/F roof blue 50% n/w.			Monitoring	
34 Lights			Front marker light 50% of leds working. Replaced				
Replace Handbrake Cables			Replace Handbrake Cables				
02 Glass / Windows			Driver switch broken replaced				
55 Tail Lift			Tail lift platform amber led not flashing. Replaced				
42 Coolant System			Leak from radiator.				
45 Engine 1			Pipe leaking to intake pipe				
34 Emergency Light System			Repair wiring to side blue light				
01 Air Conditioning 1			Air con condensor replaced				
01 Air Conditioning 2			Drain and regas system				
45 Engine 2			Intercooler damaged. Replaced				

Breakdown	24/07/2024	21:43	25/07/2024	04:01	374,668	St Leonards	SL046534
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	N/S FRONT HEADLIGHT OUT-N/S BLUE LIGHT COME OFF						
-----------	---	--	--	--	--	--	--

BREAKDOWN	25/07/2024	11:48	25/07/2024	11:51	374,827	St Leonards	SL046549
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Doors Rear	O/S/R Door stay Broken						
---------------	------------------------	--	--	--	--	--	--

Vehicle Deep Clean	09/08/2024	08:12	09/08/2024	13:30	376,644	St Leonards	SL046731
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	11/08/2024	07:38	12/08/2024	18:00	376,655	St Leonards	SL046757
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
86 Doors Rear	Doors Back door metal attached to vehicle dismantled
UB Fire Supp 12mts Service	Service of fire suppression system
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Pollen Filter Change	Pollen Filter Change
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
Engine Change Oil & Filter	
Tail Lift Inspection	
02 Windscreen Wipers	Washer jets not working
34 Emergency Lights	Cab spot light insecure
71 Body External Steps	N/S Side step not deploying
85 Body Interior 1	Saloon locker bag straps broken
34 Emergency Light System	N/S/F Wing blue L.E.D. ripped out of body / missing
55 Tail Lift	Tail lift bridge plate has no grip tape.
03 Instruments & Sensors 1	E.M.L. Illuminated on dashboard display system.
01 Air Conditioning 1	Air - con belt tensioner snapped
13 Brake Test	
13 Handbrake	Cab handbrake travel becoming excessive
41 Air Intake	Frot turbo seal cracked / split

BREAKDOWN	28/08/2024	16:00	29/08/2024	05:14	378,004	St Leonards	SL047047
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Emergency Lights	N/S/F Dytime running light not working
02 Windscreen Wipers	Washer jets not working

SAFETY INSPECTION	19/09/2024	06:00	20/09/2024	12:21	379,310	St Leonards	SL047375
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

34 Emergency Lights

O/S/F roof blue 50% n/w.

Monitoring

Tail Lift Inspection

85 Body Interior 1

Cab light not working. Bulb replaced

02 Glass / Windows

Passenger switch broken. Replaced

02 Windscreen Wipers

Washers not working. Filter in bottle blocked. Cleaned out

02 Cab Ass Fire Extinguisher

Both fire extinguishers out of date. Replaced

45 Engine 1

No3 injector blowing by. Replaced injector seal

85 Body Interior 2

Strap missing from cupboard. Replaced with spare

15 Steering 1

Power steering pipe leaking.

71 Body Exterior 2

Rear mud flap mount loose. Resecured

13 Brake Pads

Front brake pads low. Replaced

Vehicle Deep Clean

20/09/2024

14:59

22/09/2024

06:30

379,323

St Leonards

SL047398

Vehicle Deep Clean

Vehicle Deep Clean

Med Devices Recall

19/09/2024

10:21

19/09/2024

10:24

379,310

MDT Ferndown

TF003769

Decontaminated

Cleaned with clinell wipes

Med Devices Recall

Upgrade Mangar Equipment to Airflo 24 and charger.

ACCIDENT

09/10/2024

06:11

09/10/2024

10:40

379,323

St Leonards

SL047649

34 Lights

Lighting System N/S Headlight damaged. Replaced headlight and resecured bumper.

71 Body Exterior 1

Body Exterior N/S FRONT BUMPER SCRATCH

SAFETY INSPECTION

29/10/2024

06:00

30/10/2024

14:06

382,734

St Leonards

SL047987

18 Wheels Check Torques

Safety Inspection

34 Emergency Lights

O/S/F roof blue 50% n/w.

Tail Lift Inspection

Engine Change Oil & Filter

55 Tail Lift

Tail lift side rails loose

16 Suspension 1

Rear antiroll bar lower drop link bushes worn & have play / lift

13 Brakes 1	O/S/R Rear brake caliper pad retaining clip insecure						
02 Cab Assembly 1	Cab center genisys panel not working						
13 Brake Test							
13 Handbrake	Cab handbrake travel requires adjustments after brake test						
Vehicle Deep Clean	30/10/2024	05:59	30/10/2024	13:45	382,748	St Leonards	SL048011
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	03/11/2024	08:00	03/11/2024	10:56	383,004	St Leonards	SL048072
71 Body External Steps	Side step sticks						
Breakdown	03/12/2024	04:22	03/12/2024	13:30	383,004	St Leonards	SL048494
Breakdown	RUBBER FLAP ON RAMP OBSTRUCTING DOOR						
55 Tail Lift	Tail lift underrun blocks insecure. Re fit.						
Vehicle Deep Clean	10/12/2024	16:48	11/12/2024	10:18	386,824	St Leonards	SL048628
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	12/12/2024	15:00	16/12/2024	07:16	386,824	St Leonards	SL048655
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
34 Lights	O/S reverse light full of water. Replaced.						
13 Brakes 1	Rear pads worn. Replaced.						
17 Tyres Replace	O/S/R/I tyre low tread. Replaced.						
17 Tyres	Inner extension valves missing. Replaced x2.						
55 Tail Lift	Tilt sensor n/w. Replaced.Adjusted stops.						
Unplanned Repair	18/01/2025	12:00	18/01/2025	14:00	389,963	St Leonards	SL049169

56 Comms Equipment Travel Time	MDVS nort turning on. Reset and test, ok. Travel to Bournemouth
-----------------------------------	--

Vehicle Deep Clean	29/01/2025	09:00	29/01/2025	13:00	390,699	St Leonards	SL049314
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	30/01/2025	08:18	31/01/2025	07:55	390,699	St Leonards	SL049329
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 34 Emergency Light System Tail Lift Inspection 45 Engine Ad Blue 55 Tail Lift 87 - Stretchers/Chairs/Boards 85 Body Interior 1 13 Brake Test 13 Handbrake	Check and Install MDVS windows update Lighting System n/s top blue lights scratched AdBlue warning light illumintaed on dashboard display Tail lift side rails seized Stretcher belts wrongly fitted Saloon seat base swivel plunger losse N/S/F Cab handbrake travel becomming excessive
--	---

Breakdown	11/02/2025	07:26	11/02/2025	10:00	392,000	St Leonards	SL049493
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	top right blue light bulbs out
-----------	--------------------------------

Breakdown	08/03/2025	06:51	08/03/2025	07:18	393,401	St Leonards	SL049832
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	large chip obscuring drivers view - Ok for now not larger than 10mm	Monitoring
-----------	---	------------

Vehicle Deep Clean	14/03/2025	11:45	16/03/2025	14:28	393,733	St Leonards	SL049927
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	18/03/2025	10:38	19/03/2025	16:00	393,733	St Leonards	SL049986
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
Breakdown	large chip obscuring drivers view - Ok for now not larger than 10mm
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	
55 Tail Lift	Tail lift side rails loose
13 Brake Test	
Check Ferno Carry Chair Straps	Carry chair release knob broken
87 Chairs	Carry chair grip tape ripped
87 - Stretchers/Chairs/Boards	Stretcher belts in wrong positions
87 Stretcher	Stretcher mattress velcros missing
71 Body Exterior 1	Front number plate smashed
34 Emergency Lights	N/S/F Fog light surround insecure
16 Suspension 1	O/S/R/F Leaf spring buffer excessively split / worn
16 Suspension 2	O/S/R/R Leaf spring eye bushe excessively worn
16 Suspension 3	N/S/R/R Leaf spring eye bush worn
13 Handbrake	Cab handbrake travel becomming excessive
71 Body Exterior 2	Rear spray suppression wing insecure

02 Pipeline Annual Inspection	20/03/2025	11:20	20/03/2025	11:22	393,768	MDT Ferndown	TF004027
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - passed all tests.
-------------------------------	---

Unplanned Repair	31/03/2025	15:00	01/04/2025	12:28	394,540	St Leonards	SL050152
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

13 Brakes 1	Brake warning light on
86 Door Lock	C/L n/w. Replaced key battery.

BREAKDOWN	10/04/2025	10:30	10/04/2025	10:50	395,325	St Leonards	SL050332
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

85 Body Interior 2	Saloon locker 'BH3' wine rack unit broken
--------------------	---

Vehicle Deep Clean	03/05/2025	06:01	04/05/2025	11:58	397,010	St Leonards	SL050725
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	06/05/2025	06:23	06/05/2025	13:48	397,010	St Leonards	SL050774
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update. Done.	
Safety Inspection	Carried out inspection.	
18 Wheels Check Torques	Checked.	
Road Test	Done.	
02 Glass / Windows	Windscreen Chip on driver window	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight. Told to leave.	
85 Body Int Alcohol Gel Dispen	Done.	
85 Body Interior 1	Cuoboard strap broken. Replaced.	
02 Windscreen Wipers	Worn. Replaced.	
17 Tyres Replace	N/S/F & O/S/R/O tyres low tread. Replaced x2.	
13 Discs	Front disc's worn,(pads ok).	Monitoring
55 Tail Lift	Magnet bracket corroded.	
01 Heating 1	Saloon heater exhaust clips broken. Replaced x2.	
45 Engine Oil Top Up	Topped 1Ltr.	

ACCIDENT	17/07/2025	11:56	19/07/2025	06:00	403,757	St Leonards	SL052119
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	broken side light
-----------	-------------------