

| Vehicle Detail | BG1500U | ISUZU | D-MAX EXTENDED CAB | No |
|----------------|---------|----------------------------------|---|----|
| Date | Odo | Job Type | Description | |
| 27/05/2025 | | 0 BREAKDOWN RECOVERY | CALLOUT CHARGE(S) - ADD | |
| 27/05/2025 | | 0 BREAKDOWN RECOVERY | OPE-RECOVERY CHARGE(S) - ADD | |
| 24/02/2025 | | 0 RFL | RFL Mar 2025 | |
| 29/11/2024 | | 0 REPAIRS TO CLUTCH | SPIGOT BEARING - CLU / | |
| 29/11/2024 | | 0 BREAKDOWN RECOVERY | RECOVERY CHARGE(S) - ADD / | |
| 29/11/2024 | | 0 REPAIRS TO CLUTCH | MISC CLUTCH - CLU / | |
| 29/11/2024 | | 0 VALETING & STEAM CLEANING | STEAM CLEAN - ADD / | |
| 29/11/2024 | | 0 REPAIRS TO CLUTCH | CLUTCH FLYWHEEL - CLU / | |
| 29/11/2024 | | 0 REPAIRS TO CLUTCH | CLUTCH ASSEMBLY COMPLETE - CLU / | |
| 29/11/2024 | | 0 REPAIRS TO CLUTCH | CLUTCH ASSEMBLY - CLU / | |
| 29/11/2024 | | 0 REPAIRS TO CLUTCH | BOLTS - CLU / | |
| 29/11/2024 | | 0 REPAIRS TO CLUTCH | BOLTS - CLU / | |
| 29/11/2024 | | 0 Admin Charges | INVESTIGATION & REPORT - ADD / | |
| 20/11/2024 | | 0 Admin Charges | Defect (Accrual Line) / | |
| 20/11/2024 | | 0 REPAIRS TO ELECTRICS/BATTERY | BULB MISC - ELE / | |
| 02/11/2024 | | 0 ACCIDENT REPAIRS | Accident recovery - RHC04257841 | |
| 13/08/2024 | | 0 MOT | Recharge Routine, MOT - Class VII (Goods Vehicles), Rchg From Inv: 755/9017604 | |
| 13/08/2024 | | 0 SERV/SAFETY INS (+ TEST FEE) | Recharge Routine, Major Service (1link), Rchg From Inv: 755/9017604 | |
| 13/08/2024 | | 0 REPAIRS TO ELECTRICS/BATTERY | Recharge Remove & Refit, Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade/s, Rchg From | |
| 13/08/2024 | | 0 REPAIRS TO SUSPENSION | Recharge Remove & Refit, Rear Shock Absorber - Remove & Refit, Air suspension shock absorber right | |
| 13/08/2024 | | 0 REPAIRS TO SUSPENSION | Recharge Remove & Refit, Rear Shock Absorber - Remove & Refit, Air suspension shock absorber left (| |
| 13/08/2024 | | 0 REPAIRS TO ELECTRICS/BATTERY | Recharge Remove & Refit, Lamps - Remove & Refit, Lamps - Other Lamp Assy, Rchg From Inv: 755/901760 | |
| 13/08/2024 | | 0 REPAIRS TO BRAKES | Recharge Remove & Refit, Disc - Remove & Refit, Disc (incl. pads) - front (pair), Rchg From Inv: 75 | |
| 13/08/2024 | | 0 REPAIRS TO ELECTRICS/BATTERY | Recharge Remove & Refit, Battery - Remove & Refit, Battery - Split Charger, Rchg From Inv: 755/9017 | |
| 28/02/2024 | | 0 RFL | RFL Mar 24 | |
| 16/08/2023 | | 0 STATUTORY TESTING | S10 SERVICE | |
| 16/08/2023 | | 0 REPAIRS TO ELECTRICS/BATTERY | Wiring loom repair | |
| 16/08/2023 | | 0 STATUTORY TESTING | S10 SERVICE | |
| 16/08/2023 | | 0 STATUTORY TESTING | S10 SERVICE | |
| 16/08/2023 | | 0 STATUTORY TESTING | S10 SERVICE | |
| 16/08/2023 | | 0 STATUTORY TESTING | S10 SERVICE | |
| 16/08/2023 | | 0 REPAIRS TO ELECTRICS/BATTERY | Wiring loom repair | |
| 16/08/2023 | | 0 REPAIRS TO BRAKES | ROLLER BRAKE TEST | |
| 16/08/2023 | | 0 REPAIRS TO BRAKES | Handbrake Adjustment | |
| 16/08/2023 | | 0 STATUTORY TESTING | S10 SERVICE | |
| 16/08/2023 | | 0 MOT | Class VII MoT Test | |
| 06/08/2023 | | 0 REPLACEMENT HIRE COST | Mech | |
| 28/02/2023 | | 0 RFL | RFL Mar 2023 | |
| 06/09/2022 | | 0 REPAIRS TO BRAKES | Brake shoes - rear (axle set) | |
| 06/09/2022 | | 0 REPAIRS TO BRAKES | Wheel cylinder assy - rear (one) | |
| 06/09/2022 | | 0 REPAIRS TO BRAKES | BRAKE WEAR LIGHT ON - HAS TO COME OFF ROAD - | |
| 06/09/2022 | | 0 REPAIRS TO ELECTRICS/BATTERY | Lamps exterior (front) - daytime driving ligh | |
| 06/09/2022 | | 0 REPAIRS TO BRAKES | Metal brake pipes | |
| 06/09/2022 | | 0 REPAIRS TO BRAKES | Rear Brake Drums Kit | |
| 06/09/2022 | | 0 REPAIRS TO BRAKES | ROLLER BRAKE TEST | |
| 06/09/2022 | | 0 COLLECTION & DELIVERY | Basic road test (add once only) | |
| 24/08/2022 | | 0 SERV/SAFETY INS (+ TEST FEE) | S9 SERVICE | |
| 24/08/2022 | | 0 SERV/SAFETY INS (+ TEST FEE) | Class VII MoT Test | |
| 24/08/2022 | | 0 REPAIRS TO BRAKES | Front Brake Disc Kit | |
| 24/08/2022 | | 0 REPAIRS INTERNAL FITTINGS | Affix no smoking sign as none present. | |
| 24/08/2022 | | 0 REPAIRS TO ELECTRICS/BATTERY | Headlamp Alignment | |
| 24/08/2022 | | 0 REPAIRS TO ELECTRICS/BATTERY | Front amber flashers found inop. Check wiring | |
| 24/08/2022 | | 0 REPAIRS TO BODY (NON ACCIDENT) | Check towing bracket and trailer function as | |
| 24/08/2022 | | 0 REPAIRS TO BODY (NON ACCIDENT) | Check optional equipment as per service sheet | |
| 24/08/2022 | | 0 REPAIRS TO BODY (NON ACCIDENT) | Check bodywork ect as per service sheet. | |
| 24/08/2022 | | 0 REPAIRS TO BRAKES | Measure brake performance as per service shee | |
| 24/08/2022 | | 0 REPAIRS TO BODY (NON ACCIDENT) | Rear steps found damaged. Tape over sharp edg | |

| | | |
|------------|-------------------------------------|---|
| 24/08/2022 | 0 REPAIRS TO SUSPENSION | OSF wheel bearing found with excessive play. |
| 24/08/2022 | 0 REPAIRS TO SUSPENSION | NSF wheel bearing found with excessive play. |
| 17/05/2022 | 0 REPAIRS TO ELECTRICS/BATTERY | Lamps exterior - indicator/parking light bulb |
| 07/04/2022 | 0 SERV/SAFETY INS (+ TEST FEE) | BOTH CENTRAL LOCKING FOBS STOPPED WORKING/ WI |
| 28/02/2022 | 0 RFL | RFL Feb 2022 |
| 28/02/2022 | 0 RFL | RFL Feb 2022 |
| 11/02/2022 | 0 BREAKDOWN RECOVERY | ENVIROMENTAL |
| 11/02/2022 | 0 SERV/SAFETY INS (+ TEST FEE) | Winch Equipment Test |
| 11/02/2022 | 0 COLLECTION & DELIVERY | On Site Visit |
| 24/12/2021 | 101,111 ACCIDENT REPAIRS | Lamps exterior - rear lamp assy |
| 02/09/2021 | 0 SERV/SAFETY INS (+ TEST FEE) | S8 SERVICE |
| 02/09/2021 | 0 SERV/SAFETY INS (+ TEST FEE) | Class VII MoT Test |
| 31/08/2021 | 0 TYRES | Disposal of Tyre Casing |
| 31/08/2021 | 0 TYRES | Wheel Balance |
| 31/08/2021 | 0 TYRES | Tyre Valve Inner Repair |
| 31/08/2021 | 0 TYRES | Change Tyre |
| 31/08/2021 | 0 TYRES | Disposal of Tyre Casing |
| 31/08/2021 | 0 TYRES | Wheel Balance |
| 31/08/2021 | 0 TYRES | Tyre Valve Inner Repair |
| 31/08/2021 | 0 TYRES | Change Tyre |
| 06/08/2021 | 0 BREAKDOWN RECOVERY | WARNING LIGHT - RED - OTHER |
| 06/07/2021 | 0 REPAIRS TO ELECTRICS/BATTERY | REVERSING CAMERA NOT WORKING DRIVERS BELIEVES |
| 06/07/2021 | 0 REPAIRS TO ENGINE, EXHAUST | BATTERY NOT HOLDING CHARGE DRIVER SAYS POSSIB |
| 06/07/2021 | 0 REPAIRS TO ELECTRICS/BATTERY | Battery |
| 01/03/2021 | 0 RFL | RFL Feb 2021 |
| 05/02/2021 | 91,469 SERV/SAFETY INS (+ TEST FEE) | Winch Equipment Test |
| 05/02/2021 | 91,469 COLLECTION & DELIVERY | On Site Visit |
| 16/12/2020 | 0 REPAIRS TO ELECTRICS/BATTERY | JOB07222136/TSK15307197 |
| 16/11/2020 | 0 ACCIDENT REPAIRS | Lamps exterior - rear lamp assy |
| 11/11/2020 | 89,578 ACCIDENT REPAIRS | NEW EMERGENCY STOP BUTTON REQUIRED FOR THE WI |
| 11/11/2020 | 89,578 COLLECTION & DELIVERY | On Site Visit |
| 15/10/2020 | 0 SERV/SAFETY INS (+ TEST FEE) | Class VII MoT Test |
| 15/10/2020 | 0 REPAIRS TO SUSPENSION | Ball joint (Front Susp.) - lower right |
| 15/10/2020 | 0 REPAIRS TO ELECTRICS/BATTERY | Front Side Light Bulb Right |
| 15/10/2020 | 0 REPAIRS TO ELECTRICS/BATTERY | Windscreen Wiper Blade |
| 15/10/2020 | 0 REPAIRS TO SUSPENSION | Anti-roll/stabiliser bushes (Front Susp.) |
| 15/10/2020 | 0 REPAIRS TO SUSPENSION | Shock absorber/damper (one) (Rear Susp.) |
| 15/10/2020 | 0 REPAIRS TO ELECTRICS/BATTERY | Headlamp alignment |
| 15/10/2020 | 0 REPAIRS TO ELECTRICS/BATTERY | Front Side Light Bulb Left |
| 15/10/2020 | 0 SERV/SAFETY INS (+ TEST FEE) | S7 SERVICE |
| 28/05/2020 | 0 REPAIRS FOR MISUSE OR DAMAGE | Wheel Balance |
| 28/05/2020 | 0 REPAIRS FOR MISUSE OR DAMAGE | Tyre Call Out |
| 28/05/2020 | 0 REPAIRS FOR MISUSE OR DAMAGE | Disposal of Tyre Casing |
| 28/05/2020 | 0 REPAIRS FOR MISUSE OR DAMAGE | Change Tyre |
| 28/05/2020 | 0 REPAIRS FOR MISUSE OR DAMAGE | Tyre Valve Inner Repair |
| 19/03/2020 | 0 RFL | RFL Mar 2020 |
| 29/02/2020 | 0 RFL | RFL FEB 2020 |
| 18/02/2020 | 0 SERV/SAFETY INS (+ TEST FEE) | ELECTRONICS STABILITY LIGHT |
| 18/02/2020 | 0 SERV/SAFETY INS (+ TEST FEE) | SERVICE INDICATOR LIGHT ON DASHBOARD |
| 18/02/2020 | 0 SERV/SAFETY INS (+ TEST FEE) | ONLY GETTING TO 2/500 REVS |
| 18/02/2020 | 0 COLLECTION & DELIVERY | TAKE TO DEALERS FOR SPECIALIST WORK |
| 18/02/2020 | 0 SERV/SAFETY INS (+ TEST FEE) | AMBER EML - HAS BEEN TO ISUZU FOR RECALL WHICH MAY HAVE AN AFFECT |
| 18/02/2020 | 0 REPLACEMENT HIRE COST | BRE |
| 24/01/2020 | 0 REPAIRS TO ENGINE, EXHAUST | EA0919 ISUZU Fuel in Engine Oil recall end date =30-NOV-2020 |
| 22/11/2019 | 0 TYRES | Disposal of Tyre Casing |
| 22/11/2019 | 0 TYRES | Disposal of Tyre Casing |
| 14/11/2019 | 0 REPAIRS TO FUEL SYSTEM | Fuel filter element - in line |
| 14/11/2019 | 0 REPAIRS TO FUEL SYSTEM | Fuel filter element - in line |
| 07/11/2019 | 0 TYRES | Change Tyre |

| | | |
|------------|----------------------------------|--|
| 07/11/2019 | 0 TYRES | Change Tyre |
| 05/11/2019 | 0 REPAIRS FOR MISUSE OR DAMAGE | |
| 05/11/2019 | 0 REPAIRS FOR MISUSE OR DAMAGE | |
| 05/11/2019 | 0 REPAIRS FOR MISUSE OR DAMAGE | |
| 05/11/2019 | 0 REPAIRS FOR MISUSE OR DAMAGE | |
| 29/10/2019 | 0 REPAIRS TO BODY (NON ACCIDENT) | |
| 29/10/2019 | 0 REPAIRS TO BODY (NON ACCIDENT) | |
| 29/10/2019 | 0 REPAIRS TO BODY (NON ACCIDENT) | |
| 29/10/2019 | 0 REPAIRS TO BRAKES | |
| 29/10/2019 | 0 REPAIRS TO BRAKES | |
| 29/10/2019 | 0 REPAIRS TO ELECTRICS/BATTERY | Lamps exterior - headlamp bulb |
| 29/10/2019 | 0 REPAIRS TO ELECTRICS/BATTERY | |
| 29/10/2019 | 0 REPAIRS TO ELECTRICS/BATTERY | Lamps exterior - headlamp bulb |
| 29/10/2019 | 0 SERV/SAFETY INS (+ TEST FEE) | |
| 29/10/2019 | 0 SERV/SAFETY INS (+ TEST FEE) | |
| 28/10/2019 | 0 REPAIRS TO ELECTRICS/BATTERY | Check for washer pump inoperative/ check fuses and feed / earth present at motor/ find motor failed. |
| 28/10/2019 | 0 REPAIRS TO ELECTRICS/BATTERY | Check for washer pump inoperative/ check fuses and feed / earth present at motor/ find motor failed. |
| 17/10/2019 | 0 TYRES | Disposal of Tyre Casing |
| 17/10/2019 | 0 TYRES | Disposal of Tyre Casing |
| 07/10/2019 | 0 REPAIRS TO FUEL SYSTEM | Air cleaner/filter - element |
| 07/10/2019 | 0 REPAIRS TO FUEL SYSTEM | Air cleaner/filter - element |
| 15/08/2019 | 0 SERV/SAFETY INS (+ TEST FEE) | ROOF SCREWING NUT ON TRUCKMAN BODY LOOSEN |
| 31/07/2019 | 0 REPAIRS TO STEERING | Monthly Management Fee 31-JUL-19 to 31-AUG-19 |
| 31/07/2019 | 0 REPAIRS TO ELECTRICS/BATTERY | Monthly Management Fee 31-JUL-19 to 31-AUG-19 |
| 31/07/2019 | 0 SERV/SAFETY INS (+ TEST FEE) | Monthly Management Fee 31-JUL-19 to 31-AUG-19 |
| 31/07/2019 | 0 COLLECTION & DELIVERY | Monthly Management Fee 31-JUL-19 to 31-AUG-19 |
| 22/07/2019 | 0 REPAIRS TO ELECTRICS/BATTERY | RATTLE FROM UNDERNEATH THE EXHAUST DEFECT 1034201//replace bolts in heat shield |
| 01/03/2019 | 0 RFL | RFL February 2019 |
| 26/02/2019 | 0 REPAIRS FOR MISUSE OR DAMAGE | NEW NEARSIDE REAR LIGHT CLUSTER REQUIRED /DEFECT 1043460-CUSTOMER CONTACT WHEN IN 07920750562 |
| 26/02/2019 | 0 REPAIRS FOR MISUSE OR DAMAGE | NEW NEARSIDE REAR LIGHT CLUSTER REQUIRED /DEFECT 1043460-CUSTOMER CONTACT WHEN IN 07920750562 |
| 04/02/2019 | 0 SERV/SAFETY INS (+ TEST FEE) | Winch Equipment Test |
| 04/02/2019 | 0 SERV/SAFETY INS (+ TEST FEE) | Winch Equipment Test |
| 04/02/2019 | 0 COLLECTION & DELIVERY | On Site Visit |
| 04/02/2019 | 0 COLLECTION & DELIVERY | On Site Visit |
| 15/01/2019 | 0 BREAKDOWN RECOVERY | CLUTCH |
| 15/01/2019 | 0 BREAKDOWN RECOVERY | CLUTCH |
| 15/01/2019 | 0 BREAKDOWN RECOVERY | CLUTCH |
| 15/01/2019 | 0 BREAKDOWN RECOVERY | CLUTCH |
| 15/01/2019 | 0 REPAIRS TO CLUTCH | Flywheel/drive plate |
| 15/01/2019 | 0 COLLECTION & DELIVERY | Basic road test (add once only) |
| 15/01/2019 | 0 REPAIRS TO CLUTCH | Clutch - assy |
| 15/01/2019 | 0 REPAIRS TO CLUTCH | Clutch - assy |
| 28/11/2018 | 0 SERV/SAFETY INS (+ TEST FEE) | Class VII MoT Test |
| 28/11/2018 | 0 REPAIRS TO ELECTRICS/BATTERY | Headlamp alignment |
| 28/11/2018 | 0 REPAIRS TO ELECTRICS/BATTERY | FRONT BUMPER RUNNING LIGHTS FAULTY |
| 28/11/2018 | 0 REPAIRS TO ELECTRICS/BATTERY | Lamps exterior (front) - daytime driving light bulb left |
| 28/11/2018 | 0 REPAIRS TO ELECTRICS/BATTERY | Infrared remote control batteries |
| 28/11/2018 | 0 REPAIRS TO ELECTRICS/BATTERY | BOTH KEYFOBS NEED NEW BATTERY |
| 28/11/2018 | 0 SERV/SAFETY INS (+ TEST FEE) | S5 SERVICE |
| 28/11/2018 | 0 REPAIRS TO BRAKES | Disc (incl. pads) - front (pair) |
| 06/07/2018 | 0 SERV/SAFETY INS (+ TEST FEE) | REAR OBLONG NUMBER PLATE REQUIRED |
| 28/06/2018 | 0 COLLECTION & DELIVERY | On Site Visit |
| 28/06/2018 | 0 SERV/SAFETY INS (+ TEST FEE) | ESTIMATE-FOLLOWING INSPECTION- REPLACE FAULTY WINCH ROPE & STRAP- VOR |
| 28/06/2018 | 0 SERV/SAFETY INS (+ TEST FEE) | ESTIMATE-CARRIAGE |
| 28/06/2018 | 0 STATUTORY TESTING | WINCH RETEST AND PULL TEST - PLEASE CAPTURE WEIGHT TOLERANCES ON CERTIFICATE |
| 25/06/2018 | 0 ACCIDENT REPAIRS | Lamps exterior - rear lamp assy |
| 27/04/2018 | 0 TYRES | Wheel Balance |
| 27/04/2018 | 0 TYRES | Change Tyre |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Disposal of Tyre Casing |

| | | |
|------------|---------------------------------------|--|
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Wheel Balance |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Disposal of Tyre Casing |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Tyre Valve Inner Repair |
| 27/04/2018 | 0 TYRES | Tyre Valve Inner Repair |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Disposal of Tyre Casing |
| 27/04/2018 | 0 TYRES | Wheel Balance |
| 27/04/2018 | 0 TYRES | Change Tyre |
| 27/04/2018 | 0 TYRES | Tyre Valve Inner Repair |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Change Tyre |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Wheel Balance |
| 27/04/2018 | 0 TYRES | Disposal of Tyre Casing |
| 27/04/2018 | 0 TYRES | Wheel Balance |
| 27/04/2018 | 0 TYRES | Disposal of Tyre Casing |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Wheel Balance |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Disposal of Tyre Casing |
| 27/04/2018 | 0 TYRES | Disposal of Tyre Casing |
| 27/04/2018 | 0 TYRES | Wheel Balance |
| 27/04/2018 | 0 TYRES | Tyre Valve Inner Repair |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Tyre Valve Inner Repair |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Wheel Balance |
| 27/04/2018 | 0 TYRES | Tyre Valve Inner Repair |
| 27/04/2018 | 0 TYRES | Change Tyre |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Change Tyre |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Tyre Valve Inner Repair |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Change Tyre |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Tyre Valve Inner Repair |
| 27/04/2018 | 0 TYRES | Change Tyre |
| 27/04/2018 | 0 TYRES | Disposal of Tyre Casing |
| 27/04/2018 | 0 REPAIRS FOR MISUSE OR DAMAGE | Change Tyre |
| 15/02/2018 | 0 RFL | RFL EA MAR 18 |
| 06/02/2018 | 0 SERV/SAFETY INS (+ TEST FEE) | Winch Equipment Test |
| 06/02/2018 | 0 SERV/SAFETY INS (+ TEST FEE) | Winch Equipment Test |
| 06/02/2018 | 0 SERV/SAFETY INS (+ TEST FEE) | Winch Equipment Test |
| 06/02/2018 | 0 SERV/SAFETY INS (+ TEST FEE) | Winch Equipment Test |
| 24/01/2018 | 43,357 REPAIRS TO BODY (NON ACCIDENT) | PIN USED FOR TOWING A TRAILER IS MISSING - DEFECT NUMBER 0892791 - CONTCAT GRAHAM MORAN 07920 750562 |
| 24/10/2017 | 0 REPAIRS TO BODY (NON ACCIDENT) | Fuel filler flap - lock |
| 24/10/2017 | 0 REPAIRS TO HYDRAULIC UNITS | R&R Rotational Motor & Gear |
| 14/09/2017 | 0 REPAIRS TO BODY (NON ACCIDENT) | Door assy - rear |
| 01/09/2017 | 0 TYRES | C&A Wheel Alignment |
| 25/08/2017 | 0 ACCIDENT REPAIRS | Lamps exterior - rear lamp assy |
| 17/08/2017 | 0 REPAIRS FOR MISUSE OR DAMAGE | Tyre Valve Inner Repair |
| 17/08/2017 | 0 REPAIRS FOR MISUSE OR DAMAGE | Tyre Call Out |
| 17/08/2017 | 0 REPAIRS FOR MISUSE OR DAMAGE | Wheel Balance |
| 17/08/2017 | 0 REPAIRS FOR MISUSE OR DAMAGE | Disposal of Tyre Casing |
| 17/08/2017 | 0 REPAIRS FOR MISUSE OR DAMAGE | Change Tyre |
| 15/03/2017 | 0 REPAIRS TO BRAKES | ROLLER BRAKE TEST |
| 15/03/2017 | 0 REPAIRS TO ELECTRICS/BATTERY | Windscreen wiper - blade/s |
| 15/03/2017 | 0 SERV/SAFETY INS (+ TEST FEE) | S3 SERVICE |
| 15/03/2017 | 0 REPAIRS TO ELECTRICS/BATTERY | Lamps exterior - foglamp/driving lamp bulb |
| 05/03/2017 | 0 RFL | RFL ENGLAND MARCH 2017 |
| 22/02/2017 | 0 RFL | RFL FEB 17 |
| 01/02/2017 | 0 SERV/SAFETY INS (+ TEST FEE) | repair and refit rear sensor for alarm system |
| 01/02/2017 | 0 SERV/SAFETY INS (+ TEST FEE) | Wiring loom repair |
| 01/02/2017 | 0 SERV/SAFETY INS (+ TEST FEE) | ALARM KEEPS GOING OFF - VEHICLE LOCKING CORRECTLY BUT ALARM WILL NOT STOP |
| 01/02/2017 | 0 SERV/SAFETY INS (+ TEST FEE) | CARRY OUT SERVICE INSPECTION AND LOAD TEST TO WINCH/O/L UNIT - SERIAL NUMBER 028 |
| 01/02/2017 | 0 REPLACEMENT HIRE COST | NUMC / Schedule Maintenance |
| 31/01/2017 | 0 SERV/SAFETY INS (+ TEST FEE) | CARRY OUT SERVICE INSPECTION AND LOAD TEST TO WINCH |
| 12/09/2016 | 0 REPAIRS TO HYDRAULIC UNITS | Winch - Miscellaneous/Other - Labour |
| 18/07/2016 | 0 SERV/SAFETY INS (+ TEST FEE) | Manufacturer Service - Distance Based - Labour |

| | | |
|------------|--------------------------------|---|
| 18/07/2016 | 0 SERV/SAFETY INS (+ TEST FEE) | Manufacturer Service - Distance Based - Parts |
| 24/06/2016 | 0 REPAIRS TO HYDRAULIC UNITS | Winch - Miscellaneous/Other - Labour |
| 24/06/2016 | 0 COLLECTION & DELIVERY | Movement - Engineer Onsite - Labour |
| 15/02/2016 | 0 RFL | RFL March 2016 |
| 1 | | |