

WM64JXV	A&E	Carbis Bay Amb Stn					
Unplanned Repair	14/05/2015	14:42	14/05/2015	14:50	208	Redruth	RE017646
71 Body Exterior 1	Fit blast film by Autospray						
Vehicle Deep Clean	08/06/2015	11:35	08/06/2015	11:39	208	Redruth	RE017726
Vehicle Deep Clean	new vehicle not in service						
PDI Inspection	08/06/2015	14:20	30/06/2015	09:10	209	Redruth	RE017729
34 Emergency Light System	Fit new Genysyes module and test						
34 Emergency Lights	Rear Red lights not working. Repaired under warranty						
52 Electrical Aux	Fault with Genisys system. No switch panel working in saloon & power points NW						
PDI Inspection							
SAFETY INSPECTION	08/06/2015	14:23	08/06/2015	14:25	209	Redruth	RE017730
18 Wheels Check Torques	New vehicle not on the road yet						
Safety Inspection							
SAFETY INSPECTION	16/07/2015	09:41	16/07/2015	14:46	3,179	Redruth	RE017913
18 Wheels Check Torques	Filled Ad Blue tank Checklist Defect Side door C/L motor noisy. Warranty claim form sent Checklist Defect Supplied correct Stryker Pedi-mate & removed Ferno PM Awaiting Warranty						
44 Add Ad Blue							
86 Door Lock							
87 Stretcher							
Safety Inspection							
Vehicle Deep Clean	17/07/2015	08:06	17/07/2015	12:33	3,179	Redruth	RE017918
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	22/07/2015	10:00	22/07/2015	10:30	4,318	Redruth	RE017940
86 Door Lock	Adjust rear door catch & lock						

SAFETY INSPECTION	27/08/2015	08:06	28/08/2015	12:32	12,770	Redruth	RE018115
18 Wheels Check Torques							
55 Ramp			Doors Tail lift loose when up. adjust ram				
85 Body Interior 1			Body Interior Flow meter unattached, oxyliter repaired				
86 Door Lock			Checklist Defect Side door C/L motor noisy. Warranty claim form sent repaired				
86 Doors			Doors lock sticking on sliding door (intermittent) actuator fitted (supplied)				
Safety Inspection							
Vehicle Deep Clean	28/08/2015	09:58	28/08/2015	13:00	12,770	Redruth	RE018119
Vehicle Deep Clean			Vehicle Deep Clean				
Breakdown	12/09/2015	15:40	12/09/2015	17:50	15,976	Redruth	RE018184
Breakdown			EM light on NOT SEEN IN WORKSHOPS ???				
Defect Repair	23/09/2015	07:53	23/09/2015	07:54	16,073	Redruth	RE018237
03 Instruments & Sensors 1			Engine limp mode NOT SEEN AT WORKSHOPS				
SAFETY INSPECTION	12/10/2015	08:34	12/10/2015	15:30	23,229	Redruth	RE018320
18 Wheels Check Torques							
55 Ramp			Repair bend side arm and free up hight adjustment on side arms				
86 Door Lock			Adjust both door catches on sliding door				
Safety Inspection			Inspection carried out by PCS engineer				
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection			Statutory Inspection				
Vehicle Deep Clean	13/10/2015	08:51	13/10/2015	13:01	23,234	Redruth	RE018328
Vehicle Deep Clean			Vehicle Deep Clean				

Unplanned Repair	22/10/2015	12:31	27/10/2015	14:10	26,449	Redruth	RE018460
17 Tyres Replace	Replced front tyres and carryout tracking check						
Defect Repair	27/10/2015	12:11	27/10/2015	13:30	26,449	Redruth	RE018433
17 Tyres Replace	Body Exterior tyres						
Vehicle Deep Clean	23/11/2015	07:42	23/11/2015	12:02	32,672	Redruth	RE018544
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/11/2015	16:44	24/11/2015	16:12	32,672	Redruth	RE018553
13 Handbrake	Adjust handbrake.						
17 Tyres Replace	Replace all four rear tyres.						
18 Wheels Check Torques							
89 Seats	Free-up and adjust front saloon seat detend pin. see notes						
Safety Inspection	Inspection and work done by P.C.S.						
Defect Repair	10/12/2015	12:29	10/12/2015	13:07	36,132	Redruth	RE018632
86 Door Lock	Doors Side door will not open from inside REPAIRED						
Vehicle Deep Clean	05/01/2016	08:14	05/01/2016	13:43	42,941	Redruth	RE018733
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	05/01/2016	12:10	06/01/2016	10:57	42,941	Redruth	RE018736
02 Cab Assembly 1	Rev camera broken new rear panel required ordered					Parts ordered in store	
18 Wheels Check Torques							

34 Lighting System	Front white marker lamps need replacing awaiting stock order	Awaiting Parts
54 Reversing Systems	Body Exterior reversing camera bent New panel required & ordered	Parts ordered in store
55 Ramp	Repair side arm and re-fit bridge plate slide New Magnet required ordered	Parts ordered in store
71 Body Exterior 1	Assorted body damage	
87 Chairs	Rear captains chair rearing starting to get rough	Monitoring
Safety Inspection		
93 - D Service		
Service D		
MOT Pre Test		

Breakdown	31/01/2016	21:26	31/01/2016	23:58	49,446	Redruth	RE018869
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown	headlight bulb out
-----------	--------------------

Vehicle Deep Clean	15/02/2016	08:36	15/02/2016	15:04	53,030	Redruth	RE018938
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	16/02/2016	12:20	17/02/2016	16:33	53,035	Redruth	RE018943
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Cab Assembly 1	Rev camera broken new rear panel required ordered
18 Wheels Check Torques	
34 Lighting System	Front white marker lamps need replacing awaiting stock order
54 Reversing Systems	Body Exterior reversing camera bent New panel required & ordered
55 Ramp	Repair side arm and re-fit bridge plate slide New Magnet required ordered
87 Chairs	Rear captains chair rearing starting to get rough
Safety Inspection	
Travel Time	
MOT	
Gearbox Oil & Filter Change	

Defect Repair	08/03/2016	15:42	10/03/2016	08:54	57,575	Redruth	RE019051
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

71 Body External Steps	SIDE STEP DEPLOYED WARNING ON CONTINUOUS. See notes
------------------------	---

Unplanned Repair	14/03/2016	10:00	14/03/2016	12:30	58,044	Redruth	RE019086
86 Doors Rear 86 Sliding Door	force door open strip down replace broken bolt & set up cables Strip door re-fit cables and set up latches						
Unplanned Repair	21/03/2016	11:55	21/03/2016	12:08	59,868	Redruth	RE019295
17 Tyres Replace	Replace o/s/f tyre by A.T.S.						
SAFETY INSPECTION	29/03/2016	08:23	01/04/2016	16:05	61,854	Redruth	RE019153
17 Tyres Replace 18 Wheels 18 Wheels Check Torques 34 Emergency Lights 71 Body External Steps Safety Inspection 92 - C Service Service C UB Fire Suppression Service Tail Lift Annual Service Annual Air Con Service Annual Heater Service Tail Lift 6 Monthly Inspection	Replace all 4 rear tyres & N/S/F tyre Replace two cracked road wheels Replaced bulb in OSF alley light Side step will not deploy. Straightened step, lubed and tested Statutory Inspection and Weight Test Annual Air Condition Service Annual Heater Service Statutory Inspection						
Vehicle Deep Clean	30/03/2016	11:26	31/03/2016	12:26	61,854	Redruth	RE019163
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	09/05/2016	09:54	10/05/2016	11:14	69,607	Redruth	RE019363
02 Windscreen 13 Brake Pads 18 Wheels Check Torques Safety Inspection 85 Body Int Alcohol Gel Dispen Fit Throw Lines & SOP	Chip in windscreen repaired by National Mobile Windscreen Replaced front and rear pads						

Wheel Studs & Nuts Replaceme

Handbrake Cable Replacement Replace rear handbrake cables

Vehicle Deep Clean	09/05/2016	12:41	10/05/2016	12:55	69,607	Redruth	RE019366
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean not complete due to lack of manpower						
--------------------	---	--	--	--	--	--	--

SAFETY INSPECTION	22/06/2016	07:30	22/06/2016	16:35	79,584	Redruth	RE019543
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	Replace both fire extinguishers.						
------------------------------	----------------------------------	--	--	--	--	--	--

18 Wheels Check Torques							
-------------------------	--	--	--	--	--	--	--

89 Seats	Free-up both swivel seat bases. refit adjusting bar on rear facing seat.						
----------	--	--	--	--	--	--	--

Safety Inspection							
-------------------	--	--	--	--	--	--	--

Reposition grab bag shelf							
---------------------------	--	--	--	--	--	--	--

93 - D Service							
----------------	--	--	--	--	--	--	--

Service D							
-----------	--	--	--	--	--	--	--

ACCIDENT	23/07/2016	17:02	24/07/2016	14:57	86,466	Redruth	RE019692
-----------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	Replaced windscreen after vadalised on scene						
---------------	--	--	--	--	--	--	--

Breakdown	large crack in screen VOR						
-----------	---------------------------	--	--	--	--	--	--

SAFETY INSPECTION	01/08/2016	08:01	05/08/2016	12:00	88,195	Redruth	RE019719
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windows/Glass	OS saloon window smashed. Mobile windscreens fitted supplied side window.						
------------------	---	--	--	--	--	--	--

18 Wheels Check Torques							
-------------------------	--	--	--	--	--	--	--

34 Lights Bulb Replacement	Replace n/s/f day running light bulb.						
----------------------------	---------------------------------------	--	--	--	--	--	--

86 Doors Rear	Rear door modified kit fitted.						
---------------	--------------------------------	--	--	--	--	--	--

Safety Inspection							
-------------------	--	--	--	--	--	--	--

Vehicle Deep Clean	03/08/2016	11:06	03/08/2016	11:07	88,195	Redruth	RE019737
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Overdue deep clean will be done with todays clean 03/08/2016						
--------------------	--	--	--	--	--	--	--

Vehicle Deep Clean	03/08/2016	11:07	04/08/2016	08:07	88,195	Redruth	RE019738
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean not complete due to lack of manpower						
--------------------	---	--	--	--	--	--	--

Defect Repair	05/09/2016	08:34	05/09/2016	08:45	95,202	Redruth	RE019873
45 Engine Oil Top Up							
Vehicle Deep Clean	12/09/2016	08:36	12/09/2016	15:10	96,573	Redruth	RE019905
Vehicle Deep Clean	Vehicle Deep Clean assisted by Will from agency four hours						
SAFETY INSPECTION	12/09/2016	15:06	13/09/2016	12:59	96,573	Redruth	RE019912
13 Handbrake	NS low effort. readjusted and retested						
17 Tyres Replace	Replaced both front tyres and fit best two too NSR						
18 Wheels Check Torques							
71 Body External Steps	Step edge damaged						
86 Door Seals	Drivers door seal torn						
Safety Inspection							
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Defect Repair	21/10/2016	10:33	21/10/2016	11:11	105,845	Redruth	RE020097
86 Doors Rear	RIGHT REAR DOOR STAY BRACKET DETACHED FROM FLOOR. Repaired						
SAFETY INSPECTION	25/10/2016	16:03	28/10/2016	13:23	106,894	Redruth	RE020120
13 Handbrake	NSR low effort. Adjusted and retested, OK						
17 Tyres Replace	Replaced all four rear tyres						
18 Wheels Check Torques							
43 Exhaust System 1	Realigned exhaust & tail pipe						
56 Comms Equipment	Refitted cab mic						
71 Body External Steps	Side step edge damaged. Replaced side step mudflap						
86 Door Seals	DRivers door seal has a slight tear in it						
86 Sliding Door	Checked and adjusted. Bearings getting rough						
						Parts ordered in store	
						Monitoring	
						Monitoring	

89 Seats	Swivel seat bearings getting rough						
Camera Installation	Fault on CCTV control box					Monitoring	
Check Vehilce Call Signs	Check vehilce call signs are fitted and correct. Fitted						
Safety Inspection	PCS Rich						
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill						
Gearbox Oil & Filter Change							
Vehicle Deep Clean	27/10/2016	07:42	27/10/2016	13:58	106,894	Redruth	RE020126
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	09/11/2016	08:20	09/11/2016	08:38	109,340	Redruth	RE020196
34 Lights Bulb Replacement	Electrical Auxs O/S headlight bulb U/S. Replaced OS dipped beam bulb						
Defect Repair	15/11/2016	07:50	15/11/2016	14:48	110,483	Redruth	RE020231
86 Sliding Door	Body Exterior Door alarm, door require slamming, see notes.						
Breakdown	03/12/2016	18:21	03/12/2016	20:00	114,483	Redruth	RE020362
17 Tyres Replace	Replaced OSF tyre on call out						
Breakdown	F/O/S						
Vehicle Deep Clean	05/12/2016	07:55	06/12/2016	12:19	114,838	Redruth	RE020364
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/12/2016	11:03	07/12/2016	11:31	114,838	Redruth	RE020369
13 Brakes 1	Refit o/s/r brake pad retaining shim.						
18 Wheels Check Torques							
71 Body External Steps	Side step edge damaged. Replaced side step mudflap						
86 Door Seals	DRivers door seal has a slight tear in it						
86 Sliding Door	Checked and adjusted. Bearings getting rough						

Camera Installation	Fault on CCTV control box
Safety Inspection	
Supply Sat Nav	Sat nav up-grade.
MOT Pre Test	
93 - D Service	
Service D	

SAFETY INSPECTION	17/01/2017	07:43	17/01/2017	16:30	121,000	Redruth	RE020587
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	Body Exterior DAMAGED MIRROR UNIT, replaced mirror shell.
13 Brakes 1	Replace rear brake discs and pads.
13 Handbrake	Replace hand-brake shoes.
18 Wheels Check Torques	
34 Lighting System	N/s/r stop/tail and fog lights damaged. now replaced.
71 Body Exterior 1	Body Exterior INVESTIGATE POSSIBLE DRIP FROM UNDER O/S
Safety Inspection	
Medical Device and Equip Ched.	S.U ok.
Travel Time	
MOT	

Vehicle Deep Clean	18/01/2017	07:04	18/01/2017	12:20	121,000	Redruth	RE020596
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	28/02/2017	13:00	03/03/2017	12:04	134,645	Redruth	RE020827
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Heating 1	Electrical Auxs Heater in rear blows cold air, repaired by Espar (warranty)
13 Brakes 1	Replace front brake discs and pads.
18 Wheels Check Torques	
34 Lights	o/s/r body marker light damaged and not working, now replaced.
43 Exhaust System 1	rear exhaust mount broken, now replaced.
Safety Inspection	
92 - C Service	
Service C	
Annual Heater Service	Annual Heater Service
Handbrake Cable Replacement	Replace rear handbrake cable, not required vehicle not three years old.
Annual Air Con Service	Annual Air Condition Service, aux belt tensoiner replaced by Mercedes 24 hr.
UB Fire Suppression Service	New system fitted by contractor S Ball.

Vehicle Deep Clean	02/03/2017	07:33	02/03/2017	15:07	134,645	Redruth	RE020837
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Tail Lift Annual Service	06/03/2017	08:32	06/03/2017	13:21	134,645	Redruth	RE020855
---------------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Tail Lift Annual Service	Statutory Inspection and Weight Test
Tail Lift 6 Monthly Inspection	Statutory Inspection

ACCIDENT	29/03/2017	15:00	13/04/2017	12:06	139,782	Redruth	RE020993
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Saloon AC condensor damaged
34 Emergency Lights	OSF top corner blue lamp smashed
71 Body Exterior 1	Body Exterior Damage to right/top of vehicle. Wooden stake through body
85 Body Interior 1	and penetrated interior

SAFETY INSPECTION	13/04/2017	12:09	13/04/2017	18:14	139,782	Redruth	RE021075
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	Replaced wiper blades
17 Tyres Replace	Replaced 3 x NSF + Rear tyres
18 Wheels	Replaced NSR inner cracked wheel
18 Wheels Check Torques	
89 Seats	Refitted airways seat adjuster bar
Safety Inspection	

SAFETY INSPECTION	30/05/2017	16:09	02/06/2017	16:11	151,758	Redruth	RE021354
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	Replaced both fire extinguishers with in service units
02 Windscreen Wipers	Replaced wiper blades
17 Tyres Replace	Replaced both OSR tyres
18 Wheels Check Torques	
34 Lights Bulb Replacement	Replaced oSF daylight running light bulb
54 Reversing Systems	Reverse camera NW & no power to CCTV camera black box
89 Seats	Refitted airways seat adjuster bar
Safety Inspection	

93 - D Service
Service D

Vehicle Deep Clean	31/05/2017	08:13	31/05/2017	08:13	151,758	Redruth	RE021356
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	31/05/2017	08:14	31/05/2017	11:36	151,758	Redruth	RE021357
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

ACCIDENT	10/06/2017	10:48	23/06/2017	15:03	153,505	Redruth	RE021433
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Emergency Lights	Airport ligh ripped off
54 Reversing Systems	Rear camera not working, Awaiting warranty repair.
56 Comms Equipment	Aerials ripped off roof
71 Body Exterior 1	Skylight ripped off (looks to have gone under something too low)
Install Saloon CCTV Camera	Saloon camera installed and up graded.
MGS Gas Storage Modifications	MGS Gas Storage Modifications, (done.)

MRO Refresh	15/06/2017	08:05	15/06/2017	15:30	153,505	Redruth	RE021459
--------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

MRO Refresh	Clean rear of vehicle due to broken skylight. Glass everywhere.
-------------	---

Vehicle Deep Clean	03/07/2017	08:38	05/07/2017	12:39	155,919	Redruth	RE021566
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean more time needed as time put against when opened but not done
--------------------	--

SAFETY INSPECTION	03/07/2017	16:02	06/07/2017	16:45	155,919	Redruth	RE021573
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Air con in saloon not working,
18 Wheels Check Torques	
34 Lights Bulb Replacement	Both front side-light not working., bulbs now replaced.
71 Body Exterior 1	Electrical Auxs Rear O/S lower reflector/housing damaged
86 Sliding Door	Central locking not working, side door bearings worn.
Safety Inspection	
Gearbox Oil & Filter Change	

BREAKDOWN	10/07/2017	14:00	11/07/2017	11:59	156,461	Redruth	RE021618
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

03 Instruments & Sensors 1	EML on
43 Exhaust System 1	Top exhaust temperature sensor replaced by Merc 24hr
Road Test	

BREAKDOWN	12/07/2017	08:35	12/07/2017	15:39	156,484	Redruth	RE021631
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

45 Engine 1	Engine management light on. repair by 24hr Mercedes.
Gearbox Oil & Filter Change	Top up gearbox oil
Road Test	

Emergency Deep Clean	26/07/2017	09:21	26/07/2017	12:35	158,465	Redruth	RE021731
-----------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Emergency Deep Clean	Decontaminate trolley and floor. Also walls and monitoring equipment done. HEP C
----------------------	--

Defect Repair	31/07/2017	08:17	31/07/2017	11:42	158,465	Redruth	RE021753
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body Exterior 1	Other number plate broken. Replaced number plate
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card

BREAKDOWN	11/08/2017	12:14	11/08/2017	12:19	161,323	Redruth	RE021852
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	O/S mirror damaged - Replaced as necessary
------------	--

SAFETY INSPECTION	15/08/2017	09:14	15/08/2017	17:09	162,109	Redruth	RE021866
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	Both front seat armrests insecure - Re-secured	
16 Suspension 1	Rear ARB lower drop link bushes have slight play - Warranty	Awaiting Warranty
16 Suspension 2	Rear spring slipper pads starting to split - Warranty	Awaiting Warranty
18 Wheels Check Torques		
55 Tail Lift	NOTES for list of defects - New O/S Gate required (servicable at present)	Monitoring

Safety Inspection
Tail Lift 6 Monthly Inspection Statutory Inspection

Vehicle Deep Clean 16/08/2017 07:32 16/08/2017 12:55 162,114 Redruth RE021874

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 13/09/2017 14:42 13/09/2017 16:03 167,735 Redruth RE022047

Breakdown LIMP MODE

Breakdown 13/09/2017 15:08 22/09/2017 11:19 167,815 Redruth RE022048

41 Turbo Turbo blown. Mercedes of Truro replaced turbo & intake system
Breakdown EML limp mode. Mercedes 24hr attended

Vehicle Deep Clean 25/09/2017 07:24 25/09/2017 11:37 167,815 Redruth RE022135

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 25/09/2017 13:30 29/09/2017 16:17 167,815 Redruth RE022139

16 Suspension 1 Rear ARB lower drop link bushes have slight play - Warranty
16 Suspension 2 Rear spring slipper pads starting to split - Warranty
17 Tyres Replace Replace o/s/f tyre.
18 Wheels Check Torques
55 Tail Lift NOTES for list of defects - New O/S Gate required (servicable at present)
86 Doors Rear Rear door lower catch u/s
87 Stretcher Stretcher not on f.c.s serial number 160841308
Safety Inspection
WAS Firetrace rework & ServiceFire trace u/s

SAFETY INSPECTION 06/11/2017 10:04 14/11/2017 15:46 174,791 Redruth RE022405

02 Cab Assembly 1 Brake pedal rubber pad replaced
02 Cab Assembly 2 Replaced missing bulkhead rubber grommet
13 Handbrake Adjusted

15 Steering 1	Slight play OS steering
16 Suspension 1	Replaced both rear lower roll bar link bushes
16 Suspension 2	Rear spring buffer pads splitting
18 Wheels Check Torques	
34 Emergency Lights	N/s/r top blue light damaged., temporary repair made, new ordered.
34 Lights	Replaced missing OSF fof lamp surround
45 Engine 1	LH bank fuel injector seating washer leaking fumes
52 Electrical Aux	Electrical Auxs invertor - 240v plugs u/s. Working but requires new switch panel
Safety Inspection	
92 - C Service	
Service C	

Vehicle Deep Clean	15/11/2017	10:04	15/11/2017	15:29	174,857	Redruth	RE022468
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	21/11/2017	11:00	21/11/2017	11:30	176,136	Redruth	RE022508
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Electrical Auxs Bulb US, replace n/s headlight bulb.
----------------------------	--

SAFETY INSPECTION	14/12/2017	10:45	15/12/2017	11:14	180,010	Redruth	RE022673
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	refit comms speaker	
16 Suspension 1	replace n/s/f suspension arm	
17 Tyres Replace	replace all rear and n/s\f tyres	
18 Wheels	remove all wheels and clean contact surfaces	
18 Wheels Check Torques		
24 Driveshaft 1	replace rear propshaft	
43 Exhaust System 1	tailpipe corroded reqs replacing	Awaiting Parts
85 Body Interior 1	secure saloon grab handle	
99 Diagnostic Test	carry out tests and erase fault codes	
Safety Inspection		
MOT Pre Test		

Vehicle Deep Clean	15/12/2017	09:48	15/12/2017	15:02	180,010	Redruth	RE022683
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	04/01/2018	18:37	04/01/2018	20:00	183,561	Redruth	RE022802
17 Tyres Replace Breakdown	Replaced OSF tyre ATS call out R/O/S						
BREAKDOWN	05/01/2018	13:00	19/01/2018	15:15	183,628	Redruth	RE022816
11 Axle Rear 43 Exhaust System 1 55 Tail Lift 87 Chairs Road Test	Diff & pinion replaced with all new bearings by City West, Roche tailpipe corroded reqs replacing, now replaced. Straightened OS safety gate Body Exterior Bracket broken which secures carry chair. Repaired bracket Axle U/S						
SAFETY INSPECTION	31/01/2018	09:33	02/02/2018	16:10	185,904	Redruth	RE022980
02 Windscreen Wipers 13 Brake Pads 18 Wheels Check Torques 56 Comms Equipment 86 Doors Rear Safety Inspection Travel Time MOT 85 Body Int Alcohol Gel Dispen Already fitted Tail Lift 6 Monthly Inspection Tail Lift Annual Service	Replaced wiper blades Replaced rear brake pads replaced missing aerial mast Doors rear door retainer bar not connected to base Statutory Inspection Statutory Inspection and Weight Test						
Vehicle Deep Clean	02/02/2018	07:18	02/02/2018	15:00	185,910	Redruth	RE022995
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	12/03/2018	15:00	14/03/2018	15:30	193,186	Redruth	RE023241
18 Wheels Check Torques 71 Body External Steps 86 Sliding Door	Side step mud flap u/s side door trim broken						

99 Diagnostic Test	erase fault codes&reset service indicator,carryout test						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Handbrake Cable Replacement	Replace rear handbrake cables						
Wheel Hub Flanges Replaceme							
UB Fire Suppression Service							
93 - D Service							
Service D							
Vehicle Deep Clean	14/03/2018	08:26	15/03/2018	08:52	193,186	Redruth	RE023257
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	26/04/2018	13:33	27/04/2018	13:30	200,149	Redruth	RE023554
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/04/2018	15:23	27/04/2018	16:51	200,149	Redruth	RE023555
13 Brakes 1	adjust rear brakes and handbrake						
16 Suspension 1	o/s/f balljoint has wear within manufactures specifications						
16 Suspension 2	o/s/f shockabsorber has misting monitor next safety insp						
17 Tyres Replace	replace worn front tyres and clean contact surfaces						
18 Wheels Check Torques							
52 Electrical Aux	Replace torch.						
Safety Inspection							
Fit Poster Holder	Fit Poster Holder						
Breakdown	28/04/2018	16:58	30/04/2018	16:10	200,307	Redruth	RE023571
02 Windscreen	Replaced by National Mobile Windscreens						
Breakdown	10 inch crack in windscreen						
Travel Time	Take to Redruth depot and collect						
Defect Repair	16/05/2018	14:45	16/05/2018	15:54	203,495	Redruth	RE023702
55 Tail Lift	Ramp/Lift/Tail Hoist noisy, juddering ramp. Rectified leaking hose, refilled oil						

Monitoring
Monitoring

Defect Repair	24/05/2018	12:56	24/05/2018	13:17	205,075	Redruth	RE023749
71 Body Exterior 1	Body Exterior reflector o/s rear and new scratch. Replaced lower corner moulding						
Vehicle Deep Clean	04/06/2018	07:31	04/06/2018	15:54	206,937	Redruth	RE023805
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	05/06/2018	07:49	07/06/2018	16:26	206,937	Redruth	RE023816
02 Mirrors	replace n\s door mirror trim						
16 Suspension 1	o/s/f balljoint has wear within manufactures specifications						
16 Suspension 2	o/s/f shockabsorber leaking replaced both front shockabsorbers						
18 Wheels Check Torques							
45 Engine 1	engine oil leak,investigate leak, turbo leaking into air intake. reposition pipe						
45 Engine 2	exhaust leaking around turbo. Replaced gasket & new bolts fitted						
55 Tail Lift	replace faulty safety bar,repair worn threads on mounts						
99 Diagnostic Test	carryout diagnostic checks and erased fault codes,reset service indicator						
Safety Inspection							
Gearbox Oil & Filter Change							
Unplanned Repair	11/06/2018	13:59	11/06/2018	15:20	207,801	Redruth	RE023870
34 Lights	Replace damaged n/s/r fog light .						
Unplanned Repair	29/06/2018	16:00	29/06/2018	17:12	211,684	Redruth	RE024005
31 Battery Comms	Replace comms battery,						
Vehicle Deep Clean	17/07/2018	07:30	17/07/2018	16:17	215,746	Redruth	RE024096
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	17/07/2018	15:10	19/07/2018	16:18	215,746	Redruth	RE024101
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	A/c in saloon not working, condensor fan not working.
01 Air Conditioning 2	Electrical Auxs cab htr hot on the low,aircon salon u/s
02 Cab Ass Fire Extinguisher	Replace fire extinguishers.
02 Mirrors	Mirrors cracked blind spot mirror nearside, now replaced.
13 Brake Pads	Replace front brake pads.
18 Wheels Check Torques	
52 Electrical Aux	Replace torch.
Safety Inspection	
92 - C Service	
Service C	
Tail Lift 6 Monthly Inspection	Statutory Inspection

Defect Repair	30/07/2018	08:49	30/07/2018	13:52	217,591	Redruth	RE024194
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Heating 1	air con leaking water into saloon,investigate and rectify blockage in drain
02 Mirrors	Mirrors n/s mirror off.replaced damaged door mirror components
02 Windows/Glass	replace broken n/s door window switch

Defect Repair	06/08/2018	08:40	06/08/2018	12:29	219,148	Redruth	RE024242
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Doors Rear	Body Interior rear door stay broken,carried out repairs
---------------	---

Breakdown	18/08/2018	23:39	22/08/2018	11:49	221,742	Redruth	RE024331
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Charging System Breakdown	Alternator u/s, new on order. now fitted. put star on vehicle and erase faults. Battery Management light on
------------------------------	--

Vehicle Deep Clean	07/09/2018	09:08	07/09/2018	14:51	224,408	Redruth	RE024459
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/09/2018	14:51	11/09/2018	15:24	224,408	Redruth	RE024462
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	replace centre storage box button	
13 Brakes 1	adjust handbrake and rear brakes	
15 Steering 1	minor play in steering rack assembly,monitor	Monitoring
16 Suspension 1	o/s/f suspension wishbone has wear in balljoint within manufactures spec	Monitoring
17 Tyres Replace	replaced o/s/r and front tyres x4	
18 Wheels Check Torques		
52 Electrical Aux	carryout SAT NAV upgrade	
55 Tail Lift	tail lift marker lamps inop,requires further investigation	Awaiting Parts
86 Door Lock	side door handle not operating form outside,carried out adjustments,rectified	
Safety Inspection		

Breakdown	19/09/2018	22:17	19/09/2018	23:02	225,936	Redruth	RE024553
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	N/S headlight out
-----------	-------------------

Breakdown	24/09/2018	18:39	10/10/2018	12:38	226,779	Redruth	RE024583
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

41 Turbo	Boost Pressure Sensor Fault - Replaced sensor & broken pipe brackets + Gasket
43 Exhaust System 1	DPF blocked - Tunap Regen. Performed. Replaced cracked elbow from turbo - DPF
43 Exhaust System 2	EGR cooler bracket fallen off and EGR pipe fractured
99 Diagnostic Test	
Breakdown	limp mode; yellow warning light; not charging M531
Road Test	Extended roadtest

SAFETY INSPECTION	04/10/2018	11:39	05/10/2018	16:15	226,765	Redruth	RE024632
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

15 Steering 1	minor play in steering rack assembly,monitor
16 Suspension 1	o/s/f suspension wishbone has wear in balljoint within manufactures spec
18 Wheels Check Torques	
34 Emergency Lights	Replaced OSR side blue lamp
34 Lights	Replaced both front contour running LED lights
34 Lights Bulb Replacement	Replacde NSF side light bulb
55 Tail Lift	tail lift marker lamps inop,requires further investigation. Working fine this SI
85 Body Interior 1	Replaced broken side storage strap
Safety Inspection	

Vehicle Deep Clean	08/10/2018	14:06	09/10/2018	14:23	226,779	Redruth	RE024658
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	18/10/2018	09:30	18/10/2018	16:59	228,507	Redruth	RE024745
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

27 Transmission Automatic	Crew reports not going above 2nd Gear intermitently. Checked oil level. All ok
43 Exhaust System 1	DPF clean required even though carried out a short time ago
45 Engine 1	Occasionally drops into limp mode with no EML on.
99 Diagnostic Test	No faults with the gearbox. DPF ash content high (3.4g max is 2.6g)
Road Test	Extended road test showed no faults with the gearbox or engine

SAFETY INSPECTION	19/11/2018	16:13	22/11/2018	15:51	234,730	Redruth	RE024974
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Heating 1	Cab heater temperature control fault	
02 Cab Assembly 1	replaced glove box light bulb	
02 Cab Assembly 2	replaced broken drivers window switch assembly	
02 Windscreen	windscreen has stone chip,within MOTguidelines,monitor	Monitoring
13 Brakes 1	carryout brake fluid service	
15 Steering 1	o/s steering rack joint has minor wear,monitor	Monitoring
16 Suspension 1	o/s/f wishbone balljoint has lift within manufactures spec 2-3 mil,monitor	Monitoring
17 Tyres Replace	replaced n/s/r worn tyres x2	
18 Wheels Check Torques	retorque wheels after refitting and retorquing again after roadtest	
18 Wheels Removal	clean wheel contact surfaces and hub contact surfaces	
34 Lights	Electrical Auxs n/s daytime running light blub blown. Bulb replaced	
34 Lights Bulb Replacement	replace front side lamp bulbs	
45 Engine 1	engine oil leak from air intake pipe,pipe insecure removed and cleaned,see notes	
52 Electrical Aux	Carry out SAT NAV upgrade	
71 Body Exterior 1	exterior locker lock seized free off lock remove and lubricate,refit	
71 Body External Steps	Side step rumbling noise after step deployment. Motor U/S - Replaced step, rewir	
86 Door Lock	rear door lock faulty,carried out adjustments to mechanism	
86 Doors	Doors n/s rear door stay bent,repared	
86 Doors Rear	rear door trim broken,replaced trim	
89 Seats	saloon seat locking pin not functioning correctly,repared	
99 Diagnostic Test	carryout diagnostic checks and reset service indicator	
Check Winter Pack	winter bag not on vehicle,informed bag is on station ref, Colin Stribley supervi	Monitoring
Safety Inspection		
Sealing of stretcher clamp	Sealing of stretcher clamp	

93 - D Service
Service D

Vehicle Deep Clean	22/11/2018	10:03	22/11/2018	14:37	234,734	Redruth	RE025004
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	02/01/2019	08:52	02/01/2019	13:31	242,708	Redruth	RE025259
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	04/01/2019	11:45	07/01/2019	15:50	242,713	Redruth	RE025276
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen	windscreen has stone chip,within MOTguidelines,monitor	Monitoring
13 Brakes 1	Replace rear brake discs and pads.	
13 Handbrake	Replace handbrake shoes and expanders.	
15 Steering 1	o/s steering rack joint has minor wear,monitor	Monitoring
16 Suspension 1	o/s/f wishbone balljoint has lift within manufactures spec 2-3 mil,monitor	Monitoring
18 Wheels Check Torques		
86 Doors Rear	Replace o/s/r door stay bar.	
Check Winter Pack	winter bag now on vehicle,informed bag is on station ref, Colin Stribley supervi	
Safety Inspection		
MOT Pre Test		

Breakdown	12/01/2019	03:39	14/01/2019	09:01	243,453	Redruth	RE025339
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Dent To Taillift, spoke to crew, small dent vehicle not v.o.r.
-----------	--

Tail Lift Annual Service	17/01/2019	11:43	17/01/2019	14:56	244,471	Redruth	RE025375
---------------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Tail Lift Annual Service	Statutory Inspection and Weight Test carried out by SWL
Tail Lift 6 Monthly Inspection	Statutory Inspection

Vehicle Deep Clean	11/02/2019	08:00	11/02/2019	12:14	249,262	Redruth	RE025549
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	11/02/2019	08:32	12/02/2019	16:01	249,262	Redruth	RE025550
02 Windscreen	windscreen has stone chip,within MOTguidelines,monitor						
15 Steering 1	o/s steering rack joint has minor wear,monitor						
16 Suspension 1	o/s/f wishbone balljoint has lift within manufactures spec 2-3 mil,monitor						
18 Wheels Check Torques							
71 Body Exterior 1	Replace o/s/f body corner.						
71 Body External Steps	Side step not deploying. trace fault with motor sensor., new step fitted.						
Safety Inspection							
Travel Time							
MOT							
BREAKDOWN	05/03/2019	13:07	12/03/2019	15:16	253,210	Redruth	RE025696
01 Heating 1	Electrical Auxs Heater in back not working. Tested & replaced blower motor						
43 Exhaust System 1	Engine fumes in cab on occasions during shifts. EGR bypass pipe rubbed through						
55 Tail Lift	Lift ramp rail catches carry chair when raised. Adjusted loose OSR door stay						
86 Sliding Door	Doors Side door catch releases at times whilst driving. Slackened top cable						
99 Diagnostic Test	Checked and erased faults caused by fitting new EGR cooler						
Road Test	Road test and checked for leaks / levels						
Annual Heater Service	Annual Heater Serviced whilst in for a repair. Service & blower motor replaced						
Breakdown	17/03/2019	13:08	18/03/2019	17:35	254,051	Redruth	RE025765
27 Transmission Automatic	Clutch Gearbox not changing gear in D or with gear lever						
Breakdown	Power warning re gearbox, topped up gearbox and road tested.						
Vehicle Deep Clean	25/03/2019	07:01	25/03/2019	13:54	255,380	Redruth	RE025810
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	25/03/2019	08:29	28/03/2019	16:42	255,380	Redruth	RE025811
02 Windscreen	NMW repaired 3 x small stone chips across windscreen						
17 Tyres Replace	Replaced both OSR tyres and OSF tyre						

18 Wheels Check Torques	
85 Body Interior 1	saloon cupboard door loose,secured. secure side door catch assembly
99 Diagnostic Test	Diagnostic check, clear minor faults and reset the service indicator
Safety Inspection	
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab
92 - C Service	
Service C	
Annual Air Con Service	Annual Air Condition Service
Handbrake Cable Replacement	Replace rear handbrake cables
UB Fire Suppression Service	

SAFETY INSPECTION	07/05/2019	16:26	09/05/2019	10:09	262,457	Redruth	RE026080
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	refit damaged cab locker hinges	
13 Brakes 1	adjust rear brakes and handbrake	
15 Steering 1	replaced o/s track rod end and o/s track control arm	
15 Steering 2	check and adjust wheelalignment	
16 Suspension 1	both front wishbone balljoints have play,within manufactures wear limits	Monitoring
17 Tyres Replace	replace worn n/s/f tyre	
18 Wheels Check Torques	retorque wheels after refitting and retorque again after roadtest	
18 Wheels Removal	remove front wheels,derust and clean wheel contact surfaces	
52 Electrical Aux	replace faulty cab torch and charge point	
85 Body Interior 1	saloon seat base locking pin insecure,saloon locker hinge loose secured both	
86 Door Lock	side door lock not functioning correctly,carried out adjustments,rectified	
Install Saloon CCTV Camera	cctv system showing red light,requires investigation	Awaiting Parts
Safety Inspection		

Vehicle Deep Clean	09/05/2019	10:30	09/05/2019	15:37	262,466	Redruth	RE026093
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	01/06/2019	16:02	03/06/2019	15:57	263,779	Redruth	RE026223
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Battery Chassis Breakdown	Vehicle non starting , replaced chassis battery. MDT not powering up - battery check
------------------------------	---

SAFETY INSPECTION	14/10/2019	10:30	29/10/2019	13:30	265,575	Exeter	EX023628
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Ass Fire Extinguisher	Replace OOD extinguishers
02 Cab Assembly 1	window lock missing, replaced.
02 Mirrors	n/s mirror glass broken, replaced.
13 Brakes 1	o/s/f caliper slides seized, slide kit fitted.
16 Suspension 1	o/s wish bone ball joint u/s, all replaced.
16 Suspension 2	Rear spring, rear pads & rear shocks replaced.
18 Wheels Check Torques	
31 Battery Aux	Both + terminals loose, both secured
34 Lights	n/s/f white marker lamp inop-replaced.. N/S/R door interior lamp & wiring replac
45 Engine 1	Drive belt tenioner u/s. Replaced.
71 Body Exterior 2	N/S CCTV camera lens broken, replaced.
85 Body Interior 1	Replace broken scoop belt.
86 Door Seals	divers door seal replaced.
86 Sliding Door	Center hinge bearing u/s, Replaced.
Check Vehilce Call Signs	Remove old & fit new call sign stickers supplied by Autospray.
Install Saloon CCTV Camera	cctv system showing red light,requires investigation, checked by JC, all ok.
Road Test	To recheck following work.
Safety Inspection	
Axle Oil Change	Axle Oil Change done.
Tail Lift Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service

Vehicle Deep Clean	30/10/2019	07:00	30/10/2019	07:43	265,579	Exeter	EX023760
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	30/10/2019	07:00	30/10/2019	14:55	265,579	Exeter	EX023761
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	29/10/2019	13:31	29/10/2019	13:32	265,575	North Devon	NO014540
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	Raised to clear.

SAFETY INSPECTION	29/10/2019	13:32	29/10/2019	13:33	265,575	North Devon	NO014541
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	Raised to clear, job done EX23628.

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	29/10/2019	13:34	29/10/2019	13:35	265,575	North Devon	NO014542
18 Wheels Check Torques							
Safety Inspection	Raised to clear, job done EX023628						
Vehicle Deep Clean	Vehicle Deep Clean						
Tail Lift Inspection							
Breakdown	01/11/2019	12:53	06/11/2019	15:30	265,919	North Devon	NO014547
56 Comms Equipment Breakdown	Check over for power failing & not plotting correctly. Power button missing. MDT not plotting. Log desk informed.						
Emergency Deep Clean	07/11/2019	13:35	07/11/2019	15:54	266,847	North Devon	NO014557
Emergency Deep Clean							
Unplanned Repair	08/11/2019	08:30	08/11/2019	10:30	266,847	North Devon	NO014558
03 Instruments & Sensors 1	Reset service indicator & clear computer faults. Skylight leaking badly, see Notes.						
71 Body Exterior Roof							
Breakdown	11/12/2019	14:59	13/12/2019	14:50	273,524	North Devon	NO014617
03 Instruments & Sensors 1	Investigate EML cause. Find Pressure sensor failing - ordered. Fitted.						
34 Lights Bulb Replacement							
45 Engine Oil Top Up	Replaces head lamp bulb. Keeps going into limp mode Road test, no faults logged. To return to Bideford to collect tools.						
Breakdown							
Road Test							
Travel Time							
SAFETY INSPECTION	17/12/2019	12:00	20/12/2019	12:49	274,350	Exeter	EX024191
02 Windscreen Wipers	Replaced. Rear pads worn, replaced. N/S/R tyres worn to limit. Replaced.						
13 Brakes 1							
17 Tyres Replace							

18 Wheels Check Torques	
34 Emergency Lights	O/S/R top corner blue lens damaged. Next time
45 Engine 1	Oil leak at rear.
71 Body Exterior 1	O/S/R lower corner damage, repaired & cover replaced.
85 Body Interior 1	Equipment locker shelf missing.
86 Sliding Door	Sliding door body door pins damaged.
89 Seats	Replace front swivel seat bearings.
Safety Inspection	
Pollen Filter Change	Pollen Filter Changed
Fuel Filter Change	Change Fuel Filter
Air Filter Change	Air Filter Changed

Lack of Labour
Monitoring

Lack of Labour

Vehicle Deep Clean	20/12/2019	08:15	20/12/2019	14:19	274,350	Exeter	EX024223
---------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Tail Lift 12M Service & Weight	10/01/2020	09:15	10/01/2020	11:16	277,354	North Devon	NO014653
---	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Tail Lift Inspection	

Breakdown	13/01/2020	09:27	15/01/2020	12:30	277,950	North Devon	NO014657
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	
Breakdown	limp mode

Defect Repair	20/01/2020	11:00	04/02/2020	08:00	278,555	North Devon	NO014675
----------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

03 Instruments & Sensors 1	EML & limp mode. EGR valve replaced.
42 Coolant System	Coolant pump replaced.
45 Engine 1	Noisy bearing on front. Fan, idler & coolant pump replaced.
56 Comms Fitment	Comms Power Check dat not not powering up

SAFETY INSPECTION	06/02/2020	12:22	13/02/2020	10:30	278,693	Taunton	TN022952
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	tool box cover lid broken	
02 Cab Assembly 2	nearside door seal split at the bottom	Monitoring
02 Windscreen Wipers	front wipers not clearing screen, replaced front wiper blades	
13 Brake Test	carried out brake test , footbrake 41% handbrake 18%	
13 Brakes 1	front discs and pads u/s. replaced front discs and pads	
15 Steering 1	oil leak from power steering pipe , replaced clip on pipe and clean	
16 Suspension 1	slight play in nsf shockabsorber and sligh play in lower ball joint	Monitoring
16 Suspension 3	replaced offside rear anti roll bar lower bush	
17 Tyres Replace	replaced both offside rear tyres	
18 Wheels Check Torques	carried out extended road test and re-torque 180nm	
27 Transmission Automatic	centre prob bearing rubber u/s	
34 Emergency Lights	both rear top corner blue lights damaged	Monitoring
34 Lights Bulb Replacement	n/s day running light bulb u/s , replaced bulb test all ok	
44 Add Ad Blue	top up ad blue from main tank	
44 Fuel System 1	replaced fuel cap	
45 Engine 1	replaced dpf pressure sensor	
45 Engine 2	oil leak from intercooler and turbo intake pipe and air doser	
45 Engine Oil Top Up	topped up engine oil level	
52 Electrical Aux	attend to wire shorting out on starter moter ,see notes	
71 Body Exterior 1	both ns upper and lower saloon end caps damaged	Monitoring
71 Body External Steps	side step not deploying , lubricate step	
85 Body Interior 1	saloon bag strap broken on second shelf, replaced strap	
Medical Devices Check	mobimed batteries 87% & 88%	
Safety Inspection	carried out safety inspection	
Travel Time	to MOT	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change	
MOT	mot carried out at mercedes van centre	

Vehicle Deep Clean	14/02/2020	09:20	14/02/2020	15:56	278,762	North Devon	NO014719
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	14/02/2020	09:00	14/02/2020	09:30	278,762	North Devon	NO014721
----------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights Bulb Replacement	Replace head lamp bulb.
----------------------------	-------------------------

Defect Repair	19/02/2020	07:00	19/02/2020	07:45	279,084	Exeter	EX024755
----------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

86 Doors Rear	doors rear door stay bar broken, remove broken bolt and refit.
---------------	--

Breakdown	27/02/2020	19:55	27/02/2020	20:00	280,117	North Devon	NO014743
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	AUX battery failure-PCE seen						
-----------	------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	17/04/2020	06:31	18/04/2020	09:35	287,027	Exeter	EX025295
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

16 Suspension 1	rear spring eye lower bushes and arb worn x 2, REPLACED						
18 Wheels Check Torques							
34 Emergency Light System	insecure o/s/f top blue light, re[air and resecure						
34 Emergency Lights	both rear top corner blue lights damaged and insecure, replace						
34 Lighting System	Secure loose wire at rear of chassis.						
43 Exhaust System 1	tail pipe snapped off, REPLACED						
43 Exhaust System 2	DPF top bolt missing, BOLT REPLACED						
52 Electrical Aux	240v led x4 broken						
55 Tail Lift	tail lift lights inop plus ramp bent, Replace tilt sensor.						
71 Body Exterior 1	both ns upper and lower saloon end caps damaged, ends cap replaced						
85 Body Interior 1	broken bio strap bag storage and side locker strap, REPLACED						
86 Sliding Door	top lock cover broken, cover replaced.						
Safety Inspection							
Tail Lift Inspection							
UB Fire Supp 12mts Service	Service of fire suppression system						
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service completed inc exhaust replacement.						
Replace Handbrake Cables	Replace Handbrake Cables						
Engine Change Oil & Filter							

Vehicle Deep Clean	15/04/2020	10:45	15/04/2020	10:47	286,974	North Devon	NO014806
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Vehicle Deep Clean	15/04/2020	10:50	16/04/2020	11:20	286,974	North Devon	NO014807
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	14/05/2020	14:32	20/05/2020	14:29	289,940	Exeter	EX025591
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

01 Air Conditioning 1	A/C condensing fan inop
02 Mirrors	N/S wide angle damaged
15 Steering 1	Knock from steering rack
15 Steering 2	Slight play in N/S/F track rod end
16 Suspension 1	Both rear slipper pads split (front)
17 Tyres Replace	N/S/R outer tyre 3mm, Replaced.
17 Tyres Tracking	Carry out tracking x2 after rack fitted
18 Wheels Check Torques	
31 Battery Aux	Power failing CHECKED BATTERY FAILED REPLACED
31 Battery Comms	Power failing CHECKED BATTERY FAILED REPLACED
33 Ignition System	Supply new key.
43 Exhaust System 1	DPF mountings cracked REPLACED DPF and ELBOW
52 Electrical Aux	240v led covers cracked
54 Reversing Systems	Alarm light showing on DVR
85 Body Interior 1	Centre console lid pulled from hinge, stay bar pulled from box
85 Body Interior 2	Scoop locker corner shelf missing
85 Body Interior 3	velco missing from drip holders x3
86 Doors Rear	Rear door stay broken REPLACED
Road Test	Extended road test
Safety Inspection	
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service

Vehicle Deep Clean	13/05/2020	10:00	13/05/2020	15:59	289,888	North Devon	NO014857
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	08/06/2020	07:30	08/06/2020	09:00	292,404	North Devon	NO014886
----------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Sliding Door	Doors Side door not catching with loose connection. See Notes.
-----------------	--

Defect Repair	09/06/2020	07:30	09/06/2020	08:00	292,660	North Devon	NO014890
----------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

54 Reversing Systems	Body Exterior Rev Camera broken, refit loose camera.
----------------------	--

Breakdown	16/06/2020	15:04	16/06/2020	20:00	293,738	North Devon	NO014903
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windscreen	Replaced on staton by N.M.W.
Breakdown	10Cm crack N/S

SAFETY INSPECTION	03/07/2020	10:00	03/07/2020	10:00	296,317	Exeter	EX026050
18 Wheels Check Torques Safety Inspection	Inspection.						
SAFETY INSPECTION	03/07/2020	10:00	06/07/2020	13:33	296,317	Exeter	EX026051
02 Windscreen Wipers 16 Suspension 1 18 Wheels Check Torques 71 Body Exterior 1 89 Seats Safety Inspection Tail Lift Inspection	Washer inop. osf wish bone ball joints worn, replaced. JW CARRIED OUT 2ND RETORQUE Front Number plate smashed. Swivel seat pin loose, secured. B/head seat seat belt secured. adjust handrails,rectify grease nipples,SWL sticker 1 off only						Awaiting Parts Awaiting Parts
Vehicle Deep Clean	06/07/2020	06:06	06/07/2020	13:32	296,320	Exeter	EX026065
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	20/07/2020	15:30	20/07/2020	16:15	298,787	North Devon	NO014952
03 Instruments & Sensors 1 71 Body External Steps	Check computers & clear any faults. Side step hit & bent, straighten out frame & check operation.						
SAFETY INSPECTION	06/08/2020	13:20	07/08/2020	13:10	301,740	Exeter	EX026334
02 Windscreen Wipers 13 Brake Pads 17 Tyres Replace 18 Wheels Check Torques 31 Battery Chassis 31 Charging System 34 Lights Bulb Replacement 45 Engine 1	Washer inop - repaired previously Rear pads low REPLACED O/S/R + N/S/R/I worn REPLACED inc road test. Test & replace chassis battery. Battery/Charging Sys power warning when engine running - no fault on inspection replaced osf dip beam bulb tentioneer leaking REPLACED - Resonator leaking - RECTIFIED						

55 Tail Lift	Ramp/Lift/Tail Hoist tail lift handle bent - Rectified
71 Body Exterior 1	Front Number plate smashed Repaired previosly
71 Body Exterior 2	O/S bridge plate a bit insecure tightened
71 Body External Steps	Body Exterior sidestep not coming out RECTIFIED - running light faulty REPAIRED
Safety Inspection	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card

Vehicle Deep Clean	05/08/2020	08:30	06/08/2020	09:15	301,731	North Devon	NO014968
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	11/08/2020	06:37	25/08/2020	14:48	303,033	Exeter	EX026356
------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

002 Major Unit Replace Eng	Engine replaced.
17 Tyres Replace	N/S/F tyre replaced on return. Job number 251171.
45 Engine 1	SEE NOTES new engine required.

Breakdown	10/08/2020	20:11	11/08/2020	06:37	303,033	North Devon	NO014975
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Smoke, burning smell, knocking, LOP, AT EXETER WORKSHOP
-----------	---

Medical Devices Repair	04/09/2020	10:41	04/09/2020	10:46	303,033	MDT Exeter	TE000744
-------------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Decontaminated	Cleaned with clinell wipes
Defect Sheet Present No	
Defect Sheet Present Yes	
Medical Devices Repair	Replace EPCR Docking Station.

SAFETY INSPECTION	14/09/2020	11:00	17/09/2020	11:21	306,931	Exeter	EX026656
--------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------	-----------------

02 Cab Ass Fire Extinguisher	Fire extinguisher o.o.d - no stock
15 Steering 1	Power steering pump leaking from main bearing, Pump replaced.
18 Wheels Check Torques	Road test.
44 Fuel System 1	solo fuel cap not fitted
71 Body Exterior 1	Body Exterior reversing camera hanging, secured.
85 Body Interior 1	White centre console push button missing + hinge screws pulled RECTIFIED
85 Body Interior 2	drug cupboard screws pulled RECTIFIED

85 Body Interior 3 87 Stretcher Safety Inspection Tail Lift Inspection	bag storage Bio strap damaged REPLACED Stryker battery end of life REPLACED Y192725						
Vehicle Deep Clean	15/09/2020	09:20	15/09/2020	12:30	306,744	Exeter	EX026670
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	21/09/2020	08:00	21/09/2020	09:49	307,745	North Devon	NO015022
54 Warn Dev/System 56 Comms Equipment 86 Sliding Door	Doors side door alarm going off - connection broken Pt pulled microphone off wall exposed wires, remains removed & ordered. Doors side door alarming, replace broken top latch & adjusted.						
Breakdown	28/10/2020	20:01	29/10/2020	08:30	314,176	North Devon	NO015086
Breakdown	Stuck on Kerb SPOKE TO DARREN H AND D/O CHECKED OVER AND OK						
SAFETY INSPECTION	11/11/2020	14:00	13/11/2020	06:51	316,534	Exeter	EX027239
02 Cab Assembly 1 02 Mirrors 02 Windscreen Wipers 11 Axle Rear 13 Brake Pads 16 Suspension 1 17 Tyres 18 Wheels Check Torques 43 Exhaust System 1 55 Tail Lift 71 Body Exterior 1 85 Body Interior 1 Safety Inspection Engine Change Oil & Filter UB Fire Supp 6mts Service Tail Lift Inspection	SEE NOTES Body Exterior Nearside Wing Mirror top section glass smashed. screen washer bottle lid missing, cap replaced rear diff cover damaged and leaking oil, replace cover oil and gasket front brake pads worn, brake pads replaced r/o/s spring slipper split, slipper replaced o/s/f + n/s/r below trust limits, tyres repalaced top dpf securing bolt inseucre, bolt ressecured SEE NOTES SEE NOTES SEE NOTES UB Fire Supp 6mts Service, serviced						

Vehicle Deep Clean	09/11/2020	14:00	10/11/2020	15:30	316,485	North Devon	NO015113
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	16/11/2020	09:00	16/11/2020	10:30	316,903	North Devon	NO015124
17 Tyres Replace	Found n/s/r outer tyres flat on station.						
Vehicle Deep Clean	30/12/2020	10:30	30/12/2020	13:37	324,333	Exeter	EX027676
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	31/12/2020	11:00	08/01/2021	08:00	324,340	Exeter	EX027684
02 Cab Ass Fire Extinguisher	Extinguishers O.O.D. Exchanged.						
17 Tyres Replace	Replace n/s/r inner tyre						
18 Wheels Check Torques							
44 Fuel System 1	Replace solo cap - fuel filler neck damaged. Order tank						
55 Tail Lift	Platform leds on, Repaired by SWL's.						
56 Comms Equipment	Microphone in cab hanging. Reattached.						
71 Body Exterior 1	O/S/R lower corner damage, replaced.						
85 Body Interior 1	Equipment locker shelf missing, replaced.						
86 Sliding Door	Top latch cover missing, replaced. top strike pin broken						
Safety Inspection							
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Tail Lift Inspection	supply SWL tilt sensor switch						
Vehicle Deep Clean	07/01/2021	12:34	07/01/2021	15:05	324,340	Exeter	EX027746
Vehicle Deep Clean	Vehicle Deep Clean						

Defect Repair	05/02/2021	14:30	05/02/2021	17:00	328,566	North Devon	NO015287
02 Cab Assembly 1 17 Tyres 17 Tyres Replace	New log book supplied. Body Exterior Knocking from under vehicle, Screw in tyre. All four rear required, two bellow limit, 1 with screw. ATS Mobile to attend.						
Vehicle Deep Clean	11/02/2021	13:00	12/02/2021	09:44	329,619	North Devon	NO015305
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	16/02/2021	06:00	17/02/2021	13:26	329,665	Exeter	EX028078
01 Heating 1 02 Cab Assembly 1 13 Brakes 1 16 Suspension 1 18 Wheels Check Torques 55 Tail Lift 71 Body Exterior 1 85 Body Interior 1 Safety Inspection MOT	Body Interior cab will only blow hot air, flap control motor sticking,unit repla Driver side sun visor ripped off, SUN VISOR REPLACED Replace rear discs, pads, hand brake shoes & expanders.see notes Replace rear lower ARB link bushes. replaced SEE NOTES trye pressure stickers incorrect, remove and replace SEE NOTES						
SAFETY INSPECTION	23/02/2021	10:00	23/02/2021	12:00	330,473	North Devon	NO015340
16 Suspension 1 18 Wheels Check Torques Safety Inspection	Knocking sound coming front, replace o/s/f drop link at Exeter.						
Breakdown	20/03/2021	14:57	22/03/2021	13:00	334,169	North Devon	NO015399
Breakdown	ABS ESP warning on - repaired by WTR.						

ACCIDENT	08/04/2021	11:00	09/04/2021	13:30	337,561	Exeter	EX028519
02 Windows/Glass	os saloon glass smashed						
Vehicle Deep Clean	09/04/2021	08:30	09/04/2021	14:31	337,561	North Devon	NO015451
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	16/04/2021	07:56	19/04/2021	12:00	338,509	North Devon	NO015461
18 Wheels Check Torques							
71 Body Exterior 1	O/S/C lower profile pulling away from battery box. Refix with Mono bolts & seal.						
85 Body Interior 1	See Notes.						Awaiting Parts
89 Seats	Rear swivel seat RH arm rest pin missing. Remove arm rest unit part aquired.						
Safety Inspection	Chassis inspection by WTR.						
Breakdown	27/05/2021	20:28	28/05/2021	11:30	345,297	North Devon	NO015579
34 Lights Bulb Replacement	Replace n/s indicator repeater bulb.						
85 Body Interior 1	See Notes.						
Breakdown	side indicator intermittent						
Travel Time	To Ilfracombe station & return.						
Defect Repair	18/06/2021	09:36	18/06/2021	14:17	348,349	North Devon	NO015631
01 Heating 1	Other cab aircon u/s. Cab blower replaced.						
02 Cab Assembly 1	Radiator/Cooling Sys cab fan not working. Cab blower replaced.						
02 Mirrors	Replace smashed n/s mirror cover.						
SAFETY INSPECTION	22/06/2021	07:30	25/06/2021	14:15	348,896	North Devon	NO015644
13 Brakes 1	Replace front discs & pads.						
16 Suspension 1	Replace 1 rear spring buffer.						
17 Tyres Replace	O/S/F worn to limit. W/O00557277.						
18 Wheels Check Torques							

34 Lights	Replace n/s indicator repeater bulb.						
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables completed.						
Engine Change Oil & Filter	Done.						
Tail Lift Inspection							
Annual Heater Service	Annual Heater Service completed.						
Vehicle Deep Clean	22/06/2021	08:19	22/06/2021	08:20	348,896	North Devon	NO015645
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	22/06/2021	08:20	22/06/2021	14:30	348,896	North Devon	NO015646
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	16/07/2021	19:24	19/07/2021	12:25	351,886	North Devon	NO015702
Breakdown	cracked rear offside blue light- vehicle being used not VOR					Monitoring	
Breakdown	19/07/2021	07:05	19/07/2021	12:22	352,399	North Devon	NO015704
Breakdown	side door malfunctioning-Vehicle being used so not VOR					Monitoring	
SAFETY INSPECTION	21/08/2021	06:00	21/08/2021	07:18	357,264	Exeter	EX029647
18 Wheels Check Torques							
Safety Inspection							
SAFETY INSPECTION	21/08/2021	06:00	24/08/2021	08:32	357,264	Exeter	EX029648
13 Brakes 1	SEE NOTES						
17 Tyres Replace	n/s/f tyre below 1.5mm. Tyre replaced.						
18 Wheels Check Torques							
31 Battery Aux	Battery/Charging Sys Tail lift battery not holding a charge, rectified						
34 Emergency Light System	Emg Warning Devices O/S/R corner blue light broken, rectified						
34 Emergency Lights	o/s/r upper blue light smashed. unit replaced						
34 Lighting System	Body Exterior O/S/F day light running light not working, rectified						

34 Lights	SEE NOTES
45 Engine 1	SEE NOTES
55 Tail Lift	SEE NOTES
71 Body Exterior 1	Insecure spray surpressor n/s. remove seized bolt and replace bolt.
85 Body Interior 1	SEE NOTES
Road Test	road test and brake test carried out
Safety Inspection	
UB Fire Supp 12mts Service	Service of fire suppression system, no faults found
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service, carried out twelve month check.
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
Tail Lift Inspection	

Vehicle Deep Clean	19/08/2021	08:20	19/08/2021	15:50	357,212	North Devon	NO015779
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

ACCIDENT	13/09/2021	00:00	13/09/2021	00:00	357,264	Unallocated	Un001042
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior 1	FOI - Nearside Top Saloon
--------------------	---------------------------

SAFETY INSPECTION	27/09/2021	12:55	29/09/2021	12:03	357,410	Dorchester	DC026027
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher	extinguishers OOD	
16 Suspension 1	slight play in struts and arms	
17 Tyres Replace	replace all rear	
18 Wheels Check Torques		
33 Ignition System	Key fob faulty.Replace	
44 Add Ad Blue	top up	
45 Engine 1	Jactone not routed correctly	
45 Engine Oil Top Up	top up	
71 Body Exterior 2	Telma heatshield rubbing	
71 Body External Steps	rear step starting to rot	
85 Body Interior 1	remove metal straps from saloon	
85 Body Interior 2	stretcher guide buffer damaged	
86 Doors Rear	rear door top lock not securing, new cable required, temp repair	Awaiting Parts
86 Sliding Door	C/L not operating on sliding door	
89 Seatbelts	untangle rear seatbelts	
Check Winter Pack		
Safety Inspection		

Annual Air Con Service	Annual Air Condition Service						
Vehicle Deep Clean	29/09/2021	12:42	30/09/2021	09:30	357,424	Dorchester	DC026046
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	30/09/2021	11:00	30/09/2021	13:35	357,432	Dorchester	DC026053
03 Instruments & Sensors 1	service light on						
71 Body Exterior 1	Change call signs						
86 Doors Rear	rear door top lock not securing, new cable required, temp repair						
O2 Pipeline Annual Inspection	29/09/2021	13:00	29/09/2021	14:00	357,424	MDT Weymouth	DW000715
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - no faults						
Unplanned Repair	26/10/2021	09:00	26/10/2021	09:45	361,435	Dorchester	DC026215
86 Sliding Door	Outer handle ripped off.Fit new						
Unplanned Repair	26/10/2021	19:00	27/10/2021	11:40	361,435	Dorchester	DC026219
02 Glass / Windows	Windscreen 12-15inch Crack across drivers side.						
SAFETY INSPECTION	03/11/2021	07:49	04/11/2021	08:23	362,623	Dorchester	DC026267
18 Wheels Check Torques							
44 Add Ad Blue	top up						
45 Engine Oil Top Up	top up						
55 Tail Lift	rails seized and requires SWL signs						
71 Body Exterior 1	Body Exterior cracked casing of black runner on side door						
71 Body External Steps	rear step rotted						
86 Door Hinges	OSR door hinge pins worn						
86 Door Lock	rear door cylinder seized and locker door barrel broken						
86 Sliding Door	Doors cracked casing of black runner on side door						
89 Seats	saloon seatbase plunger seized						
Safety Inspection							
Tail Lift Inspection							

Vehicle Deep Clean	04/11/2021	09:00	04/11/2021	12:26	362,636	Dorchester	DC026283
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	07/11/2021	18:17	08/11/2021	10:29	363,636	Dorchester	DC026308
54 Sirens Breakdown	Sirens inop Sirens Not Working						
Breakdown	25/11/2021	17:41	26/11/2021	07:30	365,506	Dorchester	DC026450
87a - Medical Equipment Repair Breakdown	Mangar not charging side step bent						
SAFETY INSPECTION	16/12/2021	08:07	17/12/2021	09:30	367,640	Dorchester	DC026603
01 Heating 1 02 Glass / Windows 18 Wheels Check Torques 43 Exhaust System 1 44 Add Ad Blue 45 Engine Oil Top Up 55 Tail Lift 71 Body External Steps 86 Sliding Door Safety Inspection Travel Time	Saloon heater exhaust and intake split Drivers window switch broken,replace Carry out regen Hydraulic tank corroded rear step rotted Doors cracked casing of black runner on side door Awaiting Parts						
Vehicle Deep Clean	17/12/2021	13:16	17/12/2021	16:57	367,654	Dorchester	DC026626
Vehicle Deep Clean	Vehicle Deep Clean						
Wear & Tear Repair	17/12/2021	14:00	17/12/2021	15:00	367,654	MDT Weymouth	DW000765
Wear & Tear Repair	90' angled O2 probes fitted/split in line repaired						

Unplanned Repair	23/12/2021	13:00	23/12/2021	13:45	368,358	Dorchester	DC026681
45 Engine Ad Blue	AdBlue light on						
Breakdown	25/12/2021	16:01	27/12/2021	09:54	368,633	Dorchester	DC026692
Breakdown	? aux battery no heating or lights t the back						
Breakdown	30/12/2021	01:34	30/12/2021	12:18	369,175	Dorchester	DC026712
31 Battery Aux Breakdown Travel Time	Batteries showing low.Carry out checks,replace blown fuse Loss of power						
SAFETY INSPECTION	26/01/2022	08:30	28/01/2022	11:45	373,144	Dorchester	DC026942
13 Brake Pads	front pads worn						
16 Suspension 1	2 slipper pads delaminated						
16 Suspension 2	rear ARB link bushes worn						
16 Suspension 3	front struts and arms worn						
18 Wheels Check Torques							
44 Add Ad Blue	top up						
44 Fuel System 1	EML on adblu fault.EGR valve fault.Part on back order.						
45 Engine 1	to book filter						
55 Tail Lift	Hydraulic tank corroded NO PARTS						
56 Radio	cab radio hand mic cable damaged, replacement required						
86 Door Lock	rear door barrel siezed						
89 Seats	attendant seat arm rest loose						
Safety Inspection							
Travel Time							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Tail Lift Inspection							
Pollen Filter Change	Pollen Filter Change						
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
Brake Fluid Change	Brake Fluid Change						
MOT							
Engine Change Oil & Filter							

Awaiting Parts

Vehicle Deep Clean	28/01/2022	11:41	28/01/2022	17:28	373,164	Dorchester	DC026970
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/02/2022	11:00	21/02/2022	11:19	376,125	Dorchester	DC027108
42 Coolant System	coolant level low						
Breakdown	27/02/2022	13:11	01/03/2022	10:49	376,815	Dorchester	DC027144
01 Air Conditioning 1	air con leak from valve block at radiator						
42 Radiator	Leaking						
86 Door Lock	Replace sliding door barrel assembly and check operation						
Breakdown	Unable to open side door from outside						
SAFETY INSPECTION	08/03/2022	12:56	10/03/2022	14:40	377,841	Dorchester	DC027212
18 Wheels Check Torques							
Safety Inspection							
44 Fuel System 1	EML on adblu fault.EGR valve fault.Part on back order.						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Wheel Hub Flanges Replaceme							
17 Tyres Replace	Replace n/s/f						
02 Windscreen Wipers	Replace						
44 Add Ad Blue							
Travel Time							
Vehicle Deep Clean	11/03/2022	08:07	11/03/2022	11:48	377,866	Dorchester	DC027247
Vehicle Deep Clean	Vehicle Deep Clean						
02 Pipeline Annual Inspection	08/03/2022	15:00	08/03/2022	16:00	377,841	MDT Weymouth	DW000827
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - no faults						

Unplanned Repair	17/03/2022	11:55	17/03/2022	11:57	378,118	Dorchester	DC027292
Travel Time	travel to and from bridport to unlock and retrieve keys from cab						
Unplanned Repair	24/03/2022	13:45	24/03/2022	14:18	379,330	Dorchester	DC027340
55 Tail Lift	not deploying						
Breakdown	17/04/2022	19:47	19/04/2022	07:16	383,400	Dorchester	DC027497
Breakdown	1cm chip with cracks						
SAFETY INSPECTION	22/04/2022	09:09	25/04/2022	13:48	384,029	Dorchester	DC027543
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
44 Fuel System 1	EML on adblu fault, injector ordered, faults cleared					Awaiting Parts	
42 Coolant System	coolant leak from EGR hose, pinhole in hose						
41 Air Intake	air intake to turbo seal split and boost seals leaking						
41 Turbo	turbo passing oil					Monitoring	
86 Sliding Door	bottom catch cover damaged, no parts						
13 Brake Pads	rears low						
17 Tyres Replace	NSR outer low tread						
45 Engine Oil Top Up	top up						
Vehicle Deep Clean	26/04/2022	14:30	27/04/2022	12:06	384,044	Dorchester	DC027578
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	18/05/2022	16:50	20/05/2022	07:28	386,982	Dorchester	DC027693
Breakdown	Battery wont stay charged						

SAFETY INSPECTION	08/06/2022	11:56	10/06/2022	10:48	389,625	Dorchester	DC027841
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
Replace Handbrake Cables			Replace Handbrake Cables				
44 Fuel System 1			EML on adblu fault, injector ordered, faults cleared				
41 Turbo			turbo passing oil				
55 Tail Lift			Hydraulic tank corroded and SWL sign missing				
86 Doors			NSF door window switch damaged				
13 Brake Pads			front pads and discs worn				
52 Electrical Aux			OSR CCTV camera inop				
44 Add Ad Blue			top up				
45 Engine Oil Top Up			top up				
15 Steering 1			power stg pump leaking				
71 Body Exterior 1			siren surround loose				
Travel Time			take to dorchester				

Vehicle Deep Clean	13/06/2022	13:20	15/06/2022	13:25	389,639	Dorchester	DC027878
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean			Vehicle Deep Clean				
--------------------	--	--	--------------------	--	--	--	--

Unplanned Repair	15/06/2022	14:30	15/06/2022	14:58	389,810	Dorchester	DC027904
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

31 Battery Comms			MDT dropping out, battery check				
------------------	--	--	---------------------------------	--	--	--	--

SAFETY INSPECTION	13/07/2022	10:30	14/07/2022	12:34	393,785	Dorchester	DC028084
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
34 Lights			NSR upper stp/tail not working				
44 Add Ad Blue			top up				
45 Engine Oil Top Up			top up				
02 Windscreen			chip in swept area			Monitoring	
02 Windscreen Wipers			worn				
55 Tail Lift			LEDs not working				
17 Tyres Replace			NSF worn on outer edge				

Vehicle Deep Clean	15/07/2022	09:19	17/07/2022	17:35	393,797	Dorchester	DC028095	
Vehicle Deep Clean	Vehicle Deep Clean							
Unplanned Repair	19/07/2022	13:00	19/07/2022	13:24	393,869	Dorchester	DC028114	
31 Charging System Battery	MDT and radio dropping/cutting out							
Breakdown	25/07/2022	14:31	25/07/2022	15:30	395,077	Dorchester	DC028162	
Breakdown	MDT not plotting							
Unplanned Repair	11/08/2022	14:30	11/08/2022	14:52	397,758	Dorchester	DC028267	
55 Tail Lift	not deploying							
SAFETY INSPECTION	19/10/2022	10:49	19/10/2022	10:50	401,100	St Leonards	SL037887	
18 Wheels Check Torques Safety Inspection								
SAFETY INSPECTION	19/10/2022	10:51	04/11/2022	07:55	401,100	St Leonards	SL037888	
18 Wheels Check Torques Safety Inspection								
02 Windscreen	chip in swept area					Monitoring		
71 Body Exterior 1	Body Exterior N/S/F bumper							
13 Brake Pads	Warning light on							
13 Brakes 1	Retarder not working							
55 Tail Lift	Loose sensor going off all the time and replace gate							
31 Battery Comms	Comm batt power failing							
34 Emergency Lights	blue light loose in between corner lights							
24 Driveshaft 1	Drive line vibration							
86 Sliding Door	Not locking							

Engine Change Oil & Filter	Service of fire supression system
UB Fire Supp 12mts Service	Annual Heater Service
Annual Heater Service	Replace wiper motor
02 Windscreen Wipers	Replace P/S hose
15 Steering 1	Replace cracked rear leaf springs
16 Suspension 1	Both Belt Tensioners Worn, lower tensioner is cracked and split in half
45 Engine 1	
43 Exhaust System 1	
17 Tyres Replace	Replace 4x worn tyres
86 Doors Rear	

Vehicle Deep Clean	07/11/2022	08:59	07/11/2022	09:06	401,100	St Leonards	SL038040
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	07/11/2022	09:07	07/11/2022	09:08	401,100	St Leonards	SL038041
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	07/11/2022	09:08	08/11/2022	10:00	401,100	St Leonards	SL038042
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	01/12/2022	19:32	02/12/2022	07:30	401,100	St Leonards	SL038307
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	retarder isn't working;horn not working;siren faut	Monitoring
-----------	--	------------

Breakdown	05/12/2022	20:52	07/12/2022	06:37	402,786	St Leonards	SL038352
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	tail lift and MDT not working; VOR
-----------	------------------------------------

Unplanned Repair	16/12/2022	14:00	17/12/2022	16:00	404,544	St Leonards	SL038510
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Charging System	Alternator U/S. Replaced alternator and retested, charging ok.
--------------------	--

Breakdown	31/12/2022	07:10	31/12/2022	18:39	404,544	St Leonards	SL038650
Breakdown	front nearside tyre worn						
Breakdown	28/01/2023	00:00	28/01/2023	09:10	408,829	St Leonards	SL038939
Breakdown	Sat Nav doesn't power on						
Breakdown	08/02/2023	10:44	08/02/2023	14:00	408,900	St Leonards	SL039039
Breakdown	N/S rear Outer Puncture - ATS replaced						
Medical Devices Repair	16/02/2023	09:24	16/02/2023	09:29	408,900	MDT Weymouth	DW001118
Decontaminated	Cleaned with clinell wipes						
Defect Sheet Present No							
Defect Sheet Present Yes							
Medical Devices Repair	O2 leak, traced to top port, replaced seal kit and tested.						
Vehicle Deep Clean	14/02/2023	14:06	16/02/2023	08:55	410,900	St Leonards	SL039104
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	16/02/2023	14:18	20/02/2023	12:30	410,900	St Leonards	SL039135
18 Wheels Check Torques							
Safety Inspection							
02 Windscreen	chip in swept area						
Breakdown	retarder not operating. contacts worn in control box. replace						
Tail Lift Inspection							
MOT							
13 Handbrake	Handbrake excess travel. adjust shoes and cables.						
34 Lights	ns no plate light damaged. ns main beam blown. replace both						
71 Body Exterior 1	osr lower corner cap broken off. replaced cap and reflector						
86 Sliding Door	sliding door upper magnet tor. replaced magnet.						

55 Tail Lift 45 Engine 1 24 Driveshaft 1 Travel Time	trolley stop jammed. removed and freed off. - retightened both handrails. os engine mount split and worn. replace Propshaft centre bearing pulled out of mount. replace bearing						
Vehicle Deep Clean	16/02/2023	08:00	16/02/2023	08:00	410,900	St Leonards	SL039156
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	24/02/2023	02:17	24/02/2023	14:00	413,000	St Leonards	SL039195
Breakdown 44 Fuel System 1 45 Engine 1	possibl fuel leak Fuel leak. No fault found Engine oil leak - Replace Turbo seal and noise damper						
Breakdown	03/04/2023	13:07	04/04/2023	06:00	415,000	St Leonards	SL039577
Breakdown	MDT Keeps Powering Down						Monitoring
Breakdown	08/04/2023	19:01	09/04/2023	05:35	417,000	St Leonards	SL039638
Breakdown	mdt keeps turning off						
Breakdown	08/04/2023	19:02	09/04/2023	06:05	418,000	St Leonards	SL039639
Breakdown	back door catch doesnt unlock						
BREAKDOWN	22/04/2023	06:00	22/04/2023	10:00	429,061	St Leonards	SL039849
86 Doors Travel Time	Unable to open R/Doors Ferndown to Dorchester & Return.						
02 Pipeline Annual Inspection	18/04/2023	11:43	18/04/2023	11:49	419,000	MDT Ferndown	TF002647
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - replaced 1x Outlet port seal kit.						

Unplanned Repair	09/05/2023	15:58	09/05/2023	16:03	432,214	St Leonards	SL040064
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior 1	Grill Damaged. Grill surround straightened. Resecured grill.
86 Door Lock	Vehicle locking when driving. changed settings via texa
31 Battery Aux	Vehicle powering down. check batteries, ok. charging ok. unable to fault
34 Lights Bulb Replacement	O/S/F DRL light n/w

Breakdown	13/05/2023	07:52	15/05/2023	16:00	433,071	St Leonards	SL040105
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	chipped/cracked windscreen	Monitoring
-----------	----------------------------	------------

Vehicle Deep Clean	16/05/2023	14:40	17/05/2023	12:00	433,120	St Leonards	SL040149
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	18/05/2023	06:00	19/05/2023	16:00	433,120	St Leonards	SL040168
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques		
Safety Inspection		
Breakdown	chipped/cracked windscreen	
86 Doors Rear	Rear door hinges worn. Monitor	Monitoring
02 Windscreen	To be replaced by National windscreens - Friday	
85 Body Interior 1	Fit P clips for AVP	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service	
Tail Lift Inspection		
16 Suspension 1	Front shock absorbers excessive play in upper mounts. replaced	
13 Brake Pads	Rear brake pads worn. discs ok. replaced pads.	
13 Brakes 1	Front brake pads and discs worn. replace kit.	
01 Air Conditioning 1	Saloon AC condensor fan seized. replaced fan.	
71 Body Exterior 1	osf lower body corner cap damaged. replaced. - ns mirror damage. replace shell.	
02 Windscreen Wipers	Washers u/s. pump blocked. unblocked and cleaned reservoir.	
34 Lights	ns drl and sidelight blown. replace bulbs.	
45 Engine 1	oil leak from intake pipe/seals. replace intake pipe and seals and cleaned.	
86 Sliding Door	Sliding door wiring damaged. replaced/repared wiring.	
19 Chassis 1	Rear mudflap cracked. Monitor	Monitoring
89 Seats	Both swivel saloon seats bearings worn. replace bearings/shims.	
55 Tail Lift	Multiple tail lift defects. See notes.	

Breakdown	12/06/2023	16:23	13/06/2023	09:10	436,228	St Leonards	SL040528
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	fumes in cab
44 Fuel System 1	Fuel leak. (see notes)
44 Fuel System 2	Check fuel level - Replace sender if required

Vehicle Deep Clean	27/06/2023	09:14	27/06/2023	11:34	438,332	St Leonards	SL040747
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	27/06/2023	12:00	28/06/2023	13:00	438,332	St Leonards	SL040750
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
86 Doors Rear	Rear door hinges worn. Monitor
19 Chassis 1	Rear mudflap cracked. Monitor
Supply Sat Nav	Comms Power Check Sat Nav not getting past boot screen
56 Comms Equipment	Comms Power Check Not Tracking
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Air Filter Change	Air Filter Change
Pollen Filter Change	Pollen Filter Change
Tail Lift Inspection	
Engine Change Oil & Filter	
55 Tail Lift	Flasher not working. Replaced LED
71 Body Exterior 1	Call sign lettering missing.
02 Windscreen Wipers	Windscreen washer jets ot working.
13 Handbrake	Cab handbrake travel becomming excessive & requires adjustments.

Replace Vehicle Fuel Card	07/07/2023	18:00	07/07/2023	18:10	438,410	St Leonards	SL040927
----------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
---------------------------	---------------------------

Breakdown	29/07/2023	07:44	29/07/2023	18:00	438,500	St Leonards	SL041327
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	NS wing mirror smashed
Travel Time	

Vehicle Deep Clean	08/08/2023	07:32	08/08/2023	10:55	443,822	St Leonards	SL041444
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/08/2023	10:30	11/08/2023	10:15	445,822	St Leonards	SL041472
18 Wheels Check Torques							
Safety Inspection							
34 Lights Bulb Replacement	Lighting System off side rear red marker light out						
Tail Lift Inspection							
71 Body Exterior 1	NSF Fog light surround missing. replaced.						
34 Lights	NSR marker inop. traced to faulty wiring. replace wiring loom section and light.						
85 Body Interior 1	OSR Door stay bolt bent. replace bolt.						
55 Tail Lift	Warning lights not working						
27 Transmission Automatic	Rear gearbox mount split away						
Unplanned Repair	04/09/2023	14:00	11/09/2023	19:01	447,956	St Leonards	SL041825
45 Engine 1	Fan belt snapped						
55 Tail Lift	Replace flap bar						
Breakdown	14/09/2023	01:04	14/09/2023	11:03	448,102	St Leonards	SL041930
Breakdown	Rear Door Handle Broke						
Breakdown	14/09/2023	01:06	14/09/2023	11:06	448,102	St Leonards	SL041931
Breakdown	N/S/F Headlight Gone						
Breakdown	14/09/2023	01:07	14/09/2023	11:08	448,102	St Leonards	SL041932
Breakdown	Fire Suppression Warning						
Vehicle Deep Clean	16/09/2023	07:00	17/09/2023	07:00	448,111	St Leonards	SL041952
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	19/09/2023	09:00	20/09/2023	16:40	448,111	St Leonards	SL041992
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Fuel Filter Change	Change Fuel Filter
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
Annual Air Con Service	Annual Air Condition Service
Tail Lift Inspection	
Recall Notification	Mercedes airbag recall
55 Tail Lift	Tail lift side rails fixings insecure & bolts missing.
86 Doors	N/S Side door roller bearings seizing upon opening & closing.
02 Cab Assembly 1	Cab drivers seat belt slightly frayed.
71 Body External Steps	N/S Side step not opening.
87 Stretcher	Stretcher belts jamming main head rest tilt ram . (Wrongly fitted all round.).
13 Brake Test	Carry out brake test.
86 Sliding Door	N/S Sliding door upper catch covering missing.

Vehicle Deep Clean	27/10/2023	14:41	29/10/2023	11:00	449,958	St Leonards	SL042526
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	31/10/2023	06:00	31/10/2023	16:00	449,958	St Leonards	SL042572
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
42 Coolant System	Radiator/Cooling Sys COOLANT LEVEL WARNING
Replace Handbrake Cables	Replace Handbrake Cables
86 Door Seals	n/s door seal, split
31 Battery Chassis	Chassis battery old and weak
71 Body Exterior 1	Camera lens cover damaged on N/S
85 Body Interior 1	Steering wheel in poor condition and cover loose

Vehicle Deep Clean	09/12/2023	11:05	10/12/2023	16:00	452,572	St Leonards	SL043123
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	11/12/2023	09:00	15/12/2023	12:20	452,572	St Leonards	SL043142
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
 Safety Inspection
 Annual Heater Service
 UB Fire Supp 12mts Service
 UB Fire Supp 6mts Service
 Tail Lift Inspection
 13 Handbrake
 86 Doors Rear
 86 Sliding Door
 19 Chassis 1
 16 Suspension 1
 16 Suspension 2
 16 Suspension 3
 19 Chassis 2
 42 Coolant System
 27 Transmission Automatic

Annual Heater Service
 Service of fire suppression system
 UB Fire Supp 6mts Service
 Adjusted handbrake shoes and cables.
 OSF Door hinge worn.
 Sliding door upper latch insecure. resecured to door.
 Fuel tank heatshield insecure. repaired and resecured
 NSR Spring buffers split. replaced.
 Rear shock absorbers corroded. replaced
 Rear anti roll bar lower drop link bushes worn. replaced bushes.
 Rear mudflap cracked and insecure. resecured
 Coolant leak from coolant temperature sensor. replaced sensor and cleaned.
 Oil leak from transmission oil cooler. (see notes)

Monitoring

Breakdown	03/01/2024	15:53	03/01/2024	17:24	454,003	St Leonards	SL043457
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Rear Door Jammed Shut. Replaced cable for upper latch on osr door.						
-----------	--	--	--	--	--	--	--

SAFETY INSPECTION	22/01/2024	06:00	22/01/2024	11:50	455,151	St Leonards	SL043669
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
 Safety Inspection
 86 Doors Rear
 02 Mirrors
 UB Fire Supp Repair
 Brake Fluid Change
 MOT
 89 Seats

OSF Door hinge worn.
 Mirrors Passenger Wing mirror shattered on morning vdi
 Engine fire suppression alarm
 Brake Fluid Change
 Done 19.01.24
 N/S/F seat base cover starting to split

Monitoring

Monitoring

Vehicle Deep Clean	23/01/2024	06:00	23/01/2024	14:18	455,151	St Leonards	SL043682
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	26/01/2024	20:41	28/01/2024	12:56	455,468	St Leonards	SL043736
Breakdown	Fumes in cab						
45 Engine 1	Injector seals leaking. injector 1 & 5. cleaned carbon and replaced seals.						
O2 Pipeline Annual Inspection	05/03/2024	11:13	05/03/2024	11:14	457,528	MDT Weymouth	DW001783
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
SAFETY INSPECTION	07/03/2024	06:00	08/03/2024	11:51	457,528	St Leonards	SL044296
18 Wheels Check Torques							
Safety Inspection							
86 Doors Rear	OSF Door hinge worn.					Monitoring	
89 Seats	N/S/F seat base cover torn. replaced base, cushion and cover.						
Tail Lift Inspection							
02 Cab Assembly 1	- Cab Torch u/s. replaced torch -N/S Window switch broken. replaced						
34 Lights Bulb Replacement	OSF Drl bulb blown. replaced						
86 Sliding Door	(SEE NOTES)						
86 Door Lock	Side locker lock barrell broken. replaced.						
55 Tail Lift	-NS platform light U/S replaced - o/s hose perished. replaced						
85 Body Interior 1	Underseat locker door hinge loose. resecured.						
16 Suspension 1	osr road spring both buffers split. replaced						
13 Brake Pads	Front pads worn. discs measured ok. replaced pads and slider kit.						
17 Tyres Replace	X4 Rear tyres replaced.						
71 Body Exterior 1	Tail lift bridge plate guides insecure. resecured to body.						
Vehicle Deep Clean	09/03/2024	06:30	09/03/2024	10:09	457,566	St Leonards	SL044330
Vehicle Deep Clean	Vehicle Deep Clean						
AVP Check	11/03/2024	09:00	11/03/2024	10:30	457,717	St Leonards	SL044348
Complete AVP Check	Carry out AVP check						
AVP Check	12/03/2024	09:30	12/03/2024	11:00	457,785	St Leonards	SL044371

Complete AVP Check	Carry out AVP check						
AVP Check	13/03/2024	08:40	13/03/2024	09:50	457,916	St Leonards	SL044392
Complete AVP Check	Carry out AVP check						
AVP Check	14/03/2024	08:30	14/03/2024	10:00	457,968	St Leonards	SL044410
Complete AVP Check	Carry out AVP check						
AVP Check	15/03/2024	08:40	15/03/2024	09:30	458,036	St Leonards	SL044429
Complete AVP Check	Carry out AVP check						
Med Devices Recall	22/03/2024	10:03	22/03/2024	10:05	458,036	MDT Ferndown	TF003380
Decontaminated Med Devices Recall	Cleaned with clinell wipes Install Airflo 24 and charging bracket.						
Emergency Deep Clean	11/04/2024	15:35	12/04/2024	07:09	461,428	St Leonards	SL044855
Emergency Deep Clean							
Vehicle Deep Clean	16/04/2024	13:21	17/04/2024	10:00	461,803	St Leonards	SL044927
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/04/2024	08:30	19/04/2024	06:33	461,803	St Leonards	SL044949
18 Wheels Check Torques Safety Inspection 86 Doors Rear 44 Add Ad Blue 52 Electrical Aux 45 Engine Oil Top Up 55 Tail Lift	Checked. Carried out inspection. OSF Door hinge worn. Topped 15ltrs. 230V w/lights broken. Replaced x2. Topped 1ltr. Trolley stop plate siezed, platform not closing tight. Freed plate and adjusted						

Monitoring

Breakdown	05/05/2024	20:28	06/05/2024	06:04	463,367	St Leonards	SL045185
Breakdown	O/s Headlight faulty						
34 Lighting System	O/S headlight Faulty, parts ordered				Monitoring		
Vehicle Deep Clean	28/05/2024	11:40	29/05/2024	06:42	465,912	St Leonards	SL045512
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/05/2024	06:00	31/05/2024	16:00	465,912	St Leonards	SL045549
18 Wheels Check Torques							
Safety Inspection							
86 Doors Rear	OSR Door hinge worn. -Monitor				Monitoring		
34 Lighting System	O/S headlight Faulty, parts ordered						
52 Electrical Aux	Battery/Charging Sys stretcher battery intermittent- Checked all working ok.						
Engine Change Oil & Filter							
Tail Lift Inspection							
Axle Oil Change	Axle Oil Change						
43 Exhaust System 1	Tailpipe excessively corroded. Replaced						
17 Tyres Replace	Both front tyres worn. Replaced						
Breakdown	09/07/2024	05:55	09/07/2024	08:51	471,220	St Leonards	SL046208
Breakdown	Drivers Window Not Closing						
Vehicle Deep Clean	12/07/2024	15:21	13/07/2024	13:17	471,465	St Leonards	SL046267
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	16/07/2024	07:00	16/07/2024	17:30	471,465	St Leonards	SL046340
18 Wheels Check Torques							
Safety Inspection							
86 Doors Rear	OSR Door hinge worn. -Monitor						

Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
55 Tail Lift	Tail lift guard rails loose
71 Body Exterior 1	Step mud flap missing. Replaced
01 Heating 1	Heater exhaust broken. Replaced exhaust
13 Brakes 1	Rear brake pads worn and discs lipped. Replaced
13 Handbrake	Handbrake not working as should. Shoes found to be deteriorated
11 Axle Rear	Reseal half shaft seals

Vehicle Deep Clean	24/08/2024	10:19	24/08/2024	14:00	475,500	St Leonards	SL046956
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	26/08/2024	10:26	27/08/2024	18:00	475,500	St Leonards	SL046983
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Pollen Filter Change	Pollen Filter Change
Tail Lift Inspection	Done.
02 Cab Assembly 1	Torch missing. Replaced.
02 Cab Assembly 2	Passenger window switch broken. Replaced.
71 Body Exterior Roof	Aerial missing, roof vent adrift. Replaced aerial,secured vent.

Unplanned Repair	26/09/2024	14:35	26/09/2024	14:56	478,585	St Leonards	SL047483
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights	Running lights not working
-----------	----------------------------

SAFETY INSPECTION	30/09/2024	07:00	03/10/2024	11:40	478,685	St Leonards	SL047527
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
89 Seatbelts	Both front seatbelts torn. Replaced both belts.
15 Steering 1	Rack leaking oil and pas pump pulley cracked. replaced and bled system.
16 Suspension 1	Fronts shock absorbers and lower arms worn. replaced all.
45 Engine 1	Injectors blowing no 1 & 3. cleaned and replaced seals. -Turbo shield replaced.

13 Brakes 1	Fronts pads and discs worn low. replaced brake kit.
42 Radiator	Radiator leaking. Replaced.
02 Windscreen Wipers	O/S Washer jet u/s and check valve leaking. replaced both.
17 Tyres Tracking	Carriedx out by SAS.
13 Handbrake	Adjusted cables.
34 Lights	NSF fog light replaced. -O/S high beam bulb replaced.
71 Body Exterior 1	Rear upper blue trim strip insecure. cleaned and resealed to body.
Tail Lift Inspection	

Vehicle Deep Clean	03/10/2024	13:18	04/10/2024	13:40	478,699	St Leonards	SL047579
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	09/10/2024	08:00	09/10/2024	10:00	479,105	St Leonards	SL047661
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Assembly 1	O/S Window switch inop. Replaced switch.
Travel Time	Travel to Bournemouth station and return to VMU.

Breakdown	16/10/2024	13:42	16/10/2024	14:55	479,390	St Leonards	SL047791
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	OSR Outer tyre punctured. -Replaced wheel/tyre.
-----------	---

Vehicle Deep Clean	12/11/2024	14:53	13/11/2024	10:15	481,259	St Leonards	SL048195
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	14/11/2024	06:00	14/11/2024	11:09	481,259	St Leonards	SL048216
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
02 Glass / Windows	Doors Unable to close OS door window glass NFF
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	

Breakdown	02/12/2024	22:36	04/12/2024	13:00	481,259	St Leonards	SL048493
Breakdown	MDT WIRING CHECK						
Breakdown	11/12/2024	21:02	13/12/2024	08:00	481,490	St Leonards	SL048643
Breakdown	mdvs screen freezed need wire check						
Vehicle Deep Clean	26/12/2024	11:12	27/12/2024	14:18	483,613	St Leonards	SL048830
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	28/12/2024	12:45	02/01/2025	12:29	483,640	St Leonards	SL048854
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test MOT Annual Air Con Service UB Fire Supp 12mts Service Annual Heater Service Tail Lift Inspection 41 Air Intake 16 Suspension 1 17 Tyres Replace 34 Lights Bulb Replacement 86 Sliding Door 45 Engine 1 42 Coolant System	Check and Install MDVS windows update Annual Air Condition Service - Rear condensor housing corroded. (still secure) Service of fire suppression system - Topped up pressure to 15 BAR. Annual Heater Service Tail lift side rails insecure and loose. retightened and resecured. NS Intercooler hose leaking. replaced. Rear anti-roll bar lower drop link bushes worn. replaced x2. X1 Tyre NSF Both front sidelight bulbs replaced. Upper latch pin adjusted. Injector no5 leaking. cleaned carbon, replaced seal and bolt. Coolant leak from hose - matrix to egr cooler 3 way hose. replaced and cleaned.						
Unplanned Repair	14/01/2025	08:00	14/01/2025	14:00	484,723	St Leonards	SL049106
56 Comms Equipment	Comms speaker in cab not working - SSS to repair						
BREAKDOWN	17/01/2025	10:48	17/01/2025	11:01	484,810	St Leonards	SL049152

31 Battery Chassis	Chassis battery low						
Vehicle Deep Clean	08/02/2025	13:12	09/02/2025	14:02	486,717	St Leonards	SL049470
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	12/02/2025	06:00	13/02/2025	06:31	486,717	St Leonards	SL049509
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test Tail Lift Inspection 13 Handbrake 13 Brake Test	Check and Install MDVS windows update Cab handbrake travel becoming excessive						
Vehicle Deep Clean	26/03/2025	13:31	27/03/2025	07:34	489,321	St Leonards	SL050083
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	28/03/2025	06:58	28/03/2025	13:00	489,321	St Leonards	SL050101
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test Tail Lift 12M Service & Weight UB Fire Supp 6mts Service Air Filter Change 85 Body Int Alcohol Gel Dispen UB Fire Suppression Discharge Tail Lift Inspection 85 Body Interior 1	Check and Install MDVS windows update Tail Lift 12M Service & Weight UB Fire Supp 6mts Service Air Filter Change Under Bonnet Fire Suppression 5 Year Discharge Test Secure saloon paperwork holder and cupboards						
02 Pipeline Annual Inspection	24/03/2025	13:58	24/03/2025	14:01	489,296	MDT Ferndown	TF004041
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - passed all tests.						

ACCIDENT	09/04/2025	06:00	10/04/2025	05:45	491,690	St Leonards	SL050312
34 Emergency Light System	Lighting System Rear top blue, partially broken and cracked.						
Unplanned Repair	09/05/2025	07:00	09/05/2025	08:30	493,825	St Leonards	SL050835
86 Sliding Door	Handle broken						
Vehicle Deep Clean	14/05/2025	06:15	14/05/2025	15:15	494,418	St Leonards	SL050943
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/05/2025	15:00	15/05/2025	16:00	494,418	St Leonards	SL050952
Check MDVS for Update	Check and Install MDVS windows update. Done.						
Safety Inspection	Carried out inspection.						
18 Wheels Check Torques	Checked.						
Road Test	Done.						
34 Emergency Lights	Lighting System Rear top blue, partially broken and cracked.						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight.Told to leave.						
Engine Change Oil & Filter	Told to leave.						
85 Body Int Alcohol Gel Dispen	Removed old dispenser.						
17 Tyres Replace	O/S/R/I&O tyres low tread x2. Replaced x2.						
18 Wheels	O/S/R/O wheel rim poor condition. Replaced.						
Wheel Hub Flanges Replaceme	O/S/R in poor condition. Replaced.						
02 Cab Ass Fire Extinguisher	out of date x2. Replacedx2.						
56 Comms Fitment	Roof aerial missing. Replaced.						
87 Oxygen System	Alarm sounding. Fitted new bottle and change over valve.						
Vehicle Deep Clean	12/06/2025	12:30	13/06/2025	09:00	497,044	St Leonards	SL051503
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	21/06/2025	10:30	21/06/2025	11:38	498,050	St Leonards	SL051676
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine Oil Top Up	Topped up 1 LTR
71 Body Exterior Acc Repair	Accident damage to OSR wheel arch. Previously told ok. Taped up

Breakdown	03/07/2025	07:18	03/07/2025	11:43	499,713	St Leonards	SL051870
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Keeps powering down, "shut down imminent"
34 Lights Bulb Replacement	O/S DRL bulb blown

SAFETY INSPECTION	06/07/2025	06:00	06/07/2025	10:00	499,796	St Leonards	SL051913
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update	
Safety Inspection		
18 Wheels Check Torques		
Road Test		
13 Brake Pads	Rear pads low	Monitoring
71 Body Exterior 1	O/S/R damage around wheel arch	Monitoring
17 Tyres Replace	Replace o/s/f tyre - worn to 3mm	
89 Seats	Replace passenger seat ajuster wheel - Part taken from Decomm DCA	
Install Saloon CCTV Camera	Warning light on. Format hard drive, ok.	

SAFETY INSPECTION	26/07/2025	11:58	26/07/2025	15:12	501,299	St Leonards	SL052303
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update	
Safety Inspection		
18 Wheels Check Torques		
Road Test		
13 Discs	Front discs worn	Monitoring
71 Body Exterior 1	Damage to o/s/r of body	Monitoring
16 Suspension 1	Front strut tops knocking	Monitoring
13 Brakes 1	Slight noise from telma under heavy braking	Monitoring

Vehicle Deep Clean	27/07/2025	09:25	27/07/2025	17:59	501,299	St Leonards	SL052317
Vehicle Deep Clean	Vehicle Deep Clean						