

Vehicle Detail	BN11ZSP	TOYOTA	HI-LUX 4X4 DIESEL	No
Date	Odo	Job Type	Description	
28/08/2025		0 RFL	RFL Sept 2025	
21/08/2024		0 RFL	RFL Aug 2024	
30/08/2023		0 RFL	RFL Sept 2023	
12/01/2023	62,208	SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
12/01/2023	62,208	REPAIRS TO BRAKES	Hydraulic fluid (Brake)	
12/01/2023	62,208	SERV/SAFETY INS (+ TEST FEE)	S2 SERVICE	
12/01/2023	62,208	REPAIRS TO FUEL SYSTEM	Air cleaner/filter - assy	
23/08/2022		0 RFL	RFL Aug 2022	
07/09/2021		0 RFL	RFL AUG 2021	
29/01/2021		0 REPAIRS TO ENGINE, EXHAUST	Auxiliary drive belt (polyrib belt)	
29/01/2021		0 SERV/SAFETY INS (+ TEST FEE)	S10 SERVICE	
29/01/2021		0 REPAIRS TO ELECTRICS/BATTERY	REAR LIGHTS ISSUE/ POTENTIAL CONNECTION FAULT	
29/01/2021		0 REPAIRS TO FUEL SYSTEM	FAULT CODE OF P1604 START CONTROL FAULTY OPER	
29/01/2021		0 REPAIRS TO COOLING SYSTEM	Water pump	
29/01/2021		0 REPAIRS TO ENGINE, EXHAUST	Camshaft drive belt(s)/chain(s)	
29/01/2021		0 REPAIRS TO COOLING SYSTEM	Coolant	
29/01/2021		0 REPAIRS TO BRAKES	Hydraulic fluid (Brake)	
29/01/2021		0 SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
28/01/2021	35,062	TYRES	Wheel Balance	
28/01/2021	35,062	TYRES	Tyre Valve Inner Repair	
28/01/2021	35,062	TYRES	Disposal of Tyre Casing	
28/01/2021	35,062	TYRES	Change Tyre	
01/03/2019		0 RFL	RFL February 2019	
15/02/2018		0 RFL	RFL NE MAR 18	
01/02/2018	30,700	SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
01/02/2018	30,700	SERV/SAFETY INS (+ TEST FEE)	S7 SERVICE	
01/02/2018	30,700	REPAIRS TO BRAKES	Disc (incl. pads) - front (pair)	
01/02/2018	30,700	REPAIRS TO BODY (NON ACCIDENT)	EA0517 Vehicle condition report recall end date =30-SEP-2018	
01/02/2018	30,700	REPAIRS TO ENGINE, EXHAUST	DEF0117 Vehicle Description Audit recall end date =30-APR-2018	
01/02/2018	30,700	REPAIRS TO COOLING SYSTEM	Cooling system - drain and refill	