

Transaction date	Fleet No	Invoice No	Registration	Detail	Odometer/Hrs run	Total net	Total VAT	Total cost	
01-Jan-18	NR030069	74535192	CX17GVJ	Glass - windscreen - Parts		€238.50	€47.70	€286.20	
05-Apr-18	NR030069	74535192	CX17GVJ	Tyre worn out, NSF 2mm left, fit 185651SHVEC45G2 - Parts		€88.23	€17.65	€105.88	
05-Apr-18	NR030069	74535192	CX17GVJ	Tyre worn out, OSF 5mm left, fit 185651SHVEC45G2 - Parts		€88.23	€17.65	€105.88	
05-Apr-18	NR030069	74535192	CX17GVJ	Tyres - Environmental Disposal,NSF - Parts		€1.10	€0.22	€1.32	
05-Apr-18	NR030069	74535192	CX17GVJ	Tyres - Environmental Disposal,OSF - Parts		€1.10	€0.22	€1.32	
09-Apr-18	NR030069	74535192	CX17GVJ	Puncture Repair,NSF - Parts		€10.20	€2.04	€12.24	
09-Apr-18	NR030069	74535192	CX17GVJ	Tyre Valve,OSF - Parts		€2.24	€0.45	€2.69	
09-Apr-18	NR030069	74535192	CX17GVJ	Wheel Balance,NSR - Parts		€5.01	€1.00	€6.01	
18-Apr-18	NR030069	74535192	CX17GVJ	9000 ml/kms Service - 1999/2000 Punto Van, Fiorino, Scudo, Ducato (1. - Labour		€85.00	€17.00	€102.00	
18-Apr-18	NR030069	74535192	CX17GVJ	9000 ml/kms Service - 1999/2000 Punto Van, Fiorino, Scudo, Ducato (1. - Parts		€113.38	€22.68	€136.06	
16-Apr-19	NR030069	74820237	CX17GVJ	Tyre Valve,NSF - Parts		€2.24	€0.45	€2.69	
16-Apr-19	NR030069	74820237	CX17GVJ	Tyre Valve,SPARE - Parts		€2.24	€0.45	€2.69	
16-Apr-19	NR030069	74820237	CX17GVJ	Tyre runflat, NSF 3mm left, fit 185651SCONCT588H - Parts		€68.31	€13.66	€81.97	
16-Apr-19	NR030069	74820237	CX17GVJ	Tyre runflat, OSF 4mm left, fit 185651SCONCT588H - Parts		€68.31	€13.66	€81.97	
16-Apr-19	NR030069	74820237	CX17GVJ	Tyres - Environmental Disposal,NSF - Parts		€1.10	€0.22	€1.32	
16-Apr-19	NR030069	74820237	CX17GVJ	Tyres - Environmental Disposal,OSF - Parts		€1.10	€0.22	€1.32	
16-Apr-19	NR030069	74820237	CX17GVJ	Wheel Balance,NSR - Parts		€5.01	€1.00	€6.01	
16-Apr-19	NR030069	74820237	CX17GVJ	Wheel Balance,OSR - Parts		€5.01	€1.00	€6.01	
17-Apr-19	NR030069	74799481	CX17GVJ	Front And Rear Alignment - Check & Adjust, Wheel Alignment - front/rear - Labour Front And Rear Alignment - Check & Adjust, Wheel Alignment - front/rear TYRE WEAR INNER EDGES		€25.00	€5.00	€30.00	
17-Apr-19	NR030069	74799481	CX17GVJ	24 month Service - 1999/2000 Punto Van, Fiorino, Scudo, Ducato (1.9 Di - Labour		€77.50	€15.50	€93.00	
17-Apr-19	NR030069	74799481	CX17GVJ	24 month Service - 1999/2000 Punto Van, Fiorino, Scudo, Ducato (1.9 Di - Parts		€177.06	€35.41	€212.47	
26-Mar-20	NR030069	75116417	CX17GVJ	MOT - Class IV Cars (Up To 8 Passenger Seats) - Labour MOT - Class IV Cars - Indicating parking light assembly, Rchg From Inv: 33283		26978	€426.50	€2743.50	
26-Mar-20	NR030069	75116417	CX17GVJ	Disc - Remove & Refit, Disc (incl. pads) - front (pair) - Labour Disc - Remove & Refit, Disc (incl. pads) - front (pair) WORN,DISC,ACT.10.00MM,DISC_MIN		26978	€426.00	€2743.00	
26-Mar-20	NR030069	75116417	CX17GVJ	Disc - Remove & Refit, Disc (incl. pads) - front (pair) - Parts Disc - Remove & Refit, Disc (incl. pads) - front (pair) WORN,DISC,ACT.10.00MM,DISC_MIN		26978	€394.11	€18.82	€211.93
26-Mar-20	NR030069	75116417	CX17GVJ	36 month Service - 1999/2000 Punto Van, Fiorino, S cudo, Ducato (1.9 Diesel only) - Labour 36 month Service - 1999/2000 Punto Van, Fiorino, S cudo, Ducato (1.9 Diesel only)		26978	€890.00	€16.00	€906.00
26-Mar-20	NR030069	75116417	CX17GVJ	36 month Service - 1999/2000 Punto Van, Fiorino, S cudo, Ducato (1.9 Diesel only) - Parts 36 month Service - 1999/2000 Punto Van, Fiorino, S cudo, Ducato (1.9 Diesel only)		26978	€168.99	€33.80	€202.79
17-Nov-20	NR030069	MAINTINV00213184	CX17GVJ	Recharge Remove & Refit Front Glass - windscreen, Rchg From Inv: D397627		33917	€238.50	€47.70	€286.20
14-Dec-20	NR030069	INV00255685	CX17GVJ	Recharge Recharge For: New Tyre, Position: A 2, 185651SHPRM4, MICHELIN, Tread: 8mm, Location: Booking-FTN Valley Tyre Services LTD, Rchg From Inv: U114290363		34638	€36.18	€1.24	€37.42
14-Dec-20	NR030069	INV00255685	CX17GVJ	Recharge Recharge For: New Tyre, Position: A 3, 185651SHPRM4, MICHELIN, Tread: 8mm, Location: Booking-FTN Valley Tyre Services LTD, Rchg From Inv: U114290363		34638	€36.18	€1.24	€37.42
14-Dec-20	NR030069	INV00255685	CX17GVJ	Recharge Recharge For: Removed Tyre, Position: A 2, 185651SHPC05, CONTINENTAL, Removal Reason: Tyre - Worn Out, Tread: 2mm, Location: Booking-FTN Valley Tyre Services LTD, Rchg From Inv: U114290363		34638	€0.00	€0.00	€0.00
14-Dec-20	NR030069	INV00255685	CX17GVJ	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: A 3, Location: Booking-FTN Valley Tyre Services LTD, Rchg From Inv: U114290363		34638	€22.85	€0.57	€23.42
14-Dec-20	NR030069	INV00255685	CX17GVJ	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: A 3, Location: Booking-FTN Valley Tyre Services LTD, Rchg From Inv: U114290363		34638	€54.85	€0.00	€54.85
14-Dec-20	NR030069	INV00255685	CX17GVJ	Recharge Recharge For: Standard Wheel Balance, Position: A 3, Location: Booking-FTN Valley Tyre Services LTD, Rchg From Inv: U114290363		34638	€5.01	€1.00	€6.01
14-Dec-20	NR030069	INV00255685	CX17GVJ	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: A 3, Location: Booking-FTN Valley Tyre Services LTD, Rchg From Inv: U114290363		34638	€22.85	€0.57	€23.42
23-Feb-21	NR030069	MAINTINV00377879	CX17GVJ	Recharge Recharge For: MOT - Class IV Cars (Up To 8 Passenger Seats), Rchg From Inv: 33283		36376	€554.00	€11.00	€565.00
23-Feb-21	NR030069	MAINTINV00377879	CX17GVJ	Recharge MOT - Pre Insp - LCV - NOVUNA Bespoke Event, Rchg From Inv: 33383		36376	€554.00	€11.00	€565.00
23-Feb-21	NR030069	MAINTINV00377879	CX17GVJ	Recharge 36000 ml/kms Service - 1999/2000 Punto Van, Fiorino, Scudo, Ducato (1.9 Diesel only), Rchg From Inv: 33383		36376	€303.50	€60.70	€364.20
27-May-21	NR030069	INV00509815	CX17GVJ	Recharge Recharge For: R/RESP RSIDE VAN OUT OF HOURS, Location: Rapid Response Mobile-Vailey Tyre Service, Rchg From Inv: U114387892		38337	€897.75	€19.55	€917.30
27-May-21	NR030069	INV00509815	CX17GVJ	Recharge Recharge For: New Tyre, Position: B 1, 185651SH7577, BUDGET, Tread: 8mm, Location: Rapid Response Mobile-Vailey Tyre Service, Rchg From Inv: U114387892		38337	€684.05	€12.81	€706.86
27-May-21	NR030069	INV00509815	CX17GVJ	Recharge Recharge For: Removed Tyre, Position: B 1, 185651SHCHN14, PIRELLI, Removal Reason: Tyre - Worn Out, Tread: 2mm, Location: Rapid Response Mobile-Vailey Tyre Service, Rchg From Inv: U114387892		38337	€0.00	€0.00	€0.00
27-May-21	NR030069	INV00509815	CX17GVJ	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: B 1, Location: Rapid Response Mobile-Vailey Tyre Service, Rchg From Inv: U114387892		38337	€51.10	€0.22	€51.32
27-May-21	NR030069	INV00509815	CX17GVJ	Recharge Recharge For: Standard Wheel Balance, Position: B 1, Location: Rapid Response Mobile-Vailey Tyre Service, Rchg From Inv: U114387892		38337	€5.01	€1.00	€6.01
27-May-21	NR030069	INV00509815	CX17GVJ	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 1, Location: Rapid Response Mobile-Vailey Tyre Service, Rchg From Inv: U114387892		38337	€22.85	€0.57	€23.42
21-Jun-21	NR030069	MAINTINV00594946	CX17GVJ	Recharge Recharge For: New Tyre, Position: A 2, 185651SH585, BUDGET, Tread: 8mm, Location: Rapid Response Mobile-Gwent Mobile Tyres, Rchg From Inv: U114422977		39061	€51.54	€10.31	€61.85
21-Jun-21	NR030069	MAINTINV00594946	CX17GVJ	Recharge Recharge For: R/RESP R/SIDE VAN NORMAL HRS, Location: Rapid Response Mobile-Gwent Mobile Tyres, Rchg From Inv: U114422977		39061	€60.95	€12.19	€73.14
21-Jun-21	NR030069	MAINTINV00594946	CX17GVJ	Recharge Recharge For: Standard Tyre, Position: A 2, 185651SHPRM4, MICHELIN, Removal Reason: Tyre - Sidewall Damage, Tread: 5mm, Location: Rapid Response Mobile-Gwent Mobile Tyres, Rchg From Inv: U114422977		39061	€0.00	€0.00	€0.00
21-Jun-21	NR030069	MAINTINV00594946	CX17GVJ	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: A 2, Location: Rapid Response Mobile-Gwent Mobile Tyres, Rchg From Inv: U114422977		39061	€51.10	€1.24	€52.34
21-Jun-21	NR030069	MAINTINV00594946	CX17GVJ	Recharge Recharge For: Standard Wheel Balance, Position: A 2, Location: Rapid Response Mobile-Gwent Mobile Tyres, Rchg From Inv: U114422977		39061	€5.01	€1.00	€6.01
21-Jun-21	NR030069	MAINTINV00594946	CX17GVJ	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: A 2, Location: Rapid Response Mobile-Gwent Mobile Tyres, Rchg From Inv: U114422977		39061	€22.85	€0.57	€23.42
28-Jun-21	NR030069	MAINTINV00549510	CX17GVJ	Recharge Recharge For: New Tyre, Position: B 4, 185651SHPRM4, MICHELIN, Tread: 8mm, Location: Standard Mobile-Halfords Tyres on the Drive Swindon 1, Rchg From Inv: U114404770		39279	€86.18	€1.24	€87.42
28-Jun-21	NR030069	MAINTINV00549510	CX17GVJ	Recharge Recharge For: Removed Tyre, Position: B 4, 4016471, PIRELLI, Removal Reason: Tyre - Tread Damage, Tread: 2mm, Location: Standard Mobile-Halfords Tyres on the Drive Swindon 1, Rchg From Inv: U114404770		39279	€0.00	€0.00	€0.00
28-Jun-21	NR030069	MAINTINV00549510	CX17GVJ	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: B 4, Location: Standard Mobile-Halfords Tyres on the Drive Swindon 1, Rchg From Inv: U114404770		39279	€91.10	€0.22	€91.32
28-Jun-21	NR030069	MAINTINV00549510	CX17GVJ	Recharge Recharge For: Standard Wheel Balance, Position: B 4, Location: Standard Mobile-Halfords Tyres on the Drive Swindon 1, Rchg From Inv: U114404770		39279	€5.01	€1.00	€6.01
28-Jun-21	NR030069	MAINTINV00549510	CX17GVJ	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 4, Location: Standard Mobile-Halfords Tyres on the Drive Swindon 1, Rchg From Inv: U114404770		39279	€22.85	€0.57	€23.42
14-Sep-21	NR030069	MAINTINV00639500	CX17GVJ	Recharge CENTRAL LOCKING NOT WORKING, N/S & REAR DOORS NOT LOCKING. Rear doors bent, Rchg From Inv: 35055 CENTRAL LOCKING NOT WORKING, N		40846	€27.50	€5.00	€32.50
01-Dec-21	NR030069	INV0777090	CX17GVJ	Recharge Routine, Other Unspecified Work - Routine, Breakdown, Rchg From Inv: 86322 0112/202108:50PONTYPRIDD CF37		42660	€81.15	€16.23	€97.38
04-Mar-22	NR030069	MAINTINV00913134	CX17GVJ	Recharge Routine, MOT - Class IV Cars (Up To 8 Passenger Seats), Rchg From Inv: 36479		44685	€54.85	€0.00	€54.85
04-Mar-22	NR030069	MAINTINV00913134	CX17GVJ	Recharge Routine, MOT - Pre Insp - LCV - NOVUNA Bespoke Event, Rchg From Inv: 36479		44685	€55.00	€11.00	€66.00
04-Mar-22	NR030069	MAINTINV00913134	CX17GVJ	Recharge Remove & Refit, Bonnet - Remove & Refit, Bonnet - hinges, Rchg From Inv: 36479 n/s/r bonnet stay/hinge		44685	€56.45	€11.29	€67.74
04-Mar-22	NR030069	MAINTINV00913134	CX17GVJ	Recharge Remove & Refit, Lamps - Remove & Refit, Lamps exterior - indicator/parking light assembly, Rchg From Inv: 36479 INCORRECT COLOUR O/S/F		44685	€41.59	€4.72	€46.31
04-Mar-22	NR030069	MAINTINV00913134	CX17GVJ	Recharge Remove & Refit, Oil Lubrication - Remove & Refit, Oil sump (Engine), Rchg From Inv: 36479 sump plug damaged		44685	€47.86	€1.53	€49.39
04-Mar-22	NR030069	MAINTINV00913134	CX17GVJ	Recharge Routine, 40500 ml/kms Service - 1999/2000 Punto Van, Fiorino, Scudo, Ducato (1.9 Diesel only), Rchg From Inv: 36479		44685	€105.33	€2.07	€107.40
28-Mar-22	NR030069	MAINTINV00913134	CX17GVJ	Recharge Remove & Refit, Wash/Wipe Systems - Remove & Refit, Windscreen wiper - linkage, Rchg From Inv: 036713 BROKEN OFF		45220	€129.80	€25.96	€155.76
28-Mar-22	NR030069	MAINTINV00913134	CX17GVJ	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 036713 WIPER FAULT		45220	€27.50	€5.00	€32.50
24-Aug-22	NR030069	INV01152099	CX17GVJ	Recharge Breakdown 16/08/22 15:48 Caerphilly - Mirror Damaged/Distorted, Rchg From Inv: 988528 16/08/202215:48CAERPHILLY CF83		€123.53	€24.71	€148.24	
24-Aug-22	NR030069	INV01152099	CX17GVJ	Recharge Door (Front) - Remove & Refit, Door mirror glass left, Rchg From Inv: 988528 Mirror Glass universal		€11.85	€2.37	€14.22	
26-Aug-22	NR030069	INV0119724	CX17GVJ	Recharge Door (Front) - Remove & Refit, Door (front) - mirror (exterior) right, Rchg From Inv: 38044		€103.47	€20.69	€124.16	
18-Nov-22	NR030069	INV01295872	CX17GVJ	Recharge Remove & Refit, Door (Front) - Remove & Refit, Door (front) - handle (outer) left, Rchg From Inv: 38800 SCUTTLE CHANNEL REQUIRES UNBLO		€27.50	€5.50	€33.00	
18-Nov-22	NR030069	INV01295872	CX17GVJ	Recharge Remove & Refit, Wing (Front & Rear) - Remove & Refit, Wing - front, Rchg From Inv: 38800 N/S/F REQUIRES RESECURING		€13.75	€2.75	€16.50	
18-Nov-22	NR030069	INV01295872	CX17GVJ	Recharge Remove & Refit, Battery - Remove & Refit, Charging circuit - battery, Rchg From Inv: 38800		€109.23	€21.85	€131.08	
18-Nov-22	NR030069	INV01295872	CX17GVJ	Recharge Remove & Refit, Heater Motor - Remove & Refit, Heater motor - resistor unit, Rchg From Inv: 38800		€30.38	€6.08	€36.46	
18-Nov-22	NR030069	INV01295872	CX17GVJ	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 38800 leak in the passenger door, de		1	€355.00	€1.00	€356.00
08-Feb-23	NR030069	INV01438923	CX17GVJ	Recharge Routine, MOT - Class IV Cars (Up To 8 Passenger Seats), Rchg From Inv: 000039453		51198	€54.85	€0.00	€54.85
08-Feb-23	NR030069	INV01438923	CX17GVJ	Recharge Routine, MOT - Pre Insp - LCV - NOVUNA Bespoke Event, Rchg From Inv: 000039453		51198	€27.50	€5.50	€33.00
08-Feb-23	NR030069	INV01438923	CX17GVJ	Recharge Remove & Refit, Rear Shock Absorber - Remove & Refit, Shock absorber/damper (one) (Rear Susp.) left, Rchg From Inv: 000039453		51198	€90.61	€18.12	€108.73
08-Feb-23	NR030069	INV01438923	CX17GVJ	Recharge Routine, Service - Annual - Novuna Bespoke Event, Rchg From Inv: 000039453		51198	€224.06	€44.81	€558.87
28-Feb-23	NR030069	INV1583053	CX17GVJ	Recharge Routine, Other Unspecified Work - Routine, Breakdown, Rchg From Inv: 28/02/202208:24BERBERDA CF44 6		51874	€897.24	€17.45	€914.69
09-Mar-23	NR030069	INV1583053	CX17GVJ	Recharge Wash/Wipe Systems - Remove & Refit, Rchg From Inv: 000039453		51874	€207.50	€5.50	€523.00
09-Mar-23	NR030069	INV01489209	CX17GVJ	Recharge Washer bottle damaged - leaking, Rchg From Inv: 000039758 WASHER TANK AND PUMP REPLACEME		51874	€164.46	€29.29	€193.75
25-Apr-23	NR030069	INV1583053	CX17GVJ	Recharge Recharge For: New Tyre, Position: A 1, 185651SMICHELPRMAC4EX192T, MICHELIN, Location: VALLEY TYRE SERVICES LTD - PONTYPRIDD - CAR/VAN ONLY DRIVE IN ON THE 18/04, Rchg From Inv: U114840607 Authorised By:VALLEY TYRES Location:VALLEY TYRE SERVICES LTD - PONTYPRIDD - CAR/VAN ONLY DRIVE IN		52685	€105.19	€12.04	€117.23
25-Apr-23	NR030069								

23-Oct-24	NR030069	MAINTINV02424143	CX17GYJ	Recharge Remove & Refit, Door (Front) - Remove & Refit, Door (front) - lock assy right, Rchg From Inv: 45214 LOCK JAMMED, REMOVAL AND FREE	64762	Â€55.00	Â€11.00	Â€66.00
23-Oct-24	NR030069	MAINTINV02424143	CX17GYJ	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 45214	64762	Â€27.50	Â€5.50	Â€33.00
01-Apr-25	NR030069	MAINTINV02716980	CX17GYJ	Recharge Routine, MOT - Class IV Cars (Up To 8 Passenger Seats), Rchg From Inv: 35098138	86850	Â€54.85	Â€0.00	Â€54.85
01-Apr-25	NR030069	MAINTINV02716980	CX17GYJ	Recharge Remove & Refit, Engine Assembly - Remove & Refit, Undertray - Engine, Rchg From Inv: 35098138 undertray bolt seized and snap	86850	Â€52.00	Â€12.40	Â€64.40
01-Apr-25	NR030069	MAINTINV02716980	CX17GYJ	Recharge Remove & Refit, Front Shock Absorber - Remove & Refit, Shock absorber/damper (pair) (Front Susp.), Rchg From Inv: 35098138	86850	Â€318.19	Â€63.64	Â€381.83
01-Apr-25	NR030069	MAINTINV02716980	CX17GYJ	Recharge Remove & Refit, Front Spring - Remove & Refit, Spring/torsion bar (Front Susp.) left, Rchg From Inv: 35098138 corroded and top bushes worn	86850	Â€270.80	Â€54.16	Â€324.96
01-Apr-25	NR030069	MAINTINV02716980	CX17GYJ	Recharge Remove & Refit, Front Spring - Remove & Refit, Spring/torsion bar (Front Susp.) right, Rchg From Inv: 35098138 snapped and top bush worn	86850	Â€270.80	Â€54.16	Â€324.96
01-Apr-25	NR030069	MAINTINV02716980	CX17GYJ	Recharge Check, Checks - Check, Road test, Rchg From Inv: 35098138	86850	Â€12.40	Â€2.48	Â€14.88
01-Apr-25	NR030069	MAINTINV02716980	CX17GYJ	Recharge Routine, Service - Annual - Novuna Bespoke Event, Rchg From Inv: 35098138	86850	Â€387.66	Â€77.53	Â€465.19
12-May-25	NR030069	MAINTINV02775402	CX17GYJ	Recharge Found key to wind down spare is missing and unable to change, will need a tyre fitter to attend. Customer happy to make arrangements on Monday for a, Rchg From Inv: 00-647726 14 Ty R Felin Street Mountain	68102	Â€119.18	Â€23.84	Â€143.02
12-May-25	NR030069	MAINTINV02775402	CX17GYJ	Recharge Found key to wind down spare is missing and unable to change, will need a tyre fitter to attend. Customer happy to make arrangements on Monday for a, Rchg From Inv: 00-647726 Found key to wind down spare i	68102	Â€25.80	Â€5.96	Â€31.76
12-May-25	NR030069	MAINTINV02775402	CX17GYJ	Recharge 09/05/25 06.00 - punctured tyre Spare on board, Rchg From Inv: 00-647726 09/05/25 06.00 - punctured tyr	68102	Â€48.57	Â€9.71	Â€58.28
12-May-25	NR030069	MAINTINV02775402	CX17GYJ	Recharge 1432574 SIF - F 12/05/2025 08:30 Unknown CF45 3 612 - Puncture - No Spare W3 - No Spare Supplied by Manufacturer 53 - Tyre Repair Kit Used - RAC, Rchg From Inv: 1432574 1432574 SIF - F12/05/202508:30	68102	Â€135.26	Â€27.05	Â€162.31
Report Total:								Â€10,668.50