

VU15CKG	A&E		Truro Amb Stn				
PDI Inspection	11/05/2015	07:30	14/05/2015	15:30	210	Redruth	RE017581
71 Body Exterior 1 PDI Inspection	Blast film fitted by Autospray						
Unplanned Repair	10/06/2015	08:00	10/06/2015	10:51	3,419	Redruth	RE017741
31 Charging System 44 Add Ad Blue	vehicle power failing. Checked charging and batteries all ok Top Up and supply Adblue						
SAFETY INSPECTION	22/06/2015	10:52	23/06/2015	08:02	5,373	Redruth	RE017789
18 Wheels Check Torques 43 Exhaust System 1 44 Add Ad Blue Safety Inspection	Reposition exhaust mounts to stop exhaust striking body Top up Adblue system						
Vehicle Deep Clean	22/06/2015	11:51	23/06/2015	12:16	5,373	Redruth	RE017790
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	29/06/2015	09:30	29/06/2015	10:15	6,534	Redruth	RE017826
11 Axle Rear	Tighten rear anti-rollbar bolts & carry out road test						
Breakdown	30/06/2015	22:00	01/07/2015	15:55	7,054	Redruth	RE017836
42 Coolant System Breakdown	Fanbelt broken awaiting repair by Mercedes 24Hr Red coolant light has come on. red hot under bonet						
Unplanned Repair	07/07/2015	14:00	07/07/2015	15:44	7,840	Redruth	RE017872
44 Add Ad Blue	Fill up with adblue.						

Defect Repair	23/07/2015	09:03	24/07/2015	09:06	10,000	Launceston	LA008492
31 Charging System	Electrical Auxs sat nav keeps freezing						
BREAKDOWN	20/07/2015	08:04	20/07/2015	08:30	9,950	Redruth	RE017928
44 Add Ad Blue	Top up Ad-Blue						
Defect Repair	24/07/2015	09:07	24/07/2015	09:08	10,000	Redruth	RE017951
31 Charging System	keeps powering down. evenwhen driving Wil be repaired next insp 03/08/15 Awaiting Warranty						
BREAKDOWN	28/07/2015	08:02	28/07/2015	15:35	10,918	Redruth	RE017964
55 Ramp	Warning keeps sounding Adjust lift ram						
86 Doors	Doors Lock Door sensor continually sounding Remove cover & adjust micro switch						
Road Test	Roadtest to determine fault. Locker door & tail lift audible warning						
SAFETY INSPECTION	03/08/2015	07:30	03/08/2015	15:26	12,206	Redruth	RE017990
18 Wheels Check Torques							
31 Charging System	keeps powering down. evenwhen driving , claim form sent 03/08/2015						
87 Stretcher	Checklist Defect Harness on stretcher but no pedimate, now supplied.						
Safety Inspection							
Vehicle Deep Clean	03/08/2015	11:55	04/08/2015	14:18	12,206	Redruth	RE017991
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/09/2015	07:45	15/09/2015	13:05	21,923	Redruth	RE018193
13 Brakes 1	Adjusted Handbrake and brake tested						
16 Suspension 1	Both front struts have play Awaiting Warranty						
18 Wheels Check Torques	Completed						

34 Lights	Temp repair to N/S VRN Light unit						
55 Tail Lift	Re worked O/S tail lift buffer						
86 Door Lock	Rear door not remote locking						
87 - Stretchers/Chairs/Boards	Stretcher corner control bar missing						
87a - Medical Equipment Repair	Fitted Pedimed						
89 Seats	Refitted Rear attendant seat adjusting bar						
Safety Inspection	Carried out						
92 - C Service	carried out						
Service C							
Vehicle Deep Clean	17/09/2015	07:18	17/09/2015	13:43	21,926	Redruth	RE018204
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	13/10/2015	08:48	13/10/2015	08:51	27,694	Redruth	RE018327
56 Comms Power Failure	Power failing while driving. Bypass over volting relay RW 13/10/15						
87 - Stretchers/Chairs/Boards	Body Interior trooly wheel broken. Replace wheel with one from VOR stretcher						
Unplanned Repair	15/10/2015	14:30	15/10/2015	14:45	28,100	Redruth	RE018347
45 Engine Oil Top Up	Top up engine oil						
Unplanned Repair	16/10/2015	13:00	16/10/2015	14:00	28,258	Redruth	RE018365
17 Tyres Replace	N/S/F Tyre replaced by ATS						
Vehicle Deep Clean	26/10/2015	07:30	27/10/2015	15:05	30,247	Redruth	RE018427
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/10/2015	07:30	26/10/2015	09:50	30,242	Redruth	RE018430
16 Suspension 1	Both front struts have play						
17 Tyres Replace	Replace rear tyres						
18 Wheels Check Torques							
55 Ramp	Magten missing from side arm ordered in store						
86 Door Lock	Rear door not remote locking						
86 Doors	Adjust rear door latches						

Awaiting Warranty
Awaiting Parts

Parts ordered in store

87 - Stretchers/Chairs/Boards	Stretcher corner control bar missing	
Camera Installation	1 CCTV camera not working	Reported
Safety Inspection	INSPECTION CARRIED OUT BY PCS ENGINEER	
Tail Lift 6 Monthly Inspection	Statutory Inspection	

Awaiting Warranty

Unplanned Repair	25/11/2015	10:00	25/11/2015	11:00	35,922	Redruth	RE018565
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

71 Body External Steps	Repair damage to step , now working.
------------------------	--------------------------------------

Vehicle Deep Clean	08/12/2015	11:52	09/12/2015	14:32	38,644	Redruth	RE018617
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	09/12/2015	08:02	10/12/2015	09:11	38,649	Redruth	RE018619
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Mirrors	Replace broken mirror	
13 Handbrake	Adjust handbrake	
17 Tyres	Replace O/S/F tyre	
18 Wheels Check Torques		
34 Lights Bulb Replacement	Replace assorted blown bulbs	
44 Fuel System 1	Clip brocken on fuel fillter pipe temp repair made part orderd in store	Parts ordered in store
55 Ramp	Magten missing from side arm ordered in store REPLACED	
71 Body Exterior 1	Both front saloon corners damaged awaiting body repairs	Monitoring
71 Body External Steps	free up sticking side step Front edge missing off step	Monitoring
86 Doors	Tighten front door check straps adjust side & rear door catches	
87 Chairs	Refit adjuster bar on attendants seat	
Camera Installation	1 CCTV camera not working	Reported
Safety Inspection		
93 - D Service		
Service D		

Unplanned Repair	21/12/2015	10:30	21/12/2015	11:45	41,804	Redruth	RE018679
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

34 Lighting System	Replace smashed off rear lights
--------------------	---------------------------------

Unplanned Repair	05/01/2016	07:00	05/01/2016	07:00	44,656	Derriford	DE019399
-------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

34 Lights Bulb Replacement	Replaced n/s headlight bulb	Replaced by CSO
----------------------------	-----------------------------	-----------------

Vehicle Deep Clean	18/01/2016	10:11	19/01/2016	08:58	47,388	Redruth	RE018800
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	19/01/2016	15:00	21/01/2016	08:00	47,403	Redruth	RE018812
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

13 Brake Pads	Replace front brake pads	
18 Wheels Check Torques		
44 Fuel System 1	Clip brocken on fuel fillter pipe temp repair made part orderd in store	
52 Electrical Aux	CCTV faulty reported to WAS UK	Awaiting Warranty
55 Ramp	Side arms loose and will not slide up or down. Repaired under warranty	
71 Body Exterior 1	Both front saloon corners damaged awaiting body repairs	
71 Body External Steps	free up sticking side step Front edge missing off step	
85 Body Interior 1	Assorted scratches around vehicle	
86 Doors Rear	Rear door dificalt to open. Adjust door catches	
86 Sliding Door	Adjust catches on sliding door	
87 - Stretchers/Chairs/Boards	Supply Pedi-Mate	
87 Chairs	Re-fit adjuster knob on airways seat in saloon	
Safety Inspection		

Defect Repair	09/02/2016	08:45	09/02/2016	09:30	50,928	Redruth	RE018945
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

87 - Stretchers/Chairs/Boards	Body Interior Stretcher not releasing from bracket	Repaired
-------------------------------	--	----------

Defect Repair	12/02/2016	09:30	12/02/2016	10:15	51,698	Redruth	RE018946
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

86 Sliding Door	Body Exterior side door sticking closed	REPAIRED
-----------------	---	----------

Defect Repair	26/02/2016	13:38	26/02/2016	16:00	54,414	Redruth	RE019006
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

86 Sliding Door	Body Interior SLIDING DOOR NOT OPENING, remove panel and adjust cables.
-----------------	---

SAFETY INSPECTION	29/02/2016	07:53	02/03/2016	09:42	55,041	Redruth	RE019009
13 Brake Pads 17 Tyres Replace 18 Wheels Check Torques 34 Lights 52 Electrical Aux Safety Inspection MOT Pre Test Gearbox Oil & Filter Change Travel Time MOT	Replaced rear pads Both NSR & OSR outer tyres replaced Replaced damaged OSR stop/tail lamp CCTV faulty reported to WAS UK						
Vehicle Deep Clean	01/03/2016	10:00	02/03/2016	11:22	55,047	Redruth	RE019015
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	03/03/2016	19:55	03/03/2016	20:00	55,300	Redruth	RE019045
54 Warn Dev/System	Electrical Auxs run stop not working NO RUN LOCK FITTED ON THESE VEHICLES						
Defect Repair	15/03/2016	07:50	15/03/2016	11:33	57,373	Redruth	RE019082
56 Comms Equipment	MDT not working VEHICLE IS BEING USED MDT MUST BE WORKING						
Breakdown	16/03/2016	07:01	16/03/2016	09:21	57,903	Redruth	RE019089
17 Tyres Replace Breakdown	Tyre replaced by ATS call out tyre osf Truro stn						
Vehicle Deep Clean	11/04/2016	06:23	12/04/2016	09:10	62,957	Redruth	RE019223
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	11/04/2016	11:08	13/04/2016	15:13	62,957	Redruth	RE019225
17 Tyres Replace 18 Wheels Check Torques	Replace n/s/f tyre.						

56 Radio	Electrical Auxs music radio wont switch off. even with keys out, reset.
Safety Inspection	
92 - C Service	
Service C	
Tail Lift Annual Service	Statutory Inspection and Weight Test
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
UB Fire Suppression Service	
Tail Lift 6 Monthly Inspection	Statutory Inspection
85 Body Int Alcohol Gel Dispen	

ACCIDENT	21/04/2016	13:30	21/04/2016	15:43	64,081	Redruth	RE019299
-----------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

34 Lighting System	Replace damage reverse and indicator lights at rear, refit fireglass panel.
34 Lights	Body Exterior Rear Light Cluster

Breakdown	27/04/2016	14:11	28/04/2016	15:21	65,191	Redruth	RE019319
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels	Replace cracked wheel rim SEE JOB CRARD No RE009320
Breakdown	Fractured Wheel Rim

Defect Repair	27/04/2016	14:00	27/04/2016	15:00	65,191	Redruth	RE019320
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

17 Tyres Replace	Replaced OSF tyre due to a cracked wheel rim
18 Wheels	Body Exterior Fractured Wheel Rim. replaced OSF wheel
18 Wheels Check Torques	Roadtest and retorque wheel

SAFETY INSPECTION	25/05/2016	10:30	26/05/2017	18:48	75,000	Redruth	RE019428
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	Fit In Date Fire Extinguisher
13 Brake Pads	Replace front brake pads
13 Discs	Replace front brake discs
17 Tyres Replace	Replace both O/S/R Tyres
18 Wheels Check Torques	
87 - Stretchers/Chairs/Boards	Replace stratcher belt
Check Vehilce Call Signs	Check vehilce call signs are fitted and correct FIT NEW
Safety Inspection	

Fit Throw Lines & SOP
Wheel Studs & Nuts Replaceme

Vehicle Deep Clean	27/05/2016	12:36	27/05/2016	14:57	77,033	Redruth	RE019434
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	03/07/2016	15:55	06/07/2016	15:28	77,327	Redruth	RE019598
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

01 Air Conditioning 1	Emg Warning Devices Coolant RED light
17 Tyres Replace	NSF tyre low pressure thus loosing traction See Job No RE019603
18 Wheels	NSF wheel cracked See Job No RE019603
71 Body Exterior 1	Body Exterior Frontal damage to grill surround.
71 Body External Steps	Body Exterior Side step damaged and not deploying See Job RE019603
Breakdown	BRAKE/WHEEL ISSUE. ALSO COOLANT ISSUE

SAFETY INSPECTION	04/07/2016	16:10	08/07/2016	15:32	77,327	Redruth	RE019603
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Cab Assembly 1	Locker between front seats falling apart	
02 Windows/Glass	Replace N/S door window switch	
13 Brakes 1	Replace pedal pad	
17 Tyres Tracking	Replace N/S/F tyre	
18 Wheels	Replace cracked N/S/F wheel rim	
18 Wheels Check Torques		
42 Coolant System	Aux belt shredded Merc 24Hr Called.	
71 Body Exterior 1	O/SR lower corner damaged	
71 Body External Steps	Replace damaged side step	
87 - Stretchers/Chairs/Boards	Service carrychair tracks	
87 Oxygen System	O2 regulators out of service in August 2016	Monitoring
Safety Inspection		
Reposition grab bag shelf		
Handbrake Cable Replacement	Replace rear handbrake cables in two years time	

Vehicle Deep Clean	05/07/2016	07:34	05/07/2016	11:36	77,327	Redruth	RE019605
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean not complete due to lack of manpower saloon only
--------------------	---

Defect Repair	13/07/2016	11:38	13/07/2016	12:46	77,766	Redruth	RE019647
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

86 Doors Rear Doors rear door straining arm detached, remove broken bolt etc and replace.

Defect Repair 25/07/2016 08:45 25/07/2016 09:05 81,009 Redruth RE019695

45 Engine Oil Top Up Top up

Defect Repair 29/07/2016 15:05 29/07/2016 15:11 81,948 Redruth RE019715

34 Lights Bulb Replacement Replaced NSF dipped beam bulb

Defect Repair 12/08/2016 10:00 12/08/2016 11:30 86,732 Redruth RE019792

34 Lights Bulb Replacement Replace o/s/ f indicator bulb.
86 Door handle Body Exterior External side door handle broken. now replaced.

SAFETY INSPECTION 16/08/2016 11:48 17/08/2016 16:39 86,732 Redruth RE019802

16 Suspension 1	Slight play in both front shocks	Monitoring
17 Tyres Replace	Replace both n/s/r, & o/s/r outer (punctured) n/s/f put to o/s/r.(match pair)	
18 Wheels Check Torques		
34 Lights	OSR light lens damaged but light working	Monitoring
55 Tail Lift	Plastic sliding bars starting to pull out of rear crossmember	Monitoring
56 Comms Equipment	Baulkhead radio handset insecure-secured now	
71 Body Exterior 1	Various body damage	Awaiting Body Repair
71 Body External Steps	Step edge damaged	Monitoring
86 Door Seals	Drivers door seal has a slight tear in it	Monitoring
86 Doors Rear	Rear doors corner mods required	Awaiting Parts
86 Sliding Door	Top catch cover loose. Tightened	
87 Oxygen System	O2 regulators out of service in August 2016	Monitoring
89 Seats	Replace saloon seat base bearings.	
Camera Installation	Fault light on on CCTV control box	Awaiting Warranty
Safety Inspection	Inspection and work done by P.C.S.	
93 - D Service		
Service D		

Vehicle Deep Clean 16/08/2016 11:49 17/08/2016 12:50 86,732 Redruth RE019803

Vehicle Deep Clean Vehicle Deep Clean Saloon only.

Breakdown 26/08/2016 14:51 26/08/2016 16:45 86,852 Redruth RE019849

Breakdown Engine cuts out in warranty

Defect Repair 05/09/2016 08:01 06/09/2016 11:20 88,958 Redruth RE019871

24 Driveshaft 1 Refit propshaft after recovery. Replaced damaged bolts and clean up threads
44 Fuel System 1 Engine Cuts out, limp mode. MERC 24 came out and now has been towed to the deale

BREAKDOWN 07/09/2016 14:09 09/09/2016 16:03 89,115 Redruth RE019889

45 Engine Ad Blue
Travel Time

SAFETY INSPECTION 26/09/2016 07:51 27/09/2016 12:17 91,101 Redruth RE019972

02 Windscreen Wipers	Replaced OS washer hose	
16 Suspension 1	Slight play in both front shocks	Monitoring
18 Wheels Check Torques		
34 Lights	OSR light lens damaged but light working	
34 Lights Bulb Replacement	Replaced NSF daylight running light bulb	
43 Exhaust System 1	Replaced broken exhaust clamp	
52 Electrical Aux	Replaced faulty rechargeable torch	
55 Tail Lift	Plastic sliding bars starting to pull out of rear crossmember	Awaiting Parts
71 Body Exterior 1	Various body damage	
71 Body External Steps	Step edge damaged. Replaced rain suppressor	
85 Body Interior 1	Repaired vacuum mattress cupboard door	
86 Door Seals	Drivers door seal has a slight tear in it. Replaced seal	
86 Doors Rear	Rear doors corner mods required. Fitted	
87 Oxygen System	O2 regulators out of service in August 2016. Now up to date	
89 Seats	Refitted airways seat bar adjuster	
Camera Installation	Fault light on on CCTV control box	
Safety Inspection		
Tail Lift 6 Monthly Inspection	Statutory Inspection	

Vehicle Deep Clean	27/09/2016	10:50	27/09/2016	15:30	91,101	Redruth	RE019982
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	06/10/2016	13:02	07/10/2016	11:30	93,000	Redruth	RE020031
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

03 Instruments & Sensors 1	EML on. Merc 24hr replaced the exhaust temp sensor and carried out a regen
45 Engine Oil Top Up	Over full with engine oil causing warnings. Drained 2 litres. Erased faults
Road Test	Roadtested and the light stays off. Restart the vehicle and the EML comes on aga

SAFETY INSPECTION	07/11/2016	08:14	09/11/2016	15:20	98,886	Redruth	RE020183
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Cab Assembly 1	Glove box light staying on. Adjusted	
02 Windscreen Wipers	Replaced wiper blades	
16 Suspension 1	Slight play in both front shocks	Monitoring
18 Wheels Check Torques		
34 Lights	OSR light pod damaged	Awaiting Body Repair
55 Tail Lift	Plastic sliding bars starting to pull out of rear crossmember. Lights not flashi	Awaiting Warranty
71 Body External Steps	Step edge damaged	Awaiting Body Repair
86 Door Hinges	Tightened both front door check straps	
87 Chairs	Securing bracket broken. Removed, welded & refitted	
89 Seats	Refitted airways seat adjuster bar	
Safety Inspection		
UB Fire Suppression Discharge	Under Bonnet Fire Suppression low pressure warning sounding	Monitoring
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill	

Vehicle Deep Clean	09/11/2016	09:02	09/11/2016	15:46	98,886	Redruth	RE020199
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	13/11/2016	08:43	14/11/2016	09:39	99,403	Redruth	RE020219
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

17 Tyres Replace	Tyres rear outer tyre low, unsure if punctured. OSR inner tyre replaced
------------------	---

Defect Repair	12/12/2016	09:00	12/12/2016	09:25	105,159	Redruth	RE020397
02 Mirrors	Body Exterior nearside wing mirror. Replaced mirror glass						
Vehicle Deep Clean	16/12/2016	10:54	16/12/2016	14:36	105,840	Redruth	RE020427
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	16/12/2016	16:17	23/12/2016	14:58	105,840	Redruth	RE020429
03 Instruments & Sensors 1	EML ON BEING DONE AT CITY WEST, ROCHE						
13 Brake Pads	Replaced front and rear pads						
13 Brakes 1	Replaced rear discs						
16 Suspension 1	Slight play in both front shocks.						
17 Tyres Replace	Replaced OSF tyre						
18 Wheels Check Torques							
34 Lights	OSR light pod damaged						
55 Tail Lift	Plastic sliding bars starting to pull out of rear crossmember.						
71 Body Exterior 1	OSR lower corner moulding damaged. Sealed & replaced reflector						
71 Body External Steps	Step edge damaged						
Safety Inspection							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression low pressure warning sounding						
92 - C Service	BEING DONE AT CITY WEST, ROCHE						
Service C							
Gearbox Oil & Filter Change	BEING DONE AT CITY WEST, ROCHE						
Defect Repair	25/01/2017	13:50	25/01/2017	14:25	111,617	Redruth	RE020645
18 Wheels Balance & Alignmen	Steering steering wheel shaking at 60 mph						
71 Body Exterior 1	Body Interior side step stuck. Service due on Monday & new step to be fitted						
71 Body External Steps	Body Exterior side step not working. bent rod on grass verge						
86 Doors Rear	Doors broken. Repaired OSR door stay						
Vehicle Deep Clean	30/01/2017	10:41	31/01/2017	14:51	112,519	Redruth	RE020666
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/01/2017	17:36	03/02/2017	09:22	112,519	Redruth	RE020671

18 Wheels Balance & Alignment
 18 Wheels Check Torques
 31 Charging System Battery/Charging Sys charging socket has bent pin. Straighen pin and test
 71 Body Exterior 1 Body Exterior side step u/s. Replaced side step
 71 Body External Steps Body Exterior side step not working. bent rod on grass verge. Replaced side step
 86 Doors Rear Body Interior rear door stay bar keeps coming out. Replaced broken bolt
 86 Sliding Door Body Interior magnet for side door needs adjusting. NFF
 Medical Device and Equip Chec
 Safety Inspection
 MOT Pre Test
 Travel Time
 MOT

COMMS.FAILURE CHECK 07/03/2017 08:23 07/03/2017 12:24 119,885 Redruth RE020869

MDT Failure/Issue Error code 14 on the MDT screen. PCe repaired

Unplanned Repair 08/03/2017 08:00 08/03/2017 08:30 119,885 Redruth RE020879

02 Mirrors Replace broken mirror casing,frame and both glasses

Vehicle Deep Clean 14/03/2017 06:59 14/03/2017 14:29 121,434 Redruth RE020914

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 14/03/2017 14:15 16/03/2017 14:34 121,434 Redruth RE020915

17 Tyres Replace Rear tyres
 18 Wheels Check Torques
 34 Lighting System One number plate light very dim, found poor connection to wiring.
 52 Electrical Aux Replaced 1 x missing torch and 1 x broken torch
 56 Comms Equipment Tightened radio stalk
 71 Body Exterior 1 Replace o/s/r and n/s/r lower body corners.
 86 Door Lock Replace key fob battery.
 Safety Inspection
 WAS Firetrace rework & Service SB Ball
 Tail Lift 6 Monthly Inspection Statutory Inspection
 Annual Air Con Service Annual Air Condition Service
 Annual Heater Service Annual Heater Service

Tail Lift Annual Service Statutory Inspection and Weight Test

Unplanned Repair 22/03/2017 16:00 22/03/2017 17:00 122,356 Redruth RE020956

17 Tyres Replace Replace both front wheels and tyres.
18 Wheels Balance & AlignmenFront wheels balanced at A.T.S but still has wheel wobble.

Defect Repair 20/04/2017 09:00 20/04/2017 09:11 127,176 Redruth RE021104

01 Heating 1 Cab blower motor is not working. Due service 27/04/17 Awaiting Warranty
71 Body Exterior 1 Replaced broken front number plate

Breakdown 24/04/2017 15:54 25/04/2017 10:16 128,094 Redruth RE021124

01 Air Conditioning 1 AC belt wrapped around the cooling & stopping it from turning. RPM sensor fault
Breakdown EML. Merc 24 came to Redruth to repair cooling fan / AC belt

SAFETY INSPECTION 25/04/2017 11:05 26/04/2017 16:07 128,094 Redruth RE021127

01 Heating 1 Cab blower motor is not working. Due service 27/04/17. Repaired by City West
18 Wheels Check Torques
34 Lights Bulb Replacement Replaced NSF side light bulb. City West
85 Body Interior 1 Repaired vaccuum mattress cupboard striker plate
86 Door Lock Replaced key fob battery. City West
Safety Inspection
93 - D Service Carried out by City West Commercials
Service D

Vehicle Deep Clean 27/04/2017 07:19 27/04/2017 14:33 128,152 Redruth RE021144

Vehicle Deep Clean Vehicle Deep Clean

Defect Repair 03/05/2017 13:45 03/05/2017 14:40 129,333 Redruth RE021182

01 Heating 1 Engine Internal cab fan/ demister u/s. Needs to go to City West for repair Awaiting Warranty

85 Body Interior 1 89 Seats	Body Interior Drug safe door key missing. Supplied spare key Body Interior Drivers seat leaver u/s. Got it working but requires mechanism	Awaiting Warranty
--------------------------------	--	-------------------

Breakdown	13/05/2017	19:48	13/05/2017	21:00	131,680	Redruth	RE021236
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace Breakdown	ATS call out to replace OSR tyre REAR OFFSIDE PUNCTURE
-------------------------------	---

Vehicle Deep Clean	07/06/2017	08:58	07/06/2017	14:58	136,459	Redruth	RE021398
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/06/2017	09:45	08/06/2017	17:34	136,459	Redruth	RE021399
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Heating 1 02 Cab Ass Fire Extinguisher 18 Wheels Check Torques 44 Add Ad Blue 45 Engine Oil Top Up 86 Doors Rear 86 Sliding Door 89 Seats Safety Inspection Handbrake Cable Replacement	Engine Internal cab fan/ demister u/s. Needs to go to City West for repair Replace fire extinguishers Fill up ad blue Rear door tight to open inside remove rear door inner panel and free-up linkage. Side door tight to open .Replace door bearings. Body Interior Drivers seat leaver u/s. Got it working but requires mechanism Replace rear handbrake cables. Replace cables next year
---	---

Breakdown	30/06/2017	21:40	30/06/2017	23:00	140,643	Redruth	RE021564
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

44 Fuel System 1 Breakdown	Merc 24 attended and erased fuel rail pressure sensor fault Non Starter
-------------------------------	--

MGS Gas Storage Modifications	07/07/2017	08:15	07/07/2017	09:00	142,244	Redruth	RE021600
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

MGS Gas Storage Modifications	MGS Gas Storage Modifications, now done
-------------------------------	---

Unplanned Repair	17/07/2017	16:00	17/07/2017	16:30	144,587	Redruth	RE021676
34 Lighting System	O/s headlight not working, bulb holder u/s, new holder now fitted.						
Vehicle Deep Clean	18/07/2017	07:38	18/07/2017	12:35	144,739	Redruth	RE021677
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/07/2017	13:11	20/07/2017	12:51	144,743	Redruth	RE021683
01 Air Conditioning 1	Rear under body condenser cooling fan NW. Espar replaced condenser & fan Repaired cab center storage compartment Replaced front discs / pads & rear pads 2 x scene lights have water ingress and the other is only 66% working Exhaust tail pipe starting to hole and new will be required. Warranty claim sent Bridgeplate guides pulled out or rear frame. Drilled & replaced bolts						
02 Cab Assembly 1							
13 Brakes 1							
18 Wheels Check Torques							
34 Emergency Lights							
43 Exhaust System 1							
55 Tail Lift							
Safety Inspection							Awaiting Warranty
92 - C Service							Parts ordered in store
Service C							
Install Saloon CCTV Camera	26/07/2017	08:42	26/07/2017	12:21	144,743	Redruth	RE021730
Install Saloon CCTV Camera	John Coles fitted new camera and tested system						
Defect Repair	09/08/2017	09:00	09/08/2017	11:16	149,074	Redruth	RE021828
16 Suspension 1	Body Exterior NSF susp noise, ?topmount , no fault found. Body Exterior n/s/r reverse light lens damaged, stillworks, now replaced. Battery/Charging Sys continuously power failing, replace comms battery. Replace Vehicle Fuel Card						
34 Lights							
56 Comms Power Failure							
Replace Vehicle Fuel Card							
Defect Repair	25/08/2017	13:45	25/08/2017	14:16	152,672	Redruth	RE021931
86 Doors Rear	Rear door stay broken. Drilled out broken bolts & replaced. Refitted stay						

SAFETY INSPECTION	12/09/2017	15:09	18/09/2017	15:57	156,580	Redruth	RE022039
02 Windscreen Wipers	Replaced wiper blades						
15 Steering 1	PAS pump leaking from hose. repaired by Mercedes of Truro						
16 Suspension 1	Both front shocks have play. Replaced by Mercedes of Truro						
16 Suspension 2	OSF lower ball joint replaced by Mercedes of Truro						
16 Suspension 3	Rear spring leaf seperators x 4 replaced by Mercedes of Truro						
17 Tyres Replace	Replaced both front tyres						
18 Wheels Check Torques							
34 Emergency Light System	Replaced OSF alley light bulb						
34 Emergency Lights	2 x scene lights have water ingress and the other is only 66% working						Awaiting Warranty
43 Exhaust System 1	Exhaust tail pipe starting to hole and new will be required. Replaced tail pipe						
Safety Inspection							
Gearbox Oil & Filter Change							
Tail Lift 6 Monthly Inspection	Statutory Inspection						

Vehicle Deep Clean	19/09/2017	08:05	19/09/2017	12:16	156,721	Redruth	RE022084
Vehicle Deep Clean	Vehicle Deep Clean. More time needed as was overdue a clean						
Unplanned Repair	19/09/2017	13:00	19/09/2017	15:33	156,721	Redruth	RE022091
31 Battery Aux	Rear AUX battery smell, battery u/s and now replaced.						

Vehicle Deep Clean	10/10/2017	12:05	16/10/2017	13:42	159,878	Redruth	RE022227
Vehicle Deep Clean	Vehicle Deep Clean UNFINISHED & MADE AVAILABLE FOR THE WEEKEND						
SAFETY INSPECTION	10/10/2017	15:49	13/10/2017	10:07	159,878	Redruth	RE022229

18 Wheels Check Torques							
34 Emergency Lights	2 x scene lights have water ingress and the other is only 66% working. Replaced						
86 Door Blinds	Rear door blind not closing - warranty form sent						Awaiting Warranty
Medical Devices Repair	Replaced broken Mangar charger board						
Safety Inspection							
UB Fire Supp 6mts Service	Serviced and now pressure warning sounding. warranty claim form sent to WAS						Awaiting Warranty
UB Fire Suppression Service	Serviced and now pressure warning sounding. warranty claim form sent to WAS						

BREAKDOWN	23/10/2017	10:55	27/10/2017	14:32	161,575	Redruth	RE022312
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

32 Starting System 1	Engine trouble starting starter sticking. Sent to Mercedes of Truro
43 Exhaust System 1	Engine burning smell after emergency drive. Vehicle regenerated
45 Engine 1	Engine cutting out while driving

Breakdown	08/11/2017	17:20	13/11/2017	11:52	162,060	Redruth	RE022426
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

03 Instruments & Sensors 1	Checked with STAR & mercedes 24 hr called
43 Exhaust System 1	DPF full. Replaced by City West Commercials
44 Fuel System 1	Fuel rail pressure wiring fault. City West Commercials replaced wiring loom
52 Electrical Aux	Fire warning going off every 30 seconds. Repaired wiring fault John Coles
Breakdown	eng. shuts down each time vehicle stops

SAFETY INSPECTION	20/11/2017	09:54	21/11/2017	16:06	163,671	Redruth	RE022497
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	Other fire trace pressure low, now repaired.
17 Tyres Replace	Replace all four rear tyres.
18 Wheels Check Torques	
34 Lights	N/s/f body marker light damsged. now replaced.
52 Electrical Aux	Electrical Auxs fire warning going off every 30 seconds. now repaired.
55 Tail Lift	Remove o/s tail lift side arm and tighten adjusting bars.
71 Body Exterior 1	Replace n/s/f saloon body corner.
86 Door Blinds	Rear door blind not closing - warranty form sent
86 Doors Rear	Replace o/s/r door stay.
86 Sliding Door	Side door not opening correctly. free-up door.
Safety Inspection	
UB Fire Supp 6mts Service	Serviced and now pressure warning sounding. warranty claim form sent to WAS
93 - D Service	
Service D	

Vehicle Deep Clean	21/11/2017	09:26	21/11/2017	14:21	163,671	Redruth	RE022506
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	09/12/2017	07:21	09/12/2017	10:57	167,828	Redruth	RE022639
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

27 Transmission Automatic Breakdown	Won't shift above 2nd gear. Merc 24hr called to investigate / repair won't shift above 2nd						
-------------------------------------	--	--	--	--	--	--	--

Breakdown	18/12/2017	23:53	21/12/2017	08:51	169,748	Redruth	RE022704
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Charging System Breakdown	Battery/Charging Sys Battery/alternator red light on, battery low Engine warning lights						
------------------------------	---	--	--	--	--	--	--

MRO Refresh	21/12/2017	08:50	21/12/2017	10:43	169,806	Redruth	RE022721
--------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

MRO Refresh							
-------------	--	--	--	--	--	--	--

BREAKDOWN	02/01/2018	08:21	02/01/2018	14:00	171,526	Redruth	RE022771
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

03 Instruments & Sensors 1 41 Air Intake Road Test	EML on and no power Throttle valve stored fault (only 2 instances). Deleted stored faults						
--	--	--	--	--	--	--	--

Vehicle Deep Clean	02/01/2018	12:01	03/01/2018	11:58	171,526	Redruth	RE022773
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	03/01/2018	12:00	04/01/2018	15:27	171,535	Redruth	RE022782
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors	replace mirror arm and components						Monitoring
16 Suspension 1	advise wear in n/s/f lower balljoint within manufactures specifications						
18 Wheels Check Torques							
34 Emergency Lights	carryout repair to n/s/r lamp lense						
34 Lights	repair number plate lamp						
34 Lights Bulb Replacement	replaced n/s/r upper flashing red lamp unit and replace o/s/r fog lamp						
52 Electrical Aux	carryout repairs to light wiring to rear lights						
86 Door Lock	repair drivers door lock						
86 Doors Rear	rectify rear locker alarm going off						
87 Stretcher	carried out repair to stretcher locking mech housing						
Safety Inspection							
MOT Pre Test							

Tail Lift Annual Service Statutory Inspection and Weight Test
Tail Lift 6 Monthly Inspection Statutory Inspection

BREAKDOWN 31/01/2018 11:01 31/01/2018 16:10 177,557 Redruth RE022982

24 Driveshaft 1 Brakes Noisy under braking, scraping when not. Rear prop UJ U/S. Replaced
Road Test

SAFETY INSPECTION 12/02/2018 15:34 13/02/2018 15:59 179,554 Redruth RE023055

02 Windscreen windscreen washers inop, repaired and replaced wipers
13 Brakes 1 adjust rear brakes & handbrake
16 Suspension 1 advise wear in n/s/f lower balljoint within manufactures specifications Monitoring
18 Wheels Check Torques
86 Doors Rear rear door lock barrel seized removed lock freed off and reassembled
Safety Inspection
85 Body Int Alcohol Gel Dispen
Travel Time
MOT

BREAKDOWN 06/03/2018 15:31 08/03/2018 15:00 183,163 Redruth RE023204

01 Air Conditioning 1 Compressor retaining bolts fallen out & thrown the belt. Compressor replaced
01 Air Conditioning 2 Engine exhaust gas smell entering vehicle interior. Refridgerant smell
Annual Air Con Service Annual Air Condition Service cab & saloon whilst warranty repair done
Annual Heater Service Annual Heater Service carried out whilst warranty repair on AC

Vehicle Deep Clean 26/03/2018 10:29 26/03/2018 10:33 185,455 Redruth RE023331

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean 26/03/2018 10:33 26/03/2018 16:01 185,455 Redruth RE023332

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	27/03/2018	10:04	28/03/2018	16:30	185,625	Redruth	RE023341
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Air con belt replaced ,
13 Brakes 1	Replace rear brake discs and pads.
13 Handbrake	Replace handbrake shoes.
16 Suspension 1	advise wear in n/s/f lower balljoint within manufactures specifications
18 Wheels Check Torques	
34 Lighting System	Electrical Auxs cab light not working, replace bulb.
52 Electrical Aux	Electrical Auxs rugged cot battery not working. not lifting
87 Stretcher	Body Interior rugged strap missing, now replaced.
Safety Inspection	
92 - C Service	
Service C	
Fit Poster Holder	Fit Poster Holder
Wheel Hub Flanges Replaceme	
Handbrake Cable Replacement	Replace rear handbrake cables

BREAKDOWN	05/04/2018	07:30	06/04/2018	16:12	185,729	Redruth	RE023401
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Air con /aux belt detached. replace belt and guide roller.
71 Body External Steps	Side step damaged and not working. straighten and replace guide rollers

Breakdown	19/04/2018	15:34	20/04/2018	15:16	187,465	Redruth	RE023500
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	radiator coolant light on (red)
-----------	---------------------------------

SAFETY INSPECTION	08/05/2018	15:13	17/05/2018	08:48	191,124	Redruth	RE023640
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	AC belt thrown and hanging down, replace tensioner,
02 Cab Ass Fire Extinguisher	Replaced both fire extinguishers with in service units
13 Brakes 1	Replace front brake discs and pads.
17 Tyres Replace	Replace both front tyres.
18 Wheels Check Torques	
34 Emergency Lights	Replaced airport beacon, NSR side scene lamp & secured OSR corner blue lens
34 Lighting System	Reverse lights flashing when n/s indicator on.replace n/s top indicator &o/s fog
34 Lights Bulb Replacement	O/s/f side light, out replace bulb.
Safety Inspection	

Vehicle Deep Clean	15/05/2018	14:09	16/05/2018	14:39	191,124	Redruth	RE023685
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Vehicle Deep Clean	21/06/2018	07:54	21/06/2018	14:20	198,926	Redruth	RE023947
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	21/06/2018	12:36	22/06/2018	16:17	198,926	Redruth	RE023948
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

15 Steering 1	minor play in n\s track rod,monitor					Monitoring
16 Suspension 1	replace n/s suspension wishbone					
17 Tyres Replace	replace rear tyres					
18 Wheels Check Torques						
18 Wheels Removal	derust rear wheels and hub contact surfaces					
34 Lights	repair number plate lamp					
34 Lights Bulb Replacement	replace o\s wing indicator bulb					
45 Engine 1	engine oil leak, investigate & carryout repairs					
52 Electrical Aux	replace passenger side window switch					
55 Tail Lift	repair tail lift panel					
85 Body Interior 1	repair o\s\r upper locker hinge					
99 Diagnostic Test	carryout diagnostic checks,erase fault codes,reset service indicator					
Safety Inspection						
Tail Lift 6 Monthly Inspection	Statutory Inspection					

Vehicle Deep Clean	31/07/2018	07:42	31/07/2018	15:01	207,052	Redruth	RE024210
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	31/07/2018	16:40	08/08/2018	10:22	207,052	Redruth	RE024217
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	passenger seat trim adrift,refit trim					Monitoring
13 Brakes 1	derust, clean and grease brake pipes					
13 Brakes 2	carried out brake fluid service					
15 Steering 1	minor play in n\s track rod,monitor					
18 Wheels Check Torques						

34 Emergency Light System	replaced o/s/r upper blue light
34 Lights	Body Exterior nearside foglight trim missing
45 Engine 1	viscous fan broken up causing damage to various parts ,see notes
52 Electrical Aux	replaced missing torch
99 Diagnostic Test	reset service indicator and clear memory codes
Safety Inspection	
93 - D Service	
Service D	
Gearbox Oil & Filter Change	

Breakdown	11/08/2018	19:34	21/08/2018	15:21	207,929	Redruth	RE024281
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

44 Fuel System 1 Breakdown	Repaired wiring to injector & replaced all six injector seating washers. MB Trur EML on limp mode
-------------------------------	--

Breakdown	30/08/2018	13:40	30/08/2018	16:05	209,300	Redruth	RE024398
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Emergency Lights	Body Exterior cracked rear side blue light	Monitoring
34 Lights Bulb Replacement	Replaced NSF day running bulb	
56 Comms Equipment	Replaced missing radio aerial	
86 Sliding Door	Replaced broken side door outer handle & lubed door	
Breakdown	Sliding door handle missing	
Camera Installation	Replaced NS camera outer cover	

Breakdown	11/09/2018	07:02	11/09/2018	11:48	211,584	Redruth	RE024481
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

03 Instruments & Sensors 1 Breakdown Road Test	No EML on. Checked with STAR & NFF. Loss Of Power Roadtested as intermitently changing gear. but NFF
--	--

Vehicle Deep Clean	11/09/2018	11:18	11/09/2018	15:31	211,923	Redruth	RE024485
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	11/09/2018	15:22	14/09/2018	15:03	211,923	Redruth	RE024491
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	Centre consul lid broken, Refitted & replaced lock assembly
-------------------	---

02 Windscreen Wipers	Replaced wiper blades	
15 Steering 1	minor play in n\s track rod,monitor	Monitoring
18 Wheels Check Torques		
34 Emergency Lights	Body Exterior cracked rear side blue light 7 faulty. replaced light	
34 Lights	NSF front contour marker light NW. Replaced	
44 Fuel System 1	Replaced fuel cap with mis fueling device	
55 Tail Lift	Slow close not working	Lack of Labour
86 Door Hinges	Side door centre hinge tight to open door. Freed up & replaced lower bearing	
86 Door Lock	Scoop locker voice warning on RH bends	
86 Doors	Replaced broken drivers window switch	
Safety Inspection		

Breakdown	16/09/2018	03:34	16/09/2018	04:45	212,414	Redruth	RE024525
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace Breakdown	ATS call out to replace OSR outer tyre (punctured) bolt in driver rear outer tyre
-------------------------------	--

Breakdown	22/09/2018	00:24	25/09/2018	14:36	213,390	Redruth	RE024576
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

41 Turbo 99 Diagnostic Test Breakdown Road Test	Pressure pipes form turbo fixing bracket broken. Replaced bracket & all seals Tests carried out and faults erased ? Turbo/Engine Issue Extended road test and all ok
--	---

ACCIDENT	05/10/2018	07:34	05/10/2018	14:04	214,808	Redruth	RE024637
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body External Steps Breakdown	Side step hit.repaired step side step drops on deployment
-------------------------------------	--

SAFETY INSPECTION	22/10/2018	10:02	23/10/2018	15:21	216,699	Redruth	RE024766
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brakes 1 15 Steering 1 18 Wheels Check Torques 18 Wheels Removal 24 Driveshaft 1 52 Electrical Aux	adjust rear brakes and handbrake minor play in n\s track rod,monitor retorque wheels after refitting and retorque again after roadtest remove front wheels and swop with o/s/r for even wear on tyres grease nipple missing removed shaft and replaced grease nipple,regreased shaft carryout SAT NAV upgrade	Monitoring
--	--	------------

55 Tail Lift	Slow close not working					Awaiting Parts	
71 Body Exterior 1	damage to n/s/f bumper					Awaiting Body Repair	
86 Door Lock	side door lock insecure,secured latch						
99 Diagnostic Test	carryout diagnostic checks and erased memory						
Safety Inspection							
Vehicle Deep Clean	23/10/2018	15:05	24/10/2018	12:10	216,707	Redruth	RE024776
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	06/11/2018	12:26	13/11/2018	15:24	218,819	Redruth	RE024885
03 Instruments & Sensors 1	Engine limited power/engine management light						
27 Transmission Automatic	Erratic gear changes. Possibly due to low power						
41 Turbo	Blown impellor in turbo. Turbo replaced by MB, Truro. Hoses etc						
99 Diagnostic Test	Checked on diagnostics. Cleared faults and roadtested						
Breakdown	Lost power, burning smell						
SAFETY INSPECTION	03/12/2018	15:54	06/12/2018	12:33	222,569	Redruth	RE025086
02 Cab Assembly 1	cab light inop,replaced bulb						
15 Steering 1	minor play in n\s track rod,monitor					Monitoring	
17 Tyres Replace	replace worn n/s/r outer tyre						
18 Wheels Check Torques	retorque wheels after refitting and retoque again after roadtest						
18 Wheels Removal	swop n/s/r wheel with n/s/f for even wear and clean contact surfaces						
55 Tail Lift	Slow close not working requires repair by south west lifts					Monitoring	
71 Body Exterior 1	damage to n/s/f bumper and rear light cluster housings						
71 Body External Steps	side step not functioning correctly,rectified fault						
99 Diagnostic Test	carryout diagnostic test						
engine	replace dpf temp sensor						
Safety Inspection							
Sealing of stretcher clamp	Sealing of stretcher clamp						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	05/12/2018	08:02	05/12/2018	15:12	222,569	Redruth	RE025100
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	13/12/2018	10:15	13/12/2018	11:54	223,532	Derriford	DE025667
86 Doors Rear	Replace o/s/r door stay mount see notes						
Breakdown	23/12/2018	20:40	24/12/2018	11:46	225,083	Redruth	RE025232
34 Lighting System Breakdown	Replace n/s/headlight bulb holder. main headlight drivers side unit damaged						
Unplanned Repair	03/01/2019	08:35	03/01/2019	08:55	226,132	Redruth	RE025267
86 Door Lock	Replaced key C/L battery						
SAFETY INSPECTION	11/01/2019	10:00	16/01/2019	15:36	226,132	Redruth	RE025336
13 Brake Pads	Replace rear brake pads.						
13 Brakes 1	Replace front brake pads and discs.						
15 Steering 1	minor play in n/s track rod,monitor						
17 Tyres Replace	Replace both o/s/r tyres.						
18 Wheels Check Torques							
34 Lighting System	Replace number plate light n/s						
55 Tail Lift	Slow close not working requires repair by south west lifts, now repaired						
86 Sliding Door	Replace side door lower catch cover.						
Safety Inspection							
92 - C Service							
Service C							
MOT Pre Test							
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Travel Time							
MOT							
Vehicle Deep Clean	16/01/2019	08:05	16/01/2019	11:46	226,132	Redruth	RE025358
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	19/01/2019	21:06	21/01/2019	10:46	226,334	Redruth	RE025392
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Mirrors Breakdown	Replace n/s mirror glass,frame and cover and repair wiring. N/S wing mirror damage						
-------------------------	---	--	--	--	--	--	--

BREAKDOWN	14/02/2019	10:00	14/02/2019	11:12	230,910	Redruth	RE025575
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace	Both NSR tyres replaced at ATS Redruth						
------------------	--	--	--	--	--	--	--

Vehicle Deep Clean	27/02/2019	11:35	28/02/2019	10:07	233,417	Redruth	RE025655
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	27/02/2019	16:17	04/03/2019	09:29	233,417	Redruth	RE025663
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	replace extinguishers due on date						
02 Cab Assembly 1	cab cupboard latch adrift replaced screws and refitted						
13 Brakes 1	adjusted rear brakes and handbrake						
13 Brakes 2	derust rear brake pipes and grease						
15 Steering 1	replaced n/s steering rack arm and track rod end						
15 Steering 2	check and adjust tracking						
18 Wheels Check Torques	retorque wheels after refitting and retorque again after roadtest						
31 Charging System Battery	investigate poor starting,carried out battery test ,replaced battery,see notes						
55 Tail Lift	remove safety bars and retighten,refit safety bars and adjust						
71 Body Exterior 1	damage to n/s/f bumper						Awaiting Body Repair
71 Body External Steps	replaced side step spray suppressor						
85 Body Interior 1	n/s/r saloon cupboard trim adrift,repared						
85 Body Interior 2	front lower cupboard beneath seat hinge adrift,refitted						
86 Door Lock	free off rear door lock barrel						
99 Diagnostic Test	service light on erase memory and reset service indicator						
Safety Inspection							
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab						

Breakdown	18/03/2019	07:26	18/03/2019	09:13	235,687	Redruth	RE025767
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Side doot not opening from outside, remove cover adjust linkage etc.						
-----------	--	--	--	--	--	--	--

SAFETY INSPECTION	08/04/2019	08:38	09/04/2019	16:00	239,269	Redruth	RE025895
17 Tyres Replace	Replace o/s/f tyre.						
18 Wheels Check Torques							
34 Lighting System	Reverse lights flashing when n/s indicator on, earth fault repaired .						
71 Body Exterior 1	damage to n/s/f bumper						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service, rear fan replaced by Espar.						
Annual Heater Service	Annual Heater Service, burner replaced.						
UB Fire Suppression Service							
Vehicle Deep Clean	09/04/2019	08:00	09/04/2019	11:25	239,262	Redruth	RE025903
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	11/06/2019	11:28	12/06/2019	11:26	250,854	Redruth	RE026265
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	12/06/2019	12:16	14/06/2019	10:09	250,854	Redruth	RE026277
13 Brakes 1	adjust rear brakes and handbrake						
16 Suspension 1	n/s/r leaf spring rubber seperators worn,replaced						
17 Tyres Replace	replaced worn n/s/f tyre						
18 Wheels Balance & Alignment	check and adjust wheel alignment						
18 Wheels Check Torques	retorque wheels after refitting and retorque again after roadtest						
18 Wheels Removal	derust and clean contact surfaces						
34 Lights Bulb Replacement	replaced o/s/f daytime run light bulb						
43 Exhaust System 1	replaced corroded tailpipe section and brackets						
45 Engine 1	coolant warning light on,check level,removed excess coolant,rectified fault						
45 Engine 2	metal air intake pipe loose secured pipe						
45 Engine 3	eml light on,dpf blocked carried out dpf clean,cleared fault codes,rectied fault						
85 Body Interior 1	repair front drugs locker hinge, repaired cab locker hinge						
86 Doors Rear	free off seized rear door lock barrel						
86 Sliding Door	crew reported Side door sticking,checked operation door functioning correctly						
99 Diagnostic Test	carryout diagnostic checks and reset service indicator						
Safety Inspection							
Pollen Filter Change	Pollen Filter Change						

Fuel Filter Change
Air Filter Change
Tail Lift Inspection

Change Fuel Filter
Air Filter Change

SAFETY INSPECTION	26/11/2019	08:00	26/11/2019	08:01	251,266	Dorchester	DC021280
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	26/11/2019	08:00	26/11/2019	08:01	251,266	Dorchester	DC021281
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	26/11/2019	08:00	26/11/2019	08:01	251,266	Dorchester	DC021282
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	26/11/2019	08:14	18/12/2019	12:15	251,278	Dorchester	DC021283
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	Rear pads worn
13 Brakes 1	Front discs and pads worn
13 Brakes 2	Telmar u/s
16 Suspension 1	Rear shocks u/s and O/S slipper pads
16 Suspension 2	Front arms and struts u/s
17 Tyres	o/s/r low
18 Wheels Check Torques	
31 Battery Chassis	Batt u/s
42 Coolant System	light on
44 Fuel System 1	leak on filter
45 Engine 1	Oil leak from level sensor
45 Engine 2	Alt belt and tensioner u/s
45 Engine Ad Blue	Top up
85 Body Interior 2	fire exts out of date
86 Door Lock	let set required
Check Vehilce Call Signs	Check vehilce call signs are fitted and correct
Safety Inspection	
Axle Oil Change	Axle Oil Change
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	

UB Fire Supp 6mts Service UB Fire Supp 6mts Service
 Engine Change Oil & Filter
 MOT
 Brakes Replace Brake Fluid
 Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Vehicle Deep Clean **16/12/2019** **11:30** **17/12/2019** **12:00** **251,278** **Dorchester** **DC021419**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **18/12/2019** **08:00** **18/12/2019** **08:01** **251,288** **Dorchester** **DC021432**

18 Wheels Check Torques
 Safety Inspection
 Vehicle Deep Clean Vehicle Deep Clean
 Tail Lift Inspection

Vehicle Deep Clean **18/12/2019** **08:00** **18/12/2019** **08:01** **251,288** **Dorchester** **DC021433**

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean **18/12/2019** **08:00** **18/12/2019** **08:01** **251,288** **Dorchester** **DC021434**

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean **18/12/2019** **08:00** **18/12/2019** **08:01** **251,288** **Dorchester** **DC021435**

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN **16/01/2020** **08:45** **17/01/2020** **15:06** **252,099** **Dorchester** **DC021611**

15 Steering 1 Steering power steering noisy

BREAKDOWN **25/01/2020** **21:40** **27/01/2020** **06:21** **253,128** **Dorchester** **DC021680**

56 Comms Equipment mobi med u/s
 86 Sliding Door Doors Side door magnet u/s

Travel Time

Unplanned Repair	27/01/2020	10:49	27/01/2020	11:46	253,642	Dorchester	DC021683
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

42 Coolant System	Coolant loss reported
-------------------	-----------------------

Breakdown	08/02/2020	01:53	08/02/2020	23:59	255,000	Dorchester	DC021757
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	remote key fob not working
-----------	----------------------------

ACCIDENT	12/02/2020	12:56	28/03/2020	06:59	257,352	Dorchester	DC021786
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body Exterior Acc Repair	Recovery after RTC
Breakdown	

SAFETY INSPECTION	28/03/2020	06:59	28/03/2020	07:01	257,550	Dorchester	DC022058
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	28/03/2020	07:01	30/03/2020	09:07	257,557	Dorchester	DC022059
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

03 Instruments & Sensors 1	Radiator/Cooling Sys Coolant sensor fault
03 Instruments & Sensors 2	Radiator/Cooling Sys coolant leak
16 Suspension 1	ARB links worn
17 Tyres	2x n/s/r low
18 Wheels Check Torques	
34 Lights	Reverse light inop
71 Body Exterior 1	Rear flap loose
71 Body External Steps	Other Side step not deploying
Safety Inspection	
Travel Time	drop back
Tail Lift Inspection	

Vehicle Deep Clean	31/03/2020	08:30	31/03/2020	11:30	257,567	Dorchester	DC022074
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	01/04/2020	08:16	01/04/2020	10:15	257,697	Dorchester	DC022078
Breakdown	side door is not opening						
BREAKDOWN	04/04/2020	18:00	05/04/2020	15:00	258,487	Dorchester	DC022104
71 Body External Steps Travel Time	Step beaten off						
SAFETY INSPECTION	22/04/2020	07:30	23/04/2020	07:21	260,317	Dorchester	DC022226
18 Wheels Check Torques							
34 Emergency Lights	grill light loose						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
Safety Inspection							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
UB Fire Supp 12mts Service	Service of fire supression system						
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Tail Lift Inspection							
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	24/04/2020	07:30	24/04/2020	13:25	260,329	Dorchester	DC022252
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	31/05/2020	07:30	01/06/2020	09:00	266,640	Dorchester	DC022494
02 Windscreen Wipers	washer pipe split						
03 Instruments & Sensors 1	service light on						
17 Tyres	3x low						
18 Wheels Check Torques							
34 Emergency Lights	grill light inop, o/s side upper blue inop,						

34 Lighting System	rear white upper light not working
34 Lights	front fogs n/w
45 Engine Ad Blue	top up
45 Engine Oil Top Up	top up
85 Body Interior 1	interior light not working
85 Body Interior 2	torch not charging
Safety Inspection	
Travel Time	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service

Vehicle Deep Clean	01/06/2020	09:30	01/06/2020	16:30	266,647	Dorchester	DC022513
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	15/06/2020	11:45	15/06/2020	11:48	268,761	Glastonbury Workshop	GW019403
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-----------------------------	-----------------

34 Lights Bulb Replacement	Replace ns indicator repeater
----------------------------	-------------------------------

Unplanned Repair	06/07/2020	13:00	06/07/2020	14:37	273,699	Dorchester	DC022750
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

42 Coolant System	Level low light on.
-------------------	---------------------

Breakdown	11/07/2020	15:51	12/07/2020	01:42	274,300	Dorchester	DC022784
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	very low levels; amber warning; VOR	Awaiting Parts
-----------	-------------------------------------	----------------

Breakdown	12/07/2020	01:42	06/08/2020	15:15	274,391	Dorchester	DC022785
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

002 Major Unit Replace Eng		
17 Tyres Replace	Both n/s/r worn,o/s/r inner punctured	
34 Emergency Lights	n/s wing light inop.Replace light unit.Sort out messed up wiring from dealer	
34 Lighting System	o/s/r fog lamp smashed	
45 Engine 1	Engine not turning over	
45 Engine Ad Blue		
71 Body Exterior 1	o/s/r light cluster broken	Awaiting Parts
71 Body External Steps	sliding step sticking	
85 Body Interior 1	fire extinguisher OOD	

85 Body Interior 2	saloon cupboard strap broken
86 Doors Rear	n/s/r door stay bent
86 Sliding Door	Upper magnet bracket bent
Breakdown	very low levels; amber warning; VOR
Travel Time	
18 Wheels Check Torques	
Safety Inspection	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
Tail Lift Inspection	

Vehicle Deep Clean	07/08/2020	10:30	07/08/2020	14:00	274,404	Dorchester	DC022985
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	14/08/2020	12:15	14/08/2020	12:25	275,999	Dorchester	DC023046
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body Exterior 1	o/s/r light cluster broken	Awaiting Parts
86 Sliding Door	Doors Side door handle inoperable externally	

Unplanned Repair	18/08/2020	11:30	18/08/2020	11:59	276,561	Dorchester	DC023067
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Door Lock	side door lock handle stuck out
--------------	---------------------------------

Unplanned Repair	20/08/2020	13:00	20/08/2020	14:00	276,818	Dorchester	DC023096
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

56 Comms Equipment	Other H/H Aerial replacement
86 Doors	Doors Side door handle lock jammed - again
86 Sliding Door	Doors SIDE DOOR HANDLE SLIPPED AGAIN

SAFETY INSPECTION	25/08/2020	14:30	27/08/2020	07:21	277,743	Dorchester	DC023132
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	Dash Panel Broken
13 Brakes 1	front and rear low
17 Tyres	N/S/F low
18 Wheels Check Torques	

44 Add Ad Blue	top up
45 Engine Oil Top Up	top up
71 Body Exterior 1	o/s/r light cluster broken
Safety Inspection	
Engine Change Oil & Filter	engine replaced at 274391 miles refer to DC022785

Vehicle Deep Clean	27/08/2020	09:15	28/08/2020	11:00	277,757	Dorchester	DC023146
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	05/09/2020	16:41	07/09/2020	08:17	279,090	Dorchester	DC023196
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors Breakdown	n/s mirror glass smashed,replace near side mirror broken off
-------------------------	---

Breakdown	14/09/2020	12:06	17/09/2020	07:48	279,100	Dorchester	DC023268
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	near wing mirror smashed
-----------	--------------------------

Unplanned Repair	01/10/2020	14:05	01/10/2020	14:18	282,678	Dorchester	DC023404
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	replace OSF repeater bulb
----------------------------	---------------------------

Breakdown	02/10/2020	09:37	08/10/2020	12:19	282,874	Dorchester	DC023405
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Emergency Lights	n/s/r upper lens smashed
34 Lights	n/s reverse light inop
45 Engine 1	Fumes in cab
45 Engine Ad Blue	
71 Body External Steps	Step damaged,not opening correctly,warning going off
86 Door Lock	Central locking inop on rear door
87 - Stretchers/Chairs/Boards	Floor mount fallen apart,reassemble
Breakdown	fumes in cab
18 Wheels Check Torques	
Safety Inspection	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
Tail Lift Inspection	Under ride bars ripped out

Vehicle Deep Clean	08/10/2020	13:30	09/10/2020	10:00	282,959	Dorchester	DC023451
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	13/11/2020	10:45	16/11/2020	14:04	287,695	Dorchester	DC023695
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	A/C pipes routed incorrectly.. Pentagons Again...
02 Windscreen Wipers	washers blocked, blades u/s
03 Instruments & Sensors 1	Service light on
11 Axle Rear	Both hub seals leaking, o/s/r wheel bearing u/s
13 Handbrake	Shoes breaking up..replaced
17 Tyres	2x low, swap around on axle to fit cross climates to fronts
18 Wheels Check Torques	
24 Driveshaft 1	Prop u/s
34 Emergency Lights	O/S grill light inop
45 Engine 1	Fire trace routed in correctly... Pentagons again..
45 Engine Ad Blue	top up
55 Tail Lift	Rails siezed and magnet missing
56 Comms Equipment	EPCR cradle broken
85 Body Interior 1	2x fire exts out of date
85 Body Interior 2	Drug locker door hinge loose/damaged
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Replace Handbrake Cables	Replace Handbrake Cables

Vehicle Deep Clean	17/11/2020	08:15	17/11/2020	12:40	287,695	Dorchester	DC023712
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	08/12/2020	19:53	09/12/2020	11:03	290,316	Dorchester	DC023867
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	loss of power
-----------	---------------

SAFETY INSPECTION	30/12/2020	07:00	31/12/2020	10:07	294,921	Dorchester	DC023991
02 Cab Assembly 1	floor plate damaged						
02 Mirrors	refit NS mirror cover correctly				Awaiting Parts		
13 Brake Pads	Front pads worn,replace						
13 Handbrake	adjust						
17 Tyres Replace	Rear tyres on limit						
18 Wheels Check Torques							
34 Emergency Lights	OSF upper inner LED light at 50%				Monitoring		
34 Lighting System	replace NSR yellow marker						
45 Engine 1	viscous fan strap bolt missing (temp repair)						
45 Engine Oil Top Up	top up						
71 Body Exterior 1	NSR corner cap and reflector damaged				Monitoring		
85 Body Interior 1	replace bag cupboard strap						
85 Body Interior 2	replace stratcher guide buffer						
Safety Inspection							
MOT							
Pollen Filter Change	Pollen Filter Change						
Vehicle Deep Clean	31/12/2020	10:00	31/12/2020	14:53	294,934	Dorchester	DC024008
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	09/01/2021	17:27	09/01/2021	19:00	295,872	Dorchester	DC024072
17 Tyres Replace	O/S/F tyre replaced by ATS						
Breakdown	flat tyre						
Breakdown	17/01/2021	06:39	17/01/2021	09:40	296,861	Dorchester	DC024138
Breakdown	O/S headlight replaced by S Howells @ Yeovil						
Unplanned Repair	22/01/2021	11:24	22/01/2021	12:40	297,969	Dorchester	DC024189
34 Lights Bulb Replacement	replace OS headlight bulb and NS repeater bulb						
71 Body External Steps	Side step deploying						

SAFETY INSPECTION	03/02/2021	09:54	15/02/2021	15:30	299,492	Dorchester	DC024271
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	A/C adjuster u/s
02 Cab Assembly 1	floor plate damaged
02 Windows/Glass	n/s switch u/s
03 Instruments & Sensors 1	EML and service light on
16 Suspension 1	Rear spring eye bushes worn
17 Tyres	n/s/f tyre u/s
18 Wheels	Rim u/s
18 Wheels Check Torques	
34 Emergency Light System	both rear corner blue lens damaged
34 Emergency Lights	OSF upper inner LED light at 50%
34 Lights	n/s/f top white led u/s
45 Engine Ad Blue	Top up
56 Comms Equipment	Radio & Comm System Radio drops signal, unusable
71 Body Exterior 1	NSR corner cap and reflector damaged
71 Body External Steps	Step sticking
86 Sliding Door	bearings rough
Safety Inspection	
Travel Time	take to merc exeter
Tail Lift Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter

Vehicle Deep Clean	16/02/2021	08:15	16/02/2021	12:15	299,645	Dorchester	DC024364
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	16/02/2021	12:45	19/02/2021	09:49	299,652	Dorchester	DC024365
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Ad Blue	AdBlue fault again (Just returned from dealer for the same fault)
Road Test	
Travel Time	take to exeter

Breakdown	24/02/2021	12:14	25/02/2021	08:21	300,300	Dorchester	DC024444
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Adblue warning on
-----------	-------------------

Breakdown	08/03/2021	06:01	08/03/2021	07:30	302,645	Dorchester	DC024514
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Sidedoor alarm randomly going off						
-----------	-----------------------------------	--	--	--	--	--	--

Vehicle Deep Clean	23/03/2021	08:51	23/03/2021	13:36	305,408	Dorchester	DC024611
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	23/03/2021	12:45	24/03/2021	09:04	305,408	Dorchester	DC024613
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	Rears Low						
17 Tyres	O/S/F tyre low						
18 Wheels Check Torques							
34 Lights	Number plate light damaged						
45 Engine 1	oil leak/fumes clamp turbo to DPF,bracktk turbo to boost tube...WARRANTY ????					Monitoring	
45 Engine Ad Blue	Top up						
89 Seats	Attendant seat arm rest pin broken off						
Safety Inspection							
Engine Change Oil & Filter							
Tail Lift Inspection							

Breakdown	12/04/2021	20:35	12/04/2021	22:00	309,385	Dorchester	DC024756
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	flat tyre rear nearside outer						
-----------	-------------------------------	--	--	--	--	--	--

Breakdown	01/05/2021	14:11	05/05/2021	12:52	313,286	Dorchester	DC024880
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

03 Instruments & Sensors 1	sat nav u/s						
03 Instruments & Sensors 2	EML and service light						
13 Brakes 1	Front disc and pads worn						
13 Calipers	N/S caliper u/s						
34 Emergency Light System	N/S/R corner blue lens damaged						
45 Engine 1	oil leak/fumes clamp turbo to DPF,bracket turbo to boost tube...WARRANTY ????						
45 Engine Ad Blue	top up						

71 Body Exterior 1	Body Exterior FRONT BUMPER AND NUMBER PLATE DAMAGE
71 Body Exterior 2	Tail lift guides u/s
71 Body External Steps	Side step sticking
Breakdown	Non start - bAttery link not working
18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 12mts Service	Service of fire suppression system
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service

Vehicle Deep Clean	06/05/2021	09:35	06/05/2021	14:15	313,297	Dorchester	DC024909
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	16/05/2021	11:42	18/05/2021	07:16	314,187	Dorchester	DC024993
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	MDT not accepting booking
-----------	---------------------------

SAFETY INSPECTION	14/06/2021	11:35	15/06/2021	14:00	318,983	Dorchester	DC025228
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	passenger door wiring cover damaged
02 Windscreen Wipers	Blades Poor
13 Brakes 1	Rear brakes worn
16 Suspension 1	ARB Links worn/slip pads split
17 Tyres	Both front worn
18 Wheels Check Torques	
41 Air Intake	Air Filter Blocked
45 Engine 1	Oil Leak Resinator/boost area
45 Engine Ad Blue	top up
55 Tail Lift	Rails loose,wheel catch siezed solid/Lamp damaged
56 Comms Fitment	Aerial missing
71 Body Exterior 1	Rear flap loose
86 Door Lock	lock set required
86 Doors	magnet bent on slide door, all catch covers damaged
89 Seats	driver seat swab u/s
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service

Vehicle Deep Clean	16/06/2021	08:15	17/06/2021	09:00	318,993	Dorchester	DC025243
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	26/06/2021	08:53	27/06/2021	11:27	320,095	Dorchester	DC025330
Breakdown	sidestep deploys when driving						
Unplanned Repair	14/07/2021	11:24	14/07/2021	11:47	322,231	Dorchester	DC025449
34 Lights Bulb Replacement	Indicator reported inop, check fault. Clean connection						
SAFETY INSPECTION	26/07/2021	11:27	26/07/2021	15:30	324,272	Dorchester	DC025541
02 Cab Ass Fire Extinguisher	out of date and sallon fire ext out of date						Monitoring
16 Suspension 1	slight play in bottom arms						
18 Wheels Check Torques							
34 Lights Bulb Replacement							Lack of Labour
45 Engine 1	Exhasut blow, replace pipe/clamp/gasket..parts ordered						
45 Engine Ad Blue	top up						
56 Comms Equipment	No EPCR on vehicle when in for inspection						
71 Body Exterior 1	tail lift guides loose						
71 Body External Steps	side step sticks has been hit again						
86 Sliding Door	top magnet bent and catch damaged						
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	27/07/2021	11:15	28/07/2021	10:00	324,285	Dorchester	DC025552
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	31/07/2021	11:37	09/08/2021	10:35	324,332	Dorchester	DC025584
41 Turbo	replace turbo						
43 Exhaust System 1	clean DPF						
45 Engine 1	poss injector fault..diagnosed by AA in wincanton replace turbo and egr pipes						

Breakdown 6100 - loss of power

SAFETY INSPECTION **07/09/2021** **10:22** **08/09/2021** **15:04** **328,181** **Dorchester** **DC025853**

02 Mirrors OS mirror frame damaged
02 Windscreen Wipers washers blocked and blades worn
16 Suspension 1 slight play in bottom arms
18 Wheels Check Torques
24 Driveshaft 1 slight lift in front prop centre UJ
34 Emergency Lights OSF blue lt not flashing NO PARTS
44 Add Ad Blue top up
45 Engine 1 EML on, temp sensor and blocked DPF
55 Tail Lift magnet bracket rotted out NO PARTS
Safety Inspection
Engine Change Oil & Filter Changed DC25584, 324332 miles.Turbo replaced
Tail Lift Inspection

Vehicle Deep Clean **08/09/2021** **15:00** **09/09/2021** **13:00** **328,203** **Dorchester** **DC025870**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **16/10/2021** **10:08** **18/10/2021** **14:00** **331,470** **Dorchester** **DC026156**

02 Cab Assembly 1 window switch broken
02 Windscreen Wipers Blade damaged
13 Brake Pads All low
13 Handbrake Adjustment required
17 Tyres All low
18 Wheels Check Torques
34 Emergency Lights O/S/R top blue light damaged
45 Engine Ad Blue top up
52 Electrical Aux CCTV inop
55 Tail Lift Magnet Bracket Rotted.. NO PARTS
71 Body Exterior Acc Repair Other CAMERA DAMAGED IN RTA
86 Sliding Door Top magnet bracket bent
Safety Inspection

Monitoring

Vehicle Deep Clean	18/10/2021	14:30	19/10/2021	12:00	331,475	Dorchester	DC026168
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	18/11/2021	00:23	18/11/2021	08:23	338,000	Dorchester	DC026381
Breakdown	No charhe in batteries.Looked at by VMU East						
Breakdown	19/11/2021	06:22	19/11/2021	07:45	338,100	Dorchester	DC026384
71 Body External Steps Breakdown	Check operation, lub side step and test, ok Side step deploys half way out						
Breakdown	19/11/2021	06:25	19/11/2021	07:45	338,100	Dorchester	DC026385
56 Comms Equipment Breakdown	Re set comms, ok. MDT wont turn on						
Unplanned Repair	22/11/2021	14:20	22/11/2021	14:35	339,688	Dorchester	DC026402
03 Instruments & Sensors 1	Fire suppresion warning reported. Check electrics and pressure.NFF at time						
Unplanned Repair	23/11/2021	10:15	23/11/2021	10:36	340,411	Dorchester	DC026409
03 Instruments & Sensors 1	Fire suppresion warning going off. See notes						
Breakdown	23/11/2021	13:15	23/11/2021	13:45	339,750	Dorchester	DC026415
Breakdown	MDT WON'T TURN ON						
Breakdown	24/11/2021	06:30	24/11/2021	14:32	340,631	Dorchester	DC026421
Breakdown	Rear heater not working						
Vehicle Deep Clean	29/11/2021	11:00	29/11/2021	15:00	341,455	Dorchester	DC026462

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/11/2021	07:45	30/11/2021	14:57	341,463	Dorchester	DC026464
18 Wheels Check Torques							
34 Emergency Lights	n/s/r scene light and o/s grille light inop						
41 Turbo	Boost seals leaking						
44 Add Ad Blue							
45 Engine Oil Top Up							
55 Tail Lift	Magnet Bracket Rotted.. NO PARTS						
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables. PARTS ON BACK ORDER					Awaiting Parts	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service.System failed.Replace						
Unplanned Repair	08/12/2021	11:20	08/12/2021	11:51	342,628	Dorchester	DC026522
02 Mirrors	Replace smashed o/s mirror						
ACCIDENT	08/12/2021	21:59	09/12/2021	10:24	342,628	Dorchester	DC026531
Breakdown	wing mirror smashed						
Unplanned Repair	09/12/2021	10:15	09/12/2021	10:43	342,628	Dorchester	DC026534
01 Heating 1	Saloon heater reported inop.Carry out checks and run up heater.OK						
Unplanned Repair	22/12/2021	09:30	22/12/2021	10:45	345,207	Dorchester	DC026664
02 Mirrors	n/s mirror smashed						
BREAKDOWN	25/12/2021	10:00	25/12/2021	12:11	345,868	Dorchester	DC026704
17 Tyres Replace	Puncture n/s/r.ATS sorted						
Breakdown	05/01/2022	05:08	05/01/2022	08:08	345,900	Dorchester	DC026763
Breakdown	inner rear tyre puncture flat						

SAFETY INSPECTION	11/01/2022	10:46	14/01/2022	10:30	346,000	Dorchester	DC026807
02 Cab Ass Fire Extinguisher	saloon fire ext o.o.d						
02 Cab Assembly 1	torch inop						
02 Windscreen	chipped, new to be fitted 13.01.2021						
03 Instruments & Sensors 1	Service light on						
13 Handbrake	adjust						
16 Suspension 1	rear shocks u/s.						
16 Suspension 2	Struts and arms u/s						
17 Tyres	o/s/f tyre low						
18 Wheels Check Torques							
34 Emergency Lights	Lighting System O/S grill blue U/S						
34 Lights	n/s side light out						
52 Electrical Aux	CCTV inop						
55 Tail Lift	tank starting to rott						Monitoring
71 Body Exterior 2	Rear flap damaged...requires frame						Monitoring
71 Body External Steps	step has been hit again						
85 Body Interior 1	drug cupboard damaged						
86 Sliding Door	magnet bent again						
89 Seats	attendant seat lach loose						
Replace Handbrake Cables	Replace Handbrake Cables. PARTS ON BACK ORDER						Monitoring
Safety Inspection							
Travel Time							
Tail Lift Inspection							
Brake Fluid Change	Brake Fluid Change						
Pollen Filter Change	Pollen Filter Change						
MOT							
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Vehicle Deep Clean	14/01/2022	11:30	14/01/2022	15:54	349,030	Dorchester	DC026834
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	16/01/2022	23:43	17/01/2022	13:30	349,329	Dorchester	DC026842
55 Tail Lift	Carry out checks.Isolator on.Check operation of lift.All ok						
Breakdown	Ramp has no power to lift						

Travel Time

Breakdown	20/01/2022	16:33	21/01/2022	07:35	349,764	Dorchester	DC026892
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Side step stuck in but alarms open constantly
Travel Time	

Unplanned Repair	26/01/2022	08:10	26/01/2022	09:40	350,522	Dorchester	DC026941
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights	o/s brake light reported inop.Repair rotted loom and replace lights as req
86 Door Lock	Central locking reported inop on rear door,free off linkage

Unplanned Repair	01/02/2022	09:10	01/02/2022	10:15	351,335	Dorchester	DC026991
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	Side step deployed warning going off.Trace to damaged wire
89 Seats	Body Interior rear saloon seat not locking in place

Unplanned Repair	03/02/2022	09:00	03/02/2022	11:04	351,831	Dorchester	DC027013
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

03 Instruments & Sensors 1	Doors side step alarm still going off intermittently
71 Body External Steps	side step warning constant

Tail Lift 12M Service & Weight	07/02/2022	11:31	09/02/2022	11:49	351,846	Dorchester	DC027027
---	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights	Various light faults on rear of vehicle.Trace to faulty wiring
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Travel Time	

Unplanned Repair	16/02/2022	07:00	16/02/2022	08:18	353,118	Dorchester	DC027083
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

55 Tail Lift	Tail lift reported not working
--------------	--------------------------------

SAFETY INSPECTION	24/02/2022	07:30	24/02/2022	14:11	354,434	Dorchester	DC027125
13 Brake Pads							
15 Steering 1							
18 Wheels Check Torques							
41 Turbo							
45 Engine 1							
55 Tail Lift							
71 Body Exterior 2							
71 Body External Steps							
86 Door Lock							
86 Doors Rear							
Replace Handbrake Cables							
Safety Inspection							
Engine Change Oil & Filter							
Tail Lift Inspection							
Vehicle Deep Clean	24/02/2022	15:15	25/02/2022	14:00	354,446	Dorchester	DC027135
Vehicle Deep Clean							
02 Pipeline Annual Inspection	25/02/2022	11:00	25/02/2022	12:00	354,446	MDT Weymouth	DW000807
02 Pipeline Annual Inspection							
Breakdown	05/03/2022	00:27	05/03/2022	10:05	355,124	Dorchester	DC027184
Breakdown							
ACCIDENT	28/03/2022	18:51	30/03/2022	10:57	358,688	Dorchester	DC027357
Breakdown							
34 Emergency Lights							
34 Lighting System							
71 Body External Steps							
55 Tail Lift							

SAFETY INSPECTION	04/04/2022	07:47	06/04/2022	15:00	359,009	Dorchester	DC027389
18 Wheels Check Torques							
Safety Inspection							
Auto G/box Oil & Filter Change							
Wheel Hub Flanges Replaceme						Awaiting Parts	
44 Add Ad Blue		top up					
45 Engine Oil Top Up		top up					
86 Door Lock		rear door barrel seized					
86 Sliding Door		top magnet bracket bent					
89 Seatbelts		attendant seatbelt twisted					
55 Tail Lift		guide rails and wheel lock sticking					
86 Doors Rear		small rear door stay bent					
71 Body Exterior 1		damage to OSR corner					
15 Steering 1		power steering pump weeping oil, parts on back order					
41 Turbo		boost seals leaking					
17 Tyres		NSR inner pressure low					
Vehicle Deep Clean	05/04/2022	10:00	05/04/2022	14:30	359,009	Dorchester	DC027405
Vehicle Deep Clean		Vehicle Deep Clean					
Breakdown	12/04/2022	11:35	13/04/2022	09:42	359,479	Dorchester	DC027447
Breakdown		loud noise/belts hanging down.Replace drive belt					
52 Electrical Aux		Remove CCTV hard drive as required					
Breakdown	14/04/2022	07:26	14/04/2022	11:17	359,701	Dorchester	DC027471
Breakdown		Charge port pin bent					
Breakdown	21/04/2022	18:45	22/04/2022	13:02	359,726	Dorchester	DC027540
Breakdown		sliding side door passenger side not working					
Breakdown	10/05/2022	11:00	11/05/2022	08:56	364,347	Dorchester	DC027637

Breakdown	loss of power
41 Turbo	boost seal split

SAFETY INSPECTION	16/05/2022	10:46	18/05/2022	11:55	364,902	Dorchester	DC027668
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 12mts Service	Service of fire supression system
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
34 Lights	NSR yellow marker not working
44 Add Ad Blue	top up
45 Engine Oil Top Up	top up
02 Cab Ass Fire Extinguisher	OOD
02 Glass / Windows	passenger door window swith broken
86 Sliding Door	top magnet bracket bent
55 Tail Lift	guide rails seized and hyd tank rusted
71 Body External Steps	side step not fully deploying
16 Suspension 1	Rear ARB lower link bushes worn
17 Tyres Replace	both front
71 Body Exterior 2	rear mudflap split, replace

Vehicle Deep Clean	19/05/2022	08:30	19/05/2022	12:34	364,916	Dorchester	DC027695
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	20/05/2022	08:23	20/05/2022	13:15	365,094	Dorchester	DC027713
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	SHORELINE CONNECTION PIN BENT
-----------	-------------------------------

Breakdown	21/05/2022	21:52	23/05/2022	13:30	365,428	Dorchester	DC027717
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	intermittently loosing power, no eml. See notes
Road Test	

Breakdown	27/05/2022	13:23	28/05/2022	10:30	365,860	Dorchester	DC027757
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	NON START - just clicking...See notes
31 Battery Comms	Battery U/S

Breakdown	04/06/2022	22:14	06/06/2022	08:28	367,225	Dorchester	DC027807
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	N/S Mirror fallen out						
-----------	-----------------------	--	--	--	--	--	--

Breakdown	05/06/2022	10:36	06/06/2022	08:30	367,225	Dorchester	DC027808
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	N/S mirror smashed						
02 Mirrors	n/s mirror smashed						
44 Add Ad Blue							

SAFETY INSPECTION	29/06/2022	08:00	30/06/2022	13:32	371,130	Dorchester	DC027990
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Wheel Hub Flanges Replaceme	
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Tail Lift Inspection	
02 Windscreen Wipers	worn
02 Windscreen	15mm chip in centre of screen
86 Doors Rear	barrel seized
86 Door Lock	locker door barrel seized
71 Body External Steps	side step not fully deploying
44 Add Ad Blue	top up
45 Engine Oil Top Up	top up
86 Sliding Door	top magnet bracket bent
55 Tail Lift	handrails stiff
13 Brake Pads	all pads low
41 Turbo	boost seals leaking and boost tube damaged
17 Tyres Replace	OSRO tread low
43 Exhaust System 1	tailpipe rotting

Vehicle Deep Clean	01/07/2022	08:00	01/07/2022	14:47	371,144	Dorchester	DC028011
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	25/07/2022	14:20	25/07/2022	15:15	375,342	Dorchester	DC028163
34 Lights 02 Windscreen 86 Sliding Door	Lighting System O/S fog light broken Windscreen 4MM chip in A zone Handle stuck						
Breakdown	26/07/2022	19:25	27/07/2022	07:27	375,857	Dorchester	DC028169
Breakdown	O/S Indicator Not Working						
Breakdown	26/07/2022	19:26	27/07/2022	07:26	375,857	Dorchester	DC028170
Breakdown	Chip to W/Screen						
BREAKDOWN	28/07/2022	11:00	28/07/2022	11:30	376,158	St Leonards	SL037210
Breakdown	indicator bulb not working O/S/F Side Repeater						
Breakdown	02/08/2022	16:52	04/08/2022	07:42	377,276	Dorchester	DC028203
Breakdown	pulling left						
Breakdown	11/08/2022	06:52	15/08/2022	06:52	378,796	Dorchester	DC028258
Breakdown 52 Electrical Aux	No Power To MDT/Battery Check no power to MDT head, contractor required						
SAFETY INSPECTION	15/08/2022	06:52	16/08/2022	07:47	378,976	Dorchester	DC028281
18 Wheels Check Torques Safety Inspection 34 Lights 02 Windscreen Wipers 34 Emergency Lights 52 Electrical Aux 44 Add Ad Blue	NSR and OSF fog lights damaged worn NSR upper lens and LED missing MDT not working, awaiting contractor top up						

45 Engine Oil Top Up 71 Body External Steps 86 Door Lock	top up side step not fully deploying rear barrel seized						
Vehicle Deep Clean	16/08/2022	09:00	17/08/2022	11:53	378,988	Dorchester	DC028294
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	22/08/2022	14:45	22/08/2022	15:18	379,581	Dorchester	DC028313
02 Mirrors	NS missing						
Breakdown	06/09/2022	14:56	07/09/2022	05:54	382,468	Dorchester	DC028377
Breakdown	flat tyre rear offside outer						
Breakdown	06/09/2022	17:04	07/09/2022	05:54	382,468	Dorchester	DC028378
Breakdown	bold front offside tyre						
Unplanned Repair	11/09/2022	06:36	11/09/2022	06:40	382,800	Dorchester	DC028383
02 Mirrors 71 Body Exterior 1 71 Body Exterior 2	Body Exterior wing mirror damage Doors Side door magnet not holding Mirrors N/S mirror Broken						
Breakdown	02/11/2022	02:50	02/11/2022	10:37	392,886	Dorchester	DC028453
Breakdown	Non Starter						
Unplanned Repair	01/11/2022	10:00	01/11/2022	14:00	392,725	St Leonards	SL037995
02 Mirrors Travel Time	Mirrors wing mirrors both broken						

Vehicle Deep Clean	02/11/2022	11:05	02/11/2022	11:08	392,896	St Leonards	SL038018
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	02/11/2022	11:08	03/11/2022	08:30	392,896	St Leonards	SL038019
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	03/11/2022	08:30	03/11/2022	08:30	392,896	St Leonards	SL038020
18 Wheels Check Torques Safety Inspection							
SAFETY INSPECTION	03/11/2022	08:30	10/11/2022	12:08	392,896	St Leonards	SL038021
18 Wheels Check Torques Safety Inspection 34 Lights 55 Tail Lift Engine Change Oil & Filter Tail Lift Inspection 85 Body Interior 1 13 Brakes 1 15 Steering 1 17 Tyres Replace 41 Turbo 41 Air Intake	Lighting System CHANGED BULB STILL NOT WORKING NFF Doors ramp bars bent causing damage to back door Carry out tail lift inspection Carry out repairs in saloon Replace front brake pads and discs Replace inner tie rod and track rod end replace 2 rear tyres Turbo U/S fit new noise damper						
Unplanned Repair	17/11/2022	08:00	17/11/2022	09:00	394,210	St Leonards	SL038125
55 Tail Lift	Tail lift deployed audio warninvg sounding						
Breakdown	21/11/2022	11:29	21/11/2022	13:00	394,400	St Leonards	SL038180
Breakdown 45 Engine 1	EML limp Eml light on, Limp mode and hissing noise						
Unplanned Repair	22/11/2022	15:35	22/11/2022	16:16	395,400	St Leonards	SL038199

02 Mirrors N/S wing mirror damaged cover and glass

Breakdown **28/11/2022** **12:08** **29/11/2022** **16:00** **395,410** **St Leonards** **SL038250**

Breakdown
45 Engine 1 ENG MAN AMBER LIMP MODE
001 Recover Vehicle EML/LOP See notes.
Vehicle Recovery

BREAKDOWN **17/12/2022** **10:00** **22/12/2022** **12:13** **399,833** **St Leonards** **SL038523**

02 Mirrors Body Exterior N/S wing mirror
55 Tail Lift Ramp/Lift/Tail Hoist side step alarm fault
71 Body Exterior 1 Body Exterior audio message in error sidestep deployed
71 Body Exterior 2 Body Exterior audio message in error sidestep deployed
71 Body External Steps Side step U/S. step replaced and wired in.
15 Steering 1 O/S tyre worn on edge
45 Engine 1 Oil leak
86 Sliding Door sliding door runner hinge u/s.

Breakdown **22/12/2022** **20:31** **23/12/2022** **05:37** **399,945** **St Leonards** **SL038571**

Breakdown Rear lights flickering

Unplanned Repair **27/12/2022** **07:30** **27/12/2022** **11:30** **400,412** **St Leonards** **SL038604**

34 Lighting System N/S/R Top and bottom side light not working- Rewired

Breakdown **30/12/2022** **01:12** **30/12/2022** **09:00** **400,783** **St Leonards** **SL038642**

Breakdown spongy
01 Heating 1 Saloon heater inop. NFF

Breakdown	01/01/2023	10:15	01/01/2023	12:20	401,294	St Leonards	SL038662
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	N/S main Beam Blown
-----------	---------------------

Vehicle Deep Clean	09/01/2023	13:30	11/01/2023	08:15	402,445	St Leonards	SL038756
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	11/01/2023	08:00	16/01/2023	18:51	402,445	St Leonards	SL038768
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	
Pollen Filter Change	Pollen Filter Change
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
Replace Handbrake Cables	Replace Handbrake Cables
MOT	
34 Emergency Lights	O/S Wing blue light not working
71 Body Exterior 1	Corner reflector trim broken N/S/R
34 Lights Bulb Replacement	N/S/F main beam not working
02 Cab Ass Fire Extinguisher	Cab extinguisher expired
85 Body Interior 1	Saloon mic insecure. Retaining trim broken
52 Electrical Aux	CCTV hard drive fault. 99% full. Formatted
86 Door Seals	Drivers door seal torn
34 Lights	O/S/R light pod damaged
13 Brakes 1	Rear brake pads worn low discs also worn
31 Charging System	Aux belt deteriorated Tensioner u/s
15 Steering 1	Pas steering pump damaged, belt worn due to damage to pulley
17 Tyres	Both O/S/R tyres worn

BREAKDOWN	17/01/2023	07:12	17/01/2023	14:21	402,465	St Leonards	SL038813
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Chassis	Fit new chassis battery
Travel Time	ferndown - wimbourne

Breakdown	31/01/2023	17:03	01/02/2023	06:00	402,855	St Leonards	SL038960
Breakdown	defective/damaged radio antenna						
Unplanned Repair	07/02/2023	07:00	07/02/2023	07:25	405,485	St Leonards	SL039019
01 Heating 1	A/C System Saloon no heating						
Breakdown	07/02/2023	21:10	08/02/2023	05:55	405,633	St Leonards	SL039030
Breakdown	MDT blank screen						Monitoring
Unplanned Repair	18/02/2023	13:30	18/02/2023	13:43	407,575	St Leonards	SL039154
34 Lights	Replace osf headlight bulb						
Breakdown	21/02/2023	12:20	24/02/2023	14:30	408,073	St Leonards	SL039177
Breakdown	Spongey						
13 Brakes 1	Brake fault/Spongy brakes. See notes.						
Wheel Hub Flanges Replaceme	Poor condition. Replaced fronts.						
Unplanned Repair	05/03/2023	11:00	13/03/2023	13:00	408,738	St Leonards	SL039286
31 Charging System	Charging fault. Tail lift batt not charging with engine running - Jon Coles						
Vehicle Deep Clean	09/03/2023	16:00	12/03/2023	10:30	408,738	St Leonards	SL039320
Vehicle Deep Clean	Vehicle Deep Clean						
02 Pipeline Annual Inspection	07/03/2023	13:09	07/03/2023	13:10	408,738	MDT Ferndown	TF002546
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						

SAFETY INSPECTION	13/03/2023	07:29	14/03/2023	06:47	408,738	St Leonards	SL039356
18 Wheels Check Torques	Checked.						
Safety Inspection	Inspected.						
Breakdown	MDT blank screen						
52 Electrical Aux	Tail lift Batt not charging. John coles to repair						
02 Cab Assembly 1	Interior light n/w. Replaced bulb.						
02 Cab Assembly 2	Passenger window switch broken. Replaced.						
86 Door Lock	Rear door & scoop door locks n/w. Repaired.						
85 Body Interior 1	230v w/lights broken.Replaced x1 No parts.						
44 Fuel System 1	Fuel angel leaking. Replaced.						
13 Handbrake	low effort N/S/R.Cleaned h/brake shoes & Drum, cleaned disc & pads.						
13 Brakes 2	Telma n/w.Cleaned contacts on relays & road test.						
85 Body Interior 2	kick plate bent on rear cupboard. Straightened and secured.						
Unplanned Repair	17/03/2023	07:36	17/03/2023	10:45	408,738	St Leonards	SL039402
34 Lights	rear lights inop. Repaired broken wires .						
Unplanned Repair	01/04/2023	07:00	04/04/2023	12:13	412,258	St Leonards	SL039564
13 Brakes 1	Brakes spongy - Telma control box to replace. Replaced						
Unplanned Repair	16/04/2023	06:15	16/04/2023	06:52	413,641	St Leonards	SL039742
45 Engine Oil Top Up	1L oil topped up.						
Unplanned Repair	21/04/2023	10:00	21/04/2023	10:30	414,510	St Leonards	SL039827
55 Tail Lift	Lift not deploying. greased lift pins and adjusted tilt ram. tested all ok.						
Breakdown	29/04/2023	10:39	29/04/2023	14:00	415,736	St Leonards	SL039939
Breakdown	spongy brakes					Monitoring	

SAFETY INSPECTION	04/05/2023	06:00	05/05/2023	11:00	415,764	St Leonards	SL040003
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

Breakdown spongy brakes. NFF Telma control box fitted recently.

55 Tail Lift Ramp/Lift/Tail Hoist Have to use Manuel over ride for the tail lift. NFF

Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Tail Lift Inspection

85 Body Interior 1 Fit P clips for AVP

17 Tyres Replace Both front tyres. Nsf worn low, osf punctured.

13 Brake Pads Front brake pads worn below 50%

27 Transmission Automatic Rear gearbox mount worn. Replaced

15 Steering 1 Steering wheel worn excessively smooth

89 Seats Passenger seat base torn

24 Driveshaft 1 Slight cracking to propshaft donut

45 Engine 1 Engine oil leak around copmpressor at sump join. Washed of to monitor

85 Body Interior 2 230v Leds broken. No stock

34 Emergency Lights NSR Lens damaged and incorrect light fitted. Damage to fibreglass

Monitoring

Monitoring

Monitoring

Breakdown	29/05/2023	20:06	30/05/2023	09:25	420,395	St Leonards	SL040331
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown Limp mode

45 Engine 1 EML on. (see notes)

Breakdown	10/06/2023	15:09	13/06/2023	06:00	421,000	St Leonards	SL040500
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown SatNav & radio unavailable; vehicle battery

Vehicle Deep Clean	16/06/2023	09:34	16/06/2023	16:30	421,209	St Leonards	SL040590
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean	19/06/2023	15:00	19/06/2023	15:01	421,409	St Leonards	SL040646
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/06/2023	15:03	20/06/2023	19:38	421,409	St Leonards	SL040647
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
Tail Lift Inspection	Done.						
Engine Change Oil & Filter	Done.						
02 Cab Ass Fire Extinguisher	Out of date. Replaced.						
55 Tail Lift	Trolley stop plate seized, LED n/w.N/S Gate seized. Repaired.						
13 Handbrake	Cable adjuster seized. Replaced.						
Replace Vehicle Fuel Card	07/07/2023	18:00	07/07/2023	21:45	422,800	St Leonards	SL040925
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
ACCIDENT	16/07/2023	14:55	17/07/2023	04:51	425,377	St Leonards	SL041080
Breakdown	drivers wing mirror damaged after accident						
Vehicle Deep Clean	26/07/2023	06:00	26/07/2023	11:00	426,859	St Leonards	SL041265
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/07/2023	11:30	01/08/2023	20:05	426,859	St Leonards	SL041297
18 Wheels Check Torques							
Safety Inspection							
24 Driveshaft 1	Cracking to propshaft donut and centre bearing mount. Monitor					Monitoring	
45 Engine 1	Engine oil leak around compressor at sump join. Washed off to monitor					Monitoring	
85 Body Interior 2	230v Leds broken. Replaced x1.						
Tail Lift Inspection	NS Hose perished. replaced hose.						
UB Fire Supp 12mts Service	Service of fire suppression system						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
34 Lights	o/s wing indicator bulb blown. replace						
71 Body Exterior 1	osf mirror damaged. replaced shell and frame.						
13 Handbrake	Adjusted shoes and cables.						

86 Sliding Door	sliding door magnet torn. replaced. - upper latch loose. ressecured.	
89 Seats	Front swivel seat bearings worn. replaced bearings.	
16 Suspension 1	Rear spring buffers split and drop link bushes worn. replaced x4 each.	
19 Chassis 1	Mudflap loose. ressecured.	
15 Steering 1	osf inner tie rod excessive play. replaced inner joint and end.	
13 Brakes 1	nsr caliper slider seized. replace slider kit.	
55 Tail Lift	Corrosion on tail lift. - Monitor.	Monitoring
01 Air Conditioning 1	Rear condensor corroded and fan seized. replaced whole unit.	
15 Steering 2	NSF Wheel bearing noise when on road test. replaced whole hub assembly.	

Breakdown	14/08/2023	05:52	14/08/2023	13:27	428,670	St Leonards	SL041511
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	having to press the red button to start
-----------	---

Unplanned Repair	27/08/2023	05:54	27/08/2023	13:40	430,016	St Leonards	SL041698
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior 1	Body Exterior o/s windscreen wiper defected
02 Windscreen Wipers	Wiper Motor u/s...,Replaced

Breakdown	29/08/2023	14:06	30/08/2023	14:12	430,016	St Leonards	SL041734
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	NON STARTER
32 Starting System 1	Non start. Battery low not holding voltaGE. REPLACED BATTERY
001 Recover Vehicle	Vehicle Recovery

Vehicle Deep Clean	06/09/2023	11:00	06/09/2023	16:30	430,089	St Leonards	SL041845
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/09/2023	07:00	07/09/2023	16:00	430,089	St Leonards	SL041853
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.	
Safety Inspection	Carried out inspection.	
24 Driveshaft 1	Cracking to propshaft donut and centre bearing mount. Monitor	Monitoring
45 Engine 1	Engine oil leak around copmpressor at sump join. Washed of to monitor	
55 Tail Lift	Corrosion on tail lift. - Monitor.	Monitoring
86 Door Lock	Electrical Auxs Key fob wont lock the vehicle	

34 Lights	Lighting System OFFSIDE INDICATOR LIGHT ABOVE WHEEL ARCH
Annual Air Con Service	Annual Air Condition Service
Recall Notification	Mercedes airbag recall
02 Cab Assembly 1	Radio surround broken . Replaced.

Unplanned Repair	07/09/2023	16:00	20/09/2023	12:00	430,089	St Leonards	SL041862
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	Engine oil leak - Rygor Westbury to repair
-------------	--

Unplanned Repair	26/09/2023	07:15	26/09/2023	07:45	431,077	St Leonards	SL042095
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Emergency Light System	Electrical Auxs Genysis panel wont allow blue lights to activate , renew panel
---------------------------	--

Vehicle Deep Clean	19/10/2023	07:18	19/10/2023	13:01	434,144	St Leonards	SL042423
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	20/10/2023	07:00	21/10/2023	14:00	434,144	St Leonards	SL042444
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
24 Driveshaft 1	Cracking to propshaft donut and centre bearing mount. Monitor
55 Tail Lift	Corrosion on tail lift. - Monitor.
Annual Heater Service	Annual Heater Service
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
Tail Lift Inspection	
87 - Stretchers/Chairs/Boards	Stretcher belts wrongly fitted jamming leg tilt mechanisms.
85 Body Interior 1	Saloon cupboard drawer 'BH8' runners broken.
86 Doors	O/S/R Door stay bracket broken.
86 Doors Rear	N/S/R Door stay bar bent.
86 Sliding Door	N/S Sliding door roller bearings seizing upon opening & closing.
Tail Lift Annual Service	Tail lift O/S hose excessively leaking & low oil level.
71 Body Exterior 1	Front cab call sign stickers missing.
45 Engine 1	Front crank seal oil leak.
Tail Lift 6 Monthly Inspection	Tail lift side rails loose.
45 Engine 2	E.G.R. Top bracket bolt missing.
34 Lights	N/S/F Fog light surround insecure.
34 Lights Bulb Replacement	N/S/F Day time running bulb not working.
13 Brakes 1	Front brake pads thicknesses low & front brake discs excessively lipped.

13 Brakes 2	Cab handbrake travel becomming excessive.
Pollen Filter Change	Pollen Filter Change
71 Body External Steps	N/S Sise step seizing upon opening & closing.
13 Brake Test	Carry out brake tests.
86 Door Hinges	O/S Cab drivers door check strap loose & insecure.
34 Emergency Lights	Carry out headlight aim.

Vehicle Deep Clean	29/11/2023	13:01	30/11/2023	08:00	439,103	St Leonards	SL042972
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	01/12/2023	06:00	01/12/2023	16:00	439,103	St Leonards	SL042994
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
34 Lights	Lighting System RIGHT INDICATOR NOT WORKING
02 Cab Assembly 1	Interior light n/w. Replaced bulb.
01 Heating 1	Saloon heater exhaust split. Replaced.
02 Cab Assembly 2	Torch missing. Replaced.
02 Cab Ass Fire Extinguisher	Out of date. Replaced.
55 Tail Lift	Pipe leaking.
02 Windscreen Wipers	Washer jets blocked. Replaced x2.
17 Tyres Replace	O/S/R /I &O low tread. Cleaned rims & flanges.Replaced.
13 Brakes 1	Rear pads low. Replaced.

Unplanned Repair	07/12/2023	05:40	07/12/2023	07:12	439,205	St Leonards	SL043088
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	N/S Mirror damage
------------	-------------------

ACCIDENT	10/12/2023	10:00	10/12/2023	10:30	440,240	St Leonards	SL043129
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights	OSR Fog light damaged. replaced fog lamp.
-----------	---

Vehicle Deep Clean	09/01/2024	06:52	09/01/2024	11:30	444,644	St Leonards	SL043523
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/01/2024	13:30	11/01/2024	14:00	444,644	St Leonards	SL043544
18 Wheels Check Torques							
Safety Inspection							
34 Lights	Lighting System R side indicator temperamental						
34 Lighting System	Lighting System Rear brake light lens smashed-accident ref 260841						
Pollen Filter Change	Pollen Filter Change						
MOT							
86 Door Seals	N/S door seal split away						
86 Doors Rear	N/S/r door stay bent						
34 Lights Bulb Replacement	NSF DRL not working, replaced						
85 Body Interior 1	brake pedal rubber worn smooth						
16 Suspension 1	Slight play in lower arms					Monitoring	

Vehicle Deep Clean	26/02/2024	14:42	27/02/2024	09:58	448,253	St Leonards	SL044160
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	29/02/2024	06:48	01/03/2024	14:06	448,253	St Leonards	SL044198
18 Wheels Check Torques							
Safety Inspection							
Brake Fluid Change	Brake Fluid Change						
Replace Handbrake Cables	Replace Handbrake Cables						
Engine Change Oil & Filter							
Tail Lift Annual Service	Statutory Inspection and Weight Test						
86 Doors Rear	O/S/R Door stay bracket broken						
87 - Stretchers/Chairs/Boards	Carry chair frame bolts missing						
55 Tail Lift	Tail lift side rails loose						
87 Stretcher	Stretcher head rest tilt mechanism jammed						
45 Engine 1	Oil leak around sump bolts						
43 Exhaust System 1	Exhaust tail pipe mount broken						
43 Exhaust System 2	D.P.F. Top upper bolt missing						
13 Brakes 1	Telma rear prop flange nuts loose						
42 Coolant System	O/S Bottom hose jubilee clips leaking						
Air Filter Change	Air Filter Change						
Pollen Filter Change	Pollen Filter Change						
85 Body Interior 1	Saloon genisys panel broken						

02 Pipeline Annual Inspection	01/03/2024	11:29	01/03/2024	11:30	448,494	MDT Ferndown	TF003286
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection Annual Inspection and Pressure Test

Breakdown	09/03/2024	16:16	11/03/2024	11:03	449,306	St Leonards	SL044334
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	strong smell of diesel in the cab, seatbelt sensor					
89 Seatbelts	Air bag code for seat belt buckle. Replaced					
45 Engine 1	Cylinder 2 injector blowing by. Strong smell of fumes. Replaced seal					

Vehicle Deep Clean	05/04/2024	15:10	07/04/2024	04:41	450,994	St Leonards	SL044779
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	08/04/2024	12:35	10/04/2024	15:00	450,994	St Leonards	SL044805
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques						
Safety Inspection						
16 Suspension 1	Slight play in lower arms Replace shocks and arms					
Tail Lift Inspection	SWL to inspect					
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service					
Engine Change Oil & Filter						
11 Axle Rear	Replace corroded diff pan and seal					
24 Driveshaft 1	Prop shaft donut torn. Replaced					
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight					
17 Tyres Replace	Replace all four rear tyres					

Unplanned Repair	22/04/2024	15:30	22/04/2024	15:45	452,717	St Leonards	SL045005
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors Both NS mirror glass lens's missing. replaced both.

Unplanned Repair	03/05/2024	13:30	04/05/2024	08:40	453,669	St Leonards	SL045163
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights	Brake lights inop						
Vehicle Deep Clean	17/05/2024	15:18	19/05/2024	08:29	455,464	St Leonards	SL045371
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/05/2024	13:21	23/05/2024	17:41	455,654	St Leonards	SL045408
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
45 Engine 1	Oil leak from sump. Remove and reseal						
Engine Change Oil & Filter	Replaced						
Install Saloon CCTV Camera	CCTv camera Sliding door smashed off. Format harddrive						
Unplanned Repair	28/05/2024	08:00	28/05/2024	09:00	456,359	St Leonards	SL045514
85 Body Interior 1	sat nav mounting broken, swopped from WU63UEV, replace harness and mattress						
87 Stretcher							
Vehicle Deep Clean	02/07/2024	09:29	03/07/2024	09:31	463,996	St Leonards	SL046090
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/07/2024	16:00	10/07/2024	15:20	463,996	St Leonards	SL046204
18 Wheels Check Torques							
Safety Inspection							
Axle Oil Change	Axle Oil Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Tail Lift Inspection							
Engine Oil & Filter Change	Engine Oil & Filter Change						

Pollen Filter Change	Pollen Filter Change
45 Engine 1	Engine earth strap loose
87 Stretcher Harness Replaced	Stretcher belts wrongly fitted
45 Engine 2	Engine oil leak from front primary sump bolts
85 Body Interior 1	Saloon N/S/R seat base swivel pin loose
71 Body Exterior 1	N/S/F Wheel arch liner insecure
71 Body Exterior 2	O/S/F Wheel arch liner insecure
17 Tyres	N/S/F Tyre tread excessively worn down to wear markers
17 Tyres Replace	O/S/F Tyre tread excessively worn down to wear markers
13 Handbrake	Cab handbrake travel becoming excessive
56 Comms Fitment	Cab MDVS monitor screen insecure & rattling against cab radio buttons
55 Tail Lift	Tail lift side rails fixings insecure
Tail Lift Annual Service	Tail lift tilt ram out of adjustments & deployed alarm sounding whilst driving
71 Body External Steps	N/S Side step not deploying due to bent brackets
13 Brake Test	
02 Cab Assembly 1	Cab drivers seat belt slightly frayed
02 Windscreen Wipers	Cab windscreen washer jets not working
87 Stretcher	Stretcher side rail flap smashed. (Requires replacing with 2nd hand stretcher.).
85 Body Interior 2	Cab drivers auto-gearstick over-ride cover cap missing
03 Instruments & Sensors 1	E.M.L. Illuminated on dash due to service light programme fault

Breakdown	14/07/2024	18:37	15/07/2024	06:58	464,332	St Leonards	SL046317
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Battery faulty
-----------	----------------

Unplanned Repair	18/07/2024	16:30	19/07/2024	18:00	464,332	St Leonards	SL046402
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Chassis	Battery u/s
--------------------	-------------

BREAKDOWN	26/07/2024	15:14	26/07/2024	15:18	465,338	St Leonards	SL046566
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Camera Installation	N/S Camera smashed off
34 Lights Bulb Replacement	N/S DRL bulb not working

SAFETY INSPECTION	12/08/2024	09:04	26/08/2024	16:00	466,170	St Leonards	SL046764
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection 34 Lighting System Check and Fit P-Clips 34 Lights 85 Body Interior 1 13 Brakes 1 45 Engine 1	Lighting System Plastic cover for NS indicator and light is broke. Fixed Check for the presence of P-Clips and fit if not present All NSR lamps smashed. All Replaced Large cupboard wont latch. Resecured trim Front brake pads worn low. Replaced Engine oil leak from upper sump area.							Monitoring
Vehicle Deep Clean	23/08/2024	06:22	23/08/2024	10:40	466,170	St Leonards	SL046932	
Vehicle Deep Clean	Vehicle Deep Clean							
Unplanned Repair	30/08/2024	12:44	30/08/2024	15:50	466,563	St Leonards	SL047098	
86 Sliding Door 71 Body External Steps	Sliding door stiff. Replaced bearings Step not deploying. sorted							
Breakdown	10/09/2024	03:45	11/09/2024	05:20	468,097	St Leonards	SL047227	
Breakdown	Fumes in cab & smoke underneath the vehicle							
Unplanned Repair	11/09/2024	12:19	11/09/2024	12:23	468,183	St Leonards	SL047260	
45 Engine 1	Fumes. Found no3 injector leaking. cleaned carbon, replaced seal and bolt.							
Unplanned Repair	12/09/2024	10:30	12/09/2024	11:30	468,205	St Leonards	SL047283	
13 Brakes 1 43 Exhaust System 1	-ABS light on. -Replaced osr abs sensor. cleared codes and road tested. DPF starting to block, replace next time, parts in stores							Monitoring
SAFETY INSPECTION	22/09/2024	15:07	27/09/2024	09:20	468,851	St Leonards	SL047424	
18 Wheels Check Torques Safety Inspection 43 Exhaust System 1	-DPF internal damage., replaced. -Manifolds replace - tailpipe replace.							

Tail Lift Inspection							
UB Fire Supp 12mts Service	Service of fire suppression system						
42 Coolant System	Radiator leaking. -Replaced.						
45 Engine 1	Turbo impellor damaged. -Replaced.						
Engine Oil & Filter Change	Engine Oil & Filter Change						
34 Lights	-NSF Fog lamp water ingress, replaced - Cab interior bulb blown, replaced.						
86 Door Lock	Side locker lock barrel housing broken. replaced barrel housing.						
86 Sliding Door	-Replaced lower latch - Resecured upper latch mount -Replaced lower stay magnet						
85 Body Interior 1	Sunblind broken. replaced -underseat locker door repaired.						
16 Suspension 1	Rear roll bar drop link bushes worn. replaced x4 bushes.						
13 Brakes 1	Rear brake discs and pads worn low. replaced brake kit.						
55 Tail Lift	-Adjusted lift ram. -Replaced power pack plastic cover -guides ressecured to body						
34 Lighting System	- Rear no plate light broken. replaced.						
24 Driveshaft 1	-Propshaft centre bearing split and uj worn. replaced propshaft.						
Vehicle Deep Clean	25/09/2024	17:25	27/09/2024	10:44	468,855	St Leonards	SL047475
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	29/09/2024	01:36	29/09/2024	11:00	468,999	St Leonards	SL047515
Breakdown	CLUTCH BURNING SMELL						
Breakdown	06/10/2024	08:18	06/10/2024	11:57	469,960	St Leonards	SL047605
Breakdown	amber oil levels warning						
Breakdown	12/10/2024	22:40	13/10/2024	12:19	470,400	St Leonards	SL047716
Breakdown	side door handle issue and feels not on runner. Door handle stuck out. Repaired						
SAFETY INSPECTION	31/10/2024	11:00	02/11/2024	07:29	471,655	St Leonards	SL048039
18 Wheels Check Torques							
Safety Inspection							
71 Body Exterior 1	Body Exterior os break light, indicator plastic cover broken.						
Annual Air Con Service	Annual Air Condition Service						

Tail Lift Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
87 - Stretchers/Chairs/Boards	Stretcher belts wrongly fitted
87 Stretcher	Stretcher locking mechanism jammed with syringe tips
31 Charging System	Side charger not working
02 Windscreen	Cab windscreen buffer strips insecure & whistling
27 Transmission Automatic	Gear box oil leaking from torque converter
27 Transmission Manual	Rear axle bolts loose / leaking oil
13 Brake Test	
45 Engine Oil Top Up	Engine oil over filled requires draining

Vehicle Deep Clean	04/11/2024	09:00	05/11/2024	07:35	471,690	St Leonards	SL048088
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	21/11/2024	13:38	23/11/2024	06:00	471,699	St Leonards	SL048334
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	o/s rear tyre flat
-----------	--------------------

Breakdown	02/12/2024	10:20	02/12/2024	14:26	476,157	St Leonards	SL048488
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	N/S side indicator damage - plastic shattered. replaced indicator lens and bulb.
-----------	--

Vehicle Deep Clean	13/12/2024	06:36	13/12/2024	12:42	477,288	St Leonards	SL048659
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	16/12/2024	07:00	18/12/2024	18:00	477,288	St Leonards	SL048679
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
Road Test	
Engine Change Oil & Filter	Done.

MOT	
Tail Lift Inspection	Done.
02 Cab Assembly 1	Passenger window switch broken. Replaced.
44 Add Ad Blue	Topped 5 Ltrs.
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change. Done.
17 Tyres Replace	Low tread on outer edge, Replaced.
27 Transmission Automatic	Torque converter leaking.
71 Body Exterior Roof	Rattle/knocking from cab roof!

Unplanned Repair	25/12/2024	11:00	26/12/2024	10:00	478,047	St Leonards	SL048823
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Sliding Door	Side step deploying while driving. Replace top catch and adjust cables
-----------------	--

Unplanned Repair	01/01/2025	11:00	01/01/2025	11:15	478,747	St Leonards	SL048908
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	Mirrors NS wing mirror is broken (Accident) - Replaced. See notes
------------	--

Vehicle Deep Clean	30/01/2025	11:25	31/01/2025	14:53	482,226	St Leonards	SL049340
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	03/02/2025	07:00	06/02/2025	15:15	482,226	St Leonards	SL049391
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
02 Cab Assembly 1	Drivers window switch, cab torch battery, cab interior light bulb -All Replaced.
34 Lights	OSF Sidelight bulb replaced. - Repaired wiring for osr lower tail light.
85 Body Interior 1	Scoop retaining strap replaced.
01 Air Conditioning 1	A/C Compressor fault. replaced compressor and recharged system.
45 Engine 1	Injector No1 leaking. removed, cleaned and refitted using new seals/bolts.
86 Doors Rear	Rear door stay os bolt loose. removed and retightened.
19 Chassis 1	Spray flap resecured to chassis. - tailpipe heatshield resecured.
17 Tyres Replace	Both osr inner tyres replaced.

71 Body Exterior 1 Tail lift bridge plate guides loose. resecured.

Vehicle Deep Clean 20/03/2025 07:09 21/03/2025 08:49 489,292 St Leonards SL050008

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 21/03/2025 10:00 24/03/2025 14:17 489,318 St Leonards SL050022

Check MDVS for Update Check and Install MDVS windows update
 Safety Inspection
 18 Wheels Check Torques
 Road Test
 Annual Heater Service Annual Heater Service
 Replace Handbrake Cables Replace Handbrake Cables
 Tail Lift Inspection
 UB Fire Suppression Discharge Under Bonnet Fire Suppression 5 Year Discharge Test
 86 Doors Rear OSR Door stay bar bolt loose. resecured
 17 Tyres Replace X2
 13 Brakes 1 Front brakes worn. replaced brake kit.

02 Pipeline Annual Inspection 21/03/2025 12:44 21/03/2025 12:46 489,318 MDT Ferndown TF004033

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - passed all tests.

Breakdown 11/04/2025 16:59 12/04/2025 07:32 491,984 St Leonards SL050346

Breakdown ALTERNATOR NOT WORKING. DIFFICULT TO START
 31 Battery Chassis Battery U/S

Unplanned Repair 21/04/2025 07:00 21/04/2025 16:00 493,541 St Leonards SL050500

34 Lights Lighting System NSR light not working
 45 Engine 1 EML/LOP
 Road Test Carry out road test for LOP

Vehicle Deep Clean	06/05/2025	10:05	07/05/2025	12:04	495,624	St Leonards	SL050781
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/05/2025	06:00	09/05/2025	14:15	495,624	St Leonards	SL050817
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
85 Body Int Alcohol Gel Dispen							
Pollen Filter Change	Pollen Filter Change						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
13 Brake Test							
55 Tail Lift	Tail lift side rails loose						
31 Charging System	N/S Side charger not working						
89 Seats	Saloon N/S/F seat base bolts loose						
85 Body Interior 1	Saloon N/S/R seat arm rests loose						
87 - Stretchers/Chairs/Boards	Stretchers belts wrongly fitted AVP						
87 Stretcher	Stretchers foot plate lock covering insecure						
Unplanned Repair	16/05/2025	08:00	16/05/2025	11:01	496,293	St Leonards	SL050987
31 Charging System	Poor starting/Charging fault. Repaired -see notes.						
Breakdown	24/05/2025	13:05	26/05/2025	07:00	496,293	St Leonards	SL051157
Breakdown	Socket that connects to shoreline is bent						
Breakdown	22/06/2025	17:59	23/06/2025	10:00	499,012	St Leonards	SL051700
Breakdown	vehicle judders when turning right						

Breakdown	14/07/2025	01:20	16/07/2025	14:25	503,025	St Leonards	SL052040
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Limp mode, vehicle juddering						
99 Diagnostic Test	Carry out diagnostics. Codes cleared no faults returned. Vehicle decommissioned						
Road Test							

Decommission Vehicle	23/07/2025	09:30			503,025	St Leonards	SL052245
-----------------------------	-------------------	--------------	--	--	----------------	--------------------	-----------------