

Vehicle Detail	LT10YSN	TOYOTA	HI-LUX 4X4 DIESEL	No
Date	Odo	Job Type	Description	
01/05/2025		0 RFL	RFL May 2025	
17/03/2025		0 RFL	RFL Apr 2025	
19/03/2024		0 RFL	RFL APRIL 2024	
20/01/2023	48,529	COLLECTION & DELIVERY	Collection & Delivery	
20/01/2023	48,529	SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
20/01/2023	48,529	SERV/SAFETY INS (+ TEST FEE)	S3 SERVICE	
24/03/2022		0 RFL	RFL Mar 2022	
16/03/2021		0 RFL	RFL March 2021	
26/01/2021	45,148	SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
26/01/2021	45,148	COLLECTION & DELIVERY	Ferry To Test	
26/01/2021	45,148	REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - blade/s	
26/01/2021	45,148	SERV/SAFETY INS (+ TEST FEE)	S1 SERVICE	
15/04/2018		0 RFL	RFL April 2018	
15/03/2018		0 RFL	RFL April 2018	
07/02/2018	36,108	REPAIRS FOR MISUSE OR DAMAGE	Change Tyre	
07/02/2018	36,108	REPAIRS FOR MISUSE OR DAMAGE	Disposal of Tyre Casing	
07/02/2018	36,108	SERV/SAFETY INS (+ TEST FEE)	S8 SERVICE	
07/02/2018	36,108	REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair	
07/02/2018	36,108	REPAIRS TO ELECTRICS/BATTERY	Lamps exterior - headlamp assy right	
07/02/2018	36,108	REPAIRS TO BODY (NON ACCIDENT)	INVESTGATE FRONT WASHERS INOP AND NO RESERVE ON HANDBRAKE	
07/02/2018	36,108	REPAIRS TO ENGINE, EXHAUST	DEF0117 Vehicle Description Audit recall end date =30-APR-2018	
07/02/2018	36,108	REPAIRS FOR MISUSE OR DAMAGE	Wheel Balance	
07/02/2018	36,108	SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
07/02/2018	36,108	REPAIRS TO BODY (NON ACCIDENT)	EA0517 Vehicle condition report recall end date =30-SEP-2018	
07/02/2018	36,108	REPAIRS FOR MISUSE OR DAMAGE	Tyre Call Out	
07/02/2018		0 REPLACEMENT HIRE COST	NSMC	