

WM64JWU	A&E		Brixham Amb Stn				
PDI Inspection	27/03/2015	08:00	31/03/2015	11:03	170	Derriford	DE018093
18 Wheels Retorque	Fit wheel nut check links & tyre valve extensions						
45 Engine Ad Blue	Topped up adblue level						
71 Body Exterior 1	Fit blast film to skylight & remove seat bracket from track cupboard						
PDI Inspection							
Breakdown	03/04/2015	20:00	07/04/2015	07:30	170	Derriford	DE018123
31 Charging System	Got crew to switch onboard charger on been accidently switched off						
Breakdown	CHARGING SOCKET FAULTY						
Unplanned Repair	17/04/2015	09:00	17/04/2015	09:15	2,931	Derriford	DE018182
44 Add Ad Blue	Topped up AD blue						
SAFETY INSPECTION	28/04/2015	07:17	28/04/2015	09:39	5,198	Derriford	DE018227
18 Wheels Check Torques							
44 Add Ad Blue	topped up						
71 Body Exterior 1	fitted correct call sign						
Safety Inspection							
Vehicle Deep Clean	28/04/2015	09:31	28/04/2015	14:43	5,199	Derriford	DE018229
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	06/05/2015	11:00	06/05/2015	11:15	6,859	Derriford	DE018278
44 Add Ad Blue	Topped up Adblue done by crew						

Unplanned Repair	13/05/2015	11:10	13/05/2015	11:57	8,509	Derriford	DE018306
11 Axle Rear	Check forKnocking noise on rear Tighten rear anti rollbar link bolts						
Unplanned Repair	22/05/2015	12:00	22/05/2015	13:00	10,351	Derriford	DE018353
44 Add Ad Blue	Topped up by crew						
Unplanned Repair	03/06/2015	07:48	03/06/2015	07:56	13,262	Derriford	DE018411
31 Charging System	Battery/Charging Sys Shoreline Straighten bent pin in socket						
44 Add Ad Blue	Topped up by crew						
SAFETY INSPECTION	08/06/2015	08:06	08/06/2015	11:31	14,338	Derriford	DE018438
18 Wheels Check Torques	Renewed side step trim						
71 Body External Steps							
Safety Inspection							
Vehicle Deep Clean	08/06/2015	11:42	09/06/2015	07:37	14,359	Derriford	DE018441
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	23/06/2015	22:21	24/06/2015	14:09	17,672	Derriford	DE018507
44 Add Ad Blue	Topped up by crew						
71 Body Exterior 1							
Breakdown							
SAFETY INSPECTION	21/07/2015	07:07	21/07/2015	13:00	24,314	Derriford	DE018629
02 Cab Assembly 1	Renewed cab interior light bulb						
02 Cab Assembly 2							
	Body Interior interior light doesn't work. been repaired						

17 Tyres Replace renewed all 6 tyres
 18 Wheels Check Torques
 45 Engine Ad Blue topped up ad blue
 71 Body Exterior 1 Renewed nsf lower body corner wheel arch damaged
 86 Doors Tightened rear door stay lock nuts
 Safety Inspection
 92 - C Service
 Service C

Vehicle Deep Clean **21/07/2015** **09:00** **21/07/2015** **16:20** **24,314** **Derriford** **DE018631**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **08/08/2015** **12:27** **08/08/2015** **15:00** **28,229** **Derriford** **DE018706**

17 Tyres Replace O/s/r outer tyre replaced by ATS
 Breakdown flat tyre offside rear

SAFETY INSPECTION **02/09/2015** **07:09** **02/09/2015** **11:19** **33,965** **Derriford** **DE018811**

13 Brake Pads Removed and renewed front pads and rear pads
 18 Wheels Check Torques
 85 Body Interior 1 Tightened rear saloon seat arm rest mounting bolts
 Safety Inspection
 Tail Lift 6 Monthly Inspection Statutory Inspection

Vehicle Deep Clean **02/09/2015** **11:25** **02/09/2015** **15:55** **33,965** **Derriford** **DE018814**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **19/09/2015** **19:20** **21/09/2015** **13:18** **38,098** **Derriford** **DE018901**

71 Body External Steps checked veh moved red step locking bar veh ok
 86 Doors Check for side door fault found top latch insecure See notes
 Breakdown Side step deployed and it will not go in

Defect Repair	28/09/2015	07:00	28/09/2015	11:21	39,239	Derriford	DE018938
71 Body External Steps	straightened front runner and step locking lever tested all ok						
Vehicle Deep Clean	13/10/2015	10:33	13/10/2015	14:08	42,333	Derriford	DE019013
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/10/2015	07:42	16/10/2015	15:00	42,333	Derriford	DE019017
02 Cab Assembly 1	Renewed white knob on storage unit						
18 Wheels Check Torques							
24 Driveshaft 1	prop cntre bearing broken up Replaced by Mercedes of Plymouth						
71 Body Exterior Acc Repair	Body Exterior Driver offside bodywork damage						
86 Door handle	side door stiff to open from inside						
87 Stretcher	Repaired steering lock on stretcher						
Safety Inspection							
93 - D Service							
Service D							
Breakdown	15/11/2015	08:58	17/11/2015	14:43	48,989	Derriford	DE019143
Breakdown	vehicle not charging on Shoreline						
Vehicle Deep Clean	24/11/2015	08:00	24/11/2015	11:25	50,820	Derriford	DE019181
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	25/11/2015	06:57	26/11/2015	07:42	50,820	Derriford	DE019187
02 Cab Assembly 1	Renewed torch						
17 Tyres Replace	renewed 6x tyres						
18 Wheels Check Torques							
71 Body Exterior 1	os body damaged						
71 Body External Steps	side step creeps out						
86 Doors	inner side door handle stiff warranty						

86 Sliding Door stiff to open from inside
 87 - Stretchers/Chairs/Boards no pedemate or straps
 89 Seats seat bearings warranty
 Safety Inspection
 Gearbox Oil & Filter Change

Unplanned Repair **16/12/2015** **07:00** **16/12/2015** **17:25** **55,116** **Derriford** **DE019299**

03 Instruments & Sensors 1 Reset service mileage indicator
 31 Charging System Charging socket faulty Replaced under warranty
 71 Body External Steps Side step not working Repaired under warranty

Unplanned Repair **22/12/2015** **11:19** **22/12/2015** **12:01** **56,454** **Launceston** **LA008827**

45 Engine Oil Top Up Top up oil

Vehicle Deep Clean **05/01/2016** **10:49** **05/01/2016** **14:26** **59,875** **Derriford** **DE019380**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **06/01/2016** **07:22** **06/01/2016** **12:09** **59,876** **Derriford** **DE019382**

18 Wheels Check Torques
 45 Engine Ad Blue
 71 Body External Steps
 Safety Inspection
 MOT Pre Test
 92 - C Service
 Service C

Unplanned Repair **18/01/2016** **08:09** **18/01/2016** **09:18** **63,089** **Derriford** **DE019450**

86 Sliding Door Straighten door switch contact arm & reset switch

Breakdown	02/02/2016	02:20	02/02/2016	10:00	65,972	Derriford	DE019521
------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

34 Lights Bulb Replacement Breakdown	Replaced n/s headlight bulbs nside main beam bulb n/w
--------------------------------------	--

SAFETY INSPECTION	16/02/2016	09:04	17/02/2016	13:00	69,459	Derriford	DE019586
--------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

02 Cab Assembly 1	renewed cab storage white knob	
18 Wheels Check Torques		
24 Driveshaft 1	Propshaft centre bearing starting to Fail	Awaiting Warranty
34 Lights Bulb Replacement	Renewed os dipped beam bulb	
43 Exhaust System 1	Straightened exhaust heat shield	
44 Add Ad Blue	Topped up add blue	
87 Stretcher	Adjusted stretcher brake/wheel lock pin	
Road Test	to check speed limiter its set to 60mph	
Safety Inspection		
Travel Time		
MOT	Done by A J Motors P/O 151123347	
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by South West Lifts P/O 151124753	
Tail Lift 6 Monthly Inspection	Statutory Inspection	

Vehicle Deep Clean	17/02/2016	12:11	18/02/2016	13:40	69,469	Derriford	DE019592
---------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	25/02/2016	07:42	26/02/2016	10:30	70,966	Derriford	DE019622
-------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

03 Instruments & Sensors 1	Ecu software upgrade
24 Driveshaft 1	Propshaft centre bearing Replaced under warranty by Mercedes of plymouth
34 Lights Bulb Replacement	Replaced o/s side repeator bulb

Unplanned Repair	09/03/2016	10:00	10/03/2016	09:03	73,990	Derriford	DE019680
-------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

55 Tail Lift	Drill out sheared bolts & resecure bridge plate sliders
86 Doors Rear	O/s/r door stay sheared off removed doorstay & mount,DRILLED AND REPAIRED

Defect Repair	14/03/2016	14:26	14/03/2016	15:13	75,271	Derriford	DE019701
----------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

03 Instruments & Sensors 1	Central locking fault rear door						Awaiting Warranty
----------------------------	---------------------------------	--	--	--	--	--	-------------------

Breakdown	24/03/2016	21:24	24/03/2016	22:00	77,572	Derriford	DE019761
------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

34 Lights Bulb Replacement Breakdown	Replaced by crew Headlight N/S out, OO not available
---	---

Vehicle Deep Clean	29/03/2016	07:59	29/03/2016	11:26	78,633	Derriford	DE019777
---------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	29/03/2016	12:15	30/03/2016	11:38	78,633	Derriford	DE019779
--------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

03 Instruments & Sensors 1	Central locking fault rear door						
13 Brake Pads	Renewed front pads and rear pads						
13 Discs	Renewed front and rear discs						
17 Tyres Replace	6X tyres replaced						
18 Wheels Check Torques							
27 Transmission Manual	prop centre bearing rubber spitting failed						Awaiting Warranty
34 Lights Bulb Replacement	2x bulbs						
56 Comms Equipment	tightened stalk						
Safety Inspection							
Fit Throw Lines & SOP							
93 - D Service							
Service D							
Annual Air Con Service	Annual Air Condition Service Done by Espar P/O 151127846						

Breakdown	10/04/2016	00:08	10/04/2016	08:25	80,998	Derriford	DE019832
------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

34 Lights Bulb Replacement Breakdown	headlight bulb Replaced N/S/F Headlight gone
---	---

Install Saloon CCTV Camera	12/04/2016	08:14	12/04/2016	09:43	81,521	Derriford	DE019846
-----------------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Install Saloon CCTV Camera Fitted by John Coles
85 Body Int Alcohol Gel Dispen Fitted

Breakdown	15/04/2016	11:05	15/04/2016	14:01	82,286	Derriford	DE019872
------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

24 Driveshaft 1 Rear propshaft foremost u/j broken up,changed awaiting stock from was
Breakdown tracking and noise when braking

Defect Repair	18/04/2016	11:39	18/04/2016	11:42	82,783	Derriford	DE019882
----------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

18 Wheels Balance & AlignmenWheel balance @ ATS Liskeard.

Vehicle Deep Clean	09/05/2016	08:56	09/05/2016	13:17	87,824	Derriford	DE019972
---------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	09/05/2016	13:04	13/05/2016	08:53	87,824	Derriford	DE019974
--------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

01 Air Conditioning 1	Air Con not working Repaired by Mercedes of Plymouth	
16 Suspension 1	Front struts worn Mercedes alignment tool n/w vehicle will be called back in	Awaiting Warranty
18 Wheels Check Torques		
27 Transmission Manual	Prop centre bearing replaced by Mercedes of plymouth	
34 Lights Bulb Replacement	Cab bulb renewed	
43 Exhaust System 1	Reposition tailpipe	
55 Tail Lift	Secure bridge plate giude	
56 Comms Equipment	PTT stalk secured	
87 - Stretchers/Chairs/Boards	Service Scoop & Spinal, fit stretcher belt	
Safety Inspection		
Travel Time		
Annual Heater Service	Annual Heater Service	
Handbrake Cable Replacement	Replace rear handbrake cables	

Unplanned Repair	23/05/2016	12:00	23/05/2016	12:35	90,300	Derriford	DE020030
-------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

34 Emergency Lights Renew n/s/r blue light lens

Unplanned Repair	31/05/2016	09:00	31/05/2016	09:37	92,395	Derriford	DE020057
17 Tyres Replace 85 Body Interior 1 89 Seatbelts	replaced n/s/r inner tyre punctured Folder holder damaged Parts ordered Swivel seat belt u/s Parts Ordered					Awaiting Parts Awaiting Parts	
Unplanned Repair	02/06/2016	11:30	02/06/2016	12:10	93,024	Derriford	DE020074
89 Seatbelts	Swivel seat belt u/s replace swivel seat seatbelt						
Breakdown	05/06/2016	12:21	05/06/2016	14:30	93,200	Derriford	DE020088
17 Tyres Replace Breakdown	Replaced n/s/f tyre Done by ATS Nail in tyre						
Unplanned Repair	06/06/2016	12:30	06/06/2016	13:04	94,001	Derriford	DE020097
34 Emergency Lights	Carry out temp repair to n/s/r blue light					Awaiting Parts	
ACCIDENT	08/06/2016	15:00	08/06/2016	15:43	94,703	Derriford	DE020114
71 Body Exterior Acc Repair	Carry out temp repair to front of vehicle (hit a Deer) willrequire b/shop repai					Awaiting Body Repair	
Unplanned Repair	15/06/2016	13:39	15/06/2016	14:14	96,261	Launceston	LA009268
45 Engine Oil Top Up							
SAFETY INSPECTION	21/06/2016	11:32	23/06/2016	07:39	97,665	Derriford	DE020167
01 Air Conditioning 1 13 Brakes 1 16 Suspension 1 17 Tyres Replace 18 Wheels Check Torques	air con tensioner siezing renewed pedal rubber Front struts worn Mercedes alignment tool n/w vehicle will be called back in Replace both osr tyres and nsri tyre					Awaiting Warranty Awaiting Warranty	

24 Driveshaft 1	Prop shaft centre bearing failed again	
34 Emergency Lights	renewed n/s/r blue light	
45 Engine 1	timing chain noisy and slight misfire under load	Awaiting Warranty
71 Body Exterior Acc Repair	Carry out temp repair to front of vehicle (hit a Deer) willrequire b/shop repai	Awaiting Body Repair
85 Body Interior 1	Folder holder renewed	

Safety Inspection
 UB Fire Suppression Service
 Wheel Studs & Nuts Replaceme
 Reposition grab bag shelf
 92 - C Service
 Service C

Unplanned Repair	23/06/2016	07:39	24/06/2016	08:34	97,665	Derriford	DE020181
-------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

01 Air Conditioning 1	air con tensioner siezing	Awaiting Warranty
16 Suspension 1	Front struts worn Mercedes alignment tool n/w vehicle will be called back in	Awaiting Warranty
45 Engine 1	timing chain noisy and slight misfire under load	Awaiting Warranty
71 Body Exterior Acc Repair	Carry out temp repair to front of vehicle (hit a Deer) willrequire b/shop repai	Awaiting Warranty

Vehicle Deep Clean	23/06/2016	13:00	24/06/2016	10:38	97,665	Derriford	DE020186
---------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	08/07/2016	12:03	08/07/2016	12:06	101,035	Derriford	DE020253
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

71 Body External Steps	renewed step trim
------------------------	-------------------

BREAKDOWN	21/07/2016	01:00	21/07/2016	18:00	103,623	Launceston	LA009353
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

55 Tail Lift	Cannot raise with stretcher and patient on it. SWL replaced O ring pump-tank
--------------	--

SAFETY INSPECTION	02/08/2016	09:15	04/08/2016	14:30	106,289	Derriford	DE020352
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

01 Air Conditioning 1	air con tensioner siezing	Was warranty sent	Awaiting Warranty
02 Cab Ass Fire Extinguisher	1x fire Ex. renewed		
02 Cab Assembly 1	Cab light bulb renewed		
02 Cab Assembly 2	FireTrace warning sounding, pressure ok	Was warranty sent	Awaiting Warranty

16 Suspension 1	Front struts replaced under warranty by Mercedes of Plymouth						
17 Tyres Replace	NSF tyre renewed, tracking adjusted						
18 Wheels Check Torques							
27 Transmission Automatic	Bolt sheared on G/box pan. Fitting renewed						
45 Engine 1	timing chain noisy checked by Mercedes of Plymouth reported back ok						
55 Tail Lift	Bridge plate guides secured. LEDs n/w Warranty sent						Awaiting Warranty
71 Body Exterior 1	Front Grill surround damage						Monitoring
71 Body Exterior Acc Repair	Carry out temp repair to front of vehicle (hit a Deer) willrequire b/shop repai						Awaiting Body Repair
85 Body Interior 1	Light switch in cupboard adjusted						
86 Door Lock	Rear door locking solenoid noisy. Warranty sent						Awaiting Warranty
86 Doors	Side door latch covers secured, r. door catches adjusted						
Safety Inspection							
Gearbox Oil & Filter Change							
Tail Lift 6 Monthly Inspection	Statutory Inspection						

Vehicle Deep Clean	05/08/2016	06:55	05/08/2016	13:54	106,289	Derriford	DE020375
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	07/08/2016	13:46	08/08/2016	09:39	106,873	Derriford	DE020378
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

03 Instruments & Sensors 1	Check for fault codes clear out stored faults & reset service mileage
Breakdown	limp mode, dangerous to drive on fast road
Road Test	Carry out extended road test

Unplanned Repair	09/08/2016	12:00	10/08/2016	15:00	106,882	Derriford	DE020394
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

01 Air Conditioning 1	air con tensioner siezing Replaced by Mercedes of Plymouth under warranty
Travel Time	Take & collect vehicle to dealers

Breakdown	11/08/2016	06:27	11/08/2016	11:57	106,882	Derriford	DE020402
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Breakdown	both side mirrors broken
-----------	--------------------------

BREAKDOWN	15/08/2016	15:10	15/08/2016	16:25	108,246	Redruth	RE019800
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Sliding Door	Outer handle broken, now replaced.
-----------------	------------------------------------

Breakdown	28/08/2016	08:31	30/08/2016	11:30	111,714	Derriford	DE020491
17 Tyres Replace 56 Comms Equipment Breakdown	Tyre replaced by ATS MDT not working MDT POWERED DOWN, NOT SWITCH ON						
Unplanned Repair	30/08/2016	11:30	07/09/2016	11:15	111,714	Derriford	DE020506
45 Engine 1 Travel Time	Timimng chain rattle on engine start up Take vehicle to Dealers						
SAFETY INSPECTION	07/09/2016	11:13	08/09/2016	08:15	111,734	Derriford	DE020554
02 Cab Ass Fire Extinguisher 02 Cab Assembly 1 13 Brake Pads 17 Tyres Replace 18 Wheels Check Torques 86 Doors Rear Safety Inspection	Fire warning sounding Repaired storage cupboard in cab Renewed front brake pads Replaced nsri tyre Doors defective central locking/door catch in rear door.repaired warranty						Awaiting Warranty
Vehicle Deep Clean	08/09/2016	07:43	08/09/2016	13:28	111,734	Derriford	DE020562
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/10/2016	07:34	19/10/2016	13:33	120,923	Derriford	DE020845
02 Cab Ass Fire Extinguisher 02 Cab Assembly 1 13 Brake Pads 17 Tyres Replace 17 Tyres Tracking 18 Wheels Check Torques 34 Emergency Light System 34 Lights Bulb Replacement 55 Tail Lift 71 Body Exterior 1 71 Body Exterior 2	Fire warning sounding Saloon fire ex. renewed Rear pads renewed NSF, OS & NS Outer tyres renewed Lighting System siren not working, lights and horn fine. Awaiting panel OSf sidelight bulb renewed Bridge plate guides secured. Slow operation, New tilt sensor fitted warranty Body Exterior scraped sliding door on gatepost Spray supression secured, Body corner renewed						Awaiting Warranty Awaiting Parts Awaiting Body Repair

85 Body Interior 1	Equip. strap broken						
86 Doors Rear	Mechanism freed off						
86 Sliding Door	Top latch insecure, cover renewed						
Road Test							
Safety Inspection							
93 - D Service							
Service D							
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill						
Vehicle Deep Clean	19/10/2016	10:48	19/10/2016	14:38	120,925	Derriford	DE020860
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/10/2016	11:30	21/10/2016	15:18	121,178	Derriford	DE020878
03 Instruments & Sensors 1	Reset service milage indicator						
55 Tail Lift	Operating very slow Power pack pump replaced under warranty						
Defect Repair	07/11/2016	10:00	07/11/2016	10:57	124,823	Derriford	DE020963
02 Cab Assembly 1	Wiper blades renewed						
34 Lights Bulb Replacement	NS day running bulb renewed						
Breakdown	09/11/2016	23:52	10/11/2016	08:31	125,274	Derriford	DE020984
34 Lights Bulb Replacement	Replaced by CSO						
Breakdown	Headlight gone						
Unplanned Repair	16/11/2016	12:03	16/11/2016	12:17	126,881	Derriford	DE021018
Supply Sat Nav	Replaced SD card						
SAFETY INSPECTION	30/11/2016	07:52	01/12/2016	11:14	130,222	Derriford	DE021100
02 Cab Ass Fire Extinguisher	Fire warning sounding						Awaiting Parts
18 Wheels Check Torques							
34 Emergency Light System	Cab Genisi panel replaced under warranty						

71 Body Exterior 1 Safety Inspection MOT Pre Test	Body Exterior scraped sliding door on gatepost						
Vehicle Deep Clean	30/11/2016	11:00	01/12/2016	08:00	130,222	Derriford	DE021106
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	15/12/2016	15:00	15/12/2016	15:59	133,241	Derriford	DE021204
02 Mirrors	Replaced n/s mirror assy						
BREAKDOWN	27/12/2016	13:00	27/12/2016	15:00	135,853	Derriford	DE021273
17 Tyres Replace	Replaced both front & both o/s/r tyres Done by ATS						
Breakdown	02/01/2017	21:33	03/01/2017	10:00	137,329	Derriford	DE021293
56 Comms Equipment Breakdown	Comms equipment repaired by PCE (new board & battery) battery check required N.F.F						
SAFETY INSPECTION	11/01/2017	07:52	12/01/2017	12:30	139,063	Derriford	DE021337
02 Cab Ass Fire Extinguisher 03 Instruments & Sensors 1 11 Axle Rear 17 Tyres Replace 18 Wheels Check Torques 27 Transmission Manual 34 Lights 43 Exhaust System 1 45 Engine 1 71 Body Exterior 1 Safety Inspection Medical Device and Equip Chec	Fire warning sounding Service reset Anti roll bar cotton reel bushes renewed NSR inner tyre renewed Prop centre bearing starting to split NSF sidelight bub renewed. NSR rev light bottom LED row not working Secure/refit tailpipe Bolt replaced in EGR heat exchanger Front no plate renewed					Awaiting Warranty Awaiting Warranty Awaiting Warranty	

92 - C Service
Service C
Tail Lift 6 Monthly Inspection Statutory Inspection
Tail Lift Annual Service Statutory Inspection and Weight Test Done by south west lifts P/O 151145137
Travel Time
MOT Done by A J Motors P/O 151144118

Vehicle Deep Clean 12/01/2017 09:02 13/01/2017 07:59 139,063 Derriford DE021346

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair 23/01/2017 10:32 23/01/2017 15:00 141,216 Derriford DE021401

34 Emergency Lights O/s/r blue light lens smashed off Replaced blue light lens assy

BREAKDOWN 06/02/2017 08:27 06/02/2017 11:33 144,617 Derriford DE021483

03 Instruments & Sensors 1 EML on Merc 24 repair

SAFETY INSPECTION 22/02/2017 08:43 24/02/2017 11:31 147,821 Derriford DE021577

02 Cab Ass Fire Extinguisher Fire warning sounding Awaiting Warranty

13 Brakes 1 Renew front discs & pads

17 Tyres Replace Replaced n/s/f & n/s/r Outer tyre

17 Tyres Tracking Check & adjust tracking

18 Wheels Check Torques

27 Transmission Manual Prop centre bearing starting to split Awaiting Warranty

34 Lights Replace n/s/r reverse light assy

86 Door Lock Rear door will not open from inside

86 Sliding Door roller bearings noisy Awaiting Warranty

89 Seats tighten both swivel seat lockpin locknuts

Safety Inspection

Annual Air Con Service Annual Air Condition Service

Annual Heater Service Annual Heater Service

Handbrake Cable Replacement Replace rear handbrake cables Not required

Vehicle Deep Clean	24/02/2017	11:02	25/02/2017	08:00	147,825	Derriford	DE021589
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	30/03/2017	10:00	30/03/2017	10:56	154,549	Derriford	DE021759
17 Tyres Replace	Replaced both o/s/r tyres punctured						
Vehicle Deep Clean	05/04/2017	07:00	05/04/2017	14:27	155,859	Derriford	DE021784
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/04/2017	12:05	07/04/2017	14:44	155,859	Derriford	DE021796
02 Cab Ass Fire Extinguisher	New system fitted by John coles					Monitoring	
11 Axle Front	Lift in ball joints						
13 Brake Pads	Rear pads renewed						
18 Wheels Check Torques						Awaiting Warranty	
27 Transmission Manual	Prop centre bearing starting to split						
34 Emergency Lights	Renew os body blue					Awaiting Body Repair	
71 Body Exterior 1	Body Exterior den on N/S wheel arch						
71 Body Exterior 2	Body Exterior N/s top of side scraped.						
71 Body Exterior 3	NSF bottom body corner damage. Fog light surround renewed					Awaiting Body Repair	
85 Body Interior 1	Secure white board					Awaiting Warranty	
86 Doors Rear	Adjust latch						
86 Sliding Door	roller bearings noisy						
87a - Medical Equipment Repair	Fit mangar charger board						
Safety Inspection							
93 - D Service							
Service D							
Gearbox Oil & Filter Change							
ACCIDENT	10/04/2017	07:47	20/04/2017	14:55	155,859	Derriford	DE021812
71 Body Exterior 1	Body Exterior N/s rear wheel arch holed.						
71 Body Exterior 2	Body Exterior N/s top of side scraped.						
71 Body Exterior 3	NSF bottom body corner damage. Fog light surround renewed						

UB Fire Suppression Service New system has been fitted 07/04/17

SAFETY INSPECTION	16/05/2017	09:30	17/05/2017	07:44	161,961	Derriford	DE022024
11 Axle Front		Lift in ball joints					Awaiting Warranty
17 Tyres Replace		NSR inner tyre renewed					
18 Wheels Check Torques							
27 Transmission Manual		Prop centre bearing starting to split					Awaiting Warranty
43 Exhaust System 1		EGR pipe leak					Awaiting Warranty
55 Tail Lift		Bridge plate guides secured, handrail adjustment freed off					
86 Doors Rear		Adjust catches and latches					
86 Sliding Door		roller bearings noisy					
Safety Inspection							
Vehicle Deep Clean	17/05/2017	07:33	17/05/2017	10:58	161,961	Derriford	DE022034
Vehicle Deep Clean		Vehicle Deep Clean					
Breakdown	21/05/2017	06:55	22/05/2017	10:00	161,961	Derriford	DE022056
17 Tyres Replace		Replace n/s/f tyre used from derriford stock Done by ATS					
18 Wheels		Replaced wheel rim					
Breakdown		n/s front flat					
Unplanned Repair	22/06/2017	11:41	22/06/2017	13:40	171,303	Derriford	DE022255
15 Steering 1		Check & reset tracking					
17 Tyres Replace		Replace n/s/f tyre					
SAFETY INSPECTION	28/06/2017	07:17	29/06/2017	07:32	172,653	Derriford	DE022292
11 Axle Front		Lift in ball joints					Awaiting Warranty
16 Suspension 1		rear slipper pads split					Awaiting Warranty
16 Suspension 2		nsr shock leaking					Awaiting Warranty
16 Suspension 3		play in front struts					

18 Wheels Check Torques		
27 Transmission Manual	Prop centre bearing starting to split	Awaiting Warranty
43 Exhaust System 1	EGR pipe leak	Awaiting Warranty
43 Exhaust System 2	heater exh split	
45 Engine 1	timing chain noisy	Awaiting Warranty
71 Body Exterior 1	renewed nsf lower corner	
71 Body External Steps	Body Exterior sidestep not deploying	
86 Doors Rear	fitted mod plates	
Safety Inspection		
MGS Gas Storage Modifications	MGS Gas Storage Modifications	
Tail Lift 6 Monthly Inspection	Statutory Inspection	

Unplanned Repair	29/06/2017	07:32	18/07/2017	15:13	172,653	Derriford	DE022300
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

11 Axle Front	Lift in ball joints & play in front stuts Replaced under warranty
16 Suspension 1	rear slipper pads split replaced under warranty
16 Suspension 2	nsr shock leaking
27 Transmission Manual	Prop centre bearing starting to split
43 Exhaust System 1	EGR pipe leak repaired under warranty
45 Engine 1	timing chain noisy Replaced under warranty
Travel Time	Take vehicle to dealers

Breakdown	06/08/2017	10:23	06/08/2017	13:00	176,232	Derriford	DE022507
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

17 Tyres Replace	Tyre replaced by ATS
Breakdown	LOW TREAD

Vehicle Deep Clean	09/08/2017	07:58	09/08/2017	15:00	177,112	Derriford	DE022523
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	10/08/2017	06:58	10/08/2017	14:31	177,112	Derriford	DE022529
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Cab Ass Fire Extinguisher	swapped
02 Cab Assembly 1	Renewed cab lamp bulb
18 Wheels Check Torques	
24 Driveshaft 1	Replaced propshaft centre bearing supplied FOC
55 Ramp	repaired sliders
86 Sliding Door	renewed inner panel
Safety Inspection	
92 - C Service	

Service C							
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Vehicle Deep Clean	10/08/2017	07:01	10/08/2017	07:02	177,112	Derriford	DE022530
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/08/2017	11:30	21/08/2017	14:22	179,011	Derriford	DE022586
71 Body Exterior 1	Resecure tail lift bridge plate sliders & o/s/r body corner & reflector						
Unplanned Repair	29/08/2017	15:00	29/08/2017	15:30	180,968	Derriford	DE022638
15 Steering 1	Topped up power steering oil level						
34 Lights Bulb Replacement	Replaced n/s wing indicator bulb						
44 Add Ad Blue	Topped up adblue						
Defect Repair	11/09/2017	13:13	11/09/2017	13:16	183,711	Derriford	DE022725
17 Tyres Replace	Renew front tyres						
17 Tyres Tracking	Adjusted						
SAFETY INSPECTION	20/09/2017	08:22	20/09/2017	13:27	185,769	Derriford	DE022771
01 Air Conditioning 1	condenser fan not working					Awaiting Warranty	
02 Cab Assembly 1	repaired storage cupboard						
17 Tyres Replace	Renewed 4x rear tyres						
18 Wheels Check Torques							
24 Driveshaft 1	prop centre bearing failed					Awaiting Warranty	
34 Lights Bulb Replacement	refitted os sidelight into headlamp						
44 Add Ad Blue	topped up						
45 Engine 1	engine oil leak					Awaiting Warranty	
Safety Inspection							

Vehicle Deep Clean	20/09/2017	13:04	21/09/2017	12:30	185,769	Derriford	DE022776
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/09/2017	13:06	28/09/2017	15:30	185,796	Derriford	DE022780
15 Steering 1	Steering pump & lower column replaced under warranty prop centre bearing split Repaired oil leak from oil filter housing P/O 151160905 Take vehicle to dealers					Monitoring	
24 Driveshaft 1							
45 Engine 1							
Travel Time							
SAFETY INSPECTION	31/10/2017	08:31	01/11/2017	14:52	192,773	Derriford	DE023018
01 Air Conditioning 1	condenser fan not working Bulkhead grommet renewed See notes Handbrake shoes renewed 1/11/17 @ 192773 Miles Adjust tracking OSR side blue not working Warranty sent EGR pipe leaking, OS manifold Engine oil leak o/s of engine Bridge plate guides secured NSR bottom body corner renewed Catches/latches adjusted					Monitoring	
02 Cab Assembly 1							
13 Brakes 1							
13 Handbrake							
17 Tyres Tracking						Awaiting Warranty	
18 Wheels Check Torques							
34 Emergency Lights							
43 Exhaust System 1						Awaiting Warranty	
45 Engine 1							
55 Tail Lift						Awaiting Warranty	
71 Body Exterior 1							
86 Doors Rear							
Safety Inspection							
MOT Pre Test							
Vehicle Deep Clean	01/11/2017	13:04	02/11/2017	11:12	192,773	Derriford	DE023031
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	02/11/2017	08:50	23/11/2017	14:30	192,773	Derriford	DE023036
43 Exhaust System 1	EGR pipe leaking, OS manifold Replaced by Mercedes of Plymouth Engine oil leak o/s of engine Repaired by Mercedes of Plymouth Take vehicle to dealers						
45 Engine 1							
Travel Time							

BREAKDOWN	24/11/2017	09:30	22/12/2017	14:30	192,993	Derriford	DE023164
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

03 Instruments & Sensors 1	EML light on
45 Engine 1	Oil leak repaired by mercedes of Plymouth
Travel Time	Take vehicle to dealer

SAFETY INSPECTION	22/12/2017	07:00	22/12/2017	14:53	193,002	Derriford	DE023346
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Windscreen Wipers	washer bottle leaking sealed grommet & refitted washer pump correctly
13 Handbrake	Handbrake shoes renewed 1/11/17 @ 192773 Miles
18 Wheels Check Torques	
24 Driveshaft 1	centre bearing failed Replaced under warranty by Mercedes
31 Battery Chassis	jump point incorrectly fitted under bonnet Refitted
34 Emergency Lights	OSR side blue not working Warranty sent
55 Ramp	tail lift decals peeling
71 Body Exterior 1	ns camera dome smashed
Safety Inspection	
Travel Time	
MOT	Done by Mercedes P/O 151164229
Tail Lift 6 Monthly Inspection	Statutory Inspection
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by South west lifts P/O 151164230

Unplanned Repair	05/01/2018	07:36	05/01/2018	11:39	195,649	Derriford	DE023412
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

86 Sliding Door	Renewed rollers
UB Fire Suppression Service	Replace fire suppression system due to incorrect fitment

Unplanned Repair	17/01/2018	10:00	17/01/2018	10:52	197,314	Derriford	DE023486
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

55 Tail Lift	Adjust tilt ram
--------------	-----------------

Breakdown	22/01/2018	08:21	24/01/2018	08:30	197,650	Derriford	DE023511
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

31 Charging System	Alternator not charging Alternator replaced By Mercedes of plymouth
Breakdown	Alternator Gone

Travel Time

SAFETY INSPECTION	24/01/2018	08:47	25/01/2018	08:35	198,101	Derriford	DE023536
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Cab Assembly 1	Cab storage locker top insecure-Repaired and secured	
18 Wheels Check Torques		
24 Driveshaft 1	Propshaft centre bearing split-Warranty	Awaiting Warranty
34 Emergency Light System	Siren wiring insecured-Secured	
43 Exhaust System 1	Tail pipe badly corroded-Renewed	
45 Engine 1	Bracket bolt sheared off-Mercedes to repair	Awaiting Warranty
71 Body External Steps	Side step damaged-Repaired	
Safety Inspection	Carried out safety inspection	
93 - D Service	Carried out D service	
Service D		

Vehicle Deep Clean	25/01/2018	08:20	25/01/2018	08:21	198,101	Derriford	DE023551
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	25/01/2018	08:30	25/01/2018	15:30	198,101	Derriford	DE023552
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	27/01/2018	11:09	29/01/2018	08:19	198,418	Derriford	DE023561
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Breakdown	Possible fuel leak , taken off road -precaution
-----------	---

BREAKDOWN	29/01/2018	08:20	29/01/2018	08:45	198,418	Launceston	LA011179
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

24 Driveshaft 1	Propshaft centre bearing split-Warranty	Awaiting Warranty
44 Fuel System 1	Fuel is leaking - Found bleeder pipe seal to be split - Replaced fuel filter	
45 Engine 1	Bracket bolt sheared off-Mercedes to repair	Awaiting Warranty

BREAKDOWN	15/02/2018	15:44	16/02/2018	10:52	201,608	Derriford	DE023691
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Windscreen Wipers	Toped up washer level
03 Instruments & Sensors 1	Reset service mileage indicator
45 Engine 1	Auxiliary drive belt failed Replaced drive belt

Breakdown	25/02/2018	19:16	25/02/2018	21:00	203,829	Derriford	DE023749
17 Tyres Replace Breakdown	O/s/r outer tyre replaced by ATS 205/75 R16C osr outer slow puncture						
Breakdown	26/02/2018	01:28	26/02/2018	16:04	203,941	Derriford	DE023750
03 Instruments & Sensors 1 17 Tyres Replace Breakdown	Investigate none start See notes Replaced o/s/f tyre engine turns but wont start						
Breakdown	02/03/2018	08:14	02/03/2018	13:27	204,457	Derriford	DE023792
Breakdown MDT Failure/Issue	frozen log in screen Reboot MDT screen						
SAFETY INSPECTION	07/03/2018	07:04	08/03/2018	14:22	205,253	Derriford	DE023827
13 Brakes 1 18 Wheels Check Torques 24 Driveshaft 1 34 Emergency Lights 34 Lights 45 Engine 1 71 Body Exterior 1 71 Body Exterior 2 71 Body External Steps 85 Body Interior 1 86 Doors Rear 89 Seats Safety Inspection 85 Body Int Alcohol Gel Dispen Wheel Hub Flanges Replaceme UB Fire Suppression Service Annual Air Con Service Annual Heater Service Handbrake Cable Replacement	OSR pad spring set renewed Propshaft centre bearing split OSR blue renewed by Electricks NSF marker renewed Bracket bolt sheared off-Mercedes to repair NSF bottom body corner renewed Spray supression insecure Step intermmitant and edge renewed, 2nd hand motor fitted Equip. strap renewed Fit strenghtening plate, adjust striker plate Att. seat adjuster bar to refit Rears done, insufficent front stock Annual Air Condition Service. No pressure in system Espar P/O 151167745 Annual Heater Service Replace rear handbrake cables						
						Monitoring	
						Awaiting Parts	

Vehicle Deep Clean	08/03/2018	12:03	09/03/2018	10:34	205,253	Derriford	DE023837
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	12/03/2018	11:10	12/03/2018	11:13	205,970	Derriford	DE023859
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Mirrors	rebuilt o/s
------------	-------------

Breakdown	25/03/2018	16:43	12/04/2018	10:00	208,395	Derriford	DE023935
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

001 Recover Vehicle	Recover from launceston to Mercedes of plymouth F S Recovery P/O 151168613
002 Major Unit Replace Eng	
13 Calipers	o/s/f caliper replaced part supplied
41 Turbo	Due to turbo failure it has caused engine damage requies replacement engine
45 Engine 1	Fit replacement engine assy Mercedes P/O 151168664
Breakdown	EML on - limp mode

SAFETY INSPECTION	12/04/2018	10:21	18/04/2018	06:38	208,406	Derriford	DE024040
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

13 Brake Test	
13 Calipers	OSF caliper renewed
17 Tyres Tracking	Adjust
18 Wheels Check Torques	
24 Driveshaft 1	Propshaft centre bearing replaced 2nd hand Telma flange fitted fit missing nuts
55 Tail Lift	Bridge plate guides refitted, seized hand rail freed off
89 Seats	Att. seat adjuster bar refitted
Safety Inspection	
UB Fire Suppression Service	Re-route correctly after contractors
Wheel Hub Flanges ReplacemeDone	
Gearbox Oil & Filter Change	
Fit Poster Holder	Fit Poster Holder

Vehicle Deep Clean	17/04/2018	08:30	17/04/2018	12:02	208,406	Derriford	DE024061
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	10/05/2018	10:36	11/05/2018	14:36	212,235	Derriford	DE024213
02 Windscreen Breakdown	Windscreen replaced by N/windcreens crack on drivers side						
Unplanned Repair	24/05/2018	11:30	24/05/2018	12:10	215,289	Derriford	DE024308
56 Comms Power Failure	Replace comms battery						
Unplanned Repair	25/05/2018	11:00	25/05/2018	11:45	215,384	Derriford	DE024317
17 Tyres Replace	Replaced n/s/f tyre						
Breakdown	25/05/2018	18:15	26/05/2018	07:07	215,435	Derriford	DE024319
Breakdown	Not starting up, taking 5 or 6 times to start battery replaced						
SAFETY INSPECTION	29/05/2018	08:52	31/05/2018	07:31	215,436	Derriford	DE024324
02 Cab Assembly 1	Tool box cover cracked,Renewed OSR and NSR inner tyres worn,Renewed Propshaft centre bearing starting to crack power failing,Renewed NS camera dome smashed Side step n/w,Repaired Attendants seat adjuster adrift,Repaired Statutory Inspection						
17 Tyres Replace							
18 Wheels Check Torques							
24 Driveshaft 1							
31 Battery Chassis							
71 Body Exterior 1							
71 Body External Steps							
89 Seats							
Safety Inspection							
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection							
Vehicle Deep Clean	30/05/2018	07:59	30/05/2018	12:01	215,436	Derriford	DE024331
Vehicle Deep Clean	Vehicle Deep Clean						

Monitoring

Breakdown	15/06/2018	15:59	18/06/2018	14:30	216,000	Derriford	DE024451
34 Emergency Light System	Renewed side door blue light						
45 Engine 1	Checkes for reported fault system upgrade carried out by Mercedes						
Breakdown	EML flashing yellow; add blue system malfunct.						
Travel Time	Take vehicle to dealers						

Breakdown	24/06/2018	14:32	28/06/2018	15:00	216,001	Derriford	DE024500
45 Engine 1	EGR valve has failed EGR Valve replaced by Mercedes under warranty						
Breakdown	Adblue failure						

Unplanned Repair	28/06/2018	09:42	28/06/2018	09:48	216,001	Derriford	DE024908
03 Instruments & Sensors 1	Check for Adblue fault carried out system upgrade Mrecedes P/O 151175639						

SAFETY INSPECTION	12/07/2018	06:35	12/07/2018	14:50	223,093	Derriford	DE024622
02 Cab Assembly 1	Centre console catch broken						
13 Brake Pads	Rear pads renewed						
18 Wheels Check Torques							
24 Driveshaft 1	Propshaft centre bearing starting to crack						
34 Emergency Light System	OSR body blue renewed						
71 Body Exterior 1	OSR bottom body corner renewed						
86 Doors Rear	Catches adjusted, os door stay replaced with 2nd hand unit						
89 Seats	Att. seat adjuster refitted						
Safety Inspection							

Vehicle Deep Clean	13/07/2018	07:00	13/07/2018	13:20	223,093	Derriford	DE024634
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	20/08/2018	09:50	20/08/2018	14:36	231,088	Derriford	DE024867
02 Cab Ass Fire Extinguisher	Fire Extinguishers out of date, no stock						

Monitoring

Awaiting Parts

02 Cab Assembly 1	1x torch us, no stock						Awaiting Parts
02 Cab Assembly 2	Centre console catch missing, on order						Awaiting Parts
17 Tyres Replace	OSR tyres renewed						
18 Wheels Check Torques							
24 Driveshaft 1	Propshaft centre bearing starting to crack						Monitoring
55 Tail Lift	LED renewed						
71 Body External Steps	Side step straightened & roller renewed						
89 Seats	Att. seat adjuster bar refitted						
Safety Inspection							
Vehicle Deep Clean	21/08/2018	08:51	21/08/2018	14:00	231,090	Derriford	DE024878
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	22/08/2018	07:20	22/08/2018	07:23	231,090	Derriford	DE024888
02 Cab Assembly 2	Centre console catch renewed						
Breakdown	16/09/2018	08:05	16/09/2018	11:40	236,159	Derriford	DE025024
17 Tyres Replace	O/s/f tyre replaced by ATS						
Breakdown	O/S F low pressure						
Breakdown	16/09/2018	10:10	16/09/2018	11:40	236,159	Derriford	DE025025
17 Tyres Replace	O/s/r tyre replaced by ATS						
Breakdown	O/S rear below limit						
SAFETY INSPECTION	02/10/2018	08:19	03/10/2018	11:01	239,155	Derriford	DE025141
02 Cab Ass Fire Extinguisher	Fire Extinguishers out of date, Changed						
02 Cab Assembly 1	1x torch us,Changed						
16 Suspension 1	slight play front lower ball joints						Monitoring
18 Wheels Check Torques							
24 Driveshaft 1	Propshaft centre bearing starting to crack						Monitoring
55 Ramp	decals peeling						Monitoring
85 Body Interior 1	cupboard shuts loose,Repaired						
86 Door Seals	o/s/f split,Renewed						
89 Seats	swivel seat pins loose,Tightened						

Safety Inspection
93 - D Service
Service D

Vehicle Deep Clean	03/10/2018	12:00	04/10/2018	09:37	239,155	Derriford	DE025157
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	11/10/2018	11:00	11/10/2018	11:23	240,214	Derriford	DE025215
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Windscreen Wipers	Replaced wiper blades
----------------------	-----------------------

SAFETY INSPECTION	14/11/2018	08:49	16/11/2018	07:43	246,971	Derriford	DE025452
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Cab Assembly 1	Cab light bulb renewed, centre console ram secured, both armrests secured	
13 Brakes 1	Renewed front discs & pads, & rear pads	
16 Suspension 1	slight play front lower ball joints	Monitoring
16 Suspension 2	Slipper pads renewed	
17 Tyres Replace	NSF tyre renewed, check camber, tracking	
18 Wheels Check Torques		
24 Driveshaft 1	Propshaft centre bearing renewed	
45 Engine 1	Reposition turbo inlet pipe	
55 Ramp	decals peeling	Monitoring
71 Body Exterior 1	Bridge plate guides secured	
85 Body Interior 1	Track cupboard door shut secured	
86 Sliding Door	Centre rollers renewed	
89 Seats	Att. seat adjuster bar refitted	
Safety Inspection		
Sealing of stretcher clamp	Sealing of stretcher clamp	
MOT Pre Test		
Tail Lift 6 Monthly Inspection	Statutory Inspection	
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by South west lifts P/O 151179620	

Vehicle Deep Clean	15/11/2018	11:30	16/11/2018	10:41	246,971	Derriford	DE025464
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	21/12/2018	20:50	21/12/2018	20:50	253,231	Derriford	DE025720
Breakdown	ns headlight blown						
SAFETY INSPECTION	27/12/2018	08:11	27/12/2018	15:15	254,642	Derriford	DE025731
16 Suspension 1	slight play front lower ball joints Servicable						
18 Wheels Check Torques							
34 Lights Bulb Replacement	Replaced n/s head light bulb						
44 Add Ad Blue	Topped up adblue						
55 Ramp	decals peeling						
71 Body Exterior 1	Replaced missing rear mudflap & Auto eject cover						
89 Seats	tighten rear swivel seat lock pin lock nut						
Camera Upgrade	Replace n/s/f Camera Done by John Coles						
Safety Inspection							
Travel Time							
MOT	Done By Mercedes of plymouth P/O 151179880						
Vehicle Deep Clean	28/12/2018	05:48	28/12/2018	13:05	254,643	Derriford	DE025740
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	08/01/2019	09:00	08/01/2019	09:52	255,300	Derriford	DE025807
01 Heating 1	Other Cab Heater blower u/s Replaced blower motor & reostat						
Breakdown	10/01/2019	05:30	10/01/2019	12:36	255,611	Derriford	DE025831
01 Heating 1	Checked vehicle for heater n/w in saloon check with reader checked unable to fau						
Breakdown	back/saloon heater not working						
Defect Repair	16/01/2019	07:13	16/01/2019	12:05	255,922	Derriford	DE025874
01 Heating 1	Saloon Heating is not working See notes						

Breakdown	31/01/2019	22:24	04/02/2019	14:40	262,256	Derriford	DE025982
34 Lights	Investigate head light n/w Repaired on job DE025997						
34 Lights Bulb Replacement	Replaced missing o/s main beam light bulb						
Breakdown	Front O/s bulb gone						
SAFETY INSPECTION	04/02/2019	06:13	05/02/2019	06:29	262,347	Derriford	DE025997
18 Wheels Check Torques							
34 Emergency Lights	os body blue damaged						
34 Lighting System	Traced fault to faulty bulb holder connection renewed os headlamp						
34 Lights	Removed and renewed os front fog lamp						
34 Lights Bulb Replacement	renewed ns body marker						
55 Ramp	decals peeling						
71 Body External Steps	straightened and repaired side step						
85 Body Interior 1	repair cupboard shuts and pcr holder						
Safety Inspection							
92 - C Service							
Service C							
Gearbox Oil & Filter Change							
Vehicle Deep Clean	05/02/2019	12:10	06/02/2019	09:34	262,349	Derriford	DE026011
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	07/02/2019	23:16	11/02/2019	06:47	262,729	Derriford	DE026034
Breakdown	MDT not plotting correctly						
Breakdown	06/03/2019	15:26	07/03/2019	07:05	262,729	Derriford	DE026205
17 Tyres Replace	Tyre replaced by ATS call out @ Saltash station						
Breakdown	BOLD CORE EXPOSED TYRE						
Unplanned Repair	07/03/2019	11:06	07/03/2019	12:36	263,531	Derriford	DE026210
17 Tyres Replace	Replaced o/s & n/s rear tyres						

BREAKDOWN	08/03/2019	11:41	08/03/2019	11:44	263,615	Launceston	LA012377
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	o/s mirror glass smashed - replaced						
------------	-------------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	20/03/2019	08:35	21/03/2019	13:18	271,130	Derriford	DE026290
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Cab Assembly 1	NS window switch renewed						
13 Brake Pads	Renewed rear pads						
16 Suspension 1	Renewed rear antiroll bar link bushes						
16 Suspension 2	Slight play in lower ball joints and nsf strut						
18 Wheels Check Torques							
24 Driveshaft 2	Propshaft centre bearing starting to perish						
34 Lights	Traced and rectified wiring issue on n/s marker						
71 Body Exterior 1	Refitted tail lift bridge plate guides						
71 Body External Steps	Renewed damaged step edge						
85 Body Interior 1	Repaired cupbord shut						
89 Seats	Attendants seat adjuster bar missing						
Safety Inspection							
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab						
UB Fire Suppression Service							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Handbrake Cable Replacement	Replace rear handbrake cables						

Vehicle Deep Clean	22/03/2019	07:00	22/03/2019	13:56	271,130	Derriford	DE026302
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	26/04/2019	13:30	26/04/2019	14:14	278,180	Derriford	DE026557
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

87 Chairs	Replace broken carry chair retaining catch & mounting bracket						
-----------	---	--	--	--	--	--	--

Vehicle Deep Clean	29/04/2019	11:31	30/04/2019	10:00	278,794	Derriford	DE026567
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	30/04/2019	09:12	01/05/2019	13:42	278,794	Derriford	DE026573
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

16 Suspension 1	Rear anti roll bar cotton reels renewed
18 Wheels Check Torques	
24 Driveshaft 1	Centre bearing renewed
34 Lighting System	OSF top body marker n/w
41 Air Intake	Pipe secured
71 Body Exterior 1	NSF bottom body corner renewed, bridge plate guide secured
86 Doors Rear	OSR door stay secured
89 Seats	Att. seat adjuster bar missing. Drivers & pass. armrests secured
Safety Inspection	
Axle Oil Change	Axle Oil Change
Pollen Filter Change	Pollen Filter Change
Fuel Filter Change	Change Fuel Filter
Air Filter Change	Air Filter Change
Tail Lift Inspection	Remove sheared bolt and renew

Defect Repair	15/05/2019	08:27	15/05/2019	08:28	278,974	Derriford	DE026666
----------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

71 Body External Steps	Free off & check operation
------------------------	----------------------------

SAFETY INSPECTION	11/06/2019	08:11	12/06/2019	08:37	286,363	Derriford	DE026855
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

16 Suspension 1	slight play front lower ball joints
18 Wheels Check Torques	
34 Lights	os marker n/w, wiring repaired
34 Lights Bulb Replacement	n/s sidelight nw
43 Exhaust System 1	Carry out dpf regen
45 Engine 1	slight oil leak
55 Ramp	re-secured tail lift bridge plate guides
71 Body External Steps	renewed step motor straighten and renewed roller
85 Body Interior 1	Renewed bio safe strap
86 Sliding Door	Re-aligned top magnet
Safety Inspection	

Vehicle Deep Clean	12/06/2019	09:00	12/06/2019	15:30	286,365	Derriford	DE026867
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	05/07/2019	06:00	05/07/2019	07:17	289,012	Derriford	DE027021
86 Doors Rear	Doors Rear door Stay come away from base, repaired door anchor point						
Unplanned Repair	09/07/2019	06:00	09/07/2019	08:34	289,456	Derriford	DE027051
03 Instruments & Sensors 1	EML lack of power read dtcs and carried out regen						
SAFETY INSPECTION	22/07/2019	10:48	23/07/2019	12:35	289,656	Derriford	DE027126
02 Cab Assembly 1	cab storage knob missing, Renewed						
02 Windscreen Wipers	washer bottle cap damaged, Renewed						
11 Axle Rear	slight oil leak						
15 Steering 1	N/S track rod end worn, Renewed						
17 Tyres Replace	o/s/f tyre worn, Renewed						
17 Tyres Tracking	Adjusted						
18 Wheels Check Torques							
24 Driveshaft 1	Propshaft centre bearing failed						
34 Lights Bulb Replacement	n/s day running light						
85 Body Interior 1	Lucas cupboard adrift, Repaired						
86 Sliding Door	top magnet not striking, Adjusted						
89 Seats	attendants seat adjuster missing						
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	23/07/2019	13:13	24/07/2019	10:53	289,657	Derriford	DE027144
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	04/09/2019	09:46	05/09/2019	09:37	293,191	Derriford	DE027397
13 Brake Pads	frnt and rears renewed						
17 Tyres Replace	rear tyres						
18 Wheels Check Torques							
34 Lighting System	renewed damaged front number plate						

86 Sliding Door
Safety Inspection
UB Fire Supp 6mts Service

SECURED AND REFITTED SIDE DOOR OUTER RAIL COVER
UB Fire Supp 6mts Service

Vehicle Deep Clean **12/09/2019** **07:53** **12/09/2019** **13:55** **293,241** **Derriford** **DE027450**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **14/09/2019** **19:32** **16/09/2019** **06:25** **294,197** **Derriford** **DE027468**

86 Door Lock
Breakdown

checked vehicle changed fob battery,still not locking find spare and swap
vehicle will not lock on fob

Vehicle Deep Clean **14/10/2019** **05:45** **14/10/2019** **09:46** **297,646** **Derriford** **DE027682**

Vehicle Deep Clean Vehicle Deep Clean

Tail Lift 12M Service & Weight **14/10/2019** **09:00** **14/10/2019** **14:55** **297,646** **Derriford** **DE027691**

Tail Lift 12M Service & Weight
Tail Lift Inspection

Tail Lift 12M Service & Weight Done by South west lifts P/O 151193186

SAFETY INSPECTION **15/10/2019** **06:12** **15/10/2019** **14:30** **297,754** **Derriford** **DE027698**

02 Cab Ass Fire Extinguisher
17 Tyres Replace
18 Wheels Check Torques
41 Air Intake
55 Ramp
55 Tail Lift
89 Seats
Safety Inspection
Engine Change Oil & Filter

swapped due to service date
N/S/F trye worn
supporting bracket broken
Bridge plate guide rails loose asdrift
decals peeling
Attendants seat adjuster bar missing

Monitoring

Unplanned Repair **17/10/2019** **08:30** **17/10/2019** **16:32** **297,793** **Derriford** **DE027725**

34 Emergency Lights N/s/r blue light knocked off See notes P/O 151193576

Breakdown	08/11/2019	16:55	11/11/2019	12:53	300,282	Derriford	DE027903
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

34 Lights Bulb Replacement	N/s headlight bulb replaced
42 Coolant System	Coolant level warning on Checked level sensor faulty replaced header tank
Breakdown	Headlight & sidelight blown

Unplanned Repair	13/11/2019	07:30	13/11/2019	14:36	300,590	Derriford	DE027927
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Cab Assembly 1	Fit methane sticker in cab
03 Instruments & Sensors 1	reset service mileage indicator
71 Body External Steps	Replaced side step switch with second hand part
85 Body Interior 1	Remove broken dressing cupboard broken shelf edging strip
87a - Medical Equipment Repair	Fit missing gromet & push cabling back into trauma wall been pulled out

Breakdown	13/11/2019	20:13	14/11/2019	07:05	300,650	Derriford	DE027934
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

55 Tail Lift	Removed tail lift deployed bracket straightened and refitted
Breakdown	tailift deployed sensor not aligned

SAFETY INSPECTION	28/11/2019	06:49	29/11/2019	13:59	302,376	Derriford	DE028029
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

01 Heating 1	Saloon heater ex. split
02 Cab Assembly 1	Torch battery renewed
16 Suspension 1	Front anti roll bar links worn
16 Suspension 2	Rear spring eye bushes worn
18 Wheels Check Torques	
34 Emergency Lights	OSR Side blue renewed
45 Engine 1	Aux belt shredding, both renewed, adjuster broken
45 Engine 2	Oil leak
55 Tail Lift	decals peeling, LED's not working, tilt switch renewed
71 Body Exterior 1	Bridge plate guides insecure
71 Body Exterior 2	NSF top body corner renewed
71 Body External Steps	Free off step
86 Doors Rear	NS door stay stiff
87 - Stretchers/Chairs/Boards	Scoop securing strap u/s, manufacture new
89 Seats	Saloon seat armrest secured
Safety Inspection	

Vehicle Deep Clean	06/12/2019	05:55	06/12/2019	10:41	302,790	Derriford	DE028086
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	08/12/2019	18:49	09/12/2019	11:17	303,001	Derriford	DE028102
31 Battery Chassis Breakdown	Check & replaced chassis battery & checked charging vehicle power - emrg start button needed						
Breakdown	14/12/2019	14:52	16/12/2019	07:08	303,746	Derriford	DE028160
31 Battery Comms 89 Seatbelts 89 Seats Breakdown	carried out battery check all ok Un tangled and un twisted saloon seat belt refitted swivel seat locating pin comms battery check						
Unplanned Repair	24/12/2019	13:15	24/12/2019	13:19	304,244	Derriford	DE028233
31 Battery Comms	battery check conducted - GOOD AND PASS						
COMMS.FAILURE CHECK	24/12/2019	13:59	24/12/2019	15:00	304,244	Derriford	DE028234
MDT Failure/Issue	Battery check ok, PCE attending						
Defect Repair	03/01/2020	06:00	03/01/2020	07:29	305,181	Derriford	DE028278
71 Body Exterior 1	Removed and straightened bonnet stay new ordered						Awaiting Parts
SAFETY INSPECTION	07/01/2020	08:24	10/01/2020	10:53	305,617	Derriford	DE028308
02 Mirrors 13 Brakes 1 16 Suspension 1	NS glass renewed Rear discs & pads renewed Rear spring pads renewed						

16 Suspension 2	Renew front lower arms						
18 Wheels Check Torques							
34 Lights	OSR orange marker renewed						
45 Engine 1	NS oil leak						
71 Body Exterior 1	Bonnet stay renewed						
71 Body Exterior 2	Bridge plate guides secured						
86 Sliding Door	Catch secured, rollers to be done						
Safety Inspection							
Travel Time							
MOT	Done by Mercedes of plymouth P/O 151195092						
Vehicle Deep Clean	10/01/2020	11:00	10/01/2020	14:35	305,723	Derriford	DE028355
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/01/2020	10:30	21/01/2020	13:02	306,129	Derriford	DE028444
86 Sliding Door	replace top door catch						
Breakdown	29/01/2020	16:56	30/01/2020	12:09	307,473	Derriford	DE028516
31 Charging System	Check charging, no alternator output, renewed						
Breakdown	NO BATTERY WORKING						
Defect Repair	12/02/2020	07:30	12/02/2020	09:00	308,573	Derriford	DE028624
03 Instruments & Sensors 1	Patient unit charge lead plug U/S. Logistics informed.						
	Awaiting Parts						
SAFETY INSPECTION	17/02/2020	06:58	18/02/2020	12:59	308,573	Derriford	DE028648
02 Cab Assembly 1	Storage unit button renewed						
03 Instruments & Sensors 1	Patient unit charge lead plug U/S. Logistics informed. Done						
03 Instruments & Sensors 2	Med Equip & Devices Manga- charging cable frayed. Renewed						
11 Axle Front	Check tracking/camber						
15 Steering 1	NS steering arm renewed						

18 Wheels Check Torques
 34 Lights Bulb Replacement NS dip bulb and holder replaced
 45 Engine 1 NS oil leak, inlet pipe seals renewed
 55 Tail Lift Adjust tilt ram
 86 Doors Rear Adjusted catches
 86 Sliding Door Centre rollers renewed, top catch cover renewed
 Safety Inspection
 Brakes Replace Brake Fluid
 Tail Lift Inspection

Vehicle Deep Clean **19/02/2020** **05:59** **19/02/2020** **12:54** **308,626** **Derriford** **DE028662**

Vehicle Deep Clean Vehicle Deep Clean

Defect Repair **25/02/2020** **07:31** **25/02/2020** **07:34** **309,010** **Derriford** **DE028702**

55 Tail Lift Deployed alarm sounding, Adjust arm stops.
 71 Body External Steps Check operation, free off side arm

Unplanned Repair **27/02/2020** **11:46** **27/02/2020** **12:17** **309,198** **Derriford** **DE028731**

71 Body External Steps Check for side step warning replaced side step rollers

Unplanned Repair **16/03/2020** **11:00** **18/03/2020** **06:35** **310,245** **Derriford** **DE028858**

02 Windows/Glass N/s/r window smashed new glass fitted by national windscreen fitted call sign

Unplanned Repair **23/03/2020** **09:30** **23/03/2020** **12:25** **311,320** **Derriford** **DE028902**

86 Sliding Door Replace broken outer door handle

Breakdown **24/03/2020** **22:57** **26/03/2020** **11:11** **311,380** **Derriford** **DE028916**

01 Air Conditioning 1 Degass & regass system
 17 Tyres Replace Replaced both front tyres
 18 Wheels Retorque
 42 Coolant System Radiator leaking

Breakdown	Coolant leak pooring out						
Wash Vehicle							
Vehicle Deep Clean	01/04/2020	08:14	01/04/2020	14:27	311,512	Derriford	DE028984
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	02/04/2020	07:23	03/04/2020	11:00	311,929	Derriford	DE028990
03 Instruments & Sensors 1	Sat nav mount broken, repaired mount						
13 Brake Pads	Front discs & pads renewed, os caliper slider freed off						
18 Wheels Check Torques							
34 Lights	OSR orange body marker wiring repaired						
43 Exhaust System 1	Tailpipe corroded/broken, renewed						
45 Engine 1	ns oil leak					Monitoring	
55 Tail Lift	LED connector cleaned						
71 Body Exterior 1	Spray supression secured						
86 Doors Rear	Bottom catch not adjusted						
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
Unplanned Repair	13/04/2020	12:30	13/04/2020	13:08	312,885	Derriford	DE029084
86 Sliding Door	Resecure side door top catch & repair micro switch lever						
Defect Repair	15/04/2020	08:03	15/04/2020	08:05	313,083	Derriford	DE029104
34 Lights Bulb Replacement	NS Main beam bulb renewed						
Breakdown	10/05/2020	16:41	11/05/2020	11:53	315,539	Derriford	DE029347
45 Engine 1	Drive belt renewed						
Breakdown	Steering wheel stuck/Alternator Light On						
Vehicle Deep Clean	13/05/2020	07:00	13/05/2020	13:07	315,692	Derriford	DE029379
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	15/05/2020	06:37	16/05/2020	14:45	315,892	Derriford	DE029398
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Cab Assembly 1	Center storage cupboard knob loose						
13 Brakes 1	o/s/f wheel binding Free off caliper						
17 Tyres Replace							
18 Wheels Check Torques							
34 Lighting System	o/s scene light n/w repaired wiring					Awaiting Parts	
43 Exhaust System 1	Straighten tailpipe bracket & replace cotton reel mount						
45 Engine 1	ns oil leak					Monitoring	
71 Body External Steps	Free off & lub						
85 Body Interior 1	Storage cupboard strap broken replaced strap						
86 Sliding Door	Side door rail trim panel loose tighten screws						
89 Seats	Swivel seat lock pins loose Tighten lock nuts Driveres seat base worn					Monitoring	
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service Drier pipes replaced by Espar P/O 151203037						
Annual Heater Service	Annual Heater Service						
Tail Lift Inspection							

ACCIDENT	20/05/2020	15:05	08/06/2020	15:59	316,089	Derriford	DE029445
-----------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

71 Body Exterior Acc Repair	O/s/r rear door been knocked off						
Breakdown	O/S Read doors ripped off / Framework						

Breakdown	12/06/2020	03:26	13/06/2020	14:53	316,410	Derriford	DE029621
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

45 Engine 1	See notes						
Breakdown	Lost power steering belt /oil leak						

Breakdown	14/06/2020	04:59	15/06/2020	14:56	316,450	Derriford	DE029637
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Mirrors	Replace n/s wide angle mirror						
85 Body Interior 1	Carry chair clamp bracket sheared off remove bracket weld up & refit					Awaiting Parts	
Breakdown	defective carry chair mechanism holder						

SAFETY INSPECTION	24/06/2020	15:30	26/06/2020	12:45	317,130	Derriford	DE029708
01 Air Conditioning 1	Air con compressor replaced by Espar P/O 151204670						
02 Cab Assembly 1	Replace missing centre storage catch button						
02 Windscreen Wipers	Replaced washer valve						
18 Wheels Check Torques							
34 Lighting System	o/s scene light n/w repaired wiring						
34 Lights	replaced o/s marker light						
45 Engine 1	ns oil leak						Monitoring
71 Body Exterior 1	Resecure tail lift sliders						
85 Body Interior 1	Resecure swivel seat lock pin						
86 Sliding Door	Resecure top magnet						
89 Seats	Swivel seat lock pins loose Tighten lock nuts Driveres seat base worn						Partially Completed
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
UB Fire Supp 12mts Service	Service of fire supression system						
UB Fire Suppression Discharge	Under Bonnet Fire Suppression Been swapped out for jactone system						
Tail Lift Inspection							
Vehicle Deep Clean	17/07/2020	07:00	17/07/2020	14:00	319,049	Derriford	DE029896
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	03/08/2020	07:00	03/08/2020	14:27	320,946	Derriford	DE029999
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	04/08/2020	12:48	04/08/2020	12:52	320,965	Derriford	DE030018
03 Instruments & Sensors 1	Investigate & clear low voltage related faults, shoreline charger on order						
SAFETY INSPECTION	05/08/2020	06:27	06/08/2020	13:33	321,090	Derriford	DE030023
15 Steering 1	Check & adjust tracking						
18 Wheels Check Torques							
27 Transmission Automatic	Pipes toG/box oil cooler not secured on chassis leg						
31 Charging System	New auto eject socket replaced by halls P/O 151206380						
42 Coolant System	Viscous fan U/S, renewed						
45 Engine 1	ns oil leak						

55 Tail Lift	LED's N/W Repaired by south west lifts P/O 151206688
71 Body Exterior 1	Bridge plate guides secured
71 Body Exterior 2	Spray supression secured
89 Seats	Swivel seat lock pins loose Tighten lock nuts Drivers seat base renewed
Safety Inspection	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card

Breakdown	15/08/2020	01:37	17/08/2020	13:07	321,090	Derriford	DE030114
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

54 Sirens	Replaced siren speaker
Breakdown	sirens not working

Breakdown	08/09/2020	18:03	09/09/2020	07:03	324,708	Derriford	DE030300
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

54 Sirens	Removed front bumper/grill removed and renewed siren driver test all ok
Breakdown	blue lights and siren not working

SAFETY INSPECTION	14/09/2020	08:54	15/09/2020	14:00	325,322	Derriford	DE030341
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Cab Ass Fire Extinguisher	Replace
02 Mirrors	NS broken repaired
11 Axle Front	Check & adjust NS tracking/camber
13 Brake Pads	Rear pads renewed
18 Wheels Check Torques	
55 Tail Lift	End plate bent, straightened
71 Body Exterior 1	Bridge plate guides secured
86 Doors	Drivers hinge pins loose, secured
Safety Inspection	
Engine Change Oil & Filter	
Tail Lift Inspection	

Breakdown	23/09/2020	19:07	24/09/2020	16:35	326,427	Derriford	DE030415
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

03 Instruments & Sensors 1	Check & clear stored fault codes
41 Air Intake	Air leak on intake replace intake pipe seals & bottom turbo hose

Breakdown	limp mode : VOR						
Vehicle Deep Clean	24/09/2020	07:00	24/09/2020	12:02	326,435	Derriford	DE030419
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/10/2020	06:48	26/10/2020	14:04	329,765	Derriford	DE030618
02 Cab Assembly 1	Centre console button renewed						
02 Windscreen Wipers	Blades renewed						
03 Instruments & Sensors 1	Update Sat Nav						
17 Tyres Replace	Front tyres renewed						
18 Wheels Check Torques							
31 Charging System	PIN MISSING ON VEH CHARGE PORT, checked ok						
34 Lighting System	Check NS scene light operation						
34 Lights Bulb Replacement	Cab light bulb renewed						
71 Body Exterior 1	Bridge plate guides secured						
71 Body External Steps	Freed off						
Safety Inspection							
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Pollen Filter Change	Pollen Filter Change						
Vehicle Deep Clean	27/10/2020	07:06	27/10/2020	12:25	329,828	Derriford	DE030629
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	02/11/2020	07:00	02/11/2020	10:20	330,357	Derriford	DE030659
31 Battery Chassis	RTeplaced chassis battery						
Tail Lift 12M Service & Weight	09/11/2020	09:11	09/11/2020	12:46	331,388	Derriford	DE030710
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight Done by South West lifts P/O 151209377						
Tail Lift Inspection							

Unplanned Repair	06/12/2020	10:30	06/12/2020	10:52	333,809	Derriford	DE030896		
86 Sliding Door	rollers failed, Removed and renewed side door roller bearings								
Breakdown	08/12/2020	16:41	10/12/2020	08:55	334,142	Derriford	DE030926		
15 Steering 1 Breakdown	power steering failed Power steering failure								
SAFETY INSPECTION	09/12/2020	09:45	11/12/2020	13:03	334,142	Derriford	DE030933		
02 Cab Assembly 1	storage knob renewed								
02 Cab Assembly 2	Tool box cover renewed and cab light bulb replaced								
02 Windscreen Wipers	Blades renewed, White check valve broken renewed								
13 Brake Pads	front pads Renewed								
15 Steering 1	os track rod end renewed & tracking								
18 Wheels Check Torques									
34 Emergency Lights	n/s blue corner lens renewed								
34 Lights Bulb Replacement	o/s sidelight, both drl bulbs, Renewed								
85 Body Interior 2	Removed linen cupboard shelf edge due to sharp edge								
85 Body Interior 3	renewed infection control cupboard rams								
Safety Inspection									
Travel Time	Take to mercedes								
MOT	Done by Mercedes P/O 151208163								
unplanned repair	18/12/2020	13:00	24/12/2020	13:27	334,754	Dorchester	DC023933		
02 Mirrors	secure drivers morror								
11 Axle Rear	wheel bearing n/s and o/s damaged								
13 Brake Pads	rears low								
13 Handbrake	Handbrake shoes breaking up								
15 Steering 1	Steering rack leaking from top seal,					Monitoring			
17 Tyres	Rears low								
34 Lights	osf white marker 50%/ n/s marker light out								
44 Add Ad Blue	top up								
45 Engine Oil Top Up	top up								
54 Warn Dev/System	genesis panel buttons sticking								
71 Body Exterior 1	fit new call sign stickers								
71 Body External Steps	side step sticking								
86 Door Lock	Lock set required								

travel time

Vehicle Deep Clean	14/12/2020	07:15	14/12/2020	13:33	334,408	Derriford	DE030962
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	31/12/2020	09:13	31/12/2020	14:57	334,754	Dorchester	DC024004
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

15 Steering 1	top up reservoir	
18 Wheels Check Torques		
34 Lights	small crack in NS headlight lens	Monitoring
45 Engine Oil Top Up	top up	
54 Sirens	genesis siren button sticking	
87 - Stretchers/Chairs/Boards	stretcher, chair and track inspected on 21/12/2020	
Safety Inspection		
Vehicle Deep Clean	Vehicle Deep Clean	

Unplanned Repair	03/02/2021	02:00	03/02/2021	02:15	340,068	Dorchester	DC024270
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	Head light bulb replaced by Bronze
----------------------------	------------------------------------

Unplanned Repair	04/02/2021	14:15	04/02/2021	14:45	340,520	Dorchester	DC024286
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	replace OSF and rim
34 Lights Bulb Replacement	replace OS repeater

Breakdown	09/02/2021	00:38	10/02/2021	08:11	341,416	Dorchester	DC024320
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

03 Instruments & Sensors 1	service light on	
17 Tyres	n.s.f low	
18 Wheels	rim u/s	
24 Driveshaft 1	Prop damper split	Monitoring
27 Transmission Automatic	sump clamp missing	Monitoring
34 Lights	O/S/R upper stop tail light LEDS out...No parts	Monitoring
45 Engine Ad Blue	top up	
55 Tail Lift	light out	
71 Body Exterior 1	n/s upper corner panel damage/camera and light damage	

85 Body Interior 1	remove cables
85 Body Interior 2	catch cover missing catch loose
Breakdown	side step not retracting
Travel Time	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change

Vehicle Deep Clean	09/02/2021	13:24	09/02/2021	15:45	341,415	Dorchester	DC024329
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	11/02/2021	07:30	11/02/2021	08:44	341,625	Dorchester	DC024343
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	Body Exterior SIDE STEP WILL NOT SECURE
------------------------	---

Breakdown	22/03/2021	14:45	23/03/2021	11:22	348,505	Dorchester	DC024609
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Cracked windscreen
-----------	--------------------

SAFETY INSPECTION	29/03/2021	11:40	30/03/2021	12:08	349,829	Dorchester	DC024657
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	Pollen filter housing smashed	
01 Heating 1	Cab Heater U/s	
02 Cab Assembly 1	Stickers in windscreen missing	
03 Instruments & Sensors 1	Fire Supression gauge in wrong place, pipe rubbing	
03 Instruments & Sensors 2	Service light on	
03 Instruments & Sensors 3	Genysis panal cant be read, pixels not working	Monitoring
15 Steering 1	Steering rack leaking from top seal, Replaced	
18 Wheels Check Torques		
24 Driveshaft 1	Prop damper split	
27 Transmission Automatic	sump clamp missing	
34 Lights	O/S/R upper stop tail light LEDS out...No parts	Monitoring
45 Engine Ad Blue	Top Up	
85 Body Interior 1	Linen cupboard damaged	
89 Seats	Passenger seat swab u/s	
Safety Inspection		

Replace Handbrake Cables Engine Change Oil & Filter	Replace Handbrake Cables						
Vehicle Deep Clean	29/03/2021	10:00	30/03/2021	15:00	349,829	Dorchester	DC024659
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	19/04/2021	08:00	19/04/2021	08:45	353,238	Dorchester	DC024788
45 Engine 1 52 Electrical Aux	EML on.Bank 1 Nox sensor intermittent Genysis panel display faulty					Awaiting Parts Awaiting Parts	
Breakdown	02/05/2021	17:36	04/05/2021	12:27	355,386	Dorchester	DC024881
Breakdown	ramp operates only when engine on; MDT power						
Unplanned Repair	05/05/2021	13:30	05/05/2021	14:05	356,014	Dorchester	DC024906
02 Mirrors	NS mirror damaged						
Unplanned Repair	10/05/2021	22:00	10/05/2021	22:15	356,707	Dorchester	DC024948
34 Lights Bulb Replacement	Headlamp bulb replaced by Bronze						
SAFETY INSPECTION	11/05/2021	09:51	12/05/2021	13:37	356,762	Dorchester	DC024952
02 Windscreen Wipers 03 Instruments & Sensors 3 13 Brake Pads 13 Calipers 18 Wheels Check Torques 34 Lights 44 Add Ad Blue 45 Engine 1 45 Engine Oil Top Up 52 Electrical Aux Safety Inspection	Replace Genysis panal cant be read, pixels not working Pads worn Sliders siezed O/S/R upper stop tail light LEDS out...No parts EML on.Bank 1 Nox sensor intermittent Genysis panel display faulty						

Tail Lift Inspection

Vehicle Deep Clean	12/05/2021	14:15	13/05/2021	12:57	356,762	Dorchester	DC024975
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	15/06/2021	07:44	15/06/2021	13:24	362,437	Dorchester	DC025232
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	EML/LOP.See notes
-------------	-------------------

Breakdown	15/06/2021	20:58	17/06/2021	12:00	362,493	Dorchester	DC025236
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

41 Air Intake Breakdown	MAF sensor faulty.See notes Limp Mode Not Going Over 15 mph
----------------------------	--

BREAKDOWN	19/06/2021	08:40	21/06/2021	13:57	362,810	Dorchester	DC025267
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	Reas low
16 Suspension 1	ARB links worn
16 Suspension 2	Slipper pads worn
17 Tyres	2x low
34 Lighting System	N/S taillight leds out/O/S Top fend off Leds out
34 Lights	O/S rear marker inop
45 Engine 1	LOP.See notes
45 Engine Ad Blue	Top Up
52 Electrical Aux	CCTV faulty
71 Body Exterior 1	Rear Flap loose
86 Sliding Door	magnet bent/ catch cover loose
89 Seatbelts	Front attenadant seat buckle u/s
89 Seats	Attendant arm rest inop
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service
18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 12mts Service	Service of fire supression system

Vehicle Deep Clean	21/06/2021	14:30	22/06/2021	11:22	362,845	Dorchester	DC025288
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	24/06/2021	14:23	25/06/2021	10:48	362,845	Dorchester	DC025322
45 Engine 1	LOP/ DPF blocked						
BREAKDOWN	29/06/2021	14:00	01/07/2021	13:20	363,126	Dorchester	DC025356
45 Engine 1	LOP.See notes						
Breakdown	24/07/2021	19:28	26/07/2021	09:23	366,353	Dorchester	DC025528
Breakdown	Not selecting gears & Power failure.See notes						
SAFETY INSPECTION	02/08/2021	11:07	02/08/2021	15:00	367,049	Dorchester	DC025594
02 Cab Ass Fire Extinguisher	out of date 2x						
17 Tyres	3x tyres replace						
18 Wheels Check Torques							
45 Engine Ad Blue	top up						
52 Electrical Aux	CCTV fault light on						
55 Tail Lift	Tilt sensor inop						
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	03/08/2021	09:00	03/08/2021	13:00	367,059	Dorchester	DC025599
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/09/2021	08:01	13/09/2021	14:48	373,035	Dorchester	DC025899
02 Windscreen Wipers							
18 Wheels Check Torques							
34 Lights Bulb Replacement	Both DLR and front side lights inop						
44 Add Ad Blue							
44 Fuel System 1	Fuel Angel missing,replace						

45 Engine Oil Top Up							
86 Doors Rear							
Safety Inspection							
UB Fire Supp 6mts Service							
o/s/r door stay snapped							
UB Fire Supp 6mts Service							
Vehicle Deep Clean	15/09/2021	09:42	15/09/2021	15:00	373,035	Dorchester	DC025931
Vehicle Deep Clean							
Unplanned Repair	12/10/2021	12:30	12/10/2021	13:00	377,608	Dorchester	DC026119
31 Battery Aux							
Reported faulty							
Breakdown	12/10/2021	16:25	13/10/2021	08:30	377,635	Dorchester	DC026124
Breakdown							
side door warning sounding. Carry out repairs							
Unplanned Repair	18/10/2021	12:55	18/10/2021	13:10	378,299	Dorchester	DC026166
02 Windscreen Wipers							
Washers inop,clean out blocked filter							
Vehicle Deep Clean	25/10/2021	13:32	26/10/2021	08:56	379,392	Dorchester	DC026209
Vehicle Deep Clean							
Vehicle Deep Clean							
SAFETY INSPECTION	26/10/2021	09:11	27/10/2021	08:08	379,399	Dorchester	DC026216
02 Cab Assembly 1							
Interior light inop							
18 Wheels Check Torques							
Crazing in n/s headlamp							
34 Lighting System							
Awaiting Parts							
44 Add Ad Blue							
Safety Inspection							
Engine Change Oil & Filter							
Tail Lift Inspection							
Fuel Filter Change							
Change Fuel Filter							
Air Filter Change							
Air Filter Change							
Pollen Filter Change							
Pollen Filter Change							

Unplanned Repair	18/11/2021	10:00	18/11/2021	10:30	382,215	Dorchester	DC026383
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

55 Tail Lift	Roller missing from tail lift
--------------	-------------------------------

Breakdown	25/11/2021	15:01	30/12/2021	15:15	383,226	Dorchester	DC026447
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	NS window switch damaged
11 Axle Rear	NS hub leaking
13 Brake Pads	all pads low
13 Calipers	replace both rear caliper carriers, seized
13 Discs	front discs worn
16 Suspension 1	rear ARB link upper bushes worn
24 Driveshaft 1	front prop centre bearing split
34 Lights	replace NS headlight
41 Air Intake	replace MAF and O2, sensor and pressure sensor
41 Turbo	Turbo failed
43 Exhaust System 1	DPF cracked, replace
43 Exhaust System 2	CAT blocked
44 Add Ad Blue	top up
45 Engine 1	change engine oil and filter
45 Engine 2	ns mount split
55 Tail Lift	hydraulic pump bent on bracket, valve damaged
71 Body Exterior 1	rear mud flap loose
85 Body Interior 1	stretcher guide buffer damaged
89 Seatbelts	refit attendants seatbelt
89 Seats	swap out seat, back adjuster seized
Breakdown	Engine Limp mode No power
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
18 Wheels Check Torques	
Safety Inspection	
MOT	

Vehicle Deep Clean	31/12/2021	09:00	31/12/2021	16:00	383,248	Dorchester	DC026723
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	20/01/2022	13:20	21/01/2022	12:33	385,514	Dorchester	DC026890
01 Air Conditioning 1	condenser starting to corrode					Monitoring	
02 Mirrors	NS mirror frame damaged						
13 Handbrake	adjust						
15 Steering 1	top up						
18 Wheels Check Torques							
34 Lighting System	Crazing in n/s headlamp, previously replaced						
44 Add Ad Blue	top up						
45 Engine 1	EML on replace EGR valve						
45 Engine Oil Top Up	top up						
55 Tail Lift	magnet bracket rotted, light constantly flashing, tilt switch required, NO PARTS						
71 Body Exterior 1	OS light pod damaged temp repair						
85 Body Interior 1	bag cupboard strap damaged NO PARTS						
85 Body Interior 2	stretcher battery missing						
86 Door Lock	rear door barrel seized						
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	21/01/2022	17:14	22/01/2022	13:33	385,543	Dorchester	DC026905
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	27/02/2022	10:40	28/02/2022	08:30	390,862	Dorchester	DC027143
Breakdown	graffiti on near & side light out						
Unplanned Repair	28/02/2022	11:30	28/02/2022	11:45	390,862	Dorchester	DC027148
52 Electrical Aux	Remove hard drive as requested						
SAFETY INSPECTION	03/03/2022	13:58	04/03/2022	15:15	391,246	Dorchester	DC027174
18 Wheels Check Torques						Monitoring	
Safety Inspection							
01 Air Conditioning 1	condenser starting to corrode						
Brake Fluid Change	Brake Fluid Change						
Wheel Hub Flanges Replaceme							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						

Travel Time		
03 Instruments & Sensors 1	EML on	
85 Body Interior 1	Cab locker damaged	
44 Add Ad Blue		
45 Engine Oil Top Up		
34 Emergency Lights	N/S/R scene light cracked. N/S/F blue lens corner cracked off	Monitoring
17 Tyres Replace	o/s/f worn,replace	
31 Battery Chassis	Failed	

Vehicle Deep Clean	07/03/2022	08:00	09/03/2022	14:00	391,260	Dorchester	DC027223
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

02 Pipeline Annual Inspection	07/03/2022	09:00	07/03/2022	09:30	391,260	MDT Weymouth	DW000824
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - faults
-------------------------------	--

SAFETY INSPECTION	11/04/2022	09:41	12/04/2022	13:09	395,702	Dorchester	DC027438
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	magnet bracket rotted
55 Tail Lift	Ramp/Lift/Tail Hoist Alarm sounding despite lift being stowed
31 Battery Comms	Comms Power Check Comms battery failing/MDT powering down
89 Seats	Other Drivers seat movement restricted/uncomfortable
01 Air Conditioning 1	condenser starting to corrode
34 Emergency Lights	N/S/F blue lens corner cracked off
34 Emergency Light System	NSR scene light cracked
43 Exhaust System 1	EML on DPF blocked
34 Lights	airport light not working
86 Doors Rear	barrel seized
45 Engine Oil Top Up	top up
85 Body Interior 1	bag cupboard strap damaged
86 Sliding Door	top magnet bracket bent
15 Steering 1	steering reservoir hose leaking
01 Air Conditioning 2	A/C compressor cable snapped
11 Axle Rear	rear axle breather split
Travel Time	

Vehicle Deep Clean	13/04/2022	08:47	13/04/2022	13:41	395,719	Dorchester	DC027457
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	28/04/2022	13:00	28/04/2022	14:10	397,293	Dorchester	DC027586
17 Tyres Replace 03 Instruments & Sensors 1	Puncture n/s/f ESP light flashing.						
Unplanned Repair	16/05/2022	14:00	16/05/2022	14:41	399,981	Dorchester	DC027671
45 Engine Oil Top Up							
SAFETY INSPECTION	25/05/2022	09:31	27/05/2022	14:44	401,365	Dorchester	DC027737
18 Wheels Check Torques Safety Inspection 03 Instruments & Sensors 1 45 Engine Oil Top Up 44 Add Ad Blue 17 Tyres Replace 31 Battery Chassis	EML on Rear tyres worn Failed,replace						
BREAKDOWN	30/05/2022	10:00	31/05/2022	11:47	401,372	Dorchester	DC027771
27 Transmission Automatic	Gearbox jammed in gear.Gear lever ECU failed						
Vehicle Deep Clean	31/05/2022	14:00	01/06/2022	11:41	401,385	Dorchester	DC027783
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	06/06/2022	10:40	06/06/2022	15:23	402,533	Dorchester	DC027811
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown 31 Battery Comms	defective AUX battery/keeps powering down battery flat						
-------------------------------	---	--	--	--	--	--	--

Breakdown	08/06/2022	16:33	09/06/2022	07:32	402,955	Dorchester	DC027844
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	O/S rear Outer						
-----------	----------------	--	--	--	--	--	--

SAFETY INSPECTION	06/07/2022	09:30	07/07/2022	08:50	406,667	Dorchester	DC028037
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
UB Fire Supp 12mts Service	Service of fire suppression system						
Engine Change Oil & Filter							
Tail Lift Inspection							
89 Seats	drivers seat not going back enough						
86 Doors Rear	barrel seized and top lock sticking						
85 Body Interior 1	bag cupboard strap broken						
02 Cab Ass Fire Extinguisher	both OOD						
44 Add Ad Blue	top up						
45 Engine 1	to book filter						
13 Brake Pads	rears low						
24 Driveshaft 1	front prop centre bearing starting to crack						
13 Handbrake	adjust						
55 Tail Lift	LEDs not working, replace tilt switch						
01 Heating 1	night heater exhaust split, no parts temp repair						

Monitoring

Vehicle Deep Clean	07/07/2022	14:30	08/07/2022	14:30	406,667	Dorchester	DC028046
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Breakdown	16/08/2022	16:48	17/08/2022	11:24	411,078	Dorchester	DC028295
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown 13 Calipers Travel Time	Brakes Spongy both front calipers seized collect from dorchester						
---	--	--	--	--	--	--	--

SAFETY INSPECTION	30/08/2022	09:53	01/09/2022	07:32	412,732	Dorchester	DC028351
18 Wheels Check Torques							
Safety Inspection							
24 Driveshaft 1							
UB Fire Supp 6mts Service							
02 Windscreen Wipers							
45 Engine 1							
45 Engine Oil Top Up							
44 Add Ad Blue							
01 Heating 1							
55 Tail Lift							
85 Body Interior 1							
85 Body Interior 2							
86 Sliding Door							
34 Lights							
71 Body Exterior 1							
17 Tyres Replace							
Vehicle Deep Clean	01/09/2022	09:00	01/09/2022	13:42	412,752	Dorchester	DC028364
Vehicle Deep Clean							
Breakdown	26/09/2022	18:08	29/09/2022	10:51	412,768	Dorchester	DC028400
Breakdown							
Breakdown	03/10/2022	18:48	10/10/2022	10:33	412,788	Dorchester	DC028414
Breakdown							
44 Fuel System 1							
001 Recover Vehicle							

Breakdown	14/10/2022	20:59	03/11/2022	12:00	412,800	Dorchester	DC028433
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	LOP wont restart
002 Major Unit Replace Eng	Engine u/s - Rygor Westbury to repair

Breakdown	23/11/2022	18:12	24/11/2022	06:29	418,675	St Leonards	SL038211
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	faulty side door
-----------	------------------

SAFETY INSPECTION	16/12/2022	07:00	16/12/2022	07:00	421,623	St Leonards	SL038502
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	16/12/2022	07:00	16/12/2022	07:00	421,623	St Leonards	SL038503
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	16/12/2022	07:00	28/12/2022	11:00	421,623	St Leonards	SL038504
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
MDT Failure/Issue	Electrical Auxs MDT WIRING CHECK REQUIRED NFF
Tail Lift Inspection	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
MOT	
34 Emergency Lights	O/S Scene light partially working
34 Lighting System	O/S/R Light pod damaged and fog light u/s. Number plate lights damaged
55 Tail Lift	Stretcher stopper plate seized, tail lift bridge guides ripped off
99 Diagnostic Test	EML light on
87 Stretcher	Stryker battery u/s
16 Suspension 1	Both bottom ball joints excessive play
16 Suspension 2	Both front shocks worn out
16 Suspension 3	Rear anti roll bar linkage bushes worn
01 Air Conditioning 1	Air con leaks around saloon compressor and condensr
17 Tyres Replace	N/S/F tyre worn
34 Lights	Water in o/s/f fog bulb holder lamp and bulb burnt out
43 Exhaust System 1	Replace DPF

89 Seats	Both Arm rests Loose- Tightened						
Vehicle Deep Clean	22/12/2022	14:07	22/12/2022	14:10	421,623	St Leonards	SL038562
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	22/12/2022	14:10	22/12/2022	14:12	421,623	St Leonards	SL038563
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	22/12/2022	14:12	23/12/2022	15:00	421,623	St Leonards	SL038564
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	23/01/2023	23:41	24/01/2023	07:43	423,950	St Leonards	SL038885
Breakdown	MDT Failing To turn on						
Breakdown	06/02/2023	10:27	07/02/2023	07:00	424,901	St Leonards	SL039008
Breakdown	Mdt not powering ON					Monitoring	
Breakdown	06/02/2023	21:12	07/02/2023	07:00	424,901	St Leonards	SL039014
Breakdown	mdt keeps turning off					Monitoring	
Breakdown	18/02/2023	13:07	20/02/2023	15:30	427,084	St Leonards	SL039153
Breakdown 45 Engine 1	Engine Management Light On. investigated fault. traced to dpf temp sensor. Replace DPF temp sensor						
Breakdown	24/02/2023	21:04	25/02/2023	14:00	427,587	St Leonards	SL039207

Breakdown MDT No Power To Unit/Battery Check. OO reset MDT

Unplanned Repair **03/03/2023** **10:00** **03/03/2023** **16:28** **427,958** **St Leonards** **SL039265**

31 Battery Chassis Battery u/s
45 Engine 1 EML on.
86 Sliding Door stiff to open

02 Pipeline Annual Inspection **13/03/2023** **13:54** **13/03/2023** **13:55** **428,494** **MDT Ferndown** **TF002567**

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - No faults found.

SAFETY INSPECTION **17/05/2023** **08:00** **18/05/2023** **16:30** **436,459** **St Leonards** **SL040155**

18 Wheels Check Torques
Safety Inspection
Breakdown mdt keeps turning off. NFF
Supply Sat Nav Electrical Auxs sat nav fault - NFF
MDT Failure/Issue MDT Failure/Issue mdt failing to turn on. NFF
Tail Lift Inspection
85 Body Interior 1 Fit P clips for AVP
13 Brakes 1 Front brake Discs badly lipped pads worn low. Replaced
13 Brakes 2 Rear brake discs Badly lipped nearly worn through wear sensor. Replaced
16 Suspension 1 Rear Buffer pads torn. Replaced
17 Tyres Replace All tyres low. Replace and clean hubs
45 Engine 1 Oil leak from O/S/F of engine, cleaned off to monitor.
45 Engine 2 Oil leak from intake resonator seals.
45 Engine 3 EML light on
02 Windscreen O/S washer jet not working. Unblock washer pump filter, replace pipe.
Pollen Filter Change Pollen Filter Change
02 Glass / Windows Window switch broken drivers door. Replaced
86 Doors Drivers door weather strip damaged. Replaced
86 Doors Rear Rear door not opening properly top latch not releasing. Repaired and adjusted.

Monitoring

Breakdown	27/05/2023	07:52	09/06/2023	13:24	436,967	St Leonards	SL040295
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	ENG MAN AMBER LIGHT LIMP MODE. carry out regen. road tested ok by crew
45 Engine 1	EML on
11 Axle Rear	Bearing nosie from rear axle. See notes. Rygor Westbury to repair

Vehicle Deep Clean	27/06/2023	11:34	27/06/2023	15:38	439,348	St Leonards	SL040749
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	28/06/2023	06:30	29/06/2023	12:09	439,348	St Leonards	SL040759
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
45 Engine 1	Oil leak from O/S/F of engine, cleaned off to monitor.
56 Radio	MDT Failure/Issue mdt not powering on
56 Comms Power Failure	MDT Failure/Issue INTERMITTENTLY KEEPS LOOSING CHARGE
13 Brakes 1	Brakes grinding noise from brakes
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Tail Lift Inspection	
Engine Change Oil & Filter	Done.
45 Engine 2	EML on. CAT temp sensor.
01 Air Conditioning 1	Air con inop
Air Filter Change	Air Filter Change
13 Handbrake	Cable adjuster siezed. Replaced.
86 Door Lock	Rear door lock barrel n/w.Removed freed,lubed refitted.
86 Sliding Door	Difficult to open. Replaced centre hinge and adjusted locks and cables.
02 Cab Ass Fire Extinguisher	Out of date x2. Replaced x2.
89 Seats	Drivers seat base cover torn. Replaced cover & foam.

Breakdown	01/07/2023	07:33	01/07/2023	13:09	439,400	St Leonards	SL040810
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	oxygen alarm
-----------	--------------

Breakdown	01/07/2023	07:50	01/07/2023	13:09	439,489	St Leonards	SL040811
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	NSRO
-----------	------

Vehicle Deep Clean	02/07/2023	09:09	02/07/2023	10:00	439,489	St Leonards	SL040818
Vehicle Deep Clean	Vehicle Deep Clean						
ACCIDENT	10/07/2023	18:23	11/07/2023	10:00	441,471	St Leonards	SL040988
Breakdown	Side Step Damaged In Accident freed off chain straightened frame & lubed						
Breakdown	16/07/2023	17:34	17/07/2023	06:28	442,037	St Leonards	SL041081
Breakdown	Bottom latch of the rear doors not working						
Breakdown	16/07/2023	17:38	17/07/2023	13:00	442,037	St Leonards	SL041082
Breakdown	Fans not working in the cab. Blower motor u/s. Replaced.						
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
86 Doors Rear	Rear door not staying shut. Replace latch and adjust cables.						
71 Body External Steps	Sidestep not fully deploying.						
Breakdown	23/07/2023	04:54	24/07/2023	06:30	442,933	St Leonards	SL041214
Breakdown	side step mechanism noisy and partially out						
71 Body External Steps	Side step u/s. (see notes)						
001 Recover Vehicle	Vehicle Recovery - Arranged by OSD from Weymouth						
Unplanned Repair	26/07/2023	06:00	26/07/2023	09:00	443,082	St Leonards	SL041264
86 Sliding Door	Side door handle snapped off						
71 Body Exterior 1	Replace damaged front number plate						
Vehicle Deep Clean	07/08/2023	07:00	07/08/2023	12:30	443,865	St Leonards	SL041425
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	08/08/2023	07:00	09/08/2023	16:00	443,865	St Leonards	SL041443
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
56 Comms Equipment	MDT Failure/Issue mdt blank screen
71 Body External Steps	Other Side step not withdrawing when door is shut
Tail Lift Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Fuel Filter Change	Change Fuel Filter
Replace Handbrake Cables	Replace Handbrake Cables
34 Lights	Replace 2x side repeater lamps
87 - Stretchers/Chairs/Boards	Stretcher belts missing from main cott frame.
43 Exhaust System 1	Exhaust tail pipe insecure.
Tail Lift Annual Service	Tail lift L.E.D. not working.
71 Body Exterior 1	Rear mudflap, spray suppression wing insecure.
16 Suspension 1	Rear shock absorber.
45 Engine 1	Slight oil leak underside of engine.
Pollen Filter Change	Pollen Filter Change
55 Tail Lift	Tail lift side rails loose.
43 Exhaust System 2	DPF Top bolt snapped & bracket insecure.
86 Sliding Door	N/S Side door upper magnet check strap bent.
85 Body Interior 1	Saloon seat N/S/F arm rests loose.
02 Windscreen Wipers	Windscreen wiper blades worn.
85 Body Interior 2	N/S/R Locker bag straps broken.
45 Engine 2	Fan belt perished & snapped.
45 Engine 3	Front AC tensioner leaking excessively & snapped.
Tail Lift 6 Monthly Inspection	Tail lift hand pump controls excessively seized.
13 Brake Test	Carry out brake test.

Breakdown	10/08/2023	07:11	10/08/2023	15:00	443,982	St Leonards	SL041470
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Blue light above door knocked off	Monitoring
-----------	-----------------------------------	------------

Unplanned Repair	15/08/2023	07:00	15/08/2023	07:15	444,464	St Leonards	SL041533
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Emergency Lights	Lighting System n/s Blue light damage above side door - Re fit, ok.
---------------------	---

Breakdown	06/09/2023	00:25	07/09/2023	06:57	446,334	St Leonards	SL041839
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown 15 Steering 1	Clutch burning and fault with power steering Checked and topped fluid.. Road tested.						
BREAKDOWN	09/09/2023	06:30	09/09/2023	12:39	446,356	St Leonards	SL041879
03 Instruments & Sensors 1	AdBlue warning light on dash, rectify & take to Bournemouth station as spare.						
Vehicle Deep Clean	15/09/2023	08:43	15/09/2023	14:28	446,356	St Leonards	SL041946
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/09/2023	06:13	19/09/2023	18:00	446,356	St Leonards	SL041988
18 Wheels Check Torques							
Safety Inspection							
Breakdown	Blue light above door knocked off						
56 Comms Equipment	Comms Power Check MDT keeps turning off						
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
UB Fire Supp 12mts Service	Service of fire supression system						
Tail Lift Inspection							
Recall Notification	Merc Air Bag Recall						
02 Cab Assembly 1	footplate damage/floor mats to fit						
85 Body Interior 1	clock damaged						
02 Windscreen Wipers	blades/washer u/s						
Pollen Filter Change	Pollen Filter Change						
86 Doors	large magnet u/s						
45 Engine 1	Engine damp of oil on front of engine						
71 Body Exterior 1	Siren surround damaged						
71 Body Exterior 2	Rear flap loose.						
Vehicle Deep Clean	30/10/2023	11:30	30/10/2023	16:00	451,247	St Leonards	SL042560
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	31/10/2023	13:00	02/11/2023	13:47	451,247	St Leonards	SL042584

18 Wheels Check Torques	
Safety Inspection	
34 Emergency Lights	O/S Side blue light damaged. replaced
13 Handbrake	Excess travel. adjusted cable and shoes.
Tail Lift Inspection	Adjusted rams and lift frame stops. - resecured bridge plate guides to body.
45 Engine 2	O/S Engine mount split. replaced engine mount.
13 Brakes 1	Telma box water ingress. replaced box and both earth wires.
16 Suspension 1	Rear spring buffers x2 split. replaced
85 Body Interior 1	240v lights cracked. replaced - underseat locker door resecured.
34 Lights	nsr upper indicator led's out. replaced light.
71 Body Exterior 1	os camera cover damaged. replaced. -os fog cover missing. replaced

Unplanned Repair	27/11/2023	14:45	27/11/2023	17:00	452,282	St Leonards	SL042951
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Charging System	Battery/Charging Sys Red battery flash alternator fault
--------------------	---

Unplanned Repair	01/12/2023	15:30	02/12/2023	09:00	452,422	St Leonards	SL043019
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

01 Heating 1	Saloon heater inop
52 Electrical Aux	Zoll not charging

Vehicle Deep Clean	11/12/2023	06:00	11/12/2023	14:30	452,827	St Leonards	SL043140
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	12/12/2023	14:00	14/12/2023	16:03	452,827	St Leonards	SL043167
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques		
Safety Inspection		
Tail Lift Inspection		
MOT		
45 Engine 1	Engine oil leak from front of engine, Washed off	Monitoring
55 Tail Lift	Tail lift sump corroding pipesd also slight corrosion	Monitoring

Unplanned Repair	24/12/2023	08:30	25/12/2023	09:54	453,869	St Leonards	SL043304
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	Fan belt squeel
-------------	-----------------

56 Comms Power Failure Power failing

Breakdown 02/01/2024 12:20 02/01/2024 14:46 454,954 St Leonards SL043425

Breakdown Side door wont open
86 Sliding Door Side door top catch adrift. Resecured top latch and adjusted cables.new cover

SAFETY INSPECTION 22/01/2024 07:00 24/01/2024 16:00 457,446 St Leonards SL043668

18 Wheels Check Torques
Safety Inspection
45 Engine 1 Engine oil leak from front of engine, Washed off
55 Tail Lift Tail lift sump corroding pipesd also slight corrosion
01 Air Conditioning 1 A/C System Saloon NO HEATING IN SALON
Tail Lift Annual Service Statutory Inspection and Weight Test
13 Handbrake Cab hand brake travel becomming excessive
34 Lighting System O/S/F Side repeater bulb not working
86 Door handle N/S Side door not opening from inside
86 Sliding Door N/S Side door upper magnet check strap bent
85 Body Interior 1 Saloon locker 'BH1' shelf trim broken
Check Ferno Carry Chair StrapsCarry chair strap snapped
87 Stretcher Stretcgher belts in wrong places
01 Air Conditioning 2 Air conditioning compressor pulley loose & leaking gas / oil
Heater Service Saloon heater not working
03 Instruments & Sensors 1 E.M.L. Illuminated on dashboard display system
Tail Lift Inspection Tail lift main frame upper bushes have excessive play
13 Brake Test Carry out brake test

Vehicle Deep Clean 24/01/2024 09:51 25/01/2024 07:55 457,456 St Leonards SL043706

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 29/01/2024 11:00 29/01/2024 11:44 457,806 St Leonards SL043767

Breakdown 1cm splintering chip in drivers vision

Unplanned Repair	31/01/2024	07:00	01/02/2024	13:00	457,903	St Leonards	SL043790
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1 15 Steering 1 02 Windscreen	Engine oil leak Power steering heavy Chip in windscreen - National windscreens to repair
---	--

Unplanned Repair	22/02/2024	06:00	22/02/2024	10:00	459,559	St Leonards	SL044091
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1 Road Test	Lack of power and buring smell - NFF
--------------------------	--------------------------------------

Vehicle Deep Clean	06/03/2024	15:11	07/03/2024	11:34	460,686	St Leonards	SL044287
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	08/03/2024	08:00	12/03/2024	12:00	460,686	St Leonards	SL044314
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques Safety Inspection Tail Lift Inspection 89 Seatbelts 13 Handbrake 34 Lights 41 Air Intake 16 Suspension 1 19 Chassis 1 13 Brake Pads 34 Emergency Lights 85 Body Interior 1 02 Cab Assembly 1 55 Tail Lift 86 Door Lock 86 Sliding Door 85 Body Interior 2 44 Fuel System 1	Toe flap not straight. straightened and adjusted. Drivers seatbelt frayed. replaced belt. Adjusted handbrake cables. NSF Fog light damaged. replaced Gearbox pipes rubbed hole through intercooler. replaced intercooler. Rear anti roll bar drop link bushes worn. replaced bushes. Mudflap insecure. resecured. Front pads worn. discs ok. -replaced pads. O/S Alley light bulb blown. replaced Front upper blue lights insecure. resecured. Cab genysys panel damaged. replaced -Tail lift corroded - Tilt switch faulty - Monitor Body door lock barrells seized. replaced lock set. Sliding door lower magnet pulled out . replaced. Underseat locker door insecure. resecured Fuel hoses from engine to body pipes leaking fuel. replaced hoses. & clean.	Monitoring
---	--	------------

02 Pipeline Annual Inspection	08/03/2024	13:10	08/03/2024	13:13	460,686	MDT Ferndown	TF003310
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found.
-------------------------------	--

Med Devices Recall Upgrade - swap old obsolete compressor for Airflo 24 and charger bracket

Breakdown **24/03/2024** **12:37** **24/03/2024** **14:21** **462,116** **St Leonards** **SL044564**

Breakdown faulty turbo

ACCIDENT **28/03/2024** **09:52** **05/04/2024** **07:00** **462,391** **St Leonards** **SL044636**

Breakdown Vehicle has gone through flood water, won't start.
002 Major Unit Replace Eng Replaced Engine.

BREAKDOWN **11/04/2024** **15:45** **16/04/2024** **16:51** **462,786** **St Leonards** **SL044854**

13 Brakes 1 ABS warning light on - Faulty O/S/F sensor Monitoring

Unplanned Repair **08/04/2024** **09:30** **08/04/2024** **11:30** **462,444** **St Leonards** **SL044882**

71 Body External Steps Side step inop - Repair wiring and replace blown fuse

Vehicle Deep Clean **16/04/2024** **14:32** **17/04/2024** **09:00** **462,812** **St Leonards** **SL044929**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **19/04/2024** **06:00** **19/04/2024** **15:09** **462,812** **St Leonards** **SL044964**

18 Wheels Check Torques Checked.
Safety Inspection Carried ot inspection.
55 Tail Lift -Tail lift corroded - Tilt switch faulty - Replaced.
13 Brakes 1 ABS warning light on - Faulty O/S/F sensor. Replaced.
UB Fire Supp 6mts Service UB Fire Supp 6mts Service. Done.
Brake Fluid Change Brake Fluid Change. Done.
Install Saloon CCTV Camera Alarm on cctv. Checked & formatted.
18 Wheels Rear xtv's missing. Replaced x2.
71 Body Exterior 1 N/S/F top body capping holed. Replaced.

SAFETY INSPECTION	27/05/2024	18:00	29/05/2024	13:47	465,753	St Leonards	SL045509
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

34 Lights Lighting System N/S HEADLIGHT OUT done.

Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Tail Lift Inspection

Engine Change Oil & Filter Engine Fiited 3x weeks ago. Monitoring

34 Lighting System renew n\slr reflector.

34 Emergency Lights 1 x torch dull, test & renew battery,

02 Cab Ass Fire Extinguisher cab ftext date exp, replaced,

85 Body Interior 2 renewed cupboard clips, carried ou repair to roof blind., renew locker button.

86 Sliding Door not locking correctly, reset cable adjustment.

Vehicle Deep Clean	28/05/2024	17:11	29/05/2024	13:33	465,759	St Leonards	SL045518
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean

Vehicle Deep Clean

Unplanned Repair	31/05/2024	13:30	31/05/2024	14:00	465,810	St Leonards	SL045572
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Chassis

Test and replace chassis battery

Unplanned Repair	09/06/2024	12:30	09/06/2024	13:00	466,430	St Leonards	SL045694
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights

Replace o/s/r fog lamp

Unplanned Repair	26/06/2024	13:00	27/06/2024	07:32	466,440	St Leonards	SL046004
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1

EML/LOP. Fault with boost pressure sensor. replaced, cleared and road tested.

Unplanned Repair	05/07/2024	07:00	05/07/2024	08:20	467,944	St Leonards	SL046144
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Aux

Replaced

45 Engine Ad Blue

Top up

SAFETY INSPECTION	12/07/2024	11:00	15/07/2024	17:14	468,175	St Leonards	SL046262
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
Check and Fit P-Clips			Check for the presence of P-Clips and fit if not present				
52 Electrical Aux			Saloon mic near rear facing seat and 240v lights broken. - replaced both.				
55 Tail Lift			OS Tail lift platform light inop. replaced light. (corrosion on lift frames)				
86 Sliding Door			Upper latch loose. resecured latch.				
85 Body Interior 1			Rear seat base torn and front locker shelf missing.- replaced with spare parts.				
18 Wheels			4x rims u/s				
17 Tyres			N/S/F and all 4x Rears low				
13 Handbrake			Adjusted shoes and cables.				
13 Brake Pads			Rear pads worn low. discs ok - replaced pads and lubricated seized sliders.				
Tail Lift Inspection							

Vehicle Deep Clean	15/07/2024	17:55	16/07/2024	13:36	468,183	St Leonards	SL046339
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	30/07/2024	13:30	30/07/2024	13:45	468,451	St Leonards	SL046617
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	Replace o/s mirror glass
------------	--------------------------

Vehicle Deep Clean	22/08/2024	12:45	23/08/2024	11:00	469,973	St Leonards	SL046924
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	26/08/2024	06:36	26/08/2024	18:00	469,977	St Leonards	SL046972
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
13 Brake Test	Carry out brake test
86 Sliding Door	Adjust door cables as tight opening

Vehicle Deep Clean	27/09/2024	11:39	28/09/2024	07:46	474,665	St Leonards	SL047496
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	29/09/2024	10:00	01/10/2024	13:01	474,665	St Leonards	SL047522
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques Safety Inspection 56 Comms Equipment 55 Tail Lift	Comms roof aerial base damaged - OSD to arrange repair Tail lift tank damp	Monitoring
--	---	------------

Unplanned Repair	01/11/2024	08:00	01/11/2024	09:00	477,481	St Leonards	SL048050
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights 86 Sliding Door	NS Wing repeater intermittant. replaced bulb and cleaned contacts. Upper latch insecure. resecured latch and lubricated.
------------------------------	---

SAFETY INSPECTION	11/11/2024	07:00	14/11/2024	11:30	478,125	St Leonards	SL048174
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques Safety Inspection 55 Tail Lift 52 Electrical Aux 56 Comms Equipment 71 Body Exterior 1 UB Fire Supp 12mts Service Annual Heater Service Annual Air Con Service UB Fire Supp 6mts Service Tail Lift Inspection MOT Axle Oil Change 13 Handbrake 89 Seatbelts 17 Tyres Replace	Tail lift tank damp/corrosion & corrosion on frames. Airways battery charger for radios not working- Checked working ok. Aerial base has been damaged on top of DCA - Resecured and replaced aerial. Shore line port cover damaged - Replaced. -Rear lower corner caps, replaced. Service of fire suppression system Annual Heater Service Annual Air Condition Service UB Fire Supp 6mts Service Axle Oil Change Adjusted shoes and cables. Passenger seatbelt frayed. replaced belt. x3 Tyres worn and x1 wheel excessively corroded.	Monitoring
---	--	------------

13 Brakes 1	Front brake pads and discs worn. replaced kit.						
Vehicle Deep Clean	13/11/2024	09:44	13/11/2024	14:00	478,125	St Leonards	SL048208
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	28/11/2024	08:15	28/11/2024	09:00	479,474	St Leonards	SL048435
86 Sliding Door	Side door opening while driving. Adjusted upper latch and lubricated.						
Breakdown	06/12/2024	04:37	08/12/2024	07:45	480,362	St Leonards	SL048540
Breakdown	Burning smell (Rubber)INTO CAB						
Vehicle Deep Clean	23/12/2024	16:05	24/12/2024	15:39	482,064	St Leonards	SL048796
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/12/2024	06:00	27/12/2024	10:58	482,090	St Leonards	SL048838
Check MDVS for Update	Check and Install MDVS windows update. Done.						
Safety Inspection	Carried out inspection.						
18 Wheels Check Torques	Checked.						
Road Test							
55 Tail Lift	Tail lift tank damp/corrosion & corrosion on frames.See notes.					Monitoring	
56 Comms Equipment	Comms Power Check Airways radio in cab not showing phone book						
Accident	Body Exterior OSR paint damaged					Monitoring	
34 Lights	Lighting System NS headlight is out.Done.						
Pollen Filter Change	Pollen Filter Change						
01 Air Conditioning 1	Condensor fans n/w.Replaced fuse.						
02 Cab Assembly 1	Interior light n/w.						
44 Add Ad Blue	Topped 10Ltrs.						
02 Cab Assembly 2	Torch n/w. Replaced battery.						

Unplanned Repair	26/01/2025	07:42	26/01/2025	07:46	485,921	St Leonards	SL049251
02 Mirrors	N/S Mirror glass						
Vehicle Deep Clean	03/02/2025	17:05	04/02/2025	10:34	486,994	St Leonards	SL049403
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	11/02/2025	11:00	14/02/2025	16:06	486,994	St Leonards	SL049501
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 55 Tail Lift Accident 86 Sliding Door 02 Windscreen Wipers 17 Tyres Replace	Check and Install MDVS windows update Tail lift tank damp/corrosion & corrosion on frames.See notes. Body Exterior OSR paint damaged Door hinge rollers seized. Replaced Washer bottle blocked. Cleaned out Both rear inner tyres have punctures. Replaced						
						Monitoring	
Breakdown	18/02/2025	11:24	18/02/2025	13:24	487,294	St Leonards	SL049604
Breakdown	yellow triangle warning on dash						
Vehicle Deep Clean	21/03/2025	11:53	22/03/2025	08:07	489,766	St Leonards	SL050028
Vehicle Deep Clean	Vehicle Deep Clean						
02 Pipeline Annual Inspection	24/03/2025	14:02	24/03/2025	14:05	489,792	MDT Ferndown	TF004042
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - replace 1x Port seal kits.						

SAFETY INSPECTION	31/03/2025	12:00	01/04/2025	10:00	489,792	St Leonards	SL050141
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
55 Tail Lift	Tail lift tank damp/corrosion & corrosion on frames.See notes.
Tail Lift Inspection	
Air Filter Change	Air Filter Change
85 Body Int Alcohol Gel Dispen	
34 Emergency Lights	OSF wing blue light not working. Replaced with good spare
13 Brakes 1	Free of NSR brake slider and clean up hub flanges
85 Body Interior 1	Secure saloon cuboard hinges, document holder and O2 cuboard catches

Breakdown	14/04/2025	12:59	14/04/2025	14:00	491,028	St Leonards	SL050378
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Low oil levels
-----------	----------------

SAFETY INSPECTION	15/05/2025	06:00	15/05/2025	15:34	491,028	St Leonards	SL050955
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
71 Body Exterior 1	Body Exterior broken left side mirror. NFF
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test
Tail Lift Inspection	
Engine Change Oil & Filter	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
34 Lights Bulb Replacement	Both front sidelights not working. replaced
01 Air Conditioning 1	Cab AC not working. Replaced U/S compressor with spare
01 Air Conditioning 2	Test and regas system after replacement
02 Cab Ass Fire Extinguisher	Replace both extinguishers

Vehicle Deep Clean	19/05/2025	08:50	19/05/2025	14:00	491,028	St Leonards	SL051030
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	13/07/2025	09:28	13/07/2025	09:31	500,824	St Leonards	SL052030
34 Lights Bulb Replacement	N/S repeater not working						
Unplanned Repair	14/07/2025	08:00	14/07/2025	08:15	500,929	St Leonards	SL052050
45 Engine Ad Blue	Top up						
Decommission Vehicle	23/07/2025	09:52			500,929	St Leonards	SL052246