

WM64JYD	A&E		Weymouth Amb Stn				
PDI Inspection	19/03/2015	07:00	08/04/2015	08:00	99	St Leonards	SL015923
PDI Inspection	Carried out PDI ect.						
PDI Inspection	08/04/2015	08:00	22/04/2015	14:45	131	Dorchester	DC012828
PDI Inspection							
SAFETY INSPECTION	13/04/2015	07:00	13/04/2015	07:00	99	St Leonards	SL016035
18 Wheels Check Torques							
Safety Inspection	Not operational. PDI in progress.						
Vehicle Deep Clean	Not operational. PDI in progress.						
Unplanned Repair	25/04/2015	19:00	25/04/2015	19:30	479	Dorchester	DC012899
02 Cab Assembly 1	Keys locked in vehicle						
Travel Time							
Breakdown	25/04/2015	19:01	25/04/2015	19:50	496	St Leonards	SL016111
Breakdown	keys locked in saloon						
Breakdown	02/05/2015	21:24	02/05/2015	21:24	1,461	Dorchester	DC012928
Breakdown	door open alarm sounding loudly. Repair by crew.						
Unplanned Repair	05/05/2015	11:00	05/05/2015	11:47	1,635	Dorchester	DC012935
44 Add Ad Blue	add						

Breakdown	11/05/2015	20:24	11/05/2015	21:00	1,635	Dorchester	DC012954
Breakdown	LOW OIL filled by bronze cmd						
Unplanned Repair	16/05/2015	08:00	16/05/2015	08:30	1,635	Dorchester	DC012991
44 Add Ad Blue							
SAFETY INSPECTION	27/05/2015	07:57	27/05/2015	12:00	6,552	Dorchester	DC013032
18 Wheels Check Torques							
44 Add Ad Blue							
Safety Inspection							
Vehicle Deep Clean	28/05/2015	08:30	28/05/2015	14:15	6,564	Dorchester	DC013044
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/06/2015	09:55	08/06/2015	10:10	8,617	Dorchester	DC013096
44 Add Ad Blue							
Unplanned Repair	18/06/2015	13:30	18/06/2015	13:45	10,686	Dorchester	DC013154
44 Add Ad Blue							
Breakdown	21/06/2015	09:37	21/06/2015	11:37	11,321	Dorchester	DC013162
17 Tyres Replace	Carried out by ATS						
Breakdown	205/75R16C OSF nail in tyre						

Unplanned Repair	27/06/2015	06:40	27/06/2015	07:00	12,345	Dorchester	DC013196
44 Add Ad Blue	Topped up by Bronze						
Unplanned Repair	29/06/2015	07:00	29/06/2015	07:30	12,799	Dorchester	DC013193
44 Add Ad Blue							
Breakdown	05/07/2015	23:06	05/07/2015	23:59	14,332	Dorchester	DC013230
Breakdown	EML on - oil level warning on done by merc 24						
SAFETY INSPECTION	06/07/2015	08:00	06/07/2015	16:00	14,372	Dorchester	DC013233
18 Wheels Check Torques	Done.						
55 Tail Lift	Repair N/S Handrail.						
89 Seats	Repair saloon seat.						
Safety Inspection	Done.						
Vehicle Deep Clean	07/07/2015	09:00	07/07/2015	13:00	14,383	Dorchester	DC013239
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	14/07/2015	07:30	14/07/2015	08:10	15,575	Dorchester	DC013263
44 Add Ad Blue							
45 Engine Oil Top Up							
Unplanned Repair	23/07/2015	07:45	23/07/2015	08:15	17,492	Dorchester	DC013309
44 Add Ad Blue							

Breakdown	01/08/2015	14:46	01/08/2015	15:36	19,186	Dorchester	DC013360
17 Tyres Replace Breakdown	Carried out by ATS Gouge in tyre wall						
Unplanned Repair	03/08/2015	07:30	03/08/2015	08:00	19,500	Dorchester	DC013364
44 Add Ad Blue	Top up ADblue						
Unplanned Repair	15/08/2015	09:30	15/08/2015	09:45	21,870	Dorchester	DC013428
44 Add Ad Blue	Topped up by Bronze						
Unplanned Repair	13/08/2015	22:00	13/08/2015	22:15	21,503	Dorchester	DC013429
44 Add Ad Blue	Topped up by Bronze						
Breakdown	16/08/2015	08:00	16/08/2015	12:00	22,160	Dorchester	DC013425
17 Tyres Replace Breakdown Travel Time	front nearside flat tyre travel to and from						
SAFETY INSPECTION	17/08/2015	10:48	18/08/2015	14:28	22,325	Dorchester	DC013435
02 Cab Assembly 1 17 Tyres Replace 18 Wheels Check Torques 44 Add Ad Blue 85 Body Interior 1 Safety Inspection 92 - C Service Service C Tail Lift 6 Monthly Inspection	Checklist Defect Torch missing,cab light inop Top up Body Interior manger cushion detached fromcable for charger Statutory Inspection						
Vehicle Deep Clean	18/08/2015	13:00	19/08/2015	11:15	22,339	Dorchester	DC013447

Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/08/2015	08:30	20/08/2015	10:03	22,346	Dorchester	DC013454
03 Instruments & Sensors 1	Reverse camera inop.Repaired under warranty						
Unplanned Repair	25/08/2015	07:45	25/08/2015	08:00	23,161	Dorchester	DC013478
45 Engine Oil Top Up							
Unplanned Repair	01/09/2015	07:30	01/09/2015	08:00	24,482	Dorchester	DC013514
44 Add Ad Blue							
Unplanned Repair	15/09/2015	08:00	15/09/2015	09:01	26,930	Dorchester	DC013572
44 Add Ad Blue							
Unplanned Repair	24/09/2015	08:00	24/09/2015	08:30	28,671	Dorchester	DC013614
44 Add Ad Blue							
Unplanned Repair	23/09/2015	19:42	23/09/2015	20:00	28,585	Dorchester	DC013616
34 Lights Bulb Replacement	Replaced by Bronze						
SAFETY INSPECTION	29/09/2015	07:07	29/09/2015	13:00	28,671	Dorchester	DC013641
13 Brake Pads	front pads worn						
18 Wheels Check Torques							
44 Add Ad Blue							
Safety Inspection							

Vehicle Deep Clean	30/09/2015	09:00	30/09/2015	14:00	29,539	Dorchester	DC013658
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	07/10/2015	17:00	07/10/2015	19:30	30,958	Dorchester	DC013698
87 - Stretchers/Chairs/Boards Travel Time	stretcher not releasing travel to and from						
Unplanned Repair	09/10/2015	08:00	09/10/2015	08:30	31,317	Dorchester	DC013705
45 Engine Ad Blue	Top up						
Unplanned Repair	12/10/2015	21:00	12/10/2015	21:15	32,046	Dorchester	DC013722
34 Lights Bulb Replacement	Headlamp bulb replaced by Bronze						
Unplanned Repair	16/10/2015	09:40	16/10/2015	10:09	32,704	Dorchester	DC013737
45 Engine Ad Blue							
Unplanned Repair	25/10/2015	17:00	25/10/2015	17:15	34,769	Dorchester	DC013768
45 Engine Ad Blue	Topped up by Bronze						
Unplanned Repair	28/10/2015	06:15	28/10/2015	06:30	35,080	Dorchester	DC013783
45 Engine Ad Blue	Topped up by Bronze						
Unplanned Repair	02/11/2015	08:00	02/11/2015	08:47	36,450	Dorchester	DC013801
44 Add Ad Blue							

Unplanned Repair	05/11/2015	08:00	05/11/2015	08:30	37,034	Dorchester	DC013828
17 Tyres Replace	puncture						
SAFETY INSPECTION	09/11/2015	08:00	09/11/2015	13:30	37,813	Dorchester	DC013846
02 Cab Assembly 1	cab light inop						
18 Wheels Check Torques							
44 Add Ad Blue							
Safety Inspection							
Travel Time							
Vehicle Deep Clean	10/11/2015	08:00	10/11/2015	12:30	37,825	Dorchester	DC013852
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/11/2015	12:00	20/11/2015	12:30	39,725	Dorchester	DC013914
45 Engine Ad Blue	Top up						
Unplanned Repair	28/11/2015	12:00	28/11/2015	12:30	41,000	Dorchester	DC013943
45 Engine Ad Blue	Topped up by crew						
Unplanned Repair	03/12/2015	07:15	03/12/2015	07:51	42,202	Dorchester	DC013967
45 Engine Ad Blue							
45 Engine Oil Top Up							
Unplanned Repair	11/12/2015	10:45	11/12/2015	11:00	43,746	Dorchester	DC013999
44 Add Ad Blue							

Unplanned Repair	15/12/2015	08:30	15/12/2015	08:45	44,843	Dorchester	DC014016
56 Comms Equipment	Check aerals						
Breakdown	19/12/2015	08:00	19/12/2015	09:30	45,566	Dorchester	DC014042
17 Tyres Replace	Replace n/s/r tyres						
18 Wheels Check Torques							
45 Engine Ad Blue	Top up						
Breakdown	Bald trye						
Travel Time							
SAFETY INSPECTION	21/12/2015	08:17	21/12/2015	14:51	46,110	Dorchester	DC014050
13 Brake Pads	Rear pads worn,fit new						
17 Tyres Fit Winter							
18 Wheels Check Torques							
71 Body Exterior 1	Front number plate broken						
Safety Inspection							
93 - D Service							
Service D							
Vehicle Deep Clean	22/12/2015	08:30	22/12/2015	13:30	46,124	Dorchester	DC014059
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	01/01/2016	20:00	01/01/2016	20:15	47,990	Dorchester	DC014112
45 Engine Ad Blue	Topped up by Bronze						
Unplanned Repair	04/01/2016	08:00	04/01/2016	08:30	48,509	Dorchester	DC014108
45 Engine Ad Blue							

Unplanned Repair	07/01/2016	03:00	07/01/2016	03:15	49,057	Dorchester	DC014133
34 Lights Bulb Replacement	n/s headlight bulb replaced by Bronze						
Unplanned Repair	12/01/2016	14:45	12/01/2016	15:15	50,043	Dorchester	DC014163
45 Engine Ad Blue 86 Doors	Adjust rear door lock rod						
Unplanned Repair	13/01/2016	10:20	13/01/2016	10:35	50,234	Dorchester	DC014165
Check Winter Pack	Supply salt sticks						
Unplanned Repair	15/01/2016	08:18	15/01/2016	09:31	50,604	Dorchester	DC014181
03 Instruments & Sensors 1	Other Quiet warning via automated voice "low pressure"fire system						
Unplanned Repair	14/01/2016	17:30	14/01/2016	19:30	50,444	St Leonards	SL017788
34 Lights Bulb Replacement Travel Time	Replace o/s headlight bulb Travel to Bere Regis						
Unplanned Repair	20/01/2016	08:00	20/01/2016	08:30	51,636	Dorchester	DC014202
44 Add Ad Blue							
Unplanned Repair	27/01/2016	10:55	27/01/2016	11:11	52,813	Dorchester	DC014241
02 Mirrors	Replace n/s mirror glasses						
SAFETY INSPECTION	01/02/2016	08:00	03/02/2016	11:00	53,871	Dorchester	DC014259
18 Wheels Check Torques 24 Driveshaft 1	Centre bearing breaking up						

45 Engine Ad Blue
 85 Body Interior 1
 Road Test
 Safety Inspection
 MOT Pre Test
 Gearbox Oil & Filter Change
 Travel Time
 MOT

straps broken

Vehicle Deep Clean **03/02/2016** **10:00** **03/02/2016** **15:30** **53,945** **Dorchester** **DC014275**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **16/02/2016** **07:15** **16/02/2016** **07:45** **56,714** **Dorchester** **DC014333**

45 Engine Ad Blue

Unplanned Repair **24/02/2016** **13:00** **24/02/2016** **14:15** **58,731** **Dorchester** **DC014386**

45 Engine Ad Blue

Breakdown **01/03/2016** **19:55** **03/03/2016** **12:17** **60,169** **Dorchester** **DC014420**

Breakdown Engine management light intermitant
 Travel Time

Stretcher/Med Handling Repairs **02/03/2016** **08:00** **02/03/2016** **08:15** **60,169** **Dorchester** **DC014423**

87 - Stretchers/Chairs/Boards Supply missing pedimate

Unplanned Repair **07/03/2016** **01:00** **07/03/2016** **01:15** **60,982** **Dorchester** **DC014438**

45 Engine Ad Blue Topped up by Bronze

Unplanned Repair	07/03/2016	08:00	07/03/2016	08:45	61,040	Dorchester	DC014442
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue

SAFETY INSPECTION	14/03/2016	08:13	16/03/2016	07:30	62,485	Dorchester	DC014478
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

02 Mirrors	n/s mirror damaged repair with second hand parts
13 Brake Pads	front worn
13 Discs	worn
18 Wheels Check Torques	
45 Engine Ad Blue	
45 Engine Oil Top Up	
54 Sirens	Emg Warning Devices siren button on steering wheel very tempermental.
85 Body Interior 1	side locker straps broken
86 Doors	Emg Warning Devices larker door alarm keeps going off.
Safety Inspection	throw line fitted
Travel Time	
Tail Lift 6 Monthly Inspection	Statutory Inspection
UB Fire Suppression Service	
Annual Heater Service	Annual Heater Service
Tail Lift Annual Service	Statutory Inspection and Weight Test
Wheel Studs & Nuts Replaceme	
Handbrake Cable Replacement	Replace rear handbrake cables

Vehicle Deep Clean	16/03/2016	08:00	16/03/2016	15:07	62,499	Dorchester	DC014493
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	02/04/2016	15:00	02/04/2016	15:30	66,351	Dorchester	DC014565
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Topped up by Bronze
-------------------	---------------------

Unplanned Repair	11/04/2016	07:30	11/04/2016	08:00	67,851	Dorchester	DC014591
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

44 Add Ad Blue

Unplanned Repair	22/04/2016	09:20	22/04/2016	09:53	69,841	Dorchester	DC014649
45 Engine Ad Blue	Top up						
SAFETY INSPECTION	25/04/2016	07:17	27/04/2016	11:12	70,304	Dorchester	DC014658
17 Tyres Replace	all at trust limit						
18 Wheels Check Torques							
34 Lights Bulb Replacement	cab light inop						
44 Add Ad Blue							
45 Engine 1	Engine Intermittent limp mode.						
45 Engine 2	fan belt broken						
85 Body Interior 1	saloon strap broken						
Safety Inspection							
85 Body Int Alcohol Gel Dispen							
92 - C Service							
Service C							
Install Saloon CCTV Camera							
Vehicle Deep Clean	26/04/2016	12:15	27/04/2016	12:29	70,312	Dorchester	DC014668
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	28/04/2016	10:00	28/04/2016	10:30	70,494	Dorchester	DC014680
86 Door Lock	saying door open carry out adjustments						
Unplanned Repair	05/05/2016	07:00	05/05/2016	07:49	71,894	Dorchester	DC014711
02 Mirrors	o/s broken						
Unplanned Repair	17/05/2016	09:00	17/05/2016	10:00	74,761	Dorchester	DC014749
17 Tyres Replace	Replace tyre						
18 Wheels	Replace split rim						

Unplanned Repair	25/05/2016	06:00	25/05/2016	06:15	76,354	Dorchester	DC014777
34 Lights Bulb Replacement	Headlight replaced by Bronze						
Unplanned Repair	28/05/2016	08:15	28/05/2016	08:45	77,123	Dorchester	DC014802
71 Body External Steps	Side step damaged.Carry out repairs						
Breakdown	29/05/2016	08:40	29/05/2016	11:40	77,403	Dorchester	DC014797
02 Mirrors Breakdown Travel Time	Replace n/s mirror glass Stability control/ Limp mode lights on						
SAFETY INSPECTION	06/06/2016	16:08	09/06/2016	15:43	78,729	Dorchester	DC014837
01 Air Conditioning 1 02 Mirrors 18 Wheels Check Torques 34 Lights Bulb Replacement 44 Add Ad Blue Safety Inspection Travel Time Fit Throw Lines & SOP Reposition grab bag shelf	Tensioner failing. Body Exterior O/S door mirror glass smashed. n/s day running inop throw line fitted 07/06/16 lower shelf raised						
Vehicle Deep Clean	08/06/2016	08:30	08/06/2016	14:30	78,729	Dorchester	DC014849
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/06/2016	14:45	23/06/2016	15:43	81,623	Dorchester	DC014911
55 Tail Lift	Check noise and juddering.						

Unplanned Repair	05/07/2016	22:30	05/07/2016	22:45	84,247	Dorchester	DC014960
45 Engine Ad Blue	5 litres added by Bronze						
Unplanned Repair	06/07/2016	06:10	06/07/2016	06:40	84,308	Dorchester	DC014961
45 Engine Ad Blue							
Unplanned Repair	11/07/2016	11:45	11/07/2016	12:05	85,581	Dorchester	DC014990
89 Seats	Unable to release attendant seat base.Remove and lube						
Unplanned Repair	14/07/2016	07:30	14/07/2016	08:00	86,239	Dorchester	DC015009
45 Engine Oil Top Up							
SAFETY INSPECTION	19/07/2016	08:41	20/07/2016	15:39	87,521	Dorchester	DC015027
02 Cab Assembly 1	Torches inop						
02 Windscreen Wipers	Replace						
13 Brakes 1	Rear pads.discs and peda lrubbers worn,replace						
17 Tyres Replace	5 x tyres on limit						
18 Wheels Check Torques							
45 Engine Ad Blue							
55 Tail Lift	Guides ripped out.Refit						
Safety Inspection							
Travel Time							
Unplanned Repair	05/08/2016	11:30	05/08/2016	12:30	89,881	Dorchester	DC015096
34 Emergency Light System	n/s/r corner blue and airport light smashed off						
	Awaiting Parts						

Vehicle Deep Clean	10/08/2016	08:30	10/08/2016	13:00	90,639	Dorchester	DC015115
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	15/08/2016	14:00	15/08/2016	15:00	91,537	St Leonards	SL019025
44 Add Ad Blue	Add 20 L of Ad-blue.						
Breakdown	24/08/2016	22:35	25/08/2016	06:55	93,512	Dorchester	DC015194
Breakdown	os main beam u/s. Duty offi attended.						
Unplanned Repair	25/08/2016	07:30	25/08/2016	07:47	93,602	Dorchester	DC015196
34 Lights Bulb Replacement	Replace o/s headlamp bulb						
SAFETY INSPECTION	30/08/2016	08:30	01/09/2016	12:30	94,655	Dorchester	DC015221
02 Cab Assembly 1 02 Mirrors 13 Brake Pads 17 Tyres Replace 18 Wheels Check Torques 44 Fuel System 1 Safety Inspection Travel Time 93 - D Service Service D Tail Lift 6 Monthly Inspection	Interior light inop,replace bulb o/s mirror smashed Front pads worn,replace o/s/f on limit Fuel return pipe leaking.Replace Statutory Inspection						
Vehicle Deep Clean	01/09/2016	13:00	02/09/2016	11:45	94,669	Dorchester	DC015240
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	12/09/2016	07:00	12/09/2016	07:35	96,454	Dorchester	DC015294
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue

SAFETY INSPECTION	10/10/2016	08:34	14/10/2016	11:54	102,435	Dorchester	DC015443
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

16 Suspension 1	play in n/s/f shock absorber	Awaiting Warranty
18 Wheels Check Torques		
34 Emergency Light System	n/s/r corner blue and airport light smashed off	
34 Lights	no-plate light broken	
34 Lights Bulb Replacement	o/s running light	
45 Engine Ad Blue		
55 Tail Lift	Ramp/Lift/Tail Hoist Int Drop/snatch with patient on trolley.SEE NOTES	
Road Test		
Safety Inspection		
Travel Time		
UB Fire Suppression Service	replace complete system	
Annual Air Con Service	Annual Air Condition Service	
Gearbox Oil & Filter Change		
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill	

Vehicle Deep Clean	12/10/2016	11:00	13/10/2016	11:30	102,435	Dorchester	DC015460
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Travel Time	
Vehicle Deep Clean	Vehicle Deep Clean

Unplanned Repair	01/11/2016	10:00	01/11/2016	10:30	106,070	Dorchester	DC015579
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	Vibration reported by crew.o/s/f tyre replaced by ATS
------------------	---

Unplanned Repair	07/11/2016	08:00	07/11/2016	08:15	107,262	Dorchester	DC015609
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Oil Top Up
87 Stretcher Harness Replaced Pedimte missing,reported by crew

SAFETY INSPECTION	22/11/2016	12:00	25/11/2016	10:00	110,780	Dorchester	DC015682
02 Cab Assembly 1 16 Suspension 1 18 Wheels Check Torques 44 Add Ad Blue 45 Engine Oil Top Up 71 Body Exterior 1 Safety Inspection Travel Time	both window switches broken play in n/s/f shock absorber					Monitoring	
	rear mud flap missing						
Vehicle Deep Clean	25/11/2016	10:15	25/11/2016	14:00	110,851	Dorchester	DC015704
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	06/12/2016	17:30	07/12/2016	07:11	112,892	Dorchester	DC015764
34 Lights Travel Time	N/S head light and dipped beam n/w. Replaced bulbs x2. Travel to and from Dorchester station.						
Unplanned Repair	08/12/2016	07:00	08/12/2016	10:00	113,009	Dorchester	DC015769
34 Lights 86 Doors	n/s h/light inop door stay broken						
Unplanned Repair	23/12/2016	07:15	23/12/2016	08:15	116,373	Dorchester	DC015848
17 Tyres Replace	Tyres worn replace all rear tyres						
Unplanned Repair	27/12/2016	01:00	27/12/2016	01:30	117,252	Dorchester	DC015877
45 Engine Ad Blue	Topped up by Bronze						
Unplanned Repair	28/12/2016	15:30	28/12/2016	16:05	117,668	Dorchester	DC015878
34 Lights	Replace smashed indicaor light						

Unplanned Repair	30/12/2016	12:00	30/12/2016	12:30	118,079	Dorchester	DC015890
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

44 Add Ad Blue

SAFETY INSPECTION	04/01/2017	08:53	05/01/2017	09:53	119,185	Dorchester	DC015916
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	Replace rear pads
16 Suspension 1	play in n/s/f shock absorber.Repaired under warranty
18 Wheels Check Torques	
55 Tail Lift	o/s hand rail bent,straighten and tighten fixings
87 - Stretchers/Chairs/Boards	Carry chair mount bent.Remove and straighten
89 Seats	Attendent seat locking pin jammed.Free off
Safety Inspection	
92 - C Service	
Service C	
MOT Pre Test	
Medical Device and Equip Chec	Modified
Travel Time	
MOT	

Vehicle Deep Clean	05/01/2017	09:30	06/01/2017	10:28	119,207	Dorchester	DC015927
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Travel Time	
Vehicle Deep Clean	Vehicle Deep Clean

ACCIDENT	13/01/2017	12:00	13/01/2017	12:19	120,770	Dorchester	DC015976
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights	o/s/r light cluster smashed	Awaiting Parts
-----------	-----------------------------	----------------

Breakdown	15/01/2017	06:00	15/01/2017	11:48	121,055	Dorchester	DC015982
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Oil Top Up	Unable to check Engine oil. Vehicle Sent out before i could check level ?????.
Breakdown	low oil light on dash

Unplanned Repair	16/01/2017	12:15	16/01/2017	12:45	121,392	Dorchester	DC015988
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers	Top up screen wash
----------------------	--------------------

45 Engine Ad Blue	Top up						
Unplanned Repair	18/01/2017	05:00	18/01/2017	05:15	121,569	Dorchester	DC016003
34 Lights Bulb Replacement	Carried out by Bronze						
Unplanned Repair	23/01/2017	07:00	23/01/2017	08:15	122,315	Dorchester	DC016016
01 Heating 1	Body Interior SALOON HEATER NOT WORKING						
Unplanned Repair	30/01/2017	06:00	30/01/2017	06:15	123,665	Dorchester	DC016055
45 Engine Ad Blue	topped by crew						
Unplanned Repair	30/01/2017	12:40	30/01/2017	13:10	123,761	Dorchester	DC016061
87a - Medical Equipment Repair	Mangar charger broken,replace						
Unplanned Repair	01/02/2017	07:45	01/02/2017	08:14	124,147	Dorchester	DC016070
45 Engine Ad Blue							
Unplanned Repair	06/02/2017	14:15	06/02/2017	14:42	125,229	Dorchester	DC016097
86 Doors Rear	Door stay snapped,remove,repair and refit						
Unplanned Repair	09/02/2017	09:15	09/02/2017	09:32	125,607	Dorchester	DC016114
34 Lights Bulb Replacement	o/s running light inop						
Unplanned Repair	09/02/2017	13:30	09/02/2017	14:08	125,628	Dorchester	DC016119
86 Doors Rear	Unable to open from the outside unjam linkage						
Unplanned Repair	10/02/2017	07:15	10/02/2017	07:45	125,764	Dorchester	DC016123

45 Engine Ad Blue

SAFETY INSPECTION	13/02/2017	08:00	14/02/2017	10:30	126,342	Dorchester	DC016132
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	o/s/f worn						
18 Wheels Check Torques							
34 Lights	o/s/r light cluster smashed						
45 Engine Ad Blue							
86 Sliding Door	rollers seized						
Safety Inspection							

Vehicle Deep Clean	14/02/2017	09:00	14/02/2017	14:00	126,350	Dorchester	DC016136
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	22/02/2017	12:54	22/02/2017	13:58	127,885	Dorchester	DC016183
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Doors Rear	o/s door jammed.Strip down and adjust						
---------------	---------------------------------------	--	--	--	--	--	--

Unplanned Repair	09/03/2017	11:00	09/03/2017	11:30	130,474	Dorchester	DC016253
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Door handle	rear door handle jammed						
----------------	-------------------------	--	--	--	--	--	--

Breakdown	11/03/2017	20:46	11/03/2017	21:46	131,002	Dorchester	DC016264
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	n/s/f tyre replaced by ATS						
Breakdown	Bald Tyre done by ATS						

Unplanned Repair	13/03/2017	07:00	13/03/2017	07:30	131,347	Dorchester	DC016273
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

44 Add Ad Blue							
----------------	--	--	--	--	--	--	--

Unplanned Repair	13/03/2017	08:30	13/03/2017	08:49	131,353	Dorchester	DC016278
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	n/s mirror broken						
------------	-------------------	--	--	--	--	--	--

Unplanned Repair	14/03/2017	10:15	14/03/2017	11:00	131,566	Dorchester	DC016287
86 Doors Rear	Unable to open rear door from outside.Free off and repair mechanism						
Unplanned Repair	15/03/2017	07:00	15/03/2017	07:30	131,704	Dorchester	DC016292
34 Emergency Lights	grill lights inop bad connection						
Unplanned Repair	22/03/2017	07:00	22/03/2017	08:00	132,941	Dorchester	DC016317
02 Mirrors	n/s mirror broken						
Unplanned Repair	25/03/2017	02:00	25/03/2017	02:30	133,490	Dorchester	DC016335
45 Engine Ad Blue	Topped up by Bronze						
SAFETY INSPECTION	27/03/2017	09:15	28/03/2017	15:08	133,910	Dorchester	DC016336
02 Cab Assembly 1	cab light inop						
13 Brake Pads	front pads worn						
16 Suspension 1	rear anti roll bar rubbers worn						
18 Wheels Check Torques							
24 Driveshaft 1	centre bearing broken						
45 Engine Ad Blue							
Safety Inspection							
WAS Firetrace rework & Service							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Handbrake Cable Replacement	Replace rear handbrake cables						
Annual Air Con Service	Annual Air Condition Service						
UB Fire Suppression Service							
Annual Heater Service	Annual Heater Service						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	29/03/2017	09:00	29/03/2017	12:53	133,923	Dorchester	DC016356
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	09/04/2017	09:00	09/04/2017	10:00	135,977	Dorchester	DC016409
17 Tyres Replace Travel Time	Replace o/s/r inner and valve extension.Carry out retorque						
Breakdown	17/04/2017	07:43	17/04/2017	10:00	137,600	Dorchester	DC016435
17 Tyres Breakdown Travel Time	rim cracked replace tyre and rim NSF tyre low pressure travel to and from						
Unplanned Repair	21/04/2017	07:45	21/04/2017	08:00	138,137	Dorchester	DC016468
45 Engine Oil Top Up							
Unplanned Repair	29/04/2017	21:45	29/04/2017	22:00	139,609	Dorchester	DC016506
34 Lights Bulb Replacement	n/s headlight bulb replaced by Bronze						
Breakdown	07/05/2017	10:20	07/05/2017	12:00	140,998	Dorchester	DC016532
Breakdown	Smoking, leaking fluid. Mercedes 24 hours to att.Recovered to mercedes.						
SAFETY INSPECTION	17/05/2017	06:30	17/05/2017	15:00	141,100	Dorchester	DC016580
17 Tyres Replace 18 Wheels Check Torques 45 Engine Ad Blue Safety Inspection 93 - D Service Service D	n/s/r both worn						
MGS Gas Storage Modification	19/05/2017	11:45	19/05/2017	12:18	141,339	Dorchester	DC016600

MGS Gas Storage ModificationsMGS Gas Storage Modifications

Unplanned Repair	24/05/2017	09:00	24/05/2017	09:48	142,372	Dorchester	DC016618
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Ad Blue

Unplanned Repair	30/05/2017	07:00	30/05/2017	07:30	143,622	Dorchester	DC016639
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement running light

BREAKDOWN	07/06/2017	15:00	20/06/2017	09:45	145,417	Dorchester	DC016696
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

27 Transmission Automatic	Gearbox reported stuck in gear
45 Engine 1	LOP and oil leak
Travel Time	

SAFETY INSPECTION	20/06/2017	09:46	26/06/2017	12:16	145,530	Dorchester	DC016746
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	Other saloon aircon u/s.Check operation,nff
02 Windscreen	Windscreen smashed,organise replacement
13 Brake Pads	Rear pads worn,free off sliders,replace pads
13 Handbrake	Requires adjustment
17 Tyres Replace	Rear tyres worn,replaced
18 Wheels Check Torques	
45 Engine 1	Oil leak
45 Engine Ad Blue	Top up
55 Tail Lift	Guides ripped out,refit
Safety Inspection	
Travel Time	take to dealers
MGS Gas Storage Modifications	MGS Gas Storage Modifications.carried out 19/05/2017
Vehicle Deep Clean	Vehicle Deep Clean

Vehicle Deep Clean	26/06/2017	12:00	27/06/2017	13:00	145,602	Dorchester	DC016788
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/07/2017	07:30	20/07/2017	07:51	149,566	Dorchester	DC016906
45 Engine Oil Top Up							
Replace Vehicle Fuel Card	24/07/2017	06:52	24/07/2017	06:53	150,190	Dorchester	DC016941
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
SAFETY INSPECTION	01/08/2017	08:00	01/08/2017	16:00	151,686	Dorchester	DC016986
18 Wheels Check Torques 45 Engine Ad Blue Safety Inspection							
Unplanned Repair	23/08/2017	09:35	23/08/2017	10:12	155,751	Dorchester	DC017090
34 Lights	ns repeater inop,lens cracked and bulb blown,replac bulb.Order new lens						Awaiting Parts
Unplanned Repair	24/08/2017	13:05	24/08/2017	13:23	155,968	Dorchester	DC017099
34 Lights	ns repeater inop,lens cracked and bulb blown,replac bulb.Order new lens						
Unplanned Repair	04/09/2017	07:00	04/09/2017	07:50	157,921	Dorchester	DC017152
85 Body Interior 1	bottom draw rail broken						

SAFETY INSPECTION	11/09/2017	08:18	12/09/2017	11:30	158,912	Dorchester	DC017177
13 Brake Pads			Front pads worn,replace				
13 Discs			Front discs worn,replace				
16 Suspension 1			Play in front struts			Awaiting Warranty	
17 Tyres Replace			Front tyres worn				
18 Wheels Check Torques							
34 Emergency Lights			Replace smashed n/s/r upper lens				
34 Lights			o/s/f fog lamp cracked			Awaiting Parts	
45 Engine 1			Rattle from engine on start up,suspect cam chain			Awaiting Warranty	
45 Engine Ad Blue							
85 Body Interior 1			Replace extinguishers				
Safety Inspection							
Vehicle Deep Clean			Vehicle Deep Clean				
Gearbox Oil & Filter Change							
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection			Statutory Inspection				
Vehicle Deep Clean	12/09/2017	13:16	13/09/2017	11:00	158,926	Dorchester	DC017192
Vehicle Deep Clean			Vehicle Deep Clean				
Unplanned Repair	13/09/2017	09:17	21/09/2017	10:56	158,926	Dorchester	DC017214
16 Suspension 1			Play in front struts			Monitoring	
45 Engine 1			Rattle from engine on start up,suspect cam chain				
Travel Time							
Unplanned Repair	22/09/2017	13:30	22/09/2017	14:01	159,078	Dorchester	DC017252
01 Air Conditioning 1			Aircon inop,carry out checks and regas				
Unplanned Repair	04/10/2017	10:45	04/10/2017	11:34	161,323	Dorchester	DC017285
87 Stretcher			Floor clamp sticking.remove,clean and check operatriopn.Refit				

Unplanned Repair	16/10/2017	11:00	16/10/2017	11:15	163,748	Dorchester	DC017339
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

87a - Medical Equipment Repair	Replace Mangar charge unit
--------------------------------	----------------------------

Breakdown	21/10/2017	19:28	25/10/2017	13:30	164,774	Dorchester	DC017374
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

16 Suspension 1	rear spring buffers worn
17 Tyres Replace	replace all rear tyres
31 Charging System	Alternator failure
45 Engine Ad Blue	
45 Engine Oil Top Up	
Breakdown	Alt/bat charger light on [check charging alternator need replacing]
Road Test	
18 Wheels Check Torques	
Safety Inspection	

Vehicle Deep Clean	25/10/2017	13:30	26/10/2017	13:00	164,847	Dorchester	DC017396
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	09/11/2017	07:00	09/11/2017	07:32	167,294	Dorchester	DC017450
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Emergency Lights	Emg Warning Devices N/S grille blue light not working	Awaiting Warranty
34 Lights	Replace o/s/f side light bulb	

Unplanned Repair	26/11/2017	08:12	26/11/2017	08:30	170,867	Dorchester	DC017550
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	Hradlight bulb replaced by Bronze
----------------------------	-----------------------------------

SAFETY INSPECTION	04/12/2017	08:00	07/12/2017	10:00	171,975	Dorchester	DC017555
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brakes 1	Replace all R/Pads & Disc.
16 Suspension 1	Play in front struts
16 Suspension 2	Replace both F/Struts & both lower arms.
18 Wheels Check Torques	

31 Battery Chassis	Replace unit.
34 Emergency Lights	Emg Warning Devices N/S grille blue light not working
86 Doors	Replace side door lock cover panel.
Safety Inspection	
Vehicle Deep Clean	Vehicle Deep Clean
MOT Pre Test	
Travel Time	
MOT	

Unplanned Repair	11/12/2017	11:00	11/12/2017	11:15	172,636	Dorchester	DC017586
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Doors Rear	o/s/r door stay bent.Remove and straighten
---------------	--

Breakdown	26/12/2017	20:07	26/12/2017	23:00	175,719	Dorchester	DC017664
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	Step stuck in. Straightened step, now working but needs step(Bearing broken).
Breakdown	Side Step Stuck
Travel Time	Travel to and from Weymouth.

Breakdown	01/01/2018	09:36	03/01/2018	12:51	176,841	Dorchester	DC017691
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres	n./s/f tyre low
Breakdown	Handbrake gone

Breakdown	14/01/2018	21:55	18/01/2018	12:48	179,242	Dorchester	DC017759
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	o/s mirror smashed
17 Tyres	o/s/f tyre low
34 Lights	o/s/r light u/s
34 Lights Bulb Replacement	o/s drl not working
45 Engine 1	Engine Loss of power,
Breakdown	noise and smoke from engine
Travel Time	pick up from pentagons
93 - D Service	
Service D	

18 Wheels Check Torques
Safety Inspection

Vehicle Deep Clean	19/01/2018	08:00	19/01/2018	12:33	179,299	Dorchester	DC017799
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	22/01/2018	07:30	22/01/2018	08:00	179,744	Dorchester	DC017804
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	step frame bent
------------------------	-----------------

Unplanned Repair	19/02/2018	07:45	19/02/2018	08:00	184,949	Dorchester	DC017938
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	Step jammed,clean out dirt and lube
------------------------	-------------------------------------

Unplanned Repair	22/02/2018	12:00	22/02/2018	12:55	185,541	Dorchester	DC017964
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Doors Rear	Unable to open rear door.Free off linkage.Requires new barrel.WARRANTY	Awaiting Warranty
86 Sliding Door	Cental locking inop.Requires solenoid.WARRANTY	Awaiting Warranty

Unplanned Repair	26/02/2018	12:35	26/02/2018	12:54	186,435	Dorchester	DC017980
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights	drl bulb replaced
-----------	-------------------

SAFETY INSPECTION	27/02/2018	09:30	01/03/2018	11:37	186,659	Dorchester	DC017989
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	Front and rear pads low	
15 Steering 1	slight play n/s inner rack joint	Monitoring
17 Tyres	n/s/f tyre low all rear tyres low	
18 Wheels Check Torques		
45 Engine Ad Blue	top up ad blue	
85 Body Interior 1	bottom draw runner u/s	
Safety Inspection		
Travel Time	take to dorch	
85 Body Int Alcohol Gel Dispen		
Tail Lift 6 Monthly Inspection	Statutory Inspection	
Wheel Hub Flanges Replaceme		

UB Fire Suppression Service

Annual Heater Service

Annual Heater Service

Handbrake Cable Replacement Replace rear handbrake cables

Vehicle Deep Clean	01/03/2018	11:15	02/03/2018	12:30	186,672	Dorchester	DC018002
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	14/03/2018	16:20	19/03/2018	12:12	188,665	Dorchester	DC018066
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

44 Fuel System 1 Breakdown	Adblue fault.Pentagons to sort Limp mode, asking for adblu but tank full
----------------------------	---

Unplanned Repair	12/03/2018	02:00	12/03/2018	02:15	187,913	Dorchester	DC018073
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	Replace by Bronze
----------------------------	-------------------

Check Winter Pack	16/03/2018	10:00	16/03/2018	10:15	188,665	Dorchester	DC018078
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Check Winter Pack

BREAKDOWN	20/03/2018	12:15	22/03/2018	09:59	189,009	Dorchester	DC018101
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1 Travel Time	LOP,AdBlue fault back to Pentagon
-------------------------	-----------------------------------

Breakdown	02/04/2018	00:30	03/04/2018	08:00	190,824	Dorchester	DC018155
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	limp mode eml on.Spoken to crew.No issues
-----------	---

Unplanned Repair	04/04/2018	08:15	04/04/2018	08:56	191,154	Dorchester	DC018164
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

55 Tail Lift	Under ride guards ripped out.Refit
--------------	------------------------------------

Breakdown	08/04/2018	03:28	16/04/2018	12:30	191,877	Dorchester	DC018187
16 Suspension 1	rear anti roll bar links us.						
34 Lights	o/s side light n/w						
45 Engine 3	LOP						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
71 Body External Steps	step sticking						
86 Door Lock	rear door lock loose						
Breakdown	Limp mode,adblue light on but gauge full						
Annual Air Con Service	Annual Air Condition Service						
Fit Poster Holder	Fit Poster Holder						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
18 Wheels Check Torques							
Safety Inspection							

Vehicle Deep Clean	17/04/2018	10:00	17/04/2018	14:30	191,962	Dorchester	DC018235
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

Breakdown	10/05/2018	15:48	11/05/2018	10:19	196,275	Dorchester	DC018351
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown large crack in winscreen (dealt with by logistics)

Unplanned Repair	11/05/2018	15:00	11/05/2018	15:14	196,364	Dorchester	DC018357
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights o/s drl not working

SAFETY INSPECTION	21/05/2018	08:18	23/05/2018	13:11	198,051	Dorchester	DC018398
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres front tyres low/ ns has slow puncture

18 Wheels Check Torques

43 Exhaust System 1 tailpipe corroded and bent

45 Engine Ad Blue top up

71 Body Exterior 1 tail lift guides bent

71 Body External Steps step u/s

Safety Inspection

Monitoring

92 - C Service
Service C

Vehicle Deep Clean	23/05/2018	09:30	23/05/2018	12:30	198,067	Dorchester	DC018413
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	25/05/2018	13:30	25/05/2018	14:42	198,384	Dorchester	DC018436
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

52 Electrical Aux	sureline not charging
-------------------	-----------------------

Unplanned Repair	08/06/2018	09:00	08/06/2018	12:07	200,582	Dorchester	DC018496
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers	replace
----------------------	---------

Unplanned Repair	12/06/2018	15:30	12/06/2018	15:45	201,507	Dorchester	DC018516
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Ad Blue	
-------------------	--

ACCIDENT	25/06/2018	07:47	25/06/2018	09:00	203,723	Dorchester	DC018576
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	Rear step has been crushed.	Awaiting Parts
------------------------	-----------------------------	----------------

Unplanned Repair	29/06/2018	11:45	29/06/2018	12:32	203,859	Dorchester	DC018607
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Doors Rear	Unable to open o/s/r door.Check fault,adjust cable
---------------	--

SAFETY INSPECTION	02/07/2018	08:28	03/07/2018	07:21	204,441	Dorchester	DC018618
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	front rear pads low	
13 Calipers	o/s/f caliper u/s	
13 Discs	front discs worn	
15 Steering 1	slight play n/s inner rack joint	Monitoring
17 Tyres	all rear low	
18 Wheels Check Torques	torque wheels	

24 Driveshaft 1	rear prop u/s						
43 Exhaust System 1	tailpipe corroded and bent			Monitoring			
44 Add Ad Blue	top up						
45 Engine Oil Top Up	top up						
55 Tail Lift	under ride guides insecure						
71 Body External Steps	Rear step has been crushed.						
86 Doors Rear	Unable to open rear door.Free off linkage.Requires new barrel.WARRANTY						
86 Sliding Door	Cental locking inop.Requires solenoid.WARRANTY						
Safety Inspection							
Travel Time	take to dorch						
Vehicle Deep Clean	03/07/2018	09:42	03/07/2018	15:30	204,454	Dorchester	DC018630
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	06/07/2018	08:00	06/07/2018	08:48	204,705	Dorchester	DC018654
86 Door Lock	Doors rear external cupboard door unable to open						
Unplanned Repair	10/07/2018	12:30	10/07/2018	15:15	205,355	Dorchester	DC018670
02 Windscreen	Screen cracked. National windscreen to deal with at centre						
Unplanned Repair	24/07/2018	08:00	24/07/2018	08:15	207,913	Dorchester	DC018727
45 Engine Ad Blue							
Breakdown	26/07/2018	00:30	01/08/2018	13:56	208,000	Dorchester	DC018742
Breakdown	offside saloon window broken						
Unplanned Repair	09/08/2018	08:15	09/08/2018	08:50	209,475	Dorchester	DC018818
52 Electrical Aux	Both torches inop,trace fault.Replace charge sleeve and battery						

SAFETY INSPECTION	14/08/2018	07:06	15/08/2018	13:06	210,169	Dorchester	DC018842
01 Air Conditioning 1	belt and tensioner u/s						
02 Windscreen Wipers	washer bottle cap missing						
15 Steering 1	slight play n/s inner rack joint						
18 Wheels Check Torques							
34 Lights	Body Exterior orange marker light broken						
43 Exhaust System 1	tailpipe corroded and bent						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
Safety Inspection							
Gearbox Oil & Filter Change							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	16/08/2018	09:30	16/08/2018	13:30	210,182	Dorchester	DC018862
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	19/08/2018	20:30	19/08/2018	20:45	210,457	Dorchester	DC018874
34 Lights Bulb Replacement	Head light bulb replaced by Bronze						
Unplanned Repair	23/08/2018	07:30	23/08/2018	08:42	211,002	Dorchester	DC018900
86 Sliding Door	Side Door Doesnt Close Properly						
Breakdown	26/08/2018	01:09	28/08/2018	09:08	211,296	Dorchester	DC018914
Breakdown	ESP warning and severe juddering.See notes						
Unplanned Repair	29/08/2018	14:50	29/08/2018	15:38	211,463	Dorchester	DC018925
45 Engine 1	LOP reported,check with TEXA and road test.OK						
Unplanned Repair	02/09/2018	16:00	02/09/2018	16:15	211,935	Dorchester	DC018942

34 Lights Bulb Replacement Replace o/s running lamp bulb

Unplanned Repair **04/09/2018** **07:02** **04/09/2018** **07:46** **212,151** **Dorchester** **DC018959**

86 Sliding Door Opening on road

Unplanned Repair **05/09/2018** **09:30** **05/09/2018** **10:00** **212,246** **Dorchester** **DC018968**

86 Doors Locker door jammed,gain access and order parts Awaiting Parts

Unplanned Repair **12/09/2018** **13:15** **12/09/2018** **14:02** **213,199** **Dorchester** **DC019001**

45 Engine 1 LOP reported,check with TEXA.bad connection at fuel rail.Clean and road test

Unplanned Repair **14/09/2018** **08:00** **14/09/2018** **08:19** **213,403** **Dorchester** **DC019011**

02 Windscreen Wipers Washer bottle cap missing,replace

Unplanned Repair **20/09/2018** **08:15** **20/09/2018** **09:10** **214,185** **Dorchester** **DC019034**

17 Tyres n/s/f tyre low
45 Engine Oil Top Up top up

SAFETY INSPECTION **24/09/2018** **08:10** **25/09/2018** **08:41** **214,885** **Dorchester** **DC019052**

01 Air Conditioning 1 replace blocked filter
17 Tyres o/s/f slow puncture
18 Wheels Check Torques
34 Lights o/s side light n/w
45 Engine Ad Blue
52 Electrical Aux n/s torch inop
55 Tail Lift oil leak
86 Doors Locker door jammed,gain access and order parts
89 Seats n/s seat swab u/s
Safety Inspection

Vehicle Deep Clean	25/09/2018	09:26	25/09/2018	14:00	214,899	Dorchester	DC019063
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	26/09/2018	11:36	26/09/2018	15:16	215,016	Dorchester	DC019072
44 Fuel System 1 Breakdown	Replace missing mis fuel device Incorrect fuel in tank						
Unplanned Repair	25/10/2018	23:14	26/10/2018	11:12	219,087	Dorchester	DC019220
71 Body External Steps	Side step damaged and warning on constantly.Unable to repair step.Replace						
Unplanned Repair	29/10/2018	07:30	29/10/2018	07:53	219,493	Dorchester	DC019231
71 Body External Steps	Ramp/Lift/Tail Hoist side step intermit not deploying.See notes						
SAFETY INSPECTION	05/11/2018	08:15	06/11/2018	15:11	220,838	Dorchester	DC019266
13 Brake Pads	front and rear pads worn						
13 Discs	rear discs worn						
13 Handbrake	handbrake poor						
18 Wheels Check Torques							
34 Lights	headlight aim out						
45 Engine Ad Blue	top up						
71 Body External Steps	side step bent again						
85 Body Interior 1	rear handle loose						
Safety Inspection							
93 - D Service							
Service D							
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab						
MOT Pre Test							
Sealing of stretcher clamp	Sealing of stretcher clamp						
Travel Time							
MOT							

Vehicle Deep Clean	06/11/2018	11:49	07/11/2018	09:30	220,853	Dorchester	DC019277
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/11/2018	12:30	23/11/2018	13:05	223,708	Dorchester	DC019366
86 Doors	Locker door sensor going off,adjust switch and carry out road test						
Unplanned Repair	05/12/2018	11:15	05/12/2018	11:35	225,666	Dorchester	DC019426
34 Lights Bulb Replacement	n/s headlight						
Unplanned Repair	17/12/2018	07:30	17/12/2018	08:00	227,356	Dorchester	DC019492
45 Engine Ad Blue 45 Engine Oil Top Up							
Unplanned Repair	18/12/2018	08:00	18/12/2018	08:22	227,590	Dorchester	DC019498
85 Body Interior 1	Large draw jammed.Remove draw and remove equipment behind draw						
Unplanned Repair	18/12/2018	12:30	18/12/2018	13:09	227,627	Dorchester	DC019501
03 Instruments & Sensors 1	ABS,EML on,Carry out checks,unknown code logged.Clear and road test.OK						
SAFETY INSPECTION	19/12/2018	07:54	20/12/2018	08:30	227,815	Dorchester	DC019507
02 Windscreen Wipers 17 Tyres 18 Wheels 18 Wheels Check Torques 34 Emergency Lights 34 Lights Safety Inspection	washers blocked rear tyres low, ns/f tyre low Wheel nuts siezed replace set o/s grill light not working n/s drl not working						
Vehicle Deep Clean	20/12/2018	09:15	20/12/2018	13:45	227,826	Dorchester	DC019522

Travel Time							
Vehicle Deep Clean		Vehicle Deep Clean					
Unplanned Repair	27/12/2018	10:50	27/12/2018	11:07	229,116	Dorchester	DC019545
56 Comms Equipment		Body Exterior comms aerial lost - hit low hanging branch.Replace aerial					
BREAKDOWN	11/01/2019	07:45	21/01/2019	08:15	231,552	Dorchester	DC019609
41 Turbo		Fumes from turbo					
Defect Repair	21/01/2019	13:10	21/01/2019	13:11	231,605	Dorchester	DC019652
86 Doors Rear		Body Interior Rear door stay bar snapped					
ACCIDENT	24/01/2019	20:26	06/02/2019	13:00	232,104	Dorchester	DC019681
71 Body Exterior Acc Repair		Passenger folded back against wing. Temp repair to anable door to close.					
86 Doors		Doors Door bent, unable to close					
Breakdown		DOOR BENT BACKWARDS					
Travel Time		Ferndown to weymouth & Return.					
SAFETY INSPECTION	06/02/2019	13:56	08/02/2019	09:30	232,204	Dorchester	DC019755
17 Tyres Replace		o/s/f tyre on trust limit					
18 Wheels Check Torques							
34 Lighting System		o/s/r fog lamp inop,both upper marker inop.Replace					
45 Engine Ad Blue							
85 Body Interior 1		Extinguishers out of date					
Safety Inspection							
Tail Lift 6 Monthly Inspection		Statutory Inspection					
Vehicle Deep Clean	08/02/2019	09:32	08/02/2019	13:00	232,217	Dorchester	DC019765
Vehicle Deep Clean		Vehicle Deep Clean					

BREAKDOWN	13/02/2019	18:00	14/02/2019	10:30	233,133	Dorchester	DC019799
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1 Travel Time	EML on						
----------------------------	--------	--	--	--	--	--	--

Unplanned Repair	03/03/2019	07:48	04/03/2019	10:50	235,783	Dorchester	DC019876
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

31 Battery Aux	Ramp/Lift/Tail Hoist Not deploying						
31 Battery Comms	MDT Failure/Issue Not powering up.Broken wire in loom.					Partially Completed	
31 Charging System	Load shedding while driving. Checked to find not charging Comm's & Aux.						
31 Charging System Battery	MDT Failure/Issue Not powering up						
55 Tail Lift	Ramp/Lift/Tail Hoist Not deploying						
Travel Time	Travel to and from Weymouth.						

Breakdown	05/03/2019	15:58	07/03/2019	09:00	236,083	Dorchester	DC019888
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Breakdown	o/s rear indicator damage Engine Management						
------------------------	--	--	--	--	--	--	--

Breakdown	09/03/2019	09:43	15/03/2019	12:33	236,083	Dorchester	DC019907
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	rear pads						
16 Suspension 1	o/s rear spring worn, n/s replaced					Monitoring	
17 Tyres	n/s/f slow puncture						
24 Driveshaft 1	n/s halfshaft leaking						
45 Engine 1	Carry out checks with TEXA. See notes						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
71 Body Exterior 1	Rear flap adrift						
Breakdown	Engine cuts out when idle						
Travel Time							
18 Wheels Check Torques							
Safety Inspection							
UB Fire Suppression Service							
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
Handbrake Cable Replacement	Replace rear handbrake cables						

Vehicle Deep Clean	12/03/2019	11:24	15/03/2019	13:02	236,397	Dorchester	DC019924
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	18/03/2019	08:44	18/03/2019	08:56	236,748	Dorchester	DC019949
54 Sirens	reported n/w						
BREAKDOWN	22/03/2019	07:10	22/03/2019	08:30	237,205	Dorchester	DC019974
86 Doors 86 Sliding Door	Doors O/S sliding door handle broken Handle broken						
Unplanned Repair	01/04/2019	08:25	01/04/2019	08:49	238,352	Dorchester	DC020010
34 Lighting System	Scene light inop.Replace cracked scene light						
Unplanned Repair	02/04/2019	12:58	02/04/2019	13:14	238,577	Dorchester	DC020022
45 Engine Ad Blue	Top up						
Unplanned Repair	07/04/2019	18:00	07/04/2019	18:15	239,309	Dorchester	DC020045
34 Lights Bulb Replacement	Headlight bulb replaced by Bronze						
Unplanned Repair	14/04/2019	07:30	14/04/2019	08:15	240,534	Dorchester	DC020078
56 Comms Equipment Travel Time	MDT screen frozen.Reboot,ok						

SAFETY INSPECTION	23/04/2019	10:19	24/04/2019	13:29	241,928	Dorchester	DC020111
02 Windscreen Wipers	washers blocked						
13 Brake Pads	front low						
13 Calipers	N/S caliper u/s						
18 Wheels	o/s/f hub/studs damaged						
18 Wheels Check Torques							
34 Lights	marker light not working o/s						
45 Engine Ad Blue	top up						
56 Comms Equipment	Comms Power Check MDT frozen						
71 Body External Steps	step sticking						
Safety Inspection							
Travel Time							
Axle Oil Change	Axle Oil Change						
Engine Change Oil & Filter							
Vehicle Deep Clean	24/04/2019	10:30	24/04/2019	14:59	241,944	Dorchester	DC020118
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/04/2019	19:08	26/04/2019	11:44	242,120	Dorchester	DC020128
Breakdown	Not powering up						
Unplanned Repair	26/04/2019	13:00	26/04/2019	14:10	242,134	Dorchester	DC020137
86 Doors Rear	Rear handle u/s						
Unplanned Repair	03/05/2019	08:00	03/05/2019	10:19	243,387	Dorchester	DC020162
45 Engine Ad Blue	level low						
Breakdown	08/05/2019	22:44	09/05/2019	11:12	244,204	Dorchester	DC020180
Breakdown	limp mode						

Tail Lift 12M Service & Weight	13/05/2019	08:19	13/05/2019	14:30	244,999	Dorchester	DC020204
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Unplanned Repair	14/05/2019	07:15	14/05/2019	07:30	245,114	Dorchester	DC020211
45 Engine Ad Blue							
Unplanned Repair	20/05/2019	10:00	20/05/2019	11:30	245,979	Dorchester	DC020245
17 Tyres Replace	Puncture o/s/f.Replace o/s/f rim and tyre,carry out retorque						
18 Wheels	o/s/f rim cracked,replace						
34 Lights	o/s/f running lamp inop.Replace bulb						
85 Body Interior 1	Emg Warning Devices FIRE EXTINGUISHER IN CAB U/S						
86 Doors	Body Exterior REAR DOOR LATCH LOOSE ON TOP						
86 Doors Rear	Body Exterior REAR DOOR LATCH LOOSE ON TOP						
Unplanned Repair	22/05/2019	11:15	22/05/2019	14:25	246,396	Dorchester	DC020258
13 Brakes 1	brake wear light on						
SAFETY INSPECTION	03/06/2019	07:45	04/06/2019	08:00	247,692	Dorchester	DC020306
13 Handbrake	adjust up						
15 Steering 1	o/s rack joint has play						
16 Suspension 1	o/s rear spring worn, n/s replaced slipper pads u/s						
17 Tyres	Rear low						
18 Wheels Check Torques							
31 Battery Comms	MDT Failure/Issue Not powering up.Broken wire in loom.						
Safety Inspection							
Vehicle Deep Clean	04/06/2019	14:50	05/06/2019	09:00	247,703	Dorchester	DC020321
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	09/06/2019	19:07	10/06/2019	08:32	248,414	Dorchester	DC020337

56 Comms Power Failure Breakdown Carry out checks,battery and charge system ok
Will not turn off/on

Unplanned Repair 18/06/2019 07:40 18/06/2019 07:57 249,338 Dorchester DC020375

45 Engine Ad Blue

COMMS.FAILURE CHECK28/06/2019 12:00 28/06/2019 12:38 250,740 Dorchester DC020422

MDT Failure/Issue Carry out battery check,ok.Reboot system

Unplanned Repair 03/07/2019 07:00 03/07/2019 08:30 251,253 Dorchester DC020451

01 Air Conditioning 1 Other Rear A/C not cold
52 Electrical Aux Comms Power Check Repeated comms power fail
56 Comms Power Failure Battery/Charging Sys Repeated power fails Batt check ok 12.8

Breakdown 06/07/2019 14:52 08/07/2019 10:45 251,757 Dorchester DC020472

52 Electrical Aux Breakdown comm fail
overheating/coolant light on dash

SAFETY INSPECTION 15/07/2019 07:30 15/07/2019 15:30 252,677 Dorchester DC020506

01 Air Conditioning 1 Sallon a/c has leak on hose, idler u/s
13 Brake Pads Rear worn uneven
13 Brakes 1 pedal rubber u/s
17 Tyres N/S/R inner u/s
18 Wheels Check Torques
34 Lights O/S drl not working
45 Engine Ad Blue top up
45 Engine Oil Top Up top up
89 Seats Driver swab and cover u/s
Safety Inspection
Pollen Filter Change Pollen Filter Change

Fuel Filter Change Air Filter Change Tail Lift Inspection	Change Fuel Filter Air Filter Change						
Vehicle Deep Clean	16/07/2019	09:30	16/07/2019	13:39	252,689	Dorchester	DC020513
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	27/07/2019	07:15	29/07/2019	09:59	254,309	Dorchester	DC020577
15 Steering 1 Breakdown Travel Time	Steering pump found to be u/s. gringing from rear axel Ferndown to Weymouth & Return,						
BREAKDOWN	06/08/2019	23:30	06/08/2019	23:35	256,149	Dorchester	DC020618
34 Lights Bulb Replacement	Headlight bulb replaced by Bronze						
Unplanned Repair	09/08/2019	08:00	09/08/2019	08:13	256,403	Dorchester	DC020640
45 Engine Oil Top Up							
Unplanned Repair	19/08/2019	08:00	19/08/2019	08:22	257,945	Dorchester	DC020684
02 Windscreen Wipers	Washers inop,remove and clean filter.Refill						
Unplanned Repair	19/08/2019	12:00	19/08/2019	13:10	257,994	Dorchester	DC020691
56 Comms Equipment	MDT frozen out						
Unplanned Repair	23/08/2019	10:15	23/08/2019	10:45	258,801	Dorchester	DC020719
42 Coolant System	Low coolant light on,trace to faulty float switch.Replace and pressure cap						

SAFETY INSPECTION	28/08/2019	07:30	28/08/2019	14:56	259,369	Dorchester	DC020733
02 Windscreen Wipers	blades u/s						
13 Brake Pads	front worn						
13 Discs	front worn						
16 Suspension 1	Play in front struts and arms					Monitoring	
17 Tyres	n/s/f tyre worn						
18 Wheels Check Torques							
34 Lights	number plate light broken						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
Vehicle Deep Clean	29/08/2019	11:00	29/08/2019	15:00	259,381	Dorchester	DC020758
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	14/09/2019	06:21	27/09/2019	14:38	261,656	Dorchester	DC020849
31 Charging System	not charging						
45 Engine 1	Engine cranking but not starting when hot						
Breakdown	Will not start						
Travel Time							
Unplanned Repair	02/10/2019	07:45	02/10/2019	09:40	262,547	Dorchester	DC020942
71 Body External Steps	Side step reported deploying while driving						
86 Sliding Door	Inner cables frayed					Awaiting Parts	
SAFETY INSPECTION	07/10/2019	07:11	07/10/2019	14:16	263,292	Dorchester	DC020964
01 Air Conditioning 1	belt u/s						
01 Heating 1	night heater n/w						
02 Windows/Glass	Both door window switches broken						
16 Suspension 1	Play in front struts and arms	Do on MOT insp				Monitoring	

17 Tyres	o/s/f slow puncture						
18 Wheels Check Torques							
34 Emergency Lights	o/s rear top blue light lens cracked						
45 Engine 1	Injector blowing already been into merc 1x						
45 Engine Ad Blue	Top up						
45 Engine Oil Top Up	Top up						
86 Sliding Door	Inner cables frayed						
89 Seats	belts twisted and handle loose						
Safety Inspection							
Vehicle Deep Clean	08/10/2019	09:27	08/10/2019	14:21	263,306	Dorchester	DC020976
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	27/10/2019	10:15	28/10/2019	09:14	266,561	Dorchester	DC021098
86 Doors Rear	Rear door difficult to open and large rear door pins worn						
86 Sliding Door	Side door not opening from inside/outside and rollers worn						
Breakdown	side door wont open , rear door sticking						
Travel Time	Travel to Weymouth						
Unplanned Repair	30/10/2019	13:00	30/10/2019	13:15	266,892	Dorchester	DC021118
34 Lights Bulb Replacement	o/s running lamp inop.replace bulb						
Unplanned Repair	07/11/2019	07:00	07/11/2019	08:42	267,985	Dorchester	DC021164
34 Lights	o/s headlight and side light n/w						
Unplanned Repair	14/11/2019	07:30	14/11/2019	07:45	268,991	Dorchester	DC021211
02 Windscreen Wipers	Wipers reported poor,replace blades						
SAFETY INSPECTION	18/11/2019	07:30	19/11/2019	15:30	269,313	Dorchester	DC021233

Monitoring
Monitoring

02 Cab Assembly 1	drivers visor ripped						
02 Mirrors	Mirrors Drivers' side wing mirror cracked, pass door mirror cover damaged						
13 Brakes 1	replace NSF wear sensor						
16 Suspension 1	Play in front struts and arms Do on MOT insp						
17 Tyres Replace	replace NSF and all rear tyres						
18 Wheels Check Torques							
34 Emergency Lights	o/s rear top blue light lens cracked						
34 Lights	NSF top white marker inop						
34 Lights Bulb Replacement	interior light inop						
44 Add Ad Blue	top up						
45 Engine 1	Injector blowing already been into merc 1x					Monitoring	
86 Sliding Door	replace centre bar						
Safety Inspection	inspection						
Engine Change Oil & Filter							
Tail Lift Inspection							
MOT							
Vehicle Deep Clean	20/11/2019	09:17	20/11/2019	12:17	269,332	Dorchester	DC021252
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	22/11/2019	03:02	22/11/2019	09:57	269,462	Dorchester	DC021267
Breakdown	limp home mode						
BREAKDOWN	29/11/2019	11:39	29/11/2019	14:23	270,133	Dorchester	DC021308
45 Engine 1	Engine Engine continually entering limp mode						
BREAKDOWN	02/12/2019	06:30	06/12/2019	12:27	270,389	Dorchester	DC021320
45 Engine 1	EML on LOP injector blowing						
71 Body Exterior Acc Repair	reversed into bollard						
86 Sliding Door	adjust sliding door (step deploying) and road test						
Unplanned Repair	10/12/2019	10:30	10/12/2019	12:42	270,615	Dorchester	DC021366

86 Sliding Door	alarm going off						
Breakdown	12/12/2019	00:38	12/12/2019	08:29	271,001	Dorchester	DC021378
02 Mirrors	Replace n/s mirror glass						
Breakdown	wing mirror clipped car, bottom part missing						
Unplanned Repair	13/12/2019	07:00	13/12/2019	08:30	271,104	Dorchester	DC021390
86 Door Lock	sliding door handle stuck						
Unplanned Repair	17/12/2019	12:55	17/12/2019	13:28	271,681	Dorchester	DC021421
52 Electrical Aux	No power to Ortivus monitoring unit						
SAFETY INSPECTION	27/12/2019	08:09	27/12/2019	14:13	272,729	Dorchester	DC021486
02 Cab Ass Fire Extinguisher	replace fire extinguisher						
02 Mirrors	replace NS mirror cover						
02 Windscreen Wipers	washers inop						
13 Brake Pads	replace rear pads						
18 Wheels Check Torques	torque up						
44 Add Ad Blue	top up						
45 Engine 1	Injector blowing already been into merc 1x						
45 Engine Oil Top Up	top up						
86 Door Lock	Sliding door lock jams						
Safety Inspection							
Brakes Replace Brake Fluid							
Vehicle Deep Clean	30/12/2019	10:30	30/12/2019	14:06	272,735	Dorchester	DC021501
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	05/01/2020	08:24	06/01/2020	09:47	273,787	Dorchester	DC021533

17 Tyres Tyres tyre pressure low ?
 86 Sliding Door Body Exterior dide door wont open from inside

BREAKDOWN **16/01/2020** **21:45** **16/01/2020** **23:45** **275,513** **Dorchester** **DC021612**

BREAKDOWN MDT screen frozen and bleeping
 Travel Time travel to weymouth and back home

Unplanned Repair **22/01/2020** **14:30** **22/01/2020** **15:15** **276,328** **Dorchester** **DC021658**

01 Heating 1 Saloon heater inop

Breakdown **23/01/2020** **16:07** **23/01/2020** **17:50** **276,592** **Dorchester** **DC021669**

Breakdown Outer o/s/r puncture.Duty Fitter not called.Carried out by ATS

Unplanned Repair **23/01/2020** **18:00** **23/01/2020** **19:30** **276,592** **Dorchester** **DC021670**

17 Tyres Replace o/s/f tyre reported worn.Replace and carry out retorque
 Travel Time

Unplanned Repair **30/01/2020** **18:00** **30/01/2020** **18:15** **277,329** **Dorchester** **DC021709**

34 Lights Bulb Replacement Headlight bulb replaced by Bronze

Unplanned Repair **31/01/2020** **10:15** **31/01/2020** **10:46** **277,408** **Dorchester** **DC021714**

02 Windscreen Wipers Washers inop.Remove and clean out resevoir,full of goop.Refill and test.Ok

02 Pipeline Annual Inspection **06/02/2020** **15:00** **06/02/2020** **15:30** **277,408** **MDT Weymouth** **DW000150**

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - No Faults

Unplanned Repair	10/02/2020	12:00	10/02/2020	13:00	278,601	Dorchester	DC021769
56 Comms Equipment 86 Sliding Door	MDT Failure/Issue load noise from MDT alarm going off						
SAFETY INSPECTION	12/02/2020	08:11	13/02/2020	09:36	279,265	Dorchester	DC021780
13 Brake Pads 17 Tyres Replace 18 Wheels Check Torques 27 Transmission Automatic 44 Add Ad Blue 45 Engine Oil Top Up 86 Doors Rear 89 Seats Safety Inspection Tail Lift Inspection UB Fire Supp 6mts Service	replace front pads renew NSF tyre leak from sump gasket top up top up straighten NSR door stay secure cab seat arm rests UB Fire Supp 6mts Service						
Vehicle Deep Clean	13/02/2020	11:30	13/02/2020	14:59	279,278	Dorchester	DC021791
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/02/2020	14:00	21/02/2020	16:00	280,469	Dorchester	DC021843
52 Electrical Aux	No power to monitoring unit.Check system,power supply u/s.ORTIVUS to sort						
Unplanned Repair	02/03/2020	07:45	02/03/2020	08:31	281,358	Dorchester	DC021910
45 Engine Ad Blue							
BREAKDOWN	02/03/2020	19:30	02/03/2020	21:30	281,471	Dorchester	DC021917
56 Comms Fitment Travel Time	MDT frozen out						

Unplanned Repair	10/03/2020	11:30	10/03/2020	12:30	282,969	Dorchester	DC021964
34 Lighting System	o/s/r upper stop/tail lamp inop					Awaiting Parts	
Unplanned Repair	11/03/2020	10:30	11/03/2020	11:51	283,054	Dorchester	DC021974
34 Lighting System	o/s/r upper stop/tail lamp inop						
Unplanned Repair	20/03/2020	07:00	20/03/2020	12:13	283,670	Dorchester	DC022025
45 Engine 1 56 Comms Equipment	Engine Coolant leaking. Needed topping up twice in 24hrs MDT Failure PCE to repair						
Breakdown	20/03/2020	22:08	27/03/2020	06:37	284,373	Dorchester	DC022030
01 Heating 1 02 Mirrors 11 Axle Rear 13 Brake Pads 13 Brakes 1 15 Steering 1 17 Tyres 18 Wheels 42 Radiator 52 Electrical Aux Breakdown Replace Handbrake Cables UB Fire Supp 12mts Service 18 Wheels Check Torques Safety Inspection	heater not hot replace mirror and secure frame replace rear flanges inspect rear pads Servo pipe damaged adjust castor/camber angle 3x low rim cracked Rad Leaking CCTV not working cracked side window - right side; VOR Replace Handbrake Cables Service of fire suppression system						
Tail Lift 12M Service & Weight	31/03/2020	09:08	31/03/2020	12:09	284,373	Dorchester	DC022073
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Unplanned Repair	04/04/2020	07:30	04/04/2020	08:08	285,297	Dorchester	DC022097
17 Tyres Replace 18 Wheels	Puncture reported o/s/f .Check over,rim cracked.Replace wheel and tyre o/s/f rim cracked						

Unplanned Repair	08/04/2020	11:30	08/04/2020	11:47	285,826	Dorchester	DC022130
02 Windscreen Wipers	Screen washers inop.Clean resevoir and refill						
Breakdown	09/04/2020	16:52	10/04/2020	14:14	285,928	Dorchester	DC022144
Breakdown	back door not closing						
SAFETY INSPECTION	04/05/2020	08:09	05/05/2020	09:45	287,979	Dorchester	DC022308
13 Brakes 1	Rears low						
13 Handbrake	poor adjustment/noisey/bolt broken off						
16 Suspension 1	ARB links worn						
16 Suspension 2	adjust camber						
17 Tyres	N/S/F tyre out						
18 Wheels Check Torques							
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
85 Body Interior 1	torch u/s						
85 Body Interior 2	foot plate damaged						
89 Seats	attendant seat bearings u/s						
Safety Inspection							
Travel Time							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Vehicle Deep Clean	Vehicle Deep Clean						
Tail Lift Inspection							
Vehicle Deep Clean	05/05/2020	11:30	06/05/2020	10:00	287,998	Dorchester	DC022323
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/05/2020	06:50	08/05/2020	09:37	288,183	Dorchester	DC022341
01 Heating 1	Heater inop						
45 Engine 1	EML on,						

Medical Devices Repair	06/05/2020	10:30	06/05/2020	11:30	287,979	MDT Weymouth	DW000226
Decontaminated	Cleaned with clinell wipes						
Defect Sheet Present No							
Defect Sheet Present Yes							
Medical Devices Repair	Mangar Compressor/mount updated to Airflow 24 type						
Unplanned Repair	10/05/2020	13:18	10/05/2020	14:37	288,451	Dorchester	DC022348
02 Windscreen Wipers	Washers inop						
71 Body External Steps	Side step deploying whilst driving						
Breakdown	14/05/2020	02:18	14/05/2020	08:18	289,105	Dorchester	DC022372
Breakdown	Side step Deploying while driving						
Unplanned Repair	18/05/2020	11:45	18/05/2020	12:15	289,414	Dorchester	DC022394
17 Tyres	o/s/r reported soft,check over,replace valve extension.carry out retorque						
Unplanned Repair	22/05/2020	14:00	22/05/2020	15:15	289,841	Dorchester	DC022439
86 Sliding Door							
Unplanned Repair	26/05/2020	08:01	27/05/2020	09:05	290,254	Dorchester	DC022463
15 Steering 1	pump failed						
Unplanned Repair	29/05/2020	14:04	29/05/2020	14:37	290,694	Dorchester	DC022490
17 Tyres Replace	Replace o/s/r tyres						
Breakdown	09/06/2020	01:42	09/06/2020	14:12	291,853	Dorchester	DC022558
27 Transmission Automatic	Carry out checks,gear lever faulty						

Breakdown Not selecting gears properly.

SAFETY INSPECTION	15/06/2020	06:00	15/06/2020	15:30	292,355	Dorchester	DC022604
02 Windscreen Wipers	blades u/s						
13 Handbrake	adjust						
15 Steering 1	Steering rack u/s						
18 Wheels Check Torques							
43 Exhaust System 1	DPF bracket broken						
45 Engine 1	Slight blow on o/s exhaust manifold						
45 Engine Ad Blue	Top up/ cap missing						
45 Engine Oil Top Up	Top up						
55 Tail Lift	Slow close not working						
86 Sliding Door	top bearing rough						
Safety Inspection							
Vehicle Deep Clean	16/06/2020	09:00	16/06/2020	16:00	292,366	Dorchester	DC022625
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	17/06/2020	15:06	18/06/2020	14:20	292,384	Dorchester	DC022627
02 Mirrors	o/s mirror glass damaged						
15 Steering 1	PAS pump						
Breakdown	Power Steering Gone						
Breakdown	29/06/2020	17:19	30/06/2020	11:01	294,149	Dorchester	DC022699
31 Charging System	Check charge rate.Replace alternator						
Breakdown	red alternator EML on dash						
BREAKDOWN	07/07/2020	07:30	07/07/2020	09:01	294,913	Dorchester	DC022753
45 Engine Oil Top Up	top up						
71 Body External Steps	side step deploying when rear door is closed						
86 Door Lock	rear door upper lock loose						

Unplanned Repair	14/07/2020	07:30	14/07/2020	07:58	296,011	Dorchester	DC022796
56 Radio	radio not working, constant bleeping (replace aerial)						
SAFETY INSPECTION	26/07/2020	06:00	27/07/2020	07:10	297,337	Dorchester	DC022882
17 Tyres	front tyres low						
18 Wheels	Rim U/s						
18 Wheels Check Torques							
34 Lights	marker light o/s out						
45 Engine Ad Blue	Top up						
56 Comms Fitment	EPCR Bracket broken charging ok						Monitoring
86 Doors	Slide door top bearing rough						Monitoring
86 Sliding Door	top magnet bent						
Safety Inspection							
Travel Time							
Engine Change Oil & Filter							
Tail Lift Inspection							
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Vehicle Deep Clean	27/07/2020	08:30	27/07/2020	12:07	297,347	Dorchester	DC022901
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	09/08/2020	19:09	10/08/2020	08:10	299,058	Dorchester	DC022988
02 Mirrors	replace OS drivers door mirrors						
Breakdown	O/S wing mirror smashed - ? How						
Breakdown	12/08/2020	05:05	12/08/2020	07:58	299,424	Dorchester	DC023020
02 Mirrors	n/s mirror smashed,replace glass						
Breakdown	N/S mirror smashed						
Breakdown	12/08/2020	12:20	13/08/2020	07:53	299,458	Dorchester	DC023029
Breakdown	N/S Wing Mirror Broken						

Unplanned Repair	14/08/2020	11:51	14/08/2020	12:15	299,824	Dorchester	DC023267
17 Tyres Replace	Tyre replace by ATS						
Breakdown	19/08/2020	00:45	01/09/2020	07:54	300,553	Dorchester	DC023071
001 Recover Vehicle 45 Engine 1 Breakdown	Vehicle Recovery EGR cooler pipe split,Manifold gasket blowing,DPF u/s Limp mode no warnings						
Unplanned Repair	01/09/2020	11:00	01/09/2020	11:16	300,597	Dorchester	DC023176
02 Mirrors	replace NS blindspot mirror						
SAFETY INSPECTION	07/09/2020	13:13	08/09/2020	11:29	301,544	Dorchester	DC023202
02 Cab Assembly 1	bung missing to engine bay						
02 Windscreen Wipers	washers inop						
18 Wheels Check Torques							
24 Driveshaft 1	prop doughnut u/s						
45 Engine 1	EML on						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
85 Body Interior 1	torch missing						
86 Doors	Slide door top bearing rough						
86 Sliding Door	magnet bent						
89 Seats	attendant seat bearing u/s						
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Vehicle Deep Clean	09/09/2020	08:00	09/09/2020	12:30	301,554	Dorchester	DC023233
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	11/09/2020	11:30	11/09/2020	12:43	301,834	Dorchester	DC023243
24 Driveshaft 1	prop doughnut u/s						
Unplanned Repair	17/09/2020	10:50	17/09/2020	11:24	301,834	Dorchester	DC023299
89 Seats	Attenedent seat arm rest broken off.Remove,repair and refit						
Unplanned Repair	28/09/2020	08:45	28/09/2020	09:21	304,358	Dorchester	DC023371
34 Lights Bulb Replacement	o/s/f side light inop,replaced bulb						
COMMS.FAILURE CHECK	28/09/2020	09:45	28/09/2020	10:30	304,338	Dorchester	DC023373
MDT Failure/Issue	Carry out checks as per instructions						
BREAKDOWN	05/10/2020	14:30	07/10/2020	10:34	305,387	Dorchester	DC023425
34 Lights Bulb Replacement	o/s dlr bulb replaced						
45 Engine 1	Boost tube blown out,3 x injectors blowing						
Unplanned Repair	12/10/2020	07:55	12/10/2020	08:22	306,133	Dorchester	DC023463
03 Instruments & Sensors 1	EML on, no LOP						
SAFETY INSPECTION	17/10/2020	09:32	20/10/2020	08:45	306,750	Dorchester	DC023501
02 Windscreen Wipers	washers blocked						
13 Brakes 1	fronts low						
16 Suspension 1	Rear slip pads split						
16 Suspension 2	Front struts and arms worn						
17 Tyres	Rears low						
18 Wheels Check Torques							
45 Engine 1	EML on LOP						
45 Engine 2	EGR valve ordered						

Monitoring

45 Engine Ad Blue	Top up
71 Body Exterior 1	n/s/r corner cap broken
71 Body Exterior 2	Rear flap adrift
85 Body Interior 1	Linen cupboard damaged
85 Body Interior 2	Cab Fire Ext out of date
86 Sliding Door	bearings rough
Safety Inspection	
Tail Lift Inspection	
Pollen Filter Change	Pollen Filter Change

Vehicle Deep Clean	20/10/2020	09:00	20/10/2020	12:30	306,769	Dorchester	DC023518
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	23/10/2020	07:54	23/10/2020	09:03	307,139	Dorchester	DC023547
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 2	EGR valve ordered
45 Engine Oil Top Up	top up

Unplanned Repair	27/10/2020	15:15	28/10/2020	11:11	307,139	Dorchester	DC023575
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body Exterior 1	Vehicle driven off road,check for damage underneath
--------------------	---

Unplanned Repair	29/10/2020	07:30	29/10/2020	07:51	307,839	Dorchester	DC023583
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	Side step been damaged and not deploying.Repair
------------------------	---

Unplanned Repair	03/11/2020	06:00	03/11/2020	08:08	308,648	Dorchester	DC023613
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	N/S glass missing,, NO tranman or defect book filled out
71 Body External Steps	Step deploys whilst driving NO tranman or defect book filled out

SAFETY INSPECTION	30/11/2020	10:40	02/12/2020	14:10	312,142	Dorchester	DC023803
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	tensioner u/s
-----------------------	---------------

13 Brake Pads	rear low						
13 Brakes 1	pedal rubber split						
17 Tyres	front tyres low						
18 Wheels Check Torques							
34 Emergency Lights	n/s/r top blue lens damaged						
34 Lights	number plate light inop, adjust headlights						
45 Engine 1	fire trace pipe rubbing						
45 Engine 2	Fit Air mass meter						
45 Engine Ad Blue	top up						
55 Tail Lift	rails siezed						
56 Comms Fitment	EPCR Bracket broken charging ok						
85 Body Interior 1	fir ext o.o.d						
86 Doors	Slide door top bearing rough					Monitoring	
Safety Inspection							
Travel Time	take to mot						
MOT							
Tail Lift Inspection							
Vehicle Deep Clean	01/12/2020	13:00	01/12/2020	16:01	312,141	Dorchester	DC023818
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/12/2020	10:30	08/12/2020	11:14	313,100	Dorchester	DC023859
03 Instruments & Sensors 1	Fire suppression warning going off.Bypass, waiting for replacement						
87 Stretcher	Not latching into clamp.Check fault,replace hitch sleeve						
Unplanned Repair	11/12/2020	09:45	11/12/2020	10:04	313,599	Dorchester	DC023884
54 Sirens	reported n/w						
Unplanned Repair	02/01/2021	22:45	02/01/2021	23:00	317,726	Dorchester	DC024012
34 Lights Bulb Replacement	Headlight bulb replaced by Bronze						
SAFETY INSPECTION	14/01/2021	07:34	14/01/2021	14:30	319,624	Dorchester	DC024107

18 Wheels Check Torques
 44 Add Ad Blue top up
 45 Engine 1 OS engine cover missing
 45 Engine Oil Top Up top up
 85 Body Interior 1 saloon stretcher guide buffer damaged
 86 Doors Slide door top bearing rough
 86 Doors Rear door not opening from outside handle
 86 Sliding Door top magnet bracket bent
 89 Seats attendant seat plunger stuck
 Safety Inspection

Vehicle Deep Clean **15/01/2021** **11:23** **15/01/2021** **13:30** **319,637** **Dorchester** **DC024132**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **22/01/2021** **03:30** **24/01/2021** **14:00** **321,284** **Dorchester** **DC024187**

41 Turbo
 Breakdown Fumes coming into the cab and saloon
 UB Fire Supp Replace Replacement of UB Fire System

Unplanned Repair **24/01/2021** **18:11** **25/01/2021** **08:35** **321,767** **Dorchester** **DC024197**

54 Sirens Emg Warning Devices Siren and bullhorn non-functioning.

Unplanned Repair **30/01/2021** **12:15** **30/01/2021** **12:54** **321,767** **Dorchester** **DC024247**

71 Body External Steps Side step deployed warning going off,adjust side door

02 Pipeline Annual Inspection **14/02/2021** **19:09** **14/02/2021** **19:14** **323,324** **MDT Bristol** **TB002024**

02 Pipeline Annual Inspection Probe, Shrink Ferrells (£75.32 + Vat), Pressure Tested - Pass

SAFETY INSPECTION **22/02/2021** **07:50** **22/02/2021** **15:09** **324,820** **Dorchester** **DC024403**

02 Windscreen Wipers washers blocked
 18 Wheels Check Torques
 24 Driveshaft 1 propshaft centre bearing perished.Replace
 34 Lights replace NSR yellow marker
 44 Add Ad Blue top up
 86 Doors Rear lock cylinder seized
 86 Sliding Door magnet bracket bent
 Safety Inspection
 UB Fire Suppression DischargeUnder Bonnet Fire Suppression 5 Year Discharge Test.Replaced 24/01/21
 Engine Change Oil & Filter
 UB Fire Supp 6mts Service UB Fire Supp 6mts Service

Vehicle Deep Clean 22/02/2021 14:30 23/02/2021 11:17 324,833 Dorchester DC024418

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair 01/03/2021 07:00 01/03/2021 07:56 325,595 Dorchester DC024470

17 Tyres O/S/F Tyre low

Breakdown 18/03/2021 17:46 19/03/2021 07:59 327,980 Dorchester DC024591

Breakdown Nail in offside rear outer

Unplanned Repair 26/03/2021 13:50 26/03/2021 14:10 328,992 Dorchester DC024645

34 Lights Bulb Replacement DLR inop

SAFETY INSPECTION 05/04/2021 08:45 07/04/2021 12:01 330,714 Dorchester DC024701

17 Tyres Replace n/s/f tyre worn
 18 Wheels Check Torques
 43 Exhaust System 1 Tail pipe rotted through,replace
 45 Engine Ad Blue
 45 Engine Oil Top Up

Safety Inspection
 Tail Lift Inspection
 UB Fire Supp 12mts Service Service of fire suppression system.System replaced 24/01/2021
 Replace Handbrake Cables Replace Handbrake Cables
 Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Vehicle Deep Clean 06/04/2021 09:00 06/04/2021 13:15 330,714 Dorchester DC024709

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 11/04/2021 15:24 14/04/2021 12:26 331,506 Dorchester DC024747

02 Windscreen
 Breakdown Screen cracked
 crack on passenger side

BREAKDOWN 22/04/2021 07:35 23/04/2021 15:19 332,350 Dorchester DC024815

15 Steering 1 Steering reported notchy

Breakdown 25/04/2021 04:13 26/04/2021 07:08 332,613 Dorchester DC024830

Breakdown 1/4 turn play before wheels move

Breakdown 10/05/2021 08:33 10/05/2021 14:31 334,556 Dorchester DC024933

Breakdown Handlamp Not Working

Breakdown 10/05/2021 08:41 10/05/2021 14:31 334,556 Dorchester DC024934

Breakdown Saloon Heater Not Working

Breakdown 10/05/2021 08:42 10/05/2021 14:32 334,556 Dorchester DC024935

Breakdown N/Side Door jams when unlocking

SAFETY INSPECTION	18/05/2021	06:54	18/05/2021	12:39	335,855	Dorchester	DC025017
01 Heating 1							
02 Cab Assembly 1							
13 Brake Pads							
17 Tyres							
18 Wheels Check Torques							
45 Engine 1							
45 Engine 2							
86 Doors							
86 Sliding Door							
Safety Inspection							
Auto G/box Oil & Filter Change							
Vehicle Deep Clean	18/05/2021	15:05	19/05/2021	11:29	335,899	Dorchester	DC025031
Vehicle Deep Clean							
Breakdown	23/05/2021	22:02	24/05/2021	06:44	336,508	Dorchester	DC025070
Breakdown							
Unplanned Repair	24/05/2021	13:30	27/05/2021	09:33	337,000	Dorchester	DC025079
86 Doors Rear							
Travel Time							
Breakdown	24/05/2021	20:22	25/05/2021	09:31	337,000	Dorchester	DC025081
Breakdown							
Unplanned Repair	08/06/2021	06:00	08/06/2021	07:24	337,905	Dorchester	DC025187
02 Mirrors							

Unplanned Repair	18/06/2021	13:30	18/06/2021	13:45	339,214	Dorchester	DC025262
52 Electrical Aux	Remove hard drive as requested						
SAFETY INSPECTION	28/06/2021	08:23	29/06/2021	13:56	340,397	Dorchester	DC025337
01 Air Conditioning 1	Condensor and fan assembly u/s, 2x leaks at front					Awaiting Parts	
02 Cab Assembly 1	Torch inop						
13 Brakes 1	Rears worn out						
17 Tyres	N/S/F worn						
18 Wheels Check Torques							
24 Driveshaft 1	Rear prop u/s						
42 Coolant System	Header tank leaking						
45 Engine 1	Viscous fan u/s. Rad Couling damaged						
45 Engine Ad Blue	top up						
55 Tail Lift	Wheel locks siezed, rail doesnt lock, hose perrished						
86 Doors Rear	catch parts to fit from fitment of new door						
86 Sliding Door	Magnet bent top bearings rough						
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	29/06/2021	15:00	30/06/2021	12:24	340,397	Dorchester	DC025353
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	13/07/2021	09:45	13/07/2021	10:03	342,587	Dorchester	DC025435
71 Body External Steps	side step sticking						
Unplanned Repair	19/07/2021	07:44	19/07/2021	08:38	343,565	Dorchester	DC025478
86 Sliding Door	Door handle ripped off						
Unplanned Repair	25/07/2021	06:00	25/07/2021	12:58	344,604	Dorchester	DC025530

01 Air Conditioning 1 Annual Air Con Service	Condensor and fan assembly u/s. Annual Air Condition Service						
Breakdown	28/07/2021	00:52	28/07/2021	08:54	344,876	Dorchester	DC025555
86 Door Lock Breakdown	sliding door handle jammed, barrel snapped tailift jammed - will not raise						
SAFETY INSPECTION	09/08/2021	09:04	09/08/2021	14:00	346,462	Dorchester	DC025633
02 Windscreen Wipers	replace worn blades						
16 Suspension 1	ARB links worn						
16 Suspension 2	Slipper pads split2x						
17 Tyres	o/s/f worn						
18 Wheels Check Torques							
34 Lights	n/s side light inop						
45 Engine Ad Blue	top up						
55 Tail Lift	hose perished, rail doesnt lock						
Safety Inspection							
Travel Time							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Vehicle Deep Clean	09/08/2021	15:00	10/08/2021	11:00	346,469	Dorchester	DC025643
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	11/08/2021	14:20	11/08/2021	14:30	346,644	Dorchester	DC025667
56 Comms Equipment	Not transmitting properly.Replace missing aerial						
87 Stretcher	Stretcher reported intermittent,check over.Battery u/s,replace						
Breakdown	30/08/2021	00:43	30/08/2021	07:43	349,684	Dorchester	DC025802
Breakdown	side door has faulty latch - door insecure						
Unplanned Repair	01/09/2021	09:12	01/09/2021	09:14	349,874	Dorchester	DC025817
34 Lights Bulb Replacement	Replaced by Bronze						

Unplanned Repair	06/09/2021	13:26	06/09/2021	13:45	350,952	Dorchester	DC025845
44 Add Ad Blue							
Unplanned Repair	07/09/2021	13:45	07/09/2021	14:15	351,167	Dorchester	DC025861
02 Windscreen Wipers	Washer system blocked,clean through system						
SAFETY INSPECTION	19/09/2021	09:00	21/09/2021	10:05	352,641	Dorchester	DC025955
02 Cab Assembly 1	torch not charging						
02 Cab Assembly 2	driver door wiring damaged						
13 Brakes 1	Fronts Worn out						
16 Suspension 1	Rear Shocks worn						
17 Tyres	2 x low						
18 Wheels	N/S/F Loose, damaged/wear to studs and flange						
18 Wheels Check Torques							
34 Lights Bulb Replacement	N/S Main Beam inop						
45 Engine 1	Oil leak from filter housing						
45 Engine Ad Blue	Top up						
56 Comms Equipment	All Batterys Flat....Vehicle not been on charge left outside						
85 Body Interior 1	Rear Body Vent Screwed shut...Parts required						
85 Body Interior 2	emergancy hammer missing						
86 Sliding Door	strike catch broken						
Check Winter Pack	check						
Safety Inspection							
Engine Change Oil & Filter							
Tail Lift Inspection							
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Pollen Filter Change	Pollen Filter Change						
Vehicle Deep Clean	20/09/2021	10:00	20/09/2021	15:15	352,640	Dorchester	DC025963
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	22/09/2021	06:00	22/09/2021	06:36	352,675	Dorchester	DC025976
85 Body Interior 1	Rear Body Vent Screwed shut...Parts required						

Monitoring

Unplanned Repair	15/10/2021	09:45	15/10/2021	10:59	356,030	Dorchester	DC026151
86 Door Lock	rear door lock not engaging, alarm going off						
Unplanned Repair	22/10/2021	10:30	22/10/2021	10:52	357,285	Dorchester	DC026192
86 Doors Rear	Door open warning going off.Check and adjust switch						
Unplanned Repair	29/10/2021	07:59	29/10/2021	08:35	357,761	Dorchester	DC026233
52 Electrical Aux	Sat nav inop.Carry out checks,replace frozen head,modify casing						
SAFETY INSPECTION	01/11/2021	08:42	02/11/2021	14:09	358,049	Dorchester	DC026244
18 Wheels Check Torques 85 Body Interior 1 86 Sliding Door Safety Inspection MOT	Extinguishers OOD.Replace Magnet bracket bent.Realign						
Vehicle Deep Clean	01/11/2021	14:45	02/11/2021	11:06	358,063	Dorchester	DC026253
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/12/2021	10:15	08/12/2021	10:53	362,700	Dorchester	DC026520
03 Instruments & Sensors 1	EML on.Check with TEXA.See notes					Awaiting Parts	
SAFETY INSPECTION	13/12/2021	08:04	14/12/2021	08:56	363,327	Dorchester	DC026559

03 Instruments & Sensors 1	EML on.Check with TEXA.See notes						
13 Brake Pads	rears low						
17 Tyres Replace	replace OSF and NSR inner						
18 Wheels Check Torques							
34 Emergency Lights	NSF upper blue light lens damaged						
34 Lights	NS headlight has small cracks						
41 Turbo	boost seals leaking						
44 Add Ad Blue	top up						
45 Engine 1	OS engine covers missing						Awaiting Parts
52 Electrical Aux	CCtv camera 4 cover damaged						
71 Body Exterior 1	Body Exterior Impact to roof and roof lights, NSF upper corner cap damaged						
86 Door Lock	rear door lock barrel seized						
Safety Inspection							
Tail Lift Inspection							
Brake Fluid Change	Brake Fluid Change						
Vehicle Deep Clean	14/12/2021	09:30	15/12/2021	11:00	363,341	Dorchester	DC026578
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	15/12/2021	11:30	15/12/2021	11:45	363,343	Dorchester	DC026593
45 Engine 1	OS engine covers missing						
Unplanned Repair	18/12/2021	08:00	18/12/2021	08:15	363,617	Dorchester	DC026632
02 Windscreen Wipers	washers not working						
ACCIDENT	26/12/2021	10:23	28/12/2021	07:50	364,583	Dorchester	DC026693
71 Body External Steps Breakdown	Side step damaged. Carry out repair SIDE STEPS HANGING ON						
Breakdown	01/01/2022	05:33	03/01/2022	13:18	365,055	Dorchester	DC026732
01 Air Conditioning 1 Breakdown	Compressor clutch failed loud rattling noise engine compartment; VOR.See notes.Compressor bypassed						Awaiting Parts

ACCIDENT	05/01/2022	19:49	01/02/2022	08:40	365,206	Dorchester	DC026771
17 Tyres Replace 71 Body Exterior Acc Repair Breakdown	replace damaged tyre and rim to make vehicle mobile Damage to n/s/f suspension and bodywork N/S Tyre Damage / Wheel Trim ?						
SAFETY INSPECTION	01/02/2022	08:40	03/02/2022	09:06	365,310	Dorchester	DC026988
01 Air Conditioning 1 18 Wheels Check Torques 44 Add Ad Blue 45 Engine Oil Top Up Safety Inspection Travel Time UB Fire Supp 6mts Service Tail Lift Inspection	Compressor clutch failed take to dorchester UB Fire Supp 6mts Service						
Vehicle Deep Clean	03/02/2022	12:36	04/02/2022	11:38	365,317	Dorchester	DC027015
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	05/02/2022	06:00	05/02/2022	07:35	365,325	Dorchester	DC027021
86 Sliding Door	Wont open						
Unplanned Repair	08/02/2022	08:00	08/02/2022	08:08	365,377	Dorchester	DC027034
34 Lights Bulb Replacement	NS headlight not working						
Unplanned Repair	24/02/2022	12:15	24/02/2022	12:53	367,572	Dorchester	DC027129
34 Emergency Lights	OSF large blue lens detached from frame, temp repair						
SAFETY INSPECTION	07/03/2022	07:54	08/03/2022	11:10	368,167	Dorchester	DC027193

18 Wheels Check Torques							
Safety Inspection							
Wheel Hub Flanges Replaceme							
45 Engine 1							
71 Body Exterior 1							
17 Tyres							
16 Suspension 1							
34 Lights							
45 Engine Ad Blue							
02 Cab Assembly 1							
02 Cab Assembly 2							
85 Body Interior 1							
85 Body Interior 2							
52 Electrical Aux							
02 Windscreen Wipers							
89 Seats							
34 Emergency Lights							
						Monitoring	
Vehicle Deep Clean	08/03/2022	13:30	09/03/2022	10:09	368,956	Dorchester	DC027217
Vehicle Deep Clean							
Breakdown	10/03/2022	02:42	11/03/2022	15:00	369,175	Dorchester	DC027232
Breakdown							
45 Engine 1							
Breakdown	10/03/2022	14:10	11/03/2022	15:30	369,174	Dorchester	DC027246
Breakdown							
02 Pipeline Annual Inspection	09/03/2022	09:30	09/03/2022	10:00	368,956	MDT Weymouth	DW000828
02 Pipeline Annual Inspection							
Breakdown	24/03/2022	12:18	05/04/2022	09:33	370,550	Dorchester	DC027338
Breakdown							
45 Engine 1							
002 Major Unit Replace Eng							
45 Engine 2							

UB Fire Supp 12mts Service	Service of fire suppression system						
34 Lights	2 x indicators inop						
27 Transmission Automatic	Gear box, noisy and harsh gear changes in low gears					Monitoring	
17 Tyres							
Unplanned Repair	05/04/2022	11:15	05/04/2022	11:30	370,550	Dorchester	DC027402
52 Electrical Aux	Remove CCTV hard drive						
Tail Lift 12M Service & Weight	13/04/2022	10:00	13/04/2022	13:18	370,550	Dorchester	DC027464
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
SAFETY INSPECTION	19/04/2022	08:28	20/04/2022	09:28	372,069	Dorchester	DC027499
18 Wheels Check Torques							
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
34 Emergency Light System	Airport light smashed off					Awaiting Parts	
44 Add Ad Blue							
45 Engine Oil Top Up							
Vehicle Deep Clean	20/04/2022	10:30	20/04/2022	15:56	372,083	Dorchester	DC027516
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	22/04/2022	19:47	25/04/2022	16:30	372,750	Dorchester	DC027549
Breakdown	Cursor error / Battery Check						
COMMS.FAILURE CHECK	23/05/2022	10:15	23/05/2022	10:34	375,168	Dorchester	DC027723
MDT Failure/Issue	Replace missing aerial						

SAFETY INSPECTION	30/05/2022	07:56	31/05/2022	10:12	376,195	Dorchester	DC027762
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
Annual Heater Service			Annual Heater Service				
34 Emergency Lights			O/S/F blue lens on order				
27 Transmission Automatic			Gear box, noisy and harsh gear changes in low gears				
34 Emergency Light System			Airport light smashed off				
44 Add Ad Blue			top up				
45 Engine Oil Top Up			top up				
89 Seats			NSF seat height adjuster sticking				
86 Door Lock			sliding door barrel difficult to open from inside, short cable U/S, temp repair				
55 Tail Lift			adjust guide rails				
16 Suspension 1			2x rear slipper pads worn				
43 Exhaust System 1			exhaust clamp bolt missing				
Vehicle Deep Clean	01/06/2022	12:00	02/06/2022	12:24	376,508	Dorchester	DC027794
Vehicle Deep Clean			Vehicle Deep Clean				
Unplanned Repair	14/06/2022	06:30	14/06/2022	07:57	377,212	Dorchester	DC027885
56 Comms Equipment			MDT not working				
34 Lights			O/S headlight not working				
86 Door Lock			Side door not locking				
Breakdown	16/06/2022	17:05	17/06/2022	07:30	377,629	Dorchester	DC027911
Breakdown			SAT NAV SCREEN FROZEN - GARMIN FRONT SCREEN				
52 Electrical Aux			sat nav battery flat, replace head				
Breakdown	17/06/2022	22:36	29/06/2022	12:00	377,832	Dorchester	DC027916
Breakdown			LIMP MODE				
45 Engine 1			Limp mode and misfire.New engine fitted April				

Breakdown	10/07/2022	19:23	12/07/2022	10:04	379,400	Dorchester	DC028057
Breakdown	MOBIMED NOT CHARGING WIRING CHECK						
SAFETY INSPECTION	12/07/2022	10:04	13/07/2022	10:32	379,503	Dorchester	DC028073
18 Wheels Check Torques							
Safety Inspection							
Engine Change Oil & Filter							
Annual Air Con Service	Annual Air Condition Service						
34 Lights	NSF upper brake/taillight smashed						
34 Lighting System	NSR yellow marker out						
43 Exhaust System 1	EGR pipe bolt missing						
13 Brake Pads	rears low						
44 Add Ad Blue	top up						
52 Electrical Aux	Mobimed and EPCR not charging, EPCR missing						
45 Engine 1	to book oil filter						
02 Windscreen Wipers	worn						
Vehicle Deep Clean	14/07/2022	08:30	15/07/2022	09:14	379,514	Dorchester	DC028091
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	19/07/2022	14:30	20/07/2022	07:40	379,940	Dorchester	DC028115
52 Electrical Aux	MDT screen not working						
Unplanned Repair	25/07/2022	08:45	25/07/2022	09:57	380,336	Dorchester	DC028154
56 Comms Equipment	MDT inop						
56 Radio	Not connecting						
34 Lights	n/s main beam out						
Unplanned Repair	08/08/2022	08:05	08/08/2022	08:20	381,464	Dorchester	DC028230
02 Cab Ass Fire Extinguisher	Fire Extinguisher MISSING, in Cab						

ACCIDENT	14/08/2022	01:10	15/08/2022	07:00	382,047	Dorchester	DC028277
Breakdown	Side door handle pulled off. Unable to open door						
Breakdown	29/08/2022	23:56	30/08/2022	08:00	383,726	Dorchester	DC028349
Breakdown	Power Failure to Tail Lift						
86 Sliding Door	Doors Side door retaining catch not holding						
86 Door Lock	Doors Side door Jammed						
Breakdown	27/09/2022	20:12	30/09/2022	05:41	387,305	Dorchester	DC028403
Breakdown	Rear Right O2 Leaking						
Unplanned Repair	29/09/2022	19:21	29/09/2022	19:33	387,304	MDT Ferndown	TF002266
87 Oxygen System	Replaced leaking O2 changeover gauge and 2x outlet port seats.						
BREAKDOWN	05/10/2022	14:00	12/10/2022	09:54	387,322	Dorchester	DC028421
44 Fuel System 1	Fuel leal pump area Rygor Westbury to repair						
001 Recover Vehicle	Vehicle Recovery						
Breakdown	06/10/2022	06:24	06/10/2022	06:24	387,322	Dorchester	DC028423
Breakdown	FUEL LEAK						
SAFETY INSPECTION	13/10/2022	09:34	13/10/2022	09:36	387,350	St Leonards	SL037827
18 Wheels Check Torques							
Safety Inspection							

SAFETY INSPECTION	13/10/2022	09:36	17/10/2022	16:00	387,350	St Leonards	SL037829
18 Wheels Check Torques Safety Inspection Supply Sat Nav Tail Lift Inspection MOT	MDT Failure/Issue Sat Nav and MDT not linking						
Vehicle Deep Clean	19/10/2022	06:26	19/10/2022	06:27	388,190	St Leonards	SL037882
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	18/10/2022	09:00	19/10/2022	11:30	388,190	St Leonards	SL037883
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/10/2022	19:13	26/10/2022	13:30	388,929	Dorchester	DC028445
Breakdown	N/S O2 Connection leaking						
Unplanned Repair	26/10/2022	13:24	26/10/2022	13:31	388,929	MDT Ferndown	TF002339
87 Oxygen System	Repair to Oxygen port and pressure test system.						
Breakdown	17/12/2022	10:44	20/12/2022	16:00	396,527	St Leonards	SL038513
Breakdown 86 Doors 01 Heating 1 34 Lights Bulb Replacement 34 Lights	Heater in the back not working Slide door wont open SEE NOTES> saloon heater n/w.SEE NOTES> repaired connection & renewed bulb on cab int light, ols rev light damaged , renewed.						
Vehicle Deep Clean	27/12/2022	14:12	28/12/2022	11:30	396,867	St Leonards	SL038606
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	29/12/2022	06:00	02/01/2023	10:00	396,867	St Leonards	SL038628
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	
86 Sliding Door	Side door stiff to open
71 Body External Steps	Side step inop/Deploying while driving (Reported by crew)
18 Wheels	Wheel wobble over 50mph
34 Lights Bulb Replacement	Replace o/s indicator bulb
85 Body Interior 1	Replace saloon drawer runner
52 Electrical Aux	Replace 230 volt LED's and saloon Genisys panel
86 Doors Rear	Rear door fault
86 Doors	

Breakdown	26/01/2023	12:47	27/01/2023	05:30	399,206	St Leonards	SL038929
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	OSF
-----------	-----

Breakdown	28/01/2023	22:22	29/01/2023	12:11	399,569	St Leonards	SL038942
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	EML - Adblue warning. filled adblue, still eml
-----------	--

SAFETY INSPECTION	08/02/2023	10:20	08/02/2023	18:00	401,194	St Leonards	SL039036
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques		
Safety Inspection		
Air Filter Change	Air Filter Change	
Fuel Filter Change	Change Fuel Filter	
17 Tyres Replace	replace 4x	
86 Door Seals	Drivers door seal split	
Pollen Filter Change	Pollen Filter Change	
13 Brakes 1	Rear pads Approx 45% worn	Monitoring
55 Tail Lift	Tail lift buffers missing	Monitoring

Vehicle Deep Clean	12/02/2023	10:49	13/02/2023	15:30	401,194	St Leonards	SL039085
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	18/03/2023	15:15	18/03/2023	15:22	404,915	St Leonards	SL039412
45 Engine 1	Engine management light active (See notes) (Spare part used from vor vehicle)						
45 Engine Oil Top Up							
71 Body External Steps	Step jamming when deploying. straightened runners, cleaned and lubed. all ok.						
Unplanned Repair	21/03/2023	17:30	21/03/2023	18:05	405,123	St Leonards	SL039436
17 Tyres	Puncture on rear						
Unplanned Repair	01/04/2023	15:00	01/04/2023	15:30	406,082	St Leonards	SL039555
86 Doors	Equipment locker stiff to open. adjusted cables on latches.						
86 Doors Rear	Rear door not shutting/opening very vell. adjusted cables for door and lubricate						
02 Pipeline Annual Inspection	01/04/2023	09:28	01/04/2023	09:31	406,046	MDT Ferndown	TF002620
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - replaced 1x port seal.						
Unplanned Repair	07/04/2023	06:45	07/04/2023	07:45	406,606	St Leonards	SL039624
55 Tail Lift	Tail lift not working. (see notes)						
Unplanned Repair	08/04/2023	13:30	08/04/2023	13:32	406,640	St Leonards	SL039636
03 Instruments & Sensors 1	Various Dash lights on						
31 Battery Chassis	Battery u/s						
31 Battery Aux	Aux Batt u/s						

Unplanned Repair	14/04/2023	07:50	14/04/2023	07:58	406,724	St Leonards	SL039719
45 Engine Oil Top Up 85 Body Interior 1	Top up Door hinge loose						
Unplanned Repair	15/04/2023	13:00	15/04/2023	13:30	407,703	St Leonards	SL039736
45 Engine 1	EML on, Engine noise @ 2,000rpm. Roadtested n/f/f. Cleared fault,temp sensor.						
SAFETY INSPECTION	18/04/2023	06:00	19/04/2023	13:30	407,945	St Leonards	SL039767
18 Wheels Check Torques Safety Inspection 13 Brakes 1 42 Coolant System 45 Engine 1 Tail Lift Inspection 13 Brakes 2 71 Body Exterior 1 13 Calipers 86 Door Lock 85 Body Interior 1	Checked. Carried out inspection. Rear pads Approx 45% worn. Replaced disc's & pads, and hub seal. Radiator/Cooling Sys LOST ALL COOLANT NOISE FROM ENGINE EML on - O2 sensor fault Done. Front disc's & pads worn. Replaced. Replace rear panel and fit tail lift blocks rubbers torn. Replaced x2. Replaced all lock barrels. Replace white board						
Vehicle Deep Clean	21/04/2023	06:45	21/04/2023	15:00	407,945	St Leonards	SL039819
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	26/04/2023	12:00	26/04/2023	13:52	408,200	St Leonards	SL039905
45 Engine 1	EML. on Temp sensor ordered						
Unplanned Repair	06/05/2023	09:59	06/05/2023	10:45	409,195	St Leonards	SL040027
02 Windscreen Wipers 86 Door Lock	Blades Split Central locking not working correctly						

Vehicle Deep Clean	01/06/2023	15:00	02/06/2023	12:30	412,453	St Leonards	SL040370
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	03/06/2023	09:30	04/06/2023	14:33	412,453	St Leonards	SL040390
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
85 Body Interior 1	Fit P clips for AVP						
13 Handbrake	Cab handbrake travel becoming excessive.						
13 Brakes 1	O/S/R Brake caliper sliders seizing.						
13 Brakes 2	N/S/R Brake caliper sliders seizing.						
55 Tail Lift	Tail lift manual controls excessively seized shut.						
Tail Lift Annual Service	Tail lift side rails stanctions insecure.						
02 Windscreen Wipers	Cab wiper blades smearing on windscreen.						
02 Cab Assembly 1	Cab drivers seat belt has slight frays.						
85 Body Interior 2	Saloon locker 'LH2' hinges broken out of unit.						
43 Exhaust System 1	Exhaust system out of alignment causing stress to lower DPF flexi.						
87 Stretcher	Stretcher head rest tilt mechanism not working.						
71 Body Exterior 2	Saloon N/S/F seat belt jammed into rear seat backing.						
Unplanned Repair	23/06/2023	15:30	23/06/2023	16:45	414,991	St Leonards	SL040704
01 Air Conditioning 1	Aircon inop						
Breakdown	24/06/2023	18:42	28/06/2023	14:30	415,176	St Leonards	SL040715
Breakdown	AirCon not working						
01 Air Conditioning 1	Saloon AC not cold. (see notes)						
01 Air Conditioning 2	Cab AC not cold. (see notes)						
02 Glass / Windows	Saloon glass smashed - Autoglaze to replace (F/Comms)						
Replace Vehicle Fuel Card	07/07/2023	18:00	07/07/2023	18:10	415,590	St Leonards	SL040919
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						

SAFETY INSPECTION	12/07/2023	16:00	17/07/2023	10:30	416,796	St Leonards	SL041038
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Engine Change Oil & Filter	
Pollen Filter Change	Pollen Filter Change
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
Replace Handbrake Cables	Replace Handbrake Cables
89 Seats	Pass seat height adjuster not working. lubed mechanism and replaced lever.
42 Coolant System	Coolant leak from engine oil cooler. new seals required
16 Suspension 1	Rear anti roll bar drop link bushes worn. replace bushes x2.
11 Axle Rear	Rear axle oil low. topped up 1 litre.
16 Suspension 2	Rear spring buffers split x4. replace.
55 Tail Lift	Tail lift pins and bushes worn out .replaced x3 pins and bushes.
16 Suspension 3	Replace rear spring bushes (Front)
45 Engine 1	Replace oil cooler seals

Vehicle Deep Clean	18/07/2023	06:00	18/07/2023	12:28	416,796	St Leonards	SL041121
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	21/08/2023	11:30	21/08/2023	16:30	420,043	St Leonards	SL041624
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	22/08/2023	06:00	22/08/2023	11:01	420,043	St Leonards	SL041643
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
Tail Lift Inspection	Done.

Unplanned Repair	15/09/2023	14:48	15/09/2023	15:47	422,474	St Leonards	SL041949
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior Acc Repair	N/S CCTV Damage to camera
-----------------------------	---------------------------

Vehicle Deep Clean	03/10/2023	11:10	03/10/2023	16:00	425,058	St Leonards	SL042182
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	05/10/2023	07:00	06/10/2023	14:00	425,058	St Leonards	SL042213
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
55 Tail Lift	Bridge plate guides loose and bent. Realigned and Secured						
71 Body Exterior 1	Body Exterior camera casing upper passenger side. Previously repaired						
Tail Lift Inspection	Inspected						
MOT							
Recall Notification	Mercedes airbag recall						
13 Brake Pads	Front brake pads worn low. Replaced						
85 Body Interior 1	CCTV Nearside outer Camera not working. New cam Tried no picture.					Monitoring	
02 Cab Ass Fire Extinguisher	Replaced Saloon extinguisher						
15 Steering 1	Steering wheel worn, replaced						

BREAKDOWN	18/10/2023	12:20	18/10/2023	16:26	426,279	St Leonards	SL042420
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

17 Tyres Replace	N/S/R outer tyre punctured. Replace tyre at verwood firestation.
Travel Time	ferndown vmu - verwood firestation and back

SAFETY INSPECTION	14/11/2023	07:00	14/11/2023	14:21	429,952	St Leonards	SL042780
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspction.						
85 Body Interior 1	CCTV Nearside outer Camera not working. New cam Tried no picture.					Monitoring	
UB Fire Supp 12mts Service	Service of fire supression system						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Annual Heater Service	Annual Heater Service Done,replaced exhaust.						
02 Cab Assembly 1	Cubby box lid broken off! Repaired.						
02 Cab Assembly 2	Drivers window switch broken. Replaced.						
34 Lights Bulb Replacement	Interior light n/w. Replaced bulb.						
85 Body Interior 2	Floor cupboard door broken off!						
17 Tyres Replace	O/S/F low tread.O/S/R/I punctured. Replaced x2.						
56 Comms Equipment	Saloon microphone broken. No parts.					Monitoring	

Vehicle Deep Clean	15/11/2023	07:08	15/11/2023	11:00	429,957	St Leonards	SL042796
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Breakdown	20/12/2023	10:43	20/12/2023	15:08	432,199	St Leonards	SL043264
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	o/s rear tyre flatten						
-----------	-----------------------	--	--	--	--	--	--

Vehicle Deep Clean	27/12/2023	11:07	27/12/2023	16:13	432,665	St Leonards	SL043334
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	28/12/2023	06:00	29/12/2023	09:45	432,665	St Leonards	SL043344
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
85 Body Interior 1	CCTV Nearside outer Camera not working. New cam Tried no picture.						Monitoring
56 Comms Equipment	Saloon microphone broken. No parts.						Monitoring
71 Body Exterior 1	Body Exterior O/S/R wheel arch damage -monitor						Monitoring
Annual Air Con Service	Annual Air Condition Service						
Tail Lift Inspection							
34 Lights Bulb Replacement	OSF DRL and sidelight bulb blown. replaced						
13 Brakes 1	OSF Slider seized. replaced caliper and bled.						
27 Transmission Automatic	Rear transmission mount perished. replaced mount.						
45 Engine 1	A/C belt tensioner worn. replaced tensioner.						
55 Tail Lift	(SEE NOTES)						

Unplanned Repair	08/01/2024	09:00	08/01/2024	11:00	433,490	St Leonards	SL043513
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

55 Tail Lift	Tail lift inop , test & renew battery, free off manual t\lift controls.						
--------------	---	--	--	--	--	--	--

Breakdown	24/01/2024	07:44	26/01/2024	15:20	434,691	St Leonards	SL043694
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	GRINDING NOISE FROM OFFSIDE						
13 Brakes 1	Telma u/s. Telma replaced.						

SAFETY INSPECTION	09/02/2024	08:00	12/02/2024	08:35	436,263	St Leonards	SL043907
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
85 Body Interior 1	CCTV Nearside outer Camera not working. New cam Tried no picture.						
56 Comms Equipment	Saloon microphone broken. No parts.						
71 Body Exterior 1	Body Exterior O/S/R wheel arch damage -monitor						
71 Body Exterior 2	Body Exterior N/S camera casing						
87 Stretcher	Stretcher wont raise - stopping and starting						
34 Emergency Lights	O/S/R side blue n/w. Replaced.						
34 Emergency Light System	N/S/F roof blue has LED n/w. Monitoring						
02 Glass / Windows	Passenger window switch broken. Replaced.						
55 Tail Lift	Guide block adrift. Resecured.						
86 Door Lock	Scoop locker not unlocking on key. Replaced handle.						
Vehicle Deep Clean	12/02/2024	16:49	13/02/2024	12:53	436,269	St Leonards	SL043947
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	22/02/2024	07:30	22/02/2024	08:00	436,937	St Leonards	SL044092
31 Battery Chassis	Replaced						
02 Pipeline Annual Inspection	19/03/2024	13:27	19/03/2024	13:30	439,591	MDT Weymouth	DW001624
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test:- passed all tests						
Vehicle Deep Clean	21/03/2024	10:30	22/03/2024	12:45	439,591	St Leonards	SL044526
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	22/03/2024	13:30	25/03/2024	15:26	439,591	St Leonards	SL044543
18 Wheels Check Torques							

Safety Inspection							
34 Emergency Light System	N/S/F roof blue has LED n/w. One single led					Monitoring	
86 Doors	Doors side door stuck. NFF						
Brake Fluid Change	Brake Fluid Change						
13 Brakes 1	Front brake pads and discs worn						
13 Brakes 2	Rear brake pads worn						
11 Axle Rear	Rear axle leaking from pan gasket. Replaced						

Vehicle Deep Clean	30/04/2024	12:24	01/05/2024	07:56	444,341	St Leonards	SL045105
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	02/05/2024	11:30	03/05/2024	09:48	444,341	St Leonards	SL045138
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
34 Emergency Light System	N/S/F roof blue has LED n/w. One single led					Monitoring	
MDT Failure/Issue	MDT Failure/Issue mdt intermittently switches off. NFF						
Engine Change Oil & Filter							

Breakdown	08/05/2024	15:37	09/05/2024	08:28	444,341	St Leonards	SL045229
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Hydraulic leak with tail lift
-----------	-------------------------------

Unplanned Repair	11/06/2024	09:00	11/06/2024	10:30	450,917	St Leonards	SL045718
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Power Failure	see notes.
------------------------	------------

SAFETY INSPECTION	17/06/2024	06:00	19/06/2024	13:33	451,455	St Leonards	SL045806
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight..SWL to do.						
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						

02 Windscreen Wipers	Replaced						
43 Exhaust System 1	Replace tail pipe						
17 Tyres Replace	Replace n/s/r/i tyre						
89 Seatbelts	Drivers seat belt frayed					Monitoring	
86 Doors	Tighten passenger door check strap						
Install Saloon CCTV Camera	Re format CCTV hard drive						
85 Body Interior 1	Secure saloon cuboard strip						

Vehicle Deep Clean	17/06/2024	15:16	18/06/2024	16:06	451,445	St Leonards	SL045830
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

AVP Check	21/06/2024	08:35	21/06/2024	10:07	451,656	St Leonards	SL045897
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check						
--------------------	---------------------	--	--	--	--	--	--

AVP Check	24/06/2024	06:20	24/06/2024	08:20	451,905	St Leonards	SL045936
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check						
--------------------	---------------------	--	--	--	--	--	--

AVP Check	25/06/2024	09:00	25/06/2024	10:30	451,963	St Leonards	SL045964
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check						
--------------------	---------------------	--	--	--	--	--	--

AVP Check	26/06/2024	07:10	26/06/2024	08:30	452,043	St Leonards	SL045991
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check						
--------------------	---------------------	--	--	--	--	--	--

AVP Check	27/06/2024	08:30	27/06/2024	10:00	452,151	St Leonards	SL046013
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check						
--------------------	---------------------	--	--	--	--	--	--

AVP Check	28/06/2024	08:10	28/06/2024	09:00	452,213	St Leonards	SL046034
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check						
--------------------	---------------------	--	--	--	--	--	--

AVP Check	01/07/2024	07:00	01/07/2024	09:00	452,577	St Leonards	SL046074
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Complete AVP Check	Carry out AVP check						
--------------------	---------------------	--	--	--	--	--	--

AVP Check	02/07/2024	07:00	02/07/2024	08:30	452,681	St Leonards	SL046089
Complete AVP Check	Carry out AVP check						
AVP Check	03/07/2024	07:41	03/07/2024	09:00	452,734	St Leonards	SL046112
Complete AVP Check	Carry out AVP check						
AVP Check	04/07/2024	06:45	04/07/2024	08:11	452,832	St Leonards	SL046122
AVP Check	04/07/2024	06:45	04/07/2024	08:11	452,832	St Leonards	SL046123
Complete AVP Check	Carry out AVP check						
AVP Check	05/07/2024	09:00	05/07/2024	12:17	452,892	St Leonards	SL046147
Complete AVP Check	Carry out AVP check						
AVP Check	08/07/2024	08:15	08/07/2024	09:50	453,186	St Leonards	SL046179
Complete AVP Check	Carry out AVP check						
AVP Check	09/07/2024	07:00	09/07/2024	08:15	453,261	St Leonards	SL046219
Complete AVP Check	Carry out AVP check						
AVP Check	10/07/2024	07:00	10/07/2024	09:00	453,334	St Leonards	SL046233
Complete AVP Check	Carry out AVP check						
AVP Check	11/07/2024	07:00	11/07/2024	08:30	453,436	St Leonards	SL046248
Complete AVP Check	Carry out AVP check						
AVP Check	12/07/2024	08:30	13/07/2024	09:44	453,513	St Leonards	SL046261
Complete AVP Check	Carry out AVP check						

AVP Check	15/07/2024	08:05	15/07/2024	09:10	453,840	St Leonards	SL046330
Complete AVP Check	Carry out AVP check						
AVP Check	16/07/2024	06:30	16/07/2024	08:30	453,919	St Leonards	SL046342
Complete AVP Check	Carry out AVP check						
AVP Check	17/07/2024	07:30	17/07/2024	09:30	454,003	St Leonards	SL046356
Complete AVP Check	Carry out AVP check						
AVP Check	18/07/2024	06:45	18/07/2024	07:45	454,092	St Leonards	SL046372
Complete AVP Check	Carry out AVP check						
AVP Check	19/07/2024	07:00	19/07/2024	09:45	454,143	St Leonards	SL046409
Complete AVP Check	Carry out AVP check						
AVP Check	22/07/2024	08:04	22/07/2024	09:56	454,503	St Leonards	SL046447
Complete AVP Check	Carry out AVP check						
AVP Check	23/07/2024	06:00	23/07/2024	07:00	454,662	St Leonards	SL046462
Complete AVP Check	Carry out AVP check						
Vehicle Deep Clean	02/08/2024	09:00	05/08/2024	11:00	454,796	St Leonards	SL046662
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	05/08/2024	16:00	07/08/2024	16:00	454,796	St Leonards	SL046689
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Axle Oil Change	Axle Oil Change
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Tail Lift Inspection	
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
01 Air Conditioning 1	Saloon ac system leaking refigridgerant at lp service port. replaced and regassed.
71 Body Exterior 1	Front no plate damaged. replaced. -lift bridge plate guides resecured to body.
02 Cab Assembly 1	Ns window switch replaced - cab int bulb replaced.
86 Door Lock	Rear door central locking actuator stiff. freed off and lubricated mech.
89 Seats	Front swivel attendant seat bearing loose. replaced bearings.
85 Body Interior 1	X3 Saloon locker door hinges loose. resecured.
45 Engine 1	NS lower intercooler hose leaking excessively. replaced.
27 Transmission Automatic	Rear gearbox mount loose, threads worn. repaired threads and refitted mount.
16 Suspension 1	Rear roll bar lower link bushes worn - rear spring eye bushes worn. - replaced.
45 Engine 2	Engine oil cooler leak. removed, cleaned and replaced seals.
Engine Oil & Filter Change	Engine Oil & Filter Change
45 Engine 3	AC Belt tensioner worn and belt split. replaced
13 Brakes 1	Telma relay box water ingress. replaced control box.

Unplanned Repair	29/08/2024	08:45	29/08/2024	09:45	454,890	St Leonards	SL047057
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	EML on. Electrical fault with AdBlue metering valve. replaced and reset.
-------------	--

SAFETY INSPECTION	09/09/2024	06:00	09/09/2024	14:48	454,890	St Leonards	SL047202
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
71 Body Exterior 1	Body Exterior. OSR Lower corner cap damaged. replaced cap and reflector.
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	
01 Air Conditioning 1	Heating A/C inop. Heater resistor and blower faulty. replaced.
02 Windscreen Wipers	Wiper linkage excessively noisy and worn. replaced linkage assembly.
02 Cab Assembly 1	Drivers window switch broken. replaced switch assembly.
86 Doors Rear	Adjusted rear door latches/cables.

Vehicle Deep Clean	11/09/2024	08:12	11/09/2024	11:04	456,361	St Leonards	SL047253
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	06/10/2024	01:41	06/10/2024	12:00	457,490	St Leonards	SL047604
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown Travel Time 45 Engine 1	FUME SMELL IN CAB Travel to Shaftesbury Reported fumes in cab. No fault found
---	---

Vehicle Deep Clean	16/10/2024	09:00	16/10/2024	13:57	461,189	St Leonards	SL047783
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	17/10/2024	09:44	19/10/2024	14:13	461,215	St Leonards	SL047800
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques Safety Inspection 56 Comms Equipment 34 Lighting System Pollen Filter Change MOT 34 Lights Bulb Replacement 86 Door Lock 13 Discs UB Fire Supp Repair Road Test	Checked. Carried out inspection. MDT Failure/Issue mdt intermittently switches off Lighting System Rear L lightbar found damaged during VDI Pollen Filter Change. Done. F/Comms Fri18th @ 13:00. O/S headlight n/w. Replaced bulb. C/L n/w on rear door. Adjusted & lubbed. Rear disc's worn. Repair of UB Fire Supp System.Routed wrong over turbo. Re-route.
---	---

Breakdown	19/11/2024	05:25	19/11/2024	07:22	465,553	St Leonards	SL048291
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown 34 Lights Bulb Replacement	Tail lift not working. Fuse holder damaged swapped with good holder n/s/f DRL not working. Replaced
---	--

SAFETY INSPECTION	27/11/2024	12:00	28/11/2024	12:08	466,290	St Leonards	SL048423
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
71 Body Exterior 1	Body Exterior o/s rear side scratch while turning out of bay						
71 Body Exterior 2	Body Exterior minor scratched on o/s rear						
Tail Lift Inspection	Done.						
13 Brake Pads	Front pads worn. Replaced.						
86 Door Lock	Rear door c/l n/w.Repaired wiring & replaced actuator.						
86 Sliding Door	Key not working lock. Replaced barrel housing.						
02 Cab Assembly 1	Cubby box knob missing. Replaced.						
17 Tyres	Rear tyre extension valves missing. Replaced.						
44 Add Ad Blue	Topped 10Ltrs.						
86 Doors	Side door rollers siezed. Replaced.						
Vehicle Deep Clean	30/11/2024	11:09	01/12/2024	08:49	466,295	St Leonards	SL048465
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/12/2024	05:00	23/12/2024	16:00	468,520	St Leonards	SL048775
55 Tail Lift	Tail lift not working						
34 Lights Bulb Replacement	Replace 2x running light bulbs						
Vehicle Deep Clean	11/01/2025	11:25	28/01/2025	12:00	471,233	St Leonards	SL049067
Vehicle Deep Clean	Vehicle Deep Clean						
Wash Vehicle	MUSHROOMS GROWING INSIDE TRUCK						
SAFETY INSPECTION	15/01/2025	16:57	18/01/2025	10:00	471,233	St Leonards	SL049127
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
Annual Heater Service	Annual Heater Service						
UB Fire Supp 12mts Service	Service of fire supression system						

UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
02 Windscreen Wipers	Washers inop. flushed bottle, cleaned hoses and replaced check valve & connector
71 Body Exterior 1	O/S CCTV lens damaged. replaced.
Tail Lift Inspection	Corrosion on all tail lift.
85 Body Interior 1	LH locker door strike plate adrift. resecured. -equipment strap replaced x1.
42 Coolant System	Coolant reservoir leaking. replaced reservoir and cap.
24 Driveshaft 1	Vibration on road test. Front prop UJ on telma u/s. replaced whole propshaft.
55 Tail Lift	-Bridge plate guides resecured to body. -Bridge plate magnet bracket replaced.

SAFETY INSPECTION	02/03/2025	15:00	04/03/2025	07:06	475,896	St Leonards	SL049756
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
Tail Lift Inspection	
13 Brake Test	
02 Cab Assembly 1	Cab gearstick gaitor split
71 Body Exterior 1	O/S/F Bumper insecure
Pollen Filter Change	Pollen Filter Change
86 Doors	N/S Side door upper magnet check strap bent / insecure
86 Sliding Door	N/S Side door upper catch covering missing
87 - Stretchers/Chairs/Boards	Carry chair bracket seized

Vehicle Deep Clean	04/03/2025	06:00	04/03/2025	12:20	475,908	St Leonards	SL049779
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	18/03/2025	08:00	18/03/2025	09:19	476,713	St Leonards	SL049981
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

15 Steering 1	Pulling to left
03 Instruments & Sensors 1	Multiple warning lights

Breakdown	22/03/2025	13:08	23/03/2025	07:00	476,800	St Leonards	SL050044
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	flat battery, no odometers working in the cab
31 Charging System Battery	Test batteries and charging system, ok.
33 Ignition System	Replace key fob battery
Road Test	

O2 Pipeline Annual Inspection	18/03/2025	13:38	19/03/2025	13:40	476,771	MDT Ferndown	TF004022
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

O2 Pipeline Annual Inspection Annual Inspection and Pressure Test - replaced 1x port seat.

Unplanned Repair	28/03/2025	05:02	28/03/2025	05:05	476,800	St Leonards	SL050099
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

52 Electrical Aux 02 Cab Assembly 1	Other key fob not working, using key to lock/unlock veh Other key fob not working, central locking not working
--	---

Vehicle Deep Clean	18/04/2025	08:20	22/04/2025	08:48	480,126	St Leonards	SL050459
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	21/04/2025	12:00	22/04/2025	07:09	477,099	St Leonards	SL050509
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test Annual Air Con Service Engine Change Oil & Filter UB Fire Suppression Discharge 85 Body Int Alcohol Gel Dispen Done.	Check and Install MDVS windows update.Done. Carried out inspection. Checked. Done. Annual Air Condition Service Under Bonnet Fire Suppression 5 Year Discharge Test
---	--

Breakdown	20/07/2025	14:23	21/07/2025	07:00	491,487	St Leonards	SL052181
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	pigeons damaged passenger's side windscreen
-----------	---

Decommission Vehicle	21/07/2025	15:25			491,487	St Leonards	SL052211
-----------------------------	-------------------	--------------	--	--	----------------	--------------------	-----------------