

WM64JWO	A&E		Poole Amb Stn				
PDI Inspection	19/03/2015	07:00	27/04/2015	12:00	88	St Leonards	SL015921
PDI Inspection	Carried out PDI etc.						
SAFETY INSPECTION	21/04/2015	09:00	21/04/2015	09:00	88	St Leonards	SL016086
18 Wheels Check Torques Safety Inspection Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	02/05/2015	06:33	08/05/2015	08:00	1,307	St Leonards	SL016153
Breakdown	MDT keeps powering down - Raised by logistics. Closed down not seen.						
Unplanned Repair	04/05/2015	16:00	04/05/2015	18:00	1,307	St Leonards	SL016159
87 - Stretchers/Chairs/Boards	Stretcher lock pin u/s. Remove pin.						
Breakdown	09/05/2015	18:00	09/05/2015	19:00	2,059	St Leonards	SL016200
Breakdown Travel Time	a/blue ran out - Top up Ad Blue and educate crews Travel to Poole						
Unplanned Repair	20/05/2015	09:00	20/05/2015	09:00	3,635	St Leonards	SL016271
45 Engine Ad Blue	Top up Ad Blue						
Unplanned Repair	01/06/2015	08:00	01/06/2015	08:00	5,000	St Leonards	SL016343
45 Engine Ad Blue	Top up AD Blue						

Vehicle Deep Clean	03/06/2015	06:30	03/06/2015	14:00	5,377	St Leonards	SL016359
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	03/06/2015	06:30	03/06/2015	16:00	5,377	St Leonards	SL016360
18 Wheels Check Torques Safety Inspection	Carried out by PCS. Paper inspection sheet done.						
Unplanned Repair	13/06/2015	08:00	13/06/2015	08:00	6,587	St Leonards	SL016480
45 Engine Ad Blue	Top up Ad Blue						
Unplanned Repair	19/06/2015	14:35	19/06/2015	15:00	7,682	St Leonards	SL016461
44 Add Ad Blue	Ad-Blue low. Topped 10Ltr						
Breakdown	09/07/2015	04:04	09/07/2015	04:22	10,300	St Leonards	SL016582
Breakdown	Engine has LOP, no amber light though.						
Breakdown	10/07/2015	03:22	10/07/2015	05:22	10,956	St Leonards	SL016594
17 Tyres Replace Breakdown	N/S/R inner tyre Replaced. flat os rear inner tyre						
Breakdown	10/07/2015	03:00	10/07/2015	04:30	10,956	St Leonards	SL016601
Breakdown	flat tyre os inner						
Breakdown	11/07/2015	21:34	11/07/2015	23:00	11,205	St Leonards	SL016603
45 Engine 1 Breakdown	ENG MAN LIGHT - Repaired by Merc 24 ENG MAN LIGHT						

Unplanned Repair	14/07/2015	07:00	23/07/2015	16:00	11,539	St Leonards	SL016625
45 Engine 1	Lack of power - Pentagon to repair Warranty - Replace throttle actuator						
Vehicle Deep Clean	23/07/2015	08:00	23/07/2015	11:00	11,557	St Leonards	SL016693
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/07/2015	08:00	23/07/2015	16:00	11,557	St Leonards	SL016694
18 Wheels Check Torques 34 Lights 71 Body Exterior 1 Safety Inspection	R/R broken OSR side marker lamp OSF wing dented Carried out by PCS. Paper inspection sheet done.					Monitoring	
Breakdown	25/07/2015	07:00	31/07/2015	12:30	11,779	St Leonards	SL016710
45 Engine 1 Breakdown	Lack of power - Warranty - Rygors to repair AMBER ENG MGMT, LIMP MODE						
Unplanned Repair	11/08/2015	08:00	11/08/2015	08:00	13,199	St Leonards	SL016823
45 Engine Ad Blue	Top up Ad Blue						
Unplanned Repair	25/08/2015	12:00	25/08/2015	13:00	14,903	St Leonards	SL016913
86 Doors	Side door not opening from inside.						
Vehicle Deep Clean	27/08/2015	06:30	28/08/2015	11:30	15,172	St Leonards	SL016920
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/08/2015	07:00	28/08/2015	09:00	15,172	St Leonards	SL016921

18 Wheels Check Torques 34 Emergency Lights 71 Body Exterior 1 Safety Inspection	R/R damaged nsr blue lamp cover and LED module OSF wing dented Carried out by PCS. Paper inspection sheet done.		Monitoring				
Breakdown	03/09/2015	03:41	08/09/2015	10:30	15,435	St Leonards	SL016961
Breakdown	Reversing camera not working		Monitoring				
Unplanned Repair	09/09/2015	10:30	09/09/2015	11:00	16,359	St Leonards	SL017008
17 Tyres Replace 45 Engine Ad Blue	Replace worn n/s/f tyre Top up ad blue						
Vehicle Deep Clean	06/10/2015	06:00	07/10/2015	11:00	20,280	St Leonards	SL017163
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/10/2015	06:00	06/10/2015	16:00	20,280	St Leonards	SL017164
17 Tyres Replace 18 Wheels Check Torques 34 Lights 54 Reversing Systems 71 Body Exterior 1 86 Door Lock 87 - Stretchers/Chairs/Boards Safety Inspection 92 - C Service Service C Tail Lift 6 Monthly Inspection	Checklist Defect O/S/F and 4x rear low tread. Replaced x5. Checked. Checklist Defect O/S/R upper outline marker lamp n/w.Replaced(2nd hand part Checklist Defect Rev camera n/w.Repaired. OSF wing dented.Checked,very small dent.Monitor. Checklist Defect Side door not opening from outside.Adjusted. Checklist Defect Scoop board out of date.Checked and redated. Carried out inspection. Carried out C service. Statutory Inspection.Done.						
SAFETY INSPECTION	18/11/2015	07:25	18/11/2015	14:56	26,157	St Leonards	SL017428

02 Cab Assembly 1 13 Brakes 1 18 Wheels Check Torques Safety Inspection MOT Pre Test	Refit glove box. F/Pads & Disc At 50%. Replace at next S/I.					Monitoring	
Vehicle Deep Clean	18/11/2015	07:00	23/11/2015	13:30	26,157	St Leonards	SL017463
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	09/12/2015	21:00	09/12/2015	23:00	28,845	St Leonards	SL017569
34 Lights Bulb Replacement	N/S Headlight u/s . Replace blubs.						
Breakdown	10/12/2015	07:15	10/12/2015	13:15	28,979	St Leonards	SL017570
71 Body Exterior 1 Breakdown	Replace damaged front number plate Broken number plate						
Unplanned Repair	14/12/2015	08:41	14/12/2015	09:00	29,433	St Leonards	SL017597
44 Add Ad Blue	Add Blue low.Topped 15Ltrs						
Vehicle Deep Clean	30/12/2015	07:00	31/12/2015	12:00	31,960	St Leonards	SL017688
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/12/2015	07:00	31/12/2015	12:00	31,960	St Leonards	SL017689
01 Heating 1 13 Brakes 1 18 Wheels Check Torques Safety Inspection	Saloon Heater u/s . Reprogram unit. F/Pads & Disc At 50%. Replace at next S/I.Fitted. Done. Done.						

Unplanned Repair	25/01/2016	11:30	25/01/2016	12:30	35,860	St Leonards	SL017849
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

86 Doors Rear	Rear door stay sheared off.Drill,tap and refitted bar.						
---------------	--	--	--	--	--	--	--

Vehicle Deep Clean	10/02/2016	07:00	16/02/2016	10:00	37,996	St Leonards	SL017954
---------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	10/02/2016	07:00	12/02/2016	16:00	37,996	St Leonards	SL017955
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

16 Suspension 1	Replace rear A.R.B bolt						
18 Wheels Check Torques							
55 Tail Lift	Tail lift audio warning sounding						
86 Doors	Fit plates to OS door						
86 Doors Rear	Rear door stiff to open - WAS warranty - Jon Coles to repair						
87 - Stretchers/Chairs/Boards	Check stretcher clamp & operation NFF & fit missing harness, harness in drawer						
89 Seats	Saloon seat bearings worn - WAS warranty - Jon Coles replaced						
Safety Inspection							
Travel Time							
MOT							

SAFETY INSPECTION	24/03/2016	06:00	24/03/2016	16:00	42,406	St Leonards	SL018209
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

13 Brakes 1	R/ Pads at 50% x	Monitoring
17 Tyres	All R/Tyres at 4.5mm	Monitoring
17 Tyres Replace	Replace N/S/F Tyre.	
18 Wheels Check Torques	Done.	
52 Electrical Aux	N/S Window switch u/s. Replace unit.	
86 Doors	Checklist Defect OSR door difficult to open, & OSR door needs extra. N.F.F.	
89 Seats	Checklist Defect Front attendant seat bearings, WAS warranty.N.F.F	
Safety Inspection	Done.	
Travel Time		

Vehicle Deep Clean	29/03/2016	07:00	29/03/2016	15:00	42,406	St Leonards	SL018218
---------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Breakdown	12/04/2016	01:48	12/04/2016	11:00	44,151	St Leonards	SL018318
------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

34 Lights Bulb Replacement	O/S Headlight u/s. Replace bulb.
Breakdown	Offside headlight-see below. SEE WHAT? MAYBE I NEED SOME GLASSES!!

Unplanned Repair	11/04/2016	15:00	11/04/2016	16:00	44,021	St Leonards	SL018323
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

17 Tyres	All R/Tyres at 4.5mm	Monitoring
17 Tyres Replace	Nail in O/S/F tyre - ATS to replace @ Centre	

Tail Lift Annual Service	14/04/2016	06:30	14/04/2016	14:00	44,540	St Leonards	SL018347
---------------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

44 Fuel System 1	Fuel cap insecure Fit S/H unit.
55 Tail Lift	Bridge plate guide adrift. Remove plate Repair Mount point.
Tail Lift Annual Service	Statutory Inspection and Weight Test
Travel Time	
Tail Lift 6 Monthly Inspection	Statutory Inspection

SAFETY INSPECTION	09/05/2016	09:30	12/05/2016	16:00	47,253	St Leonards	SL018466
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

02 Cab Assembly 1	interior lamp inop, R/R bulb, repair wiring
02 Windows/Glass	R/R damaged OS window switch
13 Brakes 1	brake pedal rubber worn, R/R rear discs and pads
13 Handbrake	excessive lever travel
16 Suspension 1	Advise front lower arm joints slight wear, within tolerance at this inspection
17 Tyres Replace	R/R 4 worn rear tyres, clean faces
18 Wheels Check Torques	
85 Body Interior 1	bag cupbborad door dropped
89 Seats	rear attendant seat arm rests loose
Safety Inspection	
Wheel Hub Flanges Replaceme	
93 - D Service	
Service D	
85 Body Int Alcohol Gel Dispen	
Fit Throw Lines & SOP	
Wheel Studs & Nuts Replaceme	
Handbrake Cable Replacement	Replace rear handbrake cables
Gearbox Oil & Filter Change	

Vehicle Deep Clean	13/05/2016	07:00	13/05/2016	12:00	47,253	St Leonards	SL018498
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	20/05/2016	02:27	27/05/2016	10:00	47,253	St Leonards	SL018532
31 Battery Chassis 56 Comms Equipment Breakdown	Test and replace chassis battery Replace handheld antenna H/H antenna broken						
Unplanned Repair	01/06/2016	16:45	01/06/2016	18:15	49,426	Dorchester	DC014819
86 Sliding Door Travel Time	Unable to open side door.Top catch jammed,remove and refit						
Breakdown	01/06/2016	16:44	01/06/2016	18:15	49,426	St Leonards	SL018599
Breakdown	side door hanging off and loud noise from engine						
SAFETY INSPECTION	21/06/2016	07:00	21/06/2016	16:00	52,296	St Leonards	SL018696
18 Wheels Check Torques 34 Lighting System 34 Lights Safety Inspection Travel Time Reposition grab bag shelf	Done. Repair loom to o/s/r marker light. Replace 2 LED Light units.With S/H Parts. Done. Done. Set at 400mm.						
Vehicle Deep Clean	22/06/2016	09:30	22/06/2016	14:00	52,296	St Leonards	SL018704
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	06/07/2016	11:24	07/07/2016	08:00	54,182	St Leonards	SL018769

45 Engine 1 Breakdown	EML and limp mode. Merc 24 called by Logistics. EML on and in limp mode
--------------------------	--

Vehicle Deep Clean	04/08/2016	08:30	04/08/2016	12:30	57,478	St Leonards	SL018943
---------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Travel Time Vehicle Deep Clean	Vehicle Deep Clean
-----------------------------------	--------------------

SAFETY INSPECTION	04/08/2016	07:00	04/08/2016	16:00	57,478	St Leonards	SL018946
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

18 Wheels Check Torques Safety Inspection	Done. Done.
--	----------------

Unplanned Repair	12/08/2016	16:00	12/08/2016	18:00	58,502	Dorchester	DC015128
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

86 Sliding Door Travel Time	catches hanging off travel to and from
--------------------------------	---

Unplanned Repair	15/08/2016	08:00	15/08/2016	09:00	58,754	St Leonards	SL019011
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

86 Doors 86 Sliding Door	Doors side door alarm wont stop alerting.Adjusted cables and catches. Doors side bracket broken, wont open at all. DF aware.already done.
-----------------------------	--

SAFETY INSPECTION	07/09/2016	07:00	08/09/2016	15:00	61,906	St Leonards	SL019216
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

02 Windscreen Wipers 13 Brakes 1 16 Suspension 1 17 Tyres 18 Wheels Check Torques 45 Engine 1 Safety Inspection Annual Air Con Service Annual Heater Service	Replace wiper blades Replace front pads Replace front shocks and lower susp arms. Replace rear tyre valves Replace belt tensioner and belt. Annual Air Condition Service Annual Heater Service
--	--

Vehicle Deep Clean	09/09/2016	07:00	09/09/2016	10:00	61,906	St Leonards	SL019231
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	03/10/2016	07:59	03/10/2016	08:15	64,876	St Leonards	SL019405
34 Lights Bulb Replacement Breakdown	Replace n/s indicator bulb INDICATOR BULB						
Unplanned Repair	06/10/2016	08:15	06/10/2016	09:15	65,158	St Leonards	SL019446
02 Cab Ass Fire Extinguisher 31 Battery Chassis	Emg Warning Devices fire trace pressure low audio warning. No parts. Test and replace chassis battery						
Unplanned Repair	16/10/2016	12:30	16/10/2016	13:45	66,355	Dorchester	DC015478
71 Body External Steps 86 Sliding Door Travel Time	Side step reported not working.NFF Unable to open side door.Free off top catch and refit						
Breakdown	16/10/2016	12:35	16/10/2016	13:50	66,355	St Leonards	SL019515
Breakdown	sidestep stuck in						
SAFETY INSPECTION	20/10/2016	06:00	21/10/2016	08:55	66,869	St Leonards	SL019555
02 Mirrors 17 Tyres Replace 17 Tyres Tracking 18 Wheels Check Torques 86 Doors Safety Inspection Travel Time UB Fire Suppression Service 92 - C Service Service C Remove Ventilator Brackets Tail Lift 6 Monthly Inspection	N/S wide angle lens broken. Replaced. Front tyres low tread and worn on edges.. Replaced x2. Suspect tracking out tyres wearing unevenly. Checked and adjusted. Checked. Doors side bracket broken, wont open at all. DF aware.Already done. Carried out inspection. Done. Carried out C service. Remove Ventilator Brackets and Fill. Done. Statutory Inspection.Done.Replaced faulty tilt switch.						

Vehicle Deep Clean	21/10/2016	09:00	21/10/2016	15:00	66,869	St Leonards	SL019565
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	04/11/2016	21:25	04/11/2016	22:40	68,433	Dorchester	DC015600
86 Sliding Door Travel Time	Sliding door reported not shutting.Check fault,tighten upper catch						
Breakdown	30/10/2016	12:15	31/10/2016	06:51	67,630	St Leonards	SL019621
86 Sliding Door Breakdown Travel Time	Side door not opening. Repair and adjust top catch. Side Door Jamming Travel to and from Poole Station.						
Breakdown	04/11/2016	21:25	04/11/2016	22:25	68,483	St Leonards	SL019681
Breakdown	SIDE DOOR OPENING IN TRANSIT						
Breakdown	11/11/2016	22:04	11/11/2016	23:04	69,422	St Leonards	SL019740
02 Cab Assembly 1 Breakdown Travel Time	Fire suppression warning - Not sounding at time of test. Crew to monitor FIRE SUPRESS alarm going off Travel to PGH					Monitoring	
Unplanned Repair	26/11/2016	08:00	26/11/2016	10:30	71,642	Dorchester	DC015713
17 Tyres Replace Travel Time	puncture n/s/r out						
Unplanned Repair	01/12/2016	16:30	01/12/2016	18:30	72,376	Dorchester	DC015743
34 Lights Bulb Replacement Travel Time	travel to and from						

Breakdown	01/12/2016	16:57	01/12/2016	17:00	72,373	St Leonards	SL019905
------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Breakdown	Nearside headlight out. Bulb replaced						
-----------	---------------------------------------	--	--	--	--	--	--

Vehicle Deep Clean	05/12/2016	12:00	06/12/2016	11:00	72,852	St Leonards	SL019919
---------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	05/12/2016	08:00	08/12/2016	13:30	72,852	St Leonards	SL019924
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

02 Cab Assembly 1	Fire suppression warning. New unit fitted.						
02 Cab Assembly 2	Fit ECS factsheet. Fitted.						
13 Brakes 1	F/Disc worn but new pads fitted. Replace at next S/I.					Monitoring	
15 Steering 1	Rack leaking Refur to dealers.					Monitoring	
17 Tyres Replace	All 4 R Tyres. 3 with nails. 1 odd tyre fitted. Replace all 4 tyres.						
18 Wheels Check Torques	Done.						
89 Seats	R/Saloon seat u/s . Replace bearings.						
Safety Inspection	Done.						
UB Fire Suppression Service	Fit new unit.Fitted.						

Unplanned Repair	28/12/2016	08:00	30/12/2016	10:00	74,853	St Leonards	SL020122
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

34 Lighting System	N/S top and lower brake lights inop. Jon Coles to repair. WAS Warranty						
34 Lights Bulb Replacement	Replace 2x running light bulbs						

Breakdown	06/01/2017	11:28	08/01/2017	10:00	75,643	St Leonards	SL020204
------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Breakdown	hinge come off mounting tail lift.REmoved,drilland tap,refitted.						
Travel Time	TRavel to and from VMU.						

SAFETY INSPECTION	11/01/2017	07:00	13/01/2017	14:00	76,258	St Leonards	SL020240
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

02 Cab Assembly 1	Fit ECS factsheet. Fitted.						
13 Brakes 1	F/Disc worn but new pads fitted. Fitted Disc & Pads.						
15 Steering 1	Rack leaking Refur to dealers.					Monitoring	

18 Wheels Check Torques	Done.
31 Battery Chassis	Battery u/s. Replace unit.
71 Body Exterior 1	Repair damage to o/s/r lower corner.
86 Door Lock	Repair side door lock cover.
Safety Inspection	Done.
MOT Pre Test	Done.
Medical Device and Equip Chec	Done. unit ok.
Travel Time	
MOT	13/01/2017 . 16.15 Booked.

Vehicle Deep Clean	13/01/2017	08:55	13/01/2017	12:00	76,258	St Leonards	SL020258
---------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	20/01/2017	08:30	20/01/2017	09:00	76,655	St Leonards	SL020322
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

34 Lights Bulb Replacement	O/S Headlight.
----------------------------	----------------

Unplanned Repair	01/02/2017	12:00	01/02/2017	13:00	78,506	St Leonards	SL020417
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

71 Body External Steps	Side step n/w.Checked and replaced.
------------------------	-------------------------------------

Unplanned Repair	10/02/2017	13:00	10/02/2017	15:00	79,826	St Leonards	SL020494
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

01 Heating 1	Saloon heater inop. Check faults and replace fuel pump.
--------------	---

Breakdown	10/02/2017	13:30	10/02/2017	14:29	79,794	St Leonards	SL020495
------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

01 Heating 1 Breakdown	Saloon heater n/w. Checked wiring,checked control box. Replaced fuel pump. HEATER
---------------------------	--

Unplanned Repair	15/02/2017	13:00	15/02/2017	14:30	80,529	St Leonards	SL020539
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

55 Tail Lift	Tail lift run up guide adrift. Repair legs.
--------------	---

SAFETY INSPECTION	27/02/2017	07:00	28/02/2017	16:00	82,469	St Leonards	SL020612
15 Steering 1	Rack leaking?						Monitoring
18 Wheels Check Torques	Done.						
31 Battery Chassis	Chassis battery u/s. Replace unit.						
34 Lighting System	O/S/R Marker light u/s. Repair loom.						
55 Tail Lift	Repair R/Panel & Tail lift runners.						
Safety Inspection	Done.						
Install Saloon CCTV Camera	Carried out by Jon Coles.						
WAS Firetrace rework & Service	Carried out by Jon Coles.						
Handbrake Cable Replacement	NOT REQUIRED AT THIS TIME.						
Vehicle Deep Clean	01/03/2017	09:00	01/03/2017	15:00	82,469	St Leonards	SL020638
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	04/03/2017	15:53	04/03/2017	16:29	82,469	St Leonards	SL020663
Breakdown	FOLLOWING RTC, NOT DRIVEABLE. RCOVER						
Unplanned Repair	05/03/2017	13:00	05/03/2017	14:30	82,970	Dorchester	DC016229
13 Brakes 1 Travel Time	Poor brakes reported.Trace to cracked servo tank.Carry out temp repair.					Awaiting Parts	
Unplanned Repair	12/03/2017	08:00	12/03/2017	10:00	82,970	Dorchester	DC016272
34 Lighting System Travel Time	bad connection on repeater travel to and from						
Unplanned Repair	16/03/2017	14:15	16/03/2017	14:45	84,497	St Leonards	SL020763
34 Lights Bulb Replacement 71 Body Exterior 1	Replace n/s side repeater bulb Fit CCTV sticker to rear door.						

Breakdown	01/04/2017	19:21	01/04/2017	21:21	86,436	St Leonards	SL020881
71 Body External Steps Breakdown	Step u/s. Remove loom Repair & Refit. sidestep u/s						
SAFETY INSPECTION	05/04/2017	08:25	07/04/2017	11:00	86,978	St Leonards	SL020904
02 Windscreen Wipers	Replace both units.						
13 Brakes 1	Poor brakes reported.Trace to cracked servo tank. Replace tank.						
15 Steering 1	Rack leaking? NEEDS PUMP. Parts ordered.						Monitoring
17 Tyres Replace	O/S/F Tyre u/s . Replace unit.Also O/S/R Nail . Replace unit.						
18 Wheels Check Torques	Done.						
34 Emergency Light System	2x rear blue light lens cracked - Parts ordered.						Monitoring
56 Comms Equipment	Repair wall mount.						
89 Seats	Both saloon seats loose . Adjust both.						
Safety Inspection	Done.						
93 - D Service	Done.						
Service D	Done.						
Annual Heater Service	Annual Heater Service. Done.						
Annual Air Con Service	Annual Air Condition Service. Done.						
Tail Lift Annual Service	Statutory Inspection and Weight Test. Done by S.W.L						
Tail Lift 6 Monthly Inspection	Statutory Inspection. Done by S.W.L						
Vehicle Deep Clean	07/04/2017	07:30	07/04/2017	11:10	86,978	St Leonards	SL020919
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	26/04/2017	09:30	26/04/2017	10:00	89,088	St Leonards	SL021055
34 Lights	Side repeater inop done						
86 Sliding Door	Side door top catch insecure done						
Unplanned Repair	04/05/2017	09:00	04/05/2017	09:30	90,191	St Leonards	SL021109
86 Sliding Door	Re fit and secure top catch.						

Vehicle Deep Clean	18/05/2017	08:00	18/05/2017	11:15	92,397	St Leonards	SL021218
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/05/2017	07:00	19/05/2017	13:00	92,397	St Leonards	SL021225
15 Steering 1	Rack leaking? NEEDS PUMP. Parts ordered. replaced pump replaced near side front tyre done Test comms battery no fult found at time of test 2x rear blue light lens cracked - Parts ordered. replaced Ramp/Lift/Tail Hoist flap bent repaired MGS Gas Storage Modifications replaced parts carry out inspection						
17 Tyres Replace							
18 Wheels Check Torques							
31 Battery Comms							
34 Emergency Light System							
55 Tail Lift							
MGS Gas Storage Modifications							
Safety Inspection							
Unplanned Repair	05/06/2017	13:00	05/06/2017	14:50	94,053	St Leonards	SL021381
31 Battery Comms	Comms power failing. Test and replace battery						
Unplanned Repair	08/06/2017	10:45	08/06/2017	11:20	94,530	St Leonards	SL021417
86 Sliding Door	Side door top catch adrift . refit top catch MGS Gas Storage Modifications. Done. Carried out on 19/05/2017 (SL021225)						
MGS Gas Storage Modifications							
Unplanned Repair	14/06/2017	10:30	14/06/2017	12:00	95,387	St Leonards	SL021470
13 Brakes 1	Knocking noise from rear CHECKED CALIPER BOLTS OK TIGHTEN BOLTS ON REAR ALXE AND ANTIROLL BAR						
16 Suspension 1							
Unplanned Repair	26/06/2017	08:00	26/06/2017	08:30	96,913	St Leonards	SL021539
87 Stretcher Harness Replaced	Replace stretcher and carry chair straps						
SAFETY INSPECTION	28/06/2017	07:30	29/06/2017	14:00	97,192	St Leonards	SL021562
13 Brakes 1	Knocking noise from rear - Check and report [] no fult found]						

17 Tyres Replace	replace near side rear tyres						
18 Wheels Check Torques	done						
87 Stretcher	O2 bag damaged						
Safety Inspection	carry out inspection						
Gearbox Oil & Filter Change	carry out gear box oil and filter change						
Vehicle Deep Clean	30/06/2017	07:00	30/06/2017	11:30	97,192	St Leonards	SL021589
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	11/08/2017	16:30	11/08/2017	17:00	99,976	St Leonards	SL021925
71 Body External Steps	reported step not closing [checked step ok at time of test]						
Vehicle Deep Clean	14/08/2017	08:45	14/08/2017	14:00	100,112	St Leonards	SL021932
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/08/2017	07:00	15/08/2017	12:30	100,112	St Leonards	SL021934
18 Wheels Check Torques	DONE						
34 Lights	REPAIR WIRING ON NEAR SIDE REAR TOP SIDE LIGHT						
55 Tail Lift	Body Exterior Tail lift hinged bracket buckleed REPAIRED						
71 Body Exterior 1	REPAIR CUBBARD DOOR						
86 Sliding Door	REPLACE MIDDLE BEARINGS						
87 Stretcher	O2 bag damaged						
Safety Inspection	CARRY OUT INSPECTION						
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card DONE						
SAFETY INSPECTION	21/09/2017	07:00	26/09/2017	12:30	102,747	St Leonards	SL022239
13 Brake Pads	Front pads worn. Replaced.						
16 Suspension 1	Front struts and lower ball joints worn. Replaced struts & lower arms.						
17 Tyres Replace	O/S/R/I low tread. Replaced.						
18 Wheels Check Torques	Checked.						
87 Stretcher	O2 bag damaged.Ordered new.						
89 Seatbelts	Crew seat in saloon seatbelt not retracting. Ordered parts.Replaced.						

Monitoring

Monitoring

Safety Inspection	Carried out inspection.
Tail Lift 6 Monthly Inspection	Statutory Inspection

Vehicle Deep Clean	26/09/2017	09:17	26/09/2017	13:00	102,747	St Leonards	SL022266
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	04/10/2017	17:23	10/10/2017	14:00	103,365	St Leonards	SL022344
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1 Breakdown	Turbo u/s - Pentagon to repair (Warranty) Turbo replaced. limp mode
-----------------------	--

Unplanned Repair	11/10/2017	08:00	12/10/2017	14:30	103,417	St Leonards	SL022396
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

001 Recover Vehicle 45 Engine 1	Vehicle Recovery from Poole to Ferndown Fan belt adrift.strip belt and tenstioners[replace belts ans tenstioners]
------------------------------------	---

Breakdown	25/10/2017	11:42	25/10/2017	15:00	103,417	St Leonards	SL022508
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

87a - Medical Equipment Repair Breakdown	Repair broken wire on suction charging unit. SUCTION CHARGING UNIT ON VEH FAULT
---	--

Unplanned Repair	27/10/2017	12:00	27/10/2017	12:15	104,521	St Leonards	SL022527
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights Bulb Replacement	Replace side repeater bulb
----------------------------	----------------------------

SAFETY INSPECTION	02/11/2017	07:00	03/11/2017	13:14	104,879	St Leonards	SL022559
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Ass Fire Extinguisher	Out of date.Replaced.
02 Windscreen	Replace washer bottle cap
15 Steering 1	Steering rack leaking.Replaced rack.
17 Tyres Replace	O/S/R/O,&O/S/F low tread. Replaced.
17 Tyres Tracking	Uneven tyre wear on front. Reset tracking.

18 Wheels Check Torques	Checked.
71 Body Exterior Acc Repair	Both rear lower corner caps smashed.
87 Stretcher	Fit missing O2 bag
Safety Inspection	Carried out inspection.
UB Fire Suppression Service	Done.

Vehicle Deep Clean	06/11/2017	07:21	06/11/2017	11:00	104,879	St Leonards	SL022582
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	08/11/2017	13:15	08/11/2017	13:45	105,090	St Leonards	SL022615
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Lub side step runners
86 Sliding Door	Secure top side door catch

Unplanned Repair	27/11/2017	09:00	27/11/2017	09:30	106,728	St Leonards	SL022771
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Sliding Door	Re fit side door lock and adjust.
-----------------	-----------------------------------

SAFETY INSPECTION	14/12/2017	09:01	04/01/2018	11:00	107,881	St Leonards	SL022908
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Ass Fire Extinguisher	Out of date. Replaced.						
13 Brakes 1	Replace R/Disc & Pads next S/I.	14/12/2017.					Monitoring
13 Brakes 2	F/ Disc worn replace next S/I.						Monitoring
18 Wheels Check Torques	Checked.						
45 Engine 1	Turbo U/S Rygors to repair.						
71 Body External Steps	Step n/w intermitantly.						
86 Door Lock	Side door lock cover damaged. Parts ordered.						Monitoring
86 Door Seals	Small spit to O/S/F Door seal						Monitoring
Safety Inspection	Carried out inspection.						
92 - C Service	Carried out C service.						
Service C							
MOT Pre Test							

Vehicle Deep Clean	18/12/2017	09:56	18/12/2017	14:00	107,881	St Leonards	SL022937
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	24/01/2018	07:00	26/01/2018	16:00	109,315	St Leonards	SL023210
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

13 Brakes 1	Replace R/Disc & Pads next S/I. 14/12/2017.	
13 Brakes 2	F/ Disc worn replace next S/I.	
17 Tyres	Replace N/S/F Tyre Due to side wall damage.	
18 Wheels Check Torques	Done.	
34 Lighting System	Replace n/s headlight next inspection. Loom to change. Headlamp booked out.	Monitoring
34 Lights	Replace Damaged O/S/R Tail light unit.	
44 Add Ad Blue	Fill up Add Blue.	
52 Electrical Aux	Replace n/s Damaged window swich.	
56 Comms Equipment	Repair damaged speaker.	
71 Body Exterior 1	Repair Acc Damaged to F/End.	
71 Body Exterior Acc Repair	Body Exterior side step not retracting. Repair damaged step. Unreported Acc.	
86 Door Lock	Side door lock cover damaged. Parts ordered.	
86 Door Seals	Small spit to O/S/F Door seal. Replace damaged seal.	
86 Sliding Door	Repair unreported side door damage.	
Safety Inspection	Done.	
Wheel Hub Flanges Replaceme	Replace both F/Flanges.	
Travel Time		
MOT		

Vehicle Deep Clean	29/01/2018	11:04	30/01/2018	09:00	109,315	St Leonards	SL023248
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	12/02/2018	13:00	12/02/2018	14:00	110,234	St Leonards	SL023369
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Side step not returning. Clean up & Lube
------------------------	--

Unplanned Repair	24/02/2018	09:00	24/02/2018	11:00	110,967	St Leonards	SL023491
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Side step inop - No fault @ time of test
Travel Time	Travel to Poole

SAFETY INSPECTION	07/03/2018	07:00	09/03/2018	12:30	111,649	St Leonards	SL023578
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windows/Glass	replace off side window switch
16 Suspension 1	replaxce off side rear spring buffers
18 Wheels Check Torques	done
34 Lighting System	Replace n/s headlight next inspection. Loom to change. Headlamp booked out.
34 Lights Bulb Replacement	Replace interior light bulb [done]
Safety Inspection	carry out inspections
85 Body Int Alcohol Gel Dispen	
Wheel Hub Flanges Replaceme	Flanges replaced last inspection
Handbrake Cable Replacement	Replace rear handbrake cables [done]
Tail Lift 6 Monthly Inspection	Statutory Inspection
Tail Lift Annual Service	Statutory Inspection and Weight Test

Vehicle Deep Clean	07/03/2018	10:47	08/03/2018	08:52	111,649	St Leonards	SL023580
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	10/04/2018	09:30	11/04/2018	07:36	113,881	St Leonards	SL023833
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Charging System	Alternator u/s. Replaced.
--------------------	---------------------------

SAFETY INSPECTION	19/04/2018	07:30	20/04/2018	15:00	114,637	St Leonards	SL023919
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
86 Doors Rear	Top catch insecure. Secured.
Safety Inspection	Carried out inspection.
Fit Poster Holder	Fit Poster Holder. Done.
Annual Heater Service	Annual Heater Service.Done.Replaced burner tube and exhaust.

Vehicle Deep Clean	20/04/2018	11:30	23/04/2018	15:00	114,637	St Leonards	SL023939
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	28/05/2018	08:00	28/05/2018	10:56	117,086	St Leonards	SL024220
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

UB Fire Suppression Service	Leaking unit .Fit new system.						
-----------------------------	-------------------------------	--	--	--	--	--	--

Breakdown	30/05/2018	12:24	07/06/2018	08:00	117,194	St Leonards	SL024233
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Ejection of Shoreline Charger						
-----------	-------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	08/06/2018	07:00	08/06/2018	13:00	117,894	St Leonards	SL024289
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

17 Tyres Replace	Both N/S/R Tyres at 4.6mm	Monitoring
18 Wheels Check Torques	Done.	
27 Transmission Automatic	Small oil leak.	Monitoring
44 Add Ad Blue	Fill up 15 L.	
45 Engine 1	small oil leak.	Monitoring
52 Electrical Aux	N/S. window switch u/s. No parts.	Monitoring
89 Seats	Repair saloon seat.	
Safety Inspection	Done.	
Annual Air Con Service	Annual Air Condition Service	

SAFETY INSPECTION	16/07/2018	07:00	17/07/2018	09:06	120,770	St Leonards	SL024611
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Assembly 1	Bulkhead gromet torn. Replaced.	
17 Tyres Fit Winter	Replaced x6.Cleaned all rims and flanges.	
17 Tyres Replace	Both N/S/R Tyres at 4.6mm	
18 Wheels Check Torques	Checked.	
27 Transmission Automatic	Small oil leak.	Monitoring
34 Lights	Replace o/s/f headlight.Replaced.	
45 Engine 1	small oil leak.	Monitoring
52 Electrical Aux	N/S. window switch u/s. No parts.Replaced.	
Safety Inspection	Carried out inspection.	

Vehicle Deep Clean	17/07/2018	09:36	17/07/2018	09:38	120,770	St Leonards	SL024625
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Vehicle Deep Clean	17/07/2018	09:38	17/07/2018	12:30	120,770	St Leonards	SL024626
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	22/07/2018	09:00	23/07/2018	10:00	121,200	St Leonards	SL024685
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

01 Heating 1	Replace cab heater motor
52 Electrical Aux	Fan motor not working. Crew no show twice.

SAFETY INSPECTION	22/08/2018	07:00	24/08/2018	07:34	123,318	St Leonards	SL024932
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

01 Heating 1	Electrical Auxs Heater fan not working.No Fault found @ time of test.	
13 Brake Pads	Rear pads worn. Replaced.	
17 Tyres Replace	N/S/R/I punctured. Replaced.	
18 Wheels Check Torques	Checked.	
27 Transmission Automatic	Small oil leak.	Monitoring
45 Engine 1	small oil leak.	Monitoring
87a - Medical Equipment Repair	Med Equip & Devices ECTO2 unit not being recognized by EPCR/MobiMed	
Safety Inspection	Carried out inspection.	
Tail Lift 6 Monthly Inspection	Statutory Inspection	
93 - D Service	Carried out D service.	
Service D		

Vehicle Deep Clean	24/08/2018	08:00	24/08/2018	13:55	123,318	St Leonards	SL024947
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	30/08/2018	12:15	30/08/2018	13:15	123,693	St Leonards	SL024989
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior 1	Tail lift guide blocks adrift - Temp repair carried out	Monitoring
--------------------	---	------------

Breakdown	23/09/2018	08:54	02/10/2018	10:00	125,454	St Leonards	SL025162
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Side step fault. Switch required. Defect moved to insp job card.	Monitoring
Breakdown	side step deployed despite door being shut Step switch required	Monitoring

SAFETY INSPECTION	08/10/2018	08:00	17/10/2018	16:00	126,598	St Leonards	SL025275
02 Cab Ass Fire Extinguisher	Monitoring						
02 Cab Assembly 1							
02 Windscreen Wipers							
13 Brakes 1							
13 Brakes 2							
16 Suspension 1							
18 Wheels Check Torques							
27 Transmission Automatic							
34 Lights							
44 Add Ad Blue							
45 Engine 1							
71 Body Exterior 1							
71 Body Exterior 2							
71 Body Exterior 3							
71 Body External Steps							
85 Body Interior 1							
Breakdown							
Safety Inspection							
Wear & Tear Repair							
UB Fire Suppression Service							
	Replace both cab & saloon.						
	Replace cab torch.						
	Replace units.						
	Replace F/Pads.						
	Replace peddle rubber.						
	Play in both F/Lower arms but not 3.5 mm.						
	Done.						
	Gearbox oil leak - Pentagon to repair						
	Repair unreported damage to N/S Headlight.N/S wing.F Bumper.F.Panel.						
	Top up 10L						
	Engine oil leak - Pentagon to repair						
	Tail lift . Repair Damaged Tail lift rails. Repair damaged R/Panel.						
	Repair unreported damaged roof & N/S/R . E.M.G unit.						
	Repair unreported damage to middle of roof . remove what is left of air port lig						
	Replace Damaged side step.						
	Repair damaged storage unit.						
	Replace Damaged side step.						
	Done.						
	Replace locker straps						
	Done.						
Vehicle Deep Clean	18/10/2018	08:30	18/10/2018	12:00	126,631	St Leonards	SL025376
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	01/11/2018	13:00	01/11/2018	15:00	127,648	St Leonards	SL025499
86 Sliding Door	Side door outer handle snapped off. Replace handle.						
BREAKDOWN	03/11/2018	12:28	03/11/2018	14:28	127,809	St Leonards	SL025507
71 Body External Steps	Keeps coming out as runing . Adjust switch.						

Vehicle Deep Clean	15/11/2018	09:39	15/11/2018	13:30	128,670	St Leonards	SL025587
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/11/2018	08:00	16/11/2018	15:00	128,670	St Leonards	SL025591
16 Suspension 1	Play in both F/Lower arms but not 3.5 mm.					Monitoring	
18 Wheels Check Torques							
85 Body Interior 1	rear door not closing properly. Adjusted						
Safety Inspection							
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab						
Sealing of stretcher clamp	Sealing of stretcher clamp						
Breakdown	21/12/2018	20:02	22/12/2018	10:28	130,784	St Leonards	SL025906
31 Battery Chassis	Replace unit.						
52 Electrical Aux	Repair loom to fire suspension.						
Breakdown	Fire Suspension Off Line						
BREAKDOWN	23/12/2018	10:00	23/12/2018	12:00	130,785	St Leonards	SL025908
MDT Failure/Issue	Reset unit.						
Breakdown	23/12/2018	12:30	23/12/2018	14:30	130,893	St Leonards	SL025910
87a - Medical Equipment Repair	Temp repair done on stretcher arm.						
Breakdown	Side of stretcher not deploying						
SAFETY INSPECTION	02/01/2019	07:00	04/01/2019	08:15	131,679	St Leonards	SL025949
02 Windscreen Wipers	O/S washer jet n/w. Cleaned & adjusted.						
16 Suspension 1	Play in both F/Lower arms but not 3.5 mm.						
16 Suspension 2	Rear spring buffers torn & leaves out of alignment. Replaced and align.						
18 Wheels Check Torques	Checked.						
89 Seats	Fit seat adjuster hand wheel.						
Safety Inspection	Carried out inspection.						

MOT Pre Test
Travel Time
MOT

Vehicle Deep Clean	03/01/2019	07:00	03/01/2019	12:30	131,679	St Leonards	SL025967
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	30/01/2019	13:00	30/01/2019	14:00	133,736	St Leonards	SL026191
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine Ad Blue 89 Seats	Top up Ad blue Other rear swivel seat in saloon stuck. Replace seat plunger
-------------------------------	--

Vehicle Deep Clean	07/02/2019	08:46	07/02/2019	11:30	134,275	St Leonards	SL026251
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/02/2019	08:00	08/02/2019	15:00	134,275	St Leonards	SL026252
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques 43 Exhaust System 1 44 Add Ad Blue Safety Inspection Tail Lift 6 Monthly Inspection Tail Lift Annual Service	Exhaust rusted away. Replace unit. Top up 9L. Statutory Inspection Statutory Inspection and Weight Test
---	--

SAFETY INSPECTION	25/03/2019	07:00	28/03/2019	11:59	137,500	St Leonards	SL026589
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Assembly 1 17 Tyres Replace 17 Tyres Tracking 18 Wheels Check Torques 85 Body Interior 1 Safety Inspection Handbrake Cable Replacement Annual Air Con Service Annual Heater Service	Torch n/w. Replaced battery. Both front &O/S/R/I&O,N/S/R/O. low tread. Replaced x5.Clean rims & flanges Wearing outer edge N/S/F.Adjusted tracking. Checked. Chair brakel broken. Replaced. Carried out inspection. Replace rear handbrake cables.Done. Annual Air Condition Service Annual Heater Service.Done.
--	--

Vehicle Deep Clean	25/03/2019	09:33	25/03/2019	11:30	137,500	St Leonards	SL026591
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	24/04/2019	10:30	24/04/2019	11:30	139,556	St Leonards	SL026822
52 Electrical Aux	EPCR not charging. Carry out checks and replace blown fuse, test, ok.						
Breakdown	27/04/2019	20:38	01/05/2019	07:56	139,787	St Leonards	SL026840
Breakdown Travel Time	side door cannot open from outside Travel to and from Poole Stn.						
Vehicle Deep Clean	01/05/2019	09:32	01/05/2019	13:00	140,009	St Leonards	SL026866
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	01/05/2019	07:00	03/05/2019	08:01	140,009	St Leonards	SL026867
18 Wheels Check Torques	Checked.						
86 Sliding Door	Outer handle faulty.Repaired. replaced top catch & screws.						
Safety Inspection	Carried out inspection.						
Engine Change Oil & Filter	Done.						
Breakdown	11/06/2019	18:20	12/06/2019	07:00	142,816	St Leonards	SL027190
Breakdown	grinding/groaning from rear axle - Defect moved to inspection job card					Monitoring	
SAFETY INSPECTION	12/06/2019	07:00	17/06/2019	08:00	142,828	St Leonards	SL027191
13 Brakes 1	Rear disc's & pads worn. Replaced.						
18 Wheels Check Torques	Checked.						
34 Lights Bulb Replacement	Lighting System Faulty side indicator						
Breakdown	grinding/groaning from rear axle.Checked No fault @ time of test.						
Safety Inspection	Carried out inspection.						
WAS Firetrace rework & Service	Fire suppression low pressure warning sounding.Waiting new parts					Monitoring	

Vehicle Deep Clean	12/06/2019	09:25	12/06/2019	12:30	142,828	St Leonards	SL027193
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	28/06/2019	22:34	02/07/2019	16:00	143,542	St Leonards	SL027313
Breakdown	Satnav Freezing						
Breakdown	06/07/2019	15:48	06/07/2019	17:48	143,542	St Leonards	SL027365
Breakdown Travel Time	Left indicator gone Travel to and from Poole Station.Vehicle left on job.Cancelled.						
Unplanned Repair	20/07/2019	11:00	20/07/2019	12:30	145,643	Dorchester	DC020537
03 Instruments & Sensors 1 34 Lighting System Travel Time	Fire suppression sytem low presure warning on.See notes n/s repeater intermittent,clean contacts					Partially Completed	
SAFETY INSPECTION	25/07/2019	07:00	30/07/2019	08:30	146,009	St Leonards	SL027505
01 Air Conditioning 1 03 Instruments & Sensors 1 13 Brakes 1 17 Tyres 18 Wheels Check Torques Safety Inspection WAS Firetrace rework & Service Tail Lift Inspection	WAS A/C N/W. Paul Numford to repair.(Condensor fan). Fire suppression sytem low presure warning on.See notes Front disc's and pads worn. Replaced. N/S/R/I tyre low tread. Replaced. Checked. Carried out inspection. Fire suppression low pressure warning sounding.Waiting new parts Done.					Monitoring	
Vehicle Deep Clean	30/07/2019	09:42	30/07/2019	14:00	146,009	St Leonards	SL027536

Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	27/08/2019	07:59	27/08/2019	10:00	148,579	St Leonards	SL027728
Breakdown	205/75R16C Mich Alpin Agilis nail in osr outer						
SAFETY INSPECTION	06/09/2019	07:00	06/09/2019	15:00	149,192	St Leonards	SL027827
02 Cab Ass Fire Extinguisher	Out of date x2. Replaced x2.						
02 Cab Assembly 1	Passenger window switch broken. Replaced.						
18 Wheels Check Torques	Checked.						
55 Tail Lift	Bridge plate guide block adrift. Resecured.						
85 Body Interior 1	Cupboard door not closing. Repaired.						
87 Stretcher Harness Replaced	Pedi-mate missing. Supply another.						
Safety Inspection	Carried out inspection.						
WAS Firetrace rework & Service	Fire suppression low pressure warning sounding.Waiting new parts. Jon Coles					Monitoring	
Vehicle Deep Clean	09/09/2019	09:00	09/09/2019	13:30	149,192	St Leonards	SL027849
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	03/10/2019	08:00	03/10/2019	11:00	151,110	St Leonards	SL028069
WAS Firetrace rework & Service	Fire suppression low pressure warning sounding.Waiting new parts. Jon Coles					Monitoring	
SAFETY INSPECTION	15/10/2019	08:00	18/10/2019	09:00	152,016	St Leonards	SL028169
17 Tyres	n/s/f worn						
18 Wheels Check Torques	Checked.						
45 Engine Oil Top Up	top up						
55 Tail Lift	N/S gate adrift. Resecured.						
86 Sliding Door	Body Exterior Side door will not open from outside						
Check Winter Pack	Checked.						

Safety Inspection Carried out inspection.
 WAS Firetrace rework & Service Fire suppression low pressure warning sounding.Waiting new parts. Jon Coles
 UB Fire Supp 12mts Service Service of fire supression system - Bottle replaced by Jon Coles

Vehicle Deep Clean 15/10/2019 13:00 17/10/2019 15:00 152,016 St Leonards SL028175

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 11/11/2019 15:51 19/11/2019 08:11 153,878 St Leonards SL028404

Breakdown base radio not turning on.NO SHOW @ W/SHOP

Unplanned Repair 20/11/2019 07:54 20/11/2019 11:39 154,497 St Leonards SL028461

Referb fire suppression system System faulty.J.Coles to repair.

SAFETY INSPECTION 10/12/2019 08:56 12/12/2019 16:00 155,938 St Leonards SL028600

18 Wheels Check Torques
 34 Lights Bulb Replacement Replace n/s/f runing light.
 44 Add Ad Blue Top un unit. 15L
 Safety Inspection
 Tail Lift Inspection
 MOT

Vehicle Deep Clean 11/12/2019 07:15 11/12/2019 10:30 155,938 St Leonards SL028614

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN 08/01/2020 11:00 08/01/2020 12:01 157,887 Dorchester DC021556

42 Coolant System level light on

SAFETY INSPECTION	23/01/2020	07:00	28/01/2020	07:44	159,177	St Leonards	SL028947
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Ass Fire Extinguisher	Saloon extinguisher out of date. Replaced.
02 Cab Assembly 1	Drivers window switch broken. Replaced.
17 Tyres Replace	O/S/F,O/S/R/I& N/S/R/O low tread. Replaced x3
18 Wheels Check Torques	Checked.
45 Engine 1	Noisey pulley? Replaced water pump.
45 Engine Oil Top Up	Topped 1 ltr.
Safety Inspection	Carried out inspection.
Brakes Replace Brake Fluid	Done.
Tail Lift Inspection	Done.

Vehicle Deep Clean	29/01/2020	08:58	29/01/2020	12:00	159,177	St Leonards	SL029008
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	16/03/2020	07:00	17/03/2020	16:00	163,861	St Leonards	SL029350
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windscreen Wipers	Replace both units.
18 Wheels Check Torques	Checked.
44 Add Ad Blue	Top up unit. 14L. Unable to book out 14L of add blue as stock in balance.
71 Body Exterior 1	Unreported Rear End DAMAGE.Replace both R/Clusters 7 light units & More.
85 Body Interior 1	Repair damaged storage unit.
86 Door handle	Doors side door handle stuck
Safety Inspection	Checked.
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight Soft close not working ????
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test. Unit replaced 16/10/19

Vehicle Deep Clean	16/03/2020	10:40	17/03/2020	13:30	163,861	St Leonards	SL029351
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	04/04/2020	09:29	04/04/2020	12:00	165,974	St Leonards	SL029502
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	None Starter
-----------	--------------

SAFETY INSPECTION	08/04/2020	07:00	13/04/2020	16:00	166,329	St Leonards	SL029533
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	Replace both Damaged Mirrors.
02 Windscreen Wipers	Windscreen windscreen washers not working
13 Brakes 1	Replace F/ Disc & Pads.
13 Brakes 2	Replace R/Pads.
16 Suspension 1	Replace both lower arms.
16 Suspension 2	Replace both F/Struts.
17 Tyres Replace	Replace N/S/R Inner. Replace O/S/R Inner.
18 Wheels Check Torques	Checked.
31 Battery Chassis	replace unit. 019
44 Add Ad Blue	Top up uinit 9L.
45 Engine 1	EML on. Fit 2 new temp sensors
Fire suppression Service	Fire suppression - Deployed warning
Safety Inspection	Checked.
Pollen Filter Change	Pollen Filter Change
Fuel Filter Change	Change Fuel Filter
Air Filter Change	Air Filter Change
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service No parts.
Replace Handbrake Cables	Replace Handbrake Cables
Engine Change Oil & Filter	Done.
Tail Lift Inspection	Done.
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service

Monitoring

Vehicle Deep Clean	14/04/2020	09:29	14/04/2020	12:00	166,329	St Leonards	SL029587
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	13/05/2020	07:00	18/05/2020	09:00	169,182	St Leonards	SL029853
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

17 Tyres Replace	Replace o/s/f tyre
18 Wheels Check Torques	
45 Engine 1	Injectors leaking - Marshall to replace
85 Body Interior 1	Re fit saloon window rubber and repair damaged draw
Annual Heater Service	Annual Heater Service No parts.
Safety Inspection	

Monitoring

Vehicle Deep Clean	19/05/2020	09:03	19/05/2020	12:30	169,182	St Leonards	SL029923
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	21/05/2020	11:48	21/05/2020	12:30	169,254	St Leonards	SL029947
56 Comms Equipment Breakdown	Test comms battery and re set comms. MDT						
SAFETY INSPECTION	26/06/2020	07:00	30/06/2020	11:30	173,119	St Leonards	SL030258
02 Cab Assembly 1	Replace dash surround trim panel and fuse box cover.Replaced.						
16 Suspension 1	Replace rear shock absorbers						
17 Tyres Replace	N/S/F tyre low tread. Replaced.						
17 Tyres Tracking	Wearing N/S/F Outer. Reset tracking.						
18 Wheels Check Torques	Checked.						
45 Engine 1	Cam chain noisy on cold start. Monitor						
Annual Heater Service	Annual Heater Service.Done.						
Safety Inspection	Carried out inspection.						
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
Tail Lift Inspection	Done.						
Vehicle Deep Clean	29/06/2020	13:48	30/06/2020	10:00	173,119	St Leonards	SL030278
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	07/08/2020	10:00	12/08/2020	12:00	177,421	St Leonards	SL030652
02 Cab Ass Fire Extinguisher	Replace fire extinguisher						
02 Cab Assembly 1	secure cab centre console						
13 Brakes 1	Replace rear discs and pads						
13 Brakes 2	Replace brake light switch						
16 Suspension 1	Replace rear leaf springs, rear shcoks and a.r.b bushes						
18 Wheels Check Torques							
45 Engine 1	Cam chain noisy on cold start. Monitor						

Monitoring

Monitoring

85 Body Interior 1	Secure paperwork storage holder
89 Seatbelts	
Safety Inspection	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card

Vehicle Deep Clean	12/08/2020	10:51	13/08/2020	08:00	177,421	St Leonards	SL030687
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	17/08/2020	09:16	17/08/2020	09:16	177,421	St Leonards	SL030722
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	misfuel of 5 litres petrol
-----------	----------------------------

Breakdown	18/08/2020	04:05	18/08/2020	04:05	177,998	St Leonards	SL030732
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	MDT powering down
-----------	-------------------

Breakdown	09/09/2020	01:55	09/09/2020	09:16	180,300	St Leonards	SL030923
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Power failure. Not charging properly
-----------	--------------------------------------

SAFETY INSPECTION	16/09/2020	07:00	17/09/2020	15:00	180,865	St Leonards	SL030996
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windows/Glass	Replace n/s window switch
17 Tyres Replace	Replace 3x tyres - O/S/F, O/S/R and N/S/R
18 Wheels Check Torques	
44 Add Ad Blue	Top up ad blue
45 Engine 1	Cam chain noisy on cold start. Monitor
85 Body Interior 1	Secure cab centre console hinge and phone holder
Safety Inspection	
Tail Lift Inspection	

Monitoring

Vehicle Deep Clean	18/09/2020	09:29	18/09/2020	14:00	180,865	St Leonards	SL031027
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	23/09/2020	14:00	24/09/2020	13:00	181,014	St Leonards	SL031073
56 Comms Equipment	MDT has no signal - PCE/HALLS/IT/LOGISTICS TO REPAIR						
Breakdown	01/10/2020	17:22	02/10/2020	11:30	181,773	St Leonards	SL031156
89 Seats Breakdown	Ajust and secure saloon seat plunger attendant chair is faulty					Monitoring	
Breakdown	04/10/2020	04:07	04/10/2020	04:07	182,044	St Leonards	SL031164
Breakdown	MDT not plotting correctly					Monitoring	
Unplanned Repair	05/10/2020	10:00	05/10/2020	10:30	182,103	St Leonards	SL031178
31 Battery Comms 45 Engine 1 Breakdown	Test and replace comms Cam chain noisy on cold start. Monitor MDT not plotting correctly					Monitoring	
Vehicle Deep Clean	27/10/2020	07:22	27/10/2020	10:00	184,556	St Leonards	SL031390
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/10/2020	07:00	28/10/2020	16:00	184,556	St Leonards	SL031391
18 Wheels Check Torques 31 Battery Chassis 43 Exhaust System 1 44 Add Ad Blue 45 Engine 1 Safety Inspection UB Fire Supp 6mts Service UB Fire Supp 12mts Service	Checked. Replace u/s unit. Repair and modify more quality products from was. (Tail pipe) Unable to fill unit due to no stock of Add Blue. Cam chain noisy on cold start. Monitor Checked. UB Fire Supp 6mts Service Service of fire supression system					Monitoring	

SAFETY INSPECTION	09/12/2020	07:00	29/12/2020	10:00	188,581	St Leonards	SL031797
002 Major Unit Replace Eng	Monitoring						
02 Cab Assembly 1							
17 Tyres Fit Winter							
17 Tyres Tracking							
18 Wheels Check Torques							
34 Lights							
45 Engine 1							
Safety Inspection							
Travel Time							
Tail Lift Inspection							
MOT							
Vehicle Deep Clean	10/12/2020	07:55	29/12/2020	12:31	188,581	St Leonards	SL031811
Vehicle Deep Clean							
Breakdown	08/01/2021	08:18	08/01/2021	10:00	189,426	St Leonards	SL032088
Breakdown	dead battery						
Breakdown	11/01/2021	19:43	13/01/2021	07:00	189,500	St Leonards	SL032113
Breakdown	Windscreen washer not working						Monitoring
Unplanned Repair	13/01/2021	09:45	13/01/2021	10:15	189,700	St Leonards	SL032130
02 Mirrors	Re build damaged n/s mirror						
Breakdown	15/01/2021	22:48	16/01/2021	10:00	189,974	St Leonards	SL032164
Breakdown	Non Start. Parts on order. Now VOR due Inspection.						

SAFETY INSPECTION	18/01/2021	07:55	19/01/2021	11:05	189,984	St Leonards	SL032179
01 Air Conditioning 1	Replace filter.						
02 Mirrors	Replace mirror motor.Replace damaged Arm & Motor.						
02 Windscreen	Windscreen washers u/s.						
02 Windscreen Wipers	Replace both units.						
18 Wheels Check Torques	Checked.						
27 Transmission Automatic	Replace inhibitor switch.						
31 Battery Chassis	Replace weak unit.						
34 Emergency Lights	Airport light missing.						
44 Add Ad Blue	Fill unit. 16L						
45 Engine 1	Cam chain noisy on cold start. Monitor						Monitoring
71 Body Exterior 1	Repair damaged Tail Lift.						
Breakdown	Windscreen washer not working						
Safety Inspection	Checked.						
Vehicle Deep Clean	19/01/2021	10:14	19/01/2021	13:26	189,984	St Leonards	SL032199
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	01/02/2021	13:01	02/02/2021	12:30	191,080	St Leonards	SL032335
34 Lights Bulb Replacement	Replace o/s side repeater lamp						
Breakdown	offside indicator not working						Monitoring
Unplanned Repair	19/02/2021	10:00	25/02/2021	12:00	192,924	St Leonards	SL032500
71 Body Exterior 1	SIDE WINDOW REAR OF SLIDING DOOR SMASHED - Mobile wind to replace						
Vehicle Deep Clean	02/03/2021	07:32	02/03/2021	12:01	192,924	St Leonards	SL032586
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	02/03/2021	08:15	04/03/2021	16:00	192,924	St Leonards	SL032588
13 Brakes 1	Replace F/Disc & Pads.						
18 Wheels Check Torques	Checked						

45 Engine 1	Cam chain noisy on cold start. Monitor	Monitoring
86 Door Lock	Replace cover.	
Safety Inspection	Checked	
Engine Change Oil & Filter	Done	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight	

Breakdown	24/03/2021	22:06	25/03/2021	07:19	194,838	St Leonards	SL032809
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Assembly 1 Breakdown	Demister n/w. Replaced heater blower. Demisters not working.
--------------------------------	---

Breakdown	13/04/2021	09:27	13/04/2021	10:30	197,797	St Leonards	SL032966
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Aux Breakdown	Test and replace Aux battery Vehicle not holding charge
-----------------------------	--

SAFETY INSPECTION	16/04/2021	07:00	21/04/2021	14:00	197,797	St Leonards	SL033000
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Ass Fire Extinguisher	Out of date. Replaced.
02 Cab Assembly 1	Electrical Auxs CAB DE-MIST FAN NOT WORKING Checked.
18 Wheels Check Torques	Checked.
31 Charging System	Shore line cover broken. Replaced.
31 Charging System Battery	Battery/Charging Sys keeps powering down. Checked.
34 Lights	O/S rev light full of water. Replaced.
45 Engine 1	Cam chain noisy on cold start. Monitor
Install Saloon CCTV Camera	N/S camera n/w. Re[placed.
Safety Inspection	Carried out inspection.
Tail Lift Inspection	Done. Guide blocks & panel adrift. (Autospray).
Replace Handbrake Cables	Replace Handbrake Cables. Done.
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service. Done.

Vehicle Deep Clean	19/04/2021	11:31	20/04/2021	09:00	197,797	St Leonards	SL033029
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	08/05/2021	22:19	10/05/2021	06:45	199,602	St Leonards	SL033193
Breakdown	side door keeps opening; VOR					Monitoring	
SAFETY INSPECTION	24/05/2021	11:30	01/06/2021	12:00	200,747	St Leonards	SL033332
18 Wheels Check Torques							
42 Coolant System	Radiator leaking						
71 Body External Steps	Replace step light						
85 Body Interior 1	Secure saloon cupboard hinges						
86 Door Lock	Door locks siezed					Monitoring	
86 Sliding Door	Replce bearings and lock						
Breakdown	side door keeps opening; VOR						
Safety Inspection							
Axle Oil Change	Axle Oil Change						
Vehicle Deep Clean	27/05/2021	07:32	27/05/2021	11:00	200,747	St Leonards	SL033357
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	24/06/2021	10:15	24/06/2021	11:15	202,810	St Leonards	SL033609
86 Doors Rear	Rear door stay snapped off. Replaced						
Breakdown	08/07/2021	19:28	09/07/2021	10:00	204,140	St Leonards	SL033737
86 Sliding Door	Side door opening while driving. Secure catch						
Breakdown	SIDE DOOR OPENS WHILST DRIVING					Monitoring	
Travel Time	Travel to Poole						
SAFETY INSPECTION	23/07/2021	09:00	26/07/2021	09:52	205,123	St Leonards	SL033899
02 Cab Ass Fire Extinguisher	Out of date.						

13 Brakes 1	Rear disc's & pads worn. Replaced. Cleaned all rims.
18 Wheels Check Torques	Checked.
55 Tail Lift	O/S hand rail loose. Removed, Tightened, refitted.
86 Door Lock	Door locks siezed. Replaced lock-set.
86 Sliding Door	Top magnet u/s. Replaced.
Breakdown	SIDE DOOR OPENS WHILST DRIVING
Safety Inspection	Carried out inspection.
Wheel Hub Flanges Replaceme	Rears in poor condition. Replaced.
Tail Lift Inspection	Done.

Vehicle Deep Clean	26/07/2021	10:52	27/07/2021	10:00	205,123	St Leonards	SL033922
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	04/08/2021	14:00	04/08/2021	14:30	205,671	St Leonards	SL034018
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Sliding Door	Secure top lock, ok.
-----------------	----------------------

SAFETY INSPECTION	31/08/2021	09:00	01/09/2021	09:30	207,640	St Leonards	SL034254
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windscreen Wipers	O/S washer jet split. Replaced.
13 Handbrake	No researve travel. Adjusted.
18 Wheels Check Torques	Checked.
89 Seats	Drivers seat base cover torn. Replaced cover,cusion & base.
Safety Inspection	Carried out ninspection.
Tail Lift Inspection	Done, Replaced cracked O/S gate. Replaced O/S LED.

Vehicle Deep Clean	01/09/2021	11:31	02/09/2021	14:00	207,640	St Leonards	SL034270
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	05/09/2021	09:20	06/09/2021	06:46	207,767	St Leonards	SL034293
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	oil level below the minimum; VOR
-----------	----------------------------------

SAFETY INSPECTION	11/10/2021	06:30	11/10/2021	15:00	210,054	St Leonards	SL034613
02 Cab Assembly 1	Replace cab centre console knob						
02 Windscreen Wipers	Replace wiper blades						
18 Wheels Check Torques							
85 Body Interior 1	Replace kit strap, Secure grab handle repair shelf edge and secure mic.						
85 Body Interior 2	Replace emg call strip end caps						
86 Doors	Re fit o/s door panel						
86 Sliding Door	Straighten side door magnet bracket						
Safety Inspection							
Vehicle Deep Clean	15/10/2021	07:46	15/10/2021	10:00	210,227	St Leonards	SL034683
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	17/11/2021	14:05	18/11/2021	08:30	212,645	St Leonards	SL034987
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/11/2021	08:00	19/11/2021	14:00	212,645	St Leonards	SL034997
13 Brake Pads	Front brake pads worn. Replaced.						
17 Tyres Replace	Front tyres worn @ edges.Cleaned rim's & flanges,replaced x2 tyres.						
17 Tyres Tracking							
18 Wheels Check Torques	Checked.						
52 Electrical Aux	230V tell-tale lights broken.						
71 Body Exterior 1	Scoop cupboard strap missing.Replaced (2nd Hand).						
85 Body Interior 1	Safe cupboard door adrift.						
89 Seats	cab seats covers torn.						
Safety Inspection	Carried out inspection.						
Pollen Filter Change	Pollen Filter Change. Done.						
Tail Lift Inspection	Done.						
Unplanned Repair	19/11/2021	10:51	19/11/2021	10:56	212,645	MDT Ferndown	TF001674
87 Oxygen System	Replaced Oxygen cylinder connection probes for 90' probes.						

Unplanned Repair	22/11/2021	06:00	22/11/2021	08:00	212,656	St Leonards	SL035023
01 Heating 1	Saloon heater inop - No fault found						
Unplanned Repair	23/11/2021	08:45	23/11/2021	09:15	212,700	St Leonards	SL035049
01 Heating 1 56 Comms Equipment	Saloon heater inop - Teat, ok. No fault found. Speak to crew about operation MDT not booking on. Reset comms. OSD to arrange airwave repair						
Unplanned Repair	26/11/2021	09:45	26/11/2021	10:45	212,918	St Leonards	SL035078
86 Sliding Door	Adjust cable, catches and revit door lock						
Breakdown	27/11/2021	11:48	29/11/2021	06:00	212,988	St Leonards	SL035083
Breakdown	Stretcher panel off &won't lock					Monitoring	
MOT EXPIRES	30/12/2021	07:00	30/12/2021	10:45	214,995	St Leonards	SL035331
MOT							
Vehicle Deep Clean	30/12/2021	12:12	31/12/2021	09:00	214,995	St Leonards	SL035334
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	04/01/2022	10:00	14/01/2022	10:23	215,001	St Leonards	SL035364
18 Wheels Check Torques	Checked.						
34 Emergency Light System	O/S scene light & siren light not illuminating on genisys panel.					Monitoring	
45 Engine 1	Coolant leak - Merc of Exeter						
45 Engine 2	Oil leak - Merc of Exeter						
45 Engine Ad Blue	System empty?? Topped 10ltrs.No Parts.						
52 Electrical Aux	230v tell-tail light broken AGAIN!! NO PARTS.					Monitoring	
85 Body Interior 1	CCTV cupboard struts weak.NO PARTS.					Monitoring	
86 Sliding Door	Sticks from inside STILL!!!Adjusted lower bracket.						
Breakdown	Stretcher panel off &won't lock.Done.						
Safety Inspection	Carried out inspection.						
UB Fire Supp Repair	Repair of UB Fire Supp System. Showing in red.Repressurised.						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service. Done.						

UB Fire Supp 12mts Service Service of fire suppression system. N/A

Unplanned Repair 21/01/2022 12:00 04/02/2022 15:00 215,397 St Leonards SL035539

45 Engine 1 Fumes in cab - Rygor Westbury to repair

Vehicle Deep Clean 21/02/2022 13:46 22/02/2022 09:07 216,281 St Leonards SL035801

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 24/02/2022 09:04 25/02/2022 10:55 216,282 St Leonards SL035848

02 Cab Ass Fire Extinguisher	Out of date. Replaced.	
02 Cab Assembly 1	Torch broken. Replaced.	
16 Suspension 1	Rear spring slipper pads torn.Replaced.	
18 Wheels Check Torques	Checked.	
31 Battery Aux	Body Interior Inverter in saloon not working. NEEDS TO BE SWITCHED ON TO WORK	
31 Battery Chassis	Not holding charge. Replaced.	
34 Emergency Light System	O/S scene light & siren light not illuminating on genisys panel.NO PARTS.	Monitoring
44 Fuel System 1	Fuel leak-off pipe leaking. Replced.	
52 Electrical Aux	230v tell-tail light broken AGAIN!! NO PARTS.	Monitoring
71 Body Exterior 1	Mirrors small scratches to plastic of drivers wing mirror.GROW UP.	
71 Body Exterior 2	Body Exterior Small scratches to O/S wing mirror GROW UP>	
85 Body Interior 1	CCTV cupboard struts weak.NO PARTS.	Monitoring
87 Stretcher	Battery faulty. NO PARTS.	Monitoring
89 Seats	Saloon rear facing seat adjuster missing. NO PARTS.	Monitoring
Safety Inspection	Carried out inspection.	
Brake Fluid Change	Brake Fluid Change. Done.	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight. Done by S.W.L.	
Tail Lift Inspection	See above.	
Air Filter Change	Air Filter Change. Done.	
Fuel Filter Change	Change Fuel Filter. Done.	
Engine Change Oil & Filter	Done.	

Breakdown 10/03/2022 00:21 10/03/2022 06:00 217,055 St Leonards SL035947

Breakdown MDT power failing Monitoring

Unplanned Repair	22/03/2022	11:00	22/03/2022	12:03	217,926	St Leonards	SL036031
86 Doors	Side door open when driving						
Breakdown	19/04/2022	11:01	19/04/2022	11:16	219,904	St Leonards	SL036226
Breakdown	Puncture						
SAFETY INSPECTION	26/04/2022	06:00	26/04/2022	06:00	220,445	St Leonards	SL036291
18 Wheels Check Torques Safety Inspection							
SAFETY INSPECTION	26/04/2022	06:00	03/05/2022	08:00	220,445	St Leonards	SL036292
18 Wheels Check Torques Safety Inspection							
34 Emergency Light System	O/S scene light & siren light not illuminating on genisys panel.NO PARTS.					Monitoring	
52 Electrical Aux	230v tell-tail light broken AGAIN!! NO PARTS.					Monitoring	
85 Body Interior 1	CCTV cupboard struts weak. Replaced					Monitoring	
87 Stretcher	Battery faulty						
89 Seats	Saloon rear facing seat adjuster missing. NO PARTS.					Monitoring	
Breakdown	MDT power failing						
Wheel Hub Flanges Replaceme							
Annual Heater Service	Annual Heater Service						
Replace Handbrake Cables	Replace Handbrake Cables						
85 Body Interior 2	Secure saloon microphone						
24 Driveshaft 1	Replace centre bearing						
13 Brake Pads	Replace rear pads						
17 Tyres Replace	Replace 3x worn tyres						
Vehicle Deep Clean	03/05/2022	07:56	03/05/2022	07:58	220,445	St Leonards	SL036377
Vehicle Deep Clean	Vehicle Deep Clean						

Vehicle Deep Clean	03/05/2022	07:58	03/05/2022	12:00	220,445	St Leonards	SL036378
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	11/05/2022	10:30	11/05/2022	11:31	221,467	St Leonards	SL036511
31 Charging System	Alternator u/s						
Unplanned Repair	18/05/2022	11:30	18/05/2022	12:30	222,009	St Leonards	SL036599
86 Sliding Door	Side door opening while driving. Adjust cables						
Breakdown	29/05/2022	09:11	30/05/2022	09:30	222,597	St Leonards	SL036708
Breakdown Supply Sat Nav 56 Comms Equipment	Sat nav and MDT wont connect Sat nav inop - Replace sat nav MDT not turning on. No fault found						
Vehicle Deep Clean	21/06/2022	08:25	21/06/2022	14:00	224,878	St Leonards	SL036881
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	22/06/2022	08:00	23/06/2022	11:00	224,878	St Leonards	SL036895
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
34 Emergency Light System	O/S scene light & siren light not illuminating on genisys panel.						
52 Electrical Aux	230v tell-tail light broken. No Parts.						
85 Body Interior 1	CCTV cupboard struts weak. Replaced						
89 Seats	Saloon rear facing seat adjuster missing.						
Supply Sat Nav	Other Sat Not not loading past Garmin						
Annual Air Con Service	Annual Air Condition Service. Done.						
Tail Lift Inspection	Done.						
02 Cab Assembly 1	Torch n/w. Replaced battery.						

Monitoring
Monitoring

Monitoring

85 Body Interior Roof 34 Lights UB Fire Supp Repair	Replace skylight blind N/S/R/top indicator 50% n/w. Replaced. Repair of UB Fire Supp System. Topped up bottle & line pressure.						
Unplanned Repair	08/07/2022	12:00	08/07/2022	12:53	225,839	St Leonards	SL037065
87 Stretcher	Not securing in vehicle.						
Breakdown	19/07/2022	01:59	19/07/2022	12:30	226,693	St Leonards	SL037131
Breakdown 02 Mirrors 02 Windscreen Wipers	WASHER BOTTLE LEAKING Replace n/s mirror glass Replace washer jets, check valve and clean out pump filter					Monitoring	
ACCIDENT	19/08/2022	09:00	19/08/2022	10:00	229,214	St Leonards	SL037346
02 Mirrors	N/S mirror damaged - Replace mirror arm						
Breakdown	28/08/2022	17:42	29/08/2022	06:30	230,323	St Leonards	SL037393
Breakdown	Shoreline connections bent					Monitoring	
Breakdown	03/09/2022	13:55	05/09/2022	13:00	230,668	St Leonards	SL037436
Breakdown 32 Starting System 1	WONT START					Monitoring	
Vehicle Deep Clean	05/09/2022	09:25	05/09/2022	09:27	230,668	St Leonards	SL037441
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	05/09/2022	09:27	06/09/2022	10:00	230,668	St Leonards	SL037442

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	07/09/2022	06:00	07/09/2022	06:00	230,668	St Leonards	SL037456
18 Wheels Check Torques Safety Inspection							
SAFETY INSPECTION	07/09/2022	06:00	08/09/2022	07:00	230,668	St Leonards	SL037457
18 Wheels Check Torques Safety Inspection UB Fire Supp 6mts Service Tail Lift Inspection 34 Emergency Light System 52 Electrical Aux 89 Seats Breakdown 02 Cab Assembly 1 02 Cab Ass Fire Extinguisher 13 Brakes 1 87 Oxygen System	Checked. Carried out inspection. UB Fire Supp 6mts Service Done. O/S scene light & siren light not illuminating on genisys panel. 230v tell-tail light broken. No Parts. Saloon rear facing seat adjuster missing. WONT START Both window switches broken. Replaced x2. Out of date x2. Replaced x2. Front pads & disc's worn. Replaced. Pipe trapped in clamp.MDC to sort.					Monitoring Monitoring	
Breakdown	05/10/2022	08:27	06/10/2022	06:30	234,739	St Leonards	SL037718
Breakdown	Handbrake not holding					Monitoring	
BREAKDOWN	27/10/2022	10:00	27/10/2022	10:30	234,739	St Leonards	SL037976
44 Add Ad Blue 34 Lights Bulb Replacement	Ad blue top up n/s side repeater not working						
Breakdown	06/11/2022	09:20	07/11/2022	09:13	235,346	St Leonards	SL038033
Breakdown	side step not deploying correctly						

SAFETY INSPECTION	17/11/2022	08:30	17/11/2022	08:30	236,051	St Leonards	SL038126
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	17/11/2022	08:30	23/11/2022	10:20	236,051	St Leonards	SL038127
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
34 Emergency Light System	O/S scene light & siren light not illuminating on genisys panel.
89 Seats	Saloon rear facing seat adjuster missing.
Breakdown	Handbrake not holding
34 Lights Bulb Replacement	Lighting System N/S Side indicator Blown
52 Electrical Aux	Electrical Auxs BATTERY CHARGER NOT WORKING
13 Brakes 1	Brakes spongy
01 Heating 2	Radiator/Cooling Sys HEATER ONLY WORKS ON MAX TEMP
Tail Lift Inspection	
MOT	
01 Heating 1	Saloon heater only working on high
13 Brakes 2	Rear disc's Pads& handbrake shoes worn. Replaced all.
34 Lights	Front indicators white, side lights n/w. Replaced bulbs x4.
17 Tyres Replace	Front tyres worn on edges. Replaced x2.
15 Steering 1	O/S Rack end worn. Replaced rack end & track-rod end.
85 Body Interior 1	230v warning lights broken. Replaced.
16 Suspension 1	Rear spring seperator blocks split x2 Replaced x2.

Monitoring

Vehicle Deep Clean	21/11/2022	06:44	21/11/2022	18:00	236,051	St Leonards	SL038179
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	21/11/2022	06:44	21/11/2022	06:44	236,051	St Leonards	SL038293
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	30/11/2022	15:00	30/11/2022	16:37	236,078	St Leonards	SL038294
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Sliding Door	Side door stiff to open/close
-----------------	-------------------------------

Breakdown	06/01/2023	10:26	06/01/2023	12:21	239,651	St Leonards	SL038721
Breakdown 01 Heating 1	faulty heater in back Saloon heating						
Breakdown	25/01/2023	13:35	25/01/2023	15:00	241,508	St Leonards	SL038909
Breakdown	broken side door handle , renewed outer handle & adjusted.						
Unplanned Repair	27/01/2023	11:35	30/01/2023	11:29	241,650	St Leonards	SL038933
42 Coolant System 56 Comms Equipment	Coolant leak Hand portable battery charger inop						
Breakdown	14/02/2023	10:20	14/02/2023	17:51	244,239	St Leonards	SL039102
Breakdown 24 Driveshaft 1	Brakes Grinding Rear prop worn						
SAFETY INSPECTION	18/02/2023	12:00	24/02/2023	15:00	244,413	St Leonards	SL039155
18 Wheels Check Torques Safety Inspection 89 Seats Tail Lift Inspection 34 Lights 55 Tail Lift 85 Body Interior 1 02 Cab Assembly 1 45 Engine 1 16 Suspension 1 11 Axle Rear 15 Steering 1 13 Brakes 1 34 Lights Bulb Replacement 42 Coolant System 17 Tyres Replace 86 Doors Rear	Saloon rear facing seat adjuster missing. osr side marker and nsr reverse lamps damaged. replaced both nsr lift light u/s. and os hose bulged. replaced side locker bag straps broken. replace brake pedal rubber worn and console button missing. replace both both engine mounts split. replaced rear spring buffers x2 split and drop link bushes worn. replace rear axle oil low. topped up 1litre nsf track rod end excessive play in joint. replace nsr caliper slider seized. free off and lubricate. Replace n/s headlight bulb holder Replace radiator Replace o/s/r/o tyre Rear door bottom catch not locking						

01 Air Conditioning 1	Drain system and refill						
Vehicle Deep Clean	27/02/2023	08:00	28/02/2023	11:00	244,413	St Leonards	SL039220
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	11/03/2023	07:19	11/03/2023	13:30	244,650	St Leonards	SL039332
Breakdown	Rear door						
02 Pipeline Annual Inspection	01/04/2023	09:38	01/04/2023	09:43	247,006	MDT Ferndown	TF002622
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - replaced 2 x Port seals.						
SAFETY INSPECTION	01/05/2023	11:00	02/05/2023	10:00	250,099	St Leonards	SL039963
18 Wheels Check Torques							
Safety Inspection							
45 Engine 2	Engine AMBER WARNING LIGHT NO OTHER SYMPTOMS						
Engine Change Oil & Filter							
Tail Lift Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
45 Engine 1	EML on						
85 Body Interior 1	Fit P clips for AVP						
13 Brake Pads	Front pads very low						
Vehicle Deep Clean	03/05/2023	11:27	04/05/2023	10:54	250,099	St Leonards	SL039988
Vehicle Deep Clean	Vehicle Deep Clean						
ACCIDENT	08/05/2023	11:00	08/05/2023	12:10	250,198	St Leonards	SL040038
71 Body Exterior Acc Repair	Step damaged. straightened step and replaced roller bushes. lubed step.						

Vehicle Deep Clean	14/06/2023	10:15	14/06/2023	15:00	252,871	St Leonards	SL040550
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/06/2023	06:00	16/06/2023	10:00	252,871	St Leonards	SL040572
18 Wheels Check Torques	Checked.						
Safety Inspection	Inspected.						
71 Body External Steps	Body Exterior Side step off the truck in an accident						
MOT							
86 Door Lock	C/Locking n/w & lock barrel siezed on rear door. Repaired.						
85 Body Interior 1	O2 cupboard catch broken. Repaired.						
02 Cab Ass Fire Extinguisher	Out of date. Replaced.						
02 Windscreen	Small chip.						
UB Fire Supp 12mts Service	Service of fire supression system						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
Replace Vehicle Fuel Card	06/07/2023	07:50	06/07/2023	07:52	253,999	St Leonards	SL040889
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
ACCIDENT	08/07/2023	03:23	10/07/2023	12:00	254,120	St Leonards	SL040935
Breakdown	Accident - cracked indicator repeater						
34 Lighting System	Replace damaged side repeater lamp						
Vehicle Deep Clean	25/07/2023	12:30	25/07/2023	18:00	257,014	St Leonards	SL041258
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/07/2023	13:30	27/07/2023	17:00	257,014	St Leonards	SL041273
18 Wheels Check Torques							
Safety Inspection							

Monitoring

Monitoring

02 Windscreen	Small chip.	Monitoring
Breakdown	Accident - cracked indicator repeater. Very minor cracking	
56 Comms Equipment	Electrical Auxs WIRING CHECK FOR THORCOM. NFF	
Tail Lift Inspection		
16 Suspension 1	Excessive play in suspension arm ball joint	
16 Suspension 2	Excessive play in shock absorber mounts.	
13 Brakes 1	Rear brake pads worn below limits	
85 Body Interior 1	White board worn	
Pollen Filter Change	Pollen Filter Change. old filter dirty	
44 Add Ad Blue	Top up ad blue 8L	
13 Brake Test	carry out brake test	
13 Brakes 2	Replace Telma control box	
Road Test	Telma not working. new box fitted re road test	

Vehicle Deep Clean	04/09/2023	12:13	04/09/2023	14:41	259,090	St Leonards	SL041821
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	05/09/2023	08:00	06/09/2023	13:55	259,090	St Leonards	SL041827
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
02 Windscreen	Small chip.
87 Oxygen System	unknown fault with valve on wall ??????????
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
Recall Notification	Airbag recall

Vehicle Deep Clean	16/10/2023	06:00	16/10/2023	14:00	261,875	St Leonards	SL042389
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	17/10/2023	11:15	18/10/2023	16:00	261,875	St Leonards	SL042404
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
Pollen Filter Change	Pollen Filter Change
85 Body Interior 1	Replace mangar charger

86 Sliding Door	Sliding door lower magnet torn. replaced
85 Body Interior 2	bag strap broken. replaced -mic broken. replaced -x2 locker doors resecured.
19 Chassis 1	Rear mudflap rubber torn. replaced.

Unplanned Repair	02/11/2023	08:00	02/11/2023	08:15	262,727	St Leonards	SL042619
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior 1	Replace damaged front number plate
--------------------	------------------------------------

Vehicle Deep Clean	24/11/2023	06:40	24/11/2023	10:47	264,236	St Leonards	SL042916
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	28/11/2023	11:30	29/11/2023	06:55	264,236	St Leonards	SL042958
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
31 Battery Chassis	Chassis battery weak, not holding charge
86 Doors Rear	Rear door not securing on lower catch

Vehicle Deep Clean	08/01/2024	14:02	09/01/2024	10:30	269,503	St Leonards	SL043519
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	09/01/2024	13:30	10/01/2024	17:00	269,503	St Leonards	SL043526
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	Toe flap bent. repaired lift toe flap. -oil leak tilt ram return line. replaced
02 Cab Assembly 1	Drivers window switch broken. replaced switch
86 Doors Rear	Rear door lower latch stiff. lubricated and replaced latch cover.
85 Body Interior 1	BH Lower drawer runner broken. replaced runners.
55 Tail Lift	Tail lift mercury switch faulty. - no parts

Monitoring

24 Driveshaft 1	Front propshaft UJ worn. replaced propshaft.	
16 Suspension 1	Rear spring, rear buffers split. replaced x2 buffers.	
Replace Wheel Bolts	Replace front wheel studs and nuts.	
13 Brakes 1	Front brake discs and pads worn low. replaced front brake kit.	
85 Body Interior 2	Saloon genysys panel 'bright' button inop. - no parts	Monitoring

SAFETY INSPECTION	26/02/2024	06:00	26/02/2024	13:30	273,652	St Leonards	SL044141
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
55 Tail Lift	Tail lift mercury switch faulty. - no parts Replaced.
85 Body Interior 2	Saloon genysys panel 'bright' button inop. - no parts
45 Engine 1	Engine Amber EML. See notes.
17 Tyres Replace	O/S/R/O nailed. Replaced.
01 Heating 1	Saloon heater exhaust split. Replaced.
45 Engine Oil Top Up	On min. Topped 1Ltr.
31 Charging System	Auto-eject n/w. Repaired.
86 Doors Rear	Door stay bolt sheared. Removed,drill out and replaced bolt. Refitted.

Vehicle Deep Clean	27/02/2024	10:18	27/02/2024	15:02	273,683	St Leonards	SL044172
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

ACCIDENT	05/03/2024	09:30	05/03/2024	10:43	273,900	St Leonards	SL044264
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior Acc Repair	Body Exterior O/S/R brake light damaged. Replaced light cluster and lights.
-----------------------------	---

Vehicle Deep Clean	01/04/2024	16:42	02/04/2024	14:02	280,709	St Leonards	SL044713
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	04/04/2024	16:00	07/04/2024	04:51	280,709	St Leonards	SL044765
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Engine Change Oil & Filter	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight

02 Windscreen Wipers	Blades worn
17 Tyres	3x worn
86 Doors Rear	Split
86 Sliding Door	Bottom female catch worn
13 Brakes 1	Rears worn
45 Engine Ad Blue	Top up
45 Engine 1	Belt tensioner u/s
Road Test	

Vehicle Deep Clean	15/05/2024	09:46	15/05/2024	15:37	282,754	St Leonards	SL045332
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	17/05/2024	10:00	22/05/2024	11:30	282,754	St Leonards	SL045360
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Brake Fluid Change	Brake Fluid Change
Tail Lift Inspection	
MOT	
15 Steering 1	NSF Track rod end boot split. replaced and carried out tracking check and adjust
16 Suspension 1	Rear os spring front buffer split. replaced.
19 Chassis 1	Tail lift bridge plate guides and mudflap insecure. resecured
85 Body Interior 1	O2 locker outer trim damaged. replaced.
85 Body Interior 2	Saloon genysys button fault. replaced (spare part) -x2 locker hinges resecured.
13 Handbrake	Adjusted cables.
01 Air Conditioning 1	Saloon ac condenser fan seized. replaced whole condenser unit.
42 Coolant System	Coolant leak from hose from thermostat housing to reservoir.

02 Pipeline Annual Inspection	14/05/2024	11:44	14/05/2024	11:49	282,728	MDT Ferndown	TF003486
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - Replaced broken line pressure gauge.
-------------------------------	--

Unplanned Repair	10/06/2024	06:00	10/06/2024	16:00	283,554	St Leonards	SL045712
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	operating when on bumpy roads, adj operating plunger & test
------------------------	---

Vehicle Deep Clean	29/06/2024	09:16	30/06/2024	08:40	286,826	St Leonards	SL046045
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	01/07/2024	09:41	03/07/2024	15:00	286,826	St Leonards	SL046073
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	
UB Fire Supp 12mts Service	Service of fire supression system
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
55 Tail Lift	O/S Hand rail loose. rettightened.
34 Emergency Lights	O/S Scene light damaged. replaced.
34 Lights Bulb Replacement	NSF Sidelight bulb replaced.
15 Steering 1	Steering wheel worn. replaced steering wheel.
45 Engine 1	Oil leak from engine sump. removed, cleaned and resealed sump.
45 Engine 2	Both belt tensioners worn and ac belt split. replaced tensioners and belt.
42 Coolant System	Lower radiator hose not fully secured. replaced hose.

Unplanned Repair	15/07/2024	11:00	15/07/2024	14:45	286,999	St Leonards	SL046334
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

55 Tail Lift	Not working correctly
--------------	-----------------------

Breakdown	17/07/2024	22:17	18/07/2024	05:36	286,999	St Leonards	SL046360
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Non starter
-----------	-------------

Vehicle Deep Clean	09/08/2024	13:42	13/08/2024	09:18	292,182	St Leonards	SL046737
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	14/08/2024	06:00	15/08/2024	10:38	292,182	St Leonards	SL046796
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service
Tail Lift Inspection	
87 - Stretchers/Chairs/Boards	Stretcher belts in wrong positions
55 Tail Lift	Tail lift tilt ram needs adjustments
45 Engine 1	Signs of old oil leak underside of engine bay. (Requires cleaning & checking.).
34 Lights	N/S/F Head light bulb insecure
16 Suspension 1	Rear antiroll bar lower drop link bushes worn
13 Brake Test	
Heater Service	Saloon heater flame tube cracked

SAFETY INSPECTION	19/09/2024	14:30	01/10/2024	09:30	294,668	St Leonards	SL047383
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
34 Lights Bulb Replacement	Front DRL and sidelight bulbs blackened/dim. replaced bulbs.
52 Electrical Aux	Auto eject cover broken. -saloon genysys panel broken. Replaced both parts.
71 Body Exterior 1	Tail lift bridge plate guides insecure. resecured to body.
27 Transmission Automatic	Transmission gearbox mount perished. replaced mount.
Tail Lift Inspection	

Vehicle Deep Clean	01/10/2024	16:00	02/10/2024	12:10	294,719	St Leonards	SL047549
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	29/10/2024	06:00	06/11/2024	14:30	296,746	St Leonards	SL047989
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
86 Sliding Door	Upper latch insecure and cover missing. resecured latch and replaced cover.
85 Body Interior 1	Lower equipment strap missing. replaced.
13 Brakes 1	NSR caliper slider seized. replaced slider kit.
16 Suspension 1	Front shock absorbers excessive play. replaced shocks and bolts.
17 Tyres Replace	NSR Inner punctured. replaced.
17 Tyres Tracking	Tracking check and adjusted front toe.

01 Heating 1	Replaced cab heater controls & broken dash surround.						
Vehicle Deep Clean	30/10/2024	15:30	31/10/2024	14:45	296,746	St Leonards	SL048025
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/11/2024	11:52	25/11/2024	16:00	296,746	St Leonards	SL048388
Breakdown	NSF FLAT						
SAFETY INSPECTION	12/12/2024	15:00	16/12/2024	06:50	299,948	St Leonards	SL048656
18 Wheels Check Torques							
Safety Inspection							
34 Lights	Lighting System Intermittant indicator -Checked all ok.						
55 Tail Lift	Ramp/Lift/Tail Hoist Tail lift stuck in stow away position- Checked all ok.						
52 Electrical Aux	Comms Power Check MDVS AUX BATTERY ISSUE- Checked all ok.						
Tail Lift Inspection							
86 Door handle	Rear inner handle mount broken. replaced inner handle mount/cover.						
15 Steering 1	Oil leak pas hose from reservoir to cooler. replaced and cleaned.						
71 Body Exterior 1	Tail lift bridge plate guides insecure. resecured.						
45 Engine 1	Engine oil leak sump area. cleaned and monitor due to old vehicle.						Monitoring
15 Steering 2	Steering rack oil leak o/s rack. -Monitor due to old vehicle.						Monitoring
Road Test							
Vehicle Deep Clean	16/12/2024	10:58	17/12/2024	08:02	299,954	St Leonards	SL048683
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	22/12/2024	10:00	22/12/2024	10:30	300,156	St Leonards	SL048764
71 Body External Steps	Side step ram u/s						

BREAKDOWN	21/01/2025	16:30	22/01/2025	10:30	302,357	St Leonards	SL049198
02 Mirrors	N/S Mirror glass smashed						
Vehicle Deep Clean	28/01/2025	07:19	28/01/2025	10:43	302,689	St Leonards	SL049296
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/01/2025	08:17	31/01/2025	08:37	302,715	St Leonards	SL049328
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test UB Fire Supp 6mts Service 02 Cab Assembly 1 45 Engine 1 13 Brakes 1 Tail Lift Inspection 55 Tail Lift	Check and Install MDVS windows update UB Fire Supp 6mts Service Cab torch battery u/s replaced battery and resecured both chargers. Engine oil leak upper sump area - Clean & Monitor. Front brake pads and discs worn. replaced brake kit. Tilt switch inop. replaced with part from vor veh.						
						Monitoring	
Unplanned Repair	04/02/2025	11:08	04/02/2025	11:11	303,618	St Leonards	SL049416
UB Fire Supp Repair	Repair of UB Fire Supp System - System regas						
Unplanned Repair	14/02/2025	08:57	14/02/2025	09:03	305,216	St Leonards	SL049550
86 Doors Rear UB Fire Supp Repair 44 Add Ad Blue	O/S/R door stay broken Repair of UB Fire Supp System Adblue level low						
Vehicle Deep Clean	13/03/2025	11:49	14/03/2025	07:34	309,364	St Leonards	SL049916
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	14/03/2025	14:12	17/03/2025	08:14	309,395	St Leonards	SL049928
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 45 Engine 1 Engine Change Oil & Filter Tail Lift Inspection Pollen Filter Change 55 Tail Lift 02 Cab Assembly 1 86 Sliding Door 17 Tyres Replace	Check and Install MDVS windows update Engine oil leak upper sump area - Clean & Monitor. Pollen Filter Change Tilt switch inop. replaced switch. N/S Window switch broken. replaced - Cab interior bulb replaced. Outer runner bearings seized. replaced bearings. NSR Inner tyre replaced.	Monitoring
---	---	------------

Unplanned Repair	08/04/2025	08:00	08/04/2025	08:39	311,276	St Leonards	SL050286
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	N/S wing mirror housing damaged
------------	---------------------------------

Unplanned Repair	08/04/2025	07:30	09/04/2025	06:38	311,276	St Leonards	SL050311
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	NSF wing mirror casing damaged. Replaced cover
------------	--

SAFETY INSPECTION	06/05/2025	08:00	06/05/2025	17:22	313,616	St Leonards	SL050779
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 85 Body Int Alcohol Gel Dispen Tail Lift Inspection 13 Brake Pads 17 Tyres Replace 89 Seatbelts 02 Cab Ass Fire Extinguisher	Check and Install MDVS windows update Rear brake pads worn. Replaced Replace both NSR tyres Driver seat belt slight fraying. Expired. Replaced	Monitoring
---	--	------------

Vehicle Deep Clean	08/05/2025	07:30	09/05/2025	10:30	313,701	St Leonards	SL050826
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

O2 Pipeline Annual Inspection	05/05/2025	13:54	06/05/2025	13:55	313,621	MDT Ferndown	TF004171
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

O2 Pipeline Annual Inspection Annual Inspection and Pressure Test - Passed all tests.

MOT EXPIRES	25/05/2025	07:00	27/05/2025	10:00	315,531	St Leonards	SL051192
--------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

MOT Tuesday 0800 @ Ferndown Comms

Breakdown	14/06/2025	18:09	15/06/2025	06:24	316,831	St Leonards	SL051544
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown Non starter - Flat Battery

Breakdown	10/07/2025	15:55	13/07/2025	07:32	317,739	St Leonards	SL051988
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown FLEAS IN SALOON

Decommission Vehicle	04/08/2025	09:51			317,739	St Leonards	SL052481
-----------------------------	-------------------	--------------	--	--	----------------	--------------------	-----------------