

WM64JYE	A&E		Weymouth Amb Stn				
PDI Inspection	19/03/2015	07:00	17/04/2015	12:00	91	St Leonards	SL015922
PDI Inspection	Carried out PDI ect						
SAFETY INSPECTION	13/04/2015	07:00	13/04/2015	07:00	91	St Leonards	SL016036
18 Wheels Check Torques	Not operational. PDI in progress.						
Safety Inspection							
Vehicle Deep Clean							
Unplanned Repair	20/04/2015	13:00	20/04/2015	13:30	721	Dorchester	DC012878
44 Add Ad Blue	chech oil level						
45 Engine 1							
Unplanned Repair	01/05/2015	08:00	01/05/2015	08:30	2,597	Dorchester	DC012923
44 Add Ad Blue	top up						
Unplanned Repair	11/05/2015	15:00	11/05/2015	15:43	5,203	Dorchester	DC012953
44 Add Ad Blue							
Unplanned Repair	24/05/2015	01:15	25/05/2015	01:45	7,535	Dorchester	DC013029
44 Add Ad Blue	Topped up by Bronze						
Unplanned Repair	28/05/2015	01:00	28/05/2015	01:15	8,350	Dorchester	DC013041
44 Add Ad Blue	Emg Warning Devices Top up AD blue warning on dash, amber light						

SAFETY INSPECTION	01/06/2015	08:00	01/06/2015	13:00	9,007	Dorchester	DC013060
18 Wheels Check Torques							
34 Emergency Lights	front upper o/s blue inop		warranty			Awaiting Warranty	
44 Add Ad Blue							
45 Engine Oil Top Up							
85 Body Interior 1	draw catch not operating correctly						
Safety Inspection							
Vehicle Deep Clean	02/06/2015	09:30	02/06/2015	14:30	9,019	Dorchester	DC013073
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	13/06/2015	09:45	13/06/2015	10:00	11,205	Dorchester	DC013128
44 Add Ad Blue	Topped up by Bronze						
Unplanned Repair	17/06/2015	15:30	17/06/2015	15:45	11,755	Dorchester	DC013146
44 Add Ad Blue							
Breakdown	20/06/2015	16:29	20/06/2015	18:00	12,518	Dorchester	DC013160
17 Tyres Replace	Carried out by ATS						
Breakdown	2 front tyres changed						
Breakdown	22/06/2015	11:22	23/06/2015	09:04	12,823	Dorchester	DC013170
Breakdown	O2 pipe leaking						
Unplanned Repair	29/06/2015	07:45	29/06/2015	08:19	13,919	Dorchester	DC013194

44 Add Ad Blue

Unplanned Repair	28/06/2015	09:00	28/06/2015	09:30	13,845	Dorchester	DC013197
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

44 Add Ad Blue	Topped up by Bronze
----------------	---------------------

SAFETY INSPECTION	08/07/2015	08:00	08/07/2015	16:00	15,822	Dorchester	DC013240
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

15 Steering 1	Steering sensor out. Reset Steering peramitors.	
17 Tyres	AllR/Tyres at 4.5 mm	Monitoring
18 Wheels Check Torques	Done.	
34 Emergency Lights	front upper o/s blue inop warranty contractor	
55 Tail Lift	Remove hand rails Repair & Refit.	
Safety Inspection	Done.	
Wear & Tear Repair	Torch u/s . Replace battery.	

Vehicle Deep Clean	09/07/2015	07:00	09/07/2015	14:30	15,830	Dorchester	DC013246
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	31/07/2015	08:00	31/07/2015	08:30	19,963	Dorchester	DC013357
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

44 Add Ad Blue

BREAKDOWN	01/08/2015	09:14	03/08/2015	11:11	20,582	Dorchester	DC013367
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine 1	LOP reported.Carry out checks and long road test,ok
-------------	---

Unplanned Repair	07/08/2015	07:30	07/08/2015	07:47	21,376	Dorchester	DC013387
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Oil Top Up

Unplanned Repair	10/08/2015	14:00	10/08/2015	14:36	22,099	Dorchester	DC013396
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

89 Seats	Body Interior seat handle in back of ambulance broken	Awaiting Warranty
----------	---	-------------------

Unplanned Repair	11/08/2015	03:20	11/08/2015	03:35	22,230	Dorchester	DC013401
44 Add Ad Blue	Topped up by Bronze						
Unplanned Repair	13/08/2015	09:00	13/08/2015	09:30	22,745	Dorchester	DC013412
03 Instruments & Sensors 1	ESP light carry out checks and reset.Road test						
Unplanned Repair	14/08/2015	13:30	14/08/2015	14:27	22,966	Dorchester	DC013422
44 Add Ad Blue							
Breakdown	17/08/2015	19:30	17/08/2015	20:00	23,529	Dorchester	DC013440
Breakdown	EML/Limp mode					Awaiting Warranty	
SAFETY INSPECTION	18/08/2015	08:26	19/08/2015	10:00	23,792	Dorchester	DC013444
17 Tyres	All R/Tyres at 4.5 mm						
18 Wheels Check Torques							
44 Add Ad Blue							
85 Body Interior 1	carry chair bracket damaged repair						
89 Seats	Attendent seat seized						
Breakdown	EML/Limp mode						
Road Test							
Safety Inspection							
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	19/08/2015	12:00	20/08/2015	11:00	23,806	Dorchester	DC013450
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/08/2015	10:28	20/08/2015	13:56	23,813	Dorchester	DC013455
89 Seats	Attendent seat seized,handle broken						

Unplanned Repair	01/09/2015	08:00	01/09/2015	08:36	25,962	Dorchester	DC013513
44 Add Ad Blue							
Unplanned Repair	10/09/2015	07:00	10/09/2015	07:30	27,520	Dorchester	DC013556
44 Add Ad Blue							
Unplanned Repair	11/09/2015	18:00	11/09/2015	18:01	27,521	Dorchester	DC013589
44 Add Ad Blue topped up by bronze cmd							
Breakdown	21/09/2015	16:21	22/09/2015	08:00	29,379	Dorchester	DC013596
Breakdown mirror knocked off/smashed Monitoring							
Unplanned Repair	22/09/2015	07:30	22/09/2015	08:30	29,493	Dorchester	DC013598
86 Doors unable to open side door strip and adjust							
Unplanned Repair	23/09/2015	09:00	23/09/2015	09:37	29,801	Dorchester	DC013607
44 Add Ad Blue							
Unplanned Repair	23/09/2015	12:45	23/09/2015	13:02	29,824	Dorchester	DC013612
45 Engine Oil Top Up							
Unplanned Repair	26/09/2015	16:20	26/09/2015	16:35	30,383	Dorchester	DC013634
34 Lights Bulb Replacement Replaced by Bronze							
SAFETY INSPECTION	01/10/2015	10:00	02/10/2015	15:00	31,476	Dorchester	DC013663
18 Wheels Check Torques							

44 Add Ad Blue
Safety Inspection

Vehicle Deep Clean	05/10/2015	08:00	05/10/2015	12:00	31,507	Dorchester	DC013680
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Travel Time Vehicle Deep Clean	Vehicle Deep Clean
-----------------------------------	--------------------

Unplanned Repair	06/10/2015	09:15	06/10/2015	09:56	31,805	Dorchester	DC013685
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

02 Mirrors	n/s mirror broken
------------	-------------------

Unplanned Repair	14/10/2015	14:55	14/10/2015	15:33	33,603	Dorchester	DC013734
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue

Unplanned Repair	26/10/2015	12:00	26/10/2015	12:34	36,227	Dorchester	DC013774
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Refill
-------------------	--------

Unplanned Repair	28/10/2015	06:00	28/10/2015	06:15	36,477	Dorchester	DC013782
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

34 Lights Bulb Replacement	Carried out by Bronze
----------------------------	-----------------------

Unplanned Repair	02/11/2015	07:30	02/11/2015	08:00	37,706	Dorchester	DC013804
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue

SAFETY INSPECTION	10/11/2015	09:28	11/11/2015	14:38	39,453	Dorchester	DC013851
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

13 Brake Pads 18 Wheels Check Torques 44 Add Ad Blue	all pads worn
--	---------------

45 Engine Oil Top Up
 87 - Stretchers/Chairs/Boards straps damaged
 Safety Inspection

Vehicle Deep Clean	12/11/2015	14:00	13/11/2015	11:30	39,468	Dorchester	DC013871
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Travel Time	
Vehicle Deep Clean	Vehicle Deep Clean

Unplanned Repair	01/12/2015	13:00	01/12/2015	13:15	43,123	Taunton	TN013701
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

44 Add Ad Blue	topped up adblue
----------------	------------------

Unplanned Repair	11/12/2015	01:30	11/12/2015	01:45	45,230	Dorchester	DC014004
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Topped up by Bronze
-------------------	---------------------

Unplanned Repair	12/12/2015	14:15	12/12/2015	14:30	45,300	Dorchester	DC014007
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Top up
-------------------	--------

Unplanned Repair	14/12/2015	15:00	14/12/2015	15:30	46,011	Dorchester	DC014015
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

17 Tyres Replace	ATS replaced front tyres
------------------	--------------------------

Unplanned Repair	17/12/2015	13:00	17/12/2015	13:30	46,501	Dorchester	DC014029
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Top up
-------------------	--------

SAFETY INSPECTION	21/12/2015	09:49	23/12/2015	08:00	47,245	Dorchester	DC014053
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

17 Tyres Fit Winter	
18 Wheels Check Torques	
34 Lights Bulb Replacement	Replace o/s headlamp bulb
86 Doors	Dent in o/s/f door

Monitoring

Check Winter Pack Safety Inspection 93 - D Service Service D	Missing						
Vehicle Deep Clean	23/12/2015	08:00	23/12/2015	12:30	47,255	Dorchester	DC014064
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	29/12/2015	14:10	29/12/2015	14:27	48,250	Dorchester	DC014089
02 Mirrors	Replace n/s lower glass						
Unplanned Repair	04/01/2016	08:00	04/01/2016	08:30	49,298	Dorchester	DC014109
45 Engine Ad Blue							
Unplanned Repair	13/01/2016	07:30	13/01/2016	08:08	50,993	Dorchester	DC014164
44 Add Ad Blue							
Unplanned Repair	19/01/2016	05:00	19/01/2016	05:15	52,029	Dorchester	DC014193
34 Lights Bulb Replacement	Replaced by Bronze						
Unplanned Repair	20/01/2016	11:15	20/01/2016	11:59	52,236	Dorchester	DC014204
03 Instruments & Sensors 1	limp mode chech and clear fault road test						
Unplanned Repair	22/01/2016	08:00	22/01/2016	08:45	52,597	Dorchester	DC014215
34 Lighting System	Lighting System Indicator knocked at front, still roadworthy						

Unplanned Repair	23/01/2016	23:00	23/01/2016	23:15	52,907	Dorchester	DC014223
45 Engine Ad Blue	Topped up by Bronze						
Breakdown	24/01/2016	18:02	25/01/2016	14:28	53,083	Dorchester	DC014218
87 Stretcher Harness Replaced Breakdown	Striker trolley faulty -see below						
Unplanned Repair	28/01/2016	07:00	28/01/2016	07:39	53,641	Dorchester	DC014243
44 Add Ad Blue 45 Engine Oil Top Up							
SAFETY INSPECTION	02/02/2016	08:13	04/02/2016	16:00	54,578	Dorchester	DC014266
02 Cab Assembly 1 18 Wheels Check Torques 45 Engine Ad Blue 45 Engine Oil Top Up 85 Body Interior 1 86 Doors Safety Inspection MOT Pre Test Gearbox Oil & Filter Change Travel Time MOT Tail Lift 6 Monthly Inspection	cab light inop Emg Warning Devices amber oil light, no effect on performance. straps broken Dent in o/s/f door Statutory Inspection						
Vehicle Deep Clean	05/02/2016	08:30	05/02/2016	12:30	54,597	Dorchester	DC014287
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	16/02/2016	07:45	16/02/2016	08:15	56,568	Dorchester	DC014334
45 Engine Ad Blue							

Unplanned Repair	18/02/2016	23:45	19/02/2016	00:01	57,167	Dorchester	DC014358
34 Lights Bulb Replacement Headlight bulb replaced by Bronze							
Unplanned Repair	25/02/2016	07:30	25/02/2016	08:05	58,538	Dorchester	DC014392
45 Engine Ad Blue							
Unplanned Repair	29/02/2016	07:30	29/02/2016	11:12	59,327	Dorchester	DC014410
45 Engine 1 LOP reported							
Unplanned Repair	02/03/2016	08:00	02/03/2016	08:15	59,521	Dorchester	DC014426
87 - Stretchers/Chairs/Boards Replace misssing pedimate							
Breakdown	05/03/2016	02:15	05/03/2016	08:00	59,521	Dorchester	DC014436
Breakdown red light come on dash							
Unplanned Repair	09/03/2016	09:30	09/03/2016	10:00	61,171	Dorchester	DC014456
02 Mirrors Replace o/s casing							
Unplanned Repair	11/03/2016	10:30	11/03/2016	11:00	61,648	Dorchester	DC014467
45 Engine Ad Blue							
SAFETY INSPECTION	15/03/2016	08:30	16/03/2016	13:30	61,688	Dorchester	DC014486
17 Tyres Replace o/s/f worn							
18 Wheels Check Torques							
33 Ignition System Other Invalid key fob on fuel pump, raised to estates							
87 Stretcher wrong and missing straps							

Safety Inspection throw line fitted
 UB Fire Suppression Service
 Annual Heater Service Annual Heater Service
 Tail Lift Annual Service Statutory Inspection and Weight Test
 Wheel Studs & Nuts Replaceme
 Handbrake Cable Replacement Replace rear handbrake cables

Breakdown **21/03/2016** **17:14** **22/03/2016** **09:04** **63,454** **Dorchester** **DC014510**

86 Door Lock strip clean adjust rebuild
 Breakdown Rear door stuck

Unplanned Repair **23/03/2016** **09:00** **23/03/2016** **10:01** **63,466** **Dorchester** **DC014521**

17 Tyres Replace Punctured tyre replaced by ATS

Breakdown **28/03/2016** **20:40** **28/03/2016** **21:40** **64,365** **Dorchester** **DC014533**

Breakdown STUCK IN 2ND GEAR

Unplanned Repair **28/03/2016** **21:00** **28/03/2016** **21:30** **64,489** **Dorchester** **DC014535**

45 Engine Ad Blue Topped up by Bronze

Breakdown **01/04/2016** **19:44** **01/04/2016** **21:35** **65,017** **Dorchester** **DC014559**

17 Tyres Replace O/S/R/I tyre flat.Replaced.
 Breakdown Flat R/O/S
 Travel Time Travel to and from Weymouth.

Unplanned Repair **02/04/2016** **10:00** **02/04/2016** **12:00** **65,217** **Dorchester** **DC014563**

44 Add Ad Blue Add-Blue low,Bunker fob n/w.Supply Add-Blue.
 Travel Time Travel to and from Dorchester Stn.

Unplanned Repair **08/04/2016** **08:15** **08/04/2016** **08:50** **67,158** **Dorchester** **DC014586**

45 Engine Ad Blue	Top up						
Unplanned Repair	08/04/2016	02:30	08/04/2016	02:45	67,427	Dorchester	DC014594
34 Lights Bulb Replacement	Replaced by Bronze						
Unplanned Repair	19/04/2016	10:10	19/04/2016	10:44	68,311	Dorchester	DC014632
45 Engine Ad Blue	Top up						
Breakdown	22/04/2016	09:25	22/04/2016	11:30	68,723	Dorchester	DC014648
Breakdown	Puncture						
SAFETY INSPECTION	26/04/2016	07:37	27/04/2016	11:30	69,452	Dorchester	DC014665
13 Brake Pads	front pads worn						
17 Tyres Replace	3 tyres worn						
18 Wheels Check Torques							
34 Lighting System	rear no-plate inop						
44 Add Ad Blue							
Safety Inspection							
85 Body Int Alcohol Gel Dispen							
Vehicle Deep Clean	Vehicle Deep Clean						
92 - C Service							
Service C							
Install Saloon CCTV Camera							
Vehicle Deep Clean	27/04/2016	10:30	28/04/2016	08:30	69,466	Dorchester	DC014677
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/05/2016	16:48	26/05/2016	08:28	75,086	Dorchester	DC014784
86 Doors Rear	Rear door bottom lock rod not operating						
Breakdown	rear door will not open						
Travel Time	Travel to Weymouth						

Unplanned Repair	26/05/2016	07:00	26/05/2016	08:00	75,092	Dorchester	DC014786
86 Doors Rear	rear o/s door jammed						
Unplanned Repair	03/06/2016	06:00	03/06/2016	06:30	76,824	Dorchester	DC014827
71 Body Exterior 1	Grill damaged by Deer strike.Carry out repair.Order new						Awaiting Parts
SAFETY INSPECTION	07/06/2016	08:26	09/06/2016	12:30	77,639	Dorchester	DC014839
18 Wheels Check Torques							
34 Lights Bulb Replacement	n/s day running light inop						
45 Engine Ad Blue							
71 Body Exterior 1	Grill damaged by Deer strike.Carry out repair.Order new						
Safety Inspection							
Travel Time							
Reposition grab bag shelf	lower shelf raised						
Vehicle Deep Clean	09/06/2016	12:00	10/06/2016	12:04	77,662	Dorchester	DC014855
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	16/06/2016	09:19	16/06/2016	09:22	78,667	Dorchester	DC014879
87 Stretcher	Replace missing Pedi mate						
Unplanned Repair	23/06/2016	10:30	23/06/2016	11:45	80,000	Dorchester	DC014906
86 Doors Rear	Replace hinge pin						

Unplanned Repair	27/06/2016	07:30	27/06/2016	08:00	80,715	Dorchester	DC014916
45 Engine Oil Top Up							
Breakdown	02/07/2016	17:50	02/07/2016	19:15	81,875	Dorchester	DC014941
17 Tyres Replace	Replace o/s/f tyre						
Breakdown	BOLD TYRE						
Travel Time							
Unplanned Repair	04/07/2016	07:15	04/07/2016	07:45	82,191	Dorchester	DC014948
45 Engine Ad Blue							
Unplanned Repair	08/07/2016	07:10	08/07/2016	07:25	83,011	Dorchester	DC014973
45 Engine Oil Top Up							
Breakdown	08/07/2016	21:15	09/07/2016	12:30	83,136	Dorchester	DC014979
45 Engine 1	drive belt starting to break up						
45 Engine 2	chech for oil leaks none found oil level correct suspect oil sensor						
Breakdown	oil warning light on / headlight bulb blown						
Road Test							
Travel Time	travel to and from						
Unplanned Repair	08/07/2016	20:30	08/07/2016	22:30	83,136	Dorchester	DC014981
45 Engine 1	oil light on						
Travel Time	travel to and from						
Unplanned Repair	11/07/2016	07:00	11/07/2016	07:30	83,456	Dorchester	DC014983
45 Engine Ad Blue							
Unplanned Repair	11/07/2016	09:14	11/07/2016	09:30	83,463	Dorchester	DC014985
34 Lights	o/s running lamp inop,replace bulb						

ACCIDENT	12/07/2016	08:00	21/07/2016	09:30	83,540	Dorchester	DC014992
-----------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

71 Body Exterior Acc Repair	Collision with deer
-----------------------------	---------------------

SAFETY INSPECTION	21/07/2016	09:39	22/07/2016	10:54	83,702	Dorchester	DC015038
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

13 Brakes 1	Rear discs and pads worn
17 Tyres Replace	
18 Wheels Check Torques	
55 Tail Lift	Magnet missing from o/s rail
86 Doors Rear	o/s/r door stay snapped
Safety Inspection	
Annual Air Con Service	Annual Air Condition Service.CARRIED OUT AFTER RTC REPAIR

Vehicle Deep Clean	22/07/2016	10:30	22/07/2016	15:30	83,716	Dorchester	DC015045
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Travel Time	
Vehicle Deep Clean	Vehicle Deep Clean

Breakdown	26/07/2016	17:22	27/07/2016	07:30	84,524	Dorchester	DC015059
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Breakdown	NUMBER PLATE
-----------	--------------

Unplanned Repair	08/08/2016	09:30	08/08/2016	10:00	86,776	Dorchester	DC015102
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Top up
-------------------	--------

Unplanned Repair	24/08/2016	09:30	24/08/2016	09:49	89,893	Dorchester	DC015189
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

34 Lights Bulb Replacement	o/s repeater inop,replace bulb
----------------------------	--------------------------------

Breakdown	27/08/2016	08:00	27/08/2016	10:44	90,552	Dorchester	DC015212
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

17 Tyres Replace	N/S/R/I flat. O/s/r/i low tread. Replaced x2.
18 Wheels	Rim cracked

Breakdown
Travel Time

Puncture n/s/r. bald tyre o/s/r
Travel to and from Weymouth.

Breakdown **29/08/2016** **19:03** **29/08/2016** **20:30** **91,036** **Dorchester** **DC015216**

Breakdown N/S/F under inflated tyre

Unplanned Repair **29/08/2016** **19:00** **29/08/2016** **21:30** **91,036** **Dorchester** **DC015219**

17 Tyres Replace N/S/F tyre flat. Replaced.
18 Wheels Rim cracked
Travel Time Travel to and from Weymouth Station.

Unplanned Repair **30/08/2016** **07:45** **30/08/2016** **08:00** **91,183** **Dorchester** **DC015220**

45 Engine Oil Top Up

SAFETY INSPECTION **31/08/2016** **08:02** **01/09/2016** **13:10** **91,264** **Dorchester** **DC015226**

02 Cab Assembly 1 cab light inop
17 Tyres Replace 2 rear tyres low
18 Wheels Check Torques
Safety Inspection
Travel Time
Tail Lift 6 Monthly Inspection Statutory Inspection
93 - D Service
Service D

Vehicle Deep Clean **05/09/2016** **08:00** **05/09/2016** **11:45** **91,278** **Dorchester** **DC015251**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **05/09/2016** **16:21** **06/09/2016** **07:58** **91,285** **Dorchester** **DC015258**

Breakdown MDT Failure/battery check

Unplanned Repair **09/09/2016** **21:15** **09/09/2016** **22:30** **92,188** **Dorchester** **DC015291**

34 Lights o/s headlamp inop.See notes Awaiting Warranty

Travel Time

Breakdown	11/09/2016	06:44	11/09/2016	07:15	92,499	Dorchester	DC015290
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Breakdown	headlight drivers side
Travel Time	

Unplanned Repair	12/09/2016	08:08	12/09/2016	12:15	92,600	Dorchester	DC015296
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

34 Lights	o/s headlamp inop.See notes
Travel Time	

Unplanned Repair	15/09/2016	07:30	15/09/2016	08:00	93,297	Dorchester	DC015319
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

17 Tyres	o/s/r chech for puntures none found
----------	-------------------------------------

Unplanned Repair	28/09/2016	07:50	28/09/2016	08:05	95,922	Dorchester	DC015389
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

34 Lights Bulb Replacement	n/s riding light inop
----------------------------	-----------------------

Unplanned Repair	29/09/2016	10:00	29/09/2016	10:39	96,050	Dorchester	DC015398
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

86 Sliding Door	repair cover adjust magnet bracket
-----------------	------------------------------------

SAFETY INSPECTION	12/10/2016	07:54	13/10/2016	14:00	98,716	Dorchester	DC015456
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

13 Brake Pads	front pads worn	
13 Discs	front discs worn	
16 Suspension 1	rear road spring buffers broken	
16 Suspension 2	front n/s shock absorber play	Awaiting Warranty
18 Wheels Check Torques		
45 Engine Ad Blue		
86 Doors Rear	rear o/s door seperating from frame	
89 Seatbelts	Attendent seat belt broken.Replace	
Safety Inspection		
Travel Time		
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill	

Vehicle Deep Clean	14/10/2016	08:30	14/10/2016	13:22	98,729	Dorchester	DC015474
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/10/2016	07:00	21/10/2016	07:34	100,224	Dorchester	DC015517
45 Engine Oil Top Up							
Unplanned Repair	25/10/2016	13:55	25/10/2016	14:08	101,196	Dorchester	DC015542
56 Comms Equipment	Electrical Auxs Cab Radio fist mic cable split.Carry out temp repair.PCE to sort						
Breakdown	06/11/2016	01:55	15/11/2016	14:26	103,790	Dorchester	DC015598
03 Instruments & Sensors 1 Breakdown Travel Time	Fire trace deployed warning going off ERROR WITH FIRE SUPPRESSOR SENSOR						
SAFETY INSPECTION	23/11/2016	09:12	29/11/2016	10:42	105,366	Dorchester	DC015690
16 Suspension 2 18 Wheels Check Torques 44 Add Ad Blue 45 Engine Oil Top Up 56 Comms Equipment Safety Inspection Travel Time Gearbox Oil & Filter Change	front n/s shock absorber play replace s d card						
Vehicle Deep Clean	29/11/2016	08:00	30/11/2016	10:15	105,426	Dorchester	DC015721
Travel Time							

Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/12/2016	07:00	08/12/2016	07:34	106,735	Dorchester	DC015770
45 Engine Oil Top Up							
SAFETY INSPECTION	03/01/2017	08:00	04/01/2017	12:47	112,027	Dorchester	DC015903
02 Cab Assembly 1	cab light inop						
17 Tyres Replace	replace two tyres						
18 Wheels Check Torques							
34 Lights	n/s/r marker light inop						
45 Engine Ad Blue							
Safety Inspection							
MOT Pre Test							
Medical Device and Equip Chec correct							
92 - C Service							
Service C							
Travel Time							
MOT							
Vehicle Deep Clean	04/01/2017	12:00	05/01/2017	11:15	112,048	Dorchester	DC015920
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	14/01/2017	20:40	14/01/2017	21:10	113,664	Dorchester	DC016006
17 Tyres Replace	Puncture reported.Repaired by ATS						
BREAKDOWN	15/01/2017	06:00	15/01/2017	11:00	113,678	Dorchester	DC015981
17 Tyres	Re torque N/S/F wheel.						
Travel Time	Longham to weymouth to Doecheater & Return.						

Unplanned Repair	17/01/2017	13:00	17/01/2017	13:43	114,070	Dorchester	DC015996
45 Engine Ad Blue							
Unplanned Repair	02/02/2017	08:10	02/02/2017	08:27	116,944	Dorchester	DC016075
45 Engine Oil Top Up							
Unplanned Repair	08/02/2017	01:00	08/02/2017	01:15	118,261	Dorchester	DC016106
34 Lights Bulb Replacement Head light bulb replaced by Bronze							
Unplanned Repair	08/02/2017	07:55	08/02/2017	08:13	118,356	Dorchester	DC016107
34 Lights n/s/ repeater smashed.Carry out temp repair and order new Awaiting Parts							
Unplanned Repair	09/02/2017	11:00	09/02/2017	11:15	118,474	Dorchester	DC016118
34 Lights n/s/ repeater smashed.Carry out temp repair and order new.Replace							
Unplanned Repair	10/02/2017	07:00	10/02/2017	07:15	118,587	Dorchester	DC016120
87a - Medical Equipment RepairReplace Mangar charger.Wire broken							
SAFETY INSPECTION	15/02/2017	07:00	15/02/2017	15:30	119,438	Dorchester	DC016140
17 Tyres Replace rear tyres worn x4 replaced 18 Wheels Check Torques checked 34 Lights repair ns marker light and number plate light 34 Lights Bulb Replacement side light inop. replaced bulb 45 Engine Ad Blue filled up 71 Body Exterior 1 Body Exterior damage noted to rear near side blue light 86 Sliding Door bearings worn replaced bearings Safety Inspection done							
Vehicle Deep Clean	15/02/2017	13:00	16/02/2017	12:00	119,450	Dorchester	DC016147

Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	22/02/2017	08:09	22/02/2017	09:11	120,760	Dorchester	DC016177
17 Tyres 18 Wheels 18 Wheels Retorque	Check rear tyres,punctures reported by driver.Check fault,both inner rims u/s Replace both inner wheels due to cracked rims						
Unplanned Repair	27/02/2017	10:00	27/02/2017	10:55	121,738	Dorchester	DC016198
86 Door Lock	Central locking fault on sliding door.Carry out repair						
BREAKDOWN	28/02/2017	07:30	28/02/2017	14:00	121,795	Dorchester	DC016206
01 Heating 1 86 Sliding Door Travel Time	Other CAB HEATER DEFECTIVE.Blower inop Replace smashed inner panel						
Unplanned Repair	09/03/2017	14:25	09/03/2017	14:43	123,370	Dorchester	DC016256
34 Lights Bulb Replacement	n/s running light inop						
Unplanned Repair	12/03/2017	00:15	12/03/2017	00:30	123,824	Dorchester	DC016271
34 Lights Bulb Replacement	Headlight bulb replaced by Bronze						
Unplanned Repair	21/03/2017	11:07	21/03/2017	11:10	125,757	Dorchester	DC016314
17 Tyres Replace	replace both o/s/r by ATS						
Unplanned Repair	23/03/2017	12:50	23/03/2017	13:06	126,173	Dorchester	DC016325
02 Windscreen Wipers							

SAFETY INSPECTION	28/03/2017	09:00	03/04/2017	11:18	127,150	Dorchester	DC016351
01 Air Conditioning 1	Tensioner u/s						Awaiting Parts
13 Brake Pads	Rear pads worn,replace						
13 Brakes 1	Replace pedal rubber						
18 Wheels Check Torques							
34 Emergency Light System	Airport light missing						
55 Tail Lift	Refit bridge plate guides						
Safety Inspection							
Travel Time							
WAS Firetrace rework & Service							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Handbrake Cable Replacement	Replace rear handbrake cables						
UB Fire Suppression Service							
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	30/03/2017	08:00	30/03/2017	12:30	127,150	Dorchester	DC016360
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	21/04/2017	09:50	24/04/2017	12:39	130,680	Dorchester	DC016470
45 Engine 1	LOP reported,Gone to Pentagon						
Travel Time							
SAFETY INSPECTION	08/05/2017	08:00	09/05/2017	15:00	133,201	Dorchester	DC016535
13 Brake Pads	front pads worn						
17 Tyres Replace	o/s/f worn						
18 Wheels Check Torques							
34 Emergency Light System	Airport light missing						
Safety Inspection							
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
93 - D Service							
Service D							

Vehicle Deep Clean	09/05/2017	09:30	09/05/2017	14:30	133,209	Dorchester	DC016542
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	14/05/2017	07:00	14/05/2017	09:30	134,051	Dorchester	DC016560
17 Tyres Replace	puncture						
18 Wheels	cracked						
Breakdown	N/S/F						
Travel Time	travel to and from						
Unplanned Repair	16/05/2017	07:00	16/05/2017	07:31	134,327	Dorchester	DC016570
17 Tyres Replace	puncture n/s/f						
18 Wheels	wheel rim cracked						
MGS Gas Storage Modifications	19/05/2017	11:00	19/05/2017	11:30	134,884	Dorchester	DC016601
MGS Gas Storage Modifications	MGS Gas Storage Modifications						
Breakdown	20/05/2017	19:10	20/05/2017	20:10	135,191	Dorchester	DC016603
Breakdown	limp mode ESP light on						
Travel Time							
Unplanned Repair	25/05/2017	07:10	25/05/2017	07:40	136,064	Dorchester	DC016625
02 Mirrors	n/s mirror smashed,replace						
Unplanned Repair	09/06/2017	08:15	09/06/2017	09:15	138,726	Dorchester	DC016702
86 Door handle	Body Exterior Rear side door handle (outside) snapped off						

COMMS.FAILURE CHECK	19/06/2017	12:05	19/06/2017	13:05	140,860	Dorchester	DC016740
MDT Failure/Issue							
SAFETY INSPECTION	20/06/2017	08:00	21/06/2017	08:50	140,860	Dorchester	DC016745
02 Cab Assembly 1 cab light inop							
17 Tyres Replace rear tyre X 3							
18 Wheels cracked rim							
18 Wheels Check Torques							
34 Emergency Lights top corner damaged temp repair carried out							
45 Engine Ad Blue							
55 Tail Lift sliders damaged							
Road Test							
Safety Inspection							
MGS Gas Storage ModificationsMGS Gas Storage Modifications fitted on 19/05/17							
Vehicle Deep Clean	21/06/2017	09:00	21/06/2017	14:45	140,861	Dorchester	DC016763
Vehicle Deep Clean Vehicle Deep Clean							
Unplanned Repair	27/06/2017	12:15	27/06/2017	12:46	141,869	Dorchester	DC016796
86 Sliding Door Outer handle jammed.Free off							
Breakdown	27/06/2017	16:35	27/06/2017	16:45	140,885	Dorchester	DC016798
Breakdown eml limp mode sorted over phone							
Unplanned Repair	04/07/2017	15:00	04/07/2017	15:30	143,062	Dorchester	DC016833
86 Door Lock side door jammed							
Unplanned Repair	10/07/2017	07:30	10/07/2017	07:45	144,082	Dorchester	DC016857
45 Engine Oil Top Up							

Breakdown	19/07/2017	04:02	19/07/2017	12:12	145,629	Dorchester	DC016895
34 Lights Bulb Replacement Breakdown	n/s running light inop,replace bulb limp mode and EML on						
Replace Vehicle Fuel Card	21/07/2017	11:13	21/07/2017	11:13	145,955	Dorchester	DC016928
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Breakdown	23/07/2017	17:45	26/07/2017	10:40	146,406	Dorchester	DC016938
44 Fuel System 1 Breakdown Travel Time	Fuel pressure issues limp mode 5-6 times today						
Unplanned Repair	26/07/2017	17:00	26/07/2017	17:15	146,531	Dorchester	DC016967
34 Lights Bulb Replacement	Head light bulb replaced by Bronze						
Unplanned Repair	27/07/2017	07:30	27/07/2017	07:47	146,568	Dorchester	DC016968
45 Engine Oil Top Up							
SAFETY INSPECTION	31/07/2017	10:00	01/08/2017	12:00	147,246	Dorchester	DC016983
18 Wheels Check Torques 45 Engine Ad Blue 55 Tail Lift 86 Sliding Door Safety Inspection	sliders damaged top magnet bracket bent reposition						
Vehicle Deep Clean	01/08/2017	10:30	02/08/2017	08:35	147,253	Dorchester	DC016990
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	01/09/2017	12:00	01/09/2017	12:40	152,889	Dorchester	DC017150
44 Add Ad Blue							
Unplanned Repair	08/09/2017	08:15	08/09/2017	08:30	154,242	Dorchester	DC017176
45 Engine Oil Top Up							
SAFETY INSPECTION	12/09/2017	08:14	14/09/2017	10:30	154,991	Dorchester	DC017188
13 Brake Pads	front and rear pads worn						
17 Tyres Replace	o/s/r both at limit						
18 Wheels Check Torques							
34 Emergency Lights	o/s upper blue damagd						
44 Add Ad Blue							
Safety Inspection							
Travel Time							
92 - C Service							
Service C							
Gearbox Oil & Filter Change							
Vehicle Deep Clean	14/09/2017	12:00	15/09/2017	11:30	155,010	Dorchester	DC017210
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	02/10/2017	19:28	03/10/2017	09:50	157,944	Dorchester	DC017273
86 Sliding Door Breakdown	Check fault,replaced damaged outer door handle defective slide door/cannot be open from outside						
Unplanned Repair	04/10/2017	08:30	04/10/2017	08:45	158,013	Dorchester	DC017286
45 Engine Oil Top Up							
Unplanned Repair	05/10/2017	09:25	05/10/2017	10:03	158,205	Dorchester	DC017294
86 Sliding Door	Door warning going off.Check fault,adjust switch						

Breakdown	08/10/2017	19:56	08/10/2017	21:00	158,868	Dorchester	DC017301
17 Tyres Replace Breakdown	Check and replace o/s/r tyres,carry out retorque two bold tyres/ offside rear						
Unplanned Repair	10/10/2017	11:20	10/10/2017	11:37	159,093	Dorchester	DC017315
34 Lights Bulb Replacement	Replace n/s day running lamp bulb						
Breakdown	13/10/2017	18:35	10/11/2017	13:00	159,604	Dorchester	DC017335
31 Charging System 45 Engine 1 Breakdown Travel Time	Carry out checks,alternator u/s Rattle on start up,suspect cam chain/tensioner battery alternator						
SAFETY INSPECTION	10/11/2017	13:00	14/11/2017	08:00	159,818	Dorchester	DC017461
16 Suspension 1 17 Tyres 18 Wheels Check Torques 34 Emergency Lights 45 Engine Ad Blue 86 Sliding Door Safety Inspection Travel Time Tail Lift 6 Monthly Inspection	rear anti roll bar rubbers worn chech for leaks replace valve ext upper blue corner broken Doors Side loading door not opening from outside Statutory Inspection						
Vehicle Deep Clean	14/11/2017	08:00	15/11/2017	13:00	159,833	Dorchester	DC017468
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/11/2017	07:00	20/11/2017	08:15	160,558	Dorchester	DC017495

17 Tyres Replace	n/s/r inner						
Unplanned Repair	27/11/2017	06:45	27/11/2017	07:15	161,975	Dorchester	DC017528
45 Engine Ad Blue							
SAFETY INSPECTION	06/12/2017	08:34	11/12/2017	08:34	163,750	Dorchester	DC017565
02 Cab Assembly 1	N/S window switch broken.Replaced.						
13 Brakes 1	Front disc's worn.Replaced disc's and pads.						
13 Brakes 2	Rear disc's worn.Pads OK Monitor.						
15 Steering 1	Lower ball joints worn. Replaced lower arms.						
16 Suspension 1	Front struts worn.Replaced.						
17 Tyres Replace	N/S/R/O nailed. Replaced.						
18 Wheels Check Torques	Checked.						
27 Transmission Automatic	Oil leak feom sump gasket.Washed.						
Safety Inspection	Carried out inspection.						
MOT Pre Test							
Vehicle Deep Clean	07/12/2017	11:31	08/12/2017	09:00	163,706	Dorchester	DC017571
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	14/12/2017	08:30	14/12/2017	09:00	164,529	Dorchester	DC017606
44 Fuel System 1	AdBlue warning light on,check and top up level,clear warning light						
Unplanned Repair	15/12/2017	09:15	15/12/2017	10:49	164,807	Dorchester	DC017611
45 Engine 1	EML on.Carry out checks,carry out regen and long road test						
Breakdown	17/12/2017	22:08	18/12/2017	06:45	164,961	Dorchester	DC017618
86 Sliding Door Breakdown	Reset door mechanism side door jammed shut						

Unplanned Repair	17/12/2017	12:05	17/12/2017	12:50	164,893	Dorchester	DC017622
31 Battery Chassis 32 Starting System 1 Travel Time	Check battery and charge rate,ok Vehicle reported not turning over.Flat battery.See notes						
Unplanned Repair	19/12/2017	07:30	19/12/2017	08:00	165,078	Dorchester	DC017631
86 Sliding Door	Sliding door reported stiff.See notes						
Unplanned Repair	22/12/2017	13:00	22/12/2017	13:53	165,469	Dorchester	DC017654
86 Sliding Door	Sliding door top runner sheared off.carry out temp repair						Awaiting Parts
Breakdown	26/12/2017	02:54	27/12/2017	08:00	165,842	Dorchester	DC017663
86 Sliding Door Breakdown	Top roller sheared off.No parts until New Year Sidedoor not opening						Awaiting Warranty
Unplanned Repair	27/12/2017	10:00	27/12/2017	10:45	166,566	Dorchester	DC017671
33 Ignition System Travel Time	Ignition key broken.Supply spare key.order new Attend vehicle at DCH and supply spare key						Awaiting Parts
Unplanned Repair	28/12/2017	07:30	28/12/2017	08:21	166,698	Dorchester	DC017677
86 Sliding Door	Top roller sheared off.No parts until New Year						
Unplanned Repair	05/01/2018	11:47	05/01/2018	13:00	168,238	Dorchester	DC017714
45 Engine 1	EML on, run diagnostic and regen						
SAFETY INSPECTION	16/01/2018	07:33	24/01/2018	12:00	170,149	Dorchester	DC017776
13 Brake Pads 13 Discs	replaced pads rear fit discs						

13 Handbrake	park brake poor
18 Wheels Check Torques	
33 Ignition System	Ignition key broken.Supply spare key.order new.DONE
34 Lights	repair no plate wiring
45 Engine 1	LOP reported,AdbLue system fault.EGR valve and DPF replaced by dealer
85 Body Interior 1	replace fire ext x2
86 Sliding Door	Sliding door top runner sheared off.carry out temp repair
Safety Inspection	
Travel Time	take to pentagon
MOT	

Vehicle Deep Clean	24/01/2018	15:07	25/01/2018	12:00	170,230	Dorchester	DC017828
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	25/01/2018	22:48	30/01/2018	12:35	170,303	Dorchester	DC017833
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

42 Coolant System	Coolant loss from EGR hose.Return to dealer
Breakdown	Coolant Light
Travel Time	

Breakdown	08/02/2018	02:12	09/02/2018	11:36	172,116	Dorchester	DC017881
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	Check with TEXA.Exhaust pressure and Temp sender faults.Return to dealer
56 Comms Equipment	MDT not powering up
Breakdown	limp mode, eng. managment light
Travel Time	

BREAKDOWN	12/02/2018	07:30	22/02/2018	10:58	172,631	Dorchester	DC017890
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

27 Transmission Automatic	Oil toppedup by dealer
45 Engine 1	LOP,EML on.Check with TEXA exhaust pressure and fuel pressure fault.Warranty
Travel Time	

Unplanned Repair	23/02/2018	11:30	23/02/2018	12:30	172,901	Dorchester	DC017967
17 Tyres Replace	Both o/s/r tyres damaged at RTC.Replaced by ATS						
SAFETY INSPECTION	26/02/2018	08:30	27/02/2018	10:02	173,468	Dorchester	DC017977
17 Tyres	n/s/f low						
18 Wheels Check Torques							
45 Engine Ad Blue	top up ad blue						
86 Doors	Doors Side door handle stuck out						
Safety Inspection							
85 Body Int Alcohol Gel Dispen							
93 - D Service							
Service D							
Wheel Hub Flanges Replaceme							
Annual Heater Service	Annual Heater Service						
Handbrake Cable Replacement	cables replaced on DC17776 24/1/18						
UB Fire Suppression Service							
Vehicle Deep Clean	27/02/2018	10:30	27/02/2018	14:00	173,482	Dorchester	DC017990
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	04/03/2018	15:10	15/03/2018	14:34	174,175	Dorchester	DC018013
Breakdown	ABS warning light on wire detached underneath.SEE NOTES						
Travel Time							
Unplanned Repair	18/03/2018	20:45	18/03/2018	21:00	174,803	Dorchester	DC018087
34 Lights Bulb Replacement	Head light bulb replaced by Bronze						
Unplanned Repair	19/03/2018	07:30	19/03/2018	07:45	174,804	Dorchester	DC018089
86 Sliding Door	Door handle jammed,free off						

Unplanned Repair	20/03/2018	07:30	20/03/2018	07:45	175,058	Dorchester	DC018096
34 Lights Bulb Replacement	n/s running light inop,replace bulb						
Unplanned Repair	23/03/2018	03:00	23/03/2018	03:15	175,669	Dorchester	DC018114
34 Lights Bulb Replacement	Headlight bulb replaced by Bronze						
Unplanned Repair	06/04/2018	08:30	06/04/2018	09:25	178,235	Dorchester	DC018181
31 Battery Chassis	non start						
SAFETY INSPECTION	10/04/2018	08:00	10/04/2018	15:30	179,049	Dorchester	DC018198
17 Tyres	n/s/r tyres low o/sf tyre low						
18 Wheels Check Torques							
34 Lights	n/s side light n/w						
43 Exhaust System 1	tailpipe u/s						
45 Engine Ad Blue	level low						
71 Body External Steps	step sticking						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Fit Poster Holder	Fit Poster Holder						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	11/04/2018	09:00	11/04/2018	13:30	179,061	Dorchester	DC018212
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/04/2018	10:15	23/04/2018	11:39	181,008	Dorchester	DC018261
45 Engine 1	LOP reported.Remove and clean pressure/temp sensor						
Breakdown	28/04/2018	16:22	28/04/2018	16:30	181,705	Dorchester	DC018286
Breakdown	N/S/R inner puncture						

Unplanned Repair	28/04/2018	16:30	28/04/2018	17:30	181,705	Dorchester	DC018290
17 Tyres Replace 18 Wheels Travel Time	n/s/r inner puncture reported.Check over,rim cracked.Replace tyre/rim Rim cracked,replace						
Breakdown	29/04/2018	07:25	29/04/2018	08:15	181,807	Dorchester	DC018287
17 Tyres Replace 18 Wheels Breakdown Travel Time	Check fault,rim cracked Replace cracked rim Puncture inner rear						
Unplanned Repair	08/05/2018	15:00	08/05/2018	15:37	183,305	Dorchester	DC018337
71 Body Exterior 1	tailift guide loose						
Unplanned Repair	11/05/2018	07:45	11/05/2018	10:19	183,734	Dorchester	DC018354
13 Brakes 1 24 Driveshaft 1 52 Electrical Aux	noisey brakes rear prop u/s Battery/Charging Sys pls check rear and coms battery						
SAFETY INSPECTION	23/05/2018	09:30	24/05/2018	10:11	185,392	Dorchester	DC018416
13 Brake Pads 18 Wheels Check Torques 34 Lighting System 45 Engine Ad Blue 45 Engine Oil Top Up 85 Body Interior 1 Safety Inspection	front pads low n/s scene light not working torch not charging						
Vehicle Deep Clean	24/05/2018	10:49	25/05/2018	09:45	185,407	Dorchester	DC018432
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	30/05/2018	08:30	30/05/2018	09:13	185,927	Dorchester	DC018444
52 Electrical Aux	mdt not powering up						
Unplanned Repair	11/06/2018	09:00	11/06/2018	09:30	188,009	Dorchester	DC018507
86 Sliding Door	Unable to open side door.Carry out repair						
SAFETY INSPECTION	04/07/2018	06:21	04/07/2018	14:54	191,880	Dorchester	DC018634
02 Cab Assembly 1	Doors side door wont open from outside						
13 Brake Pads	rear pads						
17 Tyres	n/s/f tyre low and all rears						
18 Wheels	stud u/s						
18 Wheels Check Torques							
34 Lights	n/s drl not working						
45 Engine Ad Blue	top up						
52 Electrical Aux	Check Garmin updates						
55 Tail Lift	sliders damaged						
71 Body External Steps	Body Exterior resr step buckled.REPORTED ON WRONG VEHICLE						
85 Body Interior 1	strap broken						
Safety Inspection							
92 - C Service							
Service C							
Unplanned Repair	04/07/2018	01:00	04/07/2018	01:30	191,870	Dorchester	DC018635
34 Lights Bulb Replacement							
Travel Time							
Vehicle Deep Clean	05/07/2018	08:00	05/07/2018	12:30	191,902	Dorchester	DC018645
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	22/07/2018	23:48	23/07/2018	08:58	194,082	Dorchester	DC018718
56 Comms Equipment	MDT and SAT nav not communicating.PCE to sort						
86 Sliding Door	Not staying open.Straighten top magnet bracket						
Breakdown	MDT shutting down - battery check required						
COMMS.FAILURE CHECK	24/07/2018	08:15	24/07/2018	08:30	194,280	Dorchester	DC018728
MDT Failure/Issue	Reboot system						
Breakdown	29/07/2018	15:42	30/07/2018	10:27	195,134	Dorchester	DC018757
Breakdown	5502.unable to open back and side doors						
Unplanned Repair	01/08/2018	08:30	01/08/2018	14:43	195,270	Dorchester	DC018778
56 Comms Equipment	MDT not working						
BREAKDOWN	06/08/2018	20:12	08/08/2018	06:23	196,370	Dorchester	DC018802
56 Comms Equipment	MDT Failure/Issue MDT not communicating with sat nav						
86 Doors	Cant get into rear of vehicle						
86 Doors Rear	Doors Side door not unlocking. OK inside						
86 Sliding Door	Doors side door won't open from the outside						
Breakdown	11/08/2018	21:06	13/08/2018	15:15	197,017	Dorchester	DC018829
13 Brake Pads	front pads worn						
13 Discs	front discs worn						
17 Tyres	o/s/f tyre low						
18 Wheels	front flanges u/s studs stretched						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
Breakdown	EML on in limp mode						
Travel Time							
18 Wheels Check Torques							
Safety Inspection							

Vehicle Deep Clean	14/08/2018	10:30	15/08/2018	10:00	197,041	Dorchester	DC018847
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
COMMS.FAILURE CHECK	29/08/2018	14:00	31/08/2018	16:00	199,222	Dorchester	DC018924
MDT Failure/Issue							
Unplanned Repair	03/09/2018	12:05	03/09/2018	12:25	199,602	Dorchester	DC018953
02 Mirrors	Mirrors offside blind spot lens broken.replace						
Breakdown	03/09/2018	19:03	03/09/2018	20:10	199,697	Dorchester	DC018955
86 Sliding Door	Rear door handle jammed.Reset mechanism						
Breakdown	Rear Door ~Handle Broke						
Travel Time							
Unplanned Repair	04/09/2018	16:10	04/09/2018	17:25	199,801	Dorchester	DC018964
17 Tyres Replace	Puncture o/s/r/o,replace and carry out retorque						
Travel Time							
Unplanned Repair	05/09/2018	07:30	05/09/2018	07:48	199,963	Dorchester	DC018966
89 Seatbelts	Attenedent seat belt mount loose.Tighten up						
SAFETY INSPECTION	25/09/2018	07:00	25/09/2018	14:30	202,501	Dorchester	DC019061
18 Wheels Check Torques							
34 Lights	n/s drl not working						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
55 Tail Lift	lamp damaged						
Safety Inspection							

Travel Time							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	25/09/2018	15:07	26/09/2018	13:30	202,540	Dorchester	DC019069
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	08/10/2018	15:57	08/10/2018	16:00	204,113	Dorchester	DC019137
Breakdown Travel Time	LIMP MODE.NO ELMS						
Unplanned Repair	17/10/2018	08:45	17/10/2018	09:32	205,524	Dorchester	DC019169
86 Doors Rear	Doors REAR SWINGE DOOR HINGE BOLT BROKE						
Unplanned Repair	18/10/2018	08:00	18/10/2018	08:34	205,615	Dorchester	DC019172
45 Engine 1	Ad blue light on.						
Unplanned Repair	26/10/2018	11:00	26/10/2018	12:00	206,806	Dorchester	DC019224
45 Engine 1	EML on in limp mode						
Breakdown	27/10/2018	10:59	01/11/2018	11:11	206,904	Dorchester	DC019226
41 Turbo Breakdown Travel Time	Fumes from turbo reported.See notes Engine in limp mode						
SAFETY INSPECTION	01/11/2018	11:11	05/11/2018	12:39	206,969	Dorchester	DC019256
13 Brake Pads 13 Discs 15 Steering 1	rear worn rear worn slight play in steer rack						
						Monitoring	

16 Suspension 1	play in struts and arms	Monitoring
18 Wheels Check Torques		
34 Lights	o/s drl inop	
45 Engine Ad Blue	top up	
45 Engine Oil Top Up	top up	
Safety Inspection		
Travel Time		
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab	
Gearbox Oil & Filter Change		
Sealing of stretcher clamp	Sealing of stretcher clamp	

Vehicle Deep Clean	05/11/2018	09:30	06/11/2018	08:47	206,981	Dorchester	DC019268
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	07/11/2018	23:45	29/11/2018	15:15	207,164	Dorchester	DC019286
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

41 Turbo	Turbo impellor exploded
45 Engine 1	LOP. Reset by phone.
Breakdown	In limp mode
Travel Time	

BREAKDOWN	08/12/2018	14:30	08/12/2018	16:30	208,479	Dorchester	DC019445
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

52 Electrical Aux	mobi med not charging
86 Sliding Door	Doors side door wont open from outside
Travel Time	

Unplanned Repair	13/12/2018	10:45	13/12/2018	11:19	209,057	Dorchester	DC019473
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Ad Blue
45 Engine Oil Top Up

Unplanned Repair	17/12/2018	15:15	17/12/2018	16:00	209,869	Dorchester	DC019496
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Sliding Door	Handle jammed						
SAFETY INSPECTION	18/12/2018	08:17	18/12/2018	14:56	209,926	Dorchester	DC019497
02 Windows/Glass	driver switch u/s					Monitoring Monitoring	
13 Brake Pads	front low						
15 Steering 1	slight play in steer rack						
16 Suspension 1	play in struts and arms						
18 Wheels Check Torques							
55 Tail Lift	slider damaged, guard rail damaged						
Safety Inspection							
Travel Time	take to dorch and return						
MOT Pre Test							
93 - D Service	Service done see notes						
Service D							
Vehicle Deep Clean	19/12/2018	08:00	19/12/2018	12:00	209,941	Dorchester	DC019509
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/12/2018	08:00	21/12/2018	08:30	210,195	Dorchester	DC019529
44 Fuel System 1	Engine ? Diesel leak.Trace to leak off pipe.Refit,clean and check						
Unplanned Repair	24/12/2018	08:13	24/12/2018	08:15	210,668	Dorchester	DC019538
02 Mirrors	n/s mirror glass broken						
Breakdown	18/01/2019	11:42	18/01/2019	12:07	215,020	Dorchester	DC019645
Breakdown	rear doors not opening from inside.Adjusted						
BREAKDOWN	22/01/2019	15:30	23/01/2019	10:58	215,776	Dorchester	DC019665
45 Engine 1	EML on,LOP						

Breakdown	23/01/2019	02:32	23/01/2019	10:57	215,823	Dorchester	DC019666
Breakdown	multiple alarms prior to emerg start						
Breakdown	25/01/2019	16:29	26/01/2019	16:00	216,010	Dorchester	DC019687
71 Body Exterior 1 Breakdown	Damage to O/S Mirror . Replace glass. Wing mirror O/S Crack in glass cracked						
SAFETY INSPECTION	30/01/2019	08:28	31/01/2019	13:56	217,116	Dorchester	DC019707
02 Windscreen Wipers	Sreen washers inop,replace splitter						
15 Steering 1	slight play in steer rack						
16 Suspension 1	play in struts and arms						
17 Tyres Replace	All tyres on Trust limit						
18 Wheels Check Torques							
45 Engine Ad Blue	Top up						
54 Horns	Emg Warning Devices horn push siren on/off u/s.Check operation,ok,nff						
86 Door Lock	Locker and sliding door central locking inop.Repair						
Safety Inspection							
Travel Time							
MOT							
Vehicle Deep Clean	01/02/2019	08:00	01/02/2019	12:08	217,129	Dorchester	DC019724
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	04/02/2019	06:15	04/02/2019	09:23	217,694	Dorchester	DC019736
03 Instruments & Sensors 1	ABS/ESP light on						
Unplanned Repair	05/02/2019	17:40	05/02/2019	18:40	217,897	Dorchester	DC019750
13 Brakes 1	ABS fault						
Travel Time							
BREAKDOWN	09/02/2019	12:30	11/02/2019	06:11	218,495	Dorchester	DC019772

86 Sliding Door Travel Time	handle broken						
Unplanned Repair	13/02/2019	07:45	13/02/2019	08:00	218,952	Dorchester	DC019787
52 Electrical Aux	Unable to plug in shoreline.Check fault,straighten bent pins						
Unplanned Repair	21/02/2019	11:30	21/02/2019	11:45	220,240	Dorchester	DC019831
45 Engine Oil Top Up							
Unplanned Repair	06/03/2019	07:45	06/03/2019	08:00	222,168	Dorchester	DC019891
02 Windscreen Wipers	Electrical Auxs Windscreen wash/wipe u/s. No spray.Clean washers jets						
Breakdown	09/03/2019	08:02	10/03/2019	17:45	222,478	Dorchester	DC019906
Breakdown	O/S/F indicator broken						
Unplanned Repair	10/03/2019	17:30	10/03/2019	18:30	222,735	Dorchester	DC019912
03 Instruments & Sensors 1 Travel Time	ESP light reported on						
SAFETY INSPECTION	13/03/2019	08:10	14/03/2019	13:30	223,103	Dorchester	DC019930
13 Brake Pads	rear low						
16 Suspension 1	Spring eye bush and slipper pad worn						
18 Wheels Check Torques							
34 Lighting System	scene light n/w						
34 Lights	top marker and running light out						
34 Lights Bulb Replacement	Running light inop						
44 Fuel System 1	fuel angel missing						
45 Engine Ad Blue	Top up						
45 Engine Oil Top Up	Top up						

Monitoring

85 Body Interior 1	fire ext out of date, 1x fitted 1x to do in cab					Monitoring	
85 Body Interior 2							
86 Door handle	Sliding door handle jammed					Monitoring	
86 Sliding Door							
89 Seats	Driver seat swab and cover					Monitoring	
Safety Inspection							
Annual Heater Service	Annual Heater Service						
Handbrake Cable Replacement							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Annual Air Con Service							
Annual Air Con Service	Annual Air Condition Service						
Vehicle Deep Clean	14/03/2019	14:03	15/03/2019	12:11	223,116	Dorchester	DC019938
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/03/2019	09:15	20/03/2019	10:35	223,996	Dorchester	DC019962
56 Comms Equipment	SAT nav powering down						
Unplanned Repair	25/03/2019	11:40	25/03/2019	12:09	224,169	Dorchester	DC019987
56 Comms Equipment	MDT not working						
Unplanned Repair	03/04/2019	10:45	03/04/2019	11:16	225,858	Dorchester	DC020025
56 Comms Equipment	Sat nav powering down,carry out checks.Modify casing						
Unplanned Repair	03/04/2019	14:45	03/04/2019	15:15	225,916	Dorchester	DC020030
13 Handbrake	Adjust handbrake						
Unplanned Repair	15/04/2019	07:03	15/04/2019	07:45	227,469	Dorchester	DC020079
34 Lighting System	o/s scene light inop						
52 Electrical Aux							
52 Electrical Aux	Sat nav shutting down						

Breakdown	21/04/2019	15:58	26/04/2019	12:15	228,941	Dorchester	DC020107
13 Brake Pads	front low						
13 Calipers	rear siezed up						
13 Discs	front worn						
15 Steering 1	top up						
17 Tyres	o/s/r outter low						
18 Wheels	nuts on rear siezed						
34 Lighting System	scene light n/w						
45 Engine 1	leak on egr hose						
45 Engine Ad Blue	top up						
52 Electrical Aux	Electrical Auxs Power to the SatNav?						
56 Comms Equipment	Electrical Auxs SAT NAV NOT CHARGING POWERS DOWN						
85 Body Interior 1	fire ext out of date, 1x fitted 1x to do in cab						
86 Doors Rear	handle jammed						
86 Sliding Door	doesnt open						
89 Seats	Driver seat swab and cover						
Breakdown	Turbo hose come loose						
Travel Time							
Axle Oil Change	Axle Oil Change						
18 Wheels Check Torques							
Safety Inspection							
Vehicle Deep Clean	26/04/2019	08:00	26/04/2019	13:00	228,941	Dorchester	DC020136
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	27/04/2019	11:40	27/04/2019	13:35	228,941	Dorchester	DC020139
Breakdown	No Power Battery Check Req						
Travel Time	Travel to and from weymouth/Dorchester Hospital.Waiting time.						
COMMS.FAILURE CHECK	11/05/2019	12:00	11/05/2019	14:45	230,950	Dorchester	DC020196
MDT Failure/Issue	MDT reported not powering up.Reboot system						
Travel Time							

Tail Lift 12M Service & Weight	13/05/2019	08:18	13/05/2019	12:00	231,122	Dorchester	DC020203
Tail Lift 12M Service & Weight UB Fire Supp 12mts Service	Tail Lift 12M Service & Weight Service of fire supression system						
Unplanned Repair	16/05/2019	15:15	16/05/2019	15:30	231,716	Dorchester	DC020238
02 Windscreen Wipers	Washers inop.Unblock jets and clear pipe work						
Unplanned Repair	20/05/2019	11:30	20/05/2019	12:19	232,352	Dorchester	DC020246
45 Engine 1	LOP reported,check with TEXA.Air mass poor flow.Clear code and road test						
SAFETY INSPECTION	04/06/2019	08:00	04/06/2019	14:54	234,848	Dorchester	DC020314
02 Windscreen Wipers	blades u/s						
17 Tyres	n/s front tyre low						
18 Wheels Check Torques							
34 Lights	rear lights damaged						
34 Lights Bulb Replacement	n/s side light bulb						
43 Exhaust System 1	tailpipe damage						
45 Engine Ad Blue	top up						
Safety Inspection							
Engine Change Oil & Filter							
Vehicle Deep Clean	05/06/2019	10:31	05/06/2019	14:54	234,859	Dorchester	DC020326
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	10/06/2019	01:56	10/06/2019	10:30	235,000	Dorchester	DC020339
45 Engine 1 Breakdown	Carry out checks,replace boost pressure sensor.Carry out road test Loss Of Power						

BREAKDOWN	29/06/2019	09:05	01/07/2019	06:38	235,803	Dorchester	DC020430
34 Lights	n/s drl not working						
42 Coolant System	Engine check coolant message						
BREAKDOWN	04/07/2019	15:45	04/07/2019	17:00	237,563	Dorchester	DC020466
31 Battery Chassis	power fail	replace chassis batt					
42 Coolant System	top up						
Unplanned Repair	05/07/2019	13:00	05/07/2019	14:08	237,850	Dorchester	DC020471
42 Coolant System	bottle leaking						
Unplanned Repair	09/07/2019	14:45	15/07/2019	15:30	241,279	Dorchester	DC020488
52 Electrical Aux	Ortivus unit not charging.Check fault,no power output from unit.Parts required						
Unplanned Repair	10/07/2019	11:46	10/07/2019	12:29	240,279	Dorchester	DC020491
02 Windscreen Wipers	blades u/s washers n/w						
SAFETY INSPECTION	16/07/2019	09:09	18/07/2019	11:24	241,420	Dorchester	DC020512
01 Air Conditioning 1	belt u/s						
15 Steering 1	slight Play in n/s inner rack joint					Monitoring	
16 Suspension 1	Front struts and arms have play					Monitoring	
17 Tyres	All rear low and o/s/f low						
18 Wheels Check Torques							
34 Lighting System	Marker light inop,no. plate lamp inop						
42 Radiator	Radiator leaking						
45 Engine Oil Top Up	top up						
55 Tail Lift	guides loose						
56 Comms Equipment	MDT not working						
85 Body Interior 1	Cab light inop,replace bulb						
89 Seats	Arm rest loose						
Safety Inspection							

Vehicle Deep Clean	17/07/2019	09:00	17/07/2019	12:00	241,416	Dorchester	DC020522
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	22/07/2019	11:00	22/07/2019	11:23	242,030	Dorchester	DC020547
02 Windscreen Wipers	Washers blocked						
Breakdown	24/08/2019	22:38	29/08/2019	07:48	247,229	Dorchester	DC020722
01 Heating 1	renew eberspacher exhaust						
02 Windscreen Wipers	top up washer bottle						
13 Brake Pads	replace front and rear pads						
27 Transmission Automatic	slight lift in rear output bearing						
34 Lights	NS rear door LED light dim						
44 Add Ad Blue	top up						
45 Engine Oil Top Up	top up						
52 Electrical Aux	no power to saloon 12v sockets						
71 Body Exterior Roof	Sky light smashed						
Breakdown	sunlight smashed in rear						
DEFCT01	Body Exterior sun roof struck broken						
Road Test	road test						
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
18 Wheels Check Torques	torque up						
Safety Inspection							
Vehicle Deep Clean	28/08/2019	13:30	29/08/2019	14:07	247,243	Dorchester	DC020745
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	08/10/2019	08:23	09/10/2019	14:23	253,764	Dorchester	DC020973
02 Windows/Glass	passenger switch broken						
02 Windscreen Wipers	washers not working bottle top missing						
15 Steering 1	slight Play in n/s inner rack joint						
16 Suspension 1	Front struts and arms have play						
17 Tyres							
17 Tyres Tracking	track to be adjusted by ats						
18 Wheels	2x rim cracked						
18 Wheels Check Torques							
27 Transmission Automatic	slight lift in rear output bearing						
34 Emergency Lights	N/S/R top lamp broken						
34 Lights	o/s side light out						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
56 Comms Equipment	replace epcr batts						
85 Body Interior 1	micro phone adrift						
86 Sliding Door	bearings rough						
Safety Inspection							
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Vehicle Deep Clean	10/10/2019	08:30	10/10/2019	13:45	253,775	Dorchester	DC020999
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	16/10/2019	13:35	16/10/2019	13:51	255,018	Dorchester	DC021044
86 Doors Rear	o/s rear door snapped,replace						
Breakdown	20/10/2019	21:28	21/10/2019	09:30	255,573	Dorchester	DC021061
43 Exhaust System 1	clean debris off exhaust system causing burning smell						
Breakdown	Burning smell coming through vents						
Unplanned Repair	25/10/2019	18:00	25/10/2019	21:00	256,159	St Leonards	SL028281
02 Windows/Glass	Replace o/s window switch						
34 Lights Bulb Replacement	Replace o/s headlight bulb						

Fire suppression Service Travel Time	Fire suppression audio deployed. Fit by pass plug. New switch required. Travel to Bere Regis and Ferndown.					Monitoring	
Breakdown	09/11/2019	10:48	11/11/2019	09:30	257,338	Dorchester	DC021174
Breakdown	fire retardant system low warning					Awaiting Parts	
Unplanned Repair	18/11/2019	07:30	18/11/2019	09:33	258,581	Dorchester	DC021235
71 Body Exterior 1	Front number plate missing.Replace						
SAFETY INSPECTION	19/11/2019	09:57	20/11/2019	11:30	258,645	Dorchester	DC021244
01 Heating 1	Saloon heater inop						
17 Tyres Replace	Front tyres on limit						
18 Wheels Check Torques							
45 Engine Ad Blue							
56 Comms Equipment	Microphone missing from saloon wall						
86 Door Lock	Side locker barrel turning in housing						
Check Winter Pack							
Safety Inspection							
Engine Change Oil & Filter							
Vehicle Deep Clean	21/11/2019	08:10	21/11/2019	13:30	258,659	Dorchester	DC021261
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	25/11/2019	15:00	25/11/2019	15:15	259,337	Dorchester	DC021279
31 Battery Comms	Comms battery failed,replace						
BREAKDOWN	02/12/2019	07:36	02/12/2019	12:32	260,020	Dorchester	DC021315
34 Lights Bulb Replacement	replaced by bronze						

Unplanned Repair	03/12/2019	09:30	03/12/2019	10:55	260,084	Dorchester	DC021326
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	Step inop
------------------------	-----------

Unplanned Repair	10/12/2019	11:07	10/12/2019	11:09	261,074	Dorchester	DC021364
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

44 Add Ad Blue

Breakdown	12/12/2019	19:40	12/12/2019	21:00	261,160	Dorchester	DC021387
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown Travel Time	limp mode,sluggish gears&poor starting travel to weymouth and back
--------------------------	---

Unplanned Repair	27/12/2019	10:45	27/12/2019	11:05	264,181	Dorchester	DC021490
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	n/s day running light inop,replace bulb
----------------------------	---

SAFETY INSPECTION	31/12/2019	07:56	02/01/2020	12:56	264,791	Dorchester	DC021510
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	both door mirror frames broken
13 Brake Pads	replace rear pads
16 Suspension 1	replace 2x leaf spring slipper pads
17 Tyres Replace	replace NSR tyres
18 Wheels Check Torques	
24 Driveshaft 1	replace front prop centre bearing
34 Emergency Lights	OSR upper blue light at 75%
34 Lights	NSF side marker not working
44 Add Ad Blue	top up
45 Engine Oil Top Up	top up
55 Tail Lift	free off hand rails
71 Body Exterior 1	secure rear mudflap
85 Body Interior 1	saloon fire extinguisher OOD
85 Body Interior 2	stretcher guide bump stop damaged
87a - Medical Equipment Repair	manger not charging
Safety Inspection	
Travel Time	take to dorchester
Tail Lift Inspection	

Monitoring

Awaiting Parts

MOT

Vehicle Deep Clean	02/01/2020	08:15	03/01/2020	12:32	264,811	Dorchester	DC021528
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	14/01/2020	07:41	15/01/2020	15:30	266,063	Dorchester	DC021589
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	Tensioner u/s	
18 Wheels Check Torques		
34 Emergency Lights	OSR upper blue light at 75%	Monitoring
34 Lights	indicators white side light out	
45 Engine Ad Blue	top up	
45 Engine Oil Top Up	top up	
55 Tail Lift	tilt ram u/s	
85 Body Interior 1	microphone broken off	
85 Body Interior 2	stretcher guide bump stop damaged	Monitoring
86 Doors	catch covers broken	
86 Sliding Door	top magnet bent	
Fire suppression Service	Fire suppression audio deployed. Fit by pass plug. New switch required.	Monitoring
Safety Inspection		

Vehicle Deep Clean	15/01/2020	08:30	15/01/2020	11:30	266,070	Dorchester	DC021602
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	23/01/2020	11:00	23/01/2020	12:00	266,709	Dorchester	DC021666
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1	Saloon heater inop
--------------	--------------------

Unplanned Repair	29/01/2020	06:00	29/01/2020	07:50	267,804	Dorchester	DC021692
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	tensioner u/s	replaced
71 Body External Steps	Med Equip & Devices side step not deploying	

Unplanned Repair	05/02/2020	07:30	05/02/2020	07:45	269,069	Dorchester	DC021738
02 Mirrors	Body Exterior O/S wing mirror damaged.Replace o/s wide angle mirror						
02 Pipeline Annual Inspection	05/02/2020	12:00	05/02/2020	13:00	268,976	MDT Weymouth	DW000158
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - no faults						
Breakdown	19/02/2020	18:34	21/02/2020	09:44	270,525	Dorchester	DC021835
13 Brakes 1 Breakdown	Carry out checks,o/s/r ABS sensor fault,wiring fault ABS warning light on						
SAFETY INSPECTION	25/02/2020	06:45	26/02/2020	13:02	271,070	Dorchester	DC021868
13 Brake Pads	replace front pads						
13 Brakes 1	replace NSF caliper						
13 Brakes 2	check rear calipers for seized sliders						
18 Wheels Check Torques							
34 Emergency Lights	OSR upper blue light at 75%						
44 Add Ad Blue	top up						
71 Body Exterior 1	secure mudflap						
85 Body Interior 2	stretcher guide bump stop damaged						
86 Sliding Door	adjust locking open magnet						
Fire suppression Service	Fire suppression audio deployed. Fit by pass plug. New switch required.						
Safety Inspection							
Travel Time	deliver to dorchester						
Brakes Replace Brake Fluid							
Tail Lift Inspection							
Vehicle Deep Clean	26/02/2020	13:05	27/02/2020	12:29	271,084	Dorchester	DC021889
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	04/03/2020	11:45	04/03/2020	13:42	272,012	Dorchester	DC021936
01 Heating 1	night heater noisy						

BREAKDOWN	16/03/2020	06:28	16/03/2020	09:42	273,650	Dorchester	DC021991
01 Heating 1	nighht heater inop						
01 Heating 2	cab blower not working						
34 Lights	Drls not working						
56 Comms Equipment	Electrical Auxs handportable 2211 fails to connect to netwrok						
unplanned repair	19/03/2020	07:15	19/03/2020	07:30	274,159	Dorchester	DC022015
45 Engine Oil Top Up	top up						
BREAKDOWN	26/03/2020	14:00	02/04/2020	09:04	275,261	Dorchester	DC022054
01 Heating 1	Cab blower not working, night heater inop						
45 Engine 1	Injectors blowing,, @ PENTAGONS POOLE						
Unplanned Repair	02/04/2020	15:15	02/04/2020	16:00	275,300	Dorchester	DC022091
17 Tyres Replace	Replace o/s/r tyres,inner punctured						
SAFETY INSPECTION	07/04/2020	08:00	09/04/2020	11:14	275,748	Dorchester	DC022116
18 Wheels Check Torques							
31 Charging System Battery	Crew unable plug in shorline.Check fault,straighthen pins						
45 Engine Ad Blue							
85 Body Interior 1	Cab extinguisher OOD,replace						
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test.New system fitted						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
UB Fire Supp 12mts Service	Service of fire supression system						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						

Vehicle Deep Clean	08/04/2020	12:00	09/04/2020	16:00	275,762	Dorchester	DC022131
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	14/04/2020	15:00	14/04/2020	16:00	275,762	MDT Weymouth	DW000188
87 Oxygen System	02 probes/lines leaking in 02 cupboard. Repaired - 90' probes fitted						
Unplanned Repair	10/05/2020	07:30	11/05/2020	13:53	278,799	Dorchester	DC022346
71 Body Exterior Acc Repair	Deer Strike						
unplanned repair	13/05/2020	08:00	13/05/2020	08:19	278,976	Dorchester	DC022365
54 Sirens	fit siren surround						
SAFETY INSPECTION	19/05/2020	07:25	20/05/2020	07:30	279,591	Dorchester	DC022400
02 Windscreen Wipers	washers blocked, blades u/s						
11 Axle Rear	Half shaft leaking						
13 Brakes 1	Front low						
16 Suspension 1	ARB links worn						
17 Tyres	fronts low						
18 Wheels Check Torques							
34 Lighting System	cab light o/s 1x bulb out						
34 Lights	marker light n/s/r not working						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
71 Body Exterior 1	Rear flap loose						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Tail Lift Inspection							
Vehicle Deep Clean	20/05/2020	08:30	20/05/2020	15:30	279,601	Dorchester	DC022412
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	27/05/2020	18:33	28/05/2020	12:10	280,439	Dorchester	DC022477
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	fumes in cab
-----------	--------------

SAFETY INSPECTION	29/06/2020	06:00	08/07/2020	14:33	283,788	Dorchester	DC022689
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen	Small in chip in windscreen	Monitoring
02 Windscreen Wipers	Blades split	
03 Instruments & Sensors 1	Service light on	
16 Suspension 1	Slight play in o/s Bottom arm	Monitoring
17 Tyres	N/SR tyres low	
18 Wheels Check Torques		
34 Lights	Headlight n/s not working	
45 Engine 1	Fumes in cab....Pentagon Again,,last time for injectors 02.04.2020	Monitoring
45 Engine Ad Blue	Top up	
Safety Inspection		
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change	
Engine Change Oil & Filter		

Vehicle Deep Clean	09/07/2020	08:30	09/07/2020	13:15	283,871	Dorchester	DC022776
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	10/07/2020	15:15	10/07/2020	16:00	284,011	Dorchester	DC022788
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Sliding Door	Outer door handle ripped off,replace and adjust
-----------------	---

SAFETY INSPECTION	11/08/2020	10:09	12/08/2020	10:30	288,303	Dorchester	DC023011
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen	Small in chip in windscreen
02 Windscreen Wipers	OS washers blocked
16 Suspension 1	Slight play in o/s Bottom arm
18 Wheels Check Torques	
44 Add Ad Blue	top up

45 Engine 1	Fumes in cab....Pentagon Again,,last time for injectors 02.04.2020						
45 Engine Oil Top Up	top up						
86 Sliding Door	door magnet bracket bent						
Safety Inspection							
Travel Time							
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Tail Lift Inspection							
Vehicle Deep Clean	12/08/2020	10:45	12/08/2020	15:00	288,310	Dorchester	DC023026
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	05/09/2020	07:00	05/09/2020	07:50	292,101	Dorchester	DC023192
34 Lights Bulb Replacement	Body Exterior nearside running side light bulb.Replace bulb						
BREAKDOWN	07/09/2020	07:36	07/09/2020	10:50	292,315	Dorchester	DC023198
41 Turbo	Engine screaming noise and loss of power after big bang						
45 Engine 1	Engine loss of power from engine						
Breakdown	07/09/2020	15:47	07/09/2020	17:00	292,326	Dorchester	DC023203
Breakdown	Front off side tyre punctured						
Unplanned Repair	11/09/2020	13:30	11/09/2020	15:30	292,845	Dorchester	DC023246
18 Wheels	Rim Cracked N/S/F						
Breakdown	17/09/2020	21:31	18/09/2020	09:52	293,762	Dorchester	DC023302
45 Engine Ad Blue	top up						
Breakdown	Odd noises from F/N wheel on hard braking						

Breakdown	20/09/2020	15:32	22/09/2020	14:20	294,097	Dorchester	DC023316
13 Brake Pads	front and rear low						
13 Brakes 1	Rear Discs Worn						
13 Handbrake	Handbrake shoes u/s						
34 Emergency Light System	OSR blue LEDs @75%					Monitoring	
34 Emergency Lights	OSR blue lens damaged						
43 Exhaust System 1	Carry out DPF clean,carry out road test						
44 Add Ad Blue	top up						
45 Engine 1	Repace EGR valve and reset ECU						
45 Engine 2	oil leak from NS side of engine					Monitoring	
45 Engine Oil Top Up	top up						
71 Body Exterior 1	both rear light cluster pods damaged					Awaiting Parts	
71 Body Exterior 2	both rear bottom corner caps damaged						
86 Sliding Door	straighten door magnet and secure top lock cover						
89 Seats	NSR attendant seatbase has 2 small holes in cover					Awaiting Parts	
Breakdown	limp mode; VOR						
18 Wheels Check Torques							
Safety Inspection							
Vehicle Deep Clean	23/09/2020	08:12	23/09/2020	11:50	294,098	Dorchester	DC023332
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/09/2020	13:00	23/09/2020	13:27	294,097	Dorchester	DC023343
34 Emergency Light System	OSR blue LEDs @75%						
45 Engine 2	oil leak from NS side of engine						
71 Body Exterior 1	both rear light cluster pods damaged					Awaiting Parts	
89 Seats	NSR attendant seatbase has 2 small holes in cover						
Breakdown	09/10/2020	16:32	14/10/2020	14:29	296,084	Dorchester	DC023462
001 Recover Vehicle	Vehicle Recovery						
42 Coolant System	water leak egr pipe						
Breakdown	unable to turn key in ignition						
Defect Repair	15/10/2020	07:00	15/10/2020	11:50	296,214	Dorchester	DC023485

34 Lights Bulb Replacement Electrical Auxs Nr Side headlight u/s
 56 Comms Equipment cab radio will not connect
 56 Comms Fitment Electrical Auxs Cab radio seeking signal. Will not connect.

Unplanned Repair **15/10/2020** **14:30** **15/10/2020** **14:57** **296,214** **Dorchester** **DC023493**

17 Tyres Replace replace NSR inner
 44 Add Ad Blue top up ad blue

Unplanned Repair **26/10/2020** **12:00** **26/10/2020** **12:35** **297,658** **Dorchester** **DC023562**

56 Comms Equipment sat nav not charging

Unplanned Repair **27/10/2020** **04:20** **27/10/2020** **07:20** **297,798** **Dorchester** **DC023564**

34 Lights Bulb Replacement Electrical Auxs N/S/F dipped headlight defective

Unplanned Repair **27/10/2020** **20:15** **28/10/2020** **09:34** **297,877** **Dorchester** **DC023576**

34 Emergency Lights n/s/f upper blue led smashed
 34 Lights n/s headlamp inop

Breakdown **30/10/2020** **17:42** **03/11/2020** **07:05** **298,258** **Dorchester** **DC023595**

02 Windscreen	2x chips in screen, both in zone b	Monitoring
02 Windscreen Wipers	washers blocked, blades smeary	
03 Instruments & Sensors 1	EML on, service light on	
13 Brakes 1	pedal rubber split	
16 Suspension 1	rear slip pads 2x split	
17 Tyres	o/s/r low	
34 Lights	o/s side light bulb	
45 Engine Ad Blue	top up	
56 Comms Equipment	Microphone in rear broken	Monitoring
71 Body Exterior 1	both rear light pods damaged	
85 Body Interior 1	body fire ext o.o.d	
85 Body Interior 2	sat nav bracket damaged	
89 Seats	attendant seat bearings have play	
Breakdown	Red Battery message	
Pollen Filter Change	Pollen Filter Change	
Air Filter Change	Air Filter Change	
18 Wheels Check Torques		

Safety Inspection
 UB Fire Supp 6mts Service
 Fuel Filter Change
 Tail Lift Inspection

UB Fire Supp 6mts Service
 Change Fuel Filter

Vehicle Deep Clean **03/11/2020** **09:00** **03/11/2020** **12:52** **298,268** **Dorchester** **DC023616**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **10/11/2020** **06:00** **10/11/2020** **06:30** **298,300** **Dorchester** **DC023666**

02 Mirrors N/S mirror glass missing

Unplanned Repair **19/11/2020** **14:30** **19/11/2020** **14:48** **300,335** **Dorchester** **DC023739**

34 Lighting System o/s repeater inop.Make good connection

Unplanned Repair **27/11/2020** **08:41** **27/11/2020** **09:28** **301,506** **Dorchester** **DC023785**

45 Engine 1 EML on.NOX sensor required Awaiting Parts

Unplanned Repair **03/12/2020** **07:00** **03/12/2020** **07:18** **302,530** **Dorchester** **DC023832**

45 Engine Oil Top Up top up

SAFETY INSPECTION **14/12/2020** **07:00** **15/12/2020** **13:26** **304,517** **Dorchester** **DC023895**

01 Heating 1 night heater, warm air pipe damaged.Carry out repair
 02 Windscreen 2x chips in screen, both in zone b
 02 Windscreen Wipers washers blocked
 03 Instruments & Sensors 2 Service light on

17 Tyres	3x Low, change rears to cross climate
18 Wheels Check Torques	
24 Driveshaft 1	Prop doughnut u/s
45 Engine 1	EML on.NOX sensor required
45 Engine Ad Blue	top up
45 Engine Oil Top Up	
56 Comms Equipment	Microphone in rear broken
71 Body Exterior 1	both rear light cluster pods damaged
71 Body Exterior 2	Wash outside for MOT
85 Body Interior 1	Foot plate cracked
Safety Inspection	
Travel Time	
MOT	

Vehicle Deep Clean	16/12/2020	08:45	16/12/2020	12:47	304,537	Dorchester	DC023917
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	17/12/2020	13:45	17/12/2020	14:21	304,734	Dorchester	DC023922
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

89 Seatbelts	Warning light on, carry out check,pretensioner fault.Clean connections.Ok
--------------	---

Breakdown	21/12/2020	20:01	22/12/2020	12:32	305,504	Dorchester	DC023954
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

89 Seatbelts	Replace o/s seat belt stalk
Breakdown	SRS system alarm

Unplanned Repair	31/12/2020	10:15	31/12/2020	10:43	306,828	Dorchester	DC024006
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Oil Top Up	top up
----------------------	--------

Breakdown	08/01/2021	20:04	09/01/2021	06:27	308,132	Dorchester	DC024068
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	N/S Mirror Missing
-----------	--------------------

Unplanned Repair	11/01/2021	06:45	14/01/2021	09:23	308,513	Dorchester	DC024076
03 Instruments & Sensors 1	ESP light on						
Unplanned Repair	20/01/2021	18:00	20/01/2021	18:15	309,708	Dorchester	DC024177
34 Lights Bulb Replacement	Headlamp bulb replaced by Bronze						
SAFETY INSPECTION	26/01/2021	06:00	26/01/2021	12:53	310,755	Dorchester	DC024210
02 Windscreen	2x chips in screen, both in zone b						
02 Windscreen Wipers	jet damaged, blades split						
03 Instruments & Sensors 1	Brake wear light on						
16 Suspension 1	rear shocks u/s						
16 Suspension 2	ARB links on rear worn						
18 Wheels Check Torques							
45 Engine 1	Radiator top cowling missing						
45 Engine Ad Blue	top up						
54 Reversing Systems	camera n/w						
55 Tail Lift	hand rails siezed.						
86 Doors	top and bottom plunger damaged						
86 Sliding Door	top magnet bent						
Safety Inspection							
Engine Change Oil & Filter							
Tail Lift Inspection							
Vehicle Deep Clean	26/01/2021	13:45	27/01/2021	09:00	310,755	Dorchester	DC024220
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	14/02/2021	12:55	15/02/2021	15:27	313,232	Dorchester	DC024358
Breakdown	Break lights inop						
Breakdown	14/02/2021	12:56	15/02/2021	15:27	313,232	Dorchester	DC024359
Breakdown	Brake lights inop						

Unplanned Repair	27/02/2021	09:30	27/02/2021	10:00	314,746	Dorchester	DC024466
34 Emergency Lights	N/S indicator n/w						
SAFETY INSPECTION	09/03/2021	07:18	10/03/2021	10:58	315,920	Dorchester	DC024524
02 Cab Ass Fire Extinguisher	Out Of Date						
13 Brake Pads	Low All Round						
17 Tyres	Front tyres low swap around						
18 Wheels	Rim U/S						
18 Wheels Check Torques							
34 Lights	marker light n/s inop						
45 Engine 1	Jactone pipe clip broken and rubbing tube						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
85 Body Interior 1	Drug locker door adrift						
Safety Inspection							
Vehicle Deep Clean	09/03/2021	09:15	09/03/2021	12:15	315,919	Dorchester	DC024526
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	11/03/2021	12:30	11/03/2021	13:59	316,010	Dorchester	DC024554
55 Tail Lift	Tail lift failed,carry out checks.Replace battery						
87a - Medical Equipment Repair	Monitoring unit not charging,power supply in comms locker inop.PCE to sort						
COMMS.FAILURE CHECK	09/04/2021	07:45	09/04/2021	08:15	320,016	Dorchester	DC024736
MDT Failure/Issue	Reboot system,replace aerial						
Unplanned Repair	10/04/2021	09:42	10/04/2021	09:46	320,242	Dorchester	DC024746
02 Cab Assembly 1	replaced NS window switch						
MDT Failure/Issue	Sat nav not talking/ turning off						

SAFETY INSPECTION	20/04/2021	07:00	22/04/2021	12:40	321,753	Dorchester	DC024803
02 Windscreen Wipers	washers blocked						Monitoring
18 Wheels Check Torques							
34 Lights	o/s/r indicator u/s						
45 Engine 1	turbo starting to pass oil						
45 Engine Ad Blue	top up						
55 Tail Lift	hand rail bent						
86 Sliding Door	top magnet bent again						
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
UB Fire Supp 12mts Service	Service of fire supression system						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Vehicle Deep Clean	20/04/2021	12:59	21/04/2021	11:27	321,753	Dorchester	DC024807
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	01/05/2021	09:48	01/05/2021	11:03	321,890	Dorchester	DC024879
34 Lights	n/s indicator inop						
Breakdown	02/05/2021	18:51	04/05/2021	08:43	322,800	Dorchester	DC024882
Breakdown	side indicator not working						
Unplanned Repair	12/05/2021	06:40	12/05/2021	06:55	324,146	Dorchester	DC024965
56 Comms Equipment	MDT and Radio inop						

Unplanned Repair	27/05/2021	07:53	27/05/2021	13:06	326,748	Dorchester	DC025116
02 Windscreen 71 Body Exterior 1 Travel Time	Cracked. National Windscreens to replace Black panel above cab damaged by National Windscreen					Awaiting Parts	
SAFETY INSPECTION	02/06/2021	07:27	02/06/2021	15:30	327,440	Dorchester	DC025149
02 Mirrors 13 Brake Pads 16 Suspension 1 18 Wheels Check Torques 45 Engine 1 45 Engine Ad Blue 52 Electrical Aux 71 Body Exterior 1 71 Body Exterior 2 71 Body External Steps Safety Inspection Annual Heater Service Annual Air Con Service	N/S mirror glass loose fronts low Front Struts and Arms Worn turbo starting to pass oil Top up CCTV Fault Black panel above cab damaged by National Windscreen N/S camera dome damaged Rear Step corroded. requires new Annual Heater Service Annual Air Condition Service					Monitoring Monitoring Monitoring	
Vehicle Deep Clean	02/06/2021	14:40	03/06/2021	12:00	327,445	Dorchester	DC025157
Vehicle Deep Clean	Vehicle Deep Clean						
COMMS.FAILURE CHECK	04/06/2021	08:43	04/06/2021	15:29	327,445	Dorchester	DC025169
MDT Failure/Issue	Unable to book on,cursor not following finger						
Breakdown	27/06/2021	17:50	29/06/2021	09:00	331,057	Dorchester	DC025336
Breakdown	SatNav battery issues.Fit new head						
ACCIDENT	05/07/2021	07:30	05/07/2021	09:45	331,057	Dorchester	DC025384
34 Lighting System	n/s/r marker smashed off.Carry out temp repair					Awaiting Parts	

71 Body Exterior 1	Light damage to n/s/r					Monitoring	
Breakdown	12/07/2021	16:15	13/07/2021	14:19	332,881	Dorchester	DC025429
Breakdown	MDT not powering on; VOR						
SAFETY INSPECTION	15/07/2021	08:55	20/07/2021	13:39	333,173	Dorchester	DC025462
01 Air Conditioning 1	Adjuster worn						
02 Windscreen Wipers	blades smeary						
13 Handbrake	Adjustment required						
18 Wheels Check Torques							
34 Emergency Lights	O/S/R Top corner blue damaged/broken						
34 Lighting System	n/s/r marker smashed off.Carry out temp repair,,BODYSHOP REQUIRED					Monitoring	
41 Turbo	turbo u/s						
43 Exhaust System 1	DPF u/s. crack at top						
45 Engine 1	turbo starting to pass oil						
45 Engine 2	Manifold cracked blowing o/s/EGR pipe cracked						
71 Body Exterior 1	Light damage to n/s/r						
71 Body External Steps	Rear Step corroded. requires new					Monitoring	
85 Body Interior 1	Window seal adrift						
85 Body Interior 2	Microphone loose hanging down						
87 Stretcher	Head stop bump damaged						
Safety Inspection							
Vehicle Deep Clean	20/07/2021	14:44	21/07/2021	12:01	333,191	Dorchester	DC025498
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	27/07/2021	14:23	27/07/2021	15:21	334,017	Dorchester	DC025554
31 Battery Aux	Reported faulty.Carry out checks,replace battery						
Breakdown	31/07/2021	07:16	31/07/2021	11:44	334,383	Dorchester	DC025582
45 Engine Ad Blue	top up						
Breakdown	o/s wing mirror detached						

Unplanned Repair	10/08/2021	07:45	10/08/2021	08:02	336,338	Dorchester	DC025646
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

52 Electrical Aux	Remove hard drive
-------------------	-------------------

SAFETY INSPECTION	23/08/2021	11:23	24/08/2021	10:00	338,554	Dorchester	DC025757
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher	saloon extinguisher OOD	
02 Mirrors	NS mirror frame loose	
02 Windscreen Wipers	blades worn and washer jets blocked	
13 Brake Pads	rears low	
15 Steering 1	slight oil leak at steering rack shaft seal	Monitoring
17 Tyres Replace	rears low	
18 Wheels Check Torques		
34 Lighting System	n/s/r marker smashed off.Carry out temp repair,,BODYSHOP REQUIRED	Monitoring
34 Lights Bulb Replacement	cab interior light blown	
44 Add Ad Blue	top up	
45 Engine 1	NS engine mount split	
52 Electrical Aux	CCTV fault light on, hard drive error	
55 Tail Lift	OS rail loose	
56 Radio	only 1 handheld radio present	
71 Body Exterior 1	plastic trim above windscreen cracked	
71 Body External Steps	Rear Step corroded. requires new	Monitoring
89 Seatbelts	saloon seatbelts all twisted	
Safety Inspection		
Tail Lift Inspection		
Engine Change Oil & Filter		

Vehicle Deep Clean	24/08/2021	12:30	25/08/2021	09:45	338,568	Dorchester	DC025772
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	05/09/2021	12:04	08/09/2021	14:45	340,292	Dorchester	DC025840
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

15 Steering 1	slight oil leak at steering rack shaft seal.....RACK U/S
17 Tyres	Fronts worn
18 Wheels Balance & Alignment	Tracking required Booked in ATS @ 13;30 08.09.2021

31 Charging System 71 Body Exterior 1 Breakdown	alternator u/s Black panel above cab split faulty AUX system; keeps powering down						
Unplanned Repair	09/09/2021	13:00	09/09/2021	13:56	340,292	Dorchester	DC025882
52 Electrical Aux	Battery/Charging Sys ePCR box not charging. See notes.						
Unplanned Repair	24/09/2021	08:28	24/09/2021	13:40	342,453	Dorchester	DC026007
56 Comms Equipment 71 Body External Steps	Electrical Auxs Ortivus obs box charging lead not working Rear Step corroded. requires new						
Breakdown	26/09/2021	21:06	27/09/2021	06:15	342,676	Dorchester	DC026014
Breakdown	offside headlight out						
SAFETY INSPECTION	06/10/2021	14:09	07/10/2021	14:23	344,399	Dorchester	DC026089
18 Wheels Check Torques 34 Lights 44 Add Ad Blue 45 Engine Oil Top Up 55 Tail Lift 86 Door Lock 86 Doors Check Winter Pack Safety Inspection Tail Lift Inspection	OS tail lift light dim NO PARTS top up top up guide rails loose rear door lock not working correctly drivers door panel hanging off overshoes missing						
Vehicle Deep Clean	07/10/2021	14:00	08/10/2021	14:22	344,413	Dorchester	DC026098
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	09/10/2021	18:42	11/10/2021	07:40	344,428	Dorchester	DC026107
Breakdown	SatNav keeps powering down						

SAFETY INSPECTION	16/11/2021	06:00	17/11/2021	13:00	347,689	Dorchester	DC026373
01 Air Conditioning 1	Belt u/s						
13 Brake Pads	fronts low						
13 Handbrake	adjust						
16 Suspension 1	slip pads 2x split						
18 Wheels Check Torques							
34 Lighting System	n/s/r marker smashed off.Carry out temp repair,,BODYSHOP REQUIRED					Monitoring	
34 Lights	rear fog u/s						
42 Radiator	Radiator leaking						
45 Engine 1	Oil leak from filter housing..						
45 Engine Ad Blue	top up						
52 Electrical Aux	CCTV fault						
85 Body Interior 1	microphone loose						
86 Sliding Door	top magnet bent again, bottom catch damaged						
89 Seats	passenger seat swab						
Safety Inspection							
Pollen Filter Change	Pollen Filter Change						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
MOT							
Vehicle Deep Clean	17/11/2021	09:00	17/11/2021	14:47	349,722	Dorchester	DC026379
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/11/2021	22:06	26/11/2021	15:30	351,037	Dorchester	DC026451
45 Engine 1	Turbo seals split, resinator bracket broken						
45 Engine 2	injectors blowing						
Breakdown	MECHANICAL FAULT/GEARBOX						
Breakdown	05/12/2021	07:10	07/12/2021	12:38	352,171	Dorchester	DC026500
45 Engine 1	Injector U/S						

45 Engine 2 Breakdown	UNABLE TO USE TEXA AGAIN...MARSH ROAD TO CODE INJECTOR ? Engine issue or Exhaust
--------------------------	---

Unplanned Repair	14/12/2021	22:30	15/12/2021	22:45	353,125	Dorchester	DC026586
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	Headlight bulb replaced by Bronze
----------------------------	-----------------------------------

Unplanned Repair	20/12/2021	08:30	20/12/2021	09:17	353,975	Dorchester	DC026644
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Sliding Door	Sliding door reported stiff,bearing collapsed
-----------------	---

SAFETY INSPECTION	29/12/2021	07:45	29/12/2021	13:00	355,106	Dorchester	DC026698
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	rears low	
15 Steering 1	reservoir hose leaking	
18 Wheels Check Torques		
34 Lighting System	n/s/r marker smashed off.Carry out temp repair,,BODYSHOP REQUIRED	Monitoring
44 Add Ad Blue	top up	
45 Engine Oil Top Up	top up	
55 Tail Lift	bridging plate guide bolt snapped and guide rails loose	
71 Body Exterior 2	OSR lower corner cap and reflector damaged	
71 Body Exterior 3	mudflap loose	
86 Door Lock	sliding door C/L not unlocking and earth snapped	
86 Sliding Door	top magnet bracket bent	
Safety Inspection		
Tail Lift Inspection		

Vehicle Deep Clean	29/12/2021	13:30	30/12/2021	10:30	355,120	Dorchester	DC026711
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	02/01/2022	22:06	03/01/2022	09:31	355,756	Dorchester	DC026736
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	AUX BATTERY FOR SAT NAV FAULT
-----------	-------------------------------

Breakdown	02/01/2022	23:31	03/01/2022	09:38	355,756	Dorchester	DC026737
86 Sliding Door Breakdown	upper catch cover missing and catch sticking SALOON COMPARTMENT SLIDING DOOR FAULTY						
Defect Repair	10/01/2022	08:36	10/01/2022	08:42	356,889	Dorchester	DC026794
15 Steering 1	noise from underneath when turning slowly						
52 Electrical Aux	sat nav internal battery low						
71 Body Exterior 1	Body Exterior ginding from rear when turning left						
86 Sliding Door	door magnet bracket bent, door difficult to open						
Unplanned Repair	26/01/2022	07:45	26/01/2022	09:03	358,299	Dorchester	DC026940
52 Electrical Aux	Electrical Auxs Charger for ePCR obs unit appears broken.See notes						
Unplanned Repair	29/01/2022	07:45	29/01/2022	08:00	358,949	Dorchester	DC026972
03 Instruments & Sensors 1	Warning buzzer reported going off.Check vehicle for fault.Shut locker door!!!!!!						
Vehicle Deep Clean	08/02/2022	09:00	08/02/2022	15:05	360,271	Dorchester	DC027036
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	09/02/2022	08:35	09/02/2022	14:55	360,279	Dorchester	DC027044
02 Cab Ass Fire Extinguisher	extinguisher OOD						
18 Wheels Check Torques							
34 Lighting System	n/s/r marker smashed off.Carry out temp repair,,BODYSHOP REQUIRED						
34 Lights	tail lift lights not working, tilt switch required, NO PARTS						
44 Add Ad Blue	top up						
45 Engine Oil Top Up	top up						
52 Electrical Aux	saloon 240V socket cover missing						
55 Tail Lift	both tail lift rails stiff and OS pistons loose						
56 Comms Power Failure	MDT not powering up						
86 Door Lock	locker door barrel snapped						
86 Doors Rear	rear door barrel seized						

89 Seats
 passenger seat lower/raise lever not working
 Safety Inspection
 Auto G/box Oil & Filter Change Auto G/box Oil & Filter Change

Breakdown **28/02/2022** **01:08** **28/02/2022** **13:29** **363,407** **Dorchester** **DC027145**

71 Body Exterior 1
 Breakdown replace OSR lower corner cap
 EML/Limp Mode.Trace to Lambda sensor.Replace,teach in and road test

Unplanned Repair **07/03/2022** **12:15** **07/03/2022** **13:11** **363,868** **Dorchester** **DC027199**

86 Sliding Door Unable to open from inside.Replace snapped cable

Unplanned Repair **11/03/2022** **09:10** **11/03/2022** **09:40** **364,385** **Dorchester** **DC027248**

52 Electrical Aux Sat nav not charging.Carry out checks, clean connections on power block.Test ,ok

Unplanned Repair **15/03/2022** **14:15** **15/03/2022** **15:01** **364,887** **Dorchester** **DC027278**

17 Tyres NSR outer flat, rim leak

Unplanned Repair **18/03/2022** **14:00** **18/03/2022** **14:27** **365,078** **Dorchester** **DC027303**

56 Comms Equipment MDT not powering up

O2 Pipeline Annual Inspection **15/03/2022** **14:30** **15/03/2022** **15:00** **364,887** **MDT Weymouth** **DW000843**

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - no faults

SAFETY INSPECTION **22/03/2022** **09:00** **23/03/2022** **13:00** **365,284** **Dorchester** **DC027320**

18 Wheels Check Torques
 Safety Inspection
 Brake Fluid Change Brake Fluid Change
 Engine Change Oil & Filter

Tail Lift Inspection	Tail Lift 12M Service & Weight
86 Doors Rear	rear door barrel seized
85 Body Interior 1	bag cupboard door frame upper panel broken off
16 Suspension 1	rear ARB lower link bushes worn
45 Engine 1	to order oil filter
86 Sliding Door	top magnet bracket bent
02 Windscreen Wipers	replace blades

Vehicle Deep Clean	23/03/2022	14:00	24/03/2022	12:43	365,298	Dorchester	DC027332
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	02/04/2022	10:05	02/04/2022	11:30	366,262	Dorchester	DC027386
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	Body Exterior L WIng M casing cracked
85 Body Interior 1	Electrical Auxs Stretcher light surround u/s
45 Engine Ad Blue	top up

Unplanned Repair	22/04/2022	07:45	22/04/2022	08:00	368,912	Dorchester	DC027542
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	Replace sidelight bulb
----------------------------	------------------------

Unplanned Repair	03/05/2022	10:00	03/05/2022	10:20	370,138	Dorchester	DC027601
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

44 Add Ad Blue	top up
----------------	--------

SAFETY INSPECTION	04/05/2022	07:24	06/05/2022	07:40	370,203	Dorchester	DC027603
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Wheel Hub Flanges Replaceme	
Replace Handbrake Cables	Replace Handbrake Cables
UB Fire Supp 12mts Service	Service of fire supression system
89 Seats	passenger seat height adjuster not working
45 Engine Oil Top Up	top up
86 Sliding Door	top plunger damaged, no parts

13 Discs	all discs and pads worn
17 Tyres Replace	replace NSF and NSR inner

Vehicle Deep Clean	10/05/2022	10:23	10/05/2022	11:15	370,216	Dorchester	DC027635
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

ACCIDENT	02/06/2022	07:00	02/06/2022	09:30	372,863	Dorchester	DC027795
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body Exterior Acc Repair	See notes
-----------------------------	-----------

Unplanned Repair	08/06/2022	14:35	08/06/2022	14:52	373,431	Dorchester	DC027842
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	o/s repeater inop,replace bulb
----------------------------	--------------------------------

SAFETY INSPECTION	13/06/2022	05:30	14/06/2022	06:41	374,401	Dorchester	DC027874
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
03 Instruments & Sensors 1	EML on LOP
86 Sliding Door	Plungers worn, stiff to open
02 Cab Assembly 1	Foot plate smashed
02 Cab Assembly 2	floor mats required and pedal rubber worn
02 Windscreen Wipers	wsashers blocked
17 Tyres	3x low
02 Cab Ass Fire Extinguisher	Saloon fire ext out of date
85 Body Interior 1	trim under attendant seat adrift
85 Body Interior 2	gas cupboard catches worn
11 Axle Rear	Hub seal leaking
Axle Oil Change	Axle Oil Change
71 Body Exterior Acc Repair	EXCESSIVE BODY DAMGE STILL.....BODYSHOP TO REPAIR
03 Instruments & Sensors 2	window switch u/s

Vehicle Deep Clean	14/06/2022	16:00	15/06/2022	16:10	374,408	Dorchester	DC027895
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	19/06/2022	20:13	20/06/2022	07:53	374,771	Dorchester	DC027919
Breakdown	defective stretcher						
Unplanned Repair	21/06/2022	09:30	21/06/2022	10:00	374,984	Dorchester	DC027938
03 Instruments & Sensors 1 52 Electrical Aux	Side door warning going off,adjust switch Sat nav powers down.Check power supply,clean contacts on unit						
Breakdown	23/06/2022	19:59	24/06/2022	11:44	374,984	Dorchester	DC027967
Breakdown 89 Seats	Drivers seat broken height lower will not work drivers seat lower/raise lever snapped						
Unplanned Repair	11/07/2022	09:45	11/07/2022	10:19	377,934	Dorchester	DC028060
42 Coolant System	coolant level warning light on						
Unplanned Repair	13/07/2022	12:15	13/07/2022	12:41	378,115	Dorchester	DC028085
86 Sliding Door	top catch loose						
Defect Repair	14/07/2022	13:27	14/07/2022	13:33	378,115	Dorchester	DC028093
71 Body Exterior 1 71 Body Exterior Acc Repair	Body Exterior rear wheel arch damage Body Exterior hit wall. Passenger rear wheel arch						
	Monitoring						
Unplanned Repair	22/07/2022	07:00	22/07/2022	07:58	379,701	Dorchester	DC028141
02 Windscreen Wipers	Washers blocked						

Unplanned Repair	25/07/2022	08:00	25/07/2022	08:25	379,702	Dorchester	DC028153
45 Engine Oil Top Up	1 litre added						
Breakdown	28/07/2022	15:59	29/07/2022	14:57	380,378	Dorchester	DC028180
Breakdown	Side door detached from vehicle						
Breakdown	05/08/2022	18:25	08/08/2022	08:13	381,044	Dorchester	DC028216
Breakdown	Will not come out off park						
Tail Lift Inspection							
18 Wheels Check Torques							
Safety Inspection							
34 Emergency Lights	NS upper small blue light not working						
44 Add Ad Blue	top up						
45 Engine Oil Top Up	top up						
71 Body Exterior Acc Repair	Body Exterior hit wall. NSR wheel arch and corner of body, Bodyshop						
02 Windscreen Wipers	worn						
17 Tyres Replace	both OSR low						
Vehicle Deep Clean	09/08/2022	08:08	09/08/2022	15:30	381,056	Dorchester	DC028240
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	12/08/2022	16:26	13/08/2022	07:25	381,548	Dorchester	DC028271
Breakdown	Ramp wont move away from rear door						
Unplanned Repair	15/08/2022	14:30	15/08/2022	15:08	382,118	Dorchester	DC028287
52 Electrical Aux	Sat nav cutting out						

Unplanned Repair	30/08/2022	13:30	30/08/2022	14:16	382,739	Dorchester	DC028353
44 Fuel System 1 52 Electrical Aux	no fuel card, found in storage area above cab light sat nav not working and talking to MDT						
BREAKDOWN	06/09/2022	11:15	06/09/2022	11:45	383,558	St Leonards	SL037455
Breakdown	Sat Nav faulty						
Breakdown	11/09/2022	19:49	12/09/2022	16:00	383,990	Dorchester	DC028385
Breakdown	Sliding Door Handle Broke						
Unplanned Repair	21/10/2022	12:00	21/10/2022	12:30	388,440	St Leonards	SL037916
89 Seatbelts	Other red restraint system light. SRS light on - Replace seat belt stalk						
Breakdown	02/11/2022	00:27	02/11/2022	06:30	389,710	Dorchester	DC028452
Breakdown	Str Battery faulty Showing Amber Light					Monitoring	
Breakdown	04/11/2022	10:12	04/11/2022	16:00	389,995	Dorchester	DC028456
Breakdown	Str Not Going Up/Down						
Breakdown	04/11/2022	15:48	04/11/2022	18:09	390,039	Dorchester	DC028458
Breakdown	Sirens Will not turn off at Genesis Sys						
SAFETY INSPECTION	07/11/2022	09:00	07/11/2022	09:01	390,613	St Leonards	SL038038
18 Wheels Check Torques Safety Inspection							

SAFETY INSPECTION	07/11/2022	09:01	10/11/2022	09:35	390,613	St Leonards	SL038039
18 Wheels Check Torques							
Safety Inspection	PCS						
86 Doors	Doors Side door Handle Broken						
86 Doors Rear	Doors REAR DOOR HANDLE BROKEN						
02 Windscreen Wipers	Other WINDSCREEN WASHER PIPE LEAKING - OIL BELOW						
86 Sliding Door	Doors SLIDING DOOR OFF RUNNERS						
Tail Lift Inspection							
Engine Change Oil & Filter							
MOT							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Pollen Filter Change	Pollen Filter Change						
Vehicle Deep Clean	10/11/2022	09:12	10/11/2022	09:13	390,615	St Leonards	SL038079
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	10/11/2022	09:13	11/11/2022	10:09	390,615	St Leonards	SL038080
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	18/12/2022	00:37	18/12/2022	15:47	395,052	St Leonards	SL038516
Breakdown	hit the tree branch - detach blue light						
71 Body Exterior Acc Repair							
Breakdown	23/12/2022	20:16	26/12/2022	13:30	395,400	St Leonards	SL038581
Breakdown	NS wing mirror					Monitoring	
Travel Time	Travel to Weymouth						
02 Mirrors	N/S mirror glass replaced by MRO						
Breakdown	28/01/2023	22:09	29/01/2023	09:00	396,046	St Leonards	SL038941
Breakdown	coolant leaking					Monitoring	

Unplanned Repair	31/01/2023	12:13	31/01/2023	12:45	396,046	St Leonards	SL038951
34 Lights	nsf wing repeater u/s. replaced whole lens and loom section. now working ok.						
Breakdown	21/02/2023	12:15	21/02/2023	14:00	396,350	St Leonards	SL039176
Breakdown 71 Body Exterior 1	insecure Rear metal panel damaged - Parts on order						Monitoring
Breakdown	24/02/2023	11:41	03/03/2023	14:05	403,763	St Leonards	SL039202
Breakdown 01 Heating 1	Coolent leak in cab Heater matrix leaking - Rygor Westbury to replace						
Unplanned Repair	09/03/2023	14:00	09/03/2023	15:30	404,030	St Leonards	SL039322
86 Sliding Door	(see notes)						
O2 Pipeline Annual Inspection	11/03/2023	13:37	11/03/2023	13:42	404,146	MDT Ferndown	TF002561
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - See notes.						
Breakdown	12/03/2023	21:30	13/03/2023	05:30	404,182	St Leonards	SL039351
Breakdown	amber lights						
Unplanned Repair	14/03/2023	06:51	15/03/2023	14:44	404,200	St Leonards	SL039369
13 Brakes 1 17 Tyres Replace 13 Brakes 2	ABS w/lights on. See notes. N/S/R/I punctured. Replaced tyre and rim. ABS light active. (see notes)						
Vehicle Deep Clean	31/03/2023	15:49	02/04/2023	15:00	404,338	St Leonards	SL039552

Vehicle Deep Clean

Vehicle Deep Clean

SAFETY INSPECTION **03/04/2023** **06:00** **03/04/2023** **06:00** **404,338** **St Leonards** **SL039572**

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION **03/04/2023** **06:00** **04/04/2023** **13:00** **404,338** **St Leonards** **SL039573**

18 Wheels Check Torques
Safety Inspection

Breakdown
71 Body Exterior 1 coolant leaking
71 Body Exterior 2 Rear metal panel damaged - Parts on order
34 Lights Body Exterior Front Number plate Cracked
13 Brakes 2 Lighting System Nearside side indicator out
Tail Lift Inspection Talma inoperative
71 Body Exterior 3 N/S/R Body end cap
16 Suspension 1 Rear leaf spring packers
86 Door Seals O/S Door seal badly split
55 Tail Lift Tail Lift Tilt switch faulty

Awaiting Parts

Breakdown **01/05/2023** **17:20** **02/05/2023** **07:28** **404,888** **St Leonards** **SL039968**

Breakdown unable to start the engine
45 Engine 1 Reported non start. starter battery u/s. replaced starter battery. Tested all ok
31 Battery Comms Comms battery 0.0 volts. (notes)

SAFETY INSPECTION **09/05/2023** **07:00** **10/05/2023** **17:55** **411,977** **St Leonards** **SL040044**

18 Wheels Check Torques
Safety Inspection
55 Tail Lift Tail Lift Tilt switch faulty
Air Filter Change Air Filter Change
Fuel Filter Change Change Fuel Filter
Tail Lift Inspection
85 Body Interior 1 Fit P clips for APV

02 Windscreen Wipers	Cab wiper blades smearing						
02 Cab Assembly 1	Genisys panel not lighting up						
02 Cab Assembly 2	Cab drivers seat belt slightly frayed						
34 Lights	O/S/F Side light not working						
34 Emergency Lights	O/S/F Grille blue LED not working						
34 Lights Bulb Replacement	O/S/F Day time running bulb not working						
86 Doors	N/S Side door outer catch covering bolts missing.						
85 Body Interior 2	Cab center consol knob & catch missing						
85 Body Interior 3	Saloon bag locker straps broken.						
Fit Scoop Mounting Brackets	Scoop bag strap clips broken.						
86 Sliding Door	N/S Side door lower catch covering missing						
Check Winter Pack	Shoe crampons missing from winter pack						
Tail Lift Annual Service	Tail lift O/S side rail fixings loose & bolts missing						
87 Stretcher Harness Replaced	Stretcher harness missing						
87 Stretcher	Stretcher mattress velcros removed from cott frame.						
Tail Lift 6 Monthly Inspection	Tail lift manual hand pump controls seized.						
44 Fuel System 1	Fuel filter pipes leaking into engine 'v'						
41 Turbo	Loud boost noise under acceleration.						
Re-Issue Inspection	Underside inspection						
43 Exhaust System 1	Exhaust tail pipe mount snapped						
17 Tyres	O/S/F Tyre tread low outer edge, N/S/R/O Wheel rim fatigue						
13 Brakes 2	O/S/R Brake caliper sliders excessively seized.						
13 Brakes 1	N/S/F ABS wiring insecure & hanging underside of wheel arch linings.						
13 Handbrake	Cab handbrake travel becomming excessive						
13 Brake Pads	Front brake pads & discs excessivbely worn & sliders seized.						
Vehicle Deep Clean	11/05/2023	11:15	12/05/2023	15:14	411,977	St Leonards	SL040093
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	19/05/2023	09:30	25/05/2023	14:41	412,813	St Leonards	SL040199
Supply Sat Nav	Sat nav power cable u/s - Using another cable pugged into USB port					Monitoring	
Unplanned Repair	12/06/2023	15:30	12/06/2023	16:00	414,149	St Leonards	SL040527
31 Battery Aux	Aux battery u/s						

Vehicle Deep Clean	19/06/2023	05:37	19/06/2023	14:08	415,670	St Leonards	SL040627
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	20/06/2023	15:01	22/06/2023	16:20	415,672	St Leonards	SL040665
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Supply Sat Nav	Sat nav power cable u/s - Using another cable pugged into USB port
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
UB Fire Supp 12mts Service	Service of fire supression system
Replace Handbrake Cables	Replace Handbrake Cables. Done.
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service
Engine Change Oil & Filter	Done.
34 Lights	O/S/F top marker light broken. Rep[laced
02 Windscreen Wipers	N/S washer jet blocked.
01 Air Conditioning 1	A/C compressor noisy
13 Brakes 1	Rear disc's & pads worn. Replaced.
13 Calipers	Rear caliper rubbers torn. Replaced x2.
13 Handbrake	Brake shoes broken up.. Replaced.
Wheel Hub Flanges Replaceme	Rears in poor condition. Replaced.
02 Cab Assembly 1	Bonnet soundproofing adrift. Resecured.

Breakdown	05/07/2023	21:05	06/07/2023	11:43	415,672	St Leonards	SL040882
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Accident dent to tail lift
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card

Vehicle Deep Clean	28/07/2023	13:30	29/07/2023	14:33	417,508	St Leonards	SL041312
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	30/07/2023	11:07	31/07/2023	05:02	417,508	St Leonards	SL041336
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
56 Comms Power Failure	Comms Power Check	Sat Nav is not tracking					
56 Comms Equipment	MDT Failure/Issue	mdt not connecting with the sat nav					
Tail Lift Inspection							
34 Lights	N/S tail lift warning light	not working					
85 Body Interior 1	Slide out cupboard catch	not returning					
85 Body Interior 2	Microphone in saloon	damaged/broken					

Vehicle Deep Clean	07/09/2023	11:32	08/09/2023	09:30	417,610	St Leonards	SL041855
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	11/09/2023	05:31	12/09/2023	06:07	417,610	St Leonards	SL041886
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
71 Body Exterior Acc Repair	Body Damage N/S..Bodyshop to repair					Monitoring	
Recall Notification	Mercedes Airbag Recall (Parts in Cab) Done.						
02 Windscreen Wipers	Washers n/w. Removed bottle, cleaned bottle & filter. Cleaned jets & adjusted.						
17 Tyres Replace	O/S/R/I&O, N/S/R/O low tread. Replaced x3.						
52 Electrical Aux	230v w/lights missing. Replaced x2.						
45 Engine 1	Various oil leaks. To Dealer.					Monitoring	
01 Air Conditioning 1	Cab A/C weak. Checked, de-gas, pressure test & checked for leaks. Re-gas.						

Vehicle Deep Clean	22/10/2023	08:00	23/10/2023	14:49	422,868	St Leonards	SL042461
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	26/10/2023	05:27	26/10/2023	16:07	422,875	St Leonards	SL042504
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
71 Body Exterior Acc Repair	Body Damage N/S..Bodyshop to repair						
MOT	Carried Out 24.10.23.	Passed					

85 Body Interior 1	Sliding door upper magnet worn. replaced
45 Engine 1	Main belt tensioner seized. replaced
16 Suspension 1	Rear roll bar bushes worn x4 and x2 spring buffers torn. replaced
13 Brakes 1	OSF Caliper slider lower seized. removed cleaned and regreased.

Vehicle Deep Clean	02/12/2023	06:00	03/12/2023	05:22	425,777	St Leonards	SL043021
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	04/12/2023	06:00	05/12/2023	08:30	425,777	St Leonards	SL043035
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
45 Engine 1	Oil leak oil cooler area. cleaned. monitor to check next inspection. Monitoring
71 Body Exterior 1	Body Damage N/S..Bodyshop to repair
13 Handbrake	Adjust shoes and cables.
34 Lights	NS side marker light damaged. replaced light.
71 Body Exterior 2	Damage to nsr light cluster and water in lamps. replaced cluster with all lights
34 Emergency Lights	osr side blue light u/s. replaced light unit.
13 Brakes 1	OSF Caliper slider seized. replaced slider kit.
Tail Lift Inspection	OS Hand rail straightened. stripped, cleaned and rebuild drop locking mechanism.
86 Sliding Door	Sliding door inner handle stiff. stripped and lubricated cables.
85 Body Interior 1	Saloon underseat locker door hinges insecure. resecured.

Breakdown	09/12/2023	12:00	10/12/2023	07:30	426,154	St Leonards	SL043124
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Knocking sound coming from osf. traced to play in door hinges. resecured hinges.
-----------	--

Unplanned Repair	27/12/2023	12:37	27/12/2023	13:36	428,691	St Leonards	SL043338
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	EML on
-------------	--------

Unplanned Repair	08/01/2024	10:30	08/01/2024	14:08	430,358	St Leonards	SL043515
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Side step inop , straighten brkt & lubed.
------------------------	---

44 Add Ad Blue 02 Windscreen Wipers	Top up ad blue and screenwash & eng oil. clean out & adjust screed washers.						
Vehicle Deep Clean	12/01/2024	13:43	13/01/2024	13:48	430,756	St Leonards	SL043576
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/01/2024	08:49	20/01/2024	16:00	430,756	St Leonards	SL043584
18 Wheels Check Torques							
Safety Inspection							
71 Body Exterior Acc Repair	Body Damage N/S and rear door issues. Bodyshop to repair						
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service. Topped up system pressure to 15bar.						
Engine Change Oil & Filter							
01 Air Conditioning 1	Air con service carried out.						
89 Seats	NS Passenger seat height adjuster U/S. - MONITOR					Monitoring	
41 Air Intake	Various oil leaks. (see notes)						
45 Engine 1	AC Belt tensioner worn. replaced tensioner.						
13 Brakes 1	Telma earth wire corroded and broken. replaced connector on telma.						
16 Suspension 1	Lower roll bar bushes worn. replaced.						
11 Axle Rear	Rear axle oil topped up.						
44 Fuel System 1	Fuel hoses on fuel filter leaking. replace filter and hoses.						
55 Tail Lift	Tail lift frames corrosion. - Monitor.					Monitoring	
45 Engine 2							
Throttle valve faulty after replacement of seals. replaced valve & taught in.							
Unplanned Repair	25/01/2024	15:30	25/01/2024	15:31	431,500	St Leonards	SL043725
34 Lights Bulb Replacement	osf drl bulb blown. replaced bulb.						
BREAKDOWN	07/02/2024	16:30	07/02/2024	17:33	431,631	St Leonards	SL043883
02 Cab Assembly 1	A/C System Cab No fans to windows/screen						

Breakdown	19/02/2024	20:25	20/02/2024	12:30	434,983	St Leonards	SL044052
Breakdown	back door N/S wont open due to a previous accident						
71 Body External Steps	Rear step damaged						
Unplanned Repair	21/02/2024	08:00	21/02/2024	10:27	434,983	St Leonards	SL044068
86 Doors Rear	Rear Door wont open						
Unplanned Repair	21/02/2024	08:00	21/02/2024	16:24	435,043	St Leonards	SL044084
86 Doors Rear	lubed locks renewed outer handle adj cables & r\test.						
Vehicle Deep Clean	29/02/2024	06:55	29/02/2024	16:06	435,752	St Leonards	SL044199
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	02/03/2024	13:00	04/03/2024	12:09	435,752	St Leonards	SL044227
18 Wheels Check Torques							
Safety Inspection							
71 Body Exterior 1	Body Exterior engraved dent across o/s rear in accident						
71 Body Exterior 2	Body Exterior N/S/R scrape on locker door						
71 Body Exterior 3	Doors back door step slight damage due to accident						
71 Body Exterior Acc Repair	Body damage and rear doors worn, Body shop to repair.						
86 Doors Rear	N/S/R door flexing						
71 Body External Steps	Side step runner guides worn						
16 Suspension 1	Front strut top mounts starting to knock						Monitoring
11 Axle Rear	Slight back lash in rear diff						Monitoring
Breakdown	06/04/2024	08:26	07/04/2024	04:41	438,999	St Leonards	SL044786
Breakdown	COOLANT LEVEL WARNING BELOW MINIMUM LEVEL						
Vehicle Deep Clean	09/04/2024	11:35	10/04/2024	09:00	440,191	St Leonards	SL044817
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	10/04/2024	15:00	12/04/2024	09:06	440,218	St Leonards	SL044846
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

45 Engine 1	Oil leak oil cooler area. cleaned. monitor to check next inspection.	Monitoring
-------------	--	------------

89 Seats	NS Passenger seat height adjuster U/S. - MONITOR	Monitoring
----------	--	------------

55 Tail Lift	Tail lift frames corrosion. - Monitor.	Monitoring
--------------	--	------------

16 Suspension 1	Front strut top mounts starting to knock	Monitoring
-----------------	--	------------

11 Axle Rear	Back lash in rear diff	Monitoring
--------------	------------------------	------------

45 Engine Oil Top Up	ENGINE ENGINE OIL WARNING	
----------------------	---------------------------	--

71 Body External Steps	Body Exterior rear step knocked off	
------------------------	-------------------------------------	--

Axle Oil Change	Axle Oil Change	
-----------------	-----------------	--

Tail Lift Inspection

17 Tyres	N/S/F and N/S/R inner below limit	
----------	-----------------------------------	--

02 Glass / Windows	O/S/F window switch incomplete	
--------------------	--------------------------------	--

71 Body Exterior 1	Both rear wheel arches damaged	Monitoring
--------------------	--------------------------------	------------

16 Suspension 2	Play in both front lower ball joints	Monitoring
-----------------	--------------------------------------	------------

34 Lights Bulb Replacement	N/S/F side light inop	
----------------------------	-----------------------	--

71 Body Exterior 2	Damage to n/s of body and side locker door	Monitoring
--------------------	--	------------

02 Pipeline Annual Inspection	10/04/2024	10:47	10/04/2024	10:49	440,218	MDT Ferndown	TF003403
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found.	
-------------------------------	--	--

Breakdown	23/04/2024	09:08	23/04/2024	10:00	441,067	St Leonards	SL045013
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	amber coolant warning - Top up	
-----------	--------------------------------	--

Vehicle Deep Clean	19/05/2024	13:34	20/05/2024	10:41	442,692	St Leonards	SL045389
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean	
--------------------	--------------------	--

SAFETY INSPECTION	22/05/2024	11:00	23/05/2024	16:00	442,718	St Leonards	SL045437
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques

Safety Inspection

45 Engine 1	Oil leak oil cooler area. cleaned. monitor to check next inspection.	Monitoring
-------------	--	------------

89 Seats	Replace drivers seat cushion and cover	
----------	--	--

55 Tail Lift	Tail lift frames corrosion. - Monitor.	Monitoring
16 Suspension 1	Front strut top mounts starting to knock	Monitoring
11 Axle Rear	Back lash in rear diff. Diff pan replaced	
71 Body Exterior 1	Both rear wheel arches damaged	
16 Suspension 2	Play in both front lower ball joints	Monitoring
71 Body Exterior 2	Damage to n/s of body and side locker door	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change	
43 Exhaust System 1	Replace saloon heater pipe clip	
13 Brake Pads	Replace front pads, n/s/f sliders and drill out sheared off sensor wire bolt	
86 Door Lock	Replace side locker barrell housing	
86 Sliding Door	Replace 2x side door runner trim covers	

Breakdown	03/06/2024	17:45	05/06/2024	16:30	443,719	St Leonards	SL045608
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	SHAKING if driving above 50 mph
16 Suspension 1	Vibration while driving
15 Steering 1	Steering fault
17 Tyres Tracking	Check and adjust

SAFETY INSPECTION	06/07/2024	06:00	07/07/2024	12:00	448,206	St Leonards	SL046156
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques		
Safety Inspection		
45 Engine 1	Oil leak oil cooler area. cleaned. monitor to check next inspection.	Monitoring
55 Tail Lift	Tail lift frames corrosion. - Monitor.	Monitoring
16 Suspension 1	Front strut top mounts starting to knock	
16 Suspension 2	Play in both front lower ball joints	
42 Coolant System	Engine Coolant leaking	
Tail Lift Inspection		
86 Doors Rear	Secure rear door stay mount	
17 Tyres Replace	Replace os/s/r/o and i and n/s/r/o due to wear below 3mm	

Unplanned Repair	13/07/2024	12:00	13/07/2024	13:19	448,654	St Leonards	SL046301
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

42 Coolant System	Top Up
45 Engine 1	Service light on, And unknown dash warning
17 Tyres	Fronts low. Replaced

BREAKDOWN	15/07/2024	07:54	17/07/2024	07:00	448,654	St Leonards	SL046328
42 Coolant System	Radiator/Cooling Sys coolant below minimun level						
42 Radiator	Replaced radiator, condensor and front panel.						
45 Engine 1	Vacumm pump leaking oil. replaced and cleaned.						
86 Sliding Door	Sliding door outer runner bearings seized. replaced x3 bearings.						
Unplanned Repair	23/07/2024	11:16	23/07/2024	11:20	449,651	St Leonards	SL046472
34 Lights Bulb Replacement	renew n\s\find bulb.						
Unplanned Repair	27/07/2024	12:29	27/07/2024	13:38	449,666	St Leonards	SL046571
85 Body Interior 1	Mangar charger inop. swapped with spare from decommisined vehicle						
Breakdown	10/08/2024	02:23	10/08/2024	07:54	449,698	St Leonards	SL046744
Breakdown	Rear door handle snapped						
Vehicle Deep Clean	14/08/2024	13:58	15/08/2024	12:04	452,150	St Leonards	SL046807
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/08/2024	06:30	20/08/2024	14:34	452,150	St Leonards	SL046862
18 Wheels Check Torques							
Safety Inspection							
55 Tail Lift	-Tail lift stow ram hose perished. -hand rail handle & magnet broken. replaced.						
13 Handbrake	Adjusted shoes and cables.						
15 Steering 1	Steering wheel worn. replaced wheel and bolt.						
02 Windscreen Wipers	o/s washer jet inop. replaced jet and hose.						
01 Air Conditioning 1	Rear condenser housing corroded. replaced whole assembly, hoses and service kit.						

Tail Lift Inspection	Tail lift frames corrosion. - Monitor.	Monitoring
34 Emergency Lights	NS forward scene light u/s . replaced light.	
16 Suspension 1	Rear lower ant roll bar drop link bushes worn. replaced x2 bushes.	
13 Brakes 1	OSF caliper sliders seized. replaced slider kit.	
02 Cab Assembly 1	Cab genysys panel buttons inop. replaced with 2nd hand part.	
19 Chassis 1	Rear spray flap bracked damaged. replaced whole assembly	
45 Engine 2	Injectors leaking at seal no 4 &5. removed, cleaned and refitted with new seal.	

Breakdown	27/08/2024	19:22	28/08/2024	13:44	453,100	St Leonards	SL047021
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	No Coolant
-----------	------------

Unplanned Repair	29/08/2024	11:56	29/08/2024	13:02	453,100	St Leonards	SL047068
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

42 Coolant System	Engine Low coolant warning on dash Amber. Replaced reservoir and cap.
-------------------	---

Breakdown	29/08/2024	21:45	06/09/2024	10:40	453,180	St Leonards	SL047077
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	COOLANT LOSS
45 Engine 1	Replace EGR cooler

Vehicle Deep Clean	23/09/2024	09:27	24/09/2024	10:18	455,086	St Leonards	SL047429
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	24/09/2024	14:00	26/09/2024	08:00	455,112	St Leonards	SL047447
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	Carried out inspection.
Tail Lift Inspection	Tail lift frames corrosion. - Monitor.
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight. Done by S.W.L.
Pollen Filter Change	Pollen Filter Change. Done.
Replace Handbrake Cables	Replace Handbrake Cables. Done.
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
UB Fire Supp 12mts Service	Service of fire supression system
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Annual Air Con Service	Annual Air Condition Service. All new.
Annual Heater Service	Annual Heater Service. Done.
02 Glass / Windows	Passenger window switch broken. Replaced.

02 Windscreen	Windscreen rubber adrift	Monitoring
13 Brakes 1	Replace front discs and pads	

BREAKDOWN	24/10/2024	13:45	24/10/2024	13:48	455,250	St Leonards	SL047945
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Doors Rear	Doors Rear door sticking. Plate realigned on floor
---------------	--

Vehicle Deep Clean	05/11/2024	10:26	06/11/2024	07:57	460,230	St Leonards	SL048104
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/11/2024	06:00	10/11/2024	08:00	460,230	St Leonards	SL048131
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques		
Safety Inspection		
Brake Fluid Change	Brake Fluid Change	
Engine Change Oil & Filter		
Tail Lift Inspection		
MOT		
Air Filter Change	Air Filter Change	
Fuel Filter Change	Change Fuel Filter	
13 Handbrake	Adjusted.	
89 Seats	NS Passenger seat height adjuster inop. removed, freed off, lubed and refitted.	
34 Lights	OSR Fog light inop. replaced light.	
34 Emergency Lights	Airport light inop. replaced light.	
85 Body Interior 1	Saloon genysys panel buttons inop. replaced panel.	
13 Brakes 1	NSF Slider stiff. free off and lubricated lower slider.	
13 Brake Pads	Rear brake pads worn. -Replaced.	
86 Sliding Door	Lower door bearing seized. managed to free off but needs replacing-Parts ordered	Monitoring

ACCIDENT	15/11/2024	06:00	18/11/2024	12:00	460,946	St Leonards	SL048241
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Rear step damaged
------------------------	-------------------

Unplanned Repair	28/11/2024	08:00	29/11/2024	09:00	461,573	St Leonards	SL048443
01 Heating 1	Saloon heater inop. Tested working ok.						
45 Engine Ad Blue	Ad blue warning light on - (See notes)						
34 Lights Bulb Replacement	Replaced OSF fog light bulb.						
Unplanned Repair	01/12/2024	13:05	02/12/2024	14:24	461,573	St Leonards	SL048479
42 Coolant System	EGR Cooler hose split. Hose replaced.						
Vehicle Deep Clean	17/12/2024	14:41	18/12/2024	14:21	463,442	St Leonards	SL048706
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/12/2024	08:42	20/12/2024	15:00	463,468	St Leonards	SL048737
Safety Inspection	Checked.						
18 Wheels Check Torques							
Road Test	A/C Belt tensioner leaking oil. replaced tensioner. Rear springs, front buffer pads split. replaced x2. Rear swivel seat base bearings worn. replaced bearings. OSF window switch broken. replaced switch.						
86 Sliding Door							
Tail Lift Inspection							
45 Engine 1							
16 Suspension 1							
89 Seats							
02 Cab Assembly 1							
BREAKDOWN	22/01/2025	12:00	22/01/2025	14:23	464,579	St Leonards	SL049202
Breakdown	Key locked in cab. open with spare key and changed setting for auto door locking VMU To Bournemouth station and return to VMU						
Travel Time							
Breakdown	25/01/2025	22:49	26/01/2025	08:23	464,890	St Leonards	SL049245
Breakdown	NEED JUMP BUTTON TO START EVERYTIME Chassis battery weak						
31 Battery Chassis							

Vehicle Deep Clean	30/01/2025	14:10	31/01/2025	15:45	466,627	St Leonards	SL049342
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	01/02/2025	11:00	02/02/2025	13:42	466,627	St Leonards	SL049373
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 45 Engine Oil Top Up 86 Sliding Door 87 Stretcher Tail Lift Inspection	Check and Install MDVS windows update Sliding door outer handle broken. replaced. Stretcher battery u/s. Replaced.						
BREAKDOWN	08/02/2025	12:14	08/02/2025	13:38	467,189	St Leonards	SL049469
13 Brakes 1 13 Brakes 2	ABS Warning light on Brake pedal switch and O/S/F ABS sensor faulty						
BREAKDOWN	13/03/2025	13:00	14/03/2025	16:16	468,660	St Leonards	SL049935
71 Body Exterior Acc Repair 18 Wheels Check Torques	O/S/R Wheel arch damage O/S/F Wheel markers removed. CHECK TORQUE ONLY						
02 Pipeline Annual Inspection	19/03/2025	12:10	19/03/2025	12:14	469,771	MDT Weymouth	DW002229
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test:- see notes						
Vehicle Deep Clean	19/03/2025	09:20	19/03/2025	16:20	469,771	St Leonards	SL049993
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/03/2025	10:00	21/03/2025	10:30	469,771	St Leonards	SL050012
Check MDVS for Update	Check and Install MDVS windows update						

Safety Inspection							
18 Wheels Check Torques							
Road Test							
71 Body Exterior 2	Body Exterior Damage to bodywork on O/S rear wheel arch						Monitoring
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
34 Lights Bulb Replacement	OSF H7 High beam bulb replaced.						
17 Tyres Replace	x1 replaced osf.						
71 Body Exterior 1	Tail lift bridge plate guides resecured to body.						

Unplanned Repair	07/04/2025	06:21	08/04/2025	06:27	471,724	St Leonards	SL050276
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

17 Tyres Replace	Replace both front tryres due to wheel wobble
Road Test	
18 Wheels Check Torques	Front wheels

BREAKDOWN	14/04/2025	09:00	14/04/2025	10:41	472,383	St Leonards	SL050375
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine Oil Top Up

Unplanned Repair	05/05/2025	09:52	05/05/2025	09:54	474,911	St Leonards	SL050761
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine Oil Top Up	Engine oil level low
----------------------	----------------------

SAFETY INSPECTION	08/05/2025	06:00	08/05/2025	13:00	475,046	St Leonards	SL050819
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
71 Body Exterior 2	Body Exterior Damage to bodywork on O/S rear wheel arch
85 Body Int Alcohol Gel Dispen	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
85 Body Interior 1	Secure saloon cupboard hinges

Vehicle Deep Clean	09/05/2025	11:00	10/05/2025	12:00	475,051	St Leonards	SL050841
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	27/06/2025	11:49	27/06/2025	11:51	479,995	St Leonards	SL051792
45 Engine Oil Top Up	Top up 2.5 ltr oil						
BREAKDOWN	28/06/2025	06:00	29/06/2025	10:25	480,023	St Leonards	SL051816
45 Engine 1	L.O.P. E.M.L.						
Breakdown	01/07/2025	15:57	02/07/2025	11:26	480,102	St Leonards	SL051855
Breakdown	Lost power						
Unplanned Repair	03/07/2025	15:00	03/07/2025	15:32	480,307	St Leonards	SL051878
45 Engine Oil Top Up	Engine oil low						
Breakdown	04/07/2025	11:30	05/07/2025	14:00	480,307	St Leonards	SL051887
Breakdown 45 Engine 1	Limp mode EML/LOP. No EML on. Carry out road test, No LOP.						
Vehicle Deep Clean	13/07/2025	12:00	15/07/2025	11:05	480,775	St Leonards	SL052031
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/07/2025	13:00	16/07/2025	13:00	480,775	St Leonards	SL052081
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test Tail Lift Inspection	Check and Install MDVS windows update						

Unplanned Repair	20/07/2025	10:50	21/07/2025	07:00	480,824	St Leonards	SL052179
27 Transmission Automatic	Gearbox fault						
45 Engine 1	Clear faults and road test						
Forced DPF Regeneration	Carry Out Forced DPF Regeneration						
Unplanned Repair	23/07/2025	09:00	25/07/2025	06:00	480,824	St Leonards	SL052253
45 Engine 1	Engine Limp mode - DPF blocked						
Decommission Vehicle	25/07/2025	09:25	07/08/2025	11:47	480,824	St Leonards	SL052289