

Transaction date	Fleet No	Invoice No	Registration	Detail	Odometer/Hrs run	Total net	Total VAT	Total cost	
01-Dec-16	NRO70053	73991782	DG66HLH	MANAGEMENT FEES		À£33.86	À£6.78	À£40.64	
03-Jan-17	NRO70053	74026058	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Feb-17	NRO70053	74064785	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Mar-17	NRO70053	74113742	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
05-Apr-17	NRO70053	74143388	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
02-May-17	NRO70053	74160363	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Jun-17	NRO70053	74190345	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
03-Jul-17	NRO70053	74229730	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Aug-17	NRO70053	74258923	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Sep-17	NRO70053	74285244	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
13-Sep-17	NRO70053	74314106	DG66HLH	Manufacturer Variable Service Based - Labour		À£72.90	À£14.40	À£87.30	
13-Sep-17	NRO70053	74314106	DG66HLH	Manufacturer Variable Service Based - Parts		À£117.08	À£23.42	À£140.50	
22-Sep-17	NRO70053	74314106	DG66HLH	Flashing beacon damaged - Labour		À£45.00	À£9.00	À£54.00	
22-Sep-17	NRO70053	74314106	DG66HLH	Flashing beacon damaged - Parts		À£152.96	À£30.59	À£183.55	
02-Oct-17	NRO70053	74314118	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Nov-17	NRO70053	74354375	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Dec-17	NRO70053	74379900	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
02-Jan-18	NRO70053	74393593	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Feb-18	NRO70053	74443638	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Mar-18	NRO70053	1407644	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
03-Apr-18	NRO70053	74496945	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-May-18	NRO70053	74535191	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
28-Jun-18	NRO70053	74600111	DG66HLH	Pads - front (axle set) (wheels removed) - Labour		À£47.98	À£9.60	À£57.58	
28-Jun-18	NRO70053	74600111	DG66HLH	Pads - front (axle set) (wheels removed) - Parts		À£40.00	À£8.00	À£48.00	
02-Jul-18	NRO70053	74652375	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Aug-18	NRO70053	74600110	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
03-Sep-18	NRO70053	74627282	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Oct-18	NRO70053	74647806	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
05-Oct-18	NRO70053	74667385	DG66HLH	Pads - rear (axle set) - Labour		À£32.00	À£6.40	À£38.40	
05-Oct-18	NRO70053	74667385	DG66HLH	Pads - rear (axle set) - Parts		À£46.09	À£9.22	À£55.31	
05-Oct-18	NRO70053	74667385	DG66HLH	Number plate - Labour		À£4.00	À£0.80	À£4.80	
05-Oct-18	NRO70053	74667385	DG66HLH	Number plate - Parts		À£10.00	À£2.00	À£12.00	
05-Oct-18	NRO70053	74667385	DG66HLH	Service - Labour		À£70.00	À£14.00	À£84.00	
05-Oct-18	NRO70053	74667385	DG66HLH	Service - Parts		À£11.58	À£2.32	À£13.90	
01-Nov-18	NRO70053	74667384	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
14-Nov-18	NRO70053	74877134	DG66HLH	Beacon - Flashing - Labour Beacon on the roof leaking resealed		À£40.00	À£8.00	À£48.00	
03-Dec-18	NRO70053	74693045	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
02-Jan-19	NRO70053	74707144	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Feb-19	NRO70053	74722615	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Mar-19	NRO70053	74755909	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
15-Mar-19	NRO70053	74877134	DG66HLH	Pads - rear (axle set) - Labour		À£40.00	À£8.00	À£48.00	
15-Mar-19	NRO70053	74877134	DG66HLH	Pads - rear (axle set) - Parts		À£43.37	À£8.67	À£52.04	
01-Apr-19	NRO70053	74774432	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-May-19	NRO70053	74799478	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
03-Jun-19	NRO70053	74820236	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
03-Jul-19	NRO70053	74850039	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
10-Jul-19	NRO70053	74877134	DG66HLH	Tyre side wall damage, NSF 7mm left, fit 19S7516MILUS107R - Parts		À£125.08	À£25.01	À£150.07	
10-Jul-19	NRO70053	74877134	DG66HLH	Tyres - Environmental Disposal,NSF - Parts		À£1.10	À£0.22	À£1.32	
01-Aug-19	NRO70053	74857510	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
02-Sep-19	NRO70053	74877133	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
27-Sep-19	NRO70053	74928456	DG66HLH	Pads - front (axle set) - Labour		À£60.00	À£12.00	À£72.00	
27-Sep-19	NRO70053	74928456	DG66HLH	Pads - front (axle set) - Parts		À£49.34	À£9.87	À£59.21	
27-Sep-19	NRO70053	74928456	DG66HLH	Battery - Charging circuit- Parts		À£118.74	À£23.75	À£142.49	
01-Nov-19	NRO70053	75093529	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
02-Dec-19	NRO70053	74846249	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
02-Jan-20	NRO70053	74963311	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
17-Jan-20	NRO70053	75056513	DG66HLH	Tyre worn out, NSF 2mm left, fit 19S7516MILUS107R - Parts		34908	À£121.82	À£234.36	À£146.18
17-Jan-20	NRO70053	75056513	DG66HLH	Tyres - Environmental Disposal,OSF - Parts		34908	À£1.10	À£0.22	À£1.32
17-Jan-20	NRO70053	75056513	DG66HLH	Wheel Alignment,NSF - Parts		34908	À£19.91	À£3.98	À£23.89
03-Feb-20	NRO70053	75013152	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
27-Feb-20	NRO70053	75093129	DG66HLH	Pads - rear (axle set) (wheels removed) - Labour		37625	À£40.00	À£8.00	À£48.00
27-Feb-20	NRO70053	75093129	DG66HLH	Pads - rear (axle set) (wheels removed) - Parts		37625	À£44.18	À£8.84	À£53.02
04-Mar-20	NRO70053	75093129	DG66HLH	Hose (Cooling) - bottom/outlet - Labour		38151	À£100.00	À£20.00	À£120.00
04-Mar-20	NRO70053	75093129	DG66HLH	Hose (Cooling) - bottom/outlet - Parts		38151	À£107.99	À£21.60	À£129.59
10-Mar-20	NRO70053	75056515	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Apr-20	NRO70053	75093131	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
07-May-20	NRO70053	75118418	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Jun-20	NRO70053	75133763	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
14-Jul-20	NRO70053	INW00028621	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
03-Aug-20	NRO70053	INW00061144	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Sep-20	NRO70053	INW00096790	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Oct-20	NRO70053	INW0135747	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
08-Oct-20	NRO70053	INW0255685	DG66HLH	Recharge Breakdown 08/10/2020 07:48 Deeside - Vehicle Recovery to Central Garage, Rchg From Inv: 350881 CH210108002908/10/202007:48Dee		43108	À£0.00	À£0.00	À£0.00
08-Oct-20	NRO70053	INW0255685	DG66HLH	Recharge Movement - Routine, Non-Standard Vehicle Movement, Rchg From Inv: 350881 1st Hour Really Light 3.5 I & U		43108	À£87.58	À£17.52	À£105.10
08-Oct-20	NRO70053	INW0255685	DG66HLH	Recharge Movement - Routine, Non-Standard Vehicle Movement, Rchg From Inv: 350881 Additional Hrs Really Light 3		43109	À£23.21	À£4.64	À£27.85
09-Oct-20	NRO70053	MAINTINV0012518	DG66HLH	Recharge Routine - MOT, Rchg From Inv: 21371		43109	À£54.80	À£0.00	À£54.80
09-Oct-20	NRO70053	MAINTINV0012518	DG66HLH	Recharge Routine - Annual Service, Rchg From Inv: 21371		43109	À£186.10	À£37.22	À£223.32
02-Nov-20	NRO70053	INW0172517	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
01-Dec-20	NRO70053	INW0213185	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
10-Dec-20	NRO70053	INW0255685	DG66HLH	Recharge Recharge For: New Tyre, Position: C 1, 19S7516AGICRSL, MICHELIN, Tread: 10mm, Location: Drive In-National Tyres CAERNARVON(640), Rchg From Inv: U114285712		45682	À£127.52	À£25.50	À£153.02
10-Dec-20	NRO70053	INW0255685	DG66HLH	Recharge Recharge For: Removed Tyre, Position: C 1, 19S7516AVNCO45, CONTINENTAL, Removal Reason: Tyre - Impact Damage, Tread: 9mm, Location: Drive In-National Tyres CAERNARVON(640), Rchg From Inv: U114285712		45682	À£0.00	À£0.00	À£0.00
10-Dec-20	NRO70053	INW0255685	DG66HLH	Recharge Recharge For: SICHAP DISPOSAL CAR VAN 4X4, Position: C 1, Location: Drive In-National Tyres CAERNARVON(640), Rchg From Inv: U114285712		45682	À£1.10	À£0.22	À£1.32
10-Dec-20	NRO70053	INW0255685	DG66HLH	Recharge Recharge For: Standard Wheel Balance, Position: C 1, Location: Drive In-National Tyres CAERNARVON(640), Rchg From Inv: U114285712		45682	À£2.85	À£0.57	À£3.42
10-Dec-20	NRO70053	INW0255685	DG66HLH	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: C 1, Location: Drive In-National Tyres CAERNARVON(640), Rchg From Inv: U114285712		45682	À£2.85	À£0.57	À£3.42
04-Jan-21	NRO70053	INW0252761	DG66HLH	MANAGEMENT FEES		À£16.93	À£3.39	À£20.32	
18-Jan-21	NRO70053	MAINTINV0032225	DG66HLH	Recharge Breakdown 18/01/21 09:47 Llangefni - Exhaust EGR Valve - Sticking, Rchg From Inv: 701062 18/01/202109:47LLANGEFNI LL77		46776	À£81.15	À£16.23	À£97.38
18-Jan-21	NRO70053	MAINTINV0032225	DG66HLH	Recharge Cooling System - Check, Coolant, Rchg From Inv: 701062 Anti-Freeze		46776	À£4.41	À£0.88	À£5.29
19-Jan-21	NRO70053	MAINTINV0420129	DG66HLH	Recharge Other Unspecified Work - Routine, Breakdown, Rchg From Inv: 368607 CH210118030019/01/202114:42BAn		1	À£0.00	À£0.00	À£0.00
19-Jan-21	NRO70053	MAINTINV0420129	DG66HLH	Recharge Movement - Routine, Vehicle Movement, Rchg From Inv: 368607 1st Hour Really Light 3.5 I & U		1	À£87.58	À£17.52	À£105.10
19-Jan-21	NRO70053	MAINTINV0420129	DG66HLH	Recharge Movement - Routine, Vehicle Movement, Rchg From Inv: 368607 Additional Hrs Really Light 3		1	À£39.78	À£7.96	À£47.74
20-Jan-21	NRO70053	MAINTINV0032225	DG66HLH	Recharge Remove & Refit Exhaust gas recirculation (EGR) valve, Rchg From Inv: 22082 Vehicle recovered in, requires new EGR valve.		1	À£249.16	À£49.83	À£298.99
08-Feb-21	NRO70053	MAINTINV0037879	DG66HLH	Recharge Remove & Refit Rear Pads - rear (axle set), Rchg From Inv: 22162		1	À£87.25	À£17.45	À£104.70
08-Feb-21	NRO70053	MAINTINV0037879	DG66HLH	Recharge Routine - Service, Rchg From Inv: 22162 Carry out full service. (oil filter, air filter, fuel filter and pollen)		1	À£180.90	À£36.18	À£217.08
08-Feb-21	NRO70053	MAINTINV0032225	DG66HLH	Recharge Recharge For: New Tyre, Position: B 1, 19S7516AGILIS3, MICHELIN, Tread: 10mm, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245		47517	À£114.93	À£22.99	À£137.92
08-Feb-21	NRO70053	MAINTINV0032225	DG66HLH	Recharge Recharge For: New Tyre, Position: B 2, 19S7516AGILIS3, MICHELIN, Tread: 10mm, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245		47517	À£114.93	À£22.99	À£137.92
08-Feb-21	NRO70053	MAINTINV0032225	DG66HLH	Recharge Recharge For: New Tyre, Position: B 3, 19S7516AGILIS3, MICHELIN, Tread: 10mm, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245		47517	À£114.93	À£22.99	À£137.92

08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: New Tyre, Position: B 4, 1957516AGILIS3, MICHELIN, Tread: 10mm, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE114.93	ÀE22.99	ÀE137.92
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: Removed Tyre, Position: B 1, 1957516AVANC0200, CONTINENTAL, Removal Reason: Tyre - Worn Out, Tread: 2mm, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE0.00	ÀE0.00	ÀE0.00
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: Removed Tyre, Position: B 2, 1957516AVANC0200, CONTINENTAL, Removal Reason: Tyre - Worn Out, Tread: 2mm, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE0.00	ÀE0.00	ÀE0.00
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: Removed Tyre, Position: B 3, 1957516AVANC0200, CONTINENTAL, Removal Reason: Tyre - Worn Out, Tread: 2mm, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE0.00	ÀE0.00	ÀE0.00
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: B 1, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE1.10	ÀE0.22	ÀE1.32
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: B 2, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE1.10	ÀE0.22	ÀE1.32
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: B 3, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE1.10	ÀE0.22	ÀE1.32
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: SCRAP DISPOSAL CAR VAN 4X4, Position: B 4, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE1.10	ÀE0.22	ÀE1.32
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: Standard Wheel Balance, Position: B 1, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE5.01	ÀE1.00	ÀE6.01
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: Standard Wheel Balance, Position: B 2, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE5.01	ÀE1.00	ÀE6.01
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: Standard Wheel Balance, Position: B 3, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE5.01	ÀE1.00	ÀE6.01
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: Standard Wheel Balance, Position: B 4, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE5.01	ÀE1.00	ÀE6.01
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 1, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE2.85	ÀE0.57	ÀE3.42
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 2, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE2.85	ÀE0.57	ÀE3.42
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 3, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE2.85	ÀE0.57	ÀE3.42
08-Feb-21	NR070053	MAINTINV00332225	DG66HLH	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 4, Location: Drive In-Saracens Tyres Head Office, Rchg From Inv: U114320245	47517	ÀE2.85	ÀE0.57	ÀE3.42
17-Feb-21	NR070053	INV00295985	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Mar-21	NR070053	INV00332225	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Apr-21	NR070053	INV00377878	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
04-May-21	NR070053	INV00420130	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Jun-21	NR070053	INV00461316	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Jul-21	NR070053	INV00507489	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
02-Aug-21	NR070053	INV00549509	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Sep-21	NR070053	INV00584945	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Oct-21	NR070053	INV00629494	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
07-Oct-21	NR070053	INV00732636	DG66HLH	Recharge Routine MOT, Rchg From Inv: 23669	55528	ÀE54.80	ÀE0.00	
07-Oct-21	NR070053	INV00732636	DG66HLH	Recharge Routine Pre MOT Inspection, Rchg From Inv: 23669	55528	ÀE42.50	ÀE8.50	
07-Oct-21	NR070053	INV00732636	DG66HLH	Recharge Routine Service, Rchg From Inv: 23669	55528	ÀE200.12	ÀE40.02	
01-Nov-21	NR070053	INV00683553	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
17-Dec-21	NR070053	INV00732635	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
20-Jan-22	NR070053	INV00777089	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Feb-22	NR070053	INV00820553	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Mar-22	NR070053	INV00868721	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Apr-22	NR070053	INV00913135	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
03-May-22	NR070053	INV00960586	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Jun-22	NR070053	INV01007893	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Jul-22	NR070053	INV01055074	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
26-Jul-22	NR070053	INV01152099	DG66HLH	Recharge Remove & Refit Front Pads - front (axe set), Rchg From Inv: 25640	ÀE100.76	ÀE20.15	ÀE120.91	
26-Jul-22	NR070053	INV01152099	DG66HLH	Recharge Remove & Refit Rear Pads - rear (axe set), Rchg From Inv: 25640	ÀE102.01	ÀE20.40	ÀE122.41	
01-Aug-22	NR070053	INV01102007	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Sep-22	NR070053	INV01149771	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
07-Sep-22	NR070053	INV01199724	DG66HLH	Recharge Remove & Refit Front Disc - front (pair), Rchg From Inv: 25982	ÀE166.16	ÀE33.23	ÀE199.39	
01-Oct-22	NR070053	INV01197373	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
06-Oct-22	NR070053	MAINTINV01244914	DG66HLH	Recharge Routine MOT, Rchg From Inv: 26183	59864	ÀE54.80	ÀE0.00	
06-Oct-22	NR070053	MAINTINV01244914	DG66HLH	Recharge Remove & Refit Front Windscreen wiper - blade/s, Rchg From Inv: 26183	59864	ÀE9.15	ÀE1.83	
06-Oct-22	NR070053	MAINTINV01244914	DG66HLH	Recharge Repair Wiring/Wiring loom repair, Rchg From Inv: 26183 OS fog lamp input, remove lenses to check live to holders. Clean corrosion from connections, check loom, had broken wires, repair loom and relocate.	59864	ÀE70.00	ÀE14.00	
06-Oct-22	NR070053	MAINTINV01244914	DG66HLH	Recharge Routine MOT Inspection, Rchg From Inv: 26183	59864	ÀE2.50	ÀE0.00	
06-Oct-22	NR070053	MAINTINV01244914	DG66HLH	Recharge Routine Service, Rchg From Inv: 26183	59864	ÀE214.95	ÀE42.99	
01-Nov-22	NR070053	INV01244915	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Dec-22	NR070053	INV01283723	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Feb-23	NR070053	INV01387309	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Mar-23	NR070053	INV01436306	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
03-Apr-23	NR070053	INV01462334	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
02-May-23	NR070053	INV01523243	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
02-Jun-23	NR070053	INV01580630	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
26-Jun-23	NR070053	INV01632597	DG66HLH	Recharge Remove & Refit, Disc - Remove & Refit, Disc - rear (pair), Rchg From Inv: 45700 Rear discs poor/corrosion req	63890	ÀE445.11	ÀE89.02	
26-Jun-23	NR070053	INV01632597	DG66HLH	Recharge Remove & Refit, Linings (Pads & Shoes) - Remove & Refit, Pads - rear (axe set), Rchg From Inv: 45700 rear brake pads corroded/worn	63890	ÀE70.17	ÀE14.03	
26-Jun-23	NR070053	INV01632597	DG66HLH	Recharge Check Checks - Check, Investigate & Report, Rchg From Inv: 45700 HANDBRAKE IN O/P, C/O INVESTIG	63890	ÀE0.00	ÀE0.00	
03-Jul-23	NR070053	INV01628075	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Aug-23	NR070053	INV01677892	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Sep-23	NR070053	INV01726054	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
26-Sep-23	NR070053	INV01828805	DG66HLH	Recharge Routine, Movement - Routine, Movement - Engineer/Waiting Time, Rchg From Inv: 46376 MOT CLASS 7 WAITING TIME SUB C	67588	ÀE60.00	ÀE12.00	
26-Sep-23	NR070053	INV01828805	DG66HLH	Recharge Routine, MOT - Class VII (Goods Vehicles), Rchg From Inv: 46376	67588	ÀE58.60	ÀE0.00	
26-Sep-23	NR070053	INV01828805	DG66HLH	Recharge Routine, MOT - Pre Insp - LCV - Novuna Bespoke Event, Rchg From Inv: 46376	67588	ÀE60.00	ÀE12.00	
26-Sep-23	NR070053	INV01828805	DG66HLH	Recharge Remove & Refit, Drive And Prop-Shafts - Remove & Refit, Propeller shaft coupling/UI front, Rchg From Inv: 46376 mounting damaged/cracked req	67588	ÀE238.40	ÀE47.68	
26-Sep-23	NR070053	INV01828805	DG66HLH	Recharge Remove & Refit, Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade left, Rchg From Inv: 46376 N/S WIPER POOR, REQUIRES NEW	67588	ÀE12.89	ÀE2.58	
26-Sep-23	NR070053	INV01828805	DG66HLH	Recharge Remove & Refit, Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade right, Rchg From Inv: 46376 O/S WIPER POOR, REQUIRES NEW	67588	ÀE12.89	ÀE2.58	
26-Sep-23	NR070053	INV01828805	DG66HLH	Recharge Replace Door Mirror Indicator Lamps as Damaged, Rchg From Inv: 46376	67588	ÀE49.53	ÀE5.93	
26-Sep-23	NR070053	INV01828805	DG66HLH	Recharge Wheel Nut Indicator Missing, Requires New, Rchg From Inv: 46376 wheel nut indicator missing re	67588	ÀE10.98	ÀE2.20	
26-Sep-23	NR070053	INV01828805	DG66HLH	Recharge Routine, Service - Annual - Novuna Bespoke Event, Rchg From Inv: 46376	67588	ÀE331.53	ÀE66.31	
02-Oct-23	NR070053	INV01777721	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
09-Oct-23	NR070053	INV01828805	DG66HLH	Recharge Remove & Refit, Lamps - Remove & Refit, Lamps exterior (rear) - tail light bulb right, Rchg From Inv: 46597 O/S/r side light bulb in o/p,	67912	ÀE13.25	ÀE2.65	
09-Oct-23	NR070053	INV01828805	DG66HLH	Recharge Repair, Wiring Harness - Repair, Wiring loom repair, Rchg From Inv: 46597 bad earth to a/s/r repair wiri	67912	ÀE30.00	ÀE6.00	
09-Oct-23	NR070053	INV01828805	DG66HLH	Recharge Check Checks - Check, Investigate & Report, Rchg From Inv: 46597 Investigate noise from front &	67912	ÀE30.00	ÀE6.00	
09-Oct-23	NR070053	INV01828805	DG66HLH	Recharge Check Checks - Check, Investigate & Report, Rchg From Inv: 46597 NOISE FROM FRONT FOUND STONE S	67912	ÀE30.00	ÀE6.00	
09-Oct-23	NR070053	INV01828805	DG66HLH	Recharge Check Checks - Check, Investigate & Report, Rchg From Inv: 46597 O/S/r side light in o/p	67912	ÀE6.00	ÀE1.20	
01-Nov-23	NR070053	INV01825941	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
20-Nov-23	NR070053	MAINTINV01876121	DG66HLH	Recharge Remove & Refit, Lamps - Remove & Refit, Electric Lamp Side Marker, Rchg From Inv: I013866 side markers inp - find fuse	69074	ÀE11.27	ÀE2.25	
20-Nov-23	NR070053	MAINTINV01876121	DG66HLH	Recharge Remove & Refit, Lamps - Remove & Refit, Lamps exterior - rear lamp assy left, Rchg From Inv: I013866 crack in lens, water damaging	69074	ÀE37.91	ÀE7.58	
20-Nov-23	NR070053	MAINTINV01876121	DG66HLH	Recharge Repair, Wiring Harness - Repair, Wiring loom repair, Rchg From Inv: I013866 no indicator drivers rear, rep	69074	ÀE55.25	ÀE11.05	
01-Dec-23	NR070053	INV01876122	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
02-Jan-24	NR070053	INV01926231	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Feb-24	NR070053	INV01957676	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Mar-24	NR070053	INV02027125	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
02-Apr-24	NR070053	INV02076261	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
18-Apr-24	NR070053	INV02177735	DG66HLH	Recharge Remove & Refit Front Glass - windscreen, Rchg From Inv: SIN683077	1	ÀE361.88	ÀE72.38	
03-Jun-24	NR070053	INV02173392	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
01-Jul-24	NR070053	INV02222301	DG66HLH	MANAGEMENT FEES	ÀE16.93	ÀE3.39	ÀE20.32	
08-Jul-24	NR070053	MAINTINV02324352	DG66HLH	Recharge Routine, Movement - Routine, Movement ? Novuna Request, Rchg From Inv: 00-828365 06/07 MOVEMENT AWS REQUESTED F	77891	ÀE243.25	ÀE48.65	
08-Jul-24	NR070053	MAINTINV02324352	DG66HLH	Recharge Check Checks - Check, Investigate & Report, Rchg From Inv: 01561813 check engine as using water	77891	ÀE53.00	ÀE10.60	
11-Jul-24	NR070053	MAINTINV02324352	DG66HLH	Recharge Check, Engine Management Fault Diagnosis - Check, Engine management - fault diagnosis, Rchg From Inv: I031685	77991	ÀE24.00	ÀE4.80	
11-Jul-24	NR070053	MAINTINV02324352	DG66HLH	Recharge Remove & Refit, Exhaust Gas Analysis - Remove & Refit, Exhaust Gas Recirculation (EGR) cooler, Rchg From Inv: I031685	77991	ÀE645.99	ÀE129.20	
11-Jul-24	NR070053	MAINTINV02324352	DG66HLH	Recharge Remove & Refit, Exhaust Gas Analysis - Remove & Refit, Exhaust gas recirculation (EGR) valve, Rchg From Inv: I031685	77991	ÀE266.57	ÀE53.31	
18-Jul-24	NR070053	INV02278145	DG66HLH	Recharge Recharge For: New Tyre, Position: A 4, 1957516DAVANTDX440107105R, DAVANTI, Location: Teiars Saracens Tyres Ltd King St Cerrignydrudon Corwen LL21 9ST ETA DRIVE IN, Rchg From Inv: I199191916 Authorised ByWayne Saracens Location:Teiars Saracens Tyres Ltd King St Cerrignydrudon Corwen LL21 9ST ETA DRIVE	77348	ÀE99.65	ÀE19.93	
18-Jul-24	NR070053	INV02278145	DG66HLH	Recharge Recharge For: Removed Tyre, Position: A 4, 1957516DAVANTDX440107105R, DAVANTI, Removal Reason: Tyre - Worn Out, Tread: 1mm, Location: Teiars Saracens Tyres Ltd King St Cerrignydrudon Corwen LL21 9ST ETA DRIVE IN, Rchg From Inv: I199191916 Authorised ByWayne Saracens Location:Teiars Saracens Tyres Ltd King St Cerrignydrudon Corwen LL21 9				

