

Vehicle Detail Date	WA130MG Odo	LANDROVER Job Type	DEF 110 HIGH CAP P/U Description	No
06/01/2025	0	RFL	RFL Jan 2025	
31/12/2024	0	REPAIRS FOR MISUSE OR DAMAGE	REFLECTIVE DEVICES - BOD	
31/12/2024	0	REPAIRS TO COOLING SYSTEM	COOLANT / ANTIFREEZE - ENG	
31/12/2024	0	REPAIRS TO COOLING SYSTEM	COOLANT / ANTIFREEZE - ENG	
31/12/2024	0	Admin Charges	CONSUMABLE CHARGE - ADD	
31/12/2024	0	REPAIRS FOR MISUSE OR DAMAGE	BULB MISC - ELE	
31/12/2024	0	REPAIRS FOR MISUSE OR DAMAGE	BULB MISC - ELE	
31/12/2024	0	REPAIRS TO ELECTRICS/BATTERY	Bulb Misc	
31/12/2024	0	SERV/SAFETY INS (+ TEST FEE)	ENGINE OIL - ENGENGINE OIL & F/FILTER CHANGEENGINE OIL FILTER - ENGEN	
31/12/2024	0	REPAIRS FOR MISUSE OR DAMAGE	REFLECTIVE DEVICES - BOD	
27/11/2024	45,517	Admin Charges	Recharge Routine, Other Unspecified Work - Routine, Environmental Charge, Rchg From Inv: 760555	
27/11/2024	45,517	SERV/SAFETY INS (+ TEST FEE)	Recharge Routine, Winch Inspection - Annual - MOD only - Novuna Bespoke Event, Rchg From Inv: 760555	
04/01/2024	0	RFL	RFL Jan 2024	
02/01/2024	41,479	MOT	Recharge Routine, MOT - Class IV Cars (Up To 8 Passenger Seats), Rchg From Inv: 35724040	
22/12/2023	41,468	REPAIRS TO BRAKES	Recharge Remove & Refit, Linings (Pads & Shoes) - Remove & Refit, Pads - rear (axle set), Rchg From	
22/12/2023	41,468	REPAIRS TO BRAKES	Recharge Remove & Refit, Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake), Rchg From Inv: 3	
22/12/2023	41,468	REPAIRS TO SUSPENSION	Recharge Remove & Refit, Front Hub - Remove & Refit, Hub assy (one) (Front Susp.) left, Rchg From In	
22/12/2023	41,468	SERV/SAFETY INS (+ TEST FEE)	Recharge Routine, 10 year Service - ROVER 2001/16 Defender, Rchg From Inv: 32786015	
22/12/2023	41,468	REPAIRS TO SUSPENSION	Recharge Remove & Refit, Rear Shock Absorber - Remove & Refit, Strut assy/suspension unit (pair) (Re	
22/12/2023	41,468	REPAIRS TO BRAKES	Recharge Adjust, Parking Brake - Adjust, Parking brake, Rchg From Inv: 32786015 Parking drum require	
22/12/2023	41,468	REPAIRS TO DIFF/FINAL DRIVE	Recharge Remove & Refit, Final Drive Units - Remove & Refit, Differential unit oil seal - output sha	
22/12/2023	41,468	REPAIRS TO DIFF/FINAL DRIVE	Recharge Remove & Refit, Final Drive Units - Remove & Refit, Differential unit oil seal - drive pini	
17/12/2023	0	COLLECTION & DELIVERY	Recharge Routine Movement - Engineer Onsite, Rchg From Inv: 23882 Overnight	
17/12/2023	0	SERV/SAFETY INS (+ TEST FEE)	Recharge Routine Winch Inspection - Annual, Rchg From Inv: 23882	
17/12/2023	0	COLLECTION & DELIVERY	Recharge Routine Movement - Engineer Onsite, Rchg From Inv: 23882	
17/12/2023	0	COLLECTION & DELIVERY	Recharge Routine Movement - Mileage Charge, Rchg From Inv: 23882	
21/03/2023	0	REPAIRS TO ENGINE, EXHAUST	Breakdown - Engine Fault with Recovery	
21/03/2023	0	REPAIRS TO ELECTRICS/BATTERY	Charging circuit - battery	
21/03/2023	0	REPAIRS TO ENGINE, EXHAUST	29175/Other Unspecified Work - Routine/ Unsch	
21/03/2023	0	BREAKDOWN RECOVERY	29104/Other Unspecified Work - Routine/ Break	
16/03/2023	0	SERV/SAFETY INS (+ TEST FEE)	29135/Checks - Check/ Investigate & Report	
16/03/2023	0	SERV/SAFETY INS (+ TEST FEE)	29135/Checks - Check/ Investigate & Report	
14/03/2023	0	REPAIRS TO ENGINE, EXHAUST	Breakdown - Engine Fault with Recovery	
13/03/2023	0	REPAIRS TO ENGINE, EXHAUST	Breakdown - Engine Fault with Recovery	
14/12/2022	0	SERV/SAFETY INS (+ TEST FEE)	S9 SERVICE	
14/12/2022	0	SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test	
14/12/2022	0	REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - blade/s	
14/10/2022	0	SERV/SAFETY INS (+ TEST FEE)	Winch Equipment Test	
14/10/2022	0	SERV/SAFETY INS (+ TEST FEE)	On Site Visit	
07/10/2022	0	TYRES	Wheel Balance	
07/10/2022	0	TYRES	Tyre Valve Inner Repair	
07/10/2022	0	TYRES	Change Tyre	
07/10/2022	0	TYRES	Disposal of Tyre Casing	
07/10/2022	0	TYRES	Wheel Balance	
07/10/2022	0	TYRES	Disposal of Tyre Casing	
07/10/2022	0	TYRES	Change Tyre	
07/10/2022	0	TYRES	Disposal of Tyre Casing	
07/10/2022	0	TYRES	Wheel Balance	
07/10/2022	0	TYRES	Tyre Valve Inner Repair	
07/10/2022	0	TYRES	Tyre Valve Inner Repair	
07/10/2022	0	TYRES	Tyre Valve Inner Repair	
07/10/2022	0	TYRES	Tyre Valve Inner Repair	
07/10/2022	0	TYRES	Tyre Valve Inner Repair	

07/10/2022	0 TYRES	Disposal of Tyre Casing
07/10/2022	0 TYRES	Wheel Balance
07/10/2022	0 TYRES	Tyre Valve Inner Repair
07/10/2022	0 TYRES	Change Tyre
07/10/2022	0 TYRES	Change Tyre
07/10/2022	0 TYRES	Tyre Valve Inner Repair
01/02/2022	0 SERV/SAFETY INS (+ TEST FEE)	S9 SERVICE
01/02/2022	0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
14/01/2022	22,516 REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - motor
14/01/2022	22,516 REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - linkage
14/01/2022	0 RFL	RFL Dec 2021
12/01/2022	0 REPAIRS FOR MISUSE OR DAMAGE	WIPERS
27/10/2021	0 SERV/SAFETY INS (+ TEST FEE)	Winch Equipment Test
27/10/2021	0 SERV/SAFETY INS (+ TEST FEE)	ENVIRONMENTAL CHARGE
27/10/2021	0 COLLECTION & DELIVERY	On Site Visit
23/02/2021	22,516 REPAIRS FOR MISUSE OR DAMAGE	Radio Aerial - roof/wing
23/02/2021	22,516 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
23/02/2021	22,516 REPAIRS FOR MISUSE OR DAMAGE	Radio Aerial - roof/wing
23/02/2021	22,516 SERV/SAFETY INS (+ TEST FEE)	S8 SERVICE
23/02/2021	22,516 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
23/02/2021	22,516 SERV/SAFETY INS (+ TEST FEE)	S8 SERVICE
22/01/2021	19,907 SERV/SAFETY INS (+ TEST FEE)	HAZARD LIGHTS IS NOT WORKING - COULD BE THE R
10/12/2020	19,907 REPAIRS TO CLUTCH	Clutch - assy
10/12/2020	19,907 REPAIRS TO CLUTCH	Clutch - assy
02/11/2020	0 COLLECTION & DELIVERY	MRQ01946697/MRT05017721
02/11/2020	0 SERV/SAFETY INS (+ TEST FEE)	MRQ01946697/MRT05017722
25/08/2020	0 REPAIRS TO BODY (NON ACCIDENT)	FAULTY BONNET CATCH DEFECT 0905953- check bon
05/06/2020	0 REPAIRS TO ELECTRICS/BATTERY	Lamps exterior - headlamp assy right
05/06/2020	0 REPAIRS TO BODY (NON ACCIDENT)	Number plate
09/03/2020	0 ACCIDENT REPAIRS	Lamps exterior - headlamp assy right
09/03/2020	0 SERV/SAFETY INS (+ TEST FEE)	S7 SERVICE
09/03/2020	0 REPAIRS TO BODY (NON ACCIDENT)	FAILED MOT ON BONNET NOT SHUTTING AS OUT OF ALIGNMENT
09/03/2020	0 REPAIRS TO BODY (NON ACCIDENT)	Bonnet - alignment
09/03/2020	0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
20/11/2019	0 MAINTENANCE	TRAVEL COSTS TO RETURN TO FIT PARTS
20/11/2019	0 MAINTENANCE	ESTIMATE FOR RETURN TO SITE TO FIT DAMAGED PARTS OF REMOTE CONTROL AS WIRES FRAY
20/11/2019	0 MAINTENANCE	CARRIAGE CHARGE
20/11/2019	0 MAINTENANCE	/WINCH - REMOVE & REFIT/ WINCH - MISCELLANEOUS/OTHER
20/11/2019	0 COLLECTION & DELIVERY	On Site Visit
20/11/2019	0 STATUTORY TESTING	WINCH INSPECTION COSTS REF
29/08/2019	0 REPAIRS FOR MISUSE OR DAMAGE	FLAT BATTERY
21/03/2019	0 SERV/SAFETY INS (+ TEST FEE)	S6 SERVICE
21/03/2019	0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
21/03/2019	0 REPAIRS TO ELECTRICS/BATTERY	Headlamp alignment
21/03/2019	0 REPAIRS TO BRAKES	ROLLER BRAKE TEST
12/06/2018	8,289 REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - blade/s
12/06/2018	8,289 SERV/SAFETY INS (+ TEST FEE)	S5 SERVICE
12/06/2018	8,289 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
12/06/2018	8,289 REPAIRS TO BODY (NON ACCIDENT)	EA0517 Vehicle condition report recall end date =30-SEP-2018
15/12/2017	0 RFL	RFL January 2018
19/10/2017	0 SERV/SAFETY INS (+ TEST FEE)	Engine management - fault diagnosis
19/10/2017	0 SERV/SAFETY INS (+ TEST FEE)	Winch Equipment Test
13/06/2017	0 SERV/SAFETY INS (+ TEST FEE)	PLEASE REMOVE TOW BAR/AND RACK INSIDE OF THE VEHICLE WHICH IS ATTACHED TO THE FLOOR.
09/06/2017	0 SERV/SAFETY INS (+ TEST FEE)	ABS - fault diagnosis
09/06/2017	0 REPAIRS TO BRAKES	Hydraulic system (Brake) - bleed

15/12/2016	0 RFL	RFL JAN 2017
09/06/2016	0 MOT	MOT - Class IV Cars (Up To 8 Passenger Seats) - Labour
24/03/2016	0 STATUTORY TESTING	Winch Insp/Service 12mths - Hitachi Bespoke Inspection or Test - Labour
24/03/2016	0 COLLECTION & DELIVERY	Movement - Engineer Onsite - Labour
14/02/2016	0 REPAIRS TO ELECTRICS/BATTERY	Auxiliary Battery - Labour
14/02/2016	0 REPAIRS TO ELECTRICS/BATTERY	Vehicle Tracker - modify wiring. - Labour
14/02/2016	0 ROAD TEST	Investigate & Report - Labour
14/02/2016	0 REPAIRS TO ELECTRICS/BATTERY	Auxiliary Battery - Parts
08/02/2016	0 BREAKDOWN RECOVERY	Breakdown - Labour
02/11/2015	0 MAINTENANCE	MANAGEMENT FEES
06/07/2015	0 ROAD TEST	Investigate & Report - Labour
06/07/2015	0 COLLECTION & DELIVERY	Movement - Engineer Onsite - Labour
26/03/2015	0 REPAIRS TO BRAKES	Hydraulic fluid (Brake) - Labour
26/03/2015	0 REPAIRS TO BRAKES	Hydraulic fluid (Brake) - Parts
26/03/2015	0 SERV/SAFETY INS (+ TEST FEE)	2 Year Service - ROVER 2001/- Defender - Labour
26/03/2015	0 SERV/SAFETY INS (+ TEST FEE)	2 Year Service - ROVER 2001/- Defender - Parts
24/03/2015	0 STATUTORY TESTING	Winch Insp/Service 12mths - Hitachi Bespoke Inspection
24/03/2015	0 COLLECTION & DELIVERY	Movement - Engineer Onsite - Labour
15/12/2014	0 RFL	RFL December 2014
24/03/2014	0 COLLECTION & DELIVERY	Movement - Engineer Onsite - Labour
24/03/2014	0 STATUTORY TESTING	Hitachi Bespoke Inspection or Test - Labour
06/03/2014	0 SERV/SAFETY INS (+ TEST FEE)	1 year Service - ROVER 2001/- Defender - Parts
06/03/2014	0 SERV/SAFETY INS (+ TEST FEE)	1 year Service - ROVER 2001/- Defender - Labour
01/12/2013	0 RFL	RFL December 2013
12/08/2013	0 GENERAL MODIFICATION/ADDITION	Supply wheel locking kit