

WX15NHJ	A&E		Soundwell Amb Stn				
Breakdown	11/12/2015	12:33	15/12/2015	13:14	1,713	Bristol	BL000139
Breakdown	stuck in mud						
SAFETY INSPECTION	16/12/2015	07:19	16/12/2015	08:22	1,714	Bristol	BL000170
18 Wheels Check Torques Safety Inspection							
Unplanned Repair	23/12/2015	09:30	29/12/2015	16:05	2,951	Bristol	BL000237
02 Mirrors 44 Add Ad Blue	n/s mirror broken top up						
Veh Deep Clean	29/12/2015	05:07	29/12/2015	05:09	3,275	Bristol	BL000261
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/01/2016	07:25	28/01/2016	14:00	5,632	Bristol	BL000618
18 Wheels Check Torques 85 Body Interior 1 87 Stretcher Safety Inspection Tail Lift Inspection	NFF NFF						
Breakdown	27/01/2016	10:36	27/01/2016	11:00	5,632	Bristol	BL000641
Breakdown	Sirens temperamental hard to turn on						

SAFETY INSPECTION	09/03/2016	08:19	09/03/2016	10:07	9,439	Bristol	BL001160
18 Wheels Check Torques							
55 Tail Lift			carry repairs to tail lift rails and platform				
85 Body Interior 1			repace bio strap on scoop door				
Safety Inspection							
Veh Deep Clean	14/03/2016	21:00	15/03/2016	02:00	10,051	Bristol	BL001243
Vehicle Deep Clean			Vehicle Deep Clean				
Unplanned Repair	16/03/2016	11:57	16/03/2016	12:04	10,189	Bristol	BL001280
17 Tyres Replace			n\s\r new tyre				
Breakdown	03/04/2016	15:36	03/04/2016	17:22	11,494	Bristol	BL001469
Breakdown			Near front bulge in tyre				
Unplanned Repair	15/04/2016	13:20	15/04/2016	15:51	12,591	Bristol	BL001615
44 Add Ad Blue			top up adblue				
SAFETY INSPECTION	19/04/2016	15:38	19/04/2016	18:56	12,982	Bristol	BL001657
17 Tyres Replace			Replace osf tyre				
18 Wheels Check Torques							
Safety Inspection			Carry out safety inspection				
Tail Lift Inspection			Carry out tail lift inspection				
UB Fire Suppression Service			Carry out fire suppression service				
Veh Deep Clean	05/05/2016	22:00	06/05/2016	03:15	14,402	Bristol	BL001840

Vehicle Deep Clean

Vehicle Deep Clean

SAFETY INSPECTION	01/06/2016	15:51	01/06/2016	16:43	16,832	Bristol	BL002137
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	replace fire extinguishers old ones had no date on them
17 Tyres Replace	replace 4 rear tyres
18 Wheels Check Torques	
44 Add Ad Blue	top up ad blue
Safety Inspection	

Breakdown	23/06/2016	18:23	23/06/2016	20:56	18,972	Bristol	BL002378
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

03 Instruments & Sensors 1	carried out diagnostic test no fault present / checked engine all ok
13 Handbrake	adjusted hand brake
44 Add Ad Blue	topped up adblue
Breakdown	2304 Noise when accelerating, looses power
Road Test	carried out motorway road test all ok at time of testing

SAFETY INSPECTION	15/07/2016	15:38	15/07/2016	19:16	21,215	Bristol	BL002663
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques
 Safety Inspection
 92 - C Service
 Service C
 Tail Lift Inspection
 Travel Time
 MOT
 Fit Throw Lines & SOP

Unplanned Repair	31/07/2016	12:03	31/07/2016	12:05	22,566	Bristol	BL002839
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

44 Add Ad Blue	Top up da blue
----------------	----------------

Veh Deep Clean	01/08/2016	08:00	01/08/2016	13:30	22,566	Bristol	BL002845
-----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Unplanned Repair	07/08/2016	10:00	07/08/2016	10:15	22,970	Taunton	TN014893
34 Lights Bulb Replacement	o/s dipped beam bulb replaced by OM						
Unplanned Repair	16/08/2016	09:04	16/08/2016	09:14	23,794	Bristol	BL003020
44 Add Ad Blue	top up						
Breakdown	21/08/2016	02:24	22/08/2016	11:18	24,255	Bristol	BL003071
Breakdown	F N/S flat						
SAFETY INSPECTION	24/08/2016	07:21	24/08/2016	14:11	24,401	Bristol	BL003108
02 Windscreen	added screen wash						
02 Windscreen Wipers	replaced wiper blades						
13 Brake Pads	replaced front pads and sensors						
13 Discs	replaced front discs						
18 Wheels Check Torques							
34 Emergency Lights	replaced nsf top marker light						
34 Lights	replaced ns side marker light						
44 Add Ad Blue	topped up ad blue						
55 Tail Lift	lubed tail lift and adjusted lift bed / tail lift lights not working						
Safety Inspection							
Handbrake Cable Replacement	Replace rear handbrake cables / not required as not over 3 years old						
Vehicle Deep Clean	05/09/2016	07:10	05/09/2016	10:10	25,434	Bristol	BL003234
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	07/09/2016	16:18	07/09/2016	16:21	25,665	Bristol	BL003276
34 Lighting System	ns brake light not working replace light unit						

Awaiting Parts

Unplanned Repair	18/09/2016	12:47	18/09/2016	12:51	26,654	Bristol	BL003409
44 Add Ad Blue	Top up ad blue						
Breakdown	25/09/2016	05:59	25/09/2016	17:30	26,813	Bristol	BL003474
Breakdown	n/s headlight						
SAFETY INSPECTION	04/10/2016	07:54	05/10/2016	10:40	27,799	Bristol	BL003567
02 Windscreen	top up washer fluid						
13 Brakes 1	replace rear brake pads						
18 Wheels Check Torques							
44 Add Ad Blue	top up ad blue						
55 Tail Lift	lubed tail lift and adjusted lift bed / tail lift lights not working						
Safety Inspection							
Tail Lift Inspection							
UB Fire Suppression Service							
Wheel Studs & Nuts Replacement	not due at present						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	04/10/2016	21:15	05/10/2016	02:15	27,799	Bristol	BL003580
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	15/10/2016	11:35	15/10/2016	11:39	28,768	Bristol	BL003716
02 Mirrors	replaced ns mirror glass						
86 Doors Rear	repaired bent rear door stay						
Unplanned Repair	30/10/2016	10:37	30/10/2016	10:39	30,126	Bristol	BL003894

44 Add Ad Blue Top up ad blue

SAFETY INSPECTION 16/11/2016 15:00 18/11/2016 09:40 31,362 Bristol BL004106

02 Windscreen top up
 17 Tyres Replace new tyre and clean hubs
 18 Wheels Check Torques
 45 Engine Oil Top Up top up
 87 - Stretchers/Chairs/Boards new belts
 Safety Inspection

Vehicle Deep Clean 16/11/2016 21:15 17/11/2016 02:15 31,362 Bristol BL004110

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair 27/11/2016 13:26 27/11/2016 13:40 32,142 Bristol BL004271

13 Brakes 1 Noise from rear brakes replace spring clips
 44 Add Ad Blue Top up ad blue

Unplanned Repair 29/11/2016 12:56 29/11/2016 13:06 32,142 Bristol BL004309

02 Cab Ass Fire Extinguisher fit new fire extinguishers 01/06/2016
 86 Doors Doors 2304 Side door stiff Heading to workshop
 UB Fire Suppression Dischargeno fault found

Unplanned Repair 12/12/2016 15:29 12/12/2016 15:32 33,617 Bristol BL004488

44 Add Ad Blue Top up ad blue

Unplanned Repair 03/01/2017 15:23 03/01/2017 15:25 33,617 Bristol BL004834

44 Add Ad Blue top up AdBlue

SAFETY INSPECTION	04/01/2017	11:12	04/01/2017	14:18	33,618	Bristol	BL004847
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	top up washer fluid
17 Tyres Replace	replace rear tyres
18 Wheels Check Torques	
Safety Inspection	
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill
Medical Device and Equip Chec	
Tail Lift Inspection	
Annual Heater Service	Annual Heater Service

Breakdown	09/01/2017	11:01	09/01/2017	18:07	35,773	Bristol	BL004904
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown	EML AMBER NOT RESETTING
-----------	-------------------------

Vehicle Deep Clean	09/01/2017	21:15	10/01/2017	02:15	35,784	Bristol	BL004918
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	19/01/2017	10:17	19/01/2017	10:20	36,779	Bristol	BL005072
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

44 Add Ad Blue	Top up ad blue
----------------	----------------

Vehicle Deep Clean	07/02/2017	07:01	07/02/2017	09:58	38,418	Bristol	BL005377
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/02/2017	10:14	08/02/2017	14:30	38,419	Bristol	BL005378
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

01 Air Conditioning 1	aircon drive belt being changed next service	Awaiting Parts
02 Cab Assembly 1	replaced brake pedal pad	
02 Cab Assembly 2	replaced cab torch assy	
02 Windscreen	topped up screen wash	
13 Handbrake	adjusted handbrake	
16 Suspension 1	replaced nsf and osf shockers	
18 Wheels	cleaned wheel hubs	
18 Wheels Check Torques		

31 Charging System	aux drive belt being changed next service	Awaiting Parts
34 Emergency Lights	replaced damaged osr top blue light cover	
34 Lights Bulb Replacement	replaced os headlight bulb	
44 Add Ad Blue	topped up ad blue	
55 Tail Lift	platform lights slow close not working / tested wiring and replaced tilt switch	
89 Seats	adjusted saloon seats	
99 Diagnostic Test	carried out system test	
Safety Inspection		
93 - D Service	carried out service	
Service D		

Emergency Deep Clean	13/02/2017	07:15	13/02/2017	10:42	38,681	Bristol	BL005450
-----------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Emergency Deep Clean

Breakdown	23/02/2017	11:48	23/02/2017	13:02	39,613	Bristol	BL005575
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

44 Add Ad Blue	topped up adblue
86 Doors Rear	replaced damaged door stay
Breakdown	Back door stay bar has bent in the wind

Breakdown	03/03/2017	10:55	06/03/2017	09:16	40,000	Bristol	BL005685
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown	side step wont come all the way out - checked by matt morris - NFF
-----------	--

Vehicle Deep Clean	24/03/2017	07:05	24/03/2017	10:28	42,393	Bristol	BL005921
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	24/03/2017	15:23	24/03/2017	20:53	42,393	Bristol	BL005928
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	topped up screen wash
16 Suspension 1	replaced nsr leaf spring pad rubber
18 Wheels	painted wheels
18 Wheels Check Torques	

18 Wheels Removal	cleaned all wheel hubs
44 Add Ad Blue	top up
71 Body External Steps	repair bent step frame
86 Door Lock	replaced rear door lock cover
Safety Inspection	
Tail Lift Inspection	
UB Fire Suppression Service	service not carried out as awaiting firetrace recall

Unplanned Repair	10/04/2017	18:03	10/04/2017	18:06	43,728	Bristol	BL006102
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	top up wash fluid
44 Add Ad Blue	top up ad blue

Unplanned Repair	11/04/2017	09:22	18/04/2017	17:58	43,786	Bristol	BL006117
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

42 Coolant System	check out leak from coolant (pump)
-------------------	------------------------------------

SAFETY INSPECTION	05/05/2017	10:18	18/05/2017	11:30	45,610	Bristol	BL006389
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	top up screenwash
16 Suspension 1	replaced both front shock absorbers
17 Tyres Replace	nsf tyre replaced
18 Wheels	clean f and rear wheels
18 Wheels Check Torques	check wheel torques
34 Lights	replaced os amber marker light
44 Add Ad Blue	top up adblue
Safety Inspection	carry out safety check

Vehicle Deep Clean	06/05/2017	07:00	06/05/2017	12:02	45,610	Bristol	BL006399
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	24/05/2017	17:56	24/05/2017	18:22	46,811	Bristol	BL006602
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

42 Coolant System	replace coolant bottle
-------------------	------------------------

Unplanned Repair	25/05/2017	18:12	26/05/2017	15:45	46,879	Bristol	BL006619
42 Coolant System	coolant light on - belt off - replace air con belt						
Breakdown	29/05/2017	14:38	30/05/2017	13:45	47,209	Bristol	BL006652
16 Suspension 1	jack up and check suspension check tyre pressures - NFF carry out tracking Pulling to left violently						
17 Tyres Tracking							
Breakdown							
MGS Gas Storage Modifications	09/06/2017	15:00	09/06/2017	15:01	47,948	Bristol	BL006839
MGS Gas Storage Modifications	MGS Gas Storage Modifications						
Vehicle Deep Clean	13/06/2017	07:15	13/06/2017	12:45	48,320	Bristol	BL006867
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/06/2017	07:08	15/06/2017	13:11	48,321	Bristol	BL006872
02 Windscreen Wipers	replace wiper blades						
18 Wheels Check Torques							
34 Emergency Lights	replace top o/s/r blue light cover top up ad blue						
44 Add Ad Blue							
Install Saloon CCTV Camera	straighten out camera bracket						
Safety Inspection							
WAS Firetrace rework & Service							
Tail Lift Inspection	alfa tail lifts to do						
Travel Time							
MOT							
Handbrake Cable Replacement	Replace rear handbrake cables.vehicle not 3 years old						
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Unplanned Repair	05/07/2017	07:57	05/07/2017	08:03	50,676	Bristol	BL007114

71 Body External Steps	Side step noisy replace motor						
Unplanned Repair	17/07/2017	08:06	17/07/2017	09:48	51,867	Bristol	BL007273
86 Doors Rear	Doors stay bar come off replace door stay block						
Vehicle Deep Clean	25/07/2017	23:45	26/07/2017	04:45	52,440	Bristol	BL007453
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/07/2017	18:04	26/07/2017	19:40	52,440	Bristol	BL007462
02 Windscreen	Awaiting Parts						
18 Wheels Check Torques							
44 Add Ad Blue							
45 Engine Oil Top Up							
89 Seatbelts							
Safety Inspection							
Gearbox Oil & Filter Change							
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Unplanned Repair	28/08/2017	08:55	28/08/2017	10:51	52,699	Bristol	BL007784
86 Sliding Door	refit new side door handle						
Vehicle Deep Clean	28/08/2017	20:45	29/08/2017	02:00	52,721	Bristol	BL007789
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	07/09/2017	14:41	07/09/2017	21:45	55,462	Bristol	BL007911
02 Windscreen	top up screenwash replace front discs and pads replace rear discs and pads replace 5 tyres						
13 Brakes 1							
13 Brakes 2							
17 Tyres Replace							

18 Wheels Check Torques
 18 Wheels Removal clean all wheel hubs
 42 Coolant System Radiator/Cooling Sys red coolant light on dash - NFF
 45 Engine Oil Top Up top up engine oil
 86 Door handle Doors side door handle fallen off - NFF
 89 Seatbelts Body Interior first attendant seat seatbelt not retracting - NFF
 Safety Inspection carry out safety inspection
 UB Fire Suppression Service
 Tail Lift Inspection

Vehicle Deep Clean	07/09/2017	09:30	08/09/2017	02:00	55,464	Bristol	BL007918
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	13/09/2017	20:23	14/09/2017	16:58	56,063	Bristol	BL008003
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown	N/S headlight out, stretcher not release work carry out job bl008004
-----------	--

Unplanned Repair	13/09/2017	21:12	14/09/2017	16:56	56,067	Bristol	BL008004
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

34 Lights Bulb Replacement	new dip bulb
87 Stretcher	stretcher stuck in floor holder (remove plate on floor clean lub and refit)

RE-ISSUE INSPECTION	19/10/2017	08:00	19/10/2017	11:25	58,865	Bristol	BL008463
----------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Re-Issue Inspection

SAFETY INSPECTION	19/10/2017	12:47	20/10/2017	06:38	58,865	Bristol	BL008473
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels	clean and paint wheels
18 Wheels Check Torques	
Safety Inspection	
92 - C Service	
Service C	

Breakdown	01/11/2017	10:44	01/11/2017	11:32	60,011	Bristol	BL008615
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown side door not opening from inside adjust cables

Vehicle Deep Clean **29/11/2017** **04:10** **29/11/2017** **11:00** **62,457** **Bristol** **BL008900**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **30/11/2017** **06:38** **01/12/2017** **12:57** **62,457** **Bristol** **BL008913**

02 Cab Ass Fire Extinguisher Fire extinguishers out of date
02 Windscreen Top up washers
16 Suspension 1 Replace osrear front susspension buffer
18 Wheels Check Torques
44 Add Ad Blue Top up ad blue
55 Tail Lift Resecure both tail lift rails
71 Body Exterior 1 Replace osr bottom corner and reflector
85 Body Interior 1 Repair cupbord inside side door wont close
85 Body Interior 2 Fit bolts to holes in saloon wall
89 Seats Securing pin loos for front attendants seat repair
Camera Installation Resecure rear camera
Safety Inspection Carry out safety inspection
Annual Air Con Service Annual Air Condition Service
Tail Lift Inspection Carry out tail lift inspection
Annual Heater Service Annual Heater Service

Unplanned Repair **02/01/2018** **18:42** **02/01/2018** **22:21** **65,112** **Bristol** **BL009282**

45 Engine 1 EML - carry out diagnostics and regen

Vehicle Deep Clean **09/01/2018** **07:20** **09/01/2018** **13:19** **65,622** **Bristol** **BL009356**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **09/01/2018** **13:06** **09/01/2018** **15:10** **65,623** **Bristol** **BL009359**

18 Wheels Check Torques
Safety Inspection

Unplanned Repair	24/01/2018	16:59	24/01/2018	21:42	67,072	Bristol	BL009564
Breakdown	orange EML&slight judder (NFF at time of tests)						
Unplanned Repair	14/02/2018	20:00	15/02/2018	08:22	68,818	Bristol	BL009827
34 Lights Bulb Replacement	osf bulb dip beam						
Vehicle Deep Clean	21/02/2018	23:00	22/02/2018	18:30	69,448	Bristol	BL009901
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	22/02/2018	07:04	22/02/2018	13:54	69,448	Bristol	BL009903
02 Cab Ass Fire Extinguisher	replace both fire extinguishers						
02 Windscreen	top up screenwash						
18 Wheels Check Torques							
34 Emergency Lights	N/S/R top blue lens cracked - none in stock						
45 Engine Oil Top Up	top up engine oil						
55 Tail Lift	rails siezed and loose - remove free off tighten and refit						
85 Body Interior 1	inverter socket lights dropped out - remove and refit						
86 Doors	O/S front door stay loose - tighten						
86 Doors Rear	replace rear door stay block						
Safety Inspection	Carry out safety inspection						
85 Body Int Alcohol Gel Dispen							
Tail Lift Inspection	Carry out tail lift inspection						
UB Fire Suppression Service							
Breakdown	24/02/2018	17:53	26/02/2018	10:24	69,563	Bristol	BL009948
34 Emergency Lights	repaired roof fixings and replaced damaged os rear top blue light						
44 Add Ad Blue	topped up adblue						
Breakdown	hit tree,knocked blues off roof						

Awaiting Parts

Breakdown	17/03/2018	12:23	19/03/2018	07:00	71,369	Bristol	BL010205
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown	offside rwear tyre puncture						
-----------	-----------------------------	--	--	--	--	--	--

Vehicle Deep Clean	03/04/2018	01:00	03/04/2018	05:06	72,758	Bristol	BL010386
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	03/04/2018	13:59	05/04/2018	12:44	72,758	Bristol	BL010392
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windows/Glass	top up screenwash						
13 Brake Pads	front pads						
17 Tyres Replace	nsr tyres replaced						
18 Wheels Check Torques							
34 Emergency Lights	N/S/R top blue lens cracked - none in stock						
45 Engine Ad Blue							
45 Engine Oil Top Up							
71 Body External Steps	Body Exterior sidestep not deploying						
Safety Inspection							
Wheel Hub Flanges Replaceme							
Fit Poster Holder	Fit Poster Holder						

SAFETY INSPECTION	16/05/2018	20:35	18/05/2018	10:11	75,455	Bristol	BL010874
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

18 Wheels Check Torques							
34 Lights	Drivers side rear marker light not working - Replaced side marker						
34 Lights Bulb Replacement	Offside front side light not working - Replaced bulb						
Safety Inspection	Carried out safety inspection						
Tail Lift Inspection							
Vehicle Deep Clean	Vehicle Deep Clean						
Handbrake Cable Replacement	Replaced rear handbrake cables						
Travel Time							
MOT							
93 - D Service							
Service D							
Tail Lift Annual Service	Statutory Inspection and Weight Test						

Breakdown	22/05/2018	01:35	22/05/2018	11:23	75,455	Bristol	BL010928
Breakdown	Headlight out						
Unplanned Repair	12/06/2018	12:24	15/06/2018	08:05	77,559	Bristol	BL011160
55 Ramp 89 Seats	Ramp/Lift/Tail Hoist ramp bent and black bars badly damaged (repair) rear seat pin stuck refit new pin and seat lock stuck remove clean refit						
Unplanned Repair	18/06/2018	12:29	18/06/2018	19:37	77,888	Bristol	BL011215
89 Seats	Arm rest come off rear swivel seat						
SAFETY INSPECTION	27/06/2018	08:04	27/06/2018	14:18	78,422	Bristol	BL011327
17 Tyres Replace 17 Tyres Tracking 18 Wheels Check Torques 18 Wheels Removal 55 Ramp 71 Body External W&T Repair 86 Doors Rear 86 Sliding Door 87a - Medical Equipment Repair Safety Inspection	new tyres x2 clean hubs n\s yellow bar damaged repair and refit rear body damaged and broken off (cut and drill and repair) scoop holder on door damaged drill and refit inside handle stiff stip down adjust and lub up refit trims storage cupboard trim by rear door damaged repair						
Vehicle Deep Clean	27/06/2018	09:52	27/06/2018	21:00	78,422	Bristol	BL011329
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	06/08/2018	20:00	07/08/2018	00:41	81,744	Bristol	BL011756
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	07/08/2018	11:19	07/08/2018	14:12	81,744	Bristol	BL011763
02 Windows/Glass		top up washers					
13 Brakes 1		replace rear brake pads					
16 Suspension 1		replace rear arb bushes					
18 Wheels Check Torques							
44 Fuel System 1		fit fuel solo					
45 Engine Oil Top Up							
86 Doors		repair side door blind					
Safety Inspection							
UB Fire Suppression Service							
Tail Lift Inspection							
Wheel Hub Flanges Replacement		new flanges fitted 04/2018					
Unplanned Repair	27/08/2018	11:27	27/08/2018	11:29	83,710	Bristol	BL011954
02 Windows/Glass		top washers up					
45 Engine Oil Top Up							
Breakdown	17/09/2018	10:56	17/09/2018	11:35	85,657	Bristol	BL012169
17 Tyres Replace		renew n/s/r tyre					
Breakdown		N/S rear outer 205/75R16C					
Vehicle Deep Clean	20/09/2018	00:26	20/09/2018	05:28	85,854	Bristol	BL012207
Vehicle Deep Clean		Vehicle Deep Clean					
SAFETY INSPECTION	20/09/2018	07:00	21/09/2018	08:00	85,854	Bristol	BL012209
02 Windscreen		Topped Up Screenwash					
02 Windscreen Wipers		Replaced Both Broken Washer Jet Connectors					
18 Wheels Check Torques							
18 Wheels Removal		Cleaned Hubs And Flanges					
71 Body External Steps		Spray Suppression Flap Missing - Fitted New Flap					
Safety Inspection		Carried Out Safety Inspection					

Unplanned Repair	28/09/2018	10:00	28/09/2018	15:32	86,154	Bristol	BL012287
86 Doors 86 Sliding Door	Doors 2304 Sliding door sticking drill, tap and renew rollers						
Breakdown	05/10/2018	22:15	09/10/2018	10:06	86,554	Bristol	BL012365
99 Diagnostic Test Breakdown	Checked And Found Water Pump Failed/Leaking 2304 - total coolant loss						
SAFETY INSPECTION	30/10/2018	07:56	30/10/2018	13:16	88,173	Bristol	BL012644
18 Wheels Check Torques Safety Inspection Fit 3rd Helmet Restraint Sealing of stretcher clamp Annual Heater Service Annual Air Con Service Tail Lift Inspection	Fit 3rd Helmet Restraint in Cab Sealing of stretcher clamp Annual Heater Service Annual Air Condition Service						
Vehicle Deep Clean	31/10/2018	04:47	31/10/2018	12:15	88,174	Bristol	BL012650
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	10/11/2018	13:06	11/11/2018	18:00	88,728	Bristol	BL012742
45 Engine 1 Breakdown	caheck all batteries, brakes and egine - no fault found - road test - all ok 2304- smoking wont start						
Unplanned Repair	17/11/2018	11:30	17/11/2018	12:19	89,212	Bristol	BL012817
31 Battery Comms 99 Diagnostic Test	comms shutting down , checked charge rate , replaced faulty battery eml on intermitant , carried out test and reset						

SAFETY INSPECTION	06/12/2018	07:57	06/12/2018	13:11	90,565	Bristol	BL012998
18 Wheels Check Torques							
18 Wheels Removal	clean hubs						
86 Door Hinges	rear door mod						
Safety Inspection							
Vehicle Deep Clean	07/12/2018	08:38	07/12/2018	10:45	90,665	Bristol	BL013016
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	08/12/2018	09:54	08/12/2018	10:22	90,783	Bristol	BL013030
Breakdown	2304 - amber EML on dash						
Breakdown	04/01/2019	13:56	05/01/2019	13:19	93,673	Bristol	BL013297
44 Add Ad Blue	Topped Up Ad-Blue						
45 Engine 1	Alternator Faulty - Replaced - All Ok						
Breakdown	2304-emerg start then judders						
Breakdown	14/01/2019	07:26	14/01/2019	16:37	94,057	Bristol	BL013378
31 Battery Chassis	vehicle not shoredlined / replaced chassis battery / charged org battery all o						
33 Ignition System	renew key fob						
99 Diagnostic Test	carried out diagnostic test and cleared old codes						
Breakdown	Non start - Started withg EMG button - 2304						
Travel Time	travel time to soundwell stn and return to workshop						
Vehicle Deep Clean	21/01/2019	12:49	21/01/2019	12:51	94,366	Bristol	BL013444
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	21/01/2019	22:16	23/01/2019	14:04	94,366	Bristol	BL013448
02 Windows/Glass	top up washers						

13 Brakes 1	front discs and pads replaced
16 Suspension 1	rear leaf spring buffer replaced
17 Tyres Replace	x3 tyres replaced rear
18 Wheels Check Torques	
45 Engine Ad Blue	
55 Tail Lift	replace tilt switch and repair bridge plate
Safety Inspection	
92 - C Service	
Service C	
UB Fire Suppression Service	
Tail Lift Inspection	

SAFETY INSPECTION	06/03/2019	07:39	06/03/2019	15:04	97,360	Bristol	BL013870
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	replaced out of date extinguishers	
02 Windscreen	topped up screen wash	
02 Windscreen Wipers	replaced wiper kit	
17 Tyres Replace	replaced both front tyres	
18 Wheels Balance & Alignment	tracking check reqd next inspection	Lack of Labour
18 Wheels Check Torques		
18 Wheels Removal	cleaned all wheel hubs	
34 Lights	os side marker inop carried out repair to wiring harness	
55 Tail Lift	carried out repair to seized hand pump valves	
71 Body Exterior 1	damage to nsf wing / headlight removal reqd next inspection	Monitoring
86 Door Lock	stripped scoop door and replaced lock housing	
86 Door Seals	replaced os door seal	
Safety Inspection		

Vehicle Deep Clean	06/03/2019	16:00	06/03/2019	23:00	97,360	Bristol	BL013880
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	11/04/2019	11:35	11/04/2019	13:17	99,839	Bristol	BL014196
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown	2304 - Limp mode ?Adblue issue
-----------	--------------------------------

BREAKDOWN	11/04/2019	13:12	11/04/2019	13:16	99,843	Bristol	BL014198
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

45 Engine 1	EML On No LOP
-------------	---------------

99 Diagnostic Test Fault Code Read - Faults For Faulty EGR Valve - Replaced Valve And Gasket

Unplanned Repair 15/04/2019 15:12 15/04/2019 15:13 100,067 Bristol BL014231

17 Tyres Replace osr tyre replaced
18 Wheels Check Torques osr only

Vehicle Deep Clean 16/04/2019 16:00 16/04/2019 21:00 100,105 Bristol BL014243

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 17/04/2019 11:13 21/04/2019 13:15 100,105 Bristol BL014249

02 Windows/Glass
02 Windscreen Wipers
13 Brakes 1 top up brake fluid
17 Tyres Replace Replaced Both Front And One Nearside Rear Tyre
18 Wheels Check Torques
45 Engine Ad Blue
45 Engine Oil Top Up
Safety Inspection
Tail Lift Inspection
Travel Time
MOT
Handbrake Cable Replacement Replace rear handbrake cables all ok

Tail Lift 12M Service & Weight 23/04/2019 12:28 23/04/2019 12:34 100,105 Bristol BL014774

Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Vehicle Deep Clean 03/06/2019 23:34 03/06/2019 23:59 104,224 Bristol BL014667

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 04/06/2019 07:08 10/06/2019 08:21 104,224 Bristol BL014671

01 Air Conditioning 1 rear air con fan not working requires new fan

02 Windows/Glass	
13 Brakes 1	rear discs and pads
18 Wheels Check Torques	
43 Exhaust System 1	rear tail pipe corroded
45 Engine Ad Blue	
45 Engine Oil Top Up	
55 Tail Lift	new frame, bushes, oil tank - alfa
99 Diagnostic Test	nitro test front and rear aircon system
Safety Inspection	

SAFETY INSPECTION	11/07/2019	08:12	11/07/2019	11:19	106,595	Bristol	BL015021
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen	Topped Up Screenwash
18 Wheels Check Torques	Torqued All Wheel Nuts
18 Wheels Removal	Cleaned All Hubs And Flanges
34 Emergency Lights	Nearside Rear Top Corner Blue Lens Damaged - Replaced Lens
34 Lighting System	Right Headlight Out - Old Defect
34 Lights	Offside Front Top White Running Light Not Working - Replaced Light
45 Engine 1	Amber EML On No LOP - Old Defect
45 Engine 2	Engine EML On - Duplicated Defect
Safety Inspection	Carried Out Safety Inspection
Tail Lift Inspection	Carried Out Tail Lift Inspection
UB Fire Supp 12mts Service	Carried Out Service Of Fire Supression System

Vehicle Deep Clean	11/07/2019	14:00	11/07/2019	22:00	106,595	Bristol	BL015029
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	05/08/2019	14:38	06/08/2019	08:47	109,131	Bristol	BL015255
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

15 Steering 1	flush out pas fluid replace pump fit new fluid bleed system
---------------	---

Breakdown	06/08/2019	18:04	07/08/2019	08:29	109,165	Bristol	BL015267
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	cary chair track system missing
-----------	---------------------------------

Unplanned Repair	15/08/2019	11:56	15/08/2019	12:05	110,022	Bristol	BL015331
34 Lights	nsf indicator lamp replaced all ok						
Vehicle Deep Clean	22/08/2019	14:10	22/08/2019	23:59	110,490	Bristol	BL015389
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/08/2019	11:11	23/08/2019	11:15	110,490	Bristol	BL015393
02 Windows/Glass							
18 Wheels Check Torques							
87 - Stretchers/Chairs/Boards							
Safety Inspection							
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Vehicle Deep Clean	30/09/2019	18:50	30/09/2019	23:59	113,594	Bristol	BL015690
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	03/10/2019	07:05	03/10/2019	11:31	113,594	Bristol	BL015715
13 Brakes 1	replace front brake pads and discs						
17 Tyres Replace	replace both front tyres						
18 Wheels	clean and paint wheels						
18 Wheels Check Torques							
18 Wheels Removal	clean corrosion from flanges						
45 Engine Ad Blue	top up ad blue						
86 Doors	replace sliding door bearings						
Safety Inspection							
Tail Lift Inspection							
Wash Vehicle	04/11/2019	10:45	04/11/2019	10:47	116,523	Bristol	BL015998
Wash Vehicle							

Breakdown	10/11/2019	06:13	10/11/2019	09:00	117,080	Bristol	BL016072
Breakdown	N/S outer tyre puncture						
Vehicle Deep Clean	14/11/2019	03:10	14/11/2019	13:49	117,529	Bristol	BL016125
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	09/12/2019	10:17	10/12/2019	12:44	119,712	Bristol	BL016396
Breakdown	back door wont close&red air bag light						
SAFETY INSPECTION	10/12/2019	12:35	13/12/2019	12:44	119,716	Bristol	BL016416
17 Tyres Replace	replace both front tyres						
18 Wheels Check Torques							
18 Wheels Removal	clean corrosion from flanges						
55 Tail Lift	straighten out bent h/rails tighten up sliders and lube						
86 Doors Rear	adjust rear door cables,replace top door striker						
89 Seats	tighten up saloon seat swivel pins and lube						
Safety Inspection							
Vehicle Deep Clean	10/12/2019	16:00	10/12/2019	22:00	119,716	Bristol	BL016419
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/12/2019	21:44	27/12/2019	10:50	119,800	Bristol	BL016556
Breakdown	Scratches drivers side.car hit						
Breakdown	29/12/2019	23:38	30/12/2019	08:28	120,898	Bristol	BL016577
Breakdown	2304 F N/S headlight out						

Unplanned Repair	04/01/2020	13:16	04/01/2020	14:13	121,322	Bristol	BL016624
71 Body External Steps	side step not retracting						
Breakdown	11/01/2020	10:43	11/01/2020	11:32	121,780	Bristol	BL016696
02 Windscreen Wipers	repair washer pipe						
45 Engine Ad Blue	top up ad blue						
Breakdown	Coolant level indicator on						
Breakdown	28/01/2020	01:26	28/01/2020	12:28	123,155	Bristol	BL016911
Breakdown	heating at the back not working						
SAFETY INSPECTION	03/02/2020	11:52	07/02/2020	15:18	123,499	Bristol	BL016980
02 Windows/Glass	replace n/s window switch						
18 Wheels	clean corrosion from flanges						
18 Wheels Check Torques							
34 Lights	replace o/s and n/s front flasher bulbs						
44 Fuel System 1	fit fuel solo						
45 Engine 1	Other diesel fumes in the cab,injectors leaking						
71 Body External Steps	replace step bushes						
85 Body Interior 1	replace saloon seat adjusting pin						
86 Doors	replace sliding top door magnet						
87a - Medical Equipment Repair	Med Equip & Devices catch broken on carry chair						
89 Seats	replace o/s and n/s cab seat covers						
Air Filter Change	Air Filter Change						
Pollen Filter Change	Pollen Filter Change						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Engine Change Oil & Filter							
Replace Handbrake Cables	Replace Handbrake Cables						

Vehicle Deep Clean	06/02/2020	06:44	06/02/2020	06:45	123,499	Bristol	BL017008
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	17/02/2020	19:31	17/02/2020	22:00	124,242	Bristol	BL017131
Breakdown	offside headlight not working						
Breakdown	27/02/2020	16:19	28/02/2020	20:26	124,242	Bristol	BL017238
45 Engine 1 Breakdown	Cleaned down engine, found oil filter housing seal split,renewed filter and seal oil leak from 00:00						
Unplanned Repair	02/03/2020	10:19	02/03/2020	10:26	124,585	Bristol	BL017259
02 Cab Assembly 1 45 Engine 1 55 Tail Lift	replaced key fob battery EML light on read codes reg DPF and cleaned fuel heater conector Repair to tail lift corner cap						
Breakdown	12/03/2020	11:18	14/03/2020	08:40	125,530	Bristol	BL017345
15 Steering 1 34 Lights Bulb Replacement Breakdown	Belts shredded, cleaned up pulleys, replaced belts and tensioner Replaced offside DRL Power steering failure						
SAFETY INSPECTION	19/03/2020	08:33	19/03/2020	08:38	126,003	Bristol	BL017403
18 Wheels Check Torques Safety Inspection							
SAFETY INSPECTION	19/03/2020	08:38	21/03/2020	11:24	126,003	Bristol	BL017404
02 Windscreen	Top Up Screenwash						

13 Brake Pads	Replace Rear Brake Pads
16 Suspension 1	Front Lower Arms Ball Joints Worn
16 Suspension 2	Front Shock Absorbers Worn
18 Wheels Check Torques	Torque All Wheel Nuts
18 Wheels Removal	Clean All Hubs And Flanges
34 Emergency Lights	Offside Rear Top Corner Blue Light Damaged
55 Tail Lift	Carry Out Repairs To Tail Lift Hand Rail And Buffers
71 Body Exterior 1	Both Rear Lower Corner Caps Damaged
71 Body Exterior 2	Nearside Front Lower Corner Cap Damaged
71 Body Exterior 3	Nearside Rear Wheel Arch Trim Damaged
85 Body Interior 1	Replace 1 Faulty Cab Hand Torch
86 Doors Rear	Dent To Offside Rear Door
Safety Inspection	Carry Out Safety Inspection
Tail Lift Inspection	Carry Out Tail Lift Inspection
MOT	Carry Out MOT Test
Brakes Replace Brake Fluid	Carry Out Brake Fluid Change
Tail Lift 12M Service & Weight	Carry Out Tail Lift 12M Service & Weight Test
Axle Oil Change	Carry Out Axle Oil Change

Vehicle Deep Clean	19/03/2020	11:00	23/03/2020	11:32	126,003	Bristol	BL017406
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

02 Pipeline Annual Inspection	02/04/2020	11:25	02/04/2020	11:33	126,475	MDT Bristol	TB000764
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Pipeline Annual Inspection	Repaired Splint Pipeline - Pressure Tested - Passed
Medical Devices Repair	New 90° O2 Probes £73.92 + Va) ,Ferrules (£1.20 + Vat), Shrink (£0.20 + Vat)

Breakdown	06/04/2020	04:28	06/04/2020	09:50	126,500	Bristol	BL017647
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	orange EML & Limp mode
-----------	------------------------

Breakdown	16/04/2020	10:04	16/04/2020	13:08	126,500	Bristol	BL017797
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights	replace bulb
Breakdown	front left indicator not working

Vehicle Deep Clean	25/04/2020	07:15	25/04/2020	13:15	127,928	Bristol	BL017904
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/04/2020	11:39	28/04/2020	09:18	127,928	Bristol	BL017909
18 Wheels Check Torques							
52 Electrical Aux	Replaced tail lift mercury switch						
55 Tail Lift	Stripped and straightened hand rails						
71 Body Exterior 1	Replaced front number plate						
86 Sliding Door	Adjusted catches and magnets						
Safety Inspection							
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
ACCIDENT	30/04/2020	12:46	06/05/2020	15:37	128,136	Bristol	BL017964
Breakdown	O/S side window Broken						
SAFETY INSPECTION	08/06/2020	07:51	08/06/2020	14:15	130,557	Bristol	BL018320
02 Cab Ass Fire Extinguisher	Replaced Cab Fire Extinguisher						
02 Windscreen	Topped Up Screenwash						
11 Axle Rear	Rear Half Shafts Leaking - Stripped, Cleaned And Re-sealed						
18 Wheels Check Torques	Torqued All Wheel Nuts						
18 Wheels Removal	Cleaned All Hubs And Flanges						
44 Add Ad Blue	Topped Up Ad-Blue						
Safety Inspection	Carried Out Safety Inspection						
Tail Lift Inspection	Carried Out Tail Lift Inspection						
UB Fire Supp 12mts Service	Carried Out Service Of Fire Supression System						
Vehicle Deep Clean	08/06/2020	14:38	08/06/2020	14:39	130,557	Bristol	BL018324
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	12/06/2020	07:58	12/06/2020	08:02	130,877	Bristol	BL018383
02 Mirrors	Mirrors near side wing mirror lens missing,replace with new glass						

ACCIDENT	13/06/2020	18:18	15/06/2020	08:06	131,124	Bristol	BL018394
Breakdown	ramp run over Metal plate squashed.alarms deployed						
ACCIDENT	13/06/2020	18:20	14/06/2020	11:47	131,124	Bristol	BL018395
Breakdown	number plate cracked						
Breakdown	14/06/2020	12:32	16/06/2020	12:54	131,124	Bristol	BL018399
55 Tail Lift Breakdown	repair bracket replace buffer and stop sensor Tail Lift Not Working						
Breakdown	14/06/2020	12:34	17/06/2020	14:59	131,124	Bristol	BL018400
Breakdown	Front Number plate come off						
Breakdown	23/06/2020	15:35	01/07/2020	12:29	131,669	Bristol	BL018482
01 Air Conditioning 1 41 Turbo 45 Engine 1 99 Diagnostic Test Breakdown Engine Change Oil & Filter Air Filter Change	ebaspacher pump needs replacing leaking parts to be ordered RENEW TURBO intercooler needs replacing parts to be ordered check for loss of power and noise found turbo failed Loss Of power Air Filter Change						
BREAKDOWN	08/07/2020	12:44	08/07/2020	13:15	132,169	Bristol	BL018609
45 Engine 1 99 Diagnostic Test	Engine warning Light On Carried Out Fault Code Read - Cleared Codes						
SAFETY INSPECTION	21/07/2020	15:55	21/07/2020	16:01	133,296	Bristol	BL018747

02 Windows/Glass
 17 Tyres Replace replace x6 tyres
 18 Wheels Check Torques
 55 Tail Lift replace tail lift arm
 87 - Stretchers/Chairs/Boards check equipment
 87 Stretcher repair stretcher clamp all ok
 Safety Inspection
 Replace Vehicle Fuel Card Replace Vehicle Fuel Card

Vehicle Deep Clean 21/07/2020 20:30 21/07/2020 23:59 133,296 Bristol BL018749

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean 02/09/2020 09:45 02/09/2020 15:38 136,918 Bristol BL019174

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 03/09/2020 11:41 03/09/2020 15:59 136,920 Bristol BL019188

18 Wheels Check Torques
 85 Body Interior 1 Replaced both front window switches
 85 Body Interior 2 Stripped genisys main module and replaced with donor unit for speaker issue
 Safety Inspection
 UB Fire Supp 6mts Service UB Fire Supp 6mts Service
 UB Fire Suppression DischargeUnder Bonnet Fire Suppression 5 Year Discharge Test
 Tail Lift Inspection

Breakdown 20/09/2020 01:31 25/09/2020 19:39 138,337 Bristol BL019361

02 Windows/Glass interior window missing parts on order was Awaiting Parts
 85 Body Interior 1 Fitted new saloon sliding window
 Breakdown window between saloon & cab broken

Breakdown 30/09/2020 11:38 02/10/2020 09:40 138,428 Bristol BL019480

02 Windscreen Wipers Replaced wiper switch
 99 Diagnostic Test Tested wiper relays and motor working ok

Breakdown windscreen wipers are not working

Breakdown 11/10/2020 16:30 16/10/2020 08:09 139,955 Bristol BL019618

02 Mirrors Replace nearside mirror outer cover and glass
13 Brake Pads Replace front pads
13 Brakes 1 Replaced rear disc and pads and handbrake shoes and o/s/r caliper
16 Suspension 1 Replace rear anti roll bar bushes
16 Suspension 2 Replace rear spring buffers
27 Transmission Automatic Replace front prop bush
34 Lights Replace offside rear marker light and nearside rear fog light
34 Lights Bulb Replacement Replace interior light bulb
43 Exhaust System 1 Replace DPF defferans sensor, fuel pressure sensor and o2 sensor
43 Exhaust System 2 Regen DPF after putting in cleaner
45 Engine Oil Top Up
55 Tail Lift Replace bridge plate round buffers and adjust both hand rails
56 Comms Equipment Fix n/s/r mic
71 Body Exterior 1 Replace bumper tread plate
85 Body Interior 1 Replace side door bag strap
86 Sliding Door Adjust top magnet
99 Diagnostic Test Code read faults found with fuel pressuer sensor,o2 sensor and dpf sensor
Breakdown EML on
Pollen Filter Change Pollen Filter Change
Road Test
18 Wheels Check Torques
Safety Inspection

Vehicle Deep Clean 14/10/2020 13:53 15/10/2020 15:42 139,355 Bristol BL019666

Vehicle Deep Clean Vehicle Deep Clean

O2 Pipeline Annual Inspection 13/10/2020 14:42 13/10/2020 14:44 139,355 MDT Bristol TB001539

02 Pipeline Annual Inspection Annual Inspection and Pressure Test
Medical Devices Repair SKTU001 O2 port service kit (£8.07 + VAT)

Vehicle Deep Clean 25/11/2020 04:15 25/11/2020 10:09 143,019 Bristol BL020122

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	25/11/2020	14:30	25/11/2020	21:30	143,019	Bristol	BL020127
02 Cab Assembly 1	replaced brake pedal rubber and repaired centre console lock						
02 Windscreen	topped up screen wash						
02 Windscreen Wipers	replaced wiper kit / fitted arms correctly						
15 Steering 1	replaced worn steering wheel						
18 Wheels Check Torques							
18 Wheels Removal	cleaned wheel hubs						
44 Add Ad Blue	topped up adblue						
45 Engine Oil Top Up	topped up engine oil						
85 Body Interior 1	replaced oxy cupboard door lock assy						
89 Seats	replaced saloon seat arm rest						
Safety Inspection							
Tail Lift Inspection	carried out inspection / repaired hand rail and replaced tilt switch						
Breakdown	04/12/2020	05:43	04/12/2020	08:04	143,612	Bristol	BL020231
Breakdown	Side Door Handle Stuck Open - Vehicle In Use						
Breakdown	02/01/2021	16:24	03/01/2021	09:12	146,068	Bristol	BL020531
Breakdown	side step not deploying						
BREAKDOWN	04/01/2021	13:56	04/01/2021	13:59	146,213	Bristol	BL020549
71 Body External Steps	Side Step Not Deploy - Replace Gas Strutt On Side Step						
Breakdown	05/01/2021	17:31	06/01/2021	06:53	146,300	Bristol	BL020564
Breakdown	Headlight Out						
Unplanned Repair	06/01/2021	12:15	06/01/2021	12:30	146,306	Bristol	BL020573
34 Lights Bulb Replacement	replaced ns headlight bulb						
71 Body External Steps	Body Exterior Side step not deploying / old defect						
86 Sliding Door	Body Exterior Side door wont open from Outside / old defect						

87 Chairs	Medical Devices carry chair tracks missing / old defect						
Vehicle Deep Clean	07/01/2021	02:00	07/01/2021	10:36	146,340	Bristol	BL020581
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	07/01/2021	12:30	08/01/2021	10:57	146,341	Bristol	BL020586
02 Mirrors	repair o/s mirror covers						
02 Windows/Glass	interior window missing parts on order was						
18 Wheels Check Torques							
34 Lights	front day time running lights n/w						
34 Lights Bulb Replacement	replace o/s/f side light bulb						
45 Engine Ad Blue	top up ad blue						
45 Engine Oil Top Up	top up engine oil						
85 Body Interior 1	replace equipment strap						
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
Annual Heater Service	Annual Heater Service						
Annual Air Con Service	Annual Air Condition Service						
Tail Lift Inspection	repair bent hand rails						
Breakdown	10/01/2021	19:17	11/01/2021	06:41	146,500	Bristol	BL020618
Breakdown	Amber EML						
Breakdown	28/01/2021	05:46	29/01/2021	14:07	148,835	Bristol	BL020774
13 Brakes 1	renew front discs and pads						
15 Steering 1	renew steering pipe						
17 Tyres Replace	x 1						
31 Battery Chassis	renew						
34 Lighting System	renew marker light						
44 Fuel System 1	renew fuel rail pressure sensor						
45 Engine 1	diagnostic test						
45 Engine 2	renew chain tensioner						
45 Engine 3	renew engine mounts						
86 Door handle	replace straps						
Breakdown	Orange EML on & sounds rough						

Unplanned Repair	01/02/2021	06:45	01/02/2021	11:01	148,944	Bristol	BL020830
01 Heating 1	saloon heater not working / carried out diag test / stripped and repaired all ok						
Breakdown	10/02/2021	14:27	10/02/2021	15:12	150,252	Bristol	BL020941
99 Diagnostic Test Breakdown	Carried out diagnostic test, delet fault codes, ordered fuel pressure sensor EML amber intermittent fault						
Vehicle Deep Clean	15/02/2021	20:15	16/02/2021	10:47	150,619	Bristol	BL020999
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	16/02/2021	10:19	19/02/2021	18:00	150,619	Bristol	BL021006
01 Air Conditioning 1	Regas cab a/c						
02 Windscreen Wipers	Replace washer to arm clip						
15 Steering 1	Replaced steering colum and shaft						
16 Suspension 1	Replaced rear spring buffer						
17 Tyres Replace	Replaced all 4 rear tyres						
17 Tyres Tracking	Rest tracking						
18 Wheels Check Torques							
24 Driveshaft 1	Replaced prop center bearing						
42 Coolant System	Replaced water pump and radiator						
44 Fuel System 1	Replace fuel presure sensor and fuel flap buffers						
44 Fuel System 2	replace fuel pump						
45 Engine 1	Replaced fan bearing housing, 3 pulleys, tensioner, alt pulley and 2 belts						
45 Engine 2	Replaced nearside injector seals front and middle and brake vac pump						
55 Tail Lift	Replaced tilt switch and repair offside hand rail						
71 Body Exterior 1	Replaced reversing camera mounting brackets						
85 Body Interior 1	Replace offside sun visor And Paper clip						
85 Body Interior 2	Replace nearside cab touch and repair saloon rear cupboard						
86 Doors Rear	Replaced rear offside door stay block						
86 Sliding Door	Replaced top catch cover						
87 Chairs	Replaced leg steap and replaced pro stair strap set						
89 Seats	Replaced rear saloon seat base						

Pollen Filter Change	Pollen Filter Change
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables Done last service
Annual Heater Service	Annual Heater Service Done last service
Annual Air Con Service	Annual Air Condition Service Done last service

Breakdown	25/02/2021	18:17	26/02/2021	13:50	151,385	Bristol	BL021093
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	MDT keeps freezing/crushing
-----------	-----------------------------

Unplanned Repair	02/03/2021	06:51	02/03/2021	07:07	151,692	Bristol	BL021120
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Replaced offside head light bulb
42 Coolant System	Topped up level

Vehicle Deep Clean	31/03/2021	08:16	31/03/2021	18:30	154,633	Bristol	BL021402
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

UB Fire Supp 6mts Service	31/03/2021	11:39	02/04/2021	06:06	154,633	Bristol	BL021403
----------------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	washer valve replaced
34 Lights	remove bumper and fit new headlight replace main plug and pins
56 Comms Equipment	Radio & Comm System Terrafix keeps freezing
71 Body Exterior 1	fit new front number plate
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
18 Wheels Check Torques	
Safety Inspection	
MOT	
Engine Change Oil & Filter	
Tail Lift Inspection	
Fuel Filter Change	Change Fuel Filter
Pollen Filter Change	Pollen Filter Change
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Air Filter Change	Air Filter Change
Brakes Replace Brake Fluid	
Axle Oil Change	Axle Oil Change

Breakdown	14/04/2021	13:16	15/04/2021	06:37	156,124	Bristol	BL021537
71 Body External Steps Breakdown	Repaired step wiring Side step stuck out						
BREAKDOWN	20/04/2021	10:55	20/04/2021	14:28	156,420	Bristol	BL021595
34 Lighting System	Carry Out Repairs And Replace Nearside Front Orange Marker Light Offside Side Indicator Knocked Off - Replace Missing Part Replace Damaged Nearside Lower Corner Cap Side Step Not Retracting						
34 Lights							
71 Body Exterior 1							
71 Body External Steps							
Unplanned Repair	24/04/2021	09:42	24/04/2021	09:46	156,793	Bristol	BL021638
31 Charging System	STRECHER CHARGER NOT CHARGING replaced charger						
Unplanned Repair	04/05/2021	20:40	04/05/2021	20:41	157,784	Bristol	BL021762
86 Door handle	Body Exterior side door will not open from outside						
Breakdown	16/05/2021	14:16	17/05/2021	15:52	158,693	Bristol	BL021916
13 Calipers	Cleaned and greased nearside caliper sliders Replaced offside track rod and end , nearside track rod end Replaced nearside spring eye bush and replace offside rear front buffer Replaced offside rear otter tyre Reset after steering work Replace exsanstion tank and cap Refit sky light seal Center consall botten and lock replaced and tool box cover Rewire compte sliding door read fault codes regen dpf cleared code Amber EML on dash Checked CCTV all ok						
15 Steering 1							
16 Suspension 1							
17 Tyres Replace							
17 Tyres Tracking							
42 Coolant System							
71 Body Exterior 1							
85 Body Interior 1							
86 Sliding Door							
99 Diagnostic Test							
Breakdown							
Install Saloon CCTV Camera							

Pollen Filter Change 18 Wheels Check Torques Safety Inspection	Pollen Filter Change						
Vehicle Deep Clean	18/05/2021	16:00	18/05/2021	22:00	158,696	Bristol	BL021944
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	12/06/2021	14:43	14/06/2021	20:53	161,171	Bristol	BL022225
02 Windscreen Wipers 55 Tail Lift 71 Body External Steps 86 Sliding Door UB Fire Supp 12mts Service 18 Wheels Check Torques Safety Inspection	Replaced Stripped and re-built arms side step damaged / repaired all ok Adjusted top magnet Service of fire suppression system						
Vehicle Deep Clean	23/06/2021	10:37	23/06/2021	10:39	161,171	Bristol	BL022474
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	28/06/2021	07:30	28/06/2021	08:21	162,236	Bristol	BL022380
71 Body External Steps	side step not coming out fully / repaired step frame and lubed						
Unplanned Repair	29/06/2021	10:41	29/06/2021	10:43	162,334	Bristol	BL022390
34 Lights Bulb Replacement	Nearside DRL bulb						
Breakdown	02/07/2021	10:56	02/07/2021	12:58	162,538	Bristol	BL022415
99 Diagnostic Test Breakdown Road Test	Carried out diag, cleared old fault codes and reset parameters. EML and Loss of power Found gearbox slightly jerky, possible replacement in future						

Vehicle Deep Clean	04/08/2021	18:00	04/08/2021	23:45	165,357	Bristol	BL022912
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	05/08/2021	07:17	05/08/2021	21:53	165,357	Bristol	BL022914
02 Windows/Glass	renew n/s window switch						
02 Windscreen	top up washer fluid						
13 Brake Pads	renew rear pads						
16 Suspension 1	renew raer anti roll bar bushes						
16 Suspension 2	renew rear spring pads						
18 Wheels Check Torques							
34 Lighting System	renew n/s scene bulb						
44 Add Ad Blue	top up						
45 Engine 1	test system found no engine related faults						
45 Engine Oil Top Up	top up						
99 Diagnostic Test	test cctv found unit faulty use non stock unit all ok						
Install Saloon CCTV Camera	install non stock unit						
Safety Inspection							
Tail Lift Inspection							
Defect Repair	26/08/2021	16:13	26/08/2021	16:15	167,240	Bristol	BL023124
42 Coolant System	bottom hose leaking,remove hose clean up seal rubber grease seal refit back						
Breakdown	06/09/2021	04:44	06/09/2021	14:58	167,978	Bristol	BL023223
17 Tyres Replace	replaced osr outer tyre						
Breakdown	2304 - flat osr outer						
Breakdown	14/09/2021	23:29	15/09/2021	14:30	168,594	Bristol	BL023333
Breakdown	battery charger in the cab not working STILL IN USE						

SAFETY INSPECTION	28/09/2021	07:00	28/09/2021	15:49	169,929	Bristol	BL023476
18 Wheels Check Torques							
44 Add Ad Blue							
45 Engine Oil Top Up							
55 Tail Lift							
71 Body Exterior 1							
85 Body Interior 1							
85 Body Interior 2							
87 Chairs							
87 Stretcher Harness Replaced							
Safety Inspection							
UB Fire Supp 6mts Service							
Vehicle Deep Clean	29/09/2021	06:45	29/09/2021	10:16	169,929	Bristol	BL023504
Vehicle Deep Clean							
Breakdown	02/10/2021	08:27	02/10/2021	11:37	170,500	Bristol	BL023553
Breakdown							
Breakdown	02/10/2021	08:29	02/10/2021	13:10	170,500	Bristol	BL023554
31 Battery Comms							
55 Tail Lift							
Breakdown							
SAFETY INSPECTION	27/10/2021	07:22	28/10/2021	07:29	171,636	Bristol	BL023828
02 Cab Ass Fire Extinguisher							
17 Tyres Replace							
18 Wheels Check Torques							
44 Add Ad Blue							
Med Dev/Equip Failure							
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	28/10/2021	16:15	29/10/2021	08:25	171,636	Bristol	BL023839
Vehicle Deep Clean							

Unplanned Repair	01/12/2021	12:56	06/12/2021	21:45	173,497	Bristol	BL024225
56 Comms Equipment	handheld radio charger not charging						
85 Body Interior 1	Replaced cctv hard drive						
99 Diagnostic Test	Carried out diag, found nox sensors faulty						
Vehicle Deep Clean	06/12/2021	10:12	07/12/2021	10:08	173,509	Bristol	BL024273
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/12/2021	14:27	06/12/2021	21:45	173,509	Bristol	BL024277
02 Windscreen	Top Up Screenwash						
13 Brakes 1	Replace Worn Front Brake Discs And Pads						
17 Tyres Replace	Replace 3 Worn Tyres						
18 Wheels Check Torques	Torque All Wheel Nuts						
18 Wheels Removal	Clean All Hubs For New Flanges						
34 Emergency Light System	Nearside Wing Blue LED Light Hanging Off						
44 Add Ad Blue	Top Up Ad Blue						
56 Radio	Hand Held Radio Battery Charger Not Working						
Safety Inspection	Carry Out Safety Inspection						
Wheel Hub Flanges Replaceme	Replace All Hub Flanges						
Breakdown	31/12/2021	17:49	01/01/2022	10:18	175,044	Bristol	BL024568
Breakdown	EML on-STILL IN USE						
Breakdown	23/01/2022	19:13	24/01/2022	08:42	176,497	Bristol	BL024807
Breakdown	heating at the back not working						
SAFETY INSPECTION	29/01/2022	06:51	01/02/2022	08:38	176,820	Bristol	BL024864
18 Wheels Check Torques							

42 Coolant System	Stayning around coolant tank replaced cap	Monitoring
45 Engine Oil Top Up		
55 Tail Lift	Lift ram leaking and offside hose split	
85 Body Interior 1	Replaced saloon fire exstingisher	
85 Body Interior 2	Repaired linin cupboard frame	
86 Doors Rear	Replaced offside door catch top plate	
87 Boards	Checked scoop ok	
87a - Medical Equipment Repair	Replaced EPCR battery 2	
Pollen Filter Change	Pollen Filter Change	
Safety Inspection	And admin service sheets	
Tail Lift Inspection		

Vehicle Deep Clean	30/01/2022	05:54	30/01/2022	14:00	176,820	Bristol	BL024872
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	03/02/2022	22:45	03/02/2022	22:48	176,921	Bristol	BL024930
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body External Steps	door wiring faulty
87 Stretcher	strecher clamp stripped and lubricated

Unplanned Repair	07/02/2022	14:15	07/02/2022	16:28	177,032	Bristol	BL024966
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

42 Coolant System	Stayning around coolant tank replaced cap / old defect
55 Tail Lift	Carried out repair to damaged tail lift plate / replaced tilt switch

Breakdown	10/03/2022	10:57	10/03/2022	17:22	179,270	Bristol	BL025328
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Side step wont deploy
-----------	-----------------------

Vehicle Deep Clean	10/03/2022	16:30	10/03/2022	21:00	179,281	Bristol	BL025339
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	11/03/2022	14:15	15/03/2022	14:23	179,281	Bristol	BL025347
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques

Safety Inspection	
Engine Change Oil & Filter	
MOT	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
55 Tail Lift	repaired handrail - top hat washer missing
17 Tyres Replace	replaced nsr tyre
44 Add Ad Blue	topped up adblue
71 Body External Steps	side step not fully coming out / repaired and lubed / checked operation
34 Lighting System	set up headlight alignment
18 Wheels Removal	cleaned wheel hubs
Road Test	carried out road test

02 Pipeline Annual Inspection	12/03/2022	13:04	12/03/2022	13:05	179,281	MDT Bristol	TB005673
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - Tested by Oxylitre - MS
-------------------------------	---

Breakdown	24/04/2022	09:42	25/04/2022	15:19	182,256	Bristol	BL025761
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	EML amber
45 Engine 1	carry out regen and reset values
99 Diagnostic Test	carry out diag
Road Test	

ACCIDENT	30/04/2022	15:54	02/05/2022	14:56	182,867	Bristol	BL025831
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Side step damaged
71 Body External Steps	remove step and and repair in vice re fit replace plastic trim

SAFETY INSPECTION	06/05/2022	13:50	06/05/2022	14:23	182,993	Bristol	BL025869
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
13 Brakes 1	Replaced pedal rubber
89 Seats	Replaced offside seat cover
34 Lights Bulb Replacement	offside headlamp
13 Brakes 2	Replaced rear discs and pads
85 Body Interior 1	Replaced floor mats

Tail Lift Inspection

Vehicle Deep Clean	08/05/2022	07:30	09/05/2022	14:04	182,994	Bristol	BL025879
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	18/05/2022	13:15	18/05/2022	13:19	183,374	Bristol	BL025979
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Replaced offside DRL bulb
----------------------------	---------------------------

SAFETY INSPECTION	07/06/2022	14:02	07/06/2022	14:33	185,031	Bristol	BL026161
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
34 Lights Bulb Replacement	Interior light
71 Body Exterior 1	Replaced osr lower body cap
55 Tail Lift	Replaced mercury switch
89 Seats	Replaced nearside seat cushion
44 Add Ad Blue	
45 Engine Oil Top Up	

Vehicle Deep Clean	07/06/2022	16:00	07/06/2022	16:01	185,032	Bristol	BL026165
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	07/06/2022	16:30	07/06/2022	22:00	185,032	Bristol	BL026166
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	27/07/2022	12:42	29/07/2022	12:01	187,898	Bristol	BL026712
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
31 Battery Comms	Comms Power Check tfx shutting down - tail lift needs engine on
31 Charging System Battery	Battery/Charging Sys load shedding -

Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
UB Fire Supp 12mts Service	Service of fire supression system						
Tail Lift Inspection							
02 Windscreen Wipers	replace w/blades						
34 Lights	replace blown n/s headlight bulb						
86 Doors	n/s window switch broken. waiting on stock						
Pollen Filter Change	Pollen Filter Change						
42 Radiator	replace leaking radiator						
55 Tail Lift	carry out repairs to sticking wheel chocks						
45 Engine Ad Blue	top up adblue						
45 Engine Oil Top Up	top up engine oil						
85 Body Interior 1	retro fit p .clips						
44 Fuel System 1	replace missing fuel solo						
71 Body Exterior 1	replace washer 3 way valve						
41 Turbo	replace damaged intercooler						
MRO Refresh	28/07/2022	16:30	28/07/2022	19:00	187,898	Bristol	BL026730
MRO Refresh							
Breakdown	09/08/2022	18:17	11/08/2022	07:16	188,764	Bristol	BL026854
Breakdown	LOST ALL COOLANT						
42 Coolant System	Replaced coolant hose (bottom radiator)						
Road Test							
Vehicle Deep Clean	25/08/2022	10:00	26/08/2022	11:56	189,765	Bristol	BL027006
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	29/08/2022	14:16	29/08/2022	14:23	189,765	Bristol	BL027026
18 Wheels Check Torques							
Safety Inspection							
02 Glass / Windows							
45 Engine 1	egr pipe gasket use non stock gasket						

45 Engine Oil Top Up	
17 Tyres Replace	nsr outer
86 Sliding Door	sliding door inner handle adjusted
86 Doors Rear	rear door stryker plate bent
13 Handbrake	adjust handbrake

SAFETY INSPECTION	30/09/2022	11:00	30/09/2022	14:21	192,116	Bristol	BL027299
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques		
Safety Inspection		
01 Air Conditioning 1	Rear air con inop, req's condensor and fan	Awaiting Parts
71 Body Exterior 1	Body Exterior Side step not deploying	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service	
Tail Lift Inspection		
02 Glass / Windows	Replaced offside switch	
55 Tail Lift	Stripped offside tail lift arm and replaced bolts	
71 Body External Steps	Straightened side step and lubed runners	
13 Brakes 1	Replaced front discs and pads	
85 Body Interior 1	Genisys speaker in saloon faulty - NO STOCK	

SAFETY INSPECTION	05/11/2022	11:38	07/11/2022	09:34	194,411	Bristol	BL027658
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
01 Air Conditioning 1	Rear air con inop, req's condensor and fan
71 Body Exterior 1	Body Exterior Scuff to n/s arch - plastic cover off door
02 Cab Assembly 1	Radiator/Cooling Sys FAN FOR DEMISTING WINDOWS NOT WORKING
18 Wheels Removal	clean corrosion from hubs and flanges
45 Engine Oil Top Up	top up engine oil
45 Engine Ad Blue	top up adblue
71 Body Exterior 2	replace shore line charging cover
89 Seats	replace n/s/p arm rest mounting brackets

Vehicle Deep Clean	09/11/2022	07:45	09/11/2022	07:46	194,457	Bristol	BL027699
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	09/11/2022	07:46	09/11/2022	13:34	194,457	Bristol	BL027700
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	29/11/2022	18:14	29/11/2022	18:15	195,765	Bristol	BL027910
34 Lights Bulb Replacement	Lighting System HEADLIGHT D/S OUT						
ACCIDENT	21/12/2022	17:41	15/02/2023	16:57	200,156	Bristol	BL028098
Breakdown	Dent on passenger side wheel arch						
SAFETY INSPECTION	24/01/2023	13:35	24/01/2023	13:36	198,000	Bristol	BL028528
18 Wheels Check Torques Safety Inspection Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	12/02/2023	07:44	12/02/2023	16:32	200,156	Bristol	BL028827
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/02/2023	09:01	14/02/2023	08:22	200,156	Bristol	BL028839
18 Wheels Check Torques Safety Inspection 71 Body Exterior 1 Tail Lift Inspection MOT Tail Lift 12M Service & Weight 01 Heating 1 17 Tyres Replace 45 Engine Oil Top Up	Body Exterior Scuffs on plastic in bottom all work done bodyshop Tail Lift 12M Service & Weight replace leaking fuel pipe and replace broken exhaust x4 tyres replaced						

02 Pipeline Annual Inspection	15/02/2023	07:42	15/02/2023	07:48	200,161	MDT Bristol	TB007511
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - Please see notes

Breakdown	21/02/2023	18:45	22/02/2023	10:22	200,549	Bristol	BL028995
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Non start
31 Battery Chassis	Replaced chassis battery
32 Starting System 1	Replaced starter motor

Defect Repair	22/02/2023	18:19	22/02/2023	18:21	200,567	Bristol	BL029056
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement Nearside side repeater

Unplanned Repair	09/03/2023	09:16	09/03/2023	09:18	201,098	Bristol	BL029324
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

55 Tail Lift Alfa to replace PCB - 151237246

SAFETY INSPECTION	14/03/2023	17:40	15/03/2023	07:38	201,897	Bristol	BL029430
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
71 Body External Steps	replaced step guide rollers
02 Cab Ass Fire Extinguisher	replaced cab access and rear fire extinguishers
Fit Scoop Mounting Brackets	replaced scoop mounting strap
16 Suspension 1	replaced lower arms
16 Suspension 2	replaced front shocks
24 Driveshaft 1	replaced rear prop shaft
87 Stretcher	replaced stretcher battery
87 Stretcher Harness Replaced	replaced stretcher harness
85 Body Interior 1	replaced 240v socket indicator lights
85 Body Interior 2	replaced rear microphone

Vehicle Deep Clean	15/03/2023	14:15	15/03/2023	23:59	201,900	Bristol	BL029454
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN	17/03/2023	17:53	18/03/2023	10:23	202,121	Bristol	BL029486
45 Engine 1 02 Windscreen Wipers 45 Engine 2 Road Test	replace injector seals x1 replace washer pipe and valve carry out regen reset values carry out road test						
Unplanned Repair	20/03/2023	07:39	20/03/2023	07:43	202,280	Bristol	BL029530
86 Door Lock	replace key fob battery						
ACCIDENT	29/03/2023	07:03	29/03/2023	08:49	202,845	Bristol	BL029675
Breakdown 71 Body External Steps	side step Step Not Deploying - Been Hit - Carry Out Adjustments And Lubricate						
Breakdown	02/04/2023	01:55	03/04/2023	13:33	203,198	Bristol	BL029788
Breakdown	EML/Loss of Power						
Breakdown	11/04/2023	01:20	11/04/2023	08:09	203,924	Bristol	BL029977
Breakdown 41 Air Intake 99 Diagnostic Test	EML / No loss of power Replaced air mass and air box Code read faults cleared codes						
SAFETY INSPECTION	21/04/2023	08:52	21/04/2023	16:57	204,769	Bristol	BL030207
18 Wheels Check Torques Safety Inspection Tail Lift Inspection Engine Change Oil & Filter Auto G/box Oil & Filter Change	Torque All Wheel Nuts Carry Out Safety Inspection Carry Out TailcLift Inspection Carry Out Engine Oil And Filter Change Carry Out Auto G/box Oil & Filter Change						

UB Fire Supp 6mts Service	Carry Out UB Fire Supp 6mts Service
Brake Fluid Change	Carry Out Brake Fluid Change
Air Filter Change	Carry Out Air Filter Change
Fuel Filter Change	Carry Out Fuel Filter Change
02 Windscreen	Top Up Screenwash And Replace One Way Valve
18 Wheels Removal	Clean All Hubs And Flanges
44 Add Ad Blue	Top Up Ad Blue
45 Engine 1	Engine Warning Light On
99 Diagnostic Test	Carry Out Fault Code Read - DPF Blocked - Carry Out DPF Re Gen
16 Suspension 1	Replace Rear Spring Bushes
02 Windscreen Wipers	Replace Front Wiper Blades

Vehicle Deep Clean	22/04/2023	14:00	22/04/2023	20:00	204,780	Bristol	BL030246
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	30/04/2023	13:19	31/05/2023	11:36	205,013	Bristol	BL030376
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	LOSS OF POWER STEERING AND LIMP MODE
99 Diagnostic Test	Check For Loss Of Power
45 Engine 1	Engine U/S
002 Major Unit Replace Eng	RYGOR WESTBURY

SAFETY INSPECTION	31/05/2023	07:30	31/05/2023	17:08	205,784	Bristol	BL030992
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
34 Lights	replace N/S/F marker light
55 Tail Lift	murcury switch needed for soft close - no stock
13 Brakes 1	replace rear brake pads
17 Tyres Replace	replace N/S/R inner tyre
44 Add Ad Blue	top up ad blue

Breakdown	08/06/2023	05:26	08/06/2023	08:02	206,642	Bristol	BL031094
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	oil light come on ,JOHN IN WESTON CHECKED DIP STICK AND STARTED OK
-----------	--

Unplanned Repair	11/06/2023	12:11	11/06/2023	12:23	206,642	Bristol	BL031152
54 Warn Dev/System	Emg Warning Devices bull horn - no audio pold defect						
45 Engine 1	Engine blown engine old defect						
02 Mirrors	Mirrors o/s wing mirror glass cracked old defect						
43 Exhaust System 1	Replaced DPF and pressure sensor						
Engine Change Oil & Filter							
45 Engine 2	Replaced oil filler neck						
99 Diagnostic Test	Read codes teach in sensors and DPF road tested ok						
Vehicle Deep Clean	11/06/2023	22:15	12/06/2023	04:21	206,790	Bristol	BL031167
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	05/08/2023	06:02	05/08/2023	13:22	211,708	Bristol	BL032237
Breakdown	Smell Of Fumes In Cab						
45 Engine 1	no fasult found with fumes possibly carrying out a regen						
SAFETY INSPECTION	05/08/2023	13:22	05/08/2023	13:56	211,721	Bristol	BL032238
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 12mts Service	Service of fire supression system						
Annual Heater Service	Annual Heater Service not carried out						
Annual Air Con Service	Annual Air Condition Service not carried out new engine and belts						
85 Body Interior 1	interior bulb replaced						
34 Lights Bulb Replacement	osf drl replaced						
85 Body Interior 2	interior button replaced						
55 Tail Lift	mercury switch replaced/handrail replaced						
85 Body Interior 3	replace bag strap						
89 Seats	adjust lock pins for rear swivel seats						
02 Glass / Windows	top up washers						
86 Doors Rear	replace led rear interior light unit						
13 Brakes 1	front pads replaced clean and grease seized sliders						
17 Tyres	replace x2 wheels are elongated						
86 Door Airbag	replace airbags under warranty recall						

Replace Vehicle Fuel Card	06/08/2023	16:40	06/08/2023	16:42	211,721	Bristol	BL032272
----------------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
---------------------------	---------------------------

Vehicle Deep Clean	08/08/2023	09:35	08/08/2023	14:00	211,871	Bristol	BL032309
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	13/08/2023	08:22	13/08/2023	08:28	212,227	Bristol	BL032402
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

99 Diagnostic Test 15 Steering 1	carried out diagnostics - ESP warning faulty steering angle sensor replaced clock spring
-------------------------------------	---

SAFETY INSPECTION	01/09/2023	07:59	01/09/2023	17:46	214,363	Bristol	BL032867
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques Safety Inspection 45 Engine 2 31 Battery Aux Pollen Filter Change Tail Lift Inspection 44 Add Ad Blue 01 Air Conditioning 1 34 Lights 55 Tail Lift 55 Ramp 85 Body Interior 1 54 Warn Dev/System 85 Body Interior 2 45 Engine 1	Engine ESP amber warning light -- OLD DEFECT Replaced both aux batteries Pollen Filter Change Replaced modified rear condensor and fan Replaced nsr indicator Repaired wiring and reaplced flasher module for platform lights Offside tail lift arm bearings collapsed, arm req'd -- NO STOCK Removed saloon safe Re-configured genisys speakers and repaired wiring Replaced 240 volt socket cover Tidied up engine bay wiring loom	Awaiting Parts
---	--	----------------

Vehicle Deep Clean	19/09/2023	14:00	19/09/2023	18:30	216,328	Bristol	BL033399
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	21/09/2023	07:07	21/09/2023	09:54	216,447	Bristol	BL033454
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	Replace Both Nearside Main And Dip Beam Bulbs As Blown						
----------------------------	--	--	--	--	--	--	--

Vehicle Deep Clean	15/10/2023	11:30	15/10/2023	15:40	219,082	Bristol	BL034275
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	16/10/2023	07:09	16/10/2023	16:28	219,082	Bristol	BL034303
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
55 Ramp	Offside tail lift arm bearings collapsed, arm req'd --replace as required						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
13 Brakes 1	replace front brake pads and discs						
45 Engine Oil Top Up	top up engine oil						
17 Tyres Replace	replace n/s/r outer tyre						
34 Lights	replace o/s/f fog light cover						
16 Suspension 1	replace both rear arb bushes						
45 Engine Ad Blue	top up adblue						

ACCIDENT	29/10/2023	06:53	22/11/2023	10:23	219,100	Bristol	BL034764
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Accident	Body Exterior O/S damage						
----------	--------------------------	--	--	--	--	--	--

SAFETY INSPECTION	22/11/2023	07:10	22/11/2023	13:49	219,328	Bristol	BL035567
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
86 Doors Rear	replace lower door seal						
86 Door Lock	free off sticking door lock cables and adjust						
13 Brakes 1	replace faukty telma contact box						

Vehicle Deep Clean	21/11/2023	10:50	21/11/2023	15:20	219,100	Bristol	BL035594
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Defect Repair	02/12/2023	07:48	02/12/2023	10:56	219,784	Bristol	BL035967
01 Heating 1	A/C System Saloon Blowing out cold air No fault found working ok						
Breakdown	06/12/2023	15:48	07/12/2023	10:00	220,328	Bristol	BL036097
Breakdown	RED WARNING ALTERNATOR					Monitoring	
Breakdown	06/12/2023	19:39	07/12/2023	18:26	220,328	Bristol	BL036104
Breakdown	RED WARNING ALTERNATOR						
31 Charging System	Replaced alternator						
99 Diagnostic Test	Ad-blue malfunction due to low voltage, carried out drive cycle						
43 Exhaust System 1	Carried out dpf re-gen						
Engine Change Oil & Filter							
Unplanned Repair	14/12/2023	11:20	14/12/2023	12:00	220,928	Bristol	BL037411
89 Seatbelts	Seatbelt warning light on						
99 Diagnostic Test	Carry out fault code read- no fault code stored						
Unplanned Repair	30/12/2023	07:23	30/12/2023	07:26	222,421	Bristol	BL036980
02 Mirrors	Mirrors N/S wing mirror come out replaced large glass						
33 Ignition System	Replaced key fob battery						
Vehicle Deep Clean	09/01/2024	14:30	09/01/2024	18:50	223,534	Bristol	BL037414
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	22/01/2024	09:17	22/01/2024	15:06	224,816	Bristol	BL037866
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques

Safety Inspection

17 Tyres Replace

replace o/s/r inner tyre

02 Mirrors

replace o/s mirror casings

85 Body Interior 1

replace missoing cuboard angle

MOT EXPIRES	23/01/2024	10:32	23/01/2024	12:23	224,848	Bristol	BL037908
--------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Tail Lift Inspection

MOT

17 Tyres Replace

Replace Punctured Offside Front Tyre

18 Wheels Check Torques

Offside Front Only

13 Brakes 1

Adjust Hand Brake

02 Pipeline Annual Inspection	23/01/2024	13:53	23/01/2024	13:56	224,880	MDT Bristol	TB009466
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Pipeline Annual Inspection Annual Inspection and Pressure Tested By SMC - Passed All Tests

Unplanned Repair	31/01/2024	09:52	31/01/2024	09:58	226,074	Bristol	BL038165
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

44 Add Ad Blue

Vehicle Deep Clean	12/02/2024	23:00	13/02/2024	01:30	227,491	Bristol	BL038634
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean

Vehicle Deep Clean

SAFETY INSPECTION	13/02/2024	15:42	14/02/2024	15:57	227,491	Bristol	BL038651
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques

Safety Inspection

34 Emergency Light System

Replaced bull horn switch

85 Body Interior 1

Replaced CCTV cabinet struts

55 Tail Lift

Refixed tail lift bumper bars

44 Add Ad Blue

10L

13 Brakes 2

Replaced rear discs and pads + unseized slider pins

17 Tyres

N/S/F

Unplanned Repair	23/03/2024	16:09	23/03/2024	16:53	232,584	Bristol	BL040019
86 Sliding Door	replace sliding door bearings						
Breakdown	26/03/2024	09:24	27/03/2024	16:48	232,599	Bristol	BL040093
Breakdown	AD BLUE SYSTEM MALFUNCTION						
99 Diagnostic Test	Carry Out Diagnostic Check - NOx Sensors Faulty						
43 Exhaust System 1	Replace Both Faulty NOx Sensors						
Road Test	Carry Out Extended Road Test						
SAFETY INSPECTION	27/03/2024	16:51	28/03/2024	11:17	232,599	Bristol	BL040156
18 Wheels Check Torques	Torque All Wheel Nuts						
Safety Inspection	Carry Out Safety Inspection						
02 Windscreen	Top Up Screenwash						
18 Wheels Removal	Clean All Hubs And Flanges						
85 Body Interior 1	Replace Saloon Fire Extinguisher						
85 Body Interior 2	Replace Roof Vent Cover						
55 Tail Lift	Carry Out Repair To Safety Rails						
34 Lights Bulb Replacement	Replace Blown Offside DRL Bulb						
Vehicle Deep Clean	28/03/2024	14:30	28/03/2024	18:00	233,005	Bristol	BL040211
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/05/2024	14:46	08/05/2024	18:14	237,363	Bristol	BL041563
18 Wheels Check Torques							
Safety Inspection							
86 Sliding Door	Doors Stiff side door OLD DEFECT						
71 Body Exterior 1	Refitted tail lift bumper bars						
Tail Lift Inspection	Cleaned and lubricated seized hand rails						
71 Body External Steps	Lubricated side step						
Vehicle Deep Clean	08/05/2024	11:15	08/05/2024	14:30	237,363	Bristol	BL041565

Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	19/06/2024	19:01	21/06/2024	13:32	241,804	Bristol	BL043024
Breakdown	Unable to get into gear						
27 Transmission Automatic	Replaced gear shift module						
Vehicle Deep Clean	26/06/2024	14:00	26/06/2024	17:00	242,261	Bristol	BL043274
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/06/2024	15:57	27/06/2024	18:21	242,262	Bristol	BL043275
18 Wheels Check Torques	Torque All Wheel Nuts - 180NM #2						
Safety Inspection	Carry Out Safety Inspection						
UB Fire Supp 6mts Service	Carry Out UB Fire Supp 6mts Service						
Tail Lift Inspection	Carry Out Tail Lift Inspection						
Replace Handbrake Cables	Replace Handbrake Cables						
Check and Fit P-Clips	Check For The Presence Of P-Clips And Fit If Not Present						
02 Windscreen	Top Up Screenwash						
18 Wheels Removal	Clean All Hubs And Flanges						
02 Glass / Windows	Replace Damaged Nearside Window Switch						
Breakdown	01/07/2024	17:01	01/07/2024	18:01	242,637	Bristol	BL043395
Breakdown	Low Oil Level						
45 Engine Oil Top Up							
Breakdown	13/07/2024	16:56	15/07/2024	08:40	244,055	Bristol	BL043776
Breakdown	back door not closing properly,repair broken lower door catch and adjust cables						

Vehicle Deep Clean	17/08/2024	16:00	17/08/2024	18:30	247,589	Bristol	BL044958
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	26/08/2024	13:44	26/08/2024	13:48	248,338	Bristol	BL045251
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights	Lighting System OS indicator by wind mirror not working - OLD DEFECT
56 Comms Power Failure	MDT Failure/Issue MDT not turning at all-need comms check - OLD DEFECT
86 Sliding Door	Rear door stay broken

Breakdown	08/09/2024	07:20	08/09/2024	09:31	249,717	Bristol	BL045720
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	front offside indicator not working
34 Lights Bulb Replacement	Nearside front indicator

SAFETY INSPECTION	11/09/2024	10:30	11/09/2024	17:14	250,120	Bristol	BL045877
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Engine Change Oil & Filter	
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
13 Brakes 1	replace worn out front brake pads
13 Brakes 2	replace sticking caliper sliders on o/s/f
17 Tyres Replace	replace punctured n/s/r inner tyre
Pollen Filter Change	Pollen Filter Change
87 Med Handling Equip Inspect	replace missing carry chair belt
87 Stretcher	replace both faulty stryker batteries

Vehicle Deep Clean	12/09/2024	10:10	12/09/2024	12:35	250,121	Bristol	BL045920
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	29/09/2024	08:37	29/09/2024	08:39	250,121	Bristol	BL046473
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body Exterior 1	Body Exterior scratches 1/4 length of side door OLD DEFECT
--------------------	--

86 Sliding Door	Replaced outter handle						
ACCIDENT	10/10/2024	14:25	10/10/2024	14:27	253,028	Bristol	BL046893
71 Body External Steps 02 Glass / Windows	Side step damaged, re-straightened Rectified poorly fitted osf window						
Breakdown	16/10/2024	15:30	16/10/2024	16:33	253,290	Bristol	BL047094
Breakdown	BATTERY FLAT NON STARTER						
SAFETY INSPECTION	24/10/2024	14:35	24/10/2024	17:54	254,117	Bristol	BL047389
18 Wheels Check Torques Safety Inspection Tail Lift Inspection Air Filter Change Fuel Filter Change 17 Tyres Replace	Air Filter Change Change Fuel Filter replace both rear o/s tyres and n/s/r outer below 3mm						
Vehicle Deep Clean	24/10/2024	08:15	25/10/2024	00:00	254,118	Bristol	BL047396
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	15/11/2024	09:55	15/11/2024	09:56	254,118	Bristol	BL048162
Breakdown 31 Battery Chassis	battery issues Replaced						
BREAKDOWN	27/11/2024	15:00	27/11/2024	15:06	256,886	Bristol	BL048603
42 Coolant System	Heater pipes leaking, parts ordered						

Unplanned Repair	02/12/2024	08:31	02/12/2024	08:36	257,406	Bristol	BL048788
34 Lights Bulb Replacement	Replace O/S/F DRL - N/S/F Headlight And Side Light Bulbs						
SAFETY INSPECTION	04/12/2024	15:50	04/12/2024	18:10	257,843	Bristol	BL048882
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 12mts Service	Service of fire supression system						
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Annual Heater Service	replaced all heater components						
17 Tyres Replace	both front						
Vehicle Deep Clean	05/12/2024	09:30	05/12/2024	14:00	257,846	Bristol	BL048913
Vehicle Deep Clean	Vehicle Deep Clean						
MOT EXPIRES	23/12/2024	10:35	23/12/2024	10:37	258,813	Bristol	BL049570
MOT							
Breakdown	03/01/2025	17:29	05/01/2025	06:31	259,684	Bristol	BL050001
Breakdown	3 rear light covers smashed VEHICLE IN USE						
Unplanned Repair	07/01/2025	15:48	07/01/2025	15:56	259,979	Bristol	BL050132
34 Lights	Lighting System -Rear lower light cluster is cracked						
71 Body Exterior 1	Body Exterior Broken plastic casings to rear left side lights						
SAFETY INSPECTION	14/01/2025	09:54	15/01/2025	11:04	260,688	Bristol	BL050404

Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test Tail Lift Inspection Pollen Filter Change 42 Coolant System 02 Windscreen 18 Wheels Removal 13 Brakes 1 45 Engine Oil Top Up 16 Suspension 1	Check and Install MDVS windows update Carry Out Safety Inspection Torque All Wheel Nuts - 180Nm #2 Carry Out Road Test Carry Out Tail Lift Inspection Carry Out Pollen Filter Change Coolant Warning Light On - Replace Corroded Heater Pipe And Hose Top Up Screenwash Clean All Hubs And Flanges Replace Worn Rear Brake Discs And Pads Top Up Engine Oil Level Replace Nearside Rear Split Spring Bush						
Vehicle Deep Clean	15/01/2025	14:15	15/01/2025	17:45	260,690	Bristol	BL050448
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	17/01/2025	15:59	17/01/2025	16:02	260,875	Bristol	BL050512
99 Diagnostic Test 43 Exhaust System 1	Carried out diag for EML, found cat temp sensor fault Swapped cat temp sensor with 2505						
Breakdown	18/01/2025	13:53	20/01/2025	17:15	261,084	Bristol	BL050551
Breakdown	Low coolant possible leak vehicle did not attend workshop						
02 Pipeline Annual Inspection	15/01/2025	11:35	15/01/2025	11:45	260,690	MDT Bristol	TB012067
02 Pipeline Annual Inspection	Annual Inspection and Pressure Tested By SMc - Passed All Tests						
ACCIDENT	17/02/2025	13:11	17/02/2025	13:15	263,667	Bristol	BL051668
02 Mirrors	Mirrors n/s wing mirror broken due to accident, replaced n/s glass						
SAFETY INSPECTION	25/02/2025	09:01	25/02/2025	16:17	263,667	Bristol	BL051925
Check MDVS for Update Safety Inspection 18 Wheels Check Torques	Check and Install MDVS windows update						

Road Test							
85 Body Interior 1	Replaced Dressings cubord angle plastic						
86 Sliding Door	Replaced sliding door earth wire						
55 Tail Lift	carry our repair to hand rails						
Tail Lift Inspection	Replaced wander lead and switch box						
UB Fire Supp Replace	Replacement of UB Fire System						
Vehicle Deep Clean	25/02/2025	22:55	26/02/2025	02:50	264,196	Bristol	BL051954
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	06/04/2025	12:10	06/04/2025	14:30	268,268	Bristol	BL053391
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	07/04/2025	09:31	07/04/2025	16:22	268,628	Bristol	BL053426
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection	Carry Out Safety Inspection						
18 Wheels Check Torques	Torque All Wheel Nuts - 180Nm #3						
Road Test	Carry Out Road Test						
85 Body Int Alcohol Gel Dispen	Already Fitted						
Tail Lift Inspection	Carry Out Tail Lift Inspection						
Brake Fluid Change	Carry Out Brake Fluid Change						
Wheel Hub Flanges Replaceme	Replace All Hub Flanges						
02 Windscreen	Top Up Screenwash						
02 Windscreen Wipers	Replace Worn Wiper Blades						
15 Steering 1	Top Up Power Steering Fluid						
45 Engine Oil Top Up	Top Up Engine Oil Level						
18 Wheels Removal	Clean All Hubs For New Flanges						
Unplanned Repair	13/04/2025	06:45	13/04/2025	07:00	269,007	Bristol	BL053640
34 Lights Bulb Replacement	Replace Blown Nearside Front Headlight Bulb						
SAFETY INSPECTION	21/05/2025	10:20	21/05/2025	16:20	273,347	Bristol	BL054982

Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Engine Change Oil & Filter							
Replace Handbrake Cables	Replace Handbrake Cables						
Tail Lift Inspection							
34 Lights Bulb Replacement	Cab interior light						
34 Emergency Lights	Replaced nsr scene light (damaged)						
86 Doors Rear	Adjusted rear door latches						
86 Door Lock	Replaced rear door lock						
85 Body Interior Roof	Replaced skylight blind						
52 Electrical Aux	Replaced 4 damaged inverter led's						
43 Exhaust System 1	Replaced corroded tail pipe						
Vehicle Deep Clean	21/05/2025	19:00	21/05/2025	23:57	273,347	Bristol	BL055001
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	13/06/2025	17:58	13/06/2025	18:04	275,340	Bristol	BL055707
15 Steering 1	Steering unbalance steering						
15 Steering 2	Check For Heavy Steering - Replace Faulty PAS Pump						
Road Test	Carry Out Road Test After Repair Work						
Defect Repair	08/07/2025	13:19	08/07/2025	13:22	278,059	Bristol	BL056507
86 Doors Rear	Replaced offside rear door bar and freed up mounting						
Unplanned Repair	22/07/2025	13:47	26/07/2025	11:26	279,057	Bristol	BL056963
34 Lights	Lighting System O/S RUNNING LIGHT OUT						
31 Charging System Battery	Comms Power Check Powering down intermittently, no comms when on						
01 Air Conditioning 1	A/C System Saloon Air con failed throughout						
31 Battery Aux	MDT Failure/Issue mdvs keep dying for no reason						
13 Brakes 1	No brakes see BL057079						

31 Battery Comms	comms battery needs replacing						
SAFETY INSPECTION	26/07/2025	10:02	28/07/2025	16:53	279,057	Bristol	BL057079
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
13 Brakes 1	replace front brake pads and wires						
16 Suspension 1	replace both front struts						
13 Brakes 2	replace sized o/s/f brake caliper						
16 Suspension 2	replace worn rear shocks						
16 Suspension 3	replace worn out rear lower arb bushes						
85 Body Interior 1	replace large door magnet						
85 Body Interior 2	replace cuboard angle						
89 Seats	tighten up saloon seat adjusters						
31 Battery Comms	comms battery requires replacing REPLACED						
55 Tail Lift	trolley stop plates sized REPLACED						
85 Body Interior 3	cab seat covers split						
86 Doors Rear	long door stay block loose in floor REFIXED						
01 Air Conditioning 1	pipes on top of rad cover loose and leaking fitted new hose clips						
Vehicle Deep Clean	28/07/2025	21:00	29/07/2025	00:30	279,062	Bristol	BL057180
Vehicle Deep Clean	Vehicle Deep Clean						
Decommission Vehicle	10/09/2025	13:00			279,224	Bristol	BL058743
Decommission vehicle	Decommission vehicle						