

WM64JXU	A&E		Derriford Amb Stn				
PDI Inspection	01/05/2015	07:55	01/05/2015	13:56	129	Derriford	DE018250
PDI Inspection							
SAFETY INSPECTION	26/05/2015	08:00	26/05/2015	08:05	129	Derriford	DE018381
18 Wheels Check Torques Safety Inspection							
Unplanned Repair	02/06/2015	13:52	02/06/2015	13:56	1,572	Derriford	DE018512
45 Engine Ad Blue	Topped up by crew						
Defect Repair	17/06/2015	09:10	17/06/2015	09:19	3,205	Derriford	DE018483
86 Door Lock	Side & scoop door solenoids noisy/not locking/opening warranty sent 17/06/16					Awaiting Warranty	
Unplanned Repair	24/06/2015	10:00	24/06/2015	10:15	4,386	Derriford	DE018513
44 Add Ad Blue	Topped up by crew						
SAFETY INSPECTION	06/07/2015	07:58	07/07/2015	09:45	5,827	Derriford	DE018561
18 Wheels Check Torques 44 Add Ad Blue 71 Body External Steps 86 Door handle 86 Door Lock 86 Doors 87 Gas Systems 87 Oxygen System	topped up ad blue straightened step and lubricated Doors rear door catches lubed Side & scoop door solenoids replaced under warranty Other side door not unlocking Med Equip & Devices low oxygen warning constantly Medical Devices oxygen low alarm sounds constantly						

Safety Inspection

Vehicle Deep Clean	06/07/2015	09:41	06/07/2015	09:42	5,827	Derriford	DE018562
---------------------------	-------------------	--------------	-------------------	--------------	--------------	------------------	-----------------

Vehicle Deep Clean	06/07/2015	09:43	06/07/2015	13:25	5,827	Derriford	DE018563
---------------------------	-------------------	--------------	-------------------	--------------	--------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	18/07/2015	00:45	18/07/2015	15:05	7,240	Derriford	DE018620
------------------	-------------------	--------------	-------------------	--------------	--------------	------------------	-----------------

Breakdown	non start - warning lights on dash
-----------	------------------------------------

Unplanned Repair	22/07/2015	12:06	22/07/2015	16:51	7,687	Derriford	DE018639
-------------------------	-------------------	--------------	-------------------	--------------	--------------	------------------	-----------------

56 Comms Equipment	MDT screen will not switch on batteries ok MDT screen replaced by PCE
--------------------	---

Breakdown	28/07/2015	11:11	28/07/2015	15:15	8,628	Derriford	DE018661
------------------	-------------------	--------------	-------------------	--------------	--------------	------------------	-----------------

33 Ignition System Breakdown	Mercedes 24 attended suspect ignition key fault swapped key with spare Lost ability to rev engine	Awaiting Warranty
---------------------------------	--	-------------------

Vehicle Deep Clean	19/08/2015	07:17	19/08/2015	13:15	11,856	Derriford	DE018750
---------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	20/08/2015	07:08	20/08/2015	12:21	11,858	Derriford	DE018754
--------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

18 Wheels Check Torques 33 Ignition System 34 Lights Bulb Replacement 85 Body Interior 1 Safety Inspection	Keys been checked N.F.F N/s driving light & n/s headlight n/w Replaced bulbs Checklist Defect Retaining strap for storage cupboard broken
--	---

Unplanned Repair	15/09/2015	10:55	16/09/2015	13:33	14,859	Derriford	DE018882
27 Transmission Automatic stuck in 1st gear Repaired by Mercedes of Plymouth							
Unplanned Repair	22/09/2015	07:00	23/09/2015	16:15	15,263	Derriford	DE018909
03 Instruments & Sensors 1 Eml light on vehicle in limp mode Mass air flow sensor replaced Mercedes of Plym Travel Time Take vehicle to Dealer							
BREAKDOWN	28/09/2015	07:28	29/09/2015	15:08	15,764	Derriford	DE018940
03 Instruments & Sensors 1 Check & cleared stored fault codes with star							
Vehicle Deep Clean	28/09/2015	08:36	28/09/2015	13:23	15,764	Derriford	DE018944
Vehicle Deep Clean Vehicle Deep Clean							
SAFETY INSPECTION	28/09/2015	15:04	29/09/2015	15:07	15,764	Derriford	DE018946
18 Wheels Check Torques 45 Engine Ad Blue Topped up ad blue 71 Body External Steps Straighten step support bracket Safety Inspection Tail Lift 6 Monthly Inspection Statutory Inspection							
Unplanned Repair	01/10/2015	13:00	09/10/2015	10:51	16,204	Derriford	DE018962
03 Instruments & Sensors 1 Engine Engine warning light on. Travel Time Take vehicle to dealer							
Unplanned Repair	16/10/2015	08:30	16/10/2015	13:50	16,655	Derriford	DE019030
03 Instruments & Sensors 1 GearBox Stuck in first gear/Limp mode check for fault No fault at time of test 03 Instruments & Sensors 2 Engine Power loss - vehicle in safe / limp mode 55 Tail Lift Free off jammed handrails & reset in correct position							

85 Body Interior 1 86 Doors	N/sr door stay has sheared off & pivot has seized Remove interior side door panel adjust operating cables & refit					Awaiting Warranty	
Unplanned Repair	19/10/2015	07:13	22/10/2015	16:09	16,946	Derriford	DE019035
45 Engine 1 Travel Time	Diagnose ECU wiring fault repaired by Mercedes of plymouth collect vehicle from Mercedes						
Unplanned Repair	30/10/2015	07:30	30/10/2015	09:00	17,776	Derriford	DE019086
85 Body Interior 1	N/s/r door stay & mount replaced under warranty						
SAFETY INSPECTION	09/11/2015	07:06	09/11/2015	11:55	19,261	Derriford	DE019114
18 Wheels Check Torques 71 Body Exterior 1 Safety Inspection 92 - C Service Service C	Renewed body corner						
Vehicle Deep Clean	11/11/2015	07:13	11/11/2015	11:03	19,452	Derriford	DE019130
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/11/2015	09:30	20/11/2015	11:27	20,683	Derriford	DE019169
55 Tail Lift	Remove n/s handrail refit leg pole & refit hand rail refit & secure o/s magnet						
SAFETY INSPECTION	17/12/2015	08:53	17/12/2015	13:29	24,580	Derriford	DE019306
17 Tyres Replace 18 Wheels Check Torques 45 Engine 1	Removed and renewed 6x tyres engine oil leak warranty						

71 Body Exterior 1	Refitted locker plate						
71 Body Exterior 2	tape up damaged nsr wheel arch						
Safety Inspection							
MOT Pre Test							
Vehicle Deep Clean	17/12/2015	12:17	18/12/2015	09:30	24,580	Derriford	DE019309
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	24/12/2015	09:30	24/12/2015	11:36	25,322	Derriford	DE019341
45 Engine 1	Replaced broken viscous fan drive belt						
SAFETY INSPECTION	01/02/2016	07:07	02/02/2016	11:00	29,695	Derriford	DE019512
03 Instruments & Sensors 1	Rev. Camera/Screen not working					Monitoring	
13 Brake Pads	Front and rear pads renewed						
17 Tyres Replace	o.s.r. outer tyre renewed, puncture						
18 Wheels Check Torques							
71 Body Exterior 1	Bridge plate guides broken off, 2x lower body corners renewed					Monitoring	
87 Oxygen System	Medical Devices F size 02,selector valve won't select the right 02 N.F.F						
Safety Inspection							
Travel Time							
MOT	Done by A J Motors P/O 151121170						
Vehicle Deep Clean	02/02/2016	11:00	02/02/2016	14:37	29,730	Derriford	DE019528
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	05/02/2016	09:00	05/02/2016	14:18	29,917	Derriford	DE019541
71 Body Exterior 1	Rear valance replaced & sliders refitted Done by Autospray P/O 151124698						
SAFETY INSPECTION	14/03/2016	07:06	14/03/2016	13:18	35,211	Derriford	DE019691
03 Instruments & Sensors 1	Rev. Camera/Screen not working					Awaiting Parts	
18 Wheels Check Torques							

34 Lighting System	Secure No. plate wiring						
71 Body External Steps	Straighten frame						
86 Doors	Secure lock covers						
87a - Medical Equipment Repair	Mangar bracket renewed						
Safety Inspection							
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by South west lifts P/O 151126516						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	14/03/2016	12:13	15/03/2016	09:35	35,211	Derriford	DE019698
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	05/04/2016	07:00	05/04/2016	09:11	38,330	Derriford	DE019800
71 Body Exterior 1	Replaced n/s/r light pod & 3 x damaged lights						
Alcohol Gel Dispenser Installed	08/04/2016	13:36	08/04/2016	13:37	38,681	Derriford	DE019828
85 Body Int Alcohol Gel Dispenser Fitted							
Install Saloon CCTV Camera	13/04/2016	11:42	13/04/2016	13:25	39,436	Derriford	DE019858
Install Saloon CCTV Camera Fit Throw Lines & SOP	Fitted by John coles CCTV system n/w Fitted						Awaiting Warranty
Defect Repair	14/04/2016	10:00	14/04/2016	10:30	39,442	Derriford	DE019865
86 Sliding Door	Adjust side door warning switch						
SAFETY INSPECTION	25/04/2016	07:09	26/04/2016	09:30	40,897	Derriford	DE019915
03 Instruments & Sensors 1	Rev. Camera/Screen not working						
18 Wheels Check Torques							
43 Exhaust System 1	Resecure tailpipe						
45 Engine 1	Oil leak						Awaiting Warranty
55 Tail Lift	Guardrail lock u/s. SW Lifts repair.						
71 Body Exterior 1	n.s.r. wheel arch damage						

87 Oxygen System	1x O2 regulator out of date. Flow meter mount secured						Awaiting Parts
Install Saloon CCTV Camera	Fitted by John coles CCTV system n/w						
Safety Inspection							
93 - D Service							
Service D							
Wheel Studs & Nuts Replaceme							
Handbrake Cable Replacement	Replace rear handbrake cables						
UB Fire Suppression Service	Unable to free extinguishant						
Vehicle Deep Clean	26/04/2016	09:34	26/04/2016	13:30	40,897	Derriford	DE019927
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/06/2016	07:06	06/06/2016	14:19	46,662	Derriford	DE020089
02 Cab Assembly 1	Cab light bulb renewed						
16 Suspension 1	Play in front struts						Awaiting Warranty
17 Tyres Replace	Rear tyres renewed						
18 Wheels Check Torques							
45 Engine 1	Oil leak						Awaiting Warranty
55 Tail Lift	Straighten guardrail						
87 Oxygen System	1x O2 regulator out of date.						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Reposition grab bag shelf							
Vehicle Deep Clean	07/06/2016	06:59	07/06/2016	11:27	46,662	Derriford	DE020099
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	09/06/2016	12:00	14/06/2016	15:57	46,764	Derriford	DE020121
03 Instruments & Sensors 1	Check & clear stored fault codes & reset service mileage warning						
71 Body Exterior 1	carried out temp repair to osr lower corner						
87 Oxygen System	Med Equip main oxygen system not working Repaired by Oxylitre						
SAFETY INSPECTION	14/07/2016	08:47	14/07/2016	14:52	50,850	Derriford	DE020274

01 Heating 1	Heater exhaust split	Awaiting Parts
02 Cab Ass Fire Extinguisher	2x extinguishers renewed	
13 Brake Pads	Rear pads renewed	
16 Suspension 1	Play in front struts	Awaiting Warranty
17 Tyres Replace	OSF tyre renewed	
18 Wheels Check Torques		
45 Engine 1	Oil leak	Awaiting Warranty
55 Tail Lift	Guard rail upright secured, bridge plate guide bolt renewed	
71 Body Exterior 1	OSR valance & NSR wheel arch damage	
71 Body External Steps	Step edge renewed	
87 Oxygen System	Flow meter mount secured	
Safety Inspection		
Gearbox Oil & Filter Change		

Vehicle Deep Clean	18/07/2016	07:00	18/07/2016	14:01	51,394	Derriford	DE020286
---------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	23/08/2016	08:58	24/08/2016	11:10	56,574	Derriford	DE020463
--------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

01 Heating 1	Heater exhaust split	
13 Brake Pads	renewed front pads	
13 Brakes 1	renewed pedal rubber	
13 Discs	renewed front discs	
16 Suspension 1	Play in front struts	Awaiting Warranty
18 Wheels Check Torques		
34 Lights	nsf fog surround missing	
45 Engine 1	Oil leak	Awaiting Warranty
86 Sliding Door	inner panel cracked	
Safety Inspection		
Tail Lift 6 Monthly Inspection	Statutory Inspection	

Vehicle Deep Clean	24/08/2016	09:33	25/08/2016	08:00	56,574	Derriford	DE020477
---------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	14/09/2016	07:02	14/09/2016	07:14	58,827	Derriford	DE020603
55 Tail Lift	Straigten sensor plate						
Unplanned Repair	03/10/2016	07:30	03/10/2016	09:10	60,956	Derriford	DE020725
17 Tyres Replace	Replaced o/s/r inner tyre (punctured)						
Unplanned Repair	03/10/2016	10:00	04/10/2016	11:38	60,956	Derriford	DE020733
16 Suspension 1	Play in front struts Front struts replaced under warranty by mercedes Oil leak Replaced intercooler pipe seals Done by Mercedes under warranty Take vehicle to Dealer						
45 Engine 1							
Travel Time							
SAFETY INSPECTION	07/10/2016	07:00	07/10/2016	12:19	61,314	Derriford	DE020769
03 Instruments & Sensors 1	Fire supression warning sounding, pressure ok					Monitoring	
18 Wheels Check Torques							
45 Engine 1	Camchain noisy on start					Awaiting Warranty	
71 Body Exterior 1	Rear No. Plate secured						
71 Body Exterior 2	NSR wheel arch damage					Monitoring	
86 Doors	Scoop securing strap renewed						
Safety Inspection							
92 - C Service							
Service C							
Vehicle Deep Clean	13/10/2016	06:56	13/10/2016	13:06	62,263	Derriford	DE020810
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	15/10/2016	08:01	17/10/2016	08:11	62,453	Derriford	DE020830
18 Wheels	Check ror buckled wheel found very small dent in rim Free off sticking stretcher clamp release Stretcher locknot releasing. OSR outer rim buckled						
87 - Stretchers/Chairs/Boards							
Breakdown							

Vehicle Deep Clean	18/11/2016	07:12	18/11/2016	13:11	66,921	Derriford	DE021030
---------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	21/11/2016	06:58	21/11/2016	14:30	67,292	Derriford	DE021040
--------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

03 Instruments & Sensors 1	Fire supression warning sounding, pressure ok	Monitoring
----------------------------	---	------------

03 Instruments & Sensors 2	Service light reset
----------------------------	---------------------

17 Tyres Replace	NSF & OSRO tyre renewed
------------------	-------------------------

17 Tyres Tracking	Tracking.
-------------------	-----------

18 Wheels Check Torques	
-------------------------	--

43 Exhaust System 1	Tailpipe/silencer mount secured
---------------------	---------------------------------

45 Engine 1	Camchain noisy on start	Awaiting Warranty
-------------	-------------------------	-------------------

55 Tail Lift	Guardrail uprights secured
--------------	----------------------------

71 Body Exterior 2	NSR wheel arch damage	Monitoring
--------------------	-----------------------	------------

86 Sliding Door	Latch covers secured, outer trim refitted
-----------------	---

Safety Inspection	
-------------------	--

Supply Sat Nav	Upgrade
----------------	---------

Remove Ventilator Brackets	Remove Ventilator Brackets and Fill
----------------------------	-------------------------------------

MOT Pre Test	
--------------	--

Unplanned Repair	22/11/2016	09:00	24/11/2016	16:00	67,315	Derriford	DE021054
-------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

45 Engine 1	Camchain noisy on start Tensioner replaced under warranty
-------------	---

Travel Time	
-------------	--

Unplanned Repair	16/12/2016	12:00	16/12/2016	14:37	69,871	Derriford	DE021217
-------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

55 Tail Lift	Freeoff o/s handrail & replace n/s handrail missing stop bolt
--------------	---

SAFETY INSPECTION	28/12/2016	07:12	28/12/2016	14:07	71,946	Derriford	DE021272
--------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

11 Axle Rear	Replace n/s/r spring front slipper pad
--------------	--

17 Tyres Replace	replaced o/s/f & both n/s/r tyres
------------------	-----------------------------------

18 Wheels Check Torques	
-------------------------	--

31 Battery Chassis	Check chassis battery
--------------------	-----------------------

44 Add Ad Blue	Topped up Ad blue
----------------	-------------------

86 Doors	Replaced n/s/r top door catch cover
89 Seats	Tighten both swivel seat lock pin lock nut
Safety Inspection	
Medical Device and Equip Chec	Checked ok

Vehicle Deep Clean	03/01/2017	06:30	03/01/2017	13:30	72,721	Derriford	DE021295
---------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

MOT	04/01/2017	07:19	04/01/2017	12:29	72,854	Derriford	DE021302
------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

MOT	Done by A J Motors P/O 151141599
Travel Time	

Breakdown	08/01/2017	17:13	09/01/2017	09:29	73,262	Derriford	DE021315
------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

71 Body Exterior 1	Replace front number plate
Breakdown	front number plate broken

Unplanned Repair	20/01/2017	15:00	20/01/2017	15:39	74,571	Derriford	DE021396
-------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

02 Mirrors	Replaced o/s mirror casing & frame
------------	------------------------------------

Defect Repair	06/02/2017	07:00	06/02/2017	07:51	76,468	Derriford	DE021481
----------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

86 Doors Rear	OSR door stay replaced
---------------	------------------------

SAFETY INSPECTION	16/02/2017	08:27	17/02/2017	12:11	77,703	Derriford	DE021543
--------------------------	-------------------	--------------	-------------------	--------------	---------------	------------------	-----------------

03 Instruments & Sensors 1	Fire supression warning sounding, pressure ok
18 Wheels Check Torques	
34 Lights Bulb Replacement	renewed os drl
71 Body Exterior 2	NSR wheel arch damage

Safety Inspection
 Tail Lift 6 Monthly Inspection Statutory Inspection
 Tail Lift Annual Service Statutory Inspection and Weight Test Done by South west lifts P/O 151147629

Unplanned Repair **20/02/2017** **11:00** **20/02/2017** **11:47** **77,826** **Derriford** **DE021561**

34 Lights Bulb Replacement replaced o/s headlight bulb
 86 Door Lock Remove n/s/r interior door panel free off siezed lock & refit panel

Vehicle Deep Clean **22/02/2017** **06:00** **22/02/2017** **11:00** **77,932** **Derriford** **DE021573**

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean **03/04/2017** **07:00** **03/04/2017** **14:00** **83,077** **Derriford** **DE021771**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **03/04/2017** **13:36** **06/04/2017** **15:29** **83,077** **Derriford** **DE021776**

02 Windscreen Wipers Sweep adjusted
 13 Discs renewed rear discs and pads
 17 Tyres Replace OSR tyres renewed
 18 Wheels Check Torques
 34 Lighting System NSF top marker light renewed
 71 Body Exterior 1 OSR bottom corner damage Awaiting Body Repair
 71 Body External Steps Side step n/w Repaired under warranty
 85 Body Interior 1 Equip. retaining strap renewed
 86 Sliding Door Side door roller bearings replaced under warranty
 Safety Inspection
 93 - D Service
 Service D
 Annual Heater Service Annual Heater Service
 Annual Air Con Service Annual Air Condition Service
 Handbrake Cable Replacement Replace rear handbrake cables Not Required
 UB Fire Suppression Service New sustem fitted by John coles

BREAKDOWN	13/04/2017	09:44	13/04/2017	11:12	83,742	Derriford	DE021837
55 Tail Lift	Tail lift will not deploy or lower Repaired by South west lifts under warranty						
SAFETY INSPECTION	10/05/2017	07:05	11/05/2017	14:18	86,841	Derriford	DE021980
01 Heating 1	Saloon heater exhaust replaced under warranty renewed fronts replaced worn front tyres Doors side step will not stow.Repaired under warranty renewed gate magnet OSR bottom corner damage various body damage Body Exterior Side step u/s repired as above Electrical Auxs CHARGING CABLE MANGAR ELK SNAPPED						
13 Brake Pads							
17 Tyres Replace							
18 Wheels Check Torques							
52 Electrical Aux							
55 Tail Lift							
71 Body Exterior 1							
71 Body Exterior 3							
71 Body External Steps							
Medical Devices Repair							
Safety Inspection							
Vehicle Deep Clean	10/05/2017	11:57	11/05/2017	13:30	86,841	Derriford	DE021986
Vehicle Deep Clean	Vehicle Deep Clean						
ACCIDENT	05/06/2017	11:48	16/06/2017	14:42	89,222	Derriford	DE022142
15 Steering 1	road tested for noise veh to go to merc on mon warranty N/s/r rear wheel arch & rear step replaced MGS Gas Storage ModificationsMGS Gas Storage Modifications						
71 Body External W&T Repair							
MGS Gas Storage Modifications							
Unplanned Repair	19/06/2017	07:47	19/06/2017	11:22	90,030	Derriford	DE022226
15 Steering 1	check for steering knocking noise Take vehicl to dealer						
Travel Time							
Breakdown	20/06/2017	18:08	21/06/2017	15:32	90,287	Derriford	DE022242
Breakdown	Mdt Failure Battery Check						

Vehicle Deep Clean	21/06/2017	07:01	21/06/2017	11:30	90,294	Derriford	DE022243
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	21/06/2017	13:38	22/06/2017	13:29	90,294	Derriford	DE022252
17 Tyres Replace	Replaced both n/s/r tyres						
18 Wheels Check Torques							
44 Add Ad Blue	Topped up adblue						
89 Seatbelts	Refitted rear swivel seat seatbelt cover						
Safety Inspection							
COMMS.FAILURE CHECK	26/06/2017	09:00	26/06/2017	11:00	90,294	Derriford	DE022274
MDT Failure/Issue	Check batteries & charging All ok PCE replace PCB board						
Breakdown	02/07/2017	19:25	03/07/2017	09:31	91,355	Derriford	DE022311
56 Comms Power Failure							
Breakdown	Requires Battery Checked batteries all ok PCE checked power board						
Vehicle Deep Clean	04/08/2017	07:00	04/08/2017	10:42	95,360	Derriford	DE022501
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	04/08/2017	10:55	04/08/2017	14:59	95,360	Derriford	DE022506
02 Cab Ass Fire Extinguisher	Swap extinguishers						
18 Wheels Check Torques							
55 Tail Lift	Bridge plate guide refitted						
86 Sliding Door	Latch cover renewed						
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						

Defect Repair	29/08/2017	07:29	08/09/2017	07:06	98,582	Derriford	DE022624
03 Instruments & Sensors 1 33 Ignition System Breakdown	Emg Warning Devices vehicle brake warning indicator . Ignition switch replaced under warranty						
SAFETY INSPECTION	11/09/2017	07:03	14/09/2017	07:40	98,662	Derriford	DE022715
03 Instruments & Sensors 1 11 Axle Front 16 Suspension 1 18 Wheels Check Torques 55 Tail Lift Safety Inspection	Engine AMBER ENGINE MANAGEMENT LIGHT IS ON Slight lift O/S ball joint Slight play, O/S strut Handrail secured						Monitoring Monitoring
Vehicle Deep Clean	11/09/2017	12:26	12/09/2017	11:00	98,662	Derriford	DE022724
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	16/09/2017	11:32	18/09/2017	13:55	98,942	Derriford	DE022752
56 Comms Equipment Breakdown	MDT failure repaired by PCE MDT will not power up						
Unplanned Repair	25/09/2017	10:00	25/09/2017	12:07	99,829	Derriford	DE022803
01 Air Conditioning 1 03 Instruments & Sensors 1	Saloon air con condensor fan replaced by Espar under warranty Reset service mileage indicator						
Vehicle Deep Clean	26/10/2017	10:00	27/10/2017	08:00	104,038	Derriford	DE022995
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/10/2017	07:13	27/10/2017	14:16	104,039	Derriford	DE022998
02 Cab Assembly 1 11 Axle Front	Bulkhead grommet renewed Slight lift O/S ball joint						Monitoring

16 Suspension 1	Slight play, O/S strut	Monitoring
17 Tyres Replace	Renew front tyres, & osr tyres. & check tracking	
18 Wheels Check Torques		
45 Engine 1	Cam Chain Tensioner noisy.	Awaiting Warranty
56 Comms Equipment	Comms Power Check MDT checked ok	
85 Body Interior 1	CCTV cupboard ram weak, warranty sent	Awaiting Warranty
Safety Inspection		
Gearbox Oil & Filter Change		
92 - C Service		
Service C		

Unplanned Repair	31/10/2017	07:14	01/11/2017	11:55	104,425	Derriford	DE023017
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

11 Axle Front	Slight lift O/S ball joint	Awaiting Warranty
16 Suspension 1	Slight play, O/S strut	Awaiting Warranty
45 Engine 1	Cam Chain Tensioner noisy.	Awaiting Warranty
Travel Time	Take vehicle to dealer	

Unplanned Repair	15/11/2017	10:00	15/11/2017	10:46	105,903	Derriford	DE023105
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

86 Doors	Free off n/s/r door lock key barrel & adjust release cables	
----------	---	--

Unplanned Repair	20/11/2017	07:00	20/11/2017	08:48	106,059	Derriford	DE023136
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

56 Comms Power Failure	Check batteries all ok link out power relay	
------------------------	---	--

Unplanned Repair	24/11/2017	08:00	24/11/2017	09:05	106,257	Derriford	DE023161
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

85 Body Interior 1	CCTV cupboard ram weak Replaced under warranty	
--------------------	--	--

Defect Repair	01/12/2017	08:30	01/12/2017	09:30	108,013	Derriford	DE023204
----------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

31 Battery Aux	Check batts. Auxillary renewed	
55 Tail Lift	Adjust tilt ram.	

SAFETY INSPECTION	05/12/2017	09:10	05/12/2017	14:37	108,559	Derriford	DE023223
01 Air Conditioning 1	Tensione rpivot bearing breaking up. Warranty sent					Awaiting Warranty	
11 Axle Front	Slight lift O/S ball joint					Awaiting Warranty	
13 Brake Pads	Rear pads renewed						
16 Suspension 1	Slight play, O/S strut					Awaiting Warranty	
18 Wheels Check Torques							
34 Lights Bulb Replacement	OSF sidelight bulb renewed						
45 Engine 1	Cam Chain Tensioner noisy.					Awaiting Warranty	
Safety Inspection							
MOT Pre Test							
Vehicle Deep Clean	06/12/2017	10:00	07/12/2017	06:39	108,601	Derriford	DE023236
Vehicle Deep Clean	Vehicle Deep Clean						
MRO Refresh	08/12/2017	10:33	08/12/2017	11:48	108,601	Derriford	DE023246
MRO Refresh							
SAFETY INSPECTION	18/01/2018	06:50	18/01/2018	15:39	113,737	Derriford	DE023490
01 Air Conditioning 1	Tensione pivot renewed, parts supplied by Merc.						
11 Axle Front	Slight lift O/S ball joint					Awaiting Warranty	
16 Suspension 1	Slight play, O/S strut,					Awaiting Warranty	
16 Suspension 2	Rear anti roll bar cotton reels renewed						
17 Tyres Replace	Renew NSR tyres						
18 Wheels Check Torques							
31 Battery Comms	Check ok, remove and bridge relay						
45 Engine 1	Cam Chain Tensioner noisy.						
55 Tail Lift	Bridge plate guide secured						
86 Doors Rear	Adjust catches						
87a - Medical Equipment Repair	Mangar charger lead u/s					Monitoring	
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by South west lifts P/O 151165497						
Vehicle Deep Clean	19/01/2018	07:00	19/01/2018	10:33	113,796	Derriford	DE023497

Vehicle Deep Clean	Vehicle Deep Clean						
MOT	19/01/2018	10:00	19/01/2018	15:07	113,796	Derriford	DE023500
MOT Travel Time	Done by A J Motors P/O 151163964						
Defect Repair	22/01/2018	14:01	22/01/2018	14:44	113,897	Derriford	DE023522
16 Suspension 1 43 Exhaust System 1 55 Tail Lift	OSR anti roll bar secured Straighten mount Hand rails rattling. Magnets ok					Monitoring	
Breakdown	12/02/2018	03:22	12/02/2018	07:00	114,831	Derriford	DE023657
17 Tyres Replace Breakdown	N/s/f tyre replaced by ATS Screw in tyre front nearside tyre						
Unplanned Repair	12/02/2018	09:31	15/02/2018	16:03	115,850	Derriford	DE023661
02 Mirrors 11 Axle Front 16 Suspension 1 31 Charging System Travel Time	Mirrors cracked wing mirror glass Slight lift O/S ball joint Checked by Mercedes within wear limits Slight play, O/S strut, Checked by Mercedes within wear limits alternator Replaced under warranty by Mercedes of plymouth					Awaiting Parts	
Unplanned Repair	16/02/2018	07:15	16/02/2018	07:48	116,362	Derriford	DE023693
02 Mirrors 34 Lights Bulb Replacement	Mirrors cracked wing mirror glass Replaced glass Replaced n/s headlight bulb						
Unplanned Repair	23/02/2018	06:04	23/02/2018	07:25	117,172	Derriford	DE023738
13 Brakes 1 24 Driveshaft 1 43 Exhaust System 1	noise when braking,road tested and found prop worn Removed and renewed worn rear propshaft Removed and renewed exhaust tailpipe						

SAFETY INSPECTION	28/02/2018	06:02	28/02/2018	12:14	117,706	Derriford	DE023777
02 Cab Assembly 1	toolbox cover damaged renewed						
02 Windscreen Wipers	bottle cap missing						
13 Discs	renewed front disc and pads						
18 Wheels Check Torques							
34 Lights	renewed damaged nsf fog						
55 Tail Lift	Hand rails rattling. Magnets ok						
85 Body Interior 1	linen cupboard broken re-stuck						
86 Door Seals	renewed both cab door seals						
87a - Medical Equipment Repair	Mangar charger lead u/s						
Safety Inspection							
85 Body Int Alcohol Gel Dispen							

Vehicle Deep Clean	05/03/2018	05:56	05/03/2018	10:29	118,302	Derriford	DE023800
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	19/03/2018	07:33	19/03/2018	09:57	119,377	Derriford	DE023900
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

86 Doors Rear	Replace n/s/r door handle
---------------	---------------------------

Unplanned Repair	05/04/2018	07:36	05/04/2018	09:30	120,995	Derriford	DE023995
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

03 Instruments & Sensors 1	Reset service mileage indicator
71 Body Exterior 1	Resecure tail lift bridge plate sliders
Fit Poster Holder	Fit Poster Holder

SAFETY INSPECTION	11/04/2018	06:15	12/04/2018	12:51	121,776	Derriford	DE024026
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

13 Brake Pads	renewed worn rear pads	
16 Suspension 1	Slight play front lower b/js ,rear spring slipper pads starting to split	Monitoring
18 Wheels Check Torques		

45 Engine 1	Timing chain rattle on inital start up from cold	Monitoring
Safety Inspection		
93 - D Service		
Service D		
Wheel Hub Flanges Replaceme		
Annual Heater Service	Annual Heater Service,Renewed exhaust pipe	
Annual Air Con Service	Annual Air Condition Service	
Handbrake Cable Replacement	Replace rear handbrake cables	
UB Fire Suppression Service		

Breakdown	15/04/2018	10:53	16/04/2018	09:41	122,088	Derriford	DE024051
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

44 Fuel System 1	Check for fuel leak See notes
Breakdown	Fuel leak

Unplanned Repair	17/04/2018	14:30	17/04/2018	16:26	122,217	Derriford	DE024070
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

41 Air Intake	Replaced turbo pipe seal Found retaining bracket broken parts ordered	Awaiting Parts
---------------	---	----------------

Vehicle Deep Clean	23/04/2018	06:04	23/04/2018	10:00	122,840	Derriford	DE024091
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

71 Body External Steps	Body Exterior Side step not deploying. Free off Jammed step & lub
Vehicle Deep Clean	Vehicle Deep Clean

Unplanned Repair	04/05/2018	13:00	04/05/2018	15:00	123,977	Derriford	DE024183
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

31 Charging System	Check vehicle & drop down charging systems all working at time of test	Monitoring
56 Comms Power Failure	keep sending power warning when there no apparent fault	

Vehicle Deep Clean	24/05/2018	05:53	24/05/2018	12:26	126,098	Derriford	DE024301
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	25/05/2018	06:11	25/05/2018	13:04	126,179	Derriford	DE024311
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Windscreen Wipers	Electrical Auxs Windscreen washers not working.Repaired	
16 Suspension 1	Slight play front lower b/js ,rear spring slipper pads starting to split	Monitoring
17 Tyres Replace	Replaced worn osf tyre	
18 Wheels Check Torques		
34 Lights	Lighting System NSF sidelight lamp not illuminating,Renewed	
41 Air Intake	Replaced turbo pipe seal Found retaining bracket,Renewed	
45 Engine 1	Timing chain rattle on inital start up from cold	Monitoring
56 Comms Power Failure	keep sending power warning when there no apparent fault	
71 Body External Steps	Renewed broken step trim and decal	
85 Body Interior 1	Repaired forms holder	
85 Body Interior 2	Repaired cupboard shuts and drawer runner	
87 Stretcher	stretcher clamp cover refitted inc new nut inserts	
89 Seats	refitted swivel pin ,attendants adj bar missing	
Safety Inspection		

Breakdown	10/06/2018	11:33	11/06/2018	17:49	128,086	Derriford	DE024403
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Windscreen Wipers	Replaced washer two way valve with second hand
27 Transmission Automatic	Check for reported gear selection fault N.F.F
31 Battery Chassis	Replaced chassis battery
31 Battery Comms	Replaced comms battery
56 Comms Power Failure	MDT Failure/Issue power fail - when engine running or plugged in
Breakdown	Limited gear selection

BREAKDOWN	14/06/2018	14:30	22/06/2018	14:30	128,247	Derriford	DE024440
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

03 Instruments & Sensors 1	Check for faults found turbo boost pressure low
41 Turbo	Turbo replaced by Mercedes of plymouth P/O 151172925
45 Engine 1	EML light on vehicle in limp mode

Unplanned Repair	29/06/2018	13:00	29/06/2018	14:38	129,233	Derriford	DE024541
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

03 Instruments & Sensors 1	Check fault codes found oxygen sensor had failed replaced sensor & clear fault
----------------------------	--

SAFETY INSPECTION	04/07/2018	06:44	04/07/2018	13:16	130,123	Derriford	DE024571
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Windscreen Wipers	Renewed wiper blades
----------------------	----------------------

16 Suspension 1	Slight play front lower b/js ,rear spring slipper pads starting to split					Monitoring	
17 Tyres Replace	Renewed osr tyres						
18 Wheels Check Torques							
45 Engine 1	Timing chain rattle on inital start up from cold					Monitoring	
55 Ramp	repaired broken adjuster on os adjustable gate						
89 Seatbelts	front swivel seat,seat belt anchor loose, Tightened						
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	04/07/2018	13:00	05/07/2018	10:00	130,123	Derriford	DE024578
Vehicle Deep Clean	Vehicle Deep Clean						
COMMS.FAILURE CHECK	26/07/2018	12:00	27/07/2018	14:21	133,116	Derriford	DE024725
31 Charging System	Check vehicle charging See notes						
MDT Failure/Issue							
Breakdown	01/08/2018	12:42	03/08/2018	12:40	133,522	Derriford	DE024761
45 Engine 1	belt tensioner siezed See notes						
Breakdown	LOP and smoke coming into cab						
Vehicle Deep Clean	13/08/2018	06:00	13/08/2018	10:00	134,418	Derriford	DE024827
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/08/2018	07:16	16/08/2018	07:07	134,637	Derriford	DE024842
01 Air Conditioning 1	Body Interior VENTILATION SYSTEM STOPS INTERMITTENTLY,nff						
02 Cab Ass Fire Extinguisher	swapped extinguishers due to service date						
15 Steering 1	Body Exterior STEERING HEAVY,checked ok						
16 Suspension 1	Renewed front lower arms						
18 Wheels Check Torques							
43 Exhaust System 1	Engine FUMES IN CAB,checked unable to fault						
45 Engine 1	Timing chain rattle on inital start up from cold					Monitoring	
71 Body Exterior 1	refitted and secured front grill						

85 Body Interior 1	repaired cupboard shuts						
86 Sliding Door	refitted top catch and secured						
Safety Inspection							
Defect Repair	20/08/2018	06:50	20/08/2018	07:50	134,927	Derriford	DE024864
86 Sliding Door	Investigate not staying closed. Fixings replaced						
Defect Repair	21/08/2018	06:50	21/08/2018	09:12	134,931	Derriford	DE024874
43 Exhaust System 1	Investigate fumes in cab. DPF to turbo refitted to seal exhaust.						
Defect Repair	07/09/2018	06:06	07/09/2018	14:57	136,958	Derriford	DE024975
31 Charging System Battery	checked batteries and system. PCE Att. NFF!!!!						
43 Exhaust System 1	checked for fumes?? unable to fault vehicle						
71 Body Exterior 1	Body Exterior near side rear wheel arch scratch						
Unplanned Repair	14/09/2018	07:35	14/09/2018	11:05	137,750	Derriford	DE025018
71 Body External Steps	step faulty,stripped and repaired step with 2nd hand parts to get on road						
Unplanned Repair	20/09/2018	09:30	20/09/2018	15:35	138,211	Derriford	DE025061
34 Lights	Check for reported o/s headlight wiring fault See notes						
Breakdown	22/09/2018	16:38	26/09/2018	10:49	138,211	Derriford	DE025074
02 Cab Assembly 1	Replaced torch battery						
41 Air Intake	Refit turbo outlet pipe						
86 Sliding Door	Replaced worn side door roller bearing & resecure top door catch						
Breakdown	SIDE DOOR KEEPS OPENING. FUEL SMELL IN CAB						

SAFETY INSPECTION	27/09/2018	07:05	28/09/2018	05:55	138,394	Derriford	DE025113
18 Wheels Check Torques							
34 Lights Bulb Replacement	o/s dipped beam renewed						
45 Engine 1	Timing chain rattle on initial start up from cold						
71 Body Exterior 1	2x corners renewed						
Safety Inspection							
Vehicle Deep Clean	28/09/2018	05:58	28/09/2018	09:55	138,394	Derriford	DE025117
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	01/10/2018	08:07	01/10/2018	08:37	138,394	Derriford	DE025128
55 Tail Lift	Ramp/Lift/Tail Hoist Tail lift damage Straighten stop plate bracket						
Defect Repair	09/10/2018	08:11	16/10/2018	08:57	139,151	Derriford	DE025188
34 Lights Bulb Replacement	Replace headlight bulb						
43 Exhaust System 1	Engine FUMES IN CAB Investigate reported fumes in cab See notes						
45 Engine 1	Found 1 x injector leaking on right hand bank Remove clean resal & refit						
Unplanned Repair	17/10/2018	09:06	18/10/2018	08:42	139,188	Derriford	DE025253
43 Exhaust System 1	Fumes in cab Exhaust clamp replaced by Mercedes of Plymouth P/O151178388						
Travel Time							
Unplanned Repair	23/10/2018	07:18	23/10/2018	08:11	139,629	Derriford	DE025298
Camera Upgrade	Check for CCTV not recording See notes						
	Awaiting Parts						
Unplanned Repair	29/10/2018	07:26	29/10/2018	12:17	139,915	Derriford	DE025330

34 Emergency Lights Replaced n/s/r top body blue light lens

Vehicle Deep Clean 05/11/2018 07:05 05/11/2018 14:04 140,433 Derriford DE025379

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 05/11/2018 13:45 07/11/2018 08:56 140,433 Derriford DE025390

13 Brake Pads	Rear pads renewed	
16 Suspension 1	4x slipper pads renewed	
17 Tyres Replace	NSR & NSF tyres renewed	
18 Wheels Check Torques		
55 Tail Lift	Renew handrail grip bolts	
71 Body Exterior 1	NSF top body corner renewed, Bridge plate guides secured	
71 Body Exterior 2	Spray supression secured	
86 Doors Rear	Corner strenghtening plates fitted	
Camera Upgrade	Check for CCTV not recording See notes	Awaiting Parts
Safety Inspection		
Sealing of stretcher clamp	Sealing of stretcher clamp	
92 - C Service		
Service C		

Unplanned Repair 12/11/2018 08:37 12/11/2018 09:33 140,820 Derriford DE025425

34 Lights Bulb Replacement	NS repeater n/w,renewed bulb
86 Doors Rear	Rear door stay adrift,Drill out and renewed sheared bolt refitted all ok

Breakdown 13/11/2018 22:28 14/11/2018 06:44 140,944 Derriford DE025448

86 Doors Rear	Free off clean adjust and lubed rear door mech
Breakdown	rear door will not open from outside

Emergency Deep Clean 22/11/2018 10:30 22/11/2018 14:00 141,526 Derriford DE025509

Emergency Deep Clean

Unplanned Repair	26/11/2018	08:15	26/11/2018	09:44	141,526	Derriford	DE025519
02 Mirrors	Replace o/s mirror glass, shell & cover						
56 Comms Power Failure	Check battery & charging N.F.F						
86 Door Lock	Strip off rear door inner panel Free off lock & refit						
COMMS.FAILURE CHECK	05/12/2018	07:00	05/12/2018	11:24	143,017	Derriford	DE025606
MDT Failure/Issue	Check batteries & charging all ok reported to logistics for PCE to attend Notes						
Unplanned Repair	06/12/2018	08:00	06/12/2018	08:15	143,058	Derriford	DE025617
34 Lights Bulb Replacement	Replaced n/s side repeator bulb						
Defect Repair	10/12/2018	11:54	10/12/2018	13:24	143,443	Derriford	DE025638
45 Engine 1	Cutting out, poor starting, see notes						
Breakdown	16/12/2018	17:56	17/12/2018	08:34	143,987	Derriford	DE025675
44 Fuel System 1 Breakdown	Check for fuel leak & loss of power N.F.F loss of power; smells of fuel						
Breakdown	17/12/2018	21:31	18/12/2018	11:15	144,076	Derriford	DE025683
03 Instruments & Sensors 1 Breakdown	Check & clear stored fault codes road test all working ok Gone into limp mode keeps cutting out						
SAFETY INSPECTION	19/12/2018	08:49	20/12/2018	12:00	144,144	Derriford	DE025695
02 Cab Assembly 1	Seat armrests secured						
17 Tyres	Investigate NSR inner flat tyre, valve extension renewed						
18 Wheels Check Torques							
34 Lights	OSR & OSF body markers renewed						
71 Body External Steps	Step jamming, freed off						
85 Body Interior 1	Track cupboard shut secured						

Camera Upgrade	Check for CCTV not recording See notes						Awaiting Parts
Safety Inspection							
MOT Pre Test							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Tail Lift Annual Service	Statutory Inspection and Weight Test Done by South west lifts P/O 151181144						
Vehicle Deep Clean	20/12/2018	05:49	20/12/2018	12:43	144,145	Derriford	DE025702
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	24/12/2018	07:30	24/12/2018	08:28	144,408	Derriford	DE025726
71 Body External Steps	Sraighten bent step & lubricate check operation						
Unplanned Repair	27/12/2018	08:19	27/12/2018	12:00	144,619	Derriford	DE025732
Camera Upgrade	N/s front camera replaced By John Coles						
Defect Repair	02/01/2019	08:49	02/01/2019	13:32	145,160	Derriford	DE025766
43 Exhaust System 1	Fumes in cab, check system, wash eng. bay, renew pollen filter, road test						
Breakdown	08/01/2019	05:13	08/01/2019	06:48	145,622	Derriford	DE025804
03 Instruments & Sensors 1	checked for dtcs none stored light off road tested all ok						
Breakdown	LIMP MODE						
Unplanned Repair	09/01/2019	12:30	09/01/2019	13:10	145,713	Derriford	DE025826
86 Sliding Door	Top catch lower bolt hole split fit temp bolt to retain catch part ordered						Awaiting Parts
Breakdown	12/01/2019	12:40	12/01/2019	14:40	146,079	Derriford	DE025846
17 Tyres Replace	O/s/r Tyre replaced by ATS						
Breakdown	Offside outer rear flat tyre						

Unplanned Repair	18/01/2019	11:51	18/01/2019	13:03	146,538	Derriford	DE025891
03 Instruments & Sensors 1 Road Test	Check fo reported limp mode no fault code in system Road test vehicle vehicle driving OK						
Vehicle Deep Clean	30/01/2019	07:04	30/01/2019	10:49	147,954	Derriford	DE025968
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/01/2019	11:58	01/02/2019	13:04	147,954	Derriford	DE025971
13 Brake Pads	Front pads renewed						
17 Tyres	Fit OS extension valve						
18 Wheels Check Torques							
45 Engine 1	Oil leak, injector blowing, NS cylinder bank see notes						
71 Body Exterior 2	Bridge plate guides insecure						
71 Body Exterior 3	NS & OSF bottom body corners renewed						
71 Body External Steps	Step edge renewed						
85 Body Interior 1	Side entrance handrail secured						
86 Sliding Door	Top catch renewed, adjusted links so door stays closed						
Safety Inspection							
Travel Time							
MOT	Done by Mercedes of Plymouth P/O 151181034						
Breakdown	06/02/2019	08:44	06/02/2019	11:46	148,539	Derriford	DE026016
17 Tyres Replace	N/s/f tyre replaced by ATS						
Breakdown	flat tyre n/s front						
Unplanned Repair	18/02/2019	12:00	18/02/2019	12:30	149,713	Derriford	DE026097
34 Lights	Replaced o/s/r body side marker light						
COMMS.FAILURE CHECK	22/02/2019	06:49	22/02/2019	07:38	150,129	Derriford	DE026123
MDT Failure/Issue	Battery/charging checked ok OO to contact Logistics						

Breakdown	03/03/2019	12:33	04/03/2019	14:30	151,170	Derriford	DE026175
17 Tyres Replace Breakdown	Both o/s/r tyres replaced by ATS flat tyre rear offside outer						
Unplanned Repair	06/03/2019	11:00	06/03/2019	14:00	151,533	Derriford	DE026207
03 Instruments & Sensors 1	EML light on checked fault codes See notes						
Vehicle Deep Clean	13/03/2019	05:31	13/03/2019	09:55	152,016	Derriford	DE026246
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/03/2019	12:30	15/03/2019	12:29	152,116	Derriford	DE026256
02 Cab Assembly 1	Cab torch missing replaced with one from shelf						
02 Cab Assembly 2	Refitted cab storage hinges and pivots						
13 Brake Pads	Renewed rear pads						
13 Brakes 1	Brake pedal rubber renewed						
13 Discs	Renewed rear discs						
16 Suspension 1	Removed and renewed rear shocks due to covers badly corroded						
17 Tyres Replace	O/S/F tyre renewed						
18 Wheels Check Torques							
24 Driveshaft 1	Propshaft centre bearing starting to perish						Monitoring
34 Lighting System	Repaired wiring to number plate light						
45 Engine 1	Slight oil leak						Monitoring
45 Engine 2	Removed and renewed air mass as previously ordered						
71 Body Exterior 1	Various bodywork damage						Awaiting Body Repair
89 Seats	Attendants seat adjuster bar missing						
Safety Inspection							
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab						
Unplanned Repair	25/03/2019	06:00	25/03/2019	13:22	152,116	Derriford	DE026316
03 Instruments & Sensors 1	Check & clear stored faults road test all ok at time of test						
45 Engine 1	LOP reported						

Breakdown	28/03/2019	17:51	29/03/2019	09:43	153,098	Derriford	DE026346
34 Lights Bulb Replacement 45 Engine 1 Breakdown	Renewed failed os repeater bulb road tested for fault plugged in unable to fault at time of test. engine stalling and noisy when idling						
Defect Repair	11/04/2019	11:20	11/04/2019	11:43	153,203	Derriford	DE026440
17 Tyres Replace	Renew NSF tyre						
Breakdown	15/04/2019	03:19	15/04/2019	10:32	154,847	Derriford	DE026452
41 Air Intake Breakdown	refit turbo pipe seal Query Turbo Broke						
SAFETY INSPECTION	24/04/2019	06:11	25/04/2019	07:22	155,744	Derriford	DE026529
18 Wheels Check Torques 24 Driveshaft 1 34 Lights 34 Lights Bulb Replacement 45 Engine 1 55 Tail Lift 71 Body Exterior 1 Safety Inspection Replace Handbrake Cables UB Fire Supp 12mts Service Annual Air Con Service Annual Heater Service	Propshaft centre bearing starting to perish ns foglight surround missing OS side light bulb Slight oil leak Tail lift bridge plate runners adrift Various bodywork damage Replace Handbrake Cables Service of fire supression system Annual Air Condition Service,twin system 1hr cab 1.5 body and reciever dryer Annual Heater Service						Monitoring Monitoring Awaiting Body Repair
Unplanned Repair	02/05/2019	12:00	02/05/2019	13:10	156,600	Derriford	DE026598
31 Battery Aux	checked batteries and renewed failed battery						

Breakdown	03/05/2019	12:19	07/05/2019	08:23	156,650	Derriford	DE026606
45 Engine 1 Breakdown	see notes engine cut out, no power						
Unplanned Repair	21/05/2019	13:00	21/05/2019	14:14	158,156	Derriford	DE026722
86 Door handle	Replaced side door outer handle						
COMMS.FAILURE CHECK	22/05/2019	12:00	22/05/2019	14:11	158,175	Derriford	DE026738
MDT Failure/Issue	PCE attended.						
Breakdown	25/05/2019	23:29	30/05/2019	06:30	158,363	Derriford	DE026762
86 Sliding Door Breakdown	strip and re-secure side door top lock Side door top bracket loose						
SAFETY INSPECTION	05/06/2019	08:14	05/06/2019	13:15	159,632	Derriford	DE026823
18 Wheels Check Torques							
24 Driveshaft 1	Propshaft centre bearing starting to perish						
45 Engine 1	Slight oil leak						
71 Body Exterior 1	Various bodywork damage						
Safety Inspection							
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Tail Lift Inspection							
Vehicle Deep Clean	07/06/2019	08:45	07/06/2019	08:47	159,633	Derriford	DE026841
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	07/06/2019	08:00	07/06/2019	14:21	159,880	Derriford	DE026842
Vehicle Deep Clean	Vehicle Deep Clean						

BREAKDOWN	13/06/2019	11:00	13/06/2019	14:55	160,575	Derriford	DE026871
02 Windscreen Wipers	Top windscreen washer bottle						
03 Instruments & Sensors 1	Check & clear stored faults & reset service mileage indicator						
41 Air Intake	Turbo pipe seal has failed replaced seal Pipe support bracket broken						Awaiting Parts
Breakdown	14/06/2019	19:06	17/06/2019	06:48	160,835	Derriford	DE026878
86 Doors Rear	Strip inner door panel free off and adjusted refitted tested ok						
Breakdown	back door cannot open						
Vehicle Deep Clean	18/07/2019	05:47	18/07/2019	09:58	163,992	Derriford	DE027109
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/07/2019	09:50	23/07/2019	10:23	163,992	Derriford	DE027114
02 Cab Ass Fire Extinguisher	O.O.D Swapped fire extinguishers for service						
02 Cab Assembly 1	1 X torch u/s Replaced torch						
03 Instruments & Sensors 1	Check & clear fault codes Road test vehicle ok at time of test						
17 Tyres Replace	Both n/s/r tyres worn Replaced both n/s/r tyres						
18 Wheels Check Torques							
41 Air Intake	Turbo pipe seal has failed replaced seal Pipe support bracket broken						
71 Body Exterior 1	O/s & n/s front fog light trim missing Replaced missing trims						
86 Sliding Door	Side door difficult to open replaced side door roller bearings						
89 Seats	Tighten swivel seat lock pin lock nuts						
Safety Inspection							
Defect Repair	26/07/2019	07:24	26/07/2019	08:16	164,215	Derriford	DE027165
02 Mirrors	NS mirror broken Replace frame & mirror glasses						
Supply Sat Nav	Update sat nav						
Breakdown	28/07/2019	05:42	16/08/2019	13:33	164,493	Derriford	DE027172
002 Major Unit Replace Eng	Engine replaced by Mercedes of plymouth P/O 151190757						

42 Coolant System	Water leak from water pump area
45 Engine 1	Found to require a replacement engine
86 Sliding Door	Side Door exterior handle replaced & top latch resecured
Breakdown	Side door outside handle broken
Supply Sat Nav	
Travel Time	Collect vehicle from dealers

Breakdown	16/08/2019	19:24	19/08/2019	09:52	164,510	Derriford	DE027293
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

34 Emergency Light System Breakdown	see notes aux battery&siern not working
--	--

Unplanned Repair	21/08/2019	11:00	21/08/2019	11:31	164,716	Derriford	DE027324
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

34 Lights	Replace o/s indicator lamp assy
-----------	---------------------------------

Unplanned Repair	24/08/2019	08:33	27/08/2019	08:36	165,169	Derriford	DE027337
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

31 Battery Comms	check batteries and renewed failed comms battery
------------------	--

SAFETY INSPECTION	29/08/2019	07:20	30/08/2019	07:23	165,237	Derriford	DE027349
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Cab Assembly 1	Drivers log book full
02 Cab Assembly 2	renewed cab interior lamp bulb
13 Brake Pads	Renewed front discs and pads including free of sliders
18 Wheels Check Torques	
34 Lights Bulb Replacement	renewed nearside dipped beam bulb
55 Ramp	Free off tail lift platform wheel locator
55 Tail Lift	guides adrift
56 Comms Equipment	EPCR not charging
85 Body Interior 2	Renewed bio safe strap
89 Seats	Attendants seat base adj bar missing
Safety Inspection	
Tail Lift Inspection	

Vehicle Deep Clean	02/09/2019	05:53	02/09/2019	13:24	165,238	Derriford	DE027365
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	10/09/2019	05:00	10/09/2019	07:19	165,811	Derriford	DE027427
43 Exhaust System 1	Read codes road test and regen dpf and road test						
Defect Repair	16/09/2019	05:59	16/09/2019	15:29	165,882	Derriford	DE027470
03 Instruments & Sensors 1 45 Engine 1	Check for faults found particulate filter fault carry out regen clear fault codes lop						
Defect Repair	23/09/2019	04:30	23/09/2019	08:40	166,784	Derriford	DE027514
03 Instruments & Sensors 1	left of service no reason left check and road tested all ok back on service						
Breakdown	23/09/2019	16:18	24/09/2019	12:08	166,863	Derriford	DE027520
41 Air Intake Breakdown	checked vehicle suspect o/s of intercooler failed/leaking, Renewed IN Limp mode - VMU checked						
Breakdown	25/09/2019	05:46	25/09/2019	11:19	167,030	Derriford	DE027532
41 Air Intake Breakdown	Vehicle keeps going into limp mode See notes P/O 151192418 limit to 30MPH will change gear downhill						
Breakdown	27/09/2019	09:48	30/09/2019	12:31	167,030	Derriford	DE027555
03 Instruments & Sensors 1 31 Charging System Breakdown	Check for LOP no faults in system vehicle driving ok Check batteries & charging systems all ok Loss of Power						
SAFETY INSPECTION	08/10/2019	06:12	08/10/2019	13:32	167,984	Derriford	DE027631

13 Brake Pads	Rears low
17 Tyres Replace	OSF punctured NSF 3mm on inner edge
18 Wheels Check Torques	
55 Tail Lift	Reattach tail lift runners
85 Body Interior 1	white board adrift
89 Seats	attendants seat bar missing
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service

Vehicle Deep Clean	10/10/2019	08:30	10/10/2019	12:57	168,161	Derriford	DE027663
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	04/11/2019	07:00	04/11/2019	14:09	170,668	Derriford	DE027853
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

01 Heating 1	Saloon heater n/w See Notes
71 Body External Steps	Side step intermitant Renew side step motor
Supply Sat Nav	Sat nav n/w

Breakdown	09/11/2019	16:08	13/11/2019	14:35	171,555	Derriford	DE027906
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Breakdown	MDT not plotting
-----------	------------------

Vehicle Deep Clean	22/11/2019	06:07	22/11/2019	10:59	172,496	Derriford	DE027987
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Tail Lift 12M Service & Weight	22/11/2019	11:00	22/11/2019	13:16	172,496	Derriford	DE027991
---	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight Done by South west lifts P/O 151194851
Tail Lift Inspection	

Breakdown	22/11/2019	22:01	25/11/2019	08:44	172,982	Derriford	DE027992
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

34 Emergency Light System	siren checked unable to fault
Breakdown	sirens u/s

SAFETY INSPECTION	25/11/2019	08:41	26/11/2019	09:43	173,102	Derriford	DE027998
03 Instruments & Sensors 1	Awaiting Body Repair						
17 Tyres Replace							
18 Wheels Check Torques							
34 Lighting System							
71 Body External Steps							
71 Body External W&T Repair							
85 Body Interior 1							
86 Sliding Door							
Safety Inspection							
Breakdown	06/12/2019	05:02	06/12/2019	13:12	173,104	Derriford	DE028085
Breakdown	O/S rear outer flat again Checked N.F.F						
Unplanned Repair	24/12/2019	07:34	24/12/2019	12:15	176,051	Derriford	DE028231
34 Lights Bulb Replacement							
71 Body External Steps							
89 Seats							
Vehicle Deep Clean	31/12/2019	05:52	31/12/2019	12:55	176,263	Derriford	DE028259
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	02/01/2020	07:02	14/01/2020	14:22	176,824	Derriford	DE028263
02 Cab Assembly 1							
02 Windscreen Wipers							
03 Instruments & Sensors 1							
16 Suspension 1							
18 Wheels Check Torques							
31 Battery Comms							
34 Emergency Lights							
34 Lights							
43 Exhaust System 1							

71 Body Exterior 1	OSR wheel arch damage
71 Body External W&T Repair	Various bodywork damage At Autospray
86 Doors	NS cab door stay broken away from pillar
86 Doors Rear	Catches/handle reqs adjustment
Safety Inspection	
Engine Change Oil & Filter	
MOT	Done by Mercedes of plymouth P/O 151195029

SAFETY INSPECTION	12/02/2020	11:25	13/02/2020	11:29	179,193	Derriford	DE028625
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

18 Wheels Check Torques	
34 Lights	OSF top body marker renewed
41 Air Intake	Pollen filter housing secured
86 Sliding Door	Bottom magnet renewed
Safety Inspection	
Brakes Replace Brake Fluid	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change

Vehicle Deep Clean	13/02/2020	12:13	14/02/2020	09:45	179,193	Derriford	DE028634
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	24/02/2020	08:13	24/02/2020	16:58	180,089	Derriford	DE028691
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

71 Body Exterior 1 Breakdown	Checked for accident damage found o/s shadowglass window broken see notes Check vehicle for faults Road tested all ok n.f.f	Awaiting Parts
------------------------------	--	----------------

Breakdown	16/03/2020	18:04	17/03/2020	09:36	182,519	Derriford	DE028860
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

31 Battery Comms	renewed
34 Lights	n/s scene renewed
Breakdown	MDT etc shutting down

Vehicle Deep Clean	26/03/2020	05:58	26/03/2020	13:56	183,220	Derriford	DE028929
---------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/03/2020	16:07	28/03/2020	15:30	183,220	Derriford	DE028935
02 Windscreen Wipers	washers weak replace o/s washe rjet						
13 Brake Pads	Replaced rear pads						
17 Tyres Replace	Replaced o/s/front & both n/s/r tyres						
18 Wheels Check Torques							
27 Transmission Automatic	Gear box oil leak Clean off sump & tighten sump bolts						
31 Battery Comms	Battery/Charging Sys Power failing comms battery already been replaced						
Camera Upgrade	Reverse camera not working requires John Coles to repair						
Safety Inspection							
Tail Lift Inspection							
Replace Handbrake Cables	Replace Handbrake Cables See notes						
Annual Air Con Service	Annual Air Condition Service unable free off pipes to dryer						
Annual Heater Service	Annual Heater Service						
Unplanned Repair	09/04/2020	10:00	09/04/2020	14:00	184,399	Derriford	DE029060
Annual Air Con Service	Air con pipes replaced by Espar P/O 151201751						
Unplanned Repair	17/04/2020	10:00	17/04/2020	13:39	185,048	Derriford	DE029142
31 Battery Chassis	Check for charging issues Replace faulty chassis battery						
Vehicle Deep Clean	04/05/2020	07:18	04/05/2020	12:16	186,668	Derriford	DE029299
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	24/05/2020	09:31	24/05/2020	13:58	186,668	Derriford	DE029467
17 Tyres Replace	N/s/r outer tyre replaced by ATS						
Breakdown	REAR N/S TYRE						

Awaiting Parts

Monitoring

ACCIDENT	04/06/2020	06:09	16/06/2020	13:48	188,795	Derriford	DE029559
-----------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

71 Body Exterior 1	OS body damage side panel holed						
--------------------	---------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	17/06/2020	14:08	20/06/2020	14:54	189,340	Derriford	DE029665
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Cab Ass Fire Extinguisher	Swap cab fire extinguishers for service						
02 Cab Assembly 1	Replace missing centre storage box button & replace 1 x torch						
02 Cab Assembly 2	Fused box cover missing					Awaiting Parts	
03 Instruments & Sensors 1	Reset service mileage indicator & cleared stored faults						
13 Brake Pads	Replaced front brake pads						
17 Tyres Replace	Replace n/s/f tyre						
18 Wheels Check Torques							
34 Emergency Lights	Replace n/s/r body blue light assy						
34 Lights Bulb Replacement	Replace both front side light bulbs & n/s main beam bulb						
71 Body Exterior 1	Resecure tail lift bridge plate sliders						
85 Body Interior 1	Resecure swivel seat armrest						
89 Seats	Drivers seat base cover starting to fray					Monitoring	
Camera Upgrade	Reverse camera n/w awaiting contractor					Awaiting Parts	
Safety Inspection							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Awaiting new jactone system					Awaiting Parts	
Tail Lift Inspection							

Breakdown	04/07/2020	05:16	05/07/2020	13:03	192,008	Derriford	DE029798
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

02 Windscreen	Replaced by National windscreens						
Breakdown	passengers side chip on windscreen 7.5 cm wide						

SAFETY INSPECTION	31/07/2020	06:43	03/08/2020	13:40	194,080	Derriford	DE029985
--------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

01 Air Conditioning 1	N/W, investigate Requires specialist repair					Partially Completed	
02 Cab Ass Fire Extinguisher	Saloon swapped						
02 Cab Assembly 2	Fused box cover missing						
02 Windscreen Wipers	Reposition OS arm						
16 Suspension 1	3x spring pads renewed, pick up parts						
17 Tyres Replace	OSR tyres renewed						

18 Wheels Check Torques							
34 Lights	No. plate wiring repaired						
86 Sliding Door	Top magnet rubber renewed					Monitoring	
89 Seats	Drivers seat base cover starting to fray					Monitoring	
Camera Upgrade	Reverse camera n/w awaiting contractor					Monitoring	
Safety Inspection							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Awaiting new jactone system					Awaiting Parts	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Tail Lift Inspection							

Breakdown	11/08/2020	07:59	11/08/2020	15:45	195,231	Derriford	DE030068
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Breakdown	Air Con Not Working awaiting specialist repair
-----------	--

Breakdown	16/08/2020	18:34	17/08/2020	14:17	195,977	Derriford	DE030117
------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

42 Coolant System	Radiator replaced at Torquay w/shop
Breakdown	lost coolant - overheating

BREAKDOWN	17/08/2020	07:55	18/08/2020	13:33	195,977	Torquay	TO018764
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

42 Radiator	pressure tested system crack in n/s of rad REPLACED
45 Engine 1	Engine Broke down. Recovered to Torquay

ACCIDENT	12/09/2020	10:58	18/09/2020	09:10	198,258	Derriford	DE030334
-----------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

Breakdown	Sidestep constant audible alarm, Step replaced by Autospray.
Travel Time	pick up from autospray

Unplanned Repair	02/10/2020	05:30	02/10/2020	06:44	199,727	Derriford	DE030470
-------------------------	-------------------	--------------	-------------------	--------------	----------------	------------------	-----------------

86 Doors Rear	Checked for rear door opening and no audible warning unable to fault
---------------	--

SAFETY INSPECTION	05/10/2020	11:37	07/10/2020	12:03	199,964	Derriford	DE030489
01 Air Conditioning 1	Rear condensor & fan assy replaced by Espar P/O 151208117						
02 Cab Assembly 1	Fit missing fuse box cover						
17 Tyres Replace	Replaced o/s/f tyre						
18 Wheels Check Torques							
41 Air Intake	Refit turbo pipe seals						
71 Body External Steps	Removed n/s seat and rewired step						
86 Sliding Door	Top magnet rubber renewed						
87 Boards	Scoop 039528						
89 Seats	Drivers seat base cover starting to fray, Renewed						
Camera Upgrade	Reverse camera n/w awaiting contractor						
Safety Inspection	Awaiting Parts						
Supply Sat Nav	upgraded software						
UB Fire Suppression Discharge	Replace fire suppression system with Jactonr system						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
UB Fire Supp 12mts Service	Service of fire suppression system						
Axle Oil Change	Axle Oil Change						
Engine Change Oil & Filter							
Vehicle Deep Clean	08/10/2020	12:44	08/10/2020	12:45	199,988	Derriford	DE030516
Vehicle Deep Clean	08/10/2020	12:45	08/10/2020	17:55	200,008	Derriford	DE030517
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	17/10/2020	16:16	19/10/2020	06:04	201,022	Derriford	DE030573
Breakdown	RNS - slow puncture - can hear air escaping						
Unplanned Repair	23/10/2020	11:24	23/10/2020	11:26	201,695	Derriford	DE030615
17 Tyres Replace	renewed n/s/r/i						

Breakdown	04/11/2020	18:12	05/11/2020	15:52	203,196	Derriford	DE030681
56 Comms Equipment Breakdown	Reset MDT Screen & check vehicle charging MDT/Satnav/Comms No power/battery check						
MRO Refresh	05/11/2020	14:29	05/11/2020	17:29	203,198	Derriford	DE030690
MRO Refresh							
Vehicle Deep Clean	17/11/2020	07:13	17/11/2020	12:55	204,511	Derriford	DE030765
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	17/11/2020	14:09	19/11/2020	14:06	204,512	Derriford	DE030771
02 Windscreen Wipers	Adjust sweep						
13 Brake Pads	Renew Front discs & pads, rear pads						
16 Suspension 1	Rear anti roll bar link bushes renewed						
18 Wheels Check Torques							
27 Transmission Automatic	Sump clamp renewed						
31 Battery Aux	Secure terminals						
43 Exhaust System 1	DPF split, unit renewed						
71 Body Exterior 1	Renew No. plate, fit correct front tyre pressure decal						
71 Body Exterior 2	Renew osr bottom body corner, secure bridge plate guides						
Safety Inspection							
Tail Lift Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight South west lifts P/O 151209733						
BREAKDOWN	30/11/2020	13:48	30/11/2020	13:52	205,684	Derriford	DE030856
02 Mirrors	Mirrors Nearside mirror damaged						
SAFETY INSPECTION	17/12/2020	06:40	18/12/2020	08:58	207,847	Derriford	DE030991
02 Cab Assembly 1	Centre storage unit button renewed						
02 Windows/Glass	Pass. window switch renewed						

02 Windscreen Wipers	Renew blades
16 Suspension 1	Front strut shrouds renewed
18 Wheels Check Torques	
86 Sliding Door	Top catch secured
Safety Inspection	
Pollen Filter Change	Pollen Filter Change
Fuel Filter Change	Change Fuel Filter
Air Filter Change	Air Filter Change

PDI Inspection	21/12/2020	15:14	23/12/2020	14:06	208,376	Torquay	TO019414
-----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	fitted new rubber floor mats
33 Ignition System	replaced key fob battery
86 Sliding Door	side door top latch lose drilled and re rivited
87a - Medical Equipment Repair	replaced ecs battery 62% no1
89 Seats	replaced missing saloon seat adjuster
Check Vehilce Call Signs	Check vehilce call signs are fitted and correct removed old fitted new
Medical Devices Check	fitted corect pedimate for stretcher
PDI Inspection	

Vehicle Deep Clean	23/12/2020	13:14	24/12/2020	12:37	208,376	Torquay	TO019432
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	16/01/2021	10:55	16/01/2021	12:31	210,089	Torquay	TO019579
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	os headlight inop - REPLACED
----------------------------	------------------------------

BREAKDOWN	21/01/2021	08:00	22/01/2021	09:58	210,489	Torquay	TO019622
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Heating 1	heaqter blower motor faulty - NOTE
02 Cab Assembly 1	glovebox light inop - REPLACED 239 bulb
34 Lights Bulb Replacement	spare bulb replaced

MOT EXPIRES	23/01/2021	06:32	25/01/2021	15:46	210,502	Torquay	TO019629
--------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace	nsr outer tyre 3mm - REPLACED WITH SPARE, MATCHED TO OTHER 6MM TYRE
------------------	---

18 Wheels Retorque	
34 Lighting System	ns headlamp missing rear moisture cover - REPLACED FROM SPARE
34 Lights	both sidelights fallen out of holders - REPOSITIONED
43 Exhaust System 1	Exhaust rusted and holed - REPLACED
45 Engine 1	checked for engine missfire limp mode ? checked & rlt all ok ??
45 Engine Oil Top Up	ADDED 1 LTR CARGO MAXX
86 Sliding Door	top magnet bent - ADJUSTED
89 Seats	both JANY seat swivel pins loose - TIGHTENED
MOT	Take to test
UB Fire Suppression Service	JACTONE bottle insecure - RESECURED

Vehicle Deep Clean	09/02/2021	13:26	10/02/2021	11:40	211,505	Torquay	TO019729
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	10/02/2021	14:50	11/02/2021	14:26	211,505	Torquay	TO019737
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windows/Glass	screw missing in window - REPLACED	
18 Wheels Check Torques		
24 Driveshaft 1	Centre prop dohnut starting to split - MONITOR	Monitoring
31 Battery Chassis	chassis battery bad - REPLACED	
34 Emergency Lights	nsr scene light 50% in op - MONITOR	Monitoring
34 Lights	ns + os amber marker lights inop - NO PARTS	Monitoring
41 Turbo	turb boost pipe adrift - NOTE	
42 Coolant System	expansion bottle broken - REPLACED	
55 Ramp	bridge guides loose - REPLACED 2 x FIXINGS	
71 Body Exterior 1	Body Exterior scraped r side on sign	
85 Body Interior 1	saloon bag storage strap broken - REPLACED WITH SPARE	
86 Doors Rear	door handle sticking - LUBRICATED	
86 Sliding Door	top magnet adrift - ADJUSTED	
87 Oxygen System	oxygen pressure switch not sounding when oxygen pressure low. Kev B to attend	
89 Seats	Jany seat 2 swivel pin loose - TIGHTENED	
Safety Inspection		
Tail Lift Inspection		

Unplanned Repair	15/02/2021	13:45	15/02/2021	15:15	211,990	Torquay	TO019759
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Emergency Light System	resequired n\s r top blue corner lamp repaired roof
34 Lights Bulb Replacement	replaced o\s main beam bulb

Unplanned Repair	08/03/2021	13:42	08/03/2021	13:59	214,323	Torquay	TO019863
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	bulb replaced, cleaned up 'furry' contacts						
----------------------------	--	--	--	--	--	--	--

Vehicle Deep Clean	21/03/2021	08:54	21/03/2021	14:53	215,464	Torquay	TO019919
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	23/03/2021	11:04	24/03/2021	07:13	215,464	Torquay	TO019928
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	both washer tubes split and spraying onto scuttle - REPLACED HOSES						
17 Tyres Replace	R tyres on trust limit - REPLACED						
18 Wheels	tyre tags damaged x 2 - REPLACED						
18 Wheels Check Torques							
24 Driveshaft 1	Centre prop dohnut starting to split - MONITOR					Monitoring	
34 Emergency Lights	nsr scene light 50% in op - MONITOR					Monitoring	
34 Lights	ns + os amber marker lights @50%					Monitoring	
45 Engine Oil Top Up	OIL LEVEL ON MINIMUM MARKER - TOPPED UP						
55 Tail Lift	both handrails loose - ADJUSTED N/S. REPLACED STANCHION BOLTS O/S						
86 Door Lock	both door locks insecure on side door - NOTE						
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables - LINKED IN MOT NOT UNTIL 01/02/2022 C/H AWARE						
Annual Air Con Service	Annual Air Condition Service						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Tail Lift Inspection							

Breakdown	05/04/2021	18:40	06/04/2021	09:59	217,246	Torquay	TO020003
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

71 Body External Steps	step bent and side runners twisted - ADJUSTED AND REPAIRED						
Breakdown	side step not deploying; VOR						

MRO Refresh	01/05/2021	09:51	01/05/2021	14:42	218,000	Launceston	LA014702
--------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

MRO Refresh							
-------------	--	--	--	--	--	--	--

SAFETY INSPECTION	19/05/2021	06:00	11/06/2021	11:30	219,006	St Leonards	SL033282
01 Air Conditioning 1	Clean out air intake box. Replace dust filter.						
02 Windscreen	Windscreen leaking water into cab						
02 Windscreen Wipers	Wipers juddering. Excessive play in wiper motor. Replace unit.						
13 Brakes 1	Replace rear discs, pads and calipers - F/Comms to replace						
13 Handbrake	Handbrake shoes replaced by F/Comms.						
15 Steering 1	Steering rack - F/Comms						
16 Suspension 1	Replace wishbones and front struts - F/Comms						
17 Tyres	Fit missing tyre valves - F/Comms						
18 Wheels Check Torques							
24 Driveshaft 1	Centre prop dohnut starting to split - F/Comms to replace						
34 Emergency Lights	N/S/R & O/S On Scene Lights U/S						
34 Lighting System	Rear upper red High Resitance. Fault found to main supply loom Damaged.						
34 Lights	Replace Marker lights down o/s of Unit as U/S						
44 Add Ad Blue	Top up unit 19.2 L						
45 Engine 1	Oil cooler leaking - F/Comms to replace						
45 Engine Ad Blue	Replace damaged cap						
52 Electrical Aux	Replace Damaged O/S/F Window switch.						
71 Body Exterior 1	Damage to N/S/R .						
86 Door Lock	Replace saloon door locks - F/Comms						
86 Door Seals	Replace O/S/F Door seal.						
Replace Handbrake Cables	Replace Handbrake Cables - Carried out by F/Comms						
Safety Inspection							
Wear & Tear Repair	Replace worn out Brake peddle rubber.						
Annual Heater Service	Annual Heater Service						
Vehicle Deep Clean	20/05/2021	06:48	20/05/2021	09:00	219,006	St Leonards	SL033292
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/06/2021	06:00	14/06/2021	09:00	219,034	St Leonards	SL033506
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
Vehicle Deep Clean	14/06/2021	10:46	14/06/2021	13:30	219,034	St Leonards	SL033519

Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	23/06/2021	11:17	23/06/2021	13:15	220,086	St Leonards	SL033602
55 Tail Lift Breakdown	Tail lift hose split - Replaced by SWL @ scene leaking fluid/ramp stuck down						
Breakdown	28/06/2021	16:54	30/06/2021	16:00	221,061	St Leonards	SL033635
45 Engine 1	Fumes in cab. Ferndown Comms 3000 pound repair . Not Repaired. ?????						
52 Electrical Aux	240 volts sockets damaged/inop? (Reported by crew) No Fault Found						
55 Tail Lift	Tail lift stuck. Fluid leak.						
56 Comms Equipment	Hand portable batteries not charging. Replace charger port.						
86 Doors	Drivers door not closing properly						
86 Doors Rear	Rear door stay bent. No Fault Found						
Breakdown	tail lift hydraulic fluid leak - stuck down						
Unplanned Repair	05/07/2021	06:00	06/07/2021	15:00	221,062	St Leonards	SL033683
27 Transmission Automatic	Stuck in park. Remove Dash. Fit S/H Gear pos sensor. refit Dash.						
Unplanned Repair	16/07/2021	06:00	16/07/2021	06:30	221,473	St Leonards	SL033822
44 Add Ad Blue	Top up Ad blue						
SAFETY INSPECTION	04/08/2021	07:00	06/08/2021	15:00	222,470	St Leonards	SL034010
01 Air Conditioning 1	Air con u/s Repair leaks & Re Gas.						
17 Tyres Replace	Replace O/S/R inner Tyre. Due to nail						
18 Wheels Check Torques	Checked.						
34 Lighting System	Replace both R/Door lights.						
44 Add Ad Blue	Top up unit 11L						
86 Door Lock	Replace all saloon locks . As no Keys.						

87 Oxygen System	Replace Oxygen low warning System with S/H unit .						
Safety Inspection	Checked.						
Tail Lift Inspection	Checked.						
Vehicle Deep Clean	06/08/2021	09:28	06/08/2021	13:00	222,470	St Leonards	SL034043
Vehicle Deep Clean	Vehicle Deep Clean						
02 Pipeline Annual Inspection	14/08/2021	11:00	14/08/2021	12:00	222,858	MDT Weymouth	DW000678
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - faults see notes						
SAFETY INSPECTION	22/09/2021	06:30	23/09/2021	15:00	225,953	St Leonards	SL034418
02 Windscreen Wipers	Replace both units						
13 Brakes 1	Replace F/Pads Free off slides.						
17 Tyres Replace	Replace both F/Tyres.						
18 Wheels Check Torques	Checked						
34 Lighting System	Repair damaged n/s Headlight.						
34 Lights Bulb Replacement	Replace N/S/F Side light.						
44 Add Ad Blue	Top up unit 9L						
44 Fuel System 1	Repair Fuel flap. Replace missing cap. Repair damaged neck						
52 Electrical Aux	Refit Tracker.						
Safety Inspection	Checked						
Vehicle Deep Clean	23/09/2021	08:38	24/09/2021	10:00	225,953	St Leonards	SL034430
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	04/10/2021	06:46	08/10/2021	12:00	226,673	St Leonards	SL034539
45 Engine 1	Injectors blowing - Rygor Swindon to repair strong diesel fumes in the cabin and the back						
Breakdown							

Vehicle Deep Clean	01/11/2021	07:05	01/11/2021	09:10	228,328	St Leonards	SL034825	
Vehicle Deep Clean	Vehicle Deep Clean							
SAFETY INSPECTION	01/11/2021	08:49	02/11/2021	08:23	228,328	St Leonards	SL034826	
02 Cab Ass Fire Extinguisher	Out of date. Replaced x2.							
18 Wheels Check Torques	Checked.							
71 Body Exterior 1	N/S of front bumper damaged. Monitor					Monitoring		
Safety Inspection	Carried out inspection.							
Engine Change Oil & Filter	Done.							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service							
Tail Lift Inspection	Done.							
UB Fire Supp 12mts Service	Service of fire supression system							
Unplanned Repair	18/11/2021	08:00	18/11/2021	11:00	228,883	St Leonards	SL034994	
71 Body Exterior 1	N/S of front bumper damaged. Monitor					Monitoring		
71 Body External Steps	Side step smashed off. Replaced							
Unplanned Repair	24/11/2021	13:00	24/11/2021	13:30	229,024	St Leonards	SL035065	
86 Doors	Replace side door locating catch							
SAFETY INSPECTION	10/12/2021	07:53	11/12/2021	06:45	230,044	Dorchester	DC026537	
02 Cab Assembly 1	toolbox coer/footplare damaged							
02 Windscreen Wipers	washers blocked							
16 Suspension 1	Slipper pads u/s							
16 Suspension 2	Rear shock leaking							
18 Wheels Check Torques								
45 Engine Ad Blue	top up							
71 Body Exterior 1	N/S of front bumper damaged. Monitor					Monitoring		
85 Body Interior 1	cupboard damaged							
85 Body Interior 2	microphone damaged					Monitoring		
85 Body Interior 3	Clock missing					Monitoring		
86 Doors	slide door top magnet bent							

86 Doors Rear 86 Sliding Door Safety Inspection Travel Time	Rear door stay pivot snapped bearings rough						
Vehicle Deep Clean	08/12/2021	09:29	09/12/2021	06:14	230,011	St Leonards	SL035180
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	26/12/2021	21:09	29/12/2021	08:30	231,359	St Leonards	SL035309
31 Battery Chassis 31 Charging System Battery Breakdown	Replaced Battery warning light on dash ramp not functioning , battery sign come on						
Breakdown	27/12/2021	08:21	29/12/2021	09:00	231,359	St Leonards	SL035311
45 Engine 1 45 Engine Ad Blue Breakdown	EML/LOP. Set up Texa and check faults, road test, Faults caused by low voltage Ad blue warning light on - Set up Texa, check levle and road test, NFF. Loss of power, no lights and limp mode						
Breakdown	06/01/2022	16:09	07/01/2022	06:30	231,809	St Leonards	SL035408
Breakdown	R N/S puncture inner						
Breakdown	08/01/2022	10:05	10/01/2022	06:44	232,025	St Leonards	SL035418
Breakdown	Orange EML. Checked, topped Ad-Blu 15Ltrs						
SAFETY INSPECTION	14/01/2022	07:00	18/01/2022	14:00	232,407	St Leonards	SL035463
02 Mirrors 18 Wheels Check Torques 45 Engine 1 71 Body Exterior 1 85 Body Interior 2 85 Body Interior 3	Replace damaged n/s mirror Checked. Bulk head sound/heat proofing ripped off. FIRE HAZARD. N/S of front bumper damaged. Repaired. microphone damaged. NO PARTS. Clock missing. NO PARTS.						

86 Doors Rear Safety Inspection Tail Lift Inspection MOT	Stiff to open from inside.Adjusted & Lubed. Inspected. Done.						
Vehicle Deep Clean	17/01/2022	09:59	17/01/2022	13:00	232,407	St Leonards	SL035480
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	20/01/2022	13:00	27/01/2022	15:00	232,684	St Leonards	SL035530
85 Body Interior 1 86 Sliding Door	Side door catch mount rivets pulled out of side door - Autospray to repair Door handle snapped off. Replaced and adjust cables						
Breakdown	10/02/2022	09:54	10/02/2022	10:30	233,929	St Leonards	SL035725
34 Lights Bulb Replacement Breakdown	Replace o/s headlight bulb O/S headlight Blown						
Breakdown	20/02/2022	23:29	21/02/2022	07:16	233,987	St Leonards	SL035789
Breakdown	MANGA ELK BROKEN END OF CHARGING CABLE SNAPPED						
O2 Pipeline Annual Inspection	11/03/2022	09:49	11/03/2022	09:52	236,619	MDT Ferndown	TF001850
02 Pipeline Annual Inspection 87 Oxygen System	Annual Inspection and Pressure Test - passed all test Replaced a leaking outlet port seat.						
SAFETY INSPECTION	15/03/2022	13:00	17/03/2022	14:00	236,780	St Leonards	SL035977
18 Wheels Check Torques Safety Inspection 34 Emergency Lights	Checked. Carried out inspection. Emg Warning Devices O/S rear blue cracked						

Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Brake Fluid Change	Brake Fluid Change						
13 Brake Pads	Rear pads worn. Replaced.						
02 Cab Assembly 1	Drivers sun visor torn.						
85 Body Interior 1	Linen cupboard corner broken.					Monitoring	
01 Air Conditioning 1	N/W in cab.checked for leaks and repair. Regassed system and checked,OK.						

Vehicle Deep Clean	17/03/2022	09:00	18/03/2022	13:00	236,780	St Leonards	SL035996
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	11/04/2022	23:18	19/04/2022	15:00	238,308	St Leonards	SL036180
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Fumes in the cab
45 Engine 1	Fumes in cab. A bye product of poor repair carried out by Ferndown Comm.
45 Engine 2	L.O.P Again due to poor repairs carried out by F/C
45 Engine 3	Carry out full scan to determine the extent of damage.
71 Body Exterior 1	Repairs needed to bulk head. Fire Damage by poor repair.

Unplanned Repair	21/04/2022	14:00	22/04/2022	14:00	238,506	St Leonards	SL036262
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

32 Starting System 1	Starter motor u/s
34 Lights	Indicator fault
45 Engine Ad Blue	Ad blue warning light on
86 Sliding Door	Side door central locking inop

Unplanned Repair	28/04/2022	11:00	09/05/2022	16:00	238,807	St Leonards	SL036349
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	Fumes in cab - Rygor Westbury to repair
001 Recover Vehicle	Vehicle Recovery

Breakdown	09/05/2022	07:01	09/05/2022	10:00	238,555	St Leonards	SL036453
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	RECOVERY BOOKING FOR RETURN TO W/S
-----------	------------------------------------

Vehicle Deep Clean	10/05/2022	13:56	10/05/2022	14:05	238,837	St Leonards	SL036496
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	11/05/2022	05:52	11/05/2022	09:00	238,837	St Leonards	SL036497
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	11/05/2022	06:00	11/05/2022	06:00	238,837	St Leonards	SL036500
18 Wheels Check Torques Safety Inspection							
SAFETY INSPECTION	11/05/2022	06:00	11/05/2022	12:00	238,837	St Leonards	SL036501
18 Wheels Check Torques Safety Inspection 34 Emergency Light System Replace Handbrake Cables Tail Lift Inspection 02 Cab Assembly 1 Pollen Filter Change 34 Emergency Lights 02 Cab Ass Fire Extinguisher 86 Doors Rear 55 Tail Lift 34 Lights 85 Body Interior 1	Lighting System Impact Damage to O/S rear blue light Replace Handbrake Cables Replace centre console button Pollen Filter Change Seal up cracked n/s/f blue light cover Replaced x1 Secure rear door stay Free off siezed gate adjuster Repair n/s/r side marker wiring Replace CCTV struts						
Unplanned Repair	21/06/2022	13:00	21/06/2022	13:30	240,907	St Leonards	SL036888
86 Sliding Door	Secure top and bottom catches and replace cover						
Unplanned Repair	29/06/2022	11:30	29/06/2022	12:45	241,528	St Leonards	SL036954
85 Body Interior 1	Mobi Med not charging						

Unplanned Repair	06/07/2022	08:45	06/07/2022	09:00	242,549	St Leonards	SL037028
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights Bulb Replacement	Replace n/s running light bulb
45 Engine Oil Top Up	Top up engine oil
02 Windscreen Wipers	Top up screenwash

Vehicle Deep Clean	12/07/2022	11:30	13/07/2022	15:00	243,230	St Leonards	SL037092
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	13/07/2022	11:33	15/07/2022	11:12	243,230	St Leonards	SL037104
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.	
Safety Inspection	Carried out inspection.	
Wheel Hub Flanges Replacement	Cleaned rims, replaced flanges.	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service	
Tail Lift Inspection	Done.	
31 Charging System	Battery/Charging Sys Not Charging from Shoreline	
13 Brakes 1	Front disc's & Pads worn. Replaced.	
13 Calipers	Sliders siezed n/s& o/s. Replaced.	
55 Tail Lift	Platform lights n/w. No Parts.	Monitoring
17 Tyres	N/S/F low tread. Replaced.	
Install Saloon CCTV Camera	N/W. Checked, format hard drive. Checked OK.	
34 Emergency Lights	Rear reds n/w.Trace fault to conection @ Genisys. Replaced broken lights x2.	
02 Cab Assembly 1	N/S door trunking adrift. Refitted.	

SAFETY INSPECTION	03/10/2022	08:13	03/10/2022	08:14	245,150	St Leonards	SL037686
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	

SAFETY INSPECTION	03/10/2022	08:14	04/10/2022	11:00	245,150	St Leonards	SL037687
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques		
Safety Inspection		
71 Body Exterior 1	Body Exterior scrapes to paintwork.	
89 Seats	Saloon seat cover worn	Monitoring
17 Tyres Replace	Replace 2x worn tyres and 4x XTV tyre valves	
02 Glass / Windows	Replace window switch	

85 Body Interior 1	Replace microphone	
45 Engine 1	Replace 2x engine mounts	
89 Seatbelts	Replace seat belt buckle	
55 Tail Lift	Replace platform light	
45 Engine 2	oil leak	Monitoring
24 Driveshaft 1	Prop dounut split. replaced with 2nd hand	

Vehicle Deep Clean	04/10/2022	11:34	04/10/2022	11:36	245,150	St Leonards	SL037702
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Vehicle Deep Clean	04/10/2022	11:36	05/10/2022	08:00	245,150	St Leonards	SL037703
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Breakdown	17/11/2022	07:41	17/11/2022	08:45	253,366	St Leonards	SL038123
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	loose wing mirror						
02 Mirrors	Mirror glass loose						

Breakdown	20/11/2022	10:54	21/11/2022	05:30	253,564	St Leonards	SL038169
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Wont start withou reset						
Monitoring							

Unplanned Repair	07/12/2022	14:24	07/12/2022	15:12	254,579	St Leonards	SL038371
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Charging System	Battery/Charging Sys Shireline Pin Bent						
31 Battery Chassis	Battery poor						
Travel Time							

Vehicle Deep Clean	06/01/2023	09:06	06/01/2023	09:08	256,227	St Leonards	SL038719
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Vehicle Deep Clean	06/01/2023	09:08	06/01/2023	16:04	256,227	St Leonards	SL038720
--------------------	------------	-------	------------	-------	---------	-------------	----------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/01/2023	10:00	07/01/2023	10:00	256,227	St Leonards	SL038732
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	07/01/2023	10:00	16/01/2023	16:00	256,227	St Leonards	SL038733
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

89 Seats	Saloon seat cover worn	Monitoring
----------	------------------------	------------

Annual Air Con Service	Annual Air Condition Service
------------------------	------------------------------

Annual Heater Service	Annual Heater Service
-----------------------	-----------------------

Tail Lift Inspection	Corrosion on tail lift, main frame + brackets, lift frame and reservoir.	Monitoring
----------------------	--	------------

Engine Change Oil & Filter

UB Fire Supp 12mts Service	Service of fire suppression system
----------------------------	------------------------------------

Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
--------------------------------	--------------------------------

MOT

UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
---------------------------	---------------------------

02 Cab Ass Fire Extinguisher	Both fire extinguishers out of date. replaced
------------------------------	---

02 Windscreen Wipers	nsf washer jet not spraying correctly. replaced
----------------------	---

86 Sliding Door	sliding door upper locator damaged. replaced locator and adjusted
-----------------	---

87 Stretcher	stretcher ram incorrectly fitted, hoses twisted. refitted and adjusted hoses.
--------------	---

45 Engine 1	fan belt tensioner leaking oil. replace tensioner
-------------	---

16 Suspension 1	rear anti roll bar drop link bushes worn. replaced bushes
-----------------	---

13 Brakes 1	rear brake pads and discs worn. replace
-------------	---

71 Body Exterior 1	OSR Lower corner cap damaged. replaced corner cap.
--------------------	--

34 Lights	ns upper indicator damage. ns side marker damage. replace both.
-----------	---

42 Coolant System	coolant leak from reservoir. replace reservoir
-------------------	--

55 Tail Lift	tail lift bridge plate guides loose. resecure
--------------	---

43 Exhaust System 1	tailpipe ruber hanger perished. replaced (spare part)
---------------------	---

71 Body Exterior 2	Replace front number plate
--------------------	----------------------------

89 Seatbelts	drivers seatbelt fraying. replace seatbelt
--------------	--

41 Air Intake	Air box damaged. replace airbox.
---------------	----------------------------------

16 Suspension 2	Front shock absorbers play in upper mounts. replace
-----------------	---

16 Suspension 3	Front spring rubber mounts worn. replaced mounts
-----------------	--

13 Brakes 2	Telma retarder control box electrical fault. replaced
-------------	---

Unplanned Repair	24/01/2023	11:00	25/01/2023	08:00	257,157	St Leonards	SL038897
13 Brakes 1	Grinding noise from rear					Monitoring	
Breakdown	02/03/2023	12:47	03/03/2023	11:18	262,147	St Leonards	SL039256
Breakdown	charger point plug bent						
Unplanned Repair	02/03/2023	16:30	02/03/2023	18:00	262,147	St Leonards	SL039261
55 Tail Lift	check for oil leak , reset level & renew filler seal, test ok.						
52 Electrical Aux					repair shore line terminals & test .		
02 Pipeline Annual Inspection	11/03/2023	09:50	11/03/2023	09:51	263,426	MDT Ferndown	TF002559
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found.						
SAFETY INSPECTION	14/03/2023	08:03	22/03/2023	14:30	263,427	St Leonards	SL039381
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
Pollen Filter Change	Pollen Filter Change						
31 Charging System	side charger auto eject pins broken. replaced eject unit						
13 Brakes 2	Front brake pads and discs worn. replace						
55 Tail Lift	Tail lift tank leaking - SWL to replace						
34 Lighting System	ns no plate light lamp not working. replaced						
85 Body Interior 1	240v led lights damaged. replaced all.						
13 Handbrake	handbrake excess travel. adjust cables and shoes.						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
45 Engine 1	Replace DPF temp sensor						
34 Emergency Lights	nsr upper corner blue damaged and led fault. replaces lamp and led unit.						
89 Seats	drivers seatbelt buckle damaged. replaced						
42 Coolant System	coolant leak from temp sensor. replaced sensor.						
Travel Time							

34 Lights rear lights fault. corrosion in both underside plugs. replaced both plugs.

Breakdown **27/03/2023** **20:53** **29/03/2023** **17:17** **263,608** **St Leonards** **SL039507**

Breakdown Sidestep hanging off. Sidestep replaced.

Unplanned Repair **31/03/2023** **08:35** **31/03/2023** **12:00** **263,609** **St Leonards** **SL039548**

45 Engine 1 EML. LOP

Unplanned Repair **04/04/2023** **12:00** **04/04/2023** **12:30** **264,200** **St Leonards** **SL039588**

34 Lights Bulb Replacement N/S/F indicaror replaced

SAFETY INSPECTION **28/04/2023** **10:00** **28/04/2023** **14:43** **265,950** **St Leonards** **SL039927**

18 Wheels Check Torques Checked.
 Safety Inspection Carried out inspection.
 52 Electrical Aux Electrical Auxs ZOLL CHARGING PORT NOT WORKING
 Tail Lift Inspection Done.
 Install Saloon CCTV Camera CCTV alarm on. Formatted hard drive. OK.
 85 Body Interior 1 Fitted cupboard seal clips.
 86 Door Lock Rear door lock n/w. Removed barrel, freed, lubbed & refitted.
 55 Tail Lift Oil leak. Washed, tightened pipe & checked.

Vehicle Deep Clean **30/04/2023** **06:00** **01/05/2023** **10:45** **265,950** **St Leonards** **SL039942**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **11/05/2023** **02:02** **11/05/2023** **05:37** **268,474** **St Leonards** **SL040086**

Breakdown Electrical fault

Breakdown	31/05/2023	14:11	29/06/2023	15:00	271,494	St Leonards	SL040354
Breakdown	Rattling, a pop with engine seizing, oil spillage						
002 Major Unit Replace Eng	Engine u/s - Replaced by Merc Exeter						
17 Tyres Replace	Replace 2x n/s/r tyres						
SAFETY INSPECTION	30/06/2023	14:00	01/07/2023	13:15	271,594	St Leonards	SL040806
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
34 Lights	Side step light not working						
31 Battery Aux	Aux battery weak						
31 Battery Comms	Comms battery weak						
Vehicle Deep Clean	01/07/2023	13:15	02/07/2023	15:42	271,949	St Leonards	SL040816
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	09/07/2023	18:32	10/07/2023	06:56	271,949	St Leonards	SL040963
Breakdown	Auxillary battery power low. both aux batteries faulty replaced 1new and 1used						
Vehicle Deep Clean	22/07/2023	10:00	22/07/2023	16:00	272,661	St Leonards	SL041206
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/07/2023	10:00	24/07/2023	14:30	272,661	St Leonards	SL041218
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
85 Body Interior 1	Other Flea Infestation awaiting Contractor to deal - DONE						
Replace Handbrake Cables	Replace Handbrake Cables. Done.						

UB Fire Supp 6mts Service	UB Fire Supp 6mts Service. Done.
13 Brakes 1	O/S/F brake binding. Replaced siezed sliders.
89 Seats	Drivers seat base cover torn.Replaced shell,cushion & cover.
01 Air Conditioning 1	Saloon A/C fan noisy.Replaced.
56 Radio	Roof aerial missing. Repl;aced.
86 Sliding Door	Rear hinge spring broken,rail in poor condition.Replaced & adjusted door.
85 Body Interior 2	Sun roof blind u/s. Replaced.

Vehicle Deep Clean	31/08/2023	08:30	31/08/2023	12:09	274,050	St Leonards	SL041752
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	01/09/2023	07:00	01/09/2023	11:13	274,050	St Leonards	SL041767
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.	
Safety Inspection	Carried out inspection.	
Tail Lift Inspection	Done.	
02 Windscreen Wipers	O/S washer jet blocked. Replaced.	
02 Cab Assembly 1	DRivers torch missing. No parts.	Monitoring

Unplanned Repair	19/09/2023	13:30	20/09/2023	15:00	279,662	St Leonards	SL042015
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

13 Brakes 1	Brakes spongy
15 Steering 1	Noise from steering. replaced power steering pump. filled and bled system.
17 Tyres Tracking	Carried out by SAS

Breakdown	30/09/2023	02:23	30/09/2023	11:58	280,545	St Leonards	SL042141
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	mis fuelled with unleaded. Removed fuel,tank & filter. Refitted with new fuel &
44 Fuel System 1	Removed tank & cleaned. Replaced filter . Refueled and new filter.

Vehicle Deep Clean	10/10/2023	15:05	11/10/2023	12:07	280,576	St Leonards	SL042302
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	13/10/2023	06:59	13/10/2023	12:46	280,576	St Leonards	SL042337
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
56 Comms Power Failure	Comms Power Check sat nav stuck on Garmin screen
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
Engine Change Oil & Filter	Done.
Recall Notification	Merc Air bag Recall. Done.
86 Door Lock	Scoop locker barrel n/w. Replaced housing.
17 Tyres Replace	N/S/F tyre low tread. Replaced.

Unplanned Repair	01/11/2023	11:45	01/11/2023	12:16	281,854	St Leonards	SL042604
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Chassis	Test and replace chassis battery
--------------------	----------------------------------

Vehicle Deep Clean	22/11/2023	08:43	22/11/2023	11:35	283,003	St Leonards	SL042882
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	24/11/2023	06:00	24/11/2023	13:56	283,003	St Leonards	SL042915
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
87 Stretcher	Med Equip & Devices stretcher wheel not turning
34 Lights	Ignition/Start Sys Headlight
17 Tyres Replace	O/S/R/I punctured. Replaced.
02 Cab Assembly 1	Cubby catch adrift. Resecured.
13 Brakes 1	Rear pads worn,O/S/R caliper rubbers split. Replaced pads & caliper.
02 Cab Ass Fire Extinguisher	Out of date x2. Replaced x2.
89 Seats	Saloon seat arm rest u/s. drill and replaced sheared bolt.
45 Engine 1	EML slow to go out. Test, replaced NOX sensor2

BREAKDOWN	07/12/2023	14:00	08/12/2023	14:07	283,609	St Leonards	SL043098
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windscreen	Leaking in water. Auto glaze to repair
---------------	--

Unplanned Repair	14/12/2023	06:00	15/12/2023	09:00	284,957	St Leonards	SL043197
45 Engine 1 34 Lights Bulb Replacement	Engine Limp mode 20 mph. Replace dpf pressure sensor. Replace running light bulbs						
Unplanned Repair	21/12/2023	11:30	22/12/2023	04:49	285,902	St Leonards	SL043282
71 Body External Steps	Step Damaged						
SAFETY INSPECTION	02/01/2024	09:30	05/01/2024	14:24	286,291	St Leonards	SL043418
18 Wheels Check Torques Safety Inspection 89 Seatbelts Tail Lift Inspection MOT 85 Body Interior 1 15 Steering 1 16 Suspension 1 13 Brakes 1 17 Tyres Tracking	Other seal belt warning light. No fault light and no codes stored. Lower equipment bag strap broken. replaced Play in nsf inner tie rod and rod end. replaced both. Front shock absorbers excessive play in upper mounts. replaced. Front brake pads worn and sliders seized. replaced pads and slider kits. Tracking check and adjust.						
Vehicle Deep Clean	07/01/2024	06:00	08/01/2024	06:00	286,297	St Leonards	SL043493
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	28/01/2024	22:07	29/01/2024	10:08	288,216	St Leonards	SL043758
Breakdown	Headlight out						
SAFETY INSPECTION	20/02/2024	14:00	22/02/2024	10:04	289,807	St Leonards	SL044064

18 Wheels Check Torques
 Safety Inspection
 71 Body External Steps
 34 Emergency Lights
 85 Body Interior 1
 16 Suspension 1
 55 Tail Lift

Body Exterior side steps broken undeployed. checked and lubricated. all ok.
 NS Wing blue inop. replaced blue light
 Saloon underseat locker door insecure. resecured locker door.
 Slipper pads u/s
 hose leaking.replaced

Vehicle Deep Clean **22/02/2024** **11:00** **22/02/2024** **14:00** **289,807** **St Leonards** **SL044093**

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean **26/03/2024** **13:36** **27/03/2024** **10:36** **292,699** **St Leonards** **SL044598**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **29/03/2024** **04:49** **29/03/2024** **12:06** **292,699** **St Leonards** **SL044648**

18 Wheels Check Torques
 Safety Inspection
 UB Fire Supp 12mts Service
 UB Fire Supp 6mts Service
 Tail Lift Inspection
 Brake Fluid Change
 55 Tail Lift
 24 Driveshaft 1
 02 Cab Assembly 1

Checked.
 Carried out inspection.
 Service of fire supression system. Done,
 UB Fire Supp 6mts Service
 Done.
 Brake Fluid Change. Done.
 Breather pipe on lift ram leaking. Replaced.
 Telma heat shield adrift. Resecured.
 Bonnet soundproofing adrift. Resecured.

Vehicle Deep Clean **08/05/2024** **06:47** **08/05/2024** **10:32** **295,666** **St Leonards** **SL045224**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **11/05/2024** **13:35** **14/05/2024** **17:54** **295,692** **St Leonards** **SL045281**

18 Wheels Check Torques
 Safety Inspection
 Annual Heater Service
 Annual Air Con Service
 Tail Lift Inspection

Checked.
 Carried out inspection.
 Annual Heater Service. Replaced exhaust.
 Annual Air Condition Service. Done.
 Done.

34 Lights Bulb Replacement	N/S/F sidelight n/w. Replaced bulb.
86 Sliding Door	Stiff to open/close. Adjusted rear hinge on door.
86 Doors	Drivers door not closing (Door dropped). Adjusted.
86 Doors Rear	O/S door catch/pin n/w.

02 Pipeline Annual Inspection	07/05/2024	10:59	07/05/2024	11:02	295,640	MDT Ferndown	TF003484
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found.
-------------------------------	--

Breakdown	14/06/2024	01:56	14/06/2024	14:16	298,540	St Leonards	SL045771
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	KNOCKING NOISE front o/s wheel or engine. See notes
-----------	---

Vehicle Deep Clean	26/06/2024	14:00	27/06/2024	12:24	299,266	St Leonards	SL046011
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	27/06/2024	14:00	01/07/2024	08:00	299,266	St Leonards	SL046018
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
02 Windscreen Wipers	Replace wiper blades.
UB Fire Supp Repair	Topped up gas in fire suppression system.
34 Lights Bulb Replacement	Front DRL and sidelight bulbs replaced.
86 Sliding Door	Sliding door outer runner cover insecure. resecured.
15 Steering 1	Steering wheel worn. replaced wheel and bolt.
16 Suspension 1	Rear anti roll bar drop link bushes worn. replaced bushes x4.
19 Chassis 1	Rear spray flap bracket loose. resecured.
15 Steering 2	Steering rack oil leak from rack internals. replaced Steering rack.
16 Suspension 2	Front shock absorber n/s leaking oil. replaced front shock absorbers.
Wheel Hub Flanges Replacement	Replaced due to corrosion and nuts.
17 Tyres Tracking	Carried out after replacement of steering rack.
89 Seats	Front passenger seat base worn. replace whole seat base.
16 Suspension 3	Front anti roll bar drop links ball joints worn. replaced both
02 Cab Assembly 1	Drivers window switch broken. replaced switch

Unplanned Repair	09/07/2024	07:00	09/07/2024	08:01	300,421	St Leonards	SL046217
02 Mirrors	O/S Mirror u/s.						
Unplanned Repair	20/07/2024	06:00	20/07/2024	07:45	302,171	St Leonards	SL046420
56 Comms Power Failure 31 Battery Chassis	Comms Power Check MDT keeps powering down Chassis battery u/s. Replaced						
Vehicle Deep Clean	29/07/2024	16:08	30/07/2024	11:38	303,127	St Leonards	SL046607
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	03/08/2024	06:00	03/08/2024	13:34	303,127	St Leonards	SL046664
18 Wheels Check Torques Safety Inspection 45 Engine 1 MDT Failure/Issue Check and Fit P-Clips Tail Lift Inspection 13 Brakes 1 11 Axle Rear 85 Body Interior 1 85 Body Interior 2	Engine Amber EML NFF MDT Failure/Issue Not login NFF Check for the presence of P-Clips and fit if not present Front brake pads and discs worn. Replaced Rear diff pan corroded. Replaced pan and seal White board corroded. Replaced Dash surround broken around radio . Replaced						
Unplanned Repair	13/08/2024	10:30	13/08/2024	11:10	303,600	St Leonards	SL046791
71 Body External Steps	Side step not deploying at all. Carried out checks. repaired switch on side door						
Breakdown	22/08/2024	06:20	22/08/2024	13:30	304,590	St Leonards	SL046919
Breakdown	Side Step Randomly Working						

Unplanned Repair	04/09/2024	10:00	04/09/2024	14:30	306,057	St Leonards	SL047159
71 Body External Steps Travel Time	Side step not deploying Collect from Shaftsbury						
SAFETY INSPECTION	11/09/2024	13:32	12/09/2024	15:30	306,059	St Leonards	SL047264
18 Wheels Check Torques Safety Inspection Replace Handbrake Cables Engine Change Oil & Filter UB Fire Supp 6mts Service Pollen Filter Change Tail Lift Inspection 34 Lights Bulb Replacement 86 Doors Rear 34 Lights 89 Seats 24 Driveshaft 1 27 Transmission Automatic	Replace Handbrake Cables UB Fire Supp 6mts Service Pollen Filter Change Both front indicator bulbs showing white light. replaced bulbs. Upper latch cover damaged. replaced including sticker. Step light inop. repaired wiring on underside. Saloon front swivel seat bearings worn. replaced bearings. - Armrest replaced. Propshaft-gearbox coupling perished. replaced with spare part. Rear transmission mount worn. replaced mount.						
Vehicle Deep Clean	17/09/2024	13:02	18/09/2024	09:56	306,093	St Leonards	SL047347
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	14/10/2024	13:19	14/10/2024	13:24	308,054	St Leonards	SL047734
34 Lights	O/S repeater light not working						
SAFETY INSPECTION	22/10/2024	14:00	22/10/2024	17:13	308,626	St Leonards	SL047908
18 Wheels Check Torques Safety Inspection 56 Comms Power Failure	Checked. Carried out inspection. MDT Failure/Issue Power failure, needs conns check						

34 Emergency Lights	Other A long rubber strip under bluelight (PSF) hanging
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight - Carried out on 24.7.24
Tail Lift Inspection	Done.

Vehicle Deep Clean	28/10/2024	13:35	29/10/2024	10:55	308,632	St Leonards	SL047981
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	01/12/2024	08:00	02/12/2024	05:12	311,970	St Leonards	SL048478
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Doors	Passenger cab door check strap snapped.
71 Body External Steps	N/S Side step not fully deploying

Vehicle Deep Clean	07/12/2024	14:49	09/12/2024	07:36	312,715	St Leonards	SL048572
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	12/12/2024	06:00	12/12/2024	15:03	312,715	St Leonards	SL048645
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
56 Comms Equipment	Radio & Comm System Battery is stuck in back of the HHradio
Air Filter Change	Air Filter Change. Done.
Fuel Filter Change	Change Fuel Filter. Done, replaced leaking pipe.
02 Cab Assembly 1	Torch missing. Replaced 2nd hand.
34 Lighting System	O/S/F side marker broken. Replacded.
34 Lights	O/S/R side marker n/w. Rewired.
85 Body Interior 1	cupboard strap broken. Replaced.
45 Engine Oil Top Up	Topped 1Ltr.

Unplanned Repair	23/12/2024	09:00	23/12/2024	10:30	314,162	St Leonards	SL048782
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Doors sidestep half deploy then drops after deploy fully
------------------------	--

Breakdown	26/12/2024	10:14	26/12/2024	10:58	314,655	St Leonards	SL048829
Breakdown 86 Doors	Drivers door opening whilst driving. Adjust drivers door catch and secure door rubber.						
Unplanned Repair	30/12/2024	07:30	30/12/2024	08:00	315,115	St Leonards	SL048865
34 Lights Bulb Replacement 34 Lights	Lighting System Full beam (both) not working. Replaced Clean up headlight bulb holder contacts						
Unplanned Repair	06/01/2025	12:30	06/01/2025	14:56	316,230	St Leonards	SL048971
86 Doors Rear 71 Body External Steps	Rear door stay broken. drilled out sheared stay bolt and fitted new. N/S Side step not not working						
Vehicle Deep Clean	22/01/2025	08:00	22/01/2025	15:49	317,408	St Leonards	SL049199
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	27/01/2025	05:37	29/01/2025	18:00	317,408	St Leonards	SL049264
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test Tail Lift Inspection MOT 85 Body Interior 1 87 Stretcher 13 Brakes 1 13 Handbrake 17 Tyres Replace 71 Body Exterior 1	Check and Install MDVS windows update ReTest to book @ Minster Mechanics Failed handbrake Equipment strap broken. replaced. Stretcher battery u/s. replaced. Rear brake pads and discs worn. replaced brake kit. Handbrake shoes worn out. replaced. NSF And both OSR Tyres replaced. Spray flap bracket resecured. -tail lift bridge plate guides resecured.						

Unplanned Repair	07/02/2025	11:00	07/02/2025	12:11	318,344	St Leonards	SL049457
45 Engine 1	EML. Temp sensor in elbow replaced with one from decommissioned vehicle						
Breakdown	17/02/2025	17:47	18/02/2025	13:24	319,864	St Leonards	SL049593
Breakdown	Non starter-						
Breakdown	06/03/2025	21:55	07/03/2025	17:14	321,287	St Leonards	SL049815
Breakdown	Non starter						
Vehicle Deep Clean	11/03/2025	15:22	12/03/2025	15:47	321,345	St Leonards	SL049891
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	14/03/2025	09:00	16/03/2025	13:54	321,345	St Leonards	SL049924
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
87a - Medical Equipment Repair	Med Equip & Devices Faulty stretcher, unable to lock safely. NFF						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Tail Lift Inspection							
13 Brake Pads	Front brake pads worn low. Replaced						
17 Tyres	Replaced OSF tyre due to low tread						
02 Glass / Windows	Passenger window switch broken. Replaced						
Unplanned Repair	21/03/2025	10:09	21/03/2025	10:19	321,728	St Leonards	SL050021
71 Body External Steps	Step runners bent -Straightened and lubricated.						

Unplanned Repair	22/03/2025	05:59	22/03/2025	06:01	321,728	St Leonards	SL050037
71 Body External Steps	Step Not working.						
Breakdown	09/04/2025	10:08	10/04/2025	05:47	324,684	St Leonards	SL050316
Breakdown 31 Battery Chassis	amber engine mgmt and fire suppression alarm Replace chassis battery						
BREAKDOWN	19/04/2025	09:30	20/04/2025	12:19	325,847	St Leonards	SL050491
55 Tail Lift	Crew spotted apparent leaks						
Vehicle Deep Clean	29/04/2025	07:58	29/04/2025	15:31	327,292	St Leonards	SL050645
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	01/05/2025	08:00	01/05/2025	16:00	327,292	St Leonards	SL050686
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 85 Body Int Alcohol Gel Dispen UB Fire Supp 12mts Service Tail Lift Inspection 13 Brake Test 55 Tail Lift 87 - Stretchers/Chairs/Boards 45 Engine Ad Blue	Check and Install MDVS windows update Service of fire supression system Tail lift side rails loose Stretcher belts in wrong positions AdBlue fault						
Breakdown	06/06/2025	13:12	07/06/2025	08:00	333,511	St Leonards	SL051405
Breakdown 02 Mirrors	Fire suppression system deployed warning Replace o/s mirror glass and cover						

UB Fire Supp Repair Audio warning sounding. Bypass wiring - Due for disposal

Breakdown	16/06/2025	22:53	18/06/2025	06:10	333,790	St Leonards	SL051603
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Non starter						
-----------	-------------	--	--	--	--	--	--

SAFETY INSPECTION	20/07/2025	06:00	20/07/2025	16:00	336,813	St Leonards	SL052176
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
Tail Lift Inspection	
13 Brakes 1	Replace front pads and caliper sliders due to 44% imbalance
01 Air Conditioning 1	Secure aircon pipework by drier
17 Tyres	Replace 4x rear tyres - Worn to 3mm
02 Cab Assembly 1	Replace interior light bulb and torch
86 Door Seals	Adjust drivers door catch
85 Body Interior 1	Secure salon cupboard hinges

Breakdown	28/07/2025	02:20	28/07/2025	07:08	336,990	St Leonards	SL052328
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	n/s front tyre low pressure						
-----------	-----------------------------	--	--	--	--	--	--