

WM64JXN	A&E	Wimborne Amb Stn					
PDI Inspection	13/04/2015	07:00	18/05/2015	12:00	84	St Leonards	SL016046
71 Body Exterior 1 PDI Inspection	Fit call sign - 6202 Carried out PDI and check list.						
Vehicle Deep Clean	01/06/2015	05:45	01/06/2015	10:00	1,363	St Leonards	SL016330
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	01/06/2015	06:00	03/06/2015	12:30	1,363	St Leonards	SL016336
18 Wheels Check Torques 45 Engine Ad Blue Safety Inspection	Top up Ad Blue Carried out by PCS. Paper inspection sheet done.						
Unplanned Repair	14/06/2015	08:00	14/06/2015	08:00	2,741	St Leonards	SL016481
45 Engine Ad Blue	Top up Ad Blue						
Unplanned Repair	30/06/2015	13:30	30/06/2015	14:30	4,289	St Leonards	SL016529
44 Add Ad Blue	Top Up.						
Vehicle Deep Clean	10/07/2015	07:15	10/07/2015	16:00	5,568	St Leonards	SL016596
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/07/2015	07:00	10/07/2015	13:00	5,568	St Leonards	SL016600
18 Wheels Check Torques 34 Lighting System	Reverse camera int inop						Monitoring

56 Radio	Stereo not turning off. Re set and test, ok.	Monitoring
89 Seats	Saloon seat not locking in position. Free off and adjust	
Safety Inspection	Carried out by PCS. Paper inspection sheet done.	

Unplanned Repair	28/07/2015	12:00	28/07/2015	12:00	7,857	St Leonards	SL016728
-------------------------	-------------------	--------------	-------------------	--------------	--------------	--------------------	-----------------

45 Engine Ad Blue	Top up Ad Blue
-------------------	----------------

Vehicle Deep Clean	21/08/2015	08:00	21/08/2015	16:00	10,776	St Leonards	SL016879
---------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Travel Time	
Vehicle Deep Clean	Vehicle Deep Clean

SAFETY INSPECTION	21/08/2015	08:00	21/08/2015	14:00	10,776	St Leonards	SL016880
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

18 Wheels Check Torques	
34 Lighting System	Reverse camera int inop
44 Add Ad Blue	Add adblue
56 Radio	Stereo not turning off. Re set and test, ok.
Safety Inspection	Carried out by PCS. Paper inspection sheet done.

Unplanned Repair	27/08/2015	10:00	27/08/2015	11:30	10,973	St Leonards	SL016925
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

71 Body External Steps	Side step inop - WAS Warranty form done.	Monitoring
------------------------	------------------------------------------	------------

Unplanned Repair	08/09/2015	11:00	08/09/2015	13:00	12,081	St Leonards	SL016999
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

71 Body External Steps	Side step inop - WAS Warranty form done. Side step motor replaced
------------------------	-------------------------------------------------------------------

Unplanned Repair	19/09/2015	12:34	19/09/2015	14:34	13,031	St Leonards	SL017061
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

71 Body Exterior 1	Side step u/s. Repair Damage .Reset step
--------------------	------------------------------------------

Vehicle Deep Clean	02/10/2015	07:00	02/10/2015	15:00	14,646	St Leonards	SL017146
Travel Time							
Vehicle Deep Clean		Vehicle Deep Clean					
SAFETY INSPECTION	02/10/2015	07:00	02/10/2015	16:00	14,646	St Leonards	SL017147
18 Wheels Check Torques		Done.					
Safety Inspection		Done.					
Tail Lift 6 Monthly Inspection		Statutory Inspection. Done.					
92 - C Service		Done.					
Service C							
Unplanned Repair	28/10/2015	12:45	28/10/2015	13:00	17,291	St Leonards	SL017310
45 Engine Ad Blue		Top up adblue					
Breakdown	09/11/2015	10:33	09/11/2015	12:00	18,461	St Leonards	SL017374
71 Body External Steps		Side step audio warning sounding Repair Runner.					
Breakdown		SIDE STEP STUCK DOWN					
Vehicle Deep Clean	12/11/2015	06:00	13/11/2015	14:00	18,668	St Leonards	SL017401
Travel Time							
Vehicle Deep Clean		Vehicle Deep Clean					
SAFETY INSPECTION	12/11/2015	06:00	13/11/2015	10:00	18,668	St Leonards	SL017402
17 Tyres		R/R all rear tyres, 1 flat, 3 @ Trust limit. inc cleaning very rusted wheels.					
18 Wheels Check Torques							
44 Add Ad Blue		top up adblue					
71 Body External Steps		Body Exterior Side step up with alarm still going off. Clean and adj as req					
87a - Medical Equipment Repair		R/R broken Mangar Charger using used repaired charger					
Safety Inspection		Carried out by PCS Paper inspection sheet done					

Unplanned Repair	22/11/2015	11:30	22/11/2015	12:30	19,622	St Leonards	SL017457
86 Door handle Travel Time	R+I door panel and adjust cables, test OK. Travel to Ferndown						
Unplanned Repair	03/12/2015	12:30	03/12/2015	13:00	20,931	St Leonards	SL017534
87a - Medical Equipment Repair	Mangar charger lead snapped off. Replace unit.						
Unplanned Repair	04/12/2015	14:00	04/12/2015	14:00	21,026	St Leonards	SL017540
45 Engine Ad Blue	Supply Ad Blue						
Unplanned Repair	11/12/2015	10:00	11/12/2015	11:00	21,929	St Leonards	SL017586
45 Engine Ad Blue 71 Body External Steps 87 Oxygen System	Top up Ad Blue Side step not returning - WAS warranty O2 audio warning sounding - WAS warranty					Monitoring Monitoring	
Unplanned Repair	11/12/2015	17:15	15/12/2015	15:04	21,955	St Leonards	SL017594
86 Sliding Door Travel Time	Door not closing. Refit top catch, set micro switch, adjusted cables. Travel to and from Poole Hospital						
Vehicle Deep Clean	23/12/2015	07:00	24/12/2015	10:30	23,002	St Leonards	SL017664
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/12/2015	07:00	24/12/2015	10:00	23,002	St Leonards	SL017665
17 Tyres Replace 18 Wheels Check Torques 71 Body External Steps 85 Body Interior 1 87 Oxygen System	Front tyres at Trust limit, R/R Side step not returning - WAS warranty Document locker damaged, repair as req'd and refit cover O2 audio warning sounding - WAS warranty. Repaired by Oxilite					Monitoring	

Safety Inspection Carried out by PCS. Paper inspection sheet done.

BREAKDOWN **28/12/2015** **10:56** **28/12/2015** **12:56** **23,395** **St Leonards** **SL017677**

71 Body External Steps Repair side step.

Unplanned Repair **29/12/2015** **11:21** **29/12/2015** **12:30** **23,479** **St Leonards** **SL017685**

44 Add Ad Blue
54 Sirens
MDT Failure/Issue

Siren inop intermittently NFF at time of test with steering at various angles
Power failed 3 times today, 29/12/15, battery ok, PCE to sort

Unplanned Repair **12/01/2016** **14:00** **12/01/2016** **15:00** **25,232** **St Leonards** **SL017773**

45 Engine Ad Blue
56 Comms Equipment
85 Body Interior 1

Top up Ad Blue
MDT Failure/Issue MDT keeps booking off.No Fault Found.
Repair damaged cuboard in saloon

Breakdown **14/01/2016** **14:49** **14/01/2016** **15:00** **25,422** **St Leonards** **SL017786**

56 Comms Power Failure
Breakdown

Reported comms power failing. Test battery all ok at time of test.
MDT keeps powering off. Battery Check req

Breakdown **19/01/2016** **05:11** **19/01/2016** **12:30** **25,915** **St Leonards** **SL017810**

56 Comms Power Failure
Breakdown

Test battery and charge rate, all ok at time of test.
PLS Check the comms battery & fault with side step

Unplanned Repair **04/02/2016** **18:00** **04/02/2016** **20:00** **27,668** **Dorchester** **DC014284**

34 Lights Bulb Replacement
Travel Time

travel to and from

Vehicle Deep Clean	08/02/2016	07:00	08/02/2016	12:00	27,672	St Leonards	SL017925
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/02/2016	07:00	12/02/2016	13:00	27,672	St Leonards	SL017926
13 Brakes 1	F/ Pads & Disc at 50 % Replace at next safety insp.					Monitoring	
18 Wheels Check Torques	Done.						
34 Emergency Light System	Electrical Auxs Sirens not working with head lights.No Fault Found.						
56 Comms Power Failure	Remove relay from comms. Done Connected to 30/87 pins as E/Mail.						
71 Body External Steps	Side step not returning - WAS warranty						
Safety Inspection	Done.						
MOT Pre Test	Done.						
Travel Time							
MOT							
Unplanned Repair	15/02/2016	13:50	15/02/2016	14:30	27,726	Dorchester	DC014330
03 Instruments & Sensors 1	Assault alarm going off.Check over and road test.Unable to recreate fault						
Unplanned Repair	24/02/2016	19:00	25/02/2016	21:00	28,415	Dorchester	DC014389
34 Lights Bulb Replacement							
Travel Time	travel to and from						
Unplanned Repair	04/03/2016	08:30	04/03/2016	09:30	29,368	St Leonards	SL018094
34 Lights Bulb Replacement	Replace headlight bulb						
56 Comms Power Failure	Test comms battery. Battery tested ok. Reported to Logistics.						
Breakdown	17/03/2016	23:19	18/03/2016	06:00	30,436	St Leonards	SL018173
Breakdown	road horn not operating sirens on/off - Transferred to J/C SL018178						

SAFETY INSPECTION	18/03/2016	06:00	18/03/2016	16:00	30,570	St Leonards	SL018178
13 Brakes 1	F/ Pads & Disc at 50 % Replace front pads						
18 Wheels Check Torques							
54 Sirens	Intermittent failure of siren and horn - NFF						
Safety Inspection	Carried out by PCS.						
Travel Time							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	21/03/2016	08:00	21/03/2016	12:00	30,570	St Leonards	SL018185
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	28/03/2016	12:00	28/03/2016	13:00	31,174	St Leonards	SL018216
54 Sirens	Siren u/s. No Fault found at time of test.						
Unplanned Repair	30/03/2016	10:00	30/03/2016	10:48	31,388	St Leonards	SL018235
44 Add Ad Blue	Top up Ad blue. 16 L .						
Unplanned Repair	01/04/2016	07:00	01/04/2016	09:00	31,550	St Leonards	SL018246
15 Steering 1	Power Steering u/s. Check for leaks. Top up unit.						
Unplanned Repair	14/04/2016	14:00	15/04/2016	11:30	33,092	St Leonards	SL018353
34 Lights Bulb Replacement	Replace headlight bulb						
45 Engine Ad Blue							
56 Comms Power Failure	Comms power failing.Checked and ordered relay. Relay Fitted.						
Unplanned Repair	21/04/2016	13:15	04/05/2016	12:21	33,712	St Leonards	SL018390
56 Comms Power Failure	Check and test comms battery.Done. Replaced battery.						
85 Body Interior 1	Fit 3x audio speakers. Removed to fit a other DCA.Replaced speakers x3.						

87a - Medical Equipment RepairFit mangar board.Replaced mangar board.

SAFETY INSPECTION	29/04/2016	09:00	05/05/2016	08:32	33,712	St Leonards	SL018430
13 Brake Pads	Rear pads worn.Replaced.						
13 Discs	front disc's worn.Replaced.						
15 Steering 1	Lower ball joints worn.Replaced lower arms x2.						
16 Suspension 1	Front struts worn.Replaced x2.						
17 Tyres Replace	N/S/F tyre worn on outer edge. Replaced.(205/75r16 Part worn).						
18 Wheels Check Torques	Checked.						
55 Tail Lift	Bridge plate guides bent / broken.Drill and tap sheared bolts.straighten,refit.						
Safety Inspection	Carried out inspection.						
85 Body Int Alcohol Gel Dispen	Fitted.						
Fit Throw Lines & SOP	Fitted.						
Wheel Studs & Nuts Replacement	Replaced all wheel flanges and nuts.						
Handbrake Cable Replacement	Replace rear handbrake cables.Replaced.						
UB Fire Suppression Service	Done.						
93 - D Service	Carried out D service.						
Service D							
Tail Lift Annual Service	Statutory Inspection and Weight Test.Done by S.W.L.						
Vehicle Deep Clean	04/05/2016	13:00	05/05/2016	10:00	33,712	St Leonards	SL018451
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	10/05/2016	08:00	10/05/2016	10:00	33,999	St Leonards	SL018475
56 Comms Power Failure	Comms power board replaced by PCE.						
Unplanned Repair	26/05/2016	12:00	26/05/2016	12:30	35,365	St Leonards	SL018574
45 Engine Ad Blue	Top up Ad Blue						

SAFETY INSPECTION	14/06/2016	07:19	14/06/2016	14:54	36,847	St Leonards	SL018661
18 Wheels Check Torques							
87 Oxygen System	Body Interior Oxytitre oxygen port leaking below MobiMed						
Safety Inspection							
Travel Time							
Annual Air Con Service	Annual Air Condition Service. Done.						
Annual Heater Service	Annual Heater Service						
Reposition grab bag shelf							
Vehicle Deep Clean	15/06/2016	04:55	15/06/2016	13:31	36,847	St Leonards	SL018666
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	02/07/2016	10:37	02/07/2016	12:30	38,478	Dorchester	DC014943
02 Cab Assembly 1	Fumes in cab.Carry out road test,trace to poorly fitte grommet in bulkhead.						
Travel Time							
Breakdown	02/07/2016	10:37	02/07/2016	12:00	38,478	St Leonards	SL018752
Breakdown	FUMES SMELL IN CAB						
Unplanned Repair	03/07/2016	07:30	03/07/2016	08:30	38,555	Dorchester	DC014945
45 Engine Oil Top Up							
Travel Time							
SAFETY INSPECTION	01/08/2016	08:00	02/08/2016	16:00	41,226	St Leonards	SL018900
17 Tyres Replace	All tyres low tread. Replaced x6						
18 Wheels Check Torques	Checked						
Safety Inspection	Carried out inspection.						
Travel Time	Return vehicle to Wimborne						
Vehicle Deep Clean	01/08/2016	11:56	02/08/2016	08:30	41,226	St Leonards	SL018904

Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	04/08/2016	11:00	04/08/2016	12:00	41,356	St Leonards	SL018948
45 Engine Ad Blue	Top up Ad Blue						
87 Stretcher	Re fit stretcher lock cover. Fitted.						
Unplanned Repair	27/08/2016	15:01	31/08/2016	08:00	43,069	St Leonards	SL019135
45 Engine 1	Fumes in cab. Checked, refitted bulkhead grommet.						
Travel Time	Travel to and from Ferndown VMU.						
SAFETY INSPECTION	05/09/2016	10:00	06/09/2016	07:00	43,713	St Leonards	SL019194
02 Cab Assembly 1	O/S window switch broken. Replaced.						
18 Wheels Check Torques	Checked.						
56 Comms Equipment	Radio microphone wires pulled out - PCE to repair.						
Safety Inspection	Carried out inspection.						
Travel Time							
Tail Lift 6 Monthly Inspection	Statutory Inspection.Done.						
Vehicle Deep Clean	05/09/2016	13:00	06/09/2016	09:00	43,713	St Leonards	SL019198
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	22/09/2016	19:49	27/09/2016	08:09	45,056	St Leonards	SL019337
44 Add Ad Blue	Fill Ad-Blue tank						
44 Fuel System 1	Water in fuel light on.Changed filter and road tested.OK.						
45 Engine 1	Replace fuel leak off pipes.Replaced.Filled with fuel,extended road test.						
Breakdown	adblue put in fuel tank, engine wont turnover						

Unplanned Repair	15/10/2016	07:45	15/10/2016	09:20	46,423	Dorchester	DC015476
71 Body External Steps Travel Time	Side step warning reported on.Check over,road test,unable to recreate fault.						
Breakdown	14/10/2016	20:54	15/10/2016	09:00	46,422	St Leonards	SL019513
Breakdown	Side step audible alarm						
SAFETY INSPECTION	17/10/2016	07:00	18/10/2016	12:30	46,652	St Leonards	SL019522
17 Tyres Replace	Replace worn n/s/f tyre						
18 Wheels Check Torques							
45 Engine Ad Blue	Top up Ad Blue						
85 Body Interior 1	Replace IV hanger						
Safety Inspection							
Travel Time							
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill						
Vehicle Deep Clean	18/10/2016	15:20	19/10/2016	11:30	46,652	St Leonards	SL019540
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	02/11/2016	10:45	02/11/2016	11:15	47,877	St Leonards	SL019659
34 Lights Bulb Replacement	Replace n/s side repeator bulb						
44 Add Ad Blue	Top up Ad Blue						
Unplanned Repair	08/11/2016	11:30	08/11/2016	12:00	48,497	St Leonards	SL019712
02 Cab Ass Fire Extinguisher	Fire suppression low pressure warning. Wiring mod done. New unit on order.						Monitoring
Vehicle Deep Clean	28/11/2016	09:30	29/11/2016	09:58	50,411	St Leonards	SL019870
Travel Time							

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	29/11/2016	10:47	30/11/2016	12:49	50,411	St Leonards	SL019878
02 Cab Ass Fire Extinguisher	Fire suppression low pressure warning. Wiring mod done. New unit on order.						
18 Wheels Check Torques	Checked.						
45 Engine 1	Engine oil leak.Monitor.					Monitoring	
86 Sliding Door	Bottom catch adrift. Refitted and adjusted.						
89 Seats	Saloon seat bearings worn.Monitor (no parts).					Monitoring	
Safety Inspection	Carried out inspection.						
Gearbox Oil & Filter Change	Carried out gearbox service.						
92 - C Service	Carried out C service.						
Service C							
MOT Pre Test							
UB Fire Suppression Service	Fitted complete system.						
Unplanned Repair	16/12/2016	10:30	16/12/2016	11:30	51,773	St Leonards	SL020052
55 Tail Lift	Straighten tail lift plate						
Unplanned Repair	04/01/2017	11:30	04/01/2017	12:00	53,652	St Leonards	SL020184
45 Engine Ad Blue	Top up Ad Blue						
SAFETY INSPECTION	09/01/2017	07:00	11/01/2017	14:28	54,086	St Leonards	SL020217
02 Cab Assembly 1	Fit ECS factsheet.Fitted.						
13 Discs	Rear disc's worn. Replaced disc's and pads.						
18 Wheels Check Torques	Checked.						
34 Lights	O/S repeater broken. Replaced.						
45 Engine 1	Engine oil leak.Monitor.Replaced turbo rubber and wash.Road test and check.						
89 Seats	Saloon seat bearings worn.Replaced						
Safety Inspection	Carried out inspection.						
Medical Device and Equip Chec	Checked.OK.						
Travel Time							
MOT							

Vehicle Deep Clean	10/01/2017	14:00	11/01/2017	11:15	54,086	St Leonards	SL020236
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	30/01/2017	08:27	30/01/2017	09:00	55,499	St Leonards	SL020393
44 Add Ad Blue	Done 10.4 L						
Unplanned Repair	08/02/2017	14:30	08/02/2017	14:55	56,949	St Leonards	SL020476
44 Add Ad Blue	Top up Ad Blue						
Breakdown	10/02/2017	10:58	10/02/2017	13:30	57,110	St Leonards	SL020492
71 Body External Steps Breakdown	Side step not coming out. Lub step and test, ok. side step wont stay in. does go in manually						
Breakdown	11/02/2017	10:17	11/02/2017	12:00	57,225	St Leonards	SL020497
71 Body External Steps Breakdown Travel Time	Side step stuck out.Checked,working OK.Checked switches etc. side step wont stay in Travel to and from Winborne station.						
Breakdown	12/02/2017	10:38	12/02/2017	12:38	57,290	St Leonards	SL020500
71 Body External Steps Breakdown Travel Time	Step not going in. Checked OK @ time of test SIDE STEP STUCK OUT. Travel to and from Wimborne station.						
Unplanned Repair	13/02/2017	07:00	13/02/2017	13:00	57,371	St Leonards	SL020506
71 Body External Steps Install Saloon CCTV Camera WAS Firetrace rework & Service	Side step not coming out intermittantly Jon Coles to carry out. Jon Coles to carry out.					Monitoring	
Vehicle Deep Clean	17/02/2017	06:30	17/02/2017	10:00	57,731	St Leonards	SL020544

Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	16/02/2017	15:00	17/02/2017	08:00	57,731	St Leonards	SL020545
34 Emergency Lights	Re fit n/s blue wing light						
71 Body Exterior Acc Repair	Front end accident damage.					Monitoring	
SAFETY INSPECTION	20/02/2017	10:00	22/02/2017	10:27	58,058	St Leonards	SL020566
02 Windscreen Wipers	Replace both.						
13 Brake Pads	F/Pads getting low .Replace next S/I.					Monitoring	
18 Wheels Check Torques	Done.						
45 Engine 1	Oil leak found at intake pipe & seal.Replace unit.						
71 Body Exterior Acc Repair	Front end accident damage.						
71 Body External Steps	Side step not coming out intermittantly. NFF. At time of test.						
87a - Medical Equipment Repair	Oxy warning sounding .					Monitoring	
89 Seats	Saloon seat u/s Repair unit.						
Safety Inspection	Done.						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Unplanned Repair	23/03/2017	11:00	23/03/2017	12:00	60,674	St Leonards	SL020821
34 Lighting System	Side step light inop - Jon Coles WAS Warranty.					Monitoring	
71 Body External Steps	Side step intermittantly not working - Jon Coles WAS Warranty.					Monitoring	
85 Body Interior 1	Carry chair bracket cracked - Jon Coles WAS Warranty.					Monitoring	
89 Seats	2x saloon seat bearings worn - Jon Coles WAS Warranty.					Monitoring	
BREAKDOWN	27/03/2017	04:15	27/03/2017	06:15	61,139	St Leonards	SL020845
34 Lights Bulb Replacement	replace off side head light bulb						
44 Add Ad Blue	top up add blue						
BREAKDOWN	31/03/2017	17:00	31/03/2017	19:00	61,561	St Leonards	SL020876
55 Tail Lift	Nut insert bridge and refit unit.						

Unplanned Repair	01/04/2017	10:00	01/04/2017	12:00	61,597	St Leonards	SL020880
71 Body Exterior 1	R.T.C / Damage to N/S sil panel & step. Do temp repair.						
Vehicle Deep Clean	03/04/2017	10:30	03/04/2017	14:30	61,787	St Leonards	SL020885
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	03/04/2017	08:00	10/04/2017	10:00	61,787	St Leonards	SL020886
13 Brake Pads	replaced front brake pads and wires						
17 Tyres	replaced near side front tyre						
18 Wheels Check Torques	checked						
34 Lighting System	Side step light inop - Jon Coles WAS Warranty.Done.						
41 Turbo	replace turbo seal						
71 Body External Steps	Side step damaged replaced side spep						
85 Body Interior 1	Carry chair bracket cracked - Jon Coles WAS Warranty.Done.						
87a - Medical Equipment Repair	Oxy warning sounding .						
89 Seats	2x saloon seat bearings worn - Jon Coles WAS Warranty.Done						
Safety Inspection	carry out inspection						
Annual Heater Service	Annual Heater Service						
Handbrake Cable Replacement	Replace rear handbrake cables						
Annual Air Con Service	Annual Air Condition Service						
Tail Lift Annual Service	Statutory Inspection and Weight Test.Done by S.W.L.						
Unplanned Repair	25/04/2017	13:15	25/04/2017	13:35	63,349	St Leonards	SL021046
45 Engine Ad Blue	Top up Ad Blue						
BREAKDOWN	06/05/2017	12:03	06/05/2017	14:03	64,414	St Leonards	SL021122
87 Chairs	Repair chair lock.						
Vehicle Deep Clean	12/05/2017	08:03	12/05/2017	12:00	64,856	St Leonards	SL021174

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/05/2017	07:00	16/05/2017	14:30	64,856	St Leonards	SL021180
16 Suspension 1	Replace rear A.R.B bushes						
17 Tyres Replace	replace rear and osf tyres						
18 Wheels Check Torques	done						
41 Air Intake	replace turbo hose seal						
85 Body Interior 1	replace cab and saloon fire extinguishers						
Safety Inspection	carry out inspection						
MGS Gas Storage Modifications	18/05/2017	08:00	18/05/2017	08:30	64,920	St Leonards	SL021221
MGS Gas Storage Modifications	MGS Gas Storage Modifications						
Breakdown	05/06/2017	17:23	05/06/2017	19:23	66,764	St Leonards	SL021382
001 Recover Vehicle	Vehicle Recovery. Recovery arranged by Logistics						
45 Engine 1	plug in texa check out engine in limp mode on fult found road test ok						
Breakdown	limp mode						
Breakdown	12/06/2017	18:39	15/06/2017	08:30	67,466	St Leonards	SL021451
86 Sliding Door	RAISED BY LOGISTICS. NO SHOW @ VMU.						
Breakdown	side door handle stuck open						
Unplanned Repair	15/06/2017	11:45	15/06/2017	13:00	67,701	St Leonards	SL021482
55 Tail Lift	Play in tail lift - Audio warning sounding - SWL to repair						
86 Doors Rear	Rear door stay sheared off drill out snaped bolt and replace bolt						
Vehicle Deep Clean	23/06/2017	10:30	26/06/2017	09:00	68,441	St Leonards	SL021536
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	26/06/2017	07:00	27/06/2017	11:53	68,441	St Leonards	SL021541
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

01 Heating 1	Heater exhaust broken. Replaced.
02 Cab Assembly 1	Search light holder broken off. Refitted.
02 Cab Assembly 2	Drivers window switch broken. Replaced.
02 Mirrors	N/S lower mirror lens broken. Replaced.
15 Steering 1	Check and adjust tracking as required. See notes.
17 Tyres	Vibration while driving. Replaced tyre due to bent track control arm.
18 Wheels Check Torques	Checked.
24 Driveshaft 1	Propshaft center bearing worn. Replaced.
34 Lights	Reverse camera/beeper inop? Repaired wiring and replaced beeper.
52 Electrical Aux	Inverter socket in saloon inop. No fault at time of test.
56 Comms Fitment	Phone holder broken off. Repaired and refitted.
Safety Inspection	Carried out inspection.
MGS Gas Storage Modifications	MGS Gas Storage Modifications. Done. Carried out on 18/05/2017. (SL021221)
93 - D Service	Carried out D service.
Service D	

Unplanned Repair	06/07/2017	14:45	06/07/2017	15:00	69,300	St Leonards	SL021642
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

34 Lights Bulb Replacement	Replace o/s running light bulb
----------------------------	--------------------------------

BREAKDOWN	12/07/2017	06:25	12/07/2017	08:00	69,827	St Leonards	SL021676
------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

17 Tyres Replace	REPLACE NEAR SIDE REAR OUTER TYRE
34 Lights Bulb Replacement	REPLACE OFF SIDE FRONT DRIVING LIGHT BULB

BREAKDOWN	12/07/2017	22:00	12/07/2017	23:59	69,934	St Leonards	SL021691
------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

45 Engine 1	ENGINE LIGHT ON CHECKED. LIGHT WHEN OFF ROAD TEST OK
-------------	------------------------------------------------------

Unplanned Repair	02/08/2017	13:00	02/08/2017	14:00	72,445	St Leonards	SL021849
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

27 Transmission Automatic	Clutch fault on torque converter.	Monitoring
41 Turbo	Replace turbo seal. Done.	

71 Body Exterior 1	Reverse camera inop					Monitoring	
SAFETY INSPECTION	04/08/2017	09:00	10/08/2017	11:00	72,710	St Leonards	SL021867
17 Tyres	Tyres NEAR SIDE BACK- LOW AIR PRESSURE						
18 Wheels Check Torques	done						
27 Transmission Automatic	Clutch fault on torque converter.						
31 Charging System	Auto eject not ejecting plug						
56 Comms Power Failure	Comms power failing and EPCR fault FOUND LOOSE WIRE ON FUSE						
71 Body Exterior 1	Reverse camera inop						
86 Sliding Door	Side door rollers worn						
Safety Inspection	carry out inspection						Monitoring
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	04/08/2017	12:45	07/08/2017	12:30	72,710	St Leonards	SL021869
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	04/09/2017	11:00	04/09/2017	11:30	75,209	St Leonards	SL022104
45 Engine 1	Engine oil leak						
Unplanned Repair	04/09/2017	14:15	04/09/2017	14:45	75,234	St Leonards	SL022107
44 Add Ad Blue	Top up Ad Blue						
Breakdown	10/09/2017	00:14	11/09/2017	10:29	75,957	St Leonards	SL022148
Breakdown	limp mode. No faults at time of test.						
Breakdown	10/09/2017	21:25	11/09/2017	11:30	75,956	St Leonards	SL022149
Breakdown	nsr roof blues detached (overhanging branches) REPLACED UNIT						
SAFETY INSPECTION	18/09/2017	08:00	19/09/2017	11:28	76,662	St Leonards	SL022202

02 Cab Assembly 1	N/S window switch broken.Replaced.						
13 Brake Pads	Rear pads worn. Replaced.						
13 Discs	Front disc's worn.Pads OK. Replace next inspection.(Monitor).						
17 Tyres Replace	N/S/R/O nailed. Replaced.						
18 Wheels Check Torques	Checked.						
34 Lights	N/S fog light 55% n/w. Replaced.						
45 Engine 1	Oil leak from turbo pipe.Clean. Replaced rubber.						
71 Body Exterior 1	Side door camera clear cover broken. Ordered parts.						
86 Sliding Door	Side door rollers worn. Parts in office.Replaced top and rear roller sets.						
Safety Inspection	Carried out inspection.						
Vehicle Deep Clean	19/09/2017	13:00	20/09/2017	10:00	76,662	St Leonards	SL022224
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	05/10/2017	08:36	09/10/2017	09:00	77,763	St Leonards	SL022345
45 Engine 1	Lack of power and EML on.Cleared faults and road tested.						
71 Body Exterior 1	Side door camera clear cover broken. Ordered parts.Replaced.						
Breakdown	Limp mode						
Unplanned Repair	20/10/2017	10:30	20/10/2017	12:00	79,533	St Leonards	SL022478
34 Emergency Lights	replace near side top corner blue lamp						
34 Lighting System	replace near side top stop and tail lamp						
71 Body Exterior 1	Damage to top n/s/r body - Bodyshop required						
Breakdown	22/10/2017	14:06	31/10/2017	10:00	79,764	St Leonards	SL022479
45 Engine 1	EML, LOP, Cutting out. Petrol in unit. Rygors to repair						
Breakdown	eml, limp mode, cutting out						
SAFETY INSPECTION	31/10/2017	10:00	02/11/2017	16:00	79,839	St Leonards	SL022542
13 Brakes 2	Replace peddle rubber.						

13 Discs	Front disc's worn.Pads OK. Replace next inspection. Fitted.	
18 Wheels Check Torques	Done.	
45 Engine 1	Oil leak. Repair intake seals clean up mess.	
71 Body Exterior 1	Damage to top n/s/r body - Bodyshop required & N/S of unit.	Lack of Labour
85 Body Interior 1	Repair lockers chalk bored.	
Safety Inspection	Done.	

Vehicle Deep Clean	31/10/2017	14:21	01/11/2017	11:30	79,839	St Leonards	SL022551
---------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	06/11/2017	13:30	14/11/2017	12:00	80,137	St Leonards	SL022590
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

45 Engine 1	Cutting out again - Returning to Rygors
-------------	-----------------------------------------

Unplanned Repair	22/11/2017	22:00	05/12/2017	09:00	81,322	St Leonards	SL022741
-------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

45 Engine 1	Cutting out again - Back to Rygors [put on spair]
-------------	----------------------------------------------------

BREAKDOWN	09/12/2017	13:15	27/12/2017	10:00	81,826	St Leonards	SL022870
------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

45 Engine 1	Engine cutting out AGAIN.Rygors to repair again. Torque converter/Clutch.
-------------	---------------------------------------------------------------------------

SAFETY INSPECTION	11/12/2017	07:27	11/12/2017	14:55	81,826	St Leonards	SL022876
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

18 Wheels Check Torques	done	
41 Air Intake	replace turbo seal	
71 Body Exterior 1	Damage to top n/s/r body - Bodyshop required & N/S of unit.	Monitoring
Safety Inspection	carried out inspection	
MOT Pre Test	done	

Breakdown	01/01/2018	04:33	02/01/2018	09:15	82,343	St Leonards	SL023000
------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

45 Engine 1 Breakdown	EML on Eng warning light orange						
Breakdown	07/01/2018	21:39	10/01/2018	07:00	83,153	St Leonards	SL023054
Breakdown	KEEPS STALLING						
Breakdown	09/01/2018	20:42	15/02/2018	10:45	83,210	St Leonards	SL023084
45 Engine 1 Breakdown Travel Time MOT	EML on and cutting out. [Rail Pressure] Rygors to repair. Relays replaced. engine warning light orange Carried out by Rygor						
Vehicle Deep Clean	12/01/2018	11:25	12/01/2018	11:57	83,210	St Leonards	SL023416
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/02/2018	10:45	20/02/2018	16:00	83,510	St Leonards	SL023405
17 Tyres	Tyres getting close to 4.5 mm.					Monitoring	
18 Wheels Check Torques	Done.						
34 Emergency Lights	Damage to o/s/r light bar.					Monitoring	
71 Body Exterior 1	Damage to top n/s/r body - Bodyshop required & N/S of unit.					Monitoring	
71 Body Exterior 2	Damage to n/s sill panel .Req bodyshop att.					Monitoring	
71 Body Exterior 3	Damage to Tail Lift.Repair runner.					Monitoring	
89 Seats	Repair saloon seat.						
Safety Inspection	Done.						
85 Body Int Alcohol Gel Dispen	Already fitted.						
Tail Lift 6 Monthly Inspection	Statutory Inspection. Done.						
Vehicle Deep Clean	16/02/2018	11:57	19/02/2018	11:00	83,510	St Leonards	SL023420
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/02/2018	13:28	16/04/2018	12:30	84,000	St Leonards	SL023489

45 Engine 1 Breakdown	Cutting out again - Back to Rygor. Injectors replaced. in limp mode , and intermiantly stalling
--------------------------	----------------------------------------------------------------------------------------------------

SAFETY INSPECTION	16/04/2018	12:19	16/04/2018	12:19	84,063	St Leonards	SL023889
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

18 Wheels Check Torques Safety Inspection	Inspection missed. @ Rygors (Not operational)
----------------------------------------------	-----------------------------------------------

Vehicle Deep Clean	16/04/2018	12:18	16/04/2018	12:32	84,063	St Leonards	SL023890
---------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	16/04/2018	12:30	20/04/2018	08:00	84,063	St Leonards	SL023891
--------------------------	-------------------	--------------	-------------------	--------------	---------------	--------------------	-----------------

17 Tyres	Tyres getting close to 4.5 mm.Fit 6 new tyres.
18 Wheels	Replace 6x wheel rims. Fitted.
18 Wheels Check Torques	Done.
31 Battery Comms	Battery/Charging Sys radio bat chrg unit working on 1 side. N.F.F
31 Charging System	Battery/Charging Sys Charger cable does not release when ignition turns. N.F.F
31 Charging System Battery	Electrical Auxs Driver/side battery charger does not work
34 Emergency Lights	Damage to o/s/r light bar.
34 Lighting System	Emg Warning Devices Reversing camera not working. Reset unit.
43 Exhaust System 1	Replace tailpipe & mounts.
45 Engine 1	Engine EML on over reving. Repaired by Rygor
45 Engine 2	Engine In limp mode and stalling. Repaired by Rygor
45 Engine 3	Engine Vehicle stalls randomly, even while idling. Repaired by Rygor
45 Engine Ad Blue	Engine limp mode, complete loss of power. Repaired by Rygor
52 Electrical Aux	Electrical Auxs Power sockets in rear have no power supply
54 Sirens	Emg Warning Devices Sirens do not change when hooter is pressed.N.F.F
56 Comms Equipment	Battery/Charging Sys Driver side battery charger does not charge. N.F.F
71 Body Exterior 1	Damage to top n/s/r body - Bodyshop required & N/S of unit.
71 Body Exterior 2	Damage to n/s sill panel .Req bodyshop att.
71 Body Exterior 3	Damage to Tail Lift.Repair runner.N.F.F
71 Body External Steps	Doors Side step not deploying properley. N.F.F
Safety Inspection	Done.
Fit Poster Holder	Fit Poster Holder. Fitted.
Annual Air Con Service	Annual Air Condition Service. Done.
Wheel Hub Flanges Replaceme	Fitted.
UB Fire Suppression Service	
Handbrake Cable Replacement	Replace rear handbrake cables
Annual Heater Service	Annual Heater Service

Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	16/04/2018	12:34	17/04/2018	07:30	84,063	St Leonards	SL023892
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	27/04/2018	18:40	27/04/2018	20:15	85,056	Dorchester	DC018289
45 Engine 1 Travel Time	LOP reported.See notes						
Breakdown	26/04/2018	19:04	27/04/2018	12:00	84,150	St Leonards	SL023995
45 Engine 1 Breakdown	L.O.P CREW WAS A NO SHOW. engine managment light on						
Breakdown	27/04/2018	18:02	27/04/2018	20:15	84,859	St Leonards	SL024004
Breakdown	loss of power						
Breakdown	01/05/2018	09:57	16/05/2018	09:00	85,538	St Leonards	SL024021
44 Fuel System 1 44 Fuel System 2 44 Fuel System 3 45 Engine 1 Breakdown Road Test	Replace fuel tank and sender and replace fuel. Replace injector rails and fuel pump from old engine. Travel to fuel station and fill with fuel. Cutting out again - Rygor to repair loss of power						
Breakdown	18/05/2018	03:03	18/05/2018	11:30	85,941	St Leonards	SL024153
45 Engine 1 Breakdown	EML on. Check faults and clear. Road test, ok @ time of test. Crew to monitor. Yellow EML						

Unplanned Repair	01/06/2018	01:00	01/06/2018	01:15	87,894	Dorchester	DC018458
34 Lights Bulb Replacement	Headlight bulb replaced by Bronze						
Vehicle Deep Clean	06/06/2018	11:22	07/06/2018	10:00	88,339	St Leonards	SL024274
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/06/2018	10:00	07/06/2018	15:00	88,339	St Leonards	SL024275
18 Wheels Check Torques							
33 Ignition System	Swap keys over. See John						
44 Add Ad Blue	Top up Adblue						
86 Doors	Repair side door.						
Camera Installation	CCTV U/S Hard drive unit req.Reported.						Monitoring
Safety Inspection							
Breakdown	17/06/2018	07:21	18/06/2018	14:00	89,519	St Leonards	SL024369
45 Engine 1	Lack of power and EML on. Fuel issues.See notes.						Monitoring
Breakdown	orange EML&limp mode Fuel issue						
Travel Time							
Unplanned Repair	20/06/2018	15:00	16/07/2018	12:00	89,795	St Leonards	SL024417
45 Engine 1	Lack of power and EML on. Fuel issues.See notes. Rygor to repair						
45 Engine 2	Replace engine loom. Rygor to replace.						
MOT	Carried out by F/Comms						
SAFETY INSPECTION	16/07/2018	13:00	18/07/2018	09:33	89,795	St Leonards	SL024619
02 Cab Ass Fire Extinguisher	Out of date. Replaced x2.						
02 Cab Assembly 1	Torch n/w. Replaced.						
16 Suspension 1	Rear spring Buffer split N/S&O/S. Replaced x2.						
18 Wheels Check Torques	Checked.						
55 Tail Lift	Guide block adrift. Resecured.						
86 Door Lock	Rear door lock solonoide n/w.						

Camera Installation	CCTV U/S Hard drive unit req.Reported.					Monitoring	
Safety Inspection	Carried out inspection.						
92 - C Service	Carried out C service.						
Service C							
Vehicle Deep Clean	18/07/2018	10:52	18/07/2018	14:00	89,795	St Leonards	SL024646
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	21/07/2018	02:37	25/07/2018	06:45	89,950	St Leonards	SL024679
Breakdown	Radio and reversing camera not working. Duty fitter not called.						
Unplanned Repair	09/08/2018	13:15	09/08/2018	13:45	92,185	St Leonards	SL024830
71 Body External Steps	Side step not deploying. Straighten and lub, ok.						
SAFETY INSPECTION	20/08/2018	07:00	22/08/2018	10:30	93,820	St Leonards	SL024908
16 Suspension 1	Replace both F/Struts.						
16 Suspension 2	Replace both L/Arms.						
17 Tyres Replace	Replace o/s/r inner tyre.						
18 Wheels Check Torques	Done.						
44 Add Ad Blue	Fill up 15 L.						
Camera Installation	CCTV U/S Hard drive unit req. Jon Coles to replace.						
Mangar Airflo Replace PCB	Mangar Airflo Replace PCB						
Safety Inspection	Done.						
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	22/08/2018	10:00	22/08/2018	14:18	93,825	St Leonards	SL024937
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	06/09/2018	10:00	06/09/2018	12:00	95,709	St Leonards	SL025035
86 Doors	Locker door not opening. Smash handle to gain access, replace handle/Solenoid						

Unplanned Repair	11/09/2018	11:00	11/09/2018	12:00	95,709	St Leonards	SL025075
86 Doors	Replace faulty central locking solenoid						
Breakdown	21/09/2018	18:14	04/10/2018	08:00	95,709	St Leonards	SL025155
45 Engine 1 Breakdown	Turbo & Exhaust leaking. fuel smell in cab.Turbo leaking-Pentagon to repair.						
SAFETY INSPECTION	04/10/2018	08:00	05/10/2018	13:00	95,709	St Leonards	SL025253
13 Brakes 1	replaced rear pads, freed off sliders & cleaned wheels & flanges no reserve travel on park brake.Readjusted replaced aircon belt tensioner						
13 Brakes 2							
18 Wheels Check Torques							
45 Engine 1							
Safety Inspection							
Vehicle Deep Clean	08/10/2018	08:00	08/10/2018	13:30	97,571	St Leonards	SL025274
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	19/10/2018	09:45	19/10/2018	10:00	98,629	St Leonards	SL025385
34 Lights Bulb Replacement	Replace n/s/f headlight bulb						
SAFETY INSPECTION	12/11/2018	08:00	15/11/2018	16:00	101,233	St Leonards	SL025557
13 Brake Pads	Front pads next inspection.(Monitor). Checked. Shore line not ejecting.Replaced auto-eject.(2nd hand). Emg Warning Devices Reversing camera only works intermittently						
18 Wheels Check Torques							
31 Charging System							
Camera Installation							
						Monitoring	

Safety Inspection	Carried out inspection.						
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab					Monitoring	
Sealing of stretcher clamp	Sealing of stretcher clamp.Done.						
Gearbox Oil & Filter Change	Done.						
Vehicle Deep Clean	12/11/2018	10:30	12/11/2018	14:00	101,233	St Leonards	SL025559
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	24/12/2018	07:00	28/12/2018	11:30	105,554	St Leonards	SL025913
02 Windscreen Wipers	Replace both units						
13 Brake Pads	Front pads next inspection.(Monitor).						
13 Brakes 1	Replace all Disc & pads all round.						
17 Tyres	Replace 3 R/Tyres						
18 Wheels Check Torques	Done.						
34 Lighting System	Replace N/S top led unit.						
34 Lights Bulb Replacement	GU5 Replacement.						
44 Add Ad Blue	Add 15.2L Unable to book out as no stock.????????						
86 Doors	Unable to open side door from outside.Remove locks Repair damaged units						
87a - Medical Equipment Repair	Other carry chair cushion zip broken						
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab						
Safety Inspection	Done						
Vehicle Deep Clean	24/12/2018	08:00	24/12/2018	15:00	105,554	St Leonards	SL025915
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	21/01/2019	13:00	21/01/2019	13:15	107,975	St Leonards	SL026113
34 Lights Bulb Replacement	N/S side repeater inop. Replace bulb						
SAFETY INSPECTION	04/02/2019	08:00	05/02/2019	16:00	109,296	St Leonards	SL026223
02 Cab Assembly 1	Replace dash trim panel						
13 Brakes 1	Replace peddle rubber.						
17 Tyres Replace	Replace both F/Tyres.						

17 Tyres Tracking	Carried out by Tyreland/F/Comms
18 Wheels Check Torques	Done.
86 Door Seals	Replace O/S/F Door seal
89 Seatbelts	Repair 2X Saloon seatbelts.
Safety Inspection	Done.
Tail Lift 6 Monthly Inspection	Statutory Inspection. Done.

Vehicle Deep Clean	05/02/2019	07:32	05/02/2019	10:00	109,296	St Leonards	SL026232
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	07/02/2019	18:29	15/02/2019	14:42	109,468	St Leonards	SL026260
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	Replace damaged n/s mirror.
34 Lights Bulb Replacement	Replace n/s/f indecator bulb.
Breakdown	n/s wing mirror moulding needs replacing

Breakdown	06/03/2019	17:29	06/03/2019	18:00	112,650	St Leonards	SL026470
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Gen panel no power/battery EML while driving. Crew reset Genesys, ok.
-----------	-----------------------------------------------------------------------

Vehicle Deep Clean	20/03/2019	09:00	20/03/2019	14:00	113,977	St Leonards	SL026558
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	20/03/2019	07:00	25/03/2019	11:45	113,977	St Leonards	SL026559
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

16 Suspension 1	Rear A.R.B bushes worn. Replaced.
17 Tyres Replace	O/S/R/O low tread. Replaced.
18 Wheels Check Torques	Checked.
24 Driveshaft 1	Propshaft centre bearing torn. Replaced.
Safety Inspection	Carried out inspection.
93 - D Service	Carried out D service.
Service D	
Annual Heater Service	Annual Heater Service.Done.
UB Fire Suppression Service	Done.
Handbrake Cable Replacement	Replace rear handbrake cables
Annual Air Con Service	Annual Air Condition Service
Tail Lift Annual Service	Statutory Inspection and Weight Test.Done by S.W.L.

SAFETY INSPECTION	29/04/2019	07:00	01/05/2019	10:42	118,621	St Leonards	SL026842
02 Cab Assembly 1	Torch not charging. Replaced.						
02 Windscreen Wipers	O/S washers n/w. Checked and replaced pipe.						
18 Wheels Check Torques	Checked.						
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Monitor.						Monitoring
Safety Inspection	Carried out inspection.						
Vehicle Deep Clean	29/04/2019	09:00	29/04/2019	14:30	118,621	St Leonards	SL026843
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	20/05/2019	16:01	20/05/2019	18:01	120,363	St Leonards	SL027026
31 Battery Chassis	Non start. Replace cass battery.						
Breakdown	24/05/2019	18:32	29/05/2019	09:30	120,873	St Leonards	SL027062
Breakdown	offside rear inner 205/75/R16c DUTY FITTER NOT INFORMED						
Breakdown	25/05/2019	17:21	29/05/2019	09:30	120,872	St Leonards	SL027064
Breakdown	offside front 205/75/R16c DUTY FITTER NOT INFORMED						
SAFETY INSPECTION	10/06/2019	07:00	12/06/2019	09:15	122,606	St Leonards	SL027167
02 Cab Ass Fire Extinguisher	Out of date. Replaced x2.						
02 Cab Assembly 1	Passenger window switch broken. Replaced.						
17 Tyres Replace	N/S/R/I&O low tread. Replaced x2.Cleaned rims & flanges.						
18 Wheels Check Torques	Checked.						
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Monitor.						Monitoring
Safety Inspection	Carried out inspection.						
MOT							
Brakes Replace Brake Fluid	Done.						

Vehicle Deep Clean	10/06/2019	08:52	10/06/2019	13:00	122,606	St Leonards	SL027168
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	02/07/2019	10:00	02/07/2019	10:00	124,372	St Leonards	SL027333
45 Engine 1	Crew said oil low. Checked oil at maxs.??????????						
SAFETY INSPECTION	22/07/2019	07:00	23/07/2019	07:38	126,939	St Leonards	SL027464
17 Tyres Replace	N/S/F tyre low tread. Cleaned rim and flange, Replaced tyre.						
18 Wheels Check Torques	Checked.						
71 Body Exterior 1	BIG hole ripped in cill above step.						Monitoring
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Monitor.						Monitoring
Safety Inspection	Carried out inspection.						
Engine Change Oil & Filter	Done.						
Tail Lift Inspection	Done.						
Vehicle Deep Clean	23/07/2019	13:00	24/07/2019	09:30	126,945	St Leonards	SL027484
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	01/08/2019	15:00	01/08/2019	16:00	128,075	St Leonards	SL027566
17 Tyres	Front wheels balanced by ATS						
Breakdown	21/08/2019	14:29	21/08/2019	16:00	130,398	St Leonards	SL027709
17 Tyres	ATS replaced tyre						
Breakdown	fRONT NEAR SIDE LOW PUNCTURE						
Breakdown	04/09/2019	22:50	05/09/2019	23:59	132,101	St Leonards	SL027819

Breakdown	FLAT TYRE						
Vehicle Deep Clean	06/09/2019	09:00	09/09/2019	09:00	132,486	St Leonards	SL027828
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/09/2019	08:00	10/09/2019	08:04	132,486	St Leonards	SL027829
13 Brakes 1	Front pads low. Replaced. Cleaned flanges &rims.						
13 Brakes 2	Rear pads low. Replaced. Cleaned flanges and rims.						
18 Wheels Check Torques	Checked.						
71 Body Exterior 1	BIG hole ripped in cill above step.						
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Monitor.						
86 Doors Rear	Lower catch adrift. Resecure.						
86 Sliding Door	Rollers siezed. Replaced.						
Safety Inspection	Carried out inspection.						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service.Done.						
Unplanned Repair	26/09/2019	11:30	26/09/2019	12:30	134,500	St Leonards	SL028001
44 Fuel System 1	Found leak from leak off pipe. Block off pipe. Replace next insp						
Unplanned Repair	05/10/2019	10:10	05/10/2019	11:40	135,425	Dorchester	DC020963
44 Fuel System 1	Trace fuel leak to union on high pressure pipe.Tighten and test,ok						
45 Engine 1	Oil leak reported.Check vehicle, fuel leak found						
Travel Time							
Unplanned Repair	07/10/2019	10:30	07/10/2019	11:30	135,675	St Leonards	SL028095
44 Fuel System 1	fuel leak from high pressure pump. Replace union o-ring and pipe clip.						
SAFETY INSPECTION	14/10/2019	07:00	16/10/2019	15:00	136,584	St Leonards	SL028153
01 Air Conditioning 1	Replace filter.						

13 Brakes 1	Replace F/Dics & Pads.						
16 Suspension 1	Replace both F/Struts						
16 Suspension 2	Replace both F.Lower arms						
18 Wheels Check Torques	Checked.						
34 Lights	Replace N/S/R Indecator & N/S/R Re/Light.						
44 Add Ad Blue	Fill up unit 15L						
71 Body Exterior 1	BIG hole ripped in cill above step.						Monitoring
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Monitor.						Monitoring
86 Doors	Repair damaged side door						
Check Winter Pack	Checked. 2 Salt Sticks. 695 unit fitted.						
Safety Inspection	Checked						
Tail Lift Inspection	Checked & Repaired.						
Vehicle Deep Clean	16/10/2019	11:15	16/10/2019	14:30	136,584	St Leonards	SL028185
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/10/2019	00:14	25/10/2019	09:27	136,760	St Leonards	SL028273
31 Charging System Battery Breakdown	Alternator u/s.Removed and replaced alternator. Red battery alternator light on						
BREAKDOWN	03/11/2019	19:15	03/11/2019	21:30	138,405	St Leonards	SL028337
34 Lights Travel Time	o/s headlight not working						
Unplanned Repair	22/11/2019	09:45	22/11/2019	10:52	140,694	St Leonards	SL028480
45 Engine 1	EML/Ad blue light on						
SAFETY INSPECTION	02/12/2019	08:00	04/12/2019	16:00	141,819	St Leonards	SL028540
17 Tyres Replace	Replace o/s/r tyres inner & outer.						
18 Wheels Check Torques	Done.						

31 Charging System	Shoreline charger not ejecting						
34 Lights Bulb Replacement	Replace o/s/f side light.						
44 Add Ad Blue	Top up unit 12L						
45 Engine 1	Battery/Charging Sys warning light: battery/alternator						
71 Body Exterior 1	BIG hole ripped in cill above step.					Monitoring	
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Monitor.					Monitoring	
86 Doors	Repair side door mags.						
Safety Inspection	Done.						
Vehicle Deep Clean	02/12/2019	11:52	03/12/2019	09:38	141,819	St Leonards	SL028544
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	05/12/2019	15:10	06/12/2019	09:00	141,954	St Leonards	SL028576
17 Tyres Replace	Replace o/s/r tyres due to both valves lose.						
Breakdown	OSR outer flat 205/75R16 C Winter						
Unplanned Repair	18/01/2020	18:25	18/01/2020	20:15	146,206	Dorchester	DC021620
01 Heating 1	Saloon heater fault reported.See notes						
Travel Time							
SAFETY INSPECTION	20/01/2020	08:00	22/01/2020	12:00	146,206	St Leonards	SL028905
01 Heating 1	Saloon heater inop -Air con statt control unit has been removed.??????					Monitoring	
02 Windscreen Wipers	Replace both units.						
17 Tyres Replace	Replace N/S/F N/S/R inner & outer.						
18 Wheels Check Torques	Checked.						
44 Add Ad Blue	Top up unit 9L.						
45 Engine 1	Replace Tensioners. Pulleys.						
56 Comms Equipment	Repair battery charger						
71 Body Exterior 1	BIG hole ripped in cill above step.					Monitoring	
71 Body Exterior 2	Repair N/S/R Damage.						
71 Body Exterior 3	Repair damaged n/s f/wing & bumper						
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Monitor.					Monitoring	
89 Seats	Repair saloon seats.						
Safety Inspection	Checked						
Tail Lift Inspection	Checked & Repaired.						

Vehicle Deep Clean	22/01/2020	11:29	22/01/2020	15:00	146,206	St Leonards	SL028936
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	14/02/2020	09:51	14/02/2020	12:00	152,100	St Leonards	SL029138
Breakdown	flat tyre						
Unplanned Repair	25/02/2020	10:30	25/02/2020	11:30	154,144	St Leonards	SL029208
34 Lights	O/S stop/tail lamp damaged. Replace lamp. Remove all lamps to fit.						
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Monitor.						Monitoring
Unplanned Repair	26/02/2020	10:30	26/02/2020	11:00	154,219	St Leonards	SL029216
34 Lights	Body Exterior o/s rear brake light lens broken. Already replaced on 25.2.20						
44 Add Ad Blue	Top up Adblue						
45 Engine 1	Fan belt squeel - To repair next insp						Monitoring
SAFETY INSPECTION	02/03/2020	07:00	18/03/2020	11:00	155,196	St Leonards	SL029249
01 Heating 1	Saloon heater inop -Air con statt control unit has been removed.??????						Monitoring
18 Wheels Check Torques	Checked.						
34 Emergency Lights	Top blue light insecure						
45 Engine 1	Fan belt squeel - To repair next insp						
55 Tail Lift	Tilt sensor n/w. Replaced.						
71 Body Exterior 1	BIG hole ripped in cill above step. Autospray						Awaiting Body Repair
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Autospray						Awaiting Body Repair
87 Oxygen System	Pipe kinked at bottle. MDC repaired.						
87a - Medical Equipment Repair	Mobi med not charging. Repaired.						
Safety Inspection	Carried out inspection.						
Pollen Filter Change	Pollen Filter Change. Done.						
Fuel Filter Change	Change Fuel Filter. Done.						
Air Filter Change	Air Filter Change. Done.						
Engine Change Oil & Filter	Done.						

Unplanned Repair	03/03/2020	09:00	03/03/2020	09:42	155,196	MDT Ferndown	TF000369
87 Oxygen System	Replaced 2x Oxygen cylinder connection probes to 45' probes as pipes kinked.						
Vehicle Deep Clean	18/03/2020	12:01	18/03/2020	14:30	155,341	St Leonards	SL029383
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/03/2020	10:54	23/03/2020	11:30	155,845	St Leonards	SL029415
71 Body External Steps	Side step n/w. Checked to find wiring wrong(Going through Genysis!) See notes.						
Unplanned Repair	25/03/2020	10:45	25/03/2020	11:45	156,126	St Leonards	SL029439
71 Body External Steps	Side step inop.Rewire too by-pass Genysis system.						
SAFETY INSPECTION	06/04/2020	07:00	07/04/2020	10:00	157,828	St Leonards	SL029511
01 Heating 1	Saloon heater inop -Air con statt control unit has been removed.??????						
17 Tyres Replace	Replace o/s/f Tyre.						
18 Wheels Check Torques	Checked						
44 Add Ad Blue	Top up unit. 9L						
52 Electrical Aux	Replace Missing Torch.						
71 Body Exterior 1	BIG hole ripped in cill above step. Autospray						
71 Body Exterior Acc Repair	O/S/R corner, N/S/R top corner, Rear wheel arches damaged. Autospray						
85 Body Interior 1	Repair storage unit						
Safety Inspection	Checked						
Tail Lift Inspection	Checked.						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
UB Fire Supp 12mts Service	Service of fire supression system. Serviced.						
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
Vehicle Deep Clean	07/04/2020	08:48	07/04/2020	11:00	157,828	St Leonards	SL029517
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	11/05/2020	07:00	14/05/2020	11:00	161,947	St Leonards	SL029826
01 Heating 1	Other Rear heater blowing cold air						
02 Windscreen Wipers	Replace wiperblades						
13 Brakes 1	Rears worn						
13 Brakes 2	rubber u/s						
15 Steering 1	inner joint worn						
16 Suspension 1	spring eye bushes worn						
16 Suspension 2	Slipp pads 2x						
17 Tyres	2x rear worn						
18 Wheels Check Torques							
71 Body Exterior 1	Rear flap loose						
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Tail Lift 12M Service & Weight MOT	Tail Lift 12M Service & Weight						
Vehicle Deep Clean	11/05/2020	12:16	11/05/2020	15:00	161,947	St Leonards	SL029833
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	22/06/2020	12:00	24/06/2020	08:00	166,730	St Leonards	SL030218
02 Cab Assembly 1	Drivers window switch broken. Replaced.						
02 Cab Assembly 2	Interior light n/w. Replaced bulb.						
18 Wheels Check Torques	Checked.						
55 Tail Lift	Bridge plate guide block sheared. Replaced insert and resecure.						
Safety Inspection	Carried out inspection.						
Tail Lift Inspection	Done.						
Vehicle Deep Clean	24/06/2020	08:21	24/06/2020	11:30	166,730	St Leonards	SL030228
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	01/07/2020	13:00	01/07/2020	14:00	167,481	St Leonards	SL030307

24 Driveshaft 1 Engine vibration between 35-40MPH. Replace rear propshaft

SAFETY INSPECTION 30/07/2020 07:00 30/07/2020 12:06 171,523 St Leonards SL030581

02 Cab Ass Fire Extinguisher Out of date x2. Replaced x2.
 17 Tyres Replace N/S/R/I tyre low tread. Replaced.Cleaned rim's & Flanges.
 18 Wheels Check Torques Checked.
 Safety Inspection Carried out inspection.
 Replace Vehicle Fuel Card Replace Vehicle Fuel Card

Vehicle Deep Clean 31/07/2020 06:27 31/07/2020 10:00 171,523 St Leonards SL030594

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 14/09/2020 07:00 16/09/2020 16:00 178,925 St Leonards SL030969

01 Air Conditioning 1 Clean out intake box & Replace Filter.
 02 Windscreen Wipers Replace both units.
 13 Brake Pads Replace F/Pads.
 17 Tyres Replace Replace 6 Tyres. 3 Tyres back in store room as part worns. booked out 3 Tyres
 18 Wheels Check Torques Checked.
 31 Battery Chassis Replace unit.
 42 Coolant System Replace header tank due to fault in sensor.
 43 Exhaust System 1 Replace damaged tailpipe
 44 Add Ad Blue Top up unit 15L
 52 Electrical Aux Replace N/S Window switch (Damaged)
 85 Body Interior 1 Repair damaged cab storage unit.
 Safety Inspection Checked.
 Wear & Tear Repair Clean up all 4 Flanges.
 Auto G/box Oil & Filter Change Auto G/box Oil & Filter Change
 Tail Lift Inspection Inspected.

Vehicle Deep Clean 16/09/2020 11:26 16/09/2020 15:00 178,925 St Leonards SL031003

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	28/10/2020	09:00	29/10/2020	15:00	184,743	St Leonards	SL031404
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Checked.
Engine Change Oil & Filter	Replaced.
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service. Checked all ok.

Vehicle Deep Clean	28/10/2020	10:51	28/10/2020	14:00	184,743	St Leonards	SL031409
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	04/11/2020	11:25	04/11/2020	11:44	185,797	Dorchester	DC023627
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1	Saloon heater reported inop.Saloon aircon was on.Check operation of heater,ok
--------------	-------------------------------------------------------------------------------

SAFETY INSPECTION	03/12/2020	06:00	04/12/2020	15:00	190,101	St Leonards	SL031732
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Assembly 1	Cubby box knob missing. Replaced.	
02 Cab Assembly 2	Interior light n/w. Replaced bulb.Trace and repair wiring.	
13 Handbrake	Low effort N/S. Adjusted.	
17 Tyres	Wrong tyre pressures displayed. No valve extensions fitted to O/S/R. Fitted.	
18 Wheels Check Torques	Checked.	
24 Driveshaft 1	Propshaft center bearing torn.	
34 Emergency Lights	O/S/R top corner blue light damaged. Replaced.	
34 Lighting System	N/S/R top light pod broken.	Monitoring
34 Lights	Saloon interior light lens's broken x3. Parts on order.	Monitoring
41 Air Intake	Replace missing pipe	
55 Tail Lift	Tilt sensor n/w. Replaced.	
71 Body Exterior 1	N/S/F top corner cap broken.	Monitoring
86 Sliding Door	Magnet n/w. Re-aligned bracket.	
Safety Inspection	Carried out inspection.	
Tail Lift Inspection	Done.	

Vehicle Deep Clean	04/12/2020	11:41	07/12/2020	07:00	190,101	St Leonards	SL031753
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	23/12/2020	14:00	24/12/2020	12:00	191,961	St Leonards	SL031956
45 Engine 1	Fumes in cab - Replace injector seals						
Unplanned Repair	07/01/2021	09:15	07/01/2021	09:30	193,893	St Leonards	SL032085
02 Mirrors	other N/S wing mirror broken. Replaced						
Breakdown	13/01/2021	00:53	13/01/2021	06:00	194,465	St Leonards	SL032127
Breakdown	Both R/O/S tyres flat						
SAFETY INSPECTION	20/01/2021	07:41	25/01/2021	16:00	195,523	St Leonards	SL032208
02 Cab Assembly 1	Radio surround broken.						
13 Brakes 1	Front disc's &pads worn. Replaced.						
18 Wheels Check Torques							
34 Lighting System	N/S/R top light pod broken.					Monitoring	
34 Lights	Saloon interior light lens's broken x3. Parts on order.					Monitoring	
34 Lights Bulb Replacement	o/s running light n/w.replaced bulb.						
43 Exhaust System 1	EGR pipe cracked.						
71 Body Exterior 1	N/S/F top corner cap broken.						
85 Body Interior 1	Cupboard hinges loose,shelf broken.						
86 Sliding Door	Replace side door bearing						
Safety Inspection							
Pollen Filter Change	Pollen Filter Change						
Axle Oil Change	Axle Oil Change						
Vehicle Deep Clean	20/01/2021	08:30	20/01/2021	12:25	195,523	St Leonards	SL032210
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	30/01/2021	22:05	01/02/2021	06:30	196,156	St Leonards	SL032314
Breakdown	nearside side indicator; slide door sensor n/w					Monitoring	

SAFETY INSPECTION	26/02/2021	06:00	03/03/2021	13:45	199,742	St Leonards	SL032559
13 Handbrake	Low effort n/s&o/s. Adjusted.						
17 Tyres	Valve extensions missing. Replaced.						
18 Wheels Check Torques	Checked.						
34 Lighting System	N/S/R top light pod broken. O/S brake lights inop.Rewire rear lights.						
34 Lights	Saloon interior light lens's broken x3. Replaced.						
34 Lights Bulb Replacement	O/S Rev light full of water. Replaced.						
55 Tail Lift	Tail lift blocks adrift, Tilt sensor n/w, Replaced.						
Breakdown	slide door sensor n/w.						
Safety Inspection	Carried out inspection.						
Tail Lift Inspection	Done.						

Vehicle Deep Clean	02/03/2021	05:53	03/03/2021	16:00	199,742	St Leonards	SL032584
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	13/04/2021	06:00	15/04/2021	12:00	205,146	St Leonards	SL032964
13 Brakes 1	Replace rear discs and pads						
15 Steering 1	Replace n/s track rod end						
16 Suspension 1	Replace spring buffer pads						
16 Suspension 2	Replace front susp arms						
18 Wheels Check Torques							
34 Lights	Replace scene light and n/s/f marker lamp						
34 Lights Bulb Replacement	Replace n/s/f side light bulb						
71 Body Exterior 1	Replace o/s/r corner cap						
86 Sliding Door	Straighten side door magnet catch						
89 Seats	Secure rear facing saloon seat						
Safety Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
UB Fire Supp 12mts Service	Service of fire supression system						
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
MOT							

Vehicle Deep Clean	15/04/2021	07:19	16/04/2021	07:00	205,146	St Leonards	SL032982
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	31/05/2021	13:22	01/06/2021	06:00	210,155	St Leonards	SL033398
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	significant diesel leak; VOR - Defect moved to inspection job card	Monitoring
-----------	--------------------------------------------------------------------	------------

SAFETY INSPECTION	01/06/2021	06:00	03/06/2021	09:00	210,155	St Leonards	SL033402
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Cab Assembly 1	Interior light n/w. Replaced bulb.	
02 Cab Assembly 2	Drivers sun visor torn. Replaced.	
17 Tyres Replace	N/S/R/I low tread,N/S/R/O punctured. Replaced x2.	
17 Tyres Tracking	Replaced both front tyres-worn inner edges.Reset tracking.	
18 Wheels Check Torques	Checked.	
34 Lights Bulb Replacement	N/S running light n/w. Replaced bulb.	
44 Fuel System 1	Fuel leak. Replaced filter & pipe.	
52 Electrical Aux	230V tell tail lights broken. Replaced.	
71 Body Exterior Acc Repair	N/S/R top light pod smashed.	Monitoring
86 Doors Rear	Lock barrell siezed. Replaced saloon set.	
Breakdown	significant diesel leak; VOR.Replaced fuel filter & bleed pipe with clip.	
Safety Inspection	Carried out inspection.	
Annual Heater Service	Annual Heater Service. Done.	
Annual Air Con Service	Annual Air Condition Service. Done.	
Replace Handbrake Cables	Replace Handbrake Cables. Done.	
Tail Lift Inspection	Done.	
Engine Change Oil & Filter	Done.	
Brake Fluid Change	Brake Fluid Change. Done.	

Vehicle Deep Clean	03/06/2021	09:53	03/06/2021	13:30	210,155	St Leonards	SL033433
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	27/06/2021	16:35	28/06/2021	06:45	212,495	St Leonards	SL033624
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	fire suppression warning on; VOR	Monitoring
-----------	----------------------------------	------------

Breakdown	04/07/2021	12:28	05/07/2021	10:00	213,205	St Leonards	SL033675
27 Transmission Automatic	Stuck in park. No fault found						
32 Starting System 1	Non start. Replace chassis battery						
45 Engine 1	EML and LOP. No fault found						
Breakdown	will not go into D						
Road Test							
UB Fire Supp Repair	Fire supp audio warning sounding. No fault found						

SAFETY INSPECTION	12/07/2021	08:00	15/07/2021	12:00	213,928	St Leonards	SL033756
02 Cab Ass Fire Extinguisher	Out of date x2. Replaced x2.						
18 Wheels Check Torques	Checked.						
34 Emergency Lights	Airport light n/w. Replaced.						
34 Lighting System	O/S scene light n/w. Genysis panel ordered.						
56 Radio	Roof aerial missing. Replaced.						
71 Body Exterior Acc Repair	N/S/R top light pod smashed.						
86 Sliding Door	Lower catch & Cover adrift. Replaced / resecured. straightened magnet mount.						
89 Seats	Drivers seat base cover & cushion worn. Replaced.						
Breakdown	fire suppression warning on; VOR						
Safety Inspection	Carried out inspection.						

Vehicle Deep Clean	14/07/2021	09:51	14/07/2021	14:00	213,928	St Leonards	SL033790
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	27/07/2021	14:00	31/07/2021	16:00	215,125	St Leonards	SL033933
42 Coolant System	Coolant leak - Overheating?						
45 Engine 1	EML on						
Breakdown	coolant on max; VOR						

Vehicle Deep Clean	24/08/2021	08:13	24/08/2021	11:30	217,009	St Leonards	SL034189
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	25/08/2021	15:00	26/08/2021	15:00	217,009	St Leonards	SL034209
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

16 Suspension 1	Replace rear A.R.B bushes	
18 Wheels Check Torques		
34 Lighting System	O/S scene light n/w. Genysis panel ordered. No fault found	
45 Engine 1	Replace engine mount	
55 Tail Lift	Straighten and secure tail lift underun blocks	
71 Body Exterior Acc Repair	N/S/R top light pod smashed.	Monitoring
85 Body Interior 1	Replace locker strap	
85 Body Interior 2	Secure saloon cupboard hinges and grab handle	
86 Doors	Straighten side door magnet bracket	
86 Doors Rear	Secure rear door cover	
86 Sliding Door	Doors Unable to open side door for long periods of time. No fault found.	
89 Seats	Secure saloon seat base	
Safety Inspection		
Tail Lift Inspection		

Breakdown	03/09/2021	10:12	03/09/2021	12:05	217,289	St Leonards	SL034286
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1	EML on	
Breakdown	EML amber warning constantly on	

Vehicle Deep Clean	07/10/2021	07:51	07/10/2021	11:00	220,668	St Leonards	SL034588
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean	
--------------------	--------------------	--

SAFETY INSPECTION	07/10/2021	11:00	08/10/2021	13:19	220,668	St Leonards	SL034595
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.	
55 Tail Lift	Guide blocks adrift x3. Resecured.	
71 Body Exterior 2	Rain gutter above side door pulled off. Replaced.	
71 Body Exterior Acc Repair	N/S/R top light pod smashed.	Monitoring
Safety Inspection	Carried out inspection.	

Breakdown	17/10/2021	00:23	18/10/2021	06:30	221,346	St Leonards	SL034686
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	O/S Blue Light Not Working	Monitoring
-----------	----------------------------	------------

Breakdown	17/10/2021	00:25	18/10/2021	06:30	221,346	St Leonards	SL034687
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	side door can't open					Monitoring	
-----------	----------------------	--	--	--	--	------------	--

Vehicle Deep Clean	11/11/2021	11:55	12/11/2021	08:00	223,599	St Leonards	SL034931
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	15/11/2021	06:00	16/11/2021	08:00	223,599	St Leonards	SL034947
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

17 Tyres	Replace o/s/r/o tyre						
18 Wheels Check Torques							
34 Emergency Lights	Replace o/s top blue light and secure blue light front cover						
45 Engine 1	Replace tensioner						
71 Body Exterior 1	Replace o/s/r lower coner cap and n/s/r reflector						
71 Body Exterior Acc Repair	N/S/R top light pod smashed.					Monitoring	
85 Body Interior 1	Repair various saloon cupboards						
Breakdown	side door can't open						
Safety Inspection							
UB Fire Supp Repair	Low pressure warning sounding					Monitoring	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Tail Lift Inspection							

Breakdown	11/12/2021	12:57	13/12/2021	07:15	225,885	St Leonards	SL035210
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Vehicle locking not working					Monitoring	
-----------	-----------------------------	--	--	--	--	------------	--

Unplanned Repair	14/12/2021	07:00	20/12/2021	10:00	226,047	St Leonards	SL035217
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windscreen Wipers	Wipers not clearing screen						
34 Lights Bulb Replacement	Lighting System R/H indicator blown						
45 Engine 1	Fumes in cab. Poss injectors leaking dealers to comply - Rygor Westbury						
UB Fire Supp Repair	Low pressure warning sounding					Monitoring	

SAFETY INSPECTION	05/01/2022	07:00	06/01/2022	07:00	227,833	St Leonards	SL035380
13 Brakes 1	Front pads low. Replaced. Cleaned rim's & flanges.						
18 Wheels Check Torques	Checked.						
71 Body Exterior Acc Repair	N/S/R top light pod smashed.						Monitoring
Breakdown	Vehicle locking not working. Checked & Lubed all locks.OK.						
Safety Inspection	Inspection.						
UB Fire Supp Repair	Low pressure warning sounding						Monitoring
Vehicle Deep Clean	06/01/2022	07:52	06/01/2022	11:30	227,833	St Leonards	SL035400
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	07/01/2022	13:38	10/01/2022	09:24	227,866	St Leonards	SL035417
Breakdown	ESP Warning Light/Visit W/Shops						
Breakdown	31/01/2022	00:49	31/01/2022	06:30	230,000	St Leonards	SL035606
Breakdown	headlight out						Monitoring
Breakdown	01/02/2022	07:46	02/02/2022	06:00	230,621	St Leonards	SL035626
Breakdown	Fire suppression alarming						Monitoring
Unplanned Repair	08/02/2022	13:15	08/02/2022	14:15	231,702	St Leonards	SL035704
56 Comms Power Failure	Replace comms battery						
Breakdown	09/02/2022	02:21	11/02/2022	08:00	231,795	St Leonards	SL035705
13 Brakes 1	Brake force distribution light on.See notes.						
56 Comms Equipment	Batteries not charging/ low voltage						
Breakdown	RED WARNING BRAKE FORCE DISTRIBUTION						

Breakdown	15/02/2022	15:16	15/02/2022	15:16	232,351	St Leonards	SL035759
Breakdown	Red Brake,Orange ABS&traction control					Monitoring	
Vehicle Deep Clean	16/02/2022	07:08	16/02/2022	10:00	232,351	St Leonards	SL035762
Vehicle Deep Clean	Vehicle Deep Clean						
O2 Pipeline Annual Inspection	17/02/2022	09:44	17/02/2022	09:50	232,353	MDT Ferndown	TF001798
O2 Pipeline Annual Inspection 87 Oxygen System	Annual Inspection and Pressure Test Repair leaks - replaced 1x outlet port seat & 1x O2 changeover valve gauge.						
SAFETY INSPECTION	21/02/2022	12:55	15/03/2022	08:00	232,353	St Leonards	SL035800
01 Heating 1	Saloon heater n/w on auto.Checked,replaced temp sensors x2.						
02 Cab Assembly 1	Interior light n/w.Replaced bulb.						
17 Tyres Replace	N/S/R/I tyre low tread. Replaced.cleaned rim's & flange.						
18 Wheels Check Torques	Checked.						
45 Engine 1	Oil leak from rear of engine. Possibly rear main.TO DEALER.						
55 Tail Lift	Platform lights n/w, Roll flap siezed in up postion.see notes.						
71 Body Exterior Acc Repair	N/S/R top light pod smashed.					Monitoring	
Breakdown	Red Brake,Orange ABS&traction control. TO DEALER.						
Safety Inspection	Carried out inspection.						
UB Fire Supp Repair	Low pressure warning sounding. NO PARTS.						
Tail Lift Inspection	Done.						
Unplanned Repair	21/03/2022	11:00	21/03/2022	12:09	232,669	St Leonards	SL036015
03 Instruments & Sensors 1	Fire suss alarm going off						
Breakdown	27/03/2022	05:21	28/03/2022	11:14	233,321	St Leonards	SL036066
Breakdown	engine rattle/oil spill; VOR						
15 Steering 1	PAS pump u/s						

Breakdown	03/04/2022	09:37	04/04/2022	06:15	233,333	St Leonards	SL036116
Breakdown 44 Fuel System 1	fuel cap not fitting properly Replace fuel cap						
Breakdown	09/04/2022	22:06	11/04/2022	06:00	234,105	St Leonards	SL036170
Breakdown	fuel tags missing					Monitoring	
Breakdown	14/04/2022	18:38	15/04/2022	06:00	234,649	St Leonards	SL036209
Breakdown	Red Brake Force light					Monitoring	
SAFETY INSPECTION	25/04/2022	10:30	25/04/2022	10:30	235,092	St Leonards	SL036274
18 Wheels Check Torques Safety Inspection 71 Body Exterior Acc Repair Breakdown	N/S/R top light pod smashed. Red Brake Force light					Monitoring Monitoring	
Vehicle Deep Clean	25/04/2022	10:30	25/04/2022	10:30	235,092	St Leonards	SL036275
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	25/04/2022	10:30	28/04/2022	09:00	235,092	St Leonards	SL036276
18 Wheels Check Torques Safety Inspection 71 Body Exterior Acc Repair Breakdown UB Fire Supp 12mts Service Wheel Hub Flanges Replaceme Engine Change Oil & Filter MOT 45 Engine 1 18 Wheels 17 Tyres Replace 02 Windscreen Wipers	N/S/R top light pod smashed. Red Brake Force light Service of fire supression system Engine oil leak (Rear main) Cut off wheel nuts fitted by A.T.S Replace O/S/R Inner Tyre Replace Damaged wipers. [Not Worn]						

01 Air Conditioning 1	Replace Filter & Clean out filter box.						
44 Add Ad Blue	Top up unit 9L Replace Damaged Cap						
13 Brakes 1	Replace worn out peddle rubber						
86 Door Seals	Replace worn out Drivers door seal.						

ACCIDENT	25/04/2022	07:00	27/04/2022	15:00	235,092	St Leonards	SL036281
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body Exterior 1	Underside Damage. Repair Handbrake supports R/Shock supports X More						
13 Brakes 1	Replace all R/Brakes & Handbrake as have been draged along locked up.						
18 Wheels	Replace R/Wheel brearings as they have been cooked.						
71 Body Exterior 2	Replace Damaged O/S/R Indecator. Replace Damaged O/S/R Fog Light.						

Vehicle Deep Clean	28/04/2022	06:33	28/04/2022	12:30	235,092	St Leonards	SL036329
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Breakdown	06/05/2022	05:19	09/05/2022	06:00	235,106	St Leonards	SL036429
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	CUT OUT TWICE/ BRAKE DISTRIBUTION FAILURE					Monitoring	
-----------	-------------------------------------------	--	--	--	--	------------	--

Unplanned Repair	09/05/2022	10:30	09/05/2022	11:30	236,659	St Leonards	SL036470
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Chassis	Replaced						
--------------------	----------	--	--	--	--	--	--

Breakdown	09/05/2022	21:23	10/05/2022	12:00	236,659	St Leonards	SL036473
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Lots of engine powering down warn lights						
56 Comms Power Failure	Replace Aux battery						
13 Brakes 1	Brake force distribution light on - Set up snap on. Replace key						
33 Ignition System	New ignition key required x2 - Remove spare key from key locker in office					Monitoring	

Unplanned Repair	19/05/2022	10:30	19/05/2022	11:30	237,437	St Leonards	SL036613
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Aux	Replaced						
----------------	----------	--	--	--	--	--	--

Breakdown	03/06/2022	02:55	06/06/2022	08:21	238,898	St Leonards	SL036746
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Outside sidedoor handle broke
86 Sliding Door	Side door handle broken off. Replaced & adjusted.

Vehicle Deep Clean	13/06/2022	10:04	13/06/2022	13:41	240,062	St Leonards	SL036816
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	14/06/2022	12:26	16/06/2022	12:06	240,062	St Leonards	SL036826
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
Breakdown	CUT OUT TWICE/ BRAKE DISTRIBUTION FAILURE
33 Ignition System	New ignition key required x2 - Remove spare key from key locker in office
Tail Lift Inspection	Done.
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service.Dissconected. Waiting jack-tone system.
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service. Done.
Replace Handbrake Cables	Replace Handbrake Cables. Done.
02 Cab Assembly 1	Interior light n/w. Replaced bulb.
45 Engine 1	EML on.Replaced NOX sensor.
17 Tyres Replace	O/S/F tyre worn. Replaced,Cleaned rim & flange.
55 Tail Lift	Guide blocks adrift x3.
86 Door Lock	Saloon door locks siezed x3. Replaced.

Breakdown	30/06/2022	14:52	01/07/2022	06:00	241,000	St Leonards	SL036965
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	not plotting & reversing camera not working	Monitoring
-----------	---------------------------------------------	------------

Unplanned Repair	04/07/2022	10:00	05/07/2022	14:30	241,300	St Leonards	SL036997
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Equipment	Comms tracking fault - Logistics to arrange repair
--------------------	----------------------------------------------------

Unplanned Repair	19/07/2022	07:30	04/08/2022	15:00	242,371	St Leonards	SL037135
45 Engine 1 001 Recover Vehicle	Engine oil leak - Rygor Westbury to repair Vehicle Recovery						
Breakdown	04/08/2022	08:13	04/08/2022	15:00	242,371	St Leonards	SL037253
Breakdown	Trowbridge to ferndown transport						
Unplanned Repair	12/08/2022	10:29	12/08/2022	11:00	242,929	St Leonards	SL037313
02 Cab Assembly 1	Blower motor inop						
Vehicle Deep Clean	22/08/2022	06:12	22/08/2022	06:17	243,834	St Leonards	SL037355
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	22/08/2022	06:17	22/08/2022	09:30	243,834	St Leonards	SL037356
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/08/2022	09:00	23/08/2022	09:00	243,834	St Leonards	SL037367
18 Wheels Check Torques Safety Inspection							
SAFETY INSPECTION	23/08/2022	09:00	05/09/2022	15:00	243,834	St Leonards	SL037368
18 Wheels Check Torques Safety Inspection Breakdown Tail Lift 12M Service & Weight Tail Lift Inspection 55 Tail Lift 52 Electrical Aux 45 Engine 1 15 Steering 1	Checked Checked. Failed. not plotting & reversing camera not working. No fault found. Working corretly Tail Lift 12M Service & Weight. SWL To Service SWL To Inspect Taillift faut - Possible valve block - SWL to repair Inverter Fault. Replace unit. Rear main oil seal leaking - Back to Rygor Westbury Steering rack leak - Rygor Westbury to repair						

16 Suspension 1	Replace both F/Lower arms as more than 3.5mm
16 Suspension 2	Replace both F/Struts as worn.
13 Brakes 1	Replace worn out F/Brakes. Also both calibers bleed system
71 Body Exterior 1	Re-Fit F/Bumper
17 Tyres Replace	Replace N/S/F Tyre. Due to Nail.

Breakdown	11/09/2022	10:42	12/09/2022	06:30	243,998	St Leonards	SL037503
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	HANDBRAKE WARNING ON					Monitoring
-----------	----------------------	--	--	--	--	------------

Unplanned Repair	12/09/2022	15:00	13/09/2022	07:30	244,013	St Leonards	SL037512
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

13 Brakes 1	Brake force distribution light on. Set up scanner and replace key						
-------------	-------------------------------------------------------------------	--	--	--	--	--	--

Breakdown	22/09/2022	08:33	22/09/2022	11:33	245,000	St Leonards	SL037616
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Front Number plate snapped						
-----------	----------------------------	--	--	--	--	--	--

Unplanned Repair	06/10/2022	06:00	06/10/2022	07:00	245,950	St Leonards	SL037719
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

55 Tail Lift	Replace tail lift battery						
--------------	---------------------------	--	--	--	--	--	--

Breakdown	23/10/2022	20:15	24/10/2022	07:21	247,000	St Leonards	SL037918
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Tail lift deployed audio warning all the time; VOR						
55 Tail Lift	Tail lift audio warning sounding						

Unplanned Repair	08/11/2022	10:30	08/11/2022	12:20	249,287	St Leonards	SL038056
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

03 Instruments & Sensors 1	ABS light on						
----------------------------	--------------	--	--	--	--	--	--

SAFETY INSPECTION	10/11/2022	07:27	10/11/2022	07:27	249,287	St Leonards	SL038077
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION **09/11/2022** **07:27** **16/11/2022** **12:30** **249,287** **St Leonards** **SL038078**

18 Wheels Check Torques
Safety Inspection

Breakdown	HANDBRAKE WARNING ON NFF
Tail Lift Inspection	
Pollen Filter Change	Pollen Filter Change
85 Body Interior 1	interior repairs
55 Tail Lift	Fault with flaher lights not working on tail lift
Aux drive belt change	Aux drive belt change
17 Tyres Replace	replace rear tyres

Vehicle Deep Clean **15/11/2022** **09:49** **15/11/2022** **16:21** **249,287** **St Leonards** **SL038100**

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair **01/12/2022** **13:30** **02/12/2022** **10:00** **250,177** **St Leonards** **SL038303**

45 Engine 1	Fumes in cab. Replace 3x injector seals
-------------	-----------------------------------------

Unplanned Repair **13/12/2022** **13:00** **13/12/2022** **14:00** **250,739** **St Leonards** **SL038453**

01 Heating 1	Saloon heater inop - Replace control panel
--------------	--------------------------------------------

Unplanned Repair **14/12/2022** **11:00** **14/12/2022** **12:00** **250,773** **St Leonards** **SL038464**

45 Engine 1	Replace EGR valve
-------------	-------------------

BREAKDOWN **22/12/2022** **13:00** **22/12/2022** **17:26** **251,405** **St Leonards** **SL038569**

34 Lights	O/S Taillight inop
34 Lights Bulb Replacement	N/S Side light inop

SAFETY INSPECTION	03/02/2023	07:00	03/02/2023	17:21	253,624	St Leonards	SL038971
18 Wheels Check Torques Safety Inspection Tail Lift Inspection Air Filter Change Fuel Filter Change 16 Suspension 1 45 Engine 1	Safety iNSPECTION TAIL LIFT INSPECTION Air Filter Change Change Fuel Filter N/S/R leaaf spring packer Small oil leak from rear area of engine.						Monitoring
Vehicle Deep Clean	07/02/2023	11:10	09/02/2023	15:11	253,656	St Leonards	SL039259
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	21/02/2023	04:41	21/02/2023	16:00	254,692	St Leonards	SL039171
Breakdown 55 Tail Lift 31 Battery Comms 31 Battery Aux	Tail Lift Has No Power . SEE NOTES> No power to tail lift Not charging. batt test ok, traced to relay n\w, fit used replacement. Not charging. both batteries failed, renewed. relay n\w, fit used replacement						
Breakdown	23/02/2023	22:59	24/02/2023	06:30	254,692	St Leonards	SL039194
Breakdown	Yellow warning triangle on dashboard						
Unplanned Repair	26/02/2023	09:00	26/02/2023	11:00	255,055	St Leonards	SL039218
71 Body External Steps	Side step not coming out- Replace Hydraulic Ram on side step						
Unplanned Repair	09/03/2023	11:00	09/03/2023	12:00	255,764	St Leonards	SL039323
86 Sliding Door	Side door opening while driving						

SAFETY INSPECTION	17/04/2023	09:00	20/04/2023	11:30	258,111	St Leonards	SL039753
18 Wheels Check Torques							
Safety Inspection							
45 Engine 1			Small oil leak from rear area of engine.			Monitoring	
Tail Lift 12M Service & Weight			Tail Lift 12M Service & Weight				
Tail Lift Inspection							
MOT							
17 Tyres			o\s\r\o screw in tyre, renew, clean flanges & wheels, torq, r\test & retorq.				
02 Windscreen Wipers			clean out & renew jet.				
13 Brakes 1			adj park brake travel.				
16 Suspension 1			renew spring packer o\s\r spring.				
Vehicle Deep Clean	19/04/2023	08:13	20/04/2023	10:00	258,111	St Leonards	SL039782
Vehicle Deep Clean			Vehicle Deep Clean				
02 Pipeline Annual Inspection	17/04/2023	11:40	17/04/2023	11:42	258,111	MDT Ferndown	TF002636
02 Pipeline Annual Inspection			Annual Inspection and Pressure Test - No faults found.				
Breakdown	13/05/2023	21:04	14/05/2023	09:17	259,787	St Leonards	SL040111
Breakdown			Side Door Outside Handle broken. replaced outer handle				
Unplanned Repair	22/05/2023	09:30	22/05/2023	14:11	260,481	St Leonards	SL040227
34 Lights Bulb Replacement			N/S daylight running light				
SAFETY INSPECTION	30/05/2023	09:00	30/05/2023	12:35	261,251	St Leonards	SL040335
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 6mts Service			UB Fire Supp 6mts Service				

85 Body Interior 1	Fit P clips for AVP						
Breakdown	05/06/2023	05:54	05/06/2023	06:39	261,251	St Leonards	SL040409
Breakdown	fire suppression system deployed						
Breakdown	11/06/2023	17:07	12/06/2023	13:15	261,380	St Leonards	SL040507
Breakdown 45 Engine 1	?turbo EML/LOP						
Unplanned Repair	14/06/2023	12:30	14/06/2023	13:00	262,475	St Leonards	SL040553
31 Battery Chassis	Test and replace chassis battery						
Replace Vehicle Fuel Card	10/07/2023	13:16	10/07/2023	13:16	263,909	St Leonards	SL040977
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
SAFETY INSPECTION	11/07/2023	10:00	12/07/2023	09:03	263,909	St Leonards	SL041000
18 Wheels Check Torques Safety Inspection Auto G/box Oil & Filter Change Auto G/box Oil & Filter Change Engine Change Oil & Filter Tail Lift Inspection							
Vehicle Deep Clean	12/07/2023	12:00	13/07/2023	10:00	263,909	St Leonards	SL041029
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	02/08/2023	20:00	03/08/2023	04:52	265,784	St Leonards	SL041369
Breakdown	Side Door Faulty / handle						

Breakdown	07/08/2023	13:48	26/08/2023	12:48	265,784	St Leonards	SL041434
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Acceleration gone and juddering when engine run
27 Transmission Automatic	Loss of drive - Rygor Westbury to repair
002 Major Unit Replace Gearbo	Replaced by Rygor Westbury

SAFETY INSPECTION	28/08/2023	06:00	30/08/2023	14:06	265,784	St Leonards	SL041708
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
UB Fire Supp 12mts Service	Service of fire suppression system
Brake Fluid Change	Brake Fluid Change
Replace Handbrake Cables	Replace Handbrake Cables
16 Suspension 1	Rear buffer pads torn both front
13 Brake Pads	Replace front brake pads
17 Tyres Replace	Replace worn front tyres
17 Tyres Tracking	Front wheels worn unevenly, Tracking required to adjust camber.
Wheel Hub Flanges Replacement	Front flanges badly corroded
13 Brakes 2	Brake pipe corroded by telma box, Replaced
01 Air Conditioning 1	cab aircon not working, compressor u/s replaced.
01 Air Conditioning 2	saloon aircon not working, leaking on joint replaced clips.
02 Cab Assembly 1	driver door window switch broken. Replaced
02 Windscreen	washer check valve broken.
34 Lights Bulb Replacement	dip beam bulb blown. OSF
45 Engine 1	Resenator seals leaking. Replaced

Monitoring

Vehicle Deep Clean	30/08/2023	10:00	30/08/2023	15:00	265,784	St Leonards	SL041741
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	02/10/2023	06:00	02/10/2023	12:00	268,705	St Leonards	SL042158
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	03/10/2023	09:30	12/10/2023	17:24	268,705	St Leonards	SL042180
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
-------------------------	----------

Safety Inspection	Carried out inspection.
17 Tyres Tracking	Front wheels worn unevenly, Tracking required to adjust camber.Done.
Tail Lift Inspection	Done.
Recall Notification	Mercedes airbag recall. Done.
02 Cab Assembly 1	Interior light n/w. Replaced bulb.
86 Door Lock	Scoop lcker barrel n/w. Replaced.
02 Cab Ass Fire Extinguisher	Out of date x2. Replaced x2.
45 Engine 1	Oil leak from rear main seal & core plug rear of N/S head.
43 Exhaust System 1	O/S manifold has small crack.
24 Driveshaft 1	Rear propshaft grease nipple missing.
13 Brake Pads	Rear pads worn. Replaced.
71 Body Exterior 1	Rear panel torn. Replaced.
71 Body External Steps	Side step not deploying. Replaced ram.

Unplanned Repair	04/11/2023	12:35	04/11/2023	13:15	270,601	St Leonards	SL042654
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

45 Engine 1 Road Test	EML on.
--------------------------	---------

SAFETY INSPECTION	11/11/2023	07:27	11/11/2023	14:26	270,971	St Leonards	SL042744
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
71 Body Exterior 1	Body Exterior O/S Damage NFF
45 Engine 1	Engine Amber EML NFF
54 Reversing Systems	Other Reversing camera not working. NFF WORKING
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
24 Driveshaft 1	Prop shaft support bearing rubber slight cracking
86 Sliding Door	Sliding door not holding, magnet not making contact adjusted .

Monitoring

Vehicle Deep Clean	12/11/2023	13:09	13/11/2023	09:34	270,976	St Leonards	SL042758
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	15/11/2023	00:20	15/11/2023	13:35	271,000	St Leonards	SL042793
Breakdown	Red warning light for battery/alternator						
Unplanned Repair	20/11/2023	05:22	20/11/2023	15:45	271,549	St Leonards	SL042850
45 Engine 1	Engine Amber EML						
SAFETY INSPECTION	26/12/2023	06:54	26/12/2023	12:20	271,590	St Leonards	SL043312
18 Wheels Check Torques							
Safety Inspection							
03 Instruments & Sensors 1	Other REVERSING CAMERA NOT WORKING						
87 Stretcher	Other BLACK BALL ON STRETCHER POLE MISSING						
Install Saloon CCTV Camera	CCTV not recording						
16 Suspension 1	Rear anti roll bar link bushes worn						
Vehicle Deep Clean	27/12/2023	11:20	27/12/2023	18:00	271,590	St Leonards	SL043335
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	06/02/2024	16:48	07/02/2024	15:25	276,670	St Leonards	SL043868
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	09/02/2024	08:00	13/02/2024	15:54	276,670	St Leonards	SL043906
18 Wheels Check Torques							
Safety Inspection							
24 Driveshaft 1	Prop shaft centre bearing mount split and rear uj u/s . replaced whole propshaft						
Tail Lift Inspection	Corrosion on tail lift.						
45 Engine 1	Dpt to turbo elbow cracked. replaced elbow section and gaskets/clamps/bolts.						
85 Body Interior 1	Saloon lights inop. Checked all working ok.						
34 Lights Bulb Replacement	-NSF DRL - Both front sidelights - cab interior bulb. :- all blown. replaced all						
34 Emergency Lights	ns wing blue insecure. replace mount.-os side blue damaged. replaced.						
86 Door Lock	Rear door lock barrell housing broken. replaced barrell.						
86 Sliding Door	Sliding door outer hinge seized. replaced assembly. -upper lock cover replaced.						

55 Tail Lift	See notes	
86 Doors Rear	Rear door hinges worn/movement - Monitor	Monitoring
71 Body Exterior 1	Rear blue upper body trim insecure. resecured to body.	
85 Body Interior 2	X1 equipment straps damaged. replaced strap.	
45 Engine 2	AC Belt tensioner leaking oil excessively. replaced tensioner.	
45 Engine 3	O/S Engine mount split. replaced mount.	
13 Brakes 1	NSR Brake caliper slider seized. replaced slider pin kit.	
13 Brakes 2	Front brake discs lipped but above min thickness. pads ok at 10mm. - Monitor	Monitoring
19 Chassis 1	Telma plates rubbing. telma operating ok and no noise. - Monitor	Monitoring
19 Chassis 2	Mudflap insecure. resecured to chassis.	

Vehicle Deep Clean	20/03/2024	06:36	20/03/2024	10:46	279,490	St Leonards	SL044493
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	20/03/2024	14:00	21/03/2024	11:05	279,490	St Leonards	SL044504
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
86 Doors Rear	Rear door hinges worn/movement - Monitor.Adjusted locks.
13 Brakes 2	Front brake discs lipped Replaced disc's & pads.
19 Chassis 1	Telma plates rubbing. telma operating ok and no noise. - Monitor
45 Engine 1	EML/LOP
02 Cab Assembly 1	Tool cover & fuse cover missing.Replaced.
55 Tail Lift	Oil leak from power pack.Washed,checked, tightened blanking plug.
45 Engine 2	Oil leak O/S.Washed & checked. Delete oil filler kneck.

02 Pipeline Annual Inspection	21/03/2024	12:04	21/03/2024	12:06	279,535	MDT Ferndown	TF003377
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found.
-------------------------------	--------------------------------------------------------

Breakdown	26/03/2024	14:55	27/03/2024	16:00	279,992	St Leonards	SL044605
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Amber engine management light on. (See notes)
Engine Oil & Filter Change	Engine Oil & Filter Change

ACCIDENT	22/04/2024	01:50	09/05/2024	10:39	280,955	St Leonards	SL044991
-----------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	N/S Fog light, Headlight and bumper in accident
71 Body Exterior Acc Repair	Front end accident damage - Deer strike

Vehicle Deep Clean	10/05/2024	13:50	11/05/2024	11:13	280,999	St Leonards	SL045271
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	12/05/2024	12:00	15/05/2024	10:11	281,999	St Leonards	SL045291
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
MOT	
02 Windscreen Wipers	OS Washer jet replaced.
86 Door Lock	Rear door lock barrell broken. replaced barrell housing. - upper latch cover.
55 Tail Lift	Toe flap not sat correctly. removed and straightened end stops.
86 Doors Rear	OSR Door stay bolt loose. removed and resecured.
45 Engine 1	EML. Replaced rear nox sensor and scr catalyst.
71 Body Exterior 1	Siren cover missing. replaced cover.
01 Air Conditioning 1	Saloon ac condensor fan seized. replaced whole condensor unit.

Unplanned Repair	27/05/2024	10:00	27/05/2024	12:00	286,836	St Leonards	SL045500
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights	Body Exterior n/s indicator - Replaced ns wing indicator assembly.
56 Comms Equipment	Communication system aerial broken off. replaced aerial.
52 Electrical Aux	Electrical Auxs power failure in aux systems. all batteries and charging ok.
27 Transmission Automatic	Gearbox juddering. Road tested no juddering apparent at any speed/load.

Breakdown	09/06/2024	11:58	09/06/2024	13:30	288,053	St Leonards	SL045690
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	No siren and bull horn working - Defect moved to inspection job card	Monitoring
-----------	----------------------------------------------------------------------	------------

Vehicle Deep Clean	12/06/2024	13:33	13/06/2024	09:58	288,100	St Leonards	SL045736
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	13/06/2024	12:00	14/06/2024	16:00	288,100	St Leonards	SL045756
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Breakdown	No siren and bull horn working
34 Lights	Lighting System ns mid indicator out NFF
Engine Change Oil & Filter	
34 Lighting System	OS Scene light not working. Wire broken, retrieve wire and carry out repair.
01 Air Conditioning 1	Aircon in cab smells. Carry out air con sanitiser
71 Body External Steps	Side step not deploying. Mud restricting step. Cleaned and greased
43 Exhaust System 1	DPF u.s

SAFETY INSPECTION	30/07/2024	09:00	31/07/2024	11:08	292,657	St Leonards	SL046613
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service - Replaced whole system
Tail Lift Inspection	
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
13 Brakes 1	Rear brakes worn low. replaced rear discs and pads kit.
17 Tyres Replace	Both NSR tyres low.
15 Steering 1	Steering wheel worn. replaced.

Vehicle Deep Clean	04/09/2024	09:53	05/09/2024	11:00	296,251	St Leonards	SL047156
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	06/09/2024	10:57	09/09/2024	12:51	296,251	St Leonards	SL047177
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Medical Devices Check	Med Equip & Devices Zoll faulty. Checked by MDT
Tail Lift Inspection	
Replace Handbrake Cables	Replace Handbrake Cables

UB Fire Supp 12mts Service Service of fire suppression system
 34 Lights Bulb Replacement Alley light blown. Replaced
 02 Cab Ass Fire Extinguisher Replaced both fire Extinguishers

Vehicle Deep Clean 07/09/2024 08:44 07/09/2024 08:48 296,251 St Leonards SL047183

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair 08/10/2024 14:00 08/10/2024 15:00 298,674 St Leonards SL047646

55 Tail Lift Tail lift not operating (see notes)

Vehicle Deep Clean 14/10/2024 12:30 14/10/2024 15:30 298,890 St Leonards SL047732

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 15/10/2024 09:37 16/10/2024 09:07 298,890 St Leonards SL047756

18 Wheels Check Torques Checked.
 Safety Inspection Carried out inspection.
 71 Body Exterior 1 Body Exterior paint scuff marks on OS rear
 71 Body Exterior 2 Body Exterior O/S rear scuffed
 Pollen Filter Change Pollen Filter Change. Done.
 85 Body Interior 1 Cupboard strap broken. Replaced.
 45 Engine Oil Top Up Add 1Ltr.
 89 Seats Saloon seat arm rest bolt sheared. Drill & replaced bolt.

Unplanned Repair 25/10/2024 09:00 25/10/2024 10:46 299,777 St Leonards SL047962

86 Doors Rear Doors rear door retaining rod missing
 71 Body External Steps Side Step inop. N/F/F

Vehicle Deep Clean 25/11/2024 16:40 26/11/2024 14:30 304,039 St Leonards SL048393

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	27/11/2024	09:00	01/12/2024	06:45	304,049	St Leonards	SL048411
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
17 Tyres	N/S/F Tyre tread cut through to cords & ply
86 Sliding Door	N/S Side door stiff to open
87 - Stretchers/Chairs/Boards	Stretcher belts in wrong positions
27 Transmission Automatic	Telma unit flanges excessively worn causing loud noises
13 Brake Test	
71 Body Exterior 1	N/S/F Wheel arch liner insecure
55 Tail Lift	Tail lift side rail insecure
Tail Lift Annual Service	Tail lift tilt ram need adjusting

Vehicle Deep Clean	09/01/2025	10:04	09/01/2025	15:01	309,399	St Leonards	SL049034
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	12/01/2025	14:00	13/01/2025	13:00	309,399	St Leonards	SL049082
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
17 Tyres Replace	Replace o/s/f worn tyre - below 3mm
17 Tyres	Fit tyre valve extensions
34 Emergency Lights	Replace damaged n/s/r top blue light cover.
02 Cab Assembly 1	Replace interior light bulb
86 Sliding Door	Straighten side door magnet
85 Body Interior 1	Replace bag strap
85 Body Interior 2	Secure 2x saloon cupboard door hinges

Unplanned Repair	05/02/2025	09:00	05/02/2025	13:35	312,763	St Leonards	SL049432
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

89 Seatbelts	SRS warning light on. Codes for belt buckle drivers side. Replaced buckle
--------------	---------------------------------------------------------------------------

Vehicle Deep Clean	25/02/2025	08:49	25/02/2025	11:31	314,942	St Leonards	SL049679
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	28/02/2025	06:00	28/02/2025	16:00	314,942	St Leonards	SL049725
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test 89 Seatbelts Tail Lift Inspection 13 Brake Pads 17 Tyres Replace 86 Sliding Door 34 Lighting System 34 Lights	Check and Install MDVS windows update Other Seatbelt warning light, SRS light,Red airbag light NFF Front brake pads worn low. Replaced Replace NSR tyres due to worn low. Sliding door outer hinge rollers worn OSR sidelights not working. Broken wire repaired under vehicle OS number plater light not working. Repaired broken wire						
Vehicle Deep Clean	11/04/2025	06:00	14/04/2025	08:48	318,334	St Leonards	SL050341
Vehicle Deep Clean	Vehicle Deep Clean						
02 Pipeline Annual Inspection	10/04/2025	10:42	10/04/2025	10:43	318,334	MDT Ferndown	TF004120
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - Passed all tests.						
SAFETY INSPECTION	17/04/2025	11:00	17/04/2025	16:00	318,334	St Leonards	SL050443
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test Air Filter Change Fuel Filter Change Annual Air Con Service Annual Heater Service UB Fire Supp 6mts Service	Check and Install MDVS windows update Air Filter Change Change Fuel Filter Annual Air Condition Service Annual Heater Service UB Fire Supp 6mts Service						

Engine Change Oil & Filter	
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test
85 Body Int Alcohol Gel Dispen	
34 Lights Bulb Replacement	Replace o/s main beam bulb
02 Windscreen Wipers	Replaced
86 Door Lock	Rear and locker door locks u/s
89 Seatbelts	Drivers seatbelt frayed
16 Suspension 1	Struts and lower arms worn
13 Brake Pads	Rear pads low

Monitoring

Monitoring

Monitoring

Monitoring

MOT EXPIRES	12/05/2025	08:00	14/05/2025	16:00	321,064	St Leonards	SL050898
--------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

MOT

17 Tyres Replace

Unplanned Repair	30/05/2025	12:00	30/05/2025	12:30	322,130	St Leonards	SL051279
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Chassis	Test and replace chassis battery
--------------------	----------------------------------

Vehicle Deep Clean	10/06/2025	12:00	10/06/2025	15:24	323,185	St Leonards	SL051464
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	17/06/2025	00:19	17/06/2025	13:36	323,390	St Leonards	SL051604
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	abs/esp warning on dash
-----------	-------------------------

Unplanned Repair	01/07/2025	08:30	01/07/2025	09:30	326,847	St Leonards	SL051850
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Windscreen Wipers	Clean out washer jet bung and replace jet and adjust.
86 Sliding Door	Tighten side door catch bolts, road test, ok.

Breakdown	25/07/2025	14:17	25/07/2025	15:30	326,990	St Leonards	SL052294
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	BRAKE Warning on dash						
-----------	-----------------------	--	--	--	--	--	--

Breakdown	29/07/2025	09:14	29/07/2025	11:00	329,000	St Leonards	SL052367
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Braking impaired		Monitoring				
-----------	------------------	--	------------	--	--	--	--