

WM64JXP	A&E	Swanage Amb Stn					
PDI Inspection	13/04/2015	07:00	18/05/2015	13:00	83	St Leonards	SL016045
PDI Inspection	carried out PDI and check list.						
COMMS.FAILURE CHECK	29/05/2015	10:00	29/05/2015	11:20	2,034	Dorchester	DC013048
MDT Failure/Issue	Carry out checks as requested.Data head frozen.PCE to check						
Unplanned Repair	02/06/2015	11:00	02/06/2015	11:01	2,725	Dorchester	DC013070
45 Engine Ad Blue	topped up by bronze cmd						
Unplanned Repair	05/06/2015	01:00	05/06/2015	01:15	3,479	Dorchester	DC013083
44 Add Ad Blue	Topped up by Bronze Commander						
Unplanned Repair	11/06/2015	01:00	11/06/2015	01:15	4,794	Dorchester	DC013113
44 Add Ad Blue							
Unplanned Repair	19/06/2015	10:00	19/06/2015	10:36	6,723	St Leonards	SL016459
45 Engine Ad Blue 89 Seats	Add-Blue low - Top up Ad Blue Crew seat in saloon not turning - Free off and adjust						
SAFETY INSPECTION	23/06/2015	05:30	23/06/2015	15:00	7,667	Dorchester	DC013173
16 Suspension 1 18 Wheels Check Torques 86 Door Lock Safety Inspection	Body Exterior rear N/S ARB droplink bush failed Body Exterior locker door central knocking very noisy						

Travel Time

Vehicle Deep Clean	24/06/2015	09:00	24/06/2015	12:45	7,733	Dorchester	DC013181
---------------------------	-------------------	--------------	-------------------	--------------	--------------	-------------------	-----------------

Travel Time

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	24/06/2015	12:00	24/06/2015	13:00	7,734	Dorchester	DC013348
------------------	-------------------	--------------	-------------------	--------------	--------------	-------------------	-----------------

02 Windscreen	Repair to impact damaged windscreen
---------------	-------------------------------------

Unplanned Repair	17/07/2015	13:15	17/07/2015	13:46	12,612	Dorchester	DC013281
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

44 Add Ad Blue

Unplanned Repair	19/07/2015	20:30	19/07/2015	21:15	13,064	Dorchester	DC013290
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

86 Doors	Unable to open side door.Jammed by coat sleeve.Open door
----------	--

Travel Time

Unplanned Repair	23/07/2015	10:00	23/07/2015	10:20	13,829	Dorchester	DC013311
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Oil Top Up

Unplanned Repair	28/07/2015	13:00	28/07/2015	13:30	14,783	Dorchester	DC013332
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

44 Add Ad Blue

SAFETY INSPECTION	03/08/2015	14:43	04/08/2015	14:14	16,304	Dorchester	DC013369
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

02 Windscreen	Chip in screen	Awaiting Parts
03 Instruments & Sensors 1	O2 sensor fault	
15 Steering 1	Engine steering pulling to left.Road tested OK.	
15 Steering 2	Engine FNS wheel unbalanced, vibrates over 60mph.Replaced.	
18 Wheels Check Torques	Checked.	

87 Oxygen System Safety Inspection Travel Time	Checklist Defect Low pressure alarm sounding continuously.(Warranty). Carried out inspection.					Awaiting Warranty	
Vehicle Deep Clean	04/08/2015	12:00	05/08/2015	15:30	16,322	Dorchester	DC013376
02 Windscreen 87 Oxygen System Vehicle Deep Clean	Chip in screen Checklist Defect Low pressure alarm sounding continuously.(Warranty). Vehicle Deep Clean						
Unplanned Repair	30/08/2015	07:14	30/08/2015	08:14	21,112	Dorchester	DC013508
17 Tyres 45 Engine 1	O/S/F Tyre. No Fault Found. E.M.L On. Scan unit. Remove Fault Codes. No Fault Found At Time Of Test.						
Unplanned Repair	06/09/2015	07:46	07/09/2015	07:50	22,276	Dorchester	DC013543
44 Add Ad Blue	added by bronze cmd						
Unplanned Repair	10/09/2015	18:00	10/09/2015	18:01	23,084	Dorchester	DC013588
44 Add Ad Blue	topped up by bronze cmd						
SAFETY INSPECTION	14/09/2015	05:30	14/09/2015	12:00	24,006	Dorchester	DC013566
18 Wheels Check Torques Safety Inspection Travel Time Vehicle Deep Clean 92 - C Service Service C	VMU - Dorch. Vehicle Deep Clean						
Vehicle Deep Clean	14/09/2015	12:00	15/09/2015	12:00	24,014	Dorchester	DC013574
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	27/09/2015	09:20	27/09/2015	09:35	26,826	Dorchester	DC013635
44 Add Ad Blue	Topped up by Bronze						
Breakdown	29/09/2015	20:37	29/09/2015	21:40	26,845	Dorchester	DC013653
34 Lights Bulb Replacement							
Breakdown	N/S headlight out, Duty fitter dealing						
Travel Time							
Unplanned Repair	12/10/2015	11:55	12/10/2015	12:25	29,439	Dorchester	DC013719
45 Engine Ad Blue	Top up AdBlue						
SAFETY INSPECTION	26/10/2015	05:45	27/10/2015	15:00	32,309	Dorchester	DC013769
13 Brake Pads	front pads worn						
17 Tyres Replace	tryes below trust limits						
18 Wheels Check Torques							
44 Add Ad Blue							
45 Engine Oil Top Up							
85 Body Interior 1	cupboard strap broken						
Safety Inspection							
Travel Time							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	28/10/2015	09:00	29/10/2015	10:15	32,323	Dorchester	DC013785
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/11/2015	22:00	08/11/2015	22:15	34,605	Dorchester	DC013848
45 Engine Ad Blue	Topped up by Bronze						

Breakdown	10/11/2015	20:38	10/11/2015	20:39	34,605	Dorchester	DC013855
Breakdown	broken glass on nearside wing mirror						
Unplanned Repair	10/11/2015	20:00	10/11/2015	22:00	35,058	Dorchester	DC013857
02 Mirrors Travel Time	replace n/s mirror travel to and from						
Unplanned Repair	23/11/2015	08:39	23/11/2015	10:15	37,788	Dorchester	DC013920
03 Instruments & Sensors 1 03 Instruments & Sensors 2 45 Engine Ad Blue	Other Horn intermittent fault, effecting blue lights Emg Warning Devices Horn intermittently not working Top up						
Unplanned Repair	24/11/2015	20:00	24/11/2015	21:00	37,860	St Leonards	SL017480
34 Lights Bulb Replacement Travel Time	Replace o/s headlight bulb Travel to PGH						
Unplanned Repair	04/12/2015	02:00	04/12/2015	02:15	39,932	Dorchester	DC013973
45 Engine Ad Blue	Topped up by Bronze						
Vehicle Deep Clean	07/12/2015	05:30	08/12/2015	10:05	40,646	Dorchester	DC013976
Travel Time Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/12/2015	11:00	08/12/2015	15:05	40,673	Dorchester	DC013982
02 Cab Assembly 1 02 Mirrors 18 Wheels Check Torques 34 Lighting System 34 Lights 85 Body Interior 1	Checklist Defect Torch missing. Supplied. Mirror glass loose. Replaced arm. Checked. Checklist Defect O/S top brake light n/w. Repaired. Electrical Auxs L indicator side repeater intermittant fault.Repaired. Body Interior trolley release intermittant, not releasing						

86 Door Lock	Body Exterior side door not locking with key or remote.No fault found.
89 Seats	Checklist Defect Saloon seat plunger loose. Tightened.
Safety Inspection	Carried out inspection.
Travel Time	

Unplanned Repair	21/12/2015	08:30	21/12/2015	09:15	43,233	Dorchester	DC014052
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

02 Windscreen Wipers	Replace
45 Engine Ad Blue	

Unplanned Repair	02/01/2016	11:00	02/01/2016	11:15	45,412	Dorchester	DC014113
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Topped up by Bronze
-------------------	---------------------

Unplanned Repair	06/01/2016	13:20	06/01/2016	13:50	46,374	Dorchester	DC014131
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Fill with AdBlue
-------------------	------------------

SAFETY INSPECTION	18/01/2016	05:45	19/01/2016	16:00	48,624	Dorchester	DC014189
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

13 Brake Pads	rear pads worn
17 Tyres Fit Winter	
18 Wheels Check Torques	
34 Lighting System	Lighting System N/S wing indicator not working (wiring)
44 Add Ad Blue	
56 Comms Equipment	Electrical Auxs satnav mount broken, wobbling and rattling
86 Door Blinds	side door blind broken
86 Door Lock	Electrical Auxs unable to lock side door manually or with C/L
89 Seats	Body Interior rear attendant arm rests loose
Safety Inspection	
93 - D Service	
Service D	
MOT Pre Test	
Gearbox Oil & Filter Change	
Travel Time	

MOT

Vehicle Deep Clean	20/01/2016	13:42	21/01/2016	12:55	48,643	Dorchester	DC014205
--------------------	------------	-------	------------	-------	--------	------------	----------

Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						

BREAKDOWN	21/01/2016	12:00	21/01/2016	13:00	48,643	Dorchester	DC014247
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

02 Windscreen	Repair windscreen						
---------------	-------------------	--	--	--	--	--	--

Breakdown	29/01/2016	16:27	29/01/2016	17:25	49,311	Dorchester	DC014250
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Breakdown	205/75 R16C osf flat						
-----------	----------------------	--	--	--	--	--	--

Unplanned Repair	29/01/2016	16:00	29/01/2016	18:00	49,311	Dorchester	DC014251
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

17 Tyres	puncture						
18 Wheels	cracked						
Travel Time	travel to and from						

Unplanned Repair	04/02/2016	10:00	04/02/2016	10:48	50,631	Dorchester	DC014279
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

44 Add Ad Blue

Unplanned Repair	13/02/2016	08:00	13/02/2016	08:20	52,758	Dorchester	DC014323
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Topped up by Bronze						
-------------------	---------------------	--	--	--	--	--	--

Unplanned Repair	15/02/2016	22:00	15/02/2016	22:15	53,417	Dorchester	DC014343
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

34 Lights Bulb Replacement	Replaced by Bronze						
----------------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	16/02/2016	22:30	16/02/2016	23:00	53,590	Dorchester	DC014344
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine Ad Blue	Topped up by Bronze						
Breakdown	20/02/2016	16:35	22/02/2016	10:09	54,176	Dorchester	DC014361
86 Doors	door stay broken workshop/new reqd						
86 Doors Rear	Doors rear door retaining arm has detached from base.Repair						
Breakdown	Metal arm at back broken						
Travel Time	travel to and from + waiting						
Unplanned Repair	26/02/2016	08:30	26/02/2016	09:27	55,163	Dorchester	DC014401
34 Lights	o/s repeater inop,replace bulb						
45 Engine Ad Blue							
55 Tail Lift	Bridge plate pivot fallen out,refif						
SAFETY INSPECTION	29/02/2016	05:45	29/02/2016	13:54	55,641	Dorchester	DC014406
03 Instruments & Sensors 1	Low pressure audible warning inop.Trace to broken unit,arrange warranty						
17 Tyres	Replace leaking valve extension on o/s/r inner						
18 Wheels Check Torques							
Safety Inspection							
Travel Time							
Vehicle Deep Clean	01/03/2016	08:00	01/03/2016	14:00	55,655	Dorchester	DC014416
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	08/03/2016	08:00	08/03/2016	09:07	57,203	Dorchester	DC014449
44 Fuel System 1							
45 Engine Ad Blue							
Breakdown	Smell off Diesel						
Breakdown	13/03/2016	07:07	13/03/2016	08:45	58,365	Dorchester	DC014470

44 Fuel System 1 Trace to fuel pipe,replace
Breakdown Diesel leak, strong smells. Duty fitter advised.
Travel Time

Breakdown **21/03/2016** **07:21** **21/03/2016** **10:00** **59,708** **Dorchester** **DC014506**

Breakdown flat O/S rear tyre, ATS attending.

SAFETY INSPECTION **11/04/2016** **05:30** **12/04/2016** **12:15** **64,269** **Dorchester** **DC014595**

17 Tyres Replace Puncture o/s/f
18 Wheels Check Torques
45 Engine Ad Blue
45 Engine Oil Top Up
85 Body Interior 1 cupboard strap broken
Safety Inspection
Travel Time
Tail Lift Annual Service Statutory Inspection and Weight Test
Tail Lift 6 Monthly Inspection Statutory Inspection

Vehicle Deep Clean **12/04/2016** **12:00** **13/04/2016** **14:19** **64,283** **Dorchester** **DC014605**

Travel Time
Vehicle Deep Clean Vehicle Deep Clean

Breakdown **15/04/2016** **11:27** **21/04/2016** **13:34** **64,538** **Dorchester** **DC014621**

86 Sliding Door Outer glass,blind and inner window broken
Breakdown side door glass broken
Travel Time
85 Body Int Alcohol Gel Dispen

SAFETY INSPECTION **23/05/2016** **05:30** **24/05/2016** **15:30** **70,529** **Dorchester** **DC014765**

13 Brake Pads Replace front pads
13 Discs Replace front discs
18 Wheels Check Torques

34 Lighting System n/s upper and n/s/r markers inop.Replace
 Safety Inspection
 Travel Time
 Annual Heater Service Annual Heater Service carried out
 Wheel Studs & Nuts Replaceme
 Handbrake Cable Replacement Replace rear handbrake cables
 92 - C Service
 Service C
 UB Fire Suppression Service

Vehicle Deep Clean	25/05/2016	11:00	26/05/2016	12:00	70,546	Dorchester	DC014783
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	06/06/2016	22:00	07/06/2016	00:30	73,057	Dorchester	DC014838
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

86 Doors	rear door jammed
Travel Time	travel to and from

Unplanned Repair	07/06/2016	10:00	07/06/2016	11:00	73,196	Dorchester	DC014842
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

86 Door Lock	Rear door lock inop.Check fault,requires new solenoid	Awaiting Warranty
--------------	---	-------------------

Breakdown	23/06/2016	06:57	23/06/2016	10:00	76,630	Dorchester	DC014901
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Breakdown	punticre on rear n/s tyre, ats called.
-----------	--

Breakdown	28/06/2016	03:27	28/06/2016	05:30	77,752	Dorchester	DC014919
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Breakdown	R/N/S OUTER
-----------	-------------

SAFETY INSPECTION	04/07/2016	05:45	07/07/2016	17:09	79,187	Dorchester	DC014947
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

01 Air Conditioning 1	Tensioner u/s.Rear fan u/s	Awaiting Warranty
17 Tyres Replace	rear tyres worn	

18 Wheels Check Torques
 44 Add Ad Blue
 45 Engine Oil Top Up
 86 Door Lock Rear door lock inop.Check fault,requires new solenoid
 Road Test
 Safety Inspection
 Travel Time
 Fit Throw Lines & SOP allready fitted
 Annual Air Con Service Annual Air Condition Service
 Reposition grab bag shelf shelf raised
 Install Saloon CCTV Camera

Vehicle Deep Clean **05/07/2016** **08:30** **05/07/2016** **14:00** **79,187** **Dorchester** **DC014957**

Travel Time
 Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **03/07/2016** **22:00** **03/07/2016** **22:15** **79,114** **Dorchester** **DC014966**

34 Lights Bulb Replacement Carried out by Bronze

Unplanned Repair **15/07/2016** **05:30** **15/07/2016** **12:02** **80,374** **Dorchester** **DC015014**

01 Air Conditioning 1 Tensioner u/s.Rear fan u/s
 Travel Time

Unplanned Repair **04/08/2016** **08:30** **04/08/2016** **09:15** **84,019** **Dorchester** **DC015088**

34 Lights n/s/f indicator intermittent.Trace to bulb,replace
 45 Engine Ad Blue Top up

Breakdown **14/08/2016** **02:18** **14/08/2016** **04:31** **85,739** **Dorchester** **DC015127**

Breakdown R/N/S INNER

SAFETY INSPECTION **16/08/2016** **05:45** **17/08/2016** **08:04** **86,125** **Dorchester** **DC015136**

02 Windows/Glass	Replace o/s door switch						
18 Wheels Check Torques							
45 Engine Ad Blue							
45 Engine Oil Top Up							
55 Tail Lift	Remove damaged guide						
89 Seats	Attendent seat bearings u/s						
Safety Inspection	Awaiting Warranty						
Travel Time							
Vehicle Deep Clean	17/08/2016	07:30	17/08/2016	13:00	86,142	Dorchester	DC015152
Travel Time							
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	23/08/2016	19:17	23/08/2016	22:00	87,104	Dorchester	DC015184
17 Tyres	Replace N/S/F wheel & tyre due to leaking rim. N/S/R inner valve Leaking.						
Breakdown	two tyres have rim damage, df aware.						
Breakdown	16/09/2016	06:41	16/09/2016	12:51	91,929	Dorchester	DC015324
Breakdown	left hand 02 valve leaking						
Unplanned Repair	19/09/2016	08:00	19/09/2016	08:15	92,705	Dorchester	DC015336
02 Mirrors	replace o/s mirror						
Unplanned Repair	24/09/2016	08:00	26/09/2016	08:28	93,524	Dorchester	DC015376
34 Lights Bulb Replacement	fitted by bronze						
SAFETY INSPECTION	26/09/2016	05:45	26/09/2016	16:00	93,883	Dorchester	DC015377
13 Brake Pads	rear pads worn						
18 Wheels Check Torques							

34 Emergency Lights
 89 Seats
 Safety Inspection
 Travel Time
 93 - D Service
 Service D

o/s wing light inop
 Attendent seat bearings u/s

Vehicle Deep Clean **27/09/2016** **08:30** **27/09/2016** **13:00** **93,897** **Dorchester** **DC015386**

Travel Time
 Vehicle Deep Clean Vehicle Deep Clean

Breakdown **30/09/2016** **00:48** **30/09/2016** **02:30** **94,350** **Dorchester** **DC015401**

Breakdown headlight out, was changed by OO.

Breakdown **30/09/2016** **07:35** **30/09/2016** **09:45** **94,365** **Dorchester** **DC015403**

Breakdown Puncture

SAFETY INSPECTION **07/11/2016** **06:00** **10/11/2016** **11:05** **102,613** **Dorchester** **DC015607**

03 Instruments & Sensors 1 Fire trace reporting low pressure Awaiting Warranty
 13 Brake Pads Front and rear pads worn,replace
 13 Discs Replace rear discs
 13 Handbrake
 16 Suspension 1 Play in front struts Awaiting Warranty
 17 Tyres Replace o/s/f tyre worn
 18 Wheels Check Torques
 Check Winter Pack Check and seal
 Safety Inspection
 Travel Time
 Remove Ventilator Brackets Remove Ventilator Brackets and Fill
 Gearbox Oil & Filter Change
 Tail Lift 6 Monthly Inspection Statutory Inspection

Vehicle Deep Clean **08/11/2016** **11:15** **09/11/2016** **11:00** **102,613** **Dorchester** **DC015617**

Travel Time
 Vehicle Deep Clean Vehicle Deep Clean

Breakdown	06/12/2016	07:23	06/12/2016	09:00	108,476	Dorchester	DC015756
Breakdown	Headlight						
Unplanned Repair	12/12/2016	08:50	12/12/2016	09:24	109,679	Dorchester	DC015781
87 Oxygen System	Low pressure reported.Replace cylinder,check for leaks.Close regulator						
SAFETY INSPECTION	20/12/2016	05:45	21/12/2016	14:30	111,338	Dorchester	DC015830
03 Instruments & Sensors 1	Fire trace reporting low pressure bearing carrier broken Electrical Auxs chassis battery 12v immediatly after turning off						
17 Tyres Replace							
18 Wheels Check Torques							
24 Driveshaft 1							
31 Battery Aux							
45 Engine Ad Blue							
Safety Inspection							
MOT Pre Test							
Travel Time							
MOT							
92 - C Service							
Service C							
Vehicle Deep Clean	22/12/2016	08:00	22/12/2016	12:15	111,351	Dorchester	DC015842
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	24/12/2016	09:38	24/12/2016	12:15	111,733	Dorchester	DC015852
87 Oxygen System	Check for leaks,unable to locate on visible pipe work and connections.Oxylitre? leaking o2 cylinder					Monitoring	
Breakdown							
Travel Time							
Unplanned Repair	24/12/2016	10:15	24/12/2016	14:00	111,401	Dorchester	DC015856
56 Comms Equipment	MDT inop.Check and reboot See notes						
Travel Time							

Breakdown	09/01/2017	07:50	10/01/2017	12:00	115,419	Dorchester	DC015939
34 Lights Bulb Replacement	Running lights inop.replace						
45 Engine Ad Blue	Top up						
Breakdown	AUX BATT APPEARS FAULTY TAIL LIFT FAULT						
Travel Time							
Medical Device and Equip	ChedModified						
SAFETY INSPECTION	30/01/2017	05:45	31/01/2017	08:44	120,052	Dorchester	DC016057
16 Suspension 1	Play in front struts					Monitoring	
17 Tyres Replace	n/s/f worn						
18 Wheels Check Torques							
45 Engine Ad Blue							
85 Body Interior 1	cab glove pocket light on						
85 Body Interior 2	strap missing saloon						
Road Test							
Safety Inspection							
Travel Time							
Vehicle Deep Clean	31/01/2017	09:00	01/02/2017	10:30	120,068	Dorchester	DC016065
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	02/02/2017	17:00	02/02/2017	18:45	120,068	Dorchester	DC016204
02 Windscreen	Repair to chip in windscreen						
BREAKDOWN	04/02/2017	19:06	04/02/2017	22:35	120,815	Dorchester	DC016498
001 Recover Vehicle	Vehicle Recovery - bogged down						
Unplanned Repair	20/02/2017	08:15	20/02/2017	08:45	124,448	Dorchester	DC016162
34 Lights Bulb Replacement	front side light inop						

Unplanned Repair	19/02/2017	03:00	19/02/2017	03:15	124,112	Dorchester	DC016163
34 Lights Bulb Replacement	Head light bulb replaced by Bronze						
Breakdown	28/02/2017	07:50	28/02/2017	09:00	126,182	Dorchester	DC016205
Breakdown	driver side rear outside tyre is flat						
SAFETY INSPECTION	13/03/2017	05:45	14/03/2017	13:55	128,932	Dorchester	DC016270
13 Brake Pads	front pads worn						Monitoring
16 Suspension 1	Play in front struts						
16 Suspension 2	rear spring buffers worn a/roll bar rubbers worn						
17 Tyres Replace	both n/s/r tyres worn						
18 Wheels Check Torques							
45 Engine Ad Blue							
86 Door Lock	Doors side door not locking with central locking						
Safety Inspection							
Travel Time							
WAS Firetrace rework & Service							
93 - D Service							
Service D							
UB Fire Suppression Service							
Unplanned Repair	15/03/2017	08:00	16/03/2017	11:00	128,947	Dorchester	DC016298
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	27/03/2017	20:30	27/03/2017	20:45	131,162	Dorchester	DC016346
34 Lights Bulb Replacement	Headlight bulb replaced by Bronze						
Breakdown	07/04/2017	07:59	07/04/2017	09:45	133,586	Dorchester	DC016398
43 Exhaust System 1	Carry out regen and road test						

Breakdown in limp mode.Carry out tests.requires Regen.

SAFETY INSPECTION 24/04/2017 05:45 27/04/2017 11:00 136,759 Dorchester DC016475

13 Brake Pads Rear pads worn,replace
 16 Suspension 1 Play in front struts
 17 Tyres Replace Replace front tyres
 18 Wheels Check Torques
 31 Charging System Onboard charger inop.Repaired by J.Coles
 55 Tail Lift Tilt sensor fault.Repaired by South West Lifts
 86 Door Lock Central locking inop on side door Awaiting Warranty
 87 Oxygen System Check for leaks,unable to locate on visible pipe work and connections.Oxylitre?
 Safety Inspection
 Travel Time
 Annual Air Con Service Annual Air Condition Service
 Annual Heater Service Annual Heater Service
 Handbrake Cable Replacement Replace rear handbrake cables
 Tail Lift Annual Service Statutory Inspection and Weight Test
 Tail Lift 6 Monthly Inspection Statutory Inspection

Vehicle Deep Clean 27/04/2017 12:30 28/04/2017 10:30 136,787 Dorchester DC016493

Vehicle Deep Clean Vehicle Deep Clean

MGS Gas Storage Modifications 24/05/2017 14:00 24/05/2017 14:36 141,825 Dorchester DC016623

MGS Gas Storage ModificationsMGS Gas Storage Modifications

Unplanned Repair 25/05/2017 10:45 25/05/2017 11:01 142,018 Dorchester DC016628

31 Battery Comms Battery/Charging Sys MDT powering down, ns running light u/s
 34 Lights Lighting System ns sidelight u/s
 34 Lights Bulb Replacement n/s running light

Breakdown 31/05/2017 07:31 31/05/2017 09:03 143,532 Dorchester DC016651

Breakdown Running light

Breakdown	31/05/2017	07:36	31/05/2017	09:25	143,560	Dorchester	DC016652
34 Lights Bulb Replacement	o/s running light inop,replace bulb						
87 Oxygen System	Leak reported.Check for leak,trace to loose regulator.Tighten and test.						
Breakdown	02 leaking at the back						
SAFETY INSPECTION	05/06/2017	05:30	06/06/2017	13:16	144,684	Dorchester	DC016677
02 Cab Assembly 1	cab light inop						
02 Windscreen Wipers	washers inop						
17 Tyres Replace	o/s/r outter						
18 Wheels Check Torques							
34 Lighting System	o/s scene light dim						
45 Engine Oil Top Up	Awaiting Parts						
86 Door Lock	Central locking inop on side door						
Safety Inspection							
Travel Time							
Vehicle Deep Clean	07/06/2017	08:00	07/06/2017	14:17	144,700	Dorchester	DC016695
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	20/06/2017	16:06	27/06/2017	16:00	149,090	Dorchester	DC016753
Breakdown	Air con broke in back cab						
	Monitoring						
Breakdown	29/06/2017	15:25	03/07/2017	10:12	149,384	Dorchester	DC016811
02 Mirrors	Replace n/s glass						
Breakdown	broken mirror passengers side						
COMMS.FAILURE CHECK	13/07/2017	15:15	17/07/2017	07:56	152,640	Dorchester	DC016874
56 Comms Power Failure	Electrical Auxs MDT powering down. check batteries						

MDT Failure/Issue

Unplanned Repair	11/07/2017	10:00	11/07/2017	11:00	152,142	St Leonards	SL021667
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

17 Tyres Replace	Replace o/s/r inner tyre [WHEEL SCRAP]
------------------	--

SAFETY INSPECTION	17/07/2017	07:54	04/08/2017	14:00	152,826	Dorchester	DC016879
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windows/Glass	n/s window switch broken
02 Windscreen	Chips in screen.National windscreen to repair
13 Brakes 1	Pedal rubber worn
17 Tyres Replace	Replace n/s tyres
18 Wheels Check Torques	
34 Emergency Lights	Lighting System passenger side blue light,driver side spot
34 Lighting System	o/s scene light dim
45 Engine 1	Engine lumpy idle + stalling. intermittent hard starts,rattle from cold.Warranty
56 Comms Equipment	Sat nav remote cradle broken and remote missing.PCE to sort
71 Body Exterior 1	Body Exterior Second gouge to right side of truck
86 Door Lock	Central locking inop,replace battery
Breakdown	Air con broke in back cab
Safety Inspection	
Travel Time	
92 - C Service	
Service C	
Gearbox Oil & Filter Change	

Unplanned Repair	05/08/2017	09:30	05/08/2017	12:30	153,547	St Leonards	SL021871
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Equipment	MDT n/w. Reset system.
Travel Time	TRavel to and from Ferndown VMU.

Unplanned Repair	14/08/2017	09:30	14/08/2017	10:15	155,815	Dorchester	DC017046
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Emergency Lights	grill light inop
34 Lights Bulb Replacement	various out

Unplanned Repair	18/08/2017	09:00	18/08/2017	10:05	156,844	Dorchester	DC017069
71 Body External Steps	Side step u/s and damaged.Replace						
Breakdown	20/08/2017	10:35	20/08/2017	13:45	157,475	Dorchester	DC017076
01 Air Conditioning 1 45 Engine 1 Breakdown	Replace filter. Replace Aux belt. aux belt snapped						
Breakdown	23/08/2017	02:11	23/08/2017	09:14	158,054	Dorchester	DC017087
Breakdown	leak fuel, broken number plate.See notes						
SAFETY INSPECTION	29/08/2017	05:30	29/08/2017	15:00	159,624	Dorchester	DC017120
02 Mirrors 13 Brake Pads 18 Wheels Check Torques 34 Lighting System 55 Tail Lift 56 Comms Equipment 85 Body Interior 1 85 Body Interior 2 86 Door Lock Safety Inspection Travel Time Vehicle Deep Clean Replace Vehicle Fuel Card	Mirrors Side door not opening-wing mirror removed both done front pads worn Lighting System spot light out on drivers side been done sliders damaged MDT Failure/Issue MDT will not power up - battery check needed done straps broken/missing saloon clock missing rear lower lock loose Vehicle Deep Clean Replace Vehicle Fuel Card						
Vehicle Deep Clean	30/08/2017	13:02	31/08/2017	13:15	159,639	Dorchester	DC017133
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	14/09/2017	09:20	14/09/2017	09:34	162,689	Dorchester	DC017209
34 Lights Bulb Replacement	n/s running light						

Unplanned Repair	03/10/2017	08:35	03/10/2017	08:59	166,790	Dorchester	DC017275
45 Engine Oil Top Up							
SAFETY INSPECTION	09/10/2017	05:30	10/10/2017	09:06	167,997	Dorchester	DC017304
13 Brake Pads		Replace rear pads					
17 Tyres Replace		Replace o/s tyres					
18 Wheels Check Torques							
34 Emergency Lights		o/s/r upper lens smashed					
44 Fuel System 1		Check for smell of fuel,trace to fuel pipe,replace					
45 Engine Ad Blue							
45 Engine Oil Top Up							
85 Body Interior 1		Replace extinguishers					
Safety Inspection							
Travel Time							
Tail Lift 6 Monthly Inspection		Statutory Inspection					
Vehicle Deep Clean	10/10/2017	08:54	11/10/2017	09:30	168,011	Dorchester	DC017314
Vehicle Deep Clean		Vehicle Deep Clean					
Breakdown	22/10/2017	09:23	23/10/2017	10:40	170,232	Dorchester	DC017375
01 Heating 1		Saloon heater inop.Carry out checks,replace with recon unit,replace air intake					
Breakdown		no heater in back [repair heater]					
SAFETY INSPECTION	20/11/2017	05:45	20/11/2017	15:06	176,756	Dorchester	DC017496
18 Wheels Check Torques							
31 Battery Aux		Electrical Auxs 12v socket in saloon u/s ?					
34 Emergency Lights		n/s/r upper blue damaged					
45 Engine Ad Blue							
Safety Inspection							

93 - D Service
Service D
MOT Pre Test

Vehicle Deep Clean	21/11/2017	09:41	22/11/2017	14:21	176,772	Dorchester	DC017507
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	24/11/2017	14:31	27/11/2017	11:54	177,040	Dorchester	DC017527
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

43 Exhaust System 1 Breakdown Travel Time	Carry out regen of DPF Alternator gone.Replaced under warranty
---	---

Unplanned Repair	04/12/2017	16:00	04/12/2017	16:30	178,911	St Leonards	SL022829
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lights Bulb Replacement	REPLACE NEAR SIDE HEAD LIGHT BULB AND OFF SIDE FRONT SIDE LIGHT
----------------------------	---

Unplanned Repair	14/12/2017	14:29	14/12/2017	14:33	181,308	Dorchester	DC017609
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers	Supply wiper blades
----------------------	---------------------

Breakdown	16/12/2017	15:11	16/12/2017	16:45	181,798	Dorchester	DC017615
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1 Breakdown Travel Time	Investigate LOP.Carry out regen and road test Loss of power
---	--

BREAKDOWN	14/12/2017	10:00	14/12/2017	11:00	181,265	St Leonards	SL022910
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

34 Lighting System	Replace top N/S/R LED Red.
--------------------	----------------------------

Breakdown	24/12/2017	13:31	03/01/2018	12:52	183,831	Dorchester	DC017659
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

43 Exhaust System 1 Breakdown Travel Time	Split EGR pipe ? Exhaust or Manifold Travel to and from Wareham.
---	--

SAFETY INSPECTION	05/01/2018	15:25	09/01/2018	12:30	184,284	Dorchester	DC017715
13 Brake Pads	front pads low						
13 Discs	front discs worn						
15 Steering 1	n/s inner rack joint and track rod end worn						
16 Suspension 1	n/s and o/s bottom arm joint worn						
17 Tyres	n/s/f tyre and n/s/r tyres low						
18 Wheels Check Torques							
34 Emergency Light System	Emg Warning Devices R/O/S Blue light smashed still works						
34 Emergency Lights	o/s/r top lense broken						
34 Lights	no plate lights n/w, n/s top marker light n/w						
85 Body Interior 1	step light inop						
Safety Inspection							
Travel Time							
MOT							
Vehicle Deep Clean	10/01/2018	09:30	10/01/2018	13:30	184,302	Dorchester	DC017741
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	16/01/2018	09:02	16/01/2018	09:06	185,632	Dorchester	DC017778
34 Lights Bulb Replacement	n/s running light not working						
SAFETY INSPECTION	12/02/2018	06:15	14/02/2018	09:57	191,992	Dorchester	DC017892
01 Air Conditioning 1	belt breaking up replace						
13 Brake Pads	rear pads low						
13 Discs	rear discs worn						
13 Handbrake	handbrake poor						
17 Tyres Replace							
18 Wheels Check Torques							
24 Driveshaft 1	rear prop u/s						
Safety Inspection							

Travel Time
85 Body Int Alcohol Gel Dispen

Vehicle Deep Clean	13/02/2018	15:02	14/02/2018	14:45	192,007	Dorchester	DC017902
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	20/02/2018	09:00	20/02/2018	10:30	193,201	St Leonards	SL023447
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

17 Tyres Tracking	Tracking checked and adjusted @ ATS Poole.
34 Lights Bulb Replacement	N/S running light bulb inop. Replace bulb

BREAKDOWN	26/02/2018	14:30	27/02/2018	12:22	194,652	Dorchester	DC017984
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brakes 1	ABS fault
18 Wheels Retorque	
43 Exhaust System 1	Tail pipe rotted out,replace

COMMS.FAILURE CHECK	01/03/2018	08:15	01/03/2018	09:02	195,021	Dorchester	DC017996
----------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights	o/s day running light iop
56 Comms Power Failure	Battery/Charging Sys base radio random cut,need battery check.ok
MDT Failure/Issue	

Breakdown	03/03/2018	22:13	03/03/2018	23:13	195,333	Dorchester	DC018011
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	ABS, ESP amber lights on
-----------	--------------------------

Unplanned Repair	07/03/2018	23:30	07/03/2018	23:45	196,211	Dorchester	DC018034
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	Bulb replaced by Bronze
----------------------------	-------------------------

Unplanned Repair	09/03/2018	10:00	09/03/2018	11:17	196,464	Dorchester	DC018045
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Emergency Lights	o/s grill light n/w
34 Lights	n/s headlight intermittent fault,

SAFETY INSPECTION	26/03/2018	06:00	27/03/2018	13:10	200,390	Dorchester	DC018120
02 Windscreen	has small chip in windscreen					Monitoring	
17 Tyres	o/s/f tyre has hole to cords						
18 Wheels Check Torques							
34 Lights	n/s head light u/s						
44 Add Ad Blue	top up						
52 Electrical Aux	Electrical Auxs vehicle based mangar charger defective						
55 Tail Lift	Ramp/Lift/Tail Hoist Slow/noisy tail lift						
85 Body Interior 1	Body Interior broken cupboard in side rear of truck						
Safety Inspection							
92 - C Service							
Service C							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Wheel Hub Flanges Replaceme							
Annual Heater Service	Annual Heater Service						
Handbrake Cable Replacement	Replace rear handbrake cables						
Annual Air Con Service	Annual Air Condition Service						
UB Fire Suppression Service							
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	28/03/2018	08:31	28/03/2018	13:00	200,405	Dorchester	DC018137
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	01/04/2018	10:04	01/04/2018	15:30	201,252	Dorchester	DC018153
Breakdown	Auxiliary belt came off [f replace tenstioner and belt]						
Breakdown	27/04/2018	13:08	27/04/2018	14:14	206,611	Dorchester	DC018282
Breakdown	limp mode						
Unplanned Repair	28/04/2018	19:30	28/04/2018	20:30	206,789	Dorchester	DC018292
17 Tyres Replace	n/s/f tyre worn,replace						
Travel Time							

SAFETY INSPECTION	08/05/2018	09:44	09/05/2018	08:04	208,775	Dorchester	DC018335
02 Windscreen	has small chip in windscreen					Monitoring	
16 Suspension 1	rear anti roll bar bushs u/s						
17 Tyres	n/s/r low						
18 Wheels Check Torques							
43 Exhaust System 1	cover loose						
45 Engine Ad Blue	top up						
52 Electrical Aux	Electrical Auxs veh based mangar charger cable snapped						
71 Body Exterior 1	n/s/r reflector damaged						
Safety Inspection							
Fit Poster Holder	Fit Poster Holder						
Vehicle Deep Clean	09/05/2018	09:30	09/05/2018	13:00	208,785	Dorchester	DC018343
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	14/05/2018	10:45	14/05/2018	11:46	209,769	Dorchester	DC018360
44 Fuel System 1	fuel angel u/s						
45 Engine Oil Top Up							
86 Doors Rear	bottom catch u/s						
Unplanned Repair	23/05/2018	09:45	23/05/2018	10:19	211,912	Dorchester	DC018414
03 Instruments & Sensors 1	Low battery warnings on Genysis system.Clean connectors on genysis unit.Test,ok						
BREAKDOWN	23/05/2018	15:30	25/05/2018	11:19	211,952	Dorchester	DC018427
31 Battery Chassis	Electrical failure						
31 Battery Comms	Electrical failure						
31 Charging System	Carry out checks,alternator intermittent failure						
Travel Time							

Unplanned Repair	08/06/2018	10:30	08/06/2018	12:13	214,769	Dorchester	DC018497
86 Sliding Door	bottom magnet missing						
Breakdown	14/06/2018	16:43	19/06/2018	12:49	216,101	Dorchester	DC018530
17 Tyres Replace	o/s/r tyres on limit						
34 Emergency Lights	Grill light staying on						
45 Engine Ad Blue							
Breakdown	EML/ESP						
Travel Time							
Gearbox Oil & Filter Change							
18 Wheels Check Torques							
Safety Inspection							
Vehicle Deep Clean	19/06/2018	14:17	20/06/2018	11:00	216,115	Dorchester	DC018552
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	28/06/2018	21:55	28/06/2018	22:10	218,030	Dorchester	DC018600
34 Lights Bulb Replacement	Headlight bulb replaced by Bronze						
Breakdown	30/06/2018	05:15	30/06/2018	08:45	218,260	Dorchester	DC018614
Breakdown	limp mode,gears not selecting past 3rd.See notes						
Travel Time							
Breakdown	07/07/2018	12:05	10/07/2018	13:08	219,596	Dorchester	DC018657
001 Recover Vehicle	Vehicle Recovery						
02 Cab Assembly 1	fan blower on all time						
42 Coolant System	Overheating						
Breakdown	5900 Overheated - stop warning on dash						
Travel Time	Travel to Weymouth						

Unplanned Repair	11/07/2018	15:12	11/07/2018	15:39	219,860	Dorchester	DC018675
86 Doors Rear	Rear door not locking from c/l or key - Remove trim key barrel seized +See Note+					Partially Completed	
Breakdown	22/07/2018	09:11	22/07/2018	11:29	222,629	Dorchester	DC018717
Breakdown	screw in tyre front off side. No Nail in tyre found.						
Breakdown	26/07/2018	09:18	26/07/2018	12:30	222,629	Dorchester	DC018747
Breakdown	Flea infestation						
SAFETY INSPECTION	30/07/2018	09:46	31/07/2018	08:27	224,222	Dorchester	DC018759
13 Brake Pads	front and rear pads low						
18 Wheels Check Torques							
34 Lights	o/s drl out						
45 Engine Ad Blue	top up						
86 Door Hinges	some play in o/s rear main door						
Safety Inspection							Monitoring
93 - D Service							
Service D							
Vehicle Deep Clean	31/07/2018	09:30	01/08/2018	09:00	224,233	Dorchester	DC018769
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	05/08/2018	18:00	05/08/2018	20:00	224,501	Dorchester	DC018797
02 Mirrors	N\S mirror smashed						

Unplanned Repair	07/09/2018	09:45	07/09/2018	10:22	232,797	Dorchester	DC018982
86 Sliding Door	Inner panel broken,carry out temp repair and order new					Awaiting Parts	
SAFETY INSPECTION	10/09/2018	06:00	13/09/2018	13:11	233,489	Dorchester	DC018986
02 Windscreen	has small chip in windscreen					Monitoring	
17 Tyres	front tyres low						
18 Wheels Check Torques							
34 Lights	o/s top marker not working						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
86 Door Hinges	some play in o/s rear main door					Monitoring	
86 Doors Rear	Rear door not locking from c/l or key - Remove trim key barrel seized +See Note+						
86 Sliding Door	Inner panel broken,carry out temp repair and order new						
Safety Inspection							
Tail Lift 6 Monthly Inspection	Statutory Inspection						
Vehicle Deep Clean	11/09/2018	13:08	12/09/2018	13:00	233,488	Dorchester	DC018995
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	23/09/2018	16:08	25/09/2018	10:00	235,449	Dorchester	DC019050
Breakdown	front air higher blower not working					Parts ordered in store	
Breakdown	04/10/2018	00:14	04/10/2018	14:22	237,851	Dorchester	DC019114
01 Heating 1	Blower inop						
86 Sliding Door	Handle snapped off						
Breakdown	front air higher blower not working						
Unplanned Repair	06/10/2018	21:50	06/10/2018	23:05	238,344	Dorchester	DC019128
34 Lights Bulb Replacement	n/s repeater inop,replace bulb						
86 Sliding Door	Unable to open from the inside.Check fault,refit yoke to inner handle						
Travel Time							

Breakdown	16/10/2018	17:34	17/10/2018	09:00	240,192	Dorchester	DC019166
Breakdown	wouldnt start withouth red button pressed						
SAFETY INSPECTION	24/10/2018	06:00	25/10/2018	13:00	241,675	Dorchester	DC019207
01 Heating 1	Electrical Auxs cab heater squealing						
02 Mirrors	Mirrors N/S mirror casing broken - wobbles at speed.Replace complete mirror asse						
02 Windows/Glass	Windscreen washer pump U/S						
02 Windscreen	has small chip in windscreen						
02 Windscreen Wipers	wipers u/s						
17 Tyres	2x rear tyres low						
18 Wheels Check Torques							
31 Battery Chassis	Battery/Charging Sys chassis battery going flat						
45 Engine 1	Engine power fails x 2						
45 Engine Ad Blue	top up						
55 Tail Lift	Electrical Auxs ramp warning beeps when accelerating, or on hills						
86 Door Hinges	some play in o/s rear main door						
86 Doors Rear	Doors back door not securing closed - rattles at speed						
86 Sliding Door	Doors side door stiff to open						
Safety Inspection							
92 - C Service							
Service C							
Vehicle Deep Clean	26/10/2018	09:30	26/10/2018	13:00	241,687	Dorchester	DC019222
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	27/10/2018	12:58	27/10/2018	16:02	241,801	Dorchester	DC019227
45 Engine 1	Smoke from under bonnet						
Travel Time	travel to and from swanage						
Breakdown	07/11/2018	06:33	09/11/2018	09:00	244,168	Dorchester	DC019278
55 Tail Lift	Damaged Tail lift.Check over and carry out repairs to make safe						
							Awaiting Body Repair

71 Body Exterior 1	Carry out temp repair to lower corner to get vehicle back on the road	Awaiting Body Repair
85 Body Interior 1	Unable to open draw.Gain access and replace catch assembly	
Breakdown	Accident - rear end smash - tail lift damaged	

Breakdown	02/12/2018	13:07	02/12/2018	16:00	249,279	Dorchester	DC019414
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	Replace n/s/f tyre
Breakdown	Puncture
Travel Time	Travel to Ferndown

SAFETY INSPECTION	03/12/2018	09:00	05/12/2018	08:21	249,521	Dorchester	DC019415
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Pads	front and rear pads worn	
13 Discs	front discs worn	
17 Tyres	o/s/f low all rear low	
18 Wheels	o/s front wheel rim u/s	
18 Wheels Check Torques		
24 Driveshaft 1	prop centre bearing u/s	
27 Transmission Automatic	Gearbox faint driveline vibrations from 1500-2200rpm	Monitoring
45 Engine Ad Blue	top up	
45 Engine Oil Top Up	top up	
Safety Inspection		
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab	
Sealing of stretcher clamp	Sealing of stretcher clamp	
MOT Pre Test		

Vehicle Deep Clean	05/12/2018	09:32	05/12/2018	13:31	249,536	Dorchester	DC019424
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	05/01/2019	20:15	05/01/2019	23:00	256,381	Dorchester	DC019585
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

42 Coolant System	leak from hose
Travel Time	

SAFETY INSPECTION	14/01/2019	05:00	15/01/2019	08:30	258,138	Dorchester	DC019621
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

16 Suspension 2	Suspension rear suspension knocking/creaking						Awaiting Parts
18 Wheels Check Torques							
24 Driveshaft 1	Gearbox driveline vibrations 30-50mph						
27 Transmission Automatic	Gearbox faint driveline vibrations from 1500-2200rpm						
45 Engine 1	injector chuffing						Monitoring
45 Engine Oil Top Up	top up						
55 Ramp	Ramp/Lift/Tail Hoist Not stowing - warning when accelerating uphill						
55 Tail Lift	Damaged Tail lift.Check over and carry out repairs to make safe						
71 Body Exterior 1	Carry out temp repair to lower corner to get vehicle back on the road						
85 Body Interior 1	cab torch u/s						
85 Body Interior 2	catch cover broken						
87 Chairs	Carry chair bracket damaged.Replace						
Safety Inspection							
Travel Time							
MOT							
Vehicle Deep Clean	15/01/2019	08:54	15/01/2019	14:00	258,151	Dorchester	DC019629
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	18/01/2019	15:05	18/01/2019	15:48	258,759	Dorchester	DC019647
86 Doors Rear	o/s/r door stay sheared off.Remove and repair						
BREAKDOWN	21/01/2019	07:51	29/01/2019	17:00	259,467	Dorchester	DC019654
45 Engine 1	injector chuffing						
45 Engine 2	Exhaust System Fumes in cab						
Unplanned Repair	07/02/2019	10:05	07/02/2019	11:10	261,523	Dorchester	DC019759
42 Coolant System	Level sensor faulty,replace header tank and top up coolant						
45 Engine 1	EML on,LOP.Check with TEXA,unknown fault.Clear and road test ok						
Breakdown	19/02/2019	10:03	07/03/2019	13:01	264,548	Dorchester	DC019814
41 Turbo	Turbo failed						

Breakdown limp mode.Check fault.Turbo fallen apart

SAFETY INSPECTION **07/03/2019** **13:02** **12/03/2019** **15:00** **264,625** **Dorchester** **DC019899**

01 Heating 1	saloon heater blowing cold	
15 Steering 1	slight play in rack end o/s	Monitoring
16 Suspension 2	Suspension rear suspension knocking/creaking	
17 Tyres	n/s/f tyre	
18 Wheels Check Torques		
85 Body Interior 1	fire exts out of date	
85 Body Interior 2	cupboard door smashed	
Safety Inspection		
93 - D Service	See Notes	
Service D		
Gearbox Oil & Filter Change		
Tail Lift 6 Monthly Inspection	Statutory Inspection	
Tail Lift Annual Service	Statutory Inspection and Weight Test	

Vehicle Deep Clean **11/03/2019** **09:30** **12/03/2019** **12:00** **264,646** **Dorchester** **DC019920**

Vehicle Deep Clean Vehicle Deep Clean

BREAKDOWN **17/03/2019** **20:15** **18/03/2019** **08:57** **265,895** **Dorchester** **DC019946**

34 Lights Bulb Replacement Bulb replaced by bronze

Breakdown **20/03/2019** **19:11** **20/03/2019** **22:00** **266,462** **Dorchester** **DC019964**

Breakdown flat tyre n/s/r outer
Travel Time

BREAKDOWN **21/03/2019** **10:00** **21/03/2019** **11:33** **266,622** **Dorchester** **DC019969**

17 Tyres O/S/R tyre flat
18 Wheels rim cracked

Unplanned Repair	27/03/2019	09:15	27/03/2019	10:27	268,100	Dorchester	DC019999
45 Engine Ad Blue 71 Body External Steps 86 Door handle	Doors Side step not deploying correctly.See notes Doors Back handle broken off.Replace						
SAFETY INSPECTION	08/04/2019	06:00	09/04/2019	10:58	270,823	Dorchester	DC020046
13 Brake Pads 13 Calipers 13 Discs 15 Steering 1 18 Wheels Check Torques 44 Fuel System 1 45 Engine Ad Blue 45 Engine Oil Top Up 52 Electrical Aux 85 Body Interior 1 Safety Inspection Handbrake Cable Replacement Annual Air Con Service UB Fire Suppression Service Annual Heater Service	front low one side, rear low o/s caliper u/s rear worn slight play in rack end o/s leak around pump top up top up Change EPCR battery Linen cupboard damaged and front locker shelf Replace rear handbrake cables Annual Air Condition Service Annual Heater Service						
Vehicle Deep Clean	09/04/2019	13:00	10/04/2019	12:30	270,835	Dorchester	DC020059
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	17/04/2019	09:00	17/04/2019	14:05	272,342	Dorchester	DC020092
27 Transmission Automatic	noise						
BREAKDOWN	21/04/2019	20:30	02/05/2019	13:11	273,588	Dorchester	DC020110
11 Axle Rear 13 Brakes 1	Diff bearing breaking up ABS light on,						

27 Transmission Automatic Noise axle/gbox/brakes
Travel Time

Breakdown **03/05/2019** **07:04** **03/05/2019** **09:32** **273,845** **Dorchester** **DC020159**

Breakdown MDT keeps powering down

Unplanned Repair **15/05/2019** **08:45** **15/05/2019** **09:57** **276,370** **Dorchester** **DC020222**

01 Heating 1 Other Rear heating stopped working
34 Lights Bulb Replacement Lighting System O/S Daytime running light out

SAFETY INSPECTION **20/05/2019** **06:00** **20/05/2019** **15:30** **277,906** **Dorchester** **DC020242**

13 Brakes 1 Crew reported soft brakes,
18 Wheels Check Torques
45 Engine Ad Blue top up
45 Engine Oil Top Up top up
55 Tail Lift Tilt ram bent replace
Safety Inspection
Axle Oil Change Axle Oil Change.REAR AXLE REPLACE 02/05/2019

Vehicle Deep Clean **21/05/2019** **09:00** **21/05/2019** **13:30** **277,928** **Dorchester** **DC020253**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **30/05/2019** **05:41** **30/05/2019** **08:45** **279,851** **Dorchester** **DC020287**

Breakdown nail in nsf tyre EM light on
Travel Time

Breakdown **09/06/2019** **19:14** **10/06/2019** **09:27** **282,502** **Dorchester** **DC020338**

Breakdown	BONNET CATCH BROKEN,replace catch						
SAFETY INSPECTION	01/07/2019	05:45	01/07/2019	14:41	287,022	Dorchester	DC020437
01 Air Conditioning 1	Not working in saloon						
02 Cab Assembly 1	n/s window swith u/s						
02 Windscreen Wipers	Screen washers inop						
16 Suspension 1	Rear anti roll bar bushes						
17 Tyres	n/s/f tyre low/puncture						
18 Wheels Check Torques							
45 Engine Ad Blue	top up						
71 Body Exterior 1	Body Exterior Bonnet catch fallen apart - parts missing						Awaiting Parts
71 Body External Steps	Side step intermittent						
85 Body Interior 1	Mangar charger u/s						
Safety Inspection							
Engine Change Oil & Filter							
Vehicle Deep Clean	03/07/2019	10:00	03/07/2019	13:49	287,048	Dorchester	DC020454
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	24/07/2019	08:30	24/07/2019	08:45	291,701	Dorchester	DC020561
02 Windscreen Wipers	Washers inop,clean filter and bottle.refill						
Breakdown	06/08/2019	08:41	06/08/2019	10:00	294,519	Dorchester	DC020612
45 Engine Ad Blue							
Breakdown	screen washer not wrking						
SAFETY INSPECTION	12/08/2019	06:00	13/08/2019	09:02	296,100	Dorchester	DC020649
13 Brake Pads	front low						
13 Discs	front worn						
16 Suspension 1	struts and arms u/s						

17 Tyres	all rear low
18 Wheels Check Torques	
31 Battery Chassis	chassis batt low
45 Engine Ad Blue	top up
45 Engine Oil Top Up	top up
55 Tail Lift	wheel pivot plate siezed
71 Body Exterior 1	Body Exterior Bonnet catch fallen apart - parts missing
Road Test	
Safety Inspection	

Vehicle Deep Clean	13/08/2019	10:00	13/08/2019	14:00	296,113	Dorchester	DC020660
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	06/09/2019	15:57	07/09/2019	12:40	301,483	Dorchester	DC020809
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine Oil Top Up	top up
71 Body External Steps	Side step Alarm going off
Breakdown	EML amber; AdBlue warning on
DEFCT01	Emg Warning Devices Amber EML and AdBlue Warning Light
Travel Time	

BREAKDOWN	09/09/2019	15:30	09/09/2019	18:00	302,213	Dorchester	DC020822
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	EML on
Travel Time	

breakdown	20/09/2019	20:15	21/09/2019	14:01	302,325	Dorchester	DC020886
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres	N/S/F tyre bald
Travel Time	

SAFETY INSPECTION	23/09/2019	06:30	24/09/2019	08:34	303,218	Dorchester	DC020887
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brakes 1	refit servo pipe
-------------	------------------

17 Tyres Replace	replace OSF tyre							
17 Tyres Tracking	OSF tyre worn on outer edge Mileage 305217						Monitoring	
18 Wheels Check Torques								
24 Driveshaft 1	slight lift in rear prop sliding joint						Monitoring	
27 Transmission Automatic	slight lift in rear output bearing						Monitoring	
44 Add Ad Blue	top up							
45 Engine 1	Engine EML solid yellow. Drives ok. Mileage 305217							
45 Engine Oil Top Up	top up							
71 Body External Steps	Body Exterior side step inoperative. Mileage 305217							
87 Stretcher	replace battery. mileage 305217							
Safety Inspection								
Air Filter Change	Air Filter Change							
Pollen Filter Change	Pollen Filter Change							
Fuel Filter Change	Change Fuel Filter							
Tail Lift Inspection								
Vehicle Deep Clean	24/09/2019	09:30	24/09/2019	14:42	303,376	Dorchester		DC020895
Vehicle Deep Clean	Vehicle Deep Clean							
Unplanned Repair	23/10/2019	13:25	23/10/2019	13:38	311,944	Dorchester		DC021083
34 Lights Bulb Replacement	Replace o/s headlamp bulb							
SAFETY INSPECTION	04/11/2019	06:00	08/11/2019	12:59	314,567	Dorchester		DC021141
13 Brake Pads	front and rear worn							
15 Steering 1	Rack u/s							
16 Suspension 1	Front drop links u/s							
16 Suspension 2	Slipper pads u/s							
17 Tyres	n/s/f tyre wearing							
17 Tyres Tracking	OSF tyre worn on outer edge Mileage 305217							
18 Wheels Check Torques								
24 Driveshaft 1	slight lift in rear prop sliding joint							
27 Transmission Automatic	slight lift in rear output bearing							
34 Lighting System	headlamp aim out							
34 Lights	o/s repeator n/w							
44 Fuel System 1	Fuel leak on balance pipe							
45 Engine 1	EML on							

45 Engine 2
 56 Comms Equipment
 85 Body Interior 1
 86 Doors Rear
 86 Sliding Door
 89 Seats
 Safety Inspection
 Travel Time
 UB Fire Supp 6mts Service
 Engine Change Oil & Filter
 Auto G/box Oil & Filter Change

Ad blue light on
 EPCR batt u/s
 centre cab box hinges broken
 Rear hinges u/s and handle u/s
 outter handle stiff
 driver seat swab u/s

Vehicle Deep Clean	07/11/2019	08:20	07/11/2019	13:08	314,567	Dorchester	DC021162
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	29/11/2019	10:40	29/11/2019	11:13	318,973	Dorchester	DC021307
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	Mirrors O/S mirror/case damage - reverse through trees
------------	--

Unplanned Repair	10/12/2019	14:30	10/12/2019	15:04	321,283	Dorchester	DC021367
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1	Saloon heater inop,carry out checks.replace ECU
--------------	---

Unplanned Repair	14/12/2019	09:10	14/12/2019	10:15	322,233	Dorchester	DC021401
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

55 Tail Lift Travel Time	Under rider bars damaged.Remove	Awaiting Parts
-----------------------------	---------------------------------	----------------

BREAKDOWN	10/12/2019	13:16	11/12/2019	10:00	321,284	St Leonards	SL028609
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

01 Heating 1 44 Add Ad Blue	Saloon heater not working. Req full service. Top up unit.
--------------------------------	--

SAFETY INSPECTION	16/12/2019	06:30	17/12/2019	13:23	322,587	Dorchester	DC021404
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers	blades u/s washers blocked
----------------------	----------------------------

17 Tyres
 18 Wheels
 18 Wheels Check Torques
 34 Emergency Lights
 45 Engine Ad Blue
 45 Engine Oil Top Up
 71 Body Exterior 1
 Safety Inspection
 Travel Time
 Tail Lift Inspection
 MOT
 Brakes Replace Brake Fluid

5x tyres needed
 cracked rim

 blue light above door inop
 top up
 top up
 n/s/r corner cap

Vehicle Deep Clean	17/12/2019	13:30	18/12/2019	15:30	322,801	Dorchester	DC021424
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

breakdown	21/12/2019	06:15	24/12/2019	12:47	323,460	Dorchester	DC021468
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1 Travel Time	Water leak pump u/s
----------------------------	---------------------

Breakdown	30/12/2019	18:44	31/12/2019	06:59	324,800	Dorchester	DC021508
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown Travel Time	O/S Headlight Out To and from Swanage.
--------------------------	---

Unplanned Repair	14/01/2020	10:00	14/01/2020	10:15	327,775	Dorchester	DC021594
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

89 Seatbelts	SRS light on.Clean connector to drivers seat belt stalk.Check ok
--------------	--

Breakdown	20/01/2020	07:36	20/01/2020	10:30	329,000	Dorchester	DC021617
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Doors Rear Breakdown	Check fault,free off siezed lower pin adn adjust cable Rear door stuck shut
----------------------------	--

Unplanned Repair	21/01/2020	08:00	21/01/2020	09:23	329,320	Dorchester	DC021637
34 Lights Bulb Replacement Replace 2 headlight bulbs 45 Engine Oil Top Up							
SAFETY INSPECTION	27/01/2020	10:25	27/01/2020	15:00	330,700	Dorchester	DC021682
18 Wheels Check Torques 45 Engine Ad Blue 45 Engine Oil Top Up 55 Tail Lift Under rider bars damaged.Remove Safety Inspection							
ACCIDENT	30/01/2020	05:48	22/05/2020	15:30	331,166	Dorchester	DC021700
71 Body Exterior Acc Repair Extensive damage to rear Breakdown Extensive RTC damage to rear							
Tail Lift 12M Service & Weight	21/04/2020	10:25	21/04/2020	14:00	331,166	Dorchester	DC022418
Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight.CARRIED OUT @ AUTOSPRAY Tail Lift Inspection							
SAFETY INSPECTION	24/05/2020	07:00	24/05/2020	07:01	331,270	Dorchester	DC022442
18 Wheels Check Torques Safety Inspection Vehicle Deep Clean Vehicle Deep Clean							
SAFETY INSPECTION	24/05/2020	07:00	24/05/2020	07:01	331,270	Dorchester	DC022443
18 Wheels Check Torques Safety Inspection Vehicle Deep Clean Vehicle Deep Clean							
SAFETY INSPECTION	24/05/2020	07:30	26/05/2020	15:00	331,272	Dorchester	DC022444

02 Windscreen Wipers	washers broken
13 Brakes 1	Fronts corroded/siezed
13 Brakes 2	Pedal rubber u/s
16 Suspension 1	ARB links worn
17 Tyres	extension not refitted to rears
18 Wheels Check Torques	
45 Engine 1	Boost pipe bracket broken
45 Engine Ad Blue	top up
56 Comms Power Failure	Carry out checks.Suspect internal battery.PCE to sort
85 Body Interior 1	Fire exts out of date
85 Body Interior 2	Some stickers/tape missing
86 Sliding Door	not holding
D Service	
Safety Inspection	
Travel Time	
Replace Handbrake Cables	Replace Handbrake Cables
UB Fire Supp 12mts Service	Service of fire supression system
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Vehicle Deep Clean	Vehicle Deep Clean
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	

Vehicle Deep Clean	26/05/2020	08:00	26/05/2020	08:01	331,270	Dorchester	DC022480
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

02 Pipeline Annual Inspection	26/05/2020	10:00	26/05/2020	10:30	331,270	MDT Weymouth	DW000244
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	---------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No Faults
-------------------------------	---

unplanned repair	10/06/2020	14:55	10/06/2020	15:10	333,713	Dorchester	DC022586
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	replace DRL bulbs
86 Sliding Door	Not holding open,adjust

Breakdown	01/07/2020	10:07	01/07/2020	14:21	336,605	Dorchester	DC022716
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

42 Coolant System	Trace to split hose,carry out temp repair and order new hose	Awaiting Parts
-------------------	--	----------------

Breakdown complete loss of coolant

SAFETY INSPECTION **14/07/2020** **10:01** **15/07/2020** **07:47** **338,509** **Dorchester** **DC022798**

02 Windscreen Wipers	washers poor	
15 Steering 1	Power steer hose leaking	
16 Suspension 1	ARB links worn top ones	
17 Tyres	n/s/f cut to cord	
18 Wheels Check Torques		
34 Lights	side light out o/s	
42 Coolant System	Trace to split hose,carry out temp repair and order new hose	
45 Engine 1	oil leak from sump gasket corner	Monitoring
45 Engine Ad Blue	top up	
71 Body Exterior 1	rear reflector broken	
71 Body Exterior 2	Clean off	
85 Body Interior 1	torch missing,console knob broken	
99 Diagnostic Test	EML on	
Safety Inspection		
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card	
Engine Change Oil & Filter		

Vehicle Deep Clean **15/07/2020** **09:00** **15/07/2020** **13:10** **338,521** **Dorchester** **DC022811**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **30/07/2020** **08:30** **31/07/2020** **13:52** **341,421** **Dorchester** **DC022927**

13 Handbrake	adjust
71 Body External Steps	rear step damaged

Breakdown **03/08/2020** **12:04** **05/08/2020** **08:47** **341,997** **Dorchester** **DC022946**

01 Air Conditioning 1	degas and regas both systems
42 Radiator	Leaking
Breakdown	Leaking Coolant
Travel Time	collect from dorchester

Breakdown	06/08/2020	11:17	06/08/2020	13:14	342,154	Dorchester	DC022974
Breakdown	Coolant pipe come off. dumped coolant on floor						
Unplanned Repair	09/08/2020	12:00	10/08/2020	12:00	342,807	St Leonards	SL030657
02 Windscreen Wipers 86 Sliding Door	Washers inop. Cleaned pipes,pump,& bottle. Side door difficult to open from outside						
SAFETY INSPECTION	24/08/2020	08:23	25/08/2020	07:17	344,728	Dorchester	DC023114
13 Brakes 1 17 Tyres 18 Wheels Check Torques 34 Emergency Lights 45 Engine 1 45 Engine Ad Blue 45 Engine Oil Top Up 56 Comms Equipment 85 Body Interior 1 86 Sliding Door Safety Inspection Tail Lift Inspection	Rear low Rear low grill light inop oil leak from sump gasket corner top up top up NO HANDHELD RADIOS ON VEHICLE, STILL WITH CREW FROM SWAP torch inop. top magnet bent						
Vehicle Deep Clean	25/08/2020	08:20	25/08/2020	13:00	344,740	Dorchester	DC023124
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	03/09/2020	05:30	03/09/2020	10:32	346,297	Dorchester	DC023184
45 Engine 1 54 Sirens	EML reported on Emg Warning Devices siren not working						
Unplanned Repair	25/09/2020	14:30	25/09/2020	15:03	350,301	Dorchester	DC023361

34 Lights Bulb Replacement	replace DLR bulb
44 Add Ad Blue	top up

SAFETY INSPECTION	05/10/2020	06:00	05/10/2020	15:22	352,096	Dorchester	DC023413
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers	washers blocked, blade split
13 Brake Pads	front low
18 Wheels Check Torques	
34 Lights Bulb Replacement	headlight out
44 Fuel System 1	hose leaking
45 Engine 1	EML on
45 Engine Ad Blue	top up
45 Engine Oil Top Up	top up
55 Tail Lift	rail siezed
87 - Stretchers/Chairs/Boards	Battry u/s
Safety Inspection	
Pollen Filter Change	Pollen Filter Change
Fuel Filter Change	Change Fuel Filter
Air Filter Change	Air Filter Change

Vehicle Deep Clean	06/10/2020	09:17	06/10/2020	13:05	352,110	Dorchester	DC023429
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	30/10/2020	08:32	30/10/2020	12:13	356,700	Dorchester	DC023588
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	Poor performance reported. See notes.
45 Engine Ad Blue	
56 Comms Equipment	Replace aerial
Breakdown	base radio intermit-aerial missing

SAFETY INSPECTION	16/11/2020	06:00	16/11/2020	14:06	359,496	Dorchester	DC023703
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	Dash Panel broken..panel on order	Monitoring
02 Windscreen	Small chip in screen	Monitoring
03 Instruments & Sensors 1	Service light on	
13 Brake Pads	Rears low	

13 Brakes 1	Brake Wear light on..loom on order	Monitoring
16 Suspension 1	Slight play in struts and arms	Monitoring
18 Wheels Check Torques		
45 Engine Ad Blue	Top up	
85 Body Interior 1	Other hand held fire extinguisher used	
Safety Inspection		
Travel Time		
Tail Lift Inspection		
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service	
MOT		

Vehicle Deep Clean	18/11/2020	08:15	18/11/2020	12:23	359,515	Dorchester	DC023728
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	02/12/2020	09:00	02/12/2020	09:56	361,976	Dorchester	DC023828
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	replace NS side light bulb
55 Tail Lift	tail lift bridge pin missing

COMMS.FAILURE CHECK	23/12/2020	01:54	23/12/2020	11:23	366,125	Dorchester	DC023959
----------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

56 Comms Power Failure	Comms Power Check Coms Battery alaming
86 Sliding Door	Doors Side Door Sensor Alarming
MDT Failure/Issue	

SAFETY INSPECTION	29/12/2020	06:00	30/12/2020	11:00	367,314	Dorchester	DC023981
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	Dash Panel broken..panel on order
02 Windscreen	Small chip in screen
13 Brake Pads	
13 Brakes 1	Brake Wear light on..loom on order
16 Suspension 1	Slight play in struts and arms
17 Tyres Replace	
18 Wheels Check Torques	
31 Battery Chassis	replace chassis battery
44 Add Ad Blue	top up

45 Engine Oil Top Up	top up						
55 Tail Lift	fit new serial number signs						
71 Body External Steps	side step not deploying						
85 Body Interior 1	stretcher guide buffer split						
Safety Inspection							
Vehicle Deep Clean	30/12/2020	12:00	30/12/2020	14:31	367,328	Dorchester	DC023995
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	06/01/2021	08:21	06/01/2021	09:24	368,620	Dorchester	DC024043
71 Body External Steps	Side step deploying while deploying while driving						
Unplanned Repair	08/01/2021	14:30	08/01/2021	14:52	369,077	Dorchester	DC024067
02 Windscreen Wipers	Washers inop,filter blocked again,clean out and refill						
Unplanned Repair	04/02/2021	10:00	04/02/2021	10:15	374,641	Dorchester	DC024283
34 Lights Bulb Replacement	DRL inop,replace bulb						
85 Body Interior 1	Long storage cupboard reported not shutting.Stow bin correctly !!!!!!!!						
Breakdown	05/02/2021	22:02	08/02/2021	15:26	375,007	Dorchester	DC024302
02 Windscreen Wipers	wasahers blocked, blades u/s.						
03 Instruments & Sensors 1	EML on Service light on						
16 Suspension 1	Slipper pads u/s						
17 Tyres	All rears low						
34 Lights	o/s/r tail light u/s						
43 Exhaust System 1	Tail pipe rotted						
55 Tail Lift	tilt switch u/s						
Breakdown	Radiator top hose holed						
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
Engine Change Oil & Filter							
Tail Lift Inspection							
18 Wheels Check Torques							
Safety Inspection							

Vehicle Deep Clean	08/02/2021	14:30	09/02/2021	12:07	375,021	Dorchester	DC024318
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	22/02/2021	09:58	22/02/2021	11:38	377,177	Dorchester	DC024407
34 Emergency Lights Breakdown	N/S/R upper light smashed off Nearside Rear Light bar has come off the vehicle						
Breakdown	25/02/2021	07:13	25/02/2021	09:36	377,437	Dorchester	DC024447
34 Lighting System Breakdown	Make good connections on both repeaters Two near side indicators not working ?						
Breakdown	26/02/2021	20:00	27/02/2021	10:57	377,739	Dorchester	DC024464
Breakdown	CREW REPORTED TURBO FAILURE						
Unplanned Repair	01/03/2021	09:00	01/03/2021	09:34	377,970	Dorchester	DC024472
01 Heating 1 56 Comms Equipment	Saloon heater reported not working.Run and test,ok Electrical Auxs MDT FAILS TO ALLOW BOOK ON.Reboot system						
Breakdown	03/03/2021	15:46	06/03/2021	11:51	378,479	Dorchester	DC024498
45 Engine 1 Breakdown	Injectors blowing squeaking noise from engine and fumes in cab						
Unplanned Repair	10/03/2021	02:00	10/03/2021	02:15	378,823	Dorchester	DC024531
34 Lights Bulb Replacement	Headlamp bulb replaced by Bronze						
Unplanned Repair	11/03/2021	10:00	11/03/2021	10:45	378,979	Dorchester	DC024548
34 Lights	o/s headlamp intermittent Awaiting Parts						

Unplanned Repair	18/03/2021	11:00	18/03/2021	13:45	379,878	Dorchester	DC024587
45 Engine 1	EML on						
54 Reversing Systems	Camera inop..Jon Coles repaired						
Breakdown	20/03/2021	10:25	24/03/2021	15:05	380,684	Dorchester	DC024595
01 Air Conditioning 1	Adjuster worn						
02 Cab Assembly 1	Torch missing, foot plate broken						
02 Windscreen Wipers	Washers blocked						
13 Brake Pads	Rear pads low and sensors to fit						
13 Brakes 1	Fronts worn						
16 Suspension 1	ARB links worn						
16 Suspension 2	O/S slip pads split						
17 Tyres	O/S/r puncture						
34 Emergency Lights	Grill light inop						
34 Lights	o/s headlamp to replace						
45 Engine Ad Blue	Top up						
54 Reversing Systems	CCTV Lens damaged						
85 Body Interior 1	Sky light blind u/s						
86 Sliding Door	bearings rough, magnet bent						
89 Seats	passenger seat swab worn						
Breakdown	nearside high beam n/w; offside grill blue light						
18 Wheels Check Torques							
Safety Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Vehicle Deep Clean	23/03/2021	13:30	23/03/2021	15:26	380,683	Dorchester	DC024614
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	05/05/2021	12:02	06/05/2021	11:10	388,510	Dorchester	DC024905
02 Cab Assembly 1	Brake pedal rubber split						
02 Cab Assembly 2	Defect book to replace						
02 Windows/Glass	n/s switch u/s						

03 Instruments & Sensors 1	Service light on						
17 Tyres	1x low						
18 Wheels Check Torques							
45 Engine Ad Blue	top up						
86 Sliding Door	magnet bent again						
Safety Inspection							
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Vehicle Deep Clean	06/05/2021	09:45	06/05/2021	10:45	388,520	Dorchester	DC024908
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	17/05/2021	10:00	17/05/2021	10:40	391,040	Dorchester	DC025001
86 Door Lock	adjust side door lock cable						
Breakdown	19/05/2021	08:57	19/05/2021	10:00	391,600	Dorchester	DC025033
Breakdown	R.N/S Outer Puncture						
Breakdown	23/05/2021	06:43	24/05/2021	12:30	392,418	Dorchester	DC025069
86 Sliding Door	Sliding door open warning going off						
Breakdown	side door keeps opening; VOR						
Travel Time							
Breakdown	03/06/2021	08:25	03/06/2021	11:00	394,840	Dorchester	DC025159
Breakdown	O/S/F - Screw in tyre						
BREAKDOWN	10/06/2021	07:36	11/06/2021	14:05	396,280	Dorchester	DC025201
02 Windscreen	windscreen chipped						
13 Brake Pads	rears low						
							Monitoring

16 Suspension 1	slight play in struts and arms						Monitoring
34 Emergency Lights	NSF and OSF wing blue light not flashing, Replace NSF no parts for OS						
34 Lighting System	OSF fog lt lens smashed						
34 Lights	NSR yellow marker 50%						
34 Lights Bulb Replacement	interior light inop, NS DLR out						
44 Add Ad Blue	top up						
45 Engine 1	rear crankshaft seal oil leak						Monitoring
45 Engine Oil Top Up	top up						
86 Sliding Door	Side door faulty						
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
Replace Handbrake Cables	Replace Handbrake Cables						
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 12mts Service	Service of fire suppression system						
Vehicle Deep Clean	11/06/2021	12:00	11/06/2021	17:25	396,303	Dorchester	DC025214
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	18/06/2021	14:30	18/06/2021	15:30	397,869	Dorchester	DC025265
86 Sliding Door	Door opening fault.Check all adjustments,replace cover						
Breakdown	26/06/2021	22:28	27/06/2021	06:01	399,735	Dorchester	DC025332
Breakdown	Str wheel sticking						
Unplanned Repair	08/07/2021	09:00	08/07/2021	09:48	402,499	Dorchester	DC025410
86 Doors Rear	Unable to open o/s/r door						
Breakdown	20/07/2021	20:45	23/07/2021	13:23	405,248	Dorchester	DC025500
02 Windscreen Wipers	blades poor						
03 Instruments & Sensors 1	service light on						

13 Brakes 1	rears discs worn, has new pads in it. change when worn					Monitoring	
18 Wheels	various nuts siezed, replace all						
45 Engine Ad Blue	top up						
56 Comms Equipment	MDT not working						
86 Doors Rear	Fit strenghten plates						
Breakdown	limp mode						
18 Wheels Check Torques							
Safety Inspection							
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Tail Lift Inspection							
Engine Change Oil & Filter							
Vehicle Deep Clean	23/07/2021	15:00	24/07/2021	14:32	405,310	Dorchester	DC025527
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	01/08/2021	10:32	02/08/2021	08:39	406,707	Dorchester	DC025587
Breakdown	elec fault-non starter-EMLs-no turn over						
Breakdown	06/08/2021	14:04	09/08/2021	08:15	407,752	Dorchester	DC025628
001 Recover Vehicle	Vehicle Recovery 06.08.201 14.00						
Breakdown	Fan Belt Gone						
BREAKDOWN	18/08/2021	07:30	18/08/2021	11:31	407,752	Dorchester	DC025719
31 Charging System							
Unplanned Repair	23/08/2021	11:45	23/08/2021	12:13	410,162	Dorchester	DC025758
03 Instruments & Sensors 1	AdBlue fault.Carry out checks.NOx sensor fault.Order parts						
56 Comms Equipment	MDT inop,reboot system						

Breakdown	05/09/2021	08:02	07/09/2021	09:30	413,064	Dorchester	DC025839
13 Brake Pads	all pads low						
34 Emergency Light System	OS wing blue light not flashing						
34 Emergency Lights	NSR blue lights not working						
44 Add Ad Blue	top up						
44 Fuel System 1	EML on adblue fault						
44 Fuel System 2	adblu fault						
45 Engine 1	replace NOX sensor						
45 Engine Oil Top Up	top up						
Breakdown	fault AUX system VOR at Dorchester						
18 Wheels Check Torques							
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Vehicle Deep Clean	07/09/2021	09:20	07/09/2021	14:59	413,117	Dorchester	DC025854
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	22/09/2021	23:42	23/09/2021	09:45	415,858	Dorchester	DC025993
Breakdown	MDT not powering on						
Breakdown	25/09/2021	21:15	27/09/2021	08:18	416,315	Dorchester	DC026013
Breakdown	MDT not powering on						
Breakdown	02/10/2021	16:58	04/10/2021	10:54	417,999	Dorchester	DC026064
Breakdown	EML warning and power steering gone						
Breakdown	08/10/2021	19:44	11/10/2021	07:40	419,083	Dorchester	DC026106
Breakdown	Rear doors not opening						
Travel Time							

Unplanned Repair	14/10/2021	12:00	14/10/2021	13:44	419,637	Dorchester	DC026145
34 Lights 86 Sliding Door	o/s repeater inop.Make good connection Top and bottom catches worn.Order parts					Awaiting Parts	
Vehicle Deep Clean	18/10/2021	08:15	18/10/2021	14:08	420,284	Dorchester	DC026161
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/10/2021	14:52	21/10/2021	12:19	420,292	Dorchester	DC026170
02 Glass / Windows 13 Brake Pads 13 Brakes 1 16 Suspension 1 17 Tyres Replace 18 Wheels Check Torques 34 Lights 44 Add Ad Blue 45 Engine 1 45 Engine Oil Top Up 86 Sliding Door Safety Inspection Tail Lift Inspection MOT	Door switch broken rears low rears discs worn, has new pads in it. change when worn slight play in struts and arms Rear tyres worn o/s/f marker smashed rear crankshaft seal slight oil leak Top and bottom catches worn.Order parts					Monitoring Awaiting Parts	
BREAKDOWN	25/10/2021	07:32	25/10/2021	10:35	420,696	Dorchester	DC026204
86 Doors Rear	Doors REAR DOOR UNABLE TO OPEN						
Unplanned Repair	09/11/2021	08:15	09/11/2021	09:31	423,135	Dorchester	DC026313
86 Doors Rear	Unable to open large rear door.Check fault,replace door cable						

Breakdown	26/11/2021	17:27	30/11/2021	12:30	423,200	Dorchester	DC026453
02 Cab Ass Fire Extinguisher	out of date						
03 Instruments & Sensors 1	Adblue light on and service light						
13 Brakes 1	Rears worn,						
13 Brakes 2	NO HANDBRAKE CABLES. see notes					Monitoring	
13 Handbrake	Shoes Worn out						
16 Suspension 1	Rear ARBs Worn						
17 Tyres	Fronts low						
31 Charging System	alternator belt adjuster siezed						
42 Coolant System	Radiator couling damaged and top missing						
45 Engine 1	Oil leak from boost seals/resinator bracket cracked						
45 Engine 2	Oil filter housing leaking						
45 Engine 3	both engine mounts split						
55 Tail Lift	Hose leaking						
86 Doors Rear	Replace rear catches, order in from old J/C						
89 Seats	Attendant seat bearings u/s						
Breakdown	Side door latch come off						
Travel Time							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
18 Wheels Check Torques							
Safety Inspection	Carry out inspection						
Brake Fluid Change	Brake Fluid Change						
Engine Change Oil & Filter							
Vehicle Deep Clean	30/11/2021	12:45	02/12/2021	14:14	423,690	Dorchester	DC026471
Vehicle Deep Clean	Vehicle Deep Clean						
Medical Devices Repair	30/11/2021	13:00	30/11/2021	14:00	423,690	MDT Weymouth	DW000758
Decontaminated	Cleaned with clinell wipes						
Defect Sheet Present No	No						
Defect Sheet Present Yes							
Medical Devices Repair	O2 ports service kits x2 fitted						

Breakdown	13/12/2021	07:12	13/12/2021	09:56	427,546	Dorchester	DC026558
86 Sliding Door Breakdown	door open warning on constantly SIDE DOOR WON'T LOCK						
Unplanned Repair	14/12/2021	01:45	14/12/2021	02:00	427,783	Dorchester	DC026575
34 Lights Bulb Replacement	Headlight bulb replaced by Bronze						
Unplanned Repair	15/12/2021	12:00	15/12/2021	12:31	428,103	Dorchester	DC026595
89 Seatbelts	attendants seatbelt not retracting						
Breakdown	04/01/2022	17:51	05/01/2022	09:40	432,177	Dorchester	DC026757
34 Lights Bulb Replacement	headlights not working, bulbs blown						
45 Engine 1	EML on						
86 Sliding Door	top catch loose						
87 Chairs	carry chair lock bent						
Breakdown	EML amber-limp mode, side door, carry chair						
Breakdown	07/01/2022	11:56	07/01/2022	15:13	432,289	Dorchester	DC026784
Breakdown	SIRENS NOT WORKING						
SAFETY INSPECTION	12/01/2022	08:45	13/01/2022	12:07	433,590	Dorchester	DC026813
13 Brake Pads	front pads and discs worn						
13 Brakes 2	NO HANDBRAKE CABLES. see notes						
13 Calipers	NSF caliper sliders seized						
16 Suspension 1	play in struts and arms						
18 Wheels Check Torques							
44 Fuel System 1	secure fuel pipes from filter, clamps loose						
45 Engine 1	rear crankshaft seal slight oil leak						
45 Engine Oil Top Up	top up						
55 Tail Lift	splatform rails stiff and tail lift black guide bolt sheared						
85 Body Interior 1	track locker lock securing strip damaged						
86 Door Lock	rear door lock barrel seized and sliding door barrel snapped						
86 Sliding Door	Top and bottom catches worn.Order parts						

Safety Inspection
Tail Lift Inspection

Vehicle Deep Clean	18/01/2022	08:30	18/01/2022	12:00	433,952	Dorchester	DC026861
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	23/01/2022	19:47	24/01/2022	13:31	434,338	Dorchester	DC026912
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Sliding Door Breakdown Road Test	defective side door(keeps opening); VOR
---	---

Breakdown	15/02/2022	11:17	15/02/2022	15:04	436,355	Dorchester	DC027081
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1 Breakdown	EML on and limp mode, vehicle recovered Orange EML & limp mode
--------------------------	---

Unplanned Repair	18/02/2022	07:00	18/02/2022	08:52	436,570	Dorchester	DC027094
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

31 Battery Comms 45 Engine 1 54 Sirens	comms battery reported as low limp mode reported sirens reported not working
--	--

SAFETY INSPECTION	18/02/2022	10:00	18/02/2022	12:55	436,570	Dorchester	DC027096
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen 02 Windscreen Wipers 15 Steering 1 18 Wheels Check Torques 34 Emergency Lights 44 Add Ad Blue 45 Engine 1 45 Engine Oil Top Up 71 Body Exterior 1 71 Body Exterior 2 Safety Inspection	chipped in swept area replace blades power steering reservoir hose loose OS upper front blue lens cracked NO PARTS top up rear crankshaft oil seal leaking top up Body Exterior Side door alarming when driving top catch loose Body Exterior potential damage top of vehicle into guttering	Monitoring Monitoring
--	--	--

Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Vehicle Deep Clean **21/02/2022** **09:30** **22/02/2022** **12:29** **436,585** **Dorchester** **DC027110**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **04/03/2022** **10:15** **04/03/2022** **11:24** **438,010** **Dorchester** **DC027181**

45 Engine 1 LOP reported.See notes

O2 Pipeline Annual Inspection **12/03/2022** **14:30** **12/03/2022** **15:30** **439,430** **MDT Weymouth** **DW000838**

O2 Pipeline Annual Inspection Annual Inspection and Pressure Test - right angle probes fitted, otherwise OK

Breakdown **15/03/2022** **14:52** **16/03/2022** **06:42** **439,521** **Dorchester** **DC027277**

Breakdown LIMP MODE

ACCIDENT **28/03/2022** **04:33** **28/03/2022** **11:25** **441,753** **Dorchester** **DC027348**

Breakdown R/N/S Blue Light Damage
34 Emergency Lights NSR upper blue lens knocked off, temp repair

SAFETY INSPECTION **05/04/2022** **09:28** **06/04/2022** **14:14** **442,230** **Dorchester** **DC027399**

18 Wheels Check Torques
Safety Inspection
02 Windscreen chipped in swept area
45 Engine 1 rear crankshaft oil seal leaking
Tail Lift Inspection
86 Sliding Door Catches and pins worn

34 Lights Bulb Replacement	NS DLR out
34 Emergency Lights	NSR corner blue lens damaged, no parts
34 Emergency Light System	OSF outer blue lens cracked
44 Fuel System 1	fuel angel missing
44 Add Ad Blue	top up
45 Engine Oil Top Up	top up
86 Doors Rear	barrel seized
01 Heating 1	night heater not working and exhaust split
43 Exhaust System 1	tailpipe rubber bush split
17 Tyres Replace	OSF worn
13 Brake Pads	rears low
16 Suspension 1	rear ARB link bushes worn x2

Vehicle Deep Clean	07/04/2022	08:17	07/04/2022	15:04	442,244	Dorchester	DC027418
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	20/04/2022	07:12	20/04/2022	08:12	443,830	Dorchester	DC027511
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	OSF h/l out
34 Lights Bulb Replacement	Replace o/s headlamp bulb

Breakdown	16/05/2022	10:23	25/05/2022	13:19	448,690	Dorchester	DC027667
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	O/S/R door hinge broken
18 Wheels Check Torques	
Safety Inspection	
86 Sliding Door	Difficult to open..top catch loose
34 Emergency Lights	N/S/R Top Corner blue damaged
89 Seats	Driver seat swab torn
02 Windscreen Wipers	Blades poor
45 Engine 1	Excessive oil leaks all over engine, EXTREMELY NOISE RATTLE
02 Cab Assembly 1	Cab Mats Required
03 Instruments & Sensors 1	Service light on
24 Driveshaft 1	Front Prop Rear U/J worn
16 Suspension 1	All Rear Spring Eye Bushes Worn
17 Tyres	Fronts Worn
01 Air Conditioning 1	Adjuster U/S
002 Major Unit Replace Eng	

01 Heating 1	Cab heating inop...stepper motor u/s						
27 Transmission Automatic	Gearbox rear mount u/s						
Vehicle Deep Clean	18/05/2022	09:57	18/05/2022	14:45	448,682	Dorchester	DC027686
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	07/06/2022	11:15	07/06/2022	11:25	450,404	Dorchester	DC027820
34 Emergency Lights	NSF upper blue LED hanging off						
Unplanned Repair	23/06/2022	09:30	23/06/2022	10:43	452,959	Dorchester	DC027960
02 Windscreen Wipers	washers blocked						
SAFETY INSPECTION	27/06/2022	08:30	28/06/2022	08:47	453,850	Dorchester	DC027975
18 Wheels Check Torques							
Safety Inspection							
Wheel Hub Flanges Replaceme							
Engine Change Oil & Filter	new engine fitted at 448690 miles, 25/05/2022						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Pollen Filter Change	Pollen Filter Change						
Replace Handbrake Cables	Replace Handbrake Cables						
UB Fire Supp 12mts Service	Service of fire supression system						
Tail Lift Inspection							
54 Horns	horn inop						
44 Add Ad Blue	top up						
86 Sliding Door	lock barrel snapped						
13 Brake Pads	fronts low						
02 Cab Ass Fire Extinguisher	saloon extinguisher OOD						
Vehicle Deep Clean	28/06/2022	09:42	28/06/2022	15:25	453,863	Dorchester	DC027985
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	09/07/2022	20:57	12/07/2022	15:30	456,056	Dorchester	DC028056
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	MDT no power						
-----------	--------------	--	--	--	--	--	--

Unplanned Repair	19/07/2022	10:00	19/07/2022	12:29	456,723	Dorchester	DC028112
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	Saloon a/c inop.....under vehicle fan assembly u/s					Monitoring
-----------------------	--	--	--	--	--	------------

Unplanned Repair	21/07/2022	09:30	21/07/2022	14:00	457,003	Dorchester	DC028134
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	Saloon a/c inop.....under vehicle fan assembly u/s						
01 Air Conditioning 2	Radiator/Cooling Sys AIR CON IN BACK NOT WORKING						

Breakdown	10/08/2022	01:41	11/08/2022	15:17	461,084	Dorchester	DC028245
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Adblue System Malfunction						
45 Engine Ad Blue	System Malfunction.. EGR valve faulty. WARRANTY						
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
18 Wheels Check Torques							
Safety Inspection							
45 Engine Oil Top Up	top up						
42 Coolant System	top up						
55 Tail Lift	bridging plate guides damaged and tilt switch U/S						
17 Tyres Replace	OSF and both OSR worn						
13 Brake Pads	rears low						
16 Suspension 1	1 slipper pad split						
02 Windscreen Wipers	worn						

Unplanned Repair	27/09/2022	10:58	27/09/2022	12:00	468,387	St Leonards	SL037646
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Mirrors	Body Exterior N/S wing mirror						
71 Body External Steps	Step Sticking						
34 Lights	N/S bulb out						

SAFETY INSPECTION	06/10/2022	11:00	07/10/2022	15:00	469,623	St Leonards	SL037728
18 Wheels Check Torques Safety Inspection Tail Lift Inspection 32 Starting System 1 71 Body Exterior Acc Repair 17 Tyres Tracking		Poor starting Side step u/s Tracking to be done. Gauges not working				Monitoring	
Vehicle Deep Clean	10/10/2022	08:57	10/10/2022	08:58	469,623	St Leonards	SL037778
Vehicle Deep Clean		Vehicle Deep Clean					
Vehicle Deep Clean	10/10/2022	08:58	11/10/2022	07:30	469,623	St Leonards	SL037779
Vehicle Deep Clean		Vehicle Deep Clean					
BREAKDOWN	18/10/2022	05:59	18/10/2022	11:15	470,539	St Leonards	SL037873
71 Body External Steps		Body Exterior Side step alarming					
Unplanned Repair	08/11/2022	13:00	08/11/2022	14:54	474,251	St Leonards	SL038064
71 Body External Steps		Step sticking					
MOT	09/11/2022	08:00	09/11/2022	14:57	474,252	St Leonards	SL038071
MOT Travel Time							
Unplanned Repair	21/11/2022	13:25	21/11/2022	14:55	476,245	St Leonards	SL038187
86 Sliding Door 71 Body External Steps		Not closing. Adjusted all cables, tightened locks to door, resecured lock mech. Step not deploying, Straightened brackets					

Breakdown	12/12/2022	07:53	13/12/2022	05:45	480,413	St Leonards	SL038426
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	windscreen wiper not ejecting water	
02 Windscreen Wipers	Washer jets inop	Monitoring
001 Recover Vehicle	Vehicle Recovery	

SAFETY INSPECTION	14/12/2022	10:00	14/12/2022	10:00	480,413	St Leonards	SL038459
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	14/12/2022	10:00	26/12/2022	08:00	480,413	St Leonards	SL038460
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
17 Tyres Tracking	Tracking to be done. Gauges not working
02 Windscreen Wipers	Washer jets inop. Replace check valve
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
Axle Oil Change	Axle Oil Change
Engine Change Oil & Filter	Done.
15 Steering 1	Rack ends worn.
13 Brakes 1	Front disc's & pads worn.
13 Brakes 2	Rear disc's & pads worn and calipers x2
Wheel Hub Flanges Replacement	Poor condition. Replaced all.
17 Tyres Replace	Replace 2x front tyres
44 Fuel System 1	Replace fuel cap
71 Body Exterior 1	Replace metal spray flap bracket
34 Lighting System	Replace 2x headlamps and headlamp adjuster wheel
71 Body External Steps	Replaced
86 Doors	Drivers and passenger door seals worn
34 Emergency Light System	N/S/F Wing E.M.G Fault. Replace with new
89 Seatbelts	N/S/F Seatbelt U/S.. Remove N/S Seat & all trims. Repair slides & belt operati
71 Body Exterior 2	Replace N/S/F lower body cap.
86 Sliding Door	Door U/S.
45 Engine 1	Replace viscous fan
13 Brake Test	Telma n/w.

Monitoring

Vehicle Deep Clean	26/12/2022	07:00	26/12/2022	16:00	480,413	St Leonards	SL038586
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	27/12/2022	18:02	28/12/2022	12:30	480,490	St Leonards	SL038607
Breakdown	side door wont stay shut						
86 Sliding Door	Side door fault secure top lock & adj catch, adj rear door cables.						
Travel Time							
BREAKDOWN	30/12/2022	14:25	30/12/2022	17:09	480,587	St Leonards	SL038649
86 Sliding Door	Sliding door coming open when pushed from inside						
Travel Time	Travel from Dorchester to Ferndown workshop						
ACCIDENT	08/01/2023	08:15	08/01/2023	08:30	481,956	St Leonards	SL038740
02 Mirrors	Replace smashed n/s mirror glass						
SAFETY INSPECTION	23/03/2023	14:00	24/03/2023	09:30	494,859	St Leonards	SL039469
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
86 Doors	Drivers and passenger door seals worn						
54 Warn Dev/System	Emg Warning Devices SIRENS INTERMITTENT HORN NOT WORKING						
Tail Lift Inspection	Done.						
02 Cab Assembly 1	Interior light n/w. Replaced bulb.						
34 Emergency Lights	O/S grill blue not strobbing. Replaced light.						
52 Electrical Aux	230v w/lights broken.No Parts.						
56 Comms Equipment	Aerial missing from roof. Replaced.						
02 Windscreen	Small chips.						
02 Pipeline Annual Inspection	23/03/2023	13:31	23/03/2023	13:34	494,859	MDT Ferndown	TF002588
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - Replaced cracked changeover gauge.						

Vehicle Deep Clean	27/03/2023	08:00	28/03/2023	13:28	494,861	St Leonards	SL039499
--------------------	------------	-------	------------	-------	---------	-------------	----------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	02/04/2023	11:30	03/04/2023	09:08	496,087	St Leonards	SL039567
------------------	------------	-------	------------	-------	---------	-------------	----------

45 Engine 1	Fumes in cab. (SEE NOTES)
45 Engine 2	EML various stored codes, relating to maf/air temp. relearned sensors. rtest. ok

Unplanned Repair	06/04/2023	10:00	06/04/2023	14:40	496,340	St Leonards	SL039613
------------------	------------	-------	------------	-------	---------	-------------	----------

45 Engine 1	EML/LOP. lambda fault found. Replaced and re learnt
-------------	---

SAFETY INSPECTION	24/04/2023	07:30	25/04/2023	11:35	498,293	St Leonards	SL039859
-------------------	------------	-------	------------	-------	---------	-------------	----------

18 Wheels Check Torques	
Safety Inspection	
02 Windscreen	Chips in windscreen
Tail Lift Inspection	
13 Handbrake	Handbrake excess travel. adjust shoes and cables.
01 Air Conditioning 1	Saloon AC fan seized. replaced fan and 20amp fuse
16 Suspension 1	Rear anti roll bar drop link bushes worn. replaced x4.
16 Suspension 2	Rear spring buffer x1 split. replaced
13 Brakes 1	Rear caliper slider seized causing pad uneven wear. replaced pads
13 Brakes 2	NSF caliper slider seized. freed off and lubed.
02 Cab Assembly 1	Brake pedal rubber worn. replace
55 Tail Lift	Bridge plate guides loose. resecured.
71 Body Exterior 1	Charge flap cover broken. replace cover
34 Lights	NSF Upper marker light led's out and lens loose
34 Emergency Lights	ns scene light u/s. replaced

Monitoring

Vehicle Deep Clean	26/04/2023	06:17	26/04/2023	14:41	498,293	St Leonards	SL039891
--------------------	------------	-------	------------	-------	---------	-------------	----------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	02/05/2023	12:54	02/05/2023	13:04	498,300	St Leonards	SL039975
------------------	------------	-------	------------	-------	---------	-------------	----------

02 Windscreen 17 Tyres	Chips in windscreen rears low						
Unplanned Repair	08/05/2023	08:13	08/05/2023	12:11	498,300	St Leonards	SL040034
45 Engine 1 13 Brakes 1 Travel Time	EML/LOP...EGR valve replaced TELMA inop. replaced telma control box. travel to dorchester station. check veh and bring back to ferndown						
SAFETY INSPECTION	08/06/2023	06:08	08/06/2023	13:52	499,202	St Leonards	SL040460
18 Wheels Check Torques Safety Inspection UB Fire Supp 6mts Service Pollen Filter Change Tail Lift Inspection MOT 85 Body Interior 1 86 Sliding Door 43 Exhaust System 1 86 Door Seals	UB Fire Supp 6mts Service Pollen Filter Change AVP clips Upper door catch damaged Rear exhaust rubber cotton reel broken Drivers door seal sprit - parts on back order						
Vehicle Deep Clean	09/06/2023	11:00	11/06/2023	10:00	499,202	St Leonards	SL040483
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	16/06/2023	08:56	16/06/2023	12:39	501,560	St Leonards	SL040589
Breakdown 31 Battery Chassis	Wont start Test & replace chassis battery.						
Replace Vehicle Fuel Card	07/07/2023	18:00	07/07/2023	18:00	504,639	St Leonards	SL040911
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						

SAFETY INSPECTION	19/07/2023	06:00	19/07/2023	16:00	505,993	St Leonards	SL041144
18 Wheels Check Torques							
Safety Inspection							
86 Door Seals			Drivers door seal sprit - parts on back order				
Engine Change Oil & Filter							
55 Tail Lift			Tail lift manual hand controls seized.				
87 - Stretchers/Chairs/Boards			Stretcher belts wrongly fitted causing jamming to main head tilt mechanisms.				
02 Cab Assembly 1			Cab center consol catch & knob missing & stuck in closed position.				
13 Brakes 1			Cab handbrake travel becomming excessive.				
18 Wheels			O/S/R/O Wheel rim cracked around stud holes.				
16 Suspension 1			O/S/R Leaf spring front buffer excessively worn & split.				
16 Suspension 2			N/S/R Leaf spring front buffer excessively worn & split.				
Tail Lift Inspection			Carry out inspection.				
13 Brake Test			Carry out brake test.				
Vehicle Deep Clean	20/07/2023	09:30	21/07/2023	10:00	505,993	St Leonards	SL041172
Vehicle Deep Clean			Vehicle Deep Clean				
Breakdown	28/07/2023	12:48	31/07/2023	15:06	505,993	St Leonards	SL041311
Breakdown			dashboard not showing trouble starting				
Unplanned Repair	18/08/2023	09:45	18/08/2023	10:09	508,104	St Leonards	SL041578
31 Battery Aux			Batts U/S				
SAFETY INSPECTION	28/08/2023	07:25	29/08/2023	16:00	509,145	St Leonards	SL041710
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 12mts Service			Service of fire supression system				
13 Handbrake			Handbrake excess travel. adjust shoes and cables.				
02 Cab Assembly 1			Cab interior bulb blown. replace bulb.				

13 Brakes 1	Front brake pads and discs worn. replace kit.						
85 Body Interior 1	Sliding door inner window insecure. replace window and blind assembly.						
85 Body Interior 2	Underseat BH locker door damaged. repair locker door.						
85 Body Interior 3	Rear door chair mount loose. resecure chair mount to rear door.						
Vehicle Deep Clean	29/08/2023	13:00	30/08/2023	10:00	509,145	St Leonards	SL041733
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	08/09/2023	20:13	09/09/2023	07:15	509,600	St Leonards	SL041871
Breakdown	MDT/vehicle Radio No Power Going To Them						
Unplanned Repair	22/09/2023	14:15	22/09/2023	15:15	510,597	St Leonards	SL042062
56 Comms Power Failure	Comms power failing. Replace comms battery						
Unplanned Repair	29/09/2023	12:08	29/09/2023	12:15	511,246	St Leonards	SL042135
34 Lights	N/S Indicator not working						
BREAKDOWN	28/09/2023	06:00	28/09/2023	06:30	511,059	St Leonards	SL042223
86 Sliding Door	N/S Sliding door not opening from outside.						
Vehicle Deep Clean	07/10/2023	13:04	09/10/2023	11:45	511,302	St Leonards	SL042254
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/10/2023	06:00	10/10/2023	13:17	511,302	St Leonards	SL042289
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						

56 Comms Power Failure	Comms Power Check MDT screen blank	
86 Sliding Door	Doors SIDE DOOR CAN ONLY OPEN FROM THE INSIDE	
Tail Lift Inspection	Done.	
Air Filter Change	Air Filter Change. Done.	
Fuel Filter Change	Change Fuel Filter. Done.	
Recall Notification	Mercedes airbag recall. Done.	
55 Tail Lift	O/S gate loose. Tightened.	
52 Electrical Aux	Inverter n/w.Checked & replaced.	
85 Body Interior 1	230V w/lights broken.No parts.	Monitoring
86 Door Lock	Rear door lock n/w.Replace barrel housing.	

Unplanned Repair	18/10/2023	08:00	18/10/2023	10:35	512,601	St Leonards	SL042412
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

89 Seats	Seat base torn on rear swivel chair. Replaced
----------	---

Unplanned Repair	25/10/2023	18:47	26/10/2023	16:05	512,801	St Leonards	SL042502
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

56 Comms Equipment	MDT inop and not tracking
--------------------	---------------------------

MOT	13/11/2023	07:00	13/11/2023	16:30	514,470	St Leonards	SL042761
------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

MOT	
Travel Time	

SAFETY INSPECTION	20/11/2023	13:24	22/11/2023	12:48	514,646	St Leonards	SL042861
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	
85 Body Interior 1	Various locker doors repaired.
85 Body Interior 2	Saloon glove rack end stop fitted.
52 Electrical Aux	Inverter socket outled led's damaged. replaced.
34 Lights	NSR Upper tail/brake light led's faulty. replaced lamp.

13 Brakes 1	NSF Brake caliper sliders seized. replaced slider kit.					Monitoring
13 Brakes 2	Telma plates rubbing. all operating ok.					
Vehicle Deep Clean	Vehicle Deep Clean					
Breakdown	its not moving					
27 Transmission Automatic	Loss of drive - Rygor Westbury to repair					
002 Major Unit Replace Gearbo	Replaced by Rygor Westbury					
Vehicle Deep Clean	Vehicle Deep Clean					
SAFETY INSPECTION	Indicator out					
18 Wheels Check Torques	Checked.					
Safety Inspection	Carried out inspection.					
85 Body Interior 1	Done.					
13 Brakes 2	O/S/F side marker dim. Replaced.					
Brake Fluid Change	Passenger window switch broken. Replaced.					
UB Fire Supp 6mts Service	Auto-eject cover broken. Rep[laced.					
71 Body Exterior 1						
Unplanned Repair						
34 Lights						
SAFETY INSPECTION						
18 Wheels Check Torques						
Safety Inspection						
Tail Lift Inspection						
34 Lights						
02 Cab Assembly 1						
31 Charging System						

55 Tail Lift	Tilt sensor n/w. Replaced multi-plug & replaced sensor.
--------------	---

Vehicle Deep Clean	19/02/2024	06:25	19/02/2024	12:02	519,545	St Leonards	SL044040
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	28/02/2024	16:49	28/02/2024	17:36	519,640	St Leonards	SL044197
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

31 Battery Aux	Other Inverter problem - alarm sounding
----------------	---

Breakdown	20/03/2024	02:09	20/03/2024	08:00	520,484	St Leonards	SL044492
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	REAR Door retailing bar broken
-----------	--------------------------------

Vehicle Deep Clean	27/03/2024	15:10	29/03/2024	04:54	524,454	St Leonards	SL044618
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	29/03/2024	12:58	30/03/2024	11:10	524,455	St Leonards	SL044665
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.
Safety Inspection	Carried out inspection.
Annual Heater Service	Annual Heater Service. Replaced exhaust. See notes.
Tail Lift Inspection	Done.
Engine Change Oil & Filter	Done.
34 Lights	O/S/F spot light broken. Replaced.
85 Body Interior 1	Shelf front adrift. Secured.
02 Cab Assembly 1	Bonnet soundproofing hanging down. Resecured.
45 Engine 1	EML on. Checked & replaced Nox sensor 1.

Breakdown	02/04/2024	03:10	02/04/2024	14:08	524,830	St Leonards	SL044715
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Crew think A/C gone and fume smells
-----------	-------------------------------------

Unplanned Repair	30/04/2024	13:28	30/04/2024	14:57	525,106	St Leonards	SL045106
86 Doors Rear 02 Windscreen Wipers	Bottom catch u/s. washer inop						
Vehicle Deep Clean	08/05/2024	11:16	09/05/2024	09:00	529,098	St Leonards	SL045227
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/05/2024	08:00	10/05/2024	18:00	529,098	St Leonards	SL045258
18 Wheels Check Torques Safety Inspection Tail Lift Inspection 42 Coolant System 55 Tail Lift 11 Axle Rear 02 Windscreen Wipers 85 Body Interior 1 16 Suspension 1 16 Suspension 2 87 - Stretchers/Chairs/Boards 87 Stretcher	O/S Coolant hose leaking Tail lift side rails fixings insecure Rear axle leak Windscreen washer jets not working Saloon N/S/R seat arm rest insecure O/S/R Leaf spring buffer broken Rear lower antiroll bar drop link bushes worn Stretcher belts in wrong positions Carry chair leg harness broken						
02 Pipeline Annual Inspection	14/05/2024	12:12	14/05/2024	12:14	529,098	MDT Ferndown	TF003487
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - No faults found.						
Breakdown	10/06/2024	05:16	10/06/2024	16:53	529,098	St Leonards	SL045695
Breakdown Forced DPF Regeneration	stuck low gear burning smell in cab See Notes. Carry Out Forced DPF Regeneration						

Breakdown	13/06/2024	03:32	14/06/2024	12:12	529,098	St Leonards	SL045746
------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Breakdown	Amber EML and Limp mode
Travel Time	Travel to and from christchurch ambulance station
43 Exhaust System 1	DPF blocked and will not regen. DPF system clean required
Road Test	Extended road test to force regen

SAFETY INSPECTION	22/06/2024	12:00	27/06/2024	12:52	529,500	St Leonards	SL045922
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	Checked.	
Safety Inspection	Carried out inspection.	
Annual Air Con Service	Annual Air Condition Service. Done.	
02 Cab Assembly 1	Drivers door inner panel adrift. Resecured.	
34 Emergency Lights	Long lens across rear missing. O/S top corner blue smashed.	
86 Door Seals	O/S door seal split. Replaced.	
41 Air Intake	Leaking oil @ resinator. Replaced seals & washed.	
45 Engine 1	Rear main oil seal leaking.	Monitoring
43 Exhaust System 1	DPF smelling. See history. Removed DPF. -See notes: RS	
13 Brakes 1	Front pads worn unevenly, caliper slider siezed. Replaced disc's,pads & slider.	
13 Brakes 2	Rear disc's & pads worn. Replaced.	
Wheel Hub Flanges Replaceme	Poor condition. front & rear. Replaced x4.	
17 Tyres Replace	Fronts x2, N/S/R/O,O/S/R/I. low tread. Replaced.x4.	

Vehicle Deep Clean	25/06/2024	13:54	26/06/2024	12:15	529,500	St Leonards	SL045968
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	20/07/2024	11:00	20/07/2024	11:30	538,628	St Leonards	SL046423
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

86 Doors Rear	Replace rear door stay and mount
---------------	----------------------------------

SAFETY INSPECTION	27/07/2024	05:49	28/07/2024	08:27	538,628	St Leonards	SL046569
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques
Safety Inspection

Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	
17 Tyres	Two rear tyres worn low. Replaced
86 Sliding Door	Door magnet insecure and not making contact.

Vehicle Deep Clean	29/07/2024	07:30	29/07/2024	15:33	539,017	St Leonards	SL046592
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	22/08/2024	14:00	23/08/2024	16:00	543,491	St Leonards	SL046927
-------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

71 Body External Steps	Side step smashed off. Replace step. Second hand step fitted
------------------------	--

SAFETY INSPECTION	12/09/2024	09:47	12/09/2024	16:00	543,587	St Leonards	SL047273
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
45 Engine 1	Rear main oil seal leaking.
71 Body Exterior 1	Body Exterior Scuff to plastic outer casing on O/S wing mirror
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
UB Fire Supp 12mts Service	Service of fire suppression system
02 Windscreen Wipers	Replace wiper blades
85 Body Interior 1	Replace CCTV cupboard gas struts
86 Door Lock	Free off seized rear door lock
71 Body Exterior 2	Secure rear mud flap
85 Body Interior 2	Replace large saloon draw and swap runners. Secure document holder

Vehicle Deep Clean	16/09/2024	06:56	17/09/2024	07:11	544,626	St Leonards	SL047329
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	09/10/2024	15:01	09/10/2024	15:06	544,626	St Leonards	SL047665
15 Steering 1 45 Engine Ad Blue	Steering wheel worn. Replaced wheel and bolt. Top up						
Unplanned Repair	11/10/2024	13:12	11/10/2024	14:36	544,699	St Leonards	SL047700
15 Steering 1 42 Radiator	Pump u/s. Replaced pump, filled and bled system. road tested all ok. Radiator leaking ns lower corner - Monitor until next inspection						Monitoring
SAFETY INSPECTION	17/10/2024	16:19	22/10/2024	13:00	544,700	St Leonards	SL047817
18 Wheels Check Torques Safety Inspection 42 Radiator Tail Lift Inspection Engine Change Oil & Filter Pollen Filter Change MOT Replace Handbrake Cables 15 Steering 1 16 Suspension 1 15 Steering 2 45 Engine 1 41 Air Intake 55 Tail Lift 85 Body Interior 1 02 Glass / Windows 02 Windscreen	Checked. Wrong milage-549163. Carried out inspection. Radiator leaking ns lower corner -Replaced Radiator. Done. Done. Pollen Filter Change. Done. Replace Handbrake Cables. Done. O/S rack end loose/clip missing from gaitor. Front struts worn. Lower ball joints worn. Rear main oil seal leaking. N/S intercooler hose leaking.Replaced. Guide blocks adrift, Bridge plate damaged, N/S gate siezed down. Repaired all. Strap for tracks broken. Replaced. Drivers window switch broken. Replaced. Chipped.						Monitoring
Vehicle Deep Clean	23/10/2024	07:30	23/10/2024	15:13	545,228	St Leonards	SL047915
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	30/10/2024	03:49	30/10/2024	07:00	545,228	St Leonards	SL048008
Breakdown	Headlight Out						

Breakdown	23/11/2024	06:40	26/11/2024	16:52	545,999	St Leonards	SL048351
Breakdown	side steps faulty						
71 Body External Steps	Side step inop						
34 Lights	O/S/R fog light and reflector damaged						
71 Body Exterior 1	O/S/R lower quarter covering smashed & tail lift guide bracket smashed						

Vehicle Deep Clean	04/12/2024	17:06	05/12/2024	12:28	548,874	St Leonards	SL048526
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	06/12/2024	14:01	07/12/2024	11:09	548,875	St Leonards	SL048553
18 Wheels Check Torques	Checked.						
Safety Inspection	Carried out inspection.						
02 Windscreen	Chipped.						
34 Lights	Lighting System Two light in OSR got damaged near reversing						
Accident	Body Exterior O/S/R light damaged						
71 Body External Steps	Doors side step stuck in.Straightened frame.						
56 Comms Power Failure	Comms Power Check MDVS Not connecting to router.reset.						
Tail Lift Inspection	Done.						
01 Air Conditioning 1	Saloon condensor fan siezed.Replaced.						
42 Coolant System	Anti-freeze weak.Added 4Ltrs.						
Install Saloon CCTV Camera	N/S/F camera dome smashed. Replaced.						
45 Engine Oil Top Up	Topped 1Ltr.						
34 Lights Bulb Replacement	N/S/F top marker light broken. Replaced.						

Monitoring

Unplanned Repair	21/12/2024	06:00	21/12/2024	07:22	549,361	St Leonards	SL048753
01 Heating 1	Saloon heating in cab not working. Blower motor replaced						

Breakdown	26/12/2024	23:34	27/12/2024	07:00	550,687	St Leonards	SL048836
Breakdown	AC power Alarm/Smoke and smell of burning Back						

34 Emergency Lights	Rear N/S Scene light electrical fault. replaced light unit.
44 Add Ad Blue	20L

Vehicle Deep Clean	15/01/2025	08:42	15/01/2025	11:38	558,149	St Leonards	SL049115
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	22/01/2025	15:47	24/01/2025	07:30	558,149	St Leonards	SL049203
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
86 Sliding Door	Sliding door bearings worn. replaced bearings.
55 Tail Lift	-Tilt switch inop. Replaced tilt switch. -Bridge plate guides resecured.
15 Steering 1	PAS Hose from reservoir to cooler leaking. replaced
17 Tyres Replace	Front tyres worn on edges. Replaced x2.
13 Brakes 1	Rear sliders seized. freed off and lubricated.
13 Brakes 2	Front pads worn low. Replaced pads.
85 Body Interior 1	Sliding locker runners, rh locker shelf and whiteboard all inescure. resecured
A/C Service	A/C Service
17 Tyres Tracking	Tracking check and adjusted front toe.

Vehicle Deep Clean	05/03/2025	07:09	06/03/2025	08:06	564,177	St Leonards	SL049790
---------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	08/03/2025	06:00	08/03/2025	15:13	564,299	St Leonards	SL049837
--------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	
18 Wheels Check Torques	
Road Test	

Tail Lift Inspection
 13 Brake Test
 86 Sliding Door N/S Side door upper check strap magnet bent
 55 Tail Lift Tail lift side rails bolt missing
 85 Body Interior 1 Saloon N/S/F seat arm rest broken
 87 - Stretchers/Chairs/Boards Stretcher wheel yolk brake cams require adjusting

02 Pipeline Annual Inspection **21/03/2025** **12:59** **21/03/2025** **13:00** **565,950** **MDT Ferndown** **TF004038**

02 Pipeline Annual Inspection Annual Inspection and Pressure Test - passed all tests.

Unplanned Repair **27/03/2025** **08:11** **27/03/2025** **08:13** **566,276** **St Leonards** **SL050088**

86 Sliding Door Upper catch not latching and warning going ogg

SAFETY INSPECTION **27/04/2025** **08:00** **27/04/2025** **16:00** **568,941** **St Leonards** **SL050609**

Check MDVS for Update Check and Install MDVS windows update
 Safety Inspection
 18 Wheels Check Torques
 Road Test
 Tail Lift Inspection
 85 Body Int Alcohol Gel Dispen
 Annual Heater Service Annual Heater Service
 UB Fire Suppression Discharge Under Bonnet Fire Suppression 5 Year Discharge Test
 17 Tyres Replace Replace OSR tyres due to low tread

Vehicle Deep Clean **28/04/2025** **13:49** **29/04/2025** **11:35** **568,947** **St Leonards** **SL050630**

Vehicle Deep Clean Vehicle Deep Clean

ACCIDENT **02/05/2025** **20:04** **05/05/2025** **11:20** **568,990** **St Leonards** **SL050723**

Breakdown MULTIPLE WARNINGS ON DASH - Alternator fault Replaced Alternator
 34 Emergency Lights NSR Blue light missing. Replaced lens

BREAKDOWN	12/05/2025	15:00	13/05/2025	08:40	569,948	St Leonards	SL050919
86 Doors Rear	O/S/R Door catch not releasing & jammed						
Breakdown	13/05/2025	14:42	14/05/2025	06:01	569,998	St Leonards	SL050927
Breakdown	3x chip in windscreen 10mm						
Breakdown	25/05/2025	16:35	26/05/2025	09:26	569,998	St Leonards	SL051177
Breakdown	Non starter						
Unplanned Repair	30/05/2025	09:00	02/06/2025	13:57	571,236	St Leonards	SL051275
34 Emergency Lights 42 Coolant System	Body Exterior N/S rear blue light requires new cover.Replaced lamp. Coolant warning light on. Replaced radiator.						