Condition Report



Vehicle Identification

Registration	BG15OOU	Lot Number 322
Make		ISUZU
Model		D-MAX E/C TWIN TURBO TD
Туре		Pick-up
Date of Registration		31/03/2015
Miles / KMs / Hours		144,051 miles - Warranted
MoT Expires		31/08/2025
V5		V5 here
Service History		Yes - Service Number: 8 - Service Date: 13/08/2024
CAP Values		Clean: £3,975.00, Average: £3,275.00, Poor: £2,350.00
Engine		OK
Transmission		OK
Gearbox / Clutch		ОК
Suspension		OK
Steering		OK
Brakes		OK
Tyres		Medium
Interior		Holes/Missing items
General Condition		Requires attention (Bodyshop repairs)
General Comments		All panels chipped and scratched, some panels dented, light corrosion, wheels in need of refurbishment, interior soiled, MOT fail

Images













1 of 3 7 Oct 2025 13:56

Condition Report

Brightwells Est. 1846

Vehicle Identification

Registration BG1500U

Lot Number


322



Condition Report

Brightwells

Vehicle Identification



Items in this auction are all sold as seen and without warranty, which means there is no guarantee of the following (but not limited to): condition, working condition, description, volumes, hours, mileages, testing, condition reporting, mechanics, electrics, bodywork, parts, spares, paperwork, completeness or fitness for use.

Condition reports are prepared on the "Inspection Date" and it is entirely possible that an item's condition or working ability may change after the date we have inspected it. Brightwells do not accept any responsibility for errors, misstatements or omissions within the condition report. Any repair and refurbishment prices are estimates only. Some parts may be missing from the item and if the item is described as not working or a non-runner, this is highly likely. We strongly advise that prospective buyers come to our site and view the items.

3 of 3 7 Oct 2025 13:56