

VX11GXE	A&E		Staverton Amb Stn				
Chk W/Nuts for Security	14/01/2014	12:19	14/01/2014	15:45	126,496	Gloucester	GC000008
Chk W/Nuts Security & Tightnes							
Fit FRAP Tax Disc Holder	23/09/2015	11:13	23/09/2015	11:14	202,416	Unallocated	Un000504
Veh Deep Clean	10/11/2015	11:58	16/11/2015	11:59	208,084	Gloucester	GC000056
Vehicle Deep Clean Vehicle Deep Clean							
Unplanned Repair	16/11/2015	15:02	17/11/2015	10:37	209,039	Gloucester	GC000071
55 Tail Lift fit new pipes							
Gearbox Oil & Filter Change	24/11/2015	12:54	26/11/2015	16:31	210,109	Gloucester	GC000139
13 Brakes 1 adjust hand brake shoes &cable 15 Steering 1 near side rack end 17 Tyres Replace 3 rear ats 17 Tyres Tracking 34 Lights replace torch 43 Exhaust System 1 fit clips to heat shield 55 Tail Lift loler test 71 Body External Steps fit mud flap 85 Body Interior 1 fit rear door step lights 85 Body Interior 2 fit retaining strap 86 Door Hinges adjust & reset drivers door 86 Door Lock rear door servo assy 89 Seats adjust safty catches Gearbox Oil & Filter Change make dip stick bracket Road Test							

Wheel Studs & Nuts Replaceme
 Annual Air Con Service Annual Air Condition Service
 Annual Heater Service Annual Heater Service
 93 - D Service
 Service D
 18 Wheels Check Torques
 Safety Inspection

Veh Deep Clean	17/12/2015	11:23	17/12/2015	11:25	212,959	Gloucester	GC000263
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	17/12/2015	16:34	18/12/2015	13:45	212,971	Gloucester	GC000268
71 Body Exterior 1	check doors and door locking after defect reported no fault faund						
BREAKDOWN	13/12/2015	13:02	13/12/2015	15:00	212,660	Gloucester	GC000415
31 Battery Chassis	Non starter - AA assistance required						
Breakdown	25/12/2015	23:07	25/12/2015	23:30	214,449	Gloucester	GC000289
Breakdown	flat tyre - front right						
Unplanned Repair	28/12/2015	09:03	28/12/2015	11:00	214,844	Gloucester	GC000297
33 Ignition System	key battery						
Unplanned Repair	30/12/2015	09:49	30/12/2015	11:00	214,915	Gloucester	GC000298
17 Tyres Replace	one replace one repair						
Breakdown	15/01/2016	09:18	16/01/2016	13:19	217,427	Gloucester	GC000394
Breakdown	rear heater not working						

BREAKDOWN	15/01/2016	14:58	18/01/2016	12:11	217,428	Gloucester	GC000400
01 Heating 1	at staverton carry out code read 31 /33/12.						
Breakdown	18/01/2016	04:38	18/01/2016	13:20	217,631	Gloucester	GC000407
Breakdown	wont start						
BREAKDOWN	18/01/2016	12:17	19/01/2016	13:09	217,691	Gloucester	GC000412
31 Battery Chassis Travel Time	check battery and charge rate of vehicle collect from stroud station						
Unplanned Repair	27/01/2016	10:59	27/01/2016	11:02	218,648	Gloucester	GC000495
31 Battery Chassis	Engine full loss of power, able to resart. AA attended.						
Veh Deep Clean	05/02/2016	13:04	05/02/2016	13:05	220,129	Gloucester	GC000573
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	11/02/2016	15:34	16/02/2016	13:10	220,990	Gloucester	GC000621
02 Windscreen Wipers	repair washers						
13 Brakes 1	replace front & rear pads						
16 Suspension 1	anti roll bar bushes						
17 Tyres Replace							
18 Wheels Check Torques							
45 Engine 1	idler pulley						
71 Body Exterior 1	fit call sign to bonnet						
85 Body Interior 1	tool box cover						
86 Doors	rear cupborad broken repair						
87 Chairs							
87 Stretcher Harness Replaced	replaced with used						

89 Seats o/s seat base
 Safety Inspection
 Wheel Hub Flanges Replacemereplace studs & nuts
 Tail Lift Inspection

SAFETY INSPECTION 16/02/2016 13:29 16/02/2016 13:30 220,990 Gloucester GC000647

18 Wheels Check Torques
 Safety Inspection

Breakdown 17/02/2016 00:37 18/02/2016 14:37 221,122 Gloucester GC000651

Breakdown LOP EML juddering

BREAKDOWN 14/03/2016 09:19 15/03/2016 07:51 224,494 Gloucester GC000809

02 Windscreen Wipers Other Windscreen wipers are worn. Need changing
 34 Lights

Veh Deep Clean 14/03/2016 10:40 14/03/2016 10:41 224,494 Gloucester GC000810

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 24/03/2016 06:33 29/03/2016 15:17 225,842 Gloucester GC000878

02 Windscreen Wipers fit new wipers
 13 Brakes 1 fit pedal rubber
 18 Wheels Retorque
 34 Lights Bulb Replacement fit front indicator bulbs
 55 Tail Lift check clean & lube
 71 Body External Steps repairs to s/step
 Breakdown EML on Limp mode do regen & road test ok
 Safety Inspection

SAFETY INSPECTION	04/04/2016	11:23	04/04/2016	11:25	225,852	Gloucester	GC000925
18 Wheels Check Torques Safety Inspection							
Veh Deep Clean	20/04/2016	15:02	21/04/2016	15:04	228,674	Gloucester	GC001042
Vehicle Deep Clean	Vehicle Deep Clean						
BREAKDOWN	22/04/2016	08:41	22/04/2016	10:32	228,829	Gloucester	GC001047
34 Emergency Lights 54 Sirens 55 Tail Lift 71 Body Exterior 1	defect / blue led windscreen light / check no fault found defect / repair & mod switch for bull horn defect / fit remote cable Other va						
Breakdown	23/04/2016	14:29	23/04/2016	15:00	228,901	Gloucester	GC001054
Breakdown	EM light on limp mode						
Breakdown	23/04/2016	22:25	25/04/2016	14:21	228,944	Gloucester	GC001056
45 Engine 1 Breakdown	bring in from staverton check codes & replace mass air flow . EML on loss of power						
Breakdown	01/05/2016	17:55	02/05/2016	09:25	229,637	Gloucester	GC001099
71 Body Exterior 1 Breakdown	damage to n/s fog lamp & bumper. 932 Nearside headlight out						
SAFETY INSPECTION	09/05/2016	14:17	11/05/2016	09:48	230,708	Gloucester	GC001136
16 Suspension 1 18 Wheels Check Torques 19 Chassis 1 34 Lights Road Test	fit new n/s lower suspension arm repair & mod rear mud flap bracket repair & refit n/s/f fog light mount road test						

Safety Inspection
Tail Lift Inspection
Travel Time
MOT
Handbrake Cable Replacement Replace rear handbrake cables
92 - C Service
Service C

BREAKDOWN	16/05/2016	14:52	19/05/2016	16:00	230,962	Gloucester	GC001183
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	Other A/C blowing hot air
34 Lights	Lighting System 932 Fog light loose
45 Engine 1	eml flashing.A/C & CAMRA.
54 Reversing Systems	Other Reversing camera doesn't work

Veh Deep Clean	20/05/2016	14:56	20/05/2016	14:57	230,976	Gloucester	GC001223
-----------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	25/05/2016	13:16	26/05/2016	14:20	231,004	Gloucester	GC001254
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	up Grade CCTV get A/C pipe repaired F.O.C
52 Electrical Aux	
Travel Time	

Breakdown	09/06/2016	14:19	10/06/2016	10:30	232,896	Gloucester	GC001329
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	EML and lost power
-----------	--------------------

Breakdown	10/06/2016	22:12	14/06/2016	10:43	232,950	Gloucester	GC001336
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	carry out diagnostic test reset codes.Fit pressure sensor. check strap EML on limp mode
86 Door Hinges	
Breakdown	

BREAKDOWN	14/06/2016	22:00	14/06/2016	22:15	233,016	Gloucester	GC001351
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	Replace N/S headlight Bulb	H7					
----------------------------	----------------------------	----	--	--	--	--	--

SAFETY INSPECTION	20/06/2016	08:53	21/06/2016	14:14	233,780	Gloucester	GC001375
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	fit gromit in fire wall						
17 Tyres Replace							
18 Wheels Check Torques							
89 Seatbelts	rear n/s /front						
89 Seats	rear n/s/rear base						
Safety Inspection							
Travel Time							

Veh Deep Clean	21/06/2016	13:00	23/06/2016	13:01	233,797	Gloucester	GC001407
-----------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

BREAKDOWN	24/06/2016	08:30	24/06/2016	10:53	234,162	Gloucester	GC001415
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Test	noise when braking found to be front bumper bracket.						
---------------	--	--	--	--	--	--	--

Breakdown	06/07/2016	17:17	07/07/2016	07:15	235,453	Gloucester	GC001481
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	screw fell out reg plate						
-----------	--------------------------	--	--	--	--	--	--

Unplanned Repair	12/07/2016	09:59	12/07/2016	10:31	236,099	Gloucester	GC001512
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body Exterior 1	refit front number plate						
86 Doors Rear	o/s/r door stay pivot broken . replace parts as required						

BREAKDOWN	19/07/2016	09:24	21/07/2016	08:45	237,194	Gloucester	GC001549
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights	n/s indicator						
42 Coolant System	coolent light on & tank over field.						

Travel Time

Breakdown	28/07/2016	09:40	28/07/2016	12:40	238,075	Gloucester	GC001598
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

16 Suspension 1 Breakdown	suspension dropped on back axel						
------------------------------	---------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	04/08/2016	08:36	05/08/2016	14:21	239,175	Gloucester	GC001628
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	fronts						
18 Wheels Check Torques							
42 Coolant System	check for leaks.						
Safety Inspection							
Travel Time	bring in from staverton						
Tail Lift Inspection							

Veh Deep Clean	09/08/2016	12:18	09/08/2016	12:19	239,878	Gloucester	GC001659
-----------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Breakdown	15/08/2016	18:51	16/08/2016	12:04	240,665	Gloucester	GC001690
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	possible hydraulic fluid leak clean off , check for leaks						
Road Test							

Vehicle Deep Clean	08/09/2016	13:24	08/09/2016	13:25	242,869	Gloucester	GC001840
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

Unplanned Repair	14/09/2016	14:57	14/09/2016	15:01	243,444	Gloucester	GC001879
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

89 Seats Body Interior seat in rear in lock position

Breakdown 22/09/2016 01:46 23/09/2016 08:06 244,783 Gloucester GC001926

Breakdown drivers wing mirror held on with tape

Vehicle Deep Clean 24/10/2016 13:53 24/10/2016 13:55 246,954 Gloucester GC002157

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 25/10/2016 09:37 25/10/2016 09:38 246,961 Gloucester GC002163

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION 25/10/2016 09:38 28/10/2016 08:30 246,966 Gloucester GC002164

02 Mirrors fit o/s complete arm and n/s parts
02 Windscreen Wipers replace fronts
11 Axle Front clean flanges
11 Axle Rear clean flanges
13 Brake Test
13 Brakes 1 fit rear pads and discs
13 Brakes 2 fit front pads and discs,change brake fluid.
18 Wheels Check Torques
34 Lights Bulb Replacement fit saloon lamp bulb
45 Engine 1 slight noise on start up (drive plate?) Monitor.
71 Body Exterior 2 grille cracked
86 Doors replace passenger door switch
89 Seats fit n/s base and back,o/s back covers and foams.
Road Test
Safety Inspection
Tail Lift Annual Service Statutory Inspection and Weight Test
Wheel Studs & Nuts Replaceme
Remove Ventilator Brackets Remove Ventilator Brackets and Fill
Tail Lift Inspection fit o/s ram hose
93 - D Service
Service D

Monitoring
Awaiting Parts

BREAKDOWN	22/11/2016	09:31	01/12/2016	09:54	248,119	Gloucester	GC002429
27 Transmission Automatic	drive plate						
32 Starting System 1	new starter						
43 Exhaust System 1	replace DPF						
Breakdown	recover to rygor ,drive plate faulty.						
Vehicle Deep Clean	01/12/2016	00:00	01/12/2016	13:31	248,152	Gloucester	GC002506
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	04/12/2016	17:04	08/12/2016	14:12	248,281	Gloucester	GC002528
Breakdown	side step not go back in						
SAFETY INSPECTION	06/12/2016	13:41	08/12/2016	10:42	248,293	Gloucester	GC002550
18 Wheels Check Torques							
34 Lighting System	Body Interior light above sliding door out						
45 Engine 1	slight noise on start up (drive plate?) Monitor.done at RYGORS						
54 Reversing Systems	camra faulty needs replacing					Awaiting Parts	
55 Tail Lift	flap jamed						
71 Body Exterior 2	grille cracked						
71 Body External Steps	chain broken						
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Vehicle Deep Clean	12/01/2017	14:56	12/01/2017	15:00	251,256	Gloucester	GC002846
Vehicle Deep Clean	Vehicle Deep Clean						

Vehicle Deep Clean	18/01/2017	10:32	18/01/2017	10:35	251,538	Gloucester	GC002889
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	19/01/2017	11:51	23/01/2017	08:39	251,979	Gloucester	GC002895
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	replace both rear inner tyres	
18 Wheels Check Torques		
34 Emergency Light System	parts of front light bar inop	Awaiting Parts
34 Lights Bulb Replacement	replace o/s/r saloon light bulb	
42 Coolant System	SMALL LEAK ON RAD . STOP LEAK ADDED	Monitoring
45 Engine 1	SLIGHT OIL LEAK LOWER SUMP AREA	Monitoring
45 Engine Oil Top Up		
54 Reversing Systems	camra faulty needs replacing	Awaiting Parts
71 Body Exterior Acc Repair	repair damage to n/s/r wheel arch	
85 Body Interior 1	kick bin catches	
85 Body Interior 2	equipment retaining straps	
Safety Inspection		
Medical Device and Equip Chec		
Tail Lift Inspection		

Breakdown	27/01/2017	21:38	28/01/2017	11:23	252,376	Gloucester	GC002973
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	vehicle losing charge check charge rate & shore line charging . replace batt aux
Travel Time	

Vehicle Deep Clean	30/01/2017	11:00	30/01/2017	13:00	252,589	Gloucester	GC002981
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	14/02/2017	23:10	15/02/2017	11:53	255,034	Gloucester	GC003093
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

15 Steering 1	wear in steering rack and coloum joint	Monitoring
Breakdown	knocking steering	
Travel Time	take to w/shops	

Breakdown	25/02/2017	23:14	27/02/2017	07:13	257,251	Gloucester	GC003213
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights	replace n/s/f 501 bulb
Breakdown	sidelight and headlight u/s

SAFETY INSPECTION	27/02/2017	08:35	28/02/2017	07:44	257,284	Gloucester	GC003214
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

15 Steering 1	wear in steering rack and coloum joint
18 Wheels Check Torques	
34 Emergency Light System	parts of front light bar inop
34 Lighting System	o/s/r marker lamp not working
42 Coolant System	SMALL LEAK ON RAD . STOP LEAK ADDED
43 Exhaust System 1	tail pipe clamps & rubber mount.
45 Engine 1	SLIGHT OIL LEAK LOWER SUMP AREA
54 Reversing Systems	camra foulty needs replacing
Safety Inspection	
Travel Time	bring in from staverton

SAFETY INSPECTION	20/04/2017	09:05	24/04/2017	12:38	260,807	Gloucester	GC003650
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

16 Suspension 1	Wear in lower balljoints and shock absorbers	Monitoring
17 Tyres Replace		
18 Wheels Check Torques		
34 Lights	replace n/s headlamp cover	
42 Radiator	leaking	
71 Body External Steps	Corrosion in rear door step	Monitoring
87 Stretcher Harness Replaced	Other missing lap belt	
Road Test		
Safety Inspection		
UB Fire Suppression Service		
Gearbox Oil & Filter Change		
Handbrake Cable Replacement	Replace rear handbrake cables	
Tail Lift Inspection		
Travel Time		
MOT		

Vehicle Deep Clean	25/04/2017	08:22	25/04/2017	12:51	260,821	Gloucester	GC003678
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/05/2017	14:44	25/05/2017	12:36	262,859	Gloucester	GC003952
13 Brake Test							
16 Suspension 1	Wear in lower balljoints and shock absorbers						Monitoring
18 Wheels Check Torques							
56 Comms Equipment	Radio & Comm System CCTV in rear not working						Monitoring
71 Body External Steps	Corrosion in rear door step						Monitoring
85 Body Interior 1	incubator pump strap broken . strap replaced						
85 Body Interior 2	retainer for doors on oxygen cupboard broken away ,. refitted						
Road Test							
Safety Inspection							
UB Fire Suppression Service	NOT FITTED						
Fit Throw Lines & SOP							
Vehicle Deep Clean	26/05/2017	00:48	26/05/2017	05:49	262,871	Gloucester	GC003986
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	27/05/2017	08:16	27/05/2017	08:22	262,872	Gloucester	GC003996
85 Body Interior 1	travel to staverton station . replace defective fire extingher in cab						
Travel Time							
MGS Gas Storage Modifications	06/06/2017	13:40	06/06/2017	13:42	263,416	Gloucester	GC004079
MGS Gas Storage Modifications	MGS Gas Storage Modifications						
Breakdown	10/06/2017	13:40	13/06/2017	15:00	263,482	Gloucester	GC004135
34 Emergency Lights	replace osf scene light/ repair front dash lamp						
86 Sliding Door	needs new bottom catch						
Breakdown	Side door sticking						

BREAKDOWN	25/06/2017	15:02	25/06/2017	15:05	263,934	Gloucester	GC004257
86 Sliding Door Travel Time	outer handle not working . strip and repair collect and deliver to stav						
Vehicle Deep Clean	04/07/2017	23:29	05/07/2017	05:25	265,082	Gloucester	GC004318
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	05/07/2017	11:01	06/07/2017	12:35	265,093	Gloucester	GC004323
16 Suspension 1 17 Tyres Replace 18 Wheels Check Torques 24 Driveshaft 1 54 Reversing Systems 56 Comms Equipment 56 Comms Fitment 71 Body External Steps Safety Inspection UB Fire Suppression Service Tail Lift Inspection 92 - C Service Service C	Wear in lower balljoints and shock absorbers o/s/r outer tyre rear prop bolts loose . replaced bolts Reversing camera inoperative needs replacing Radio & Comm System CCTV in rear not working internal handset mounting broken Corrosion in rear door step NOT FITTED dismantle and tighten n/s handrail					Monitoring Monitoring Monitoring Awaiting Parts Monitoring	
Breakdown	08/07/2017	17:24	10/07/2017	09:38	265,256	Gloucester	GC004360
34 Lights Breakdown Travel Time	repace bulb and broken cover after officer attempt to change front grill loose. grill broken temp repair made collect and deliver to stav						
Unplanned Repair	24/07/2017	13:44	24/07/2017	13:50	265,296	Gloucester	GC004507
85 Body Interior 1	replace rear fire extingher						
Breakdown	09/08/2017	19:22	11/08/2017	13:03	268,217	Gloucester	GC004648

55 Tail Lift	repair bridge plate & guides
87 Stretcher	head end adjust ram
Breakdown	O/S/R outer flat
Travel Time	bring in from staverton

SAFETY INSPECTION	15/08/2017	12:52	17/08/2017	11:36	268,217	Gloucester	GC004691
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

16 Suspension 1	front shock absorbers slight wear	Monitoring
17 Tyres Replace	x2 nsr tyres replaced	
18 Wheels Check Torques		
55 Tail Lift	Flexi hoses starting to perish and split	Monitoring
85 Body Interior 1	interior light bulb replaced	
87 Stretcher	floor lock cover repair.	
Road Test	retorque wheels / brake test	
Safety Inspection		
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card	
UB Fire Suppression Service	NOT FITTED	
Annual Air Con Service	Annual Air Condition Service	
Annual Heater Service	Annual Heater Service	
Tail Lift Annual Service	Statutory Inspection and Weight Test	

Vehicle Deep Clean	15/08/2017	08:30	15/08/2017	14:02	268,217	Gloucester	GC004692
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

16 Suspension 1	Wear in lower balljoints and shock absorbers
54 Reversing Systems	Reversing camera inoperative needs replacing
56 Comms Equipment	Radio & Comm System CCTV in rear not working
56 Comms Fitment	internal handset mounting broken
71 Body External Steps	Corrosion in rear door step
Vehicle Deep Clean	Vehicle Deep Clean

Breakdown	02/10/2017	12:03	02/10/2017	14:02	270,530	Gloucester	GC005145
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	O/S wing mirror indicator light smashed
-----------	---

Vehicle Deep Clean	02/10/2017	21:29	03/10/2017	02:51	271,058	Gloucester	GC005156
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	06/10/2017	14:07	10/10/2017	13:03	271,068	Gloucester	GC005197
02 Cab Assembly 1	map light						
16 Suspension 1	front shock absorbers & lower ball joints worn					Monitoring	
18 Wheels Check Torques							
34 Lights	o/s indicator side repeater lamp broken						
45 Engine 1	Carry out Diag check & DPF Regen						
45 Engine Oil Top Up							
55 Tail Lift	Flexi hoses starting to perish and split					Monitoring	
71 Body Exterior Acc Repair	o/s/r corner cap damaged						
86 Sliding Door	Doors side door jammed						
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	09/11/2017	08:00	09/11/2017	13:00	272,738	Gloucester	GC005535
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	09/11/2017	15:36	10/11/2017	10:44	272,751	Gloucester	GC005539
02 Windscreen	stone chips o/s area					Monitoring	
13 Brakes 1	front and rear pads next inspection					Monitoring	
16 Suspension 1	front shock absorbers & lower ball joints worn					Monitoring	
17 Tyres	o/s/r inner replaced with a part worn tyre						
18 Wheels Check Torques							
55 Tail Lift	Flexi hoses starting to perish and split					Monitoring	
71 Body External Steps	corrosion in rear step					Monitoring	
86 Doors	repair equipment retainer side locker door						
Safety Inspection							
Breakdown	12/11/2017	15:12	14/11/2017	07:39	273,471	Gloucester	GC005567
Breakdown	scoop locker key snapped off in lock						
Travel Time	bring in from staverton						
Vehicle Deep Clean	20/12/2017	08:00	20/12/2017	13:00	276,190	Gloucester	GC005968

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	21/12/2017	10:48	22/12/2017	14:16	276,203	Gloucester	GC005975
13 Brake Test							
13 Brakes 1		replace front and rear discs and pads					
17 Tyres Replace		nsr outer has puncture					
18 Wheels Check Torques							
Safety Inspection							
Wheel Hub Flanges Replacemehub flanges and nuts replaced							
Tail Lift Inspection							
BREAKDOWN	26/12/2017	17:36	26/12/2017	17:37	276,594	Gloucester	GC006011
86 Sliding Door		outer handle jammed . free off and repair					
Emergency Deep Clean	29/01/2018	08:00	29/01/2018	11:00	278,778	Gloucester	GC006331
Emergency Deep Clean							
SAFETY INSPECTION	05/02/2018	09:21	06/02/2018	14:29	279,207	Gloucester	GC006399
02 Windscreen		stone chips o/s area					
02 Windscreen Wipers							
16 Suspension 1		front shock absorbers & lower ball joints worn					
16 Suspension 2		rear spring buffers					
18 Wheels Check Torques							
34 Lights		n/s/f cover.					
43 Exhaust System 1		weld exhaust bracket.					
71 Body External Steps		corrosion in rear step					
85 Body Interior 1		lock cover					
Safety Inspection							
Travel Time		take to staverton.					
85 Body Int Alcohol Gel Dispen							
Vehicle Deep Clean	06/02/2018	21:03	07/02/2018	01:51	279,224	Gloucester	GC006415

Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	24/02/2018	10:44	24/02/2018	10:48	280,240	Gloucester	GC006571
89 Seats	n/s/f adjusting wheel.						
Vehicle Deep Clean	16/03/2018	08:28	16/03/2018	12:04	280,989	Gloucester	GC006745
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	16/03/2018	15:09	19/03/2018	15:35	280,998	Gloucester	GC006753
02 Cab Assembly 1	replace defective handtorch						
17 Tyres Replace	clean hubs and wheels						
18 Wheels Check Torques							
87a - Medical Equipment Repair	mobility med check						
Safety Inspection							
Travel Time	bring in from staverton						
Tail Lift Inspection							
Handbrake Cable Replacement	Replace rear handbrake cables						
Unplanned Repair	23/03/2018	10:30	24/03/2018	07:48	281,087	Gloucester	GC006810
02 Mirrors							
Travel Time	repair at Staverton						
Breakdown	15/04/2018	23:58	17/04/2018	14:35	282,111	Gloucester	GC007002
43 Exhaust System 1	replace tail pipe.						
Breakdown	Exhaust						
Travel Time							
MOT							
Fit Poster Holder	Fit Poster Holder						
18 Wheels Check Torques							
Safety Inspection							

93 - D Service
Service D

Vehicle Deep Clean	23/04/2018	08:00	23/04/2018	12:41	282,323	Gloucester	GC007086
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	14/05/2018	08:03	14/05/2018	08:05	286,108	Swindon	SD004997
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	o/s/f side light
----------------------------	------------------

Vehicle Deep Clean	06/06/2018	08:00	06/06/2018	13:00	287,542	Gloucester	GC007523
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/06/2018	07:56	08/06/2018	07:44	287,557	Gloucester	GC007530
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	replace torch
11 Axle Front	clean both front flanges
13 Brake Test	
17 Tyres Replace	both fronts
18 Wheels Check Torques	
18 Wheels Removal	remove, clean & refit wheels
18 Wheels Retorque	retorque front wheels
31 Charging System	secure slave start
34 Lights	replace o/s mirror indicator unit
71 Body Exterior 1	tighten 2x saloon seat locking pin nuts
Safety Inspection	
Tail Lift Inspection	

SAFETY INSPECTION	17/07/2018	11:14	19/07/2018	15:08	289,109	Gloucester	GC007866
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers	Relace motor linkage assembly
16 Suspension 1	replace rear ARB link bushes
18 Wheels Check Torques	

85 Body Interior 1	fit o/s door window switch
87 Stretcher	Medical Devices stretcher Back not holding weight
Safety Inspection	
Tail Lift Annual Service	Statutory Inspection and Weight Test
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service
UB Fire Suppression Service	
Wheel Hub Flanges Replaceme	

Vehicle Deep Clean	19/07/2018	08:00	19/07/2018	13:39	289,122	Gloucester	GC007895
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	31/07/2018	05:40	31/07/2018	05:55	290,027	Gloucester	GC007997
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	Replace N/S headlight Bulb H7
----------------------------	-------------------------------

BREAKDOWN	15/08/2018	08:24	15/08/2018	15:30	291,866	Gloucester	GC008124
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brakes 1	SRS ABS & telma inop.
Travel Time	bring in from staverton.

BREAKDOWN	21/08/2018	13:56	22/08/2018	14:50	291,888	Gloucester	GC008175
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brakes 1	abs ,speed sensor inop.
18 Wheels Removal	strip brake disc off to get sensor out.
85 Body Interior 1	dash panel
99 Diagnostic Test	found n/s/r sensor u/s
Travel Time	collect from staverton.

Breakdown	31/08/2018	14:31	11/09/2018	17:23	292,257	Gloucester	GC008250
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	poss leak on a/c compressor	Monitoring
02 Windscreen	small stone chips in screen	Monitoring
43 Exhaust System 1	replace broken mounting	

45 Engine 1	replace both engine mounts	
45 Engine 2	slight oil leak from lower sump area	Monitoring
45 Engine Oil Top Up		
54 Reversing Systems	cctv upgrade	
71 Body Exterior 3	reversing camera not working	Monitoring
85 Body Interior 1	cupboard straps	
85 Body Interior 2	replace broken covers and warning lamps	
86 Sliding Door	replace broken catch	
87a - Medical Equipment Repair	mobi med check .. batteries ok	
Breakdown	Skylight sunroof smashed	
Travel Time	collect from Staverton	
Tail Lift Inspection		
18 Wheels Check Torques		
Safety Inspection		

Vehicle Deep Clean	19/09/2018	00:10	19/09/2018	05:40	292,309	Gloucester	GC008379
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	25/09/2018	07:52	25/09/2018	14:17	293,029	Gloucester	GC008447
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Test	
13 Brakes 1	remove n/s/r rear disc to clean sensor
Breakdown	932 ABS & Traction amber brakes spongey

SAFETY INSPECTION	17/10/2018	13:12	20/10/2018	10:00	295,260	Gloucester	GC008684
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	2x n/s/r
18 Wheels Check Torques	
Check Winter Pack	
Safety Inspection	
Travel Time	
Tail Lift Inspection	

Vehicle Deep Clean	22/10/2018	11:30	22/10/2018	15:00	295,274	Gloucester	GC008725
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	05/11/2018	08:50	13/11/2018	08:00	296,542	Gloucester	GC008876
13 Brake Pads	replace rear pads						
13 Brakes 1	ABS light, fit new backplate and hub seal ABS ring						
13 Brakes 2	relace rear handbrake shoes						
34 Emergency Lights	Lighting System Blue lights have to be turned on manually						
SAFETY INSPECTION	21/11/2018	11:18	21/11/2018	14:48	297,009	Gloucester	GC009042
18 Wheels Check Torques							
Safety Inspection							
Travel Time							
Fit 3rd Helmet Restraint	Fit 3rd Helmet Restraint in Cab						
Sealing of stretcher clamp	Sealing of stretcher clamp						
Vehicle Deep Clean	21/11/2018	21:30	22/11/2018	03:35	297,023	Gloucester	GC009052
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	25/11/2018	09:05	27/11/2018	07:17	297,814	Gloucester	GC009085
86 Door Lock							
Breakdown	side door wont lock - vehicle unsecure						
	Lack of Labour						
Unplanned Repair	28/11/2018	14:52	28/11/2018	14:54	298,425	Gloucester	GC009123
86 Door Lock							
Breakdown	29/11/2018	17:10	30/11/2018	13:23	298,483	Gloucester	GC009136
85 Body Interior 1	replace broken equiptment straps						
86 Door Lock	replace lock kits on all doors						
Breakdown	central locking defect. swop key for spare						

Breakdown	12/12/2018	20:47	13/12/2018	10:49	299,371	Gloucester	GC009231
86 Sliding Door Breakdown	side door wont open from outside						
Unplanned Repair	18/12/2018	11:57	19/12/2018	10:48	300,183	Gloucester	GC009287
31 Charging System 34 Lights Bulb Replacement Road Test							
Vehicle Deep Clean	07/01/2019	21:30	09/01/2019	12:57	301,338	Gloucester	GC009452
85 Body Interior 1	repaint interior panel						
85 Body Interior 2	repair shelf						
86 Door Lock	and replace door magnets						
Travel Time	bring in from staverton						
Vehicle Deep Clean	Vehicle Deep Clean						
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection	and repair/replace stretcher stop bar						
92 - C Service							
Service C							
UB Fire Suppression Service							
Handbrake Cable Replacement	Replace rear handbrake cables						
Unplanned Repair	12/01/2019	11:34	12/01/2019	11:42	301,496	Gloucester	GC009496
01 Heating 1							
54 Reversing Systems	camera inop						
Travel Time	take to Staverton						
Breakdown	10/02/2019	19:35	11/02/2019	07:21	304,100	Gloucester	GC009765

Lack of Labour

Breakdown	vehicle stuck in mud						
SAFETY INSPECTION	12/02/2019	13:37	13/02/2019	14:48	304,100	Gloucester	GC009784
13 Brakes 1	bleed system.						
16 Suspension 1	rear bushies & shackles.						
17 Tyres Tracking	adjust.						
18 Wheels Check Torques							
34 Lighting System	Body Exterior N/S mirror indicator lens broken						
54 Reversing Systems	camera inop						
Safety Inspection							
Travel Time	bring in from staverton						
Vehicle Deep Clean	13/02/2019	21:31	14/02/2019	03:24	304,902	Gloucester	GC009815
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	14/02/2019	01:00	14/02/2019	11:40	305,100	Gloucester	GC009819
Unplanned Repair	14/02/2019	14:45	14/02/2019	14:50	304,915	Gloucester	GC009824
86 Doors Rear	drill door lock, replace handle & solenoid						
Breakdown	27/02/2019	23:50	28/02/2019	11:22	307,387	Gloucester	GC009928
34 Lights Bulb Replacement	n/s/f						
Breakdown	L head light intermittant goes out						
SAFETY INSPECTION	28/03/2019	14:46	03/04/2019	08:50	309,160	Gloucester	GC010158
03 Instruments & Sensors 1	Other reversing camera&passengers height adjust O/S						
03 Instruments & Sensors 2	Other Reversing camera not working						
13 Brake Pads	rear pads and clips						
13 Brakes 1	front pads and discs						
13 Brakes 2	servo pipe worn badly						
13 Discs	rear discs						
13 Handbrake	adjust						

17 Tyres
 18 Wheels Check Torques
 45 Engine 1 bad oil leak
 45 Engine Oil Top Up
 52 Electrical Aux
 54 Reversing Systems Body Interior CCTV being triggered randomly
 71 Body External Steps
 86 Doors replace inner cover
 Safety Inspection
 Wheel Hub Flanges Replaceme
 Travel Time
 MOT

Vehicle Deep Clean	03/04/2019	21:30	04/04/2019	02:30	309,171	Gloucester	GC010202
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	12/04/2019	07:46	12/04/2019	12:36	309,793	Gloucester	GC010287
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

15 Steering 1 45 Engine 1 Road Test Travel Time	clean off engine from PAS fluid leak extended road test collect parts
--	---

Unplanned Repair	13/04/2019	12:48	15/04/2019	09:37	309,877	Gloucester	GC010305
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brake Test 34 Lights Bulb Replacement Road Test	reported noise . No Fault found . roller brake test replace headlamp bulbs
--	---

BREAKDOWN	03/05/2019	10:32	03/05/2019	10:39	311,082	Gloucester	GC010457
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1 Travel Time	cab blower motor. & collect parts from rygor.
-----------------------------	--

Breakdown	05/05/2019	17:48	06/05/2019	10:42	311,597	Gloucester	GC010470
87 Stretcher Harness Replaced	replace missing straps						
Breakdown	932- reversing camera u/s. No Fault Found !!!!!						
Unplanned Repair	08/05/2019	14:49	08/05/2019	14:51	312,070	Gloucester	GC010497
03 Instruments & Sensors 1	check data point, not fitted						
SAFETY INSPECTION	09/05/2019	12:08	11/05/2019	12:18	312,070	Gloucester	GC010508
02 Windscreen Wipers							
18 Wheels Check Torques							
45 Engine Oil Top Up							
86 Sliding Door	replace rollers						
Safety Inspection							
Travel Time							
Axle Oil Change	Axle Oil Change						
Tail Lift Inspection							
Vehicle Deep Clean	13/05/2019	21:37	14/05/2019	03:25	312,161	Gloucester	GC010536
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	17/05/2019	19:23	14/06/2019	09:43	312,620	Gloucester	GC010586
002 Major Unit Replace Eng							
45 Engine 1	found turbo blown apart						
99 Diagnostic Test							
Breakdown	?Turbo- Complete loss of power						
Unplanned Repair	13/06/2019	09:15	14/06/2019	09:22	312,696	Gloucester	GC010817
17 Tyres Replace	o/s/f						
18 Wheels Balance & Alignment							
Travel Time	collect from rygor take to stav ,but had vibration .bring into w/s friday.						

Vehicle Deep Clean	21/06/2019	08:00	21/06/2019	13:19	313,012	Gloucester	GC010883
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	21/06/2019	14:19	27/06/2019	12:45	313,025	Gloucester	GC010887
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windows/Glass	n/s window switch damaged
18 Wheels Check Torques	
Safety Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
UB Fire Supp 12mts Service	Service of fire supression system
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Annual Air Con Service	Annual Air Condition Service-check only
Annual Heater Service	Annual Heater Service

Breakdown	04/07/2019	23:58	05/07/2019	08:32	313,760	Gloucester	GC011012
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	replace 501.
Breakdown	N/S headlight switching off over bumps

Breakdown	26/07/2019	23:06	05/08/2019	09:57	314,817	Gloucester	GC011225
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	carry out test found leak low pressure on comp.	Awaiting Parts
44 Fuel System 1	replace missing misfuel device	
45 Engine Oil Top Up		
54 Reversing Systems	replace buzzer and check camera operation	
85 Body Interior 1	CCTV check	
87a - Medical Equipment Repaimobi med check		
89 Seats	saloon rear seat pin.and replace arm rest	
Breakdown	N/S headlight flickering	
Travel Time		
Tail Lift Inspection		
18 Wheels Check Torques		
Safety Inspection		

Vehicle Deep Clean	01/08/2019	21:36	02/08/2019	04:01	314,817	Gloucester	GC011269
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	23/08/2019	14:01	23/08/2019	14:08	316,528	Gloucester	GC011468
01 Air Conditioning 1	carry out test found leak low pressure on comp.					Awaiting Parts	
31 Charging System	check vehicle and shoreline charging . N>F>F !!!!!!!						
34 Lights	replace broken headlamp cover						
56 Comms Equipment	Other terrafix keeps shutting down&rear cam os						
56 Comms Fitment	Radio & Comm System Aerial needs replacing?? Not tracking					Awaiting Parts	
Unplanned Repair	03/09/2019	11:19	03/09/2019	15:37	316,821	Gloucester	GC011537
56 Comms Equipment	assit terrafix replace cable						
Travel Time	to stav						
Vehicle Deep Clean	16/09/2019	08:00	16/09/2019	11:48	317,484	Gloucester	GC011633
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/09/2019	08:43	04/10/2019	14:24	318,252	Gloucester	GC011725
01 Air Conditioning 1	carry out test found leak low pressure on comp.						
02 Windscreen Wipers							
17 Tyres Replace	n/s/f						
18 Wheels Check Torques							
56 Comms Equipment	replace Aeril						
85 Body Interior 1	replace helmate holders						
89 Seats	saloon seat base.						
Safety Inspection							
Travel Time							
Unplanned Repair	22/10/2019	14:01	22/10/2019	14:03	319,066	Gloucester	GC011921

31 Battery Comms test & replace Comms battery

SAFETY INSPECTION **12/11/2019** **11:18** **13/11/2019** **12:21** **320,598** **Gloucester** **GC012099**

13 Brakes 1	TELMA will need overhaul very soon	Monitoring
17 Tyres Replace	n/s/r both.	
18 Wheels Check Torques		
Check Winter Pack		
Safety Inspection		
Tail Lift Inspection		
Pollen Filter Change	Pollen Filter Change	Monitoring
Fuel Filter Change	Change Fuel Filter	Monitoring
Air Filter Change	Air Filter Change	

Vehicle Deep Clean **13/11/2019** **21:30** **14/11/2019** **02:40** **320,621** **Gloucester** **GC012121**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **07/12/2019** **11:26** **12/12/2019** **07:49** **322,700** **Gloucester** **GC012354**

01 Air Conditioning 1	Radiator/Cooling Sys Air con needs gas	
01 Air Conditioning 2	Radiator/Cooling Sys AC not working	
01 Heating 1	Body Interior saloon heater not working -no fault found	
01 Heating 2	Radiator/Cooling Sys demister not working - old defect	
02 Windscreen	Windscreen chip below 10mm in A zone low down	Monitoring
02 Windscreen Wipers	washer jet pipe split and wipers inop	
13 Brakes 1	TELMA will need overhaul very soon	Monitoring
18 Wheels Check Torques		
34 Lights	o/s mirror indicator damaged	
34 Lights Bulb Replacement	Body Interior saloon lights not all working. N/S/F fog light not working	
45 Engine 1	intake pipe split	
52 Electrical Aux	reverse camera inop	
54 Warn Dev/System	rev cam inop	Lack of Labour
55 Tail Lift	replace both flashers. re-drill holes	
85 Body Interior 1	CCTV check	
85 Body Interior 2		
89 Seats	Body Interior rear, side seat base stick down & tighten cab seat arm rests	
99 Diagnostic Test	reset service light	
Fuel Filter Change	Change Fuel Filter	

Pollen Filter Change	Pollen Filter Change
Road Test	extended road test
Safety Inspection	
Travel Time	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Vehicle Deep Clean	Vehicle Deep Clean

Unplanned Repair	20/12/2019	13:28	20/12/2019	13:34	323,281	Gloucester	GC012485
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Emergency Lights
34 Lights Bulb Replacement

SAFETY INSPECTION	05/02/2020	13:18	13/02/2020	09:01	328,579	Gloucester	GC012885
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen	Windscreen chip below 10mm in A zone low down
13 Brakes 1	TELMA will need overhaul very soon
13 Handbrake	adjust
16 Suspension 1	leaf spring rubber X4
18 Wheels Check Torques	
31 Charging System	faulty tail lift charger (awaiting parts)
31 Charging System Battery	replace shoreline case
45 Engine Oil Top Up	
54 Warn Dev/System	rev cam inop
85 Body Interior 1	other drug cupboard shelf broken
86 Door handle	sliding door handle
86 Sliding Door	adjust cables
Brake Fluid Change	Brake Fluid Change
Road Test	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	
Vehicle Deep Clean	Vehicle Deep Clean

Awaiting Parts

SAFETY INSPECTION	28/02/2020	09:35	04/03/2020	11:09	328,658	Gloucester	GC013139
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
31 Charging System	faulty tail lift charger (awaiting parts)

86 Sliding Door	adjust catches.
Safety Inspection	
Travel Time	take to staverton.
Vehicle Deep Clean	Vehicle Deep Clean

Breakdown	22/03/2020	20:42	23/03/2020	15:48	331,002	Gloucester	GC013320
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	o/s sidelight bulb
Breakdown	N/S headlight blown replaced by oo

SAFETY INSPECTION	07/04/2020	12:03	10/04/2020	14:17	331,731	Gloucester	GC013480
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	o/s/r x2
18 Wheels Check Torques	
85 Body Interior Roof	replace fan cover
Safety Inspection	
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test
Tail Lift Inspection	
Brakes Replace Brake Fluid	
MOT	
Vehicle Deep Clean	Vehicle Deep Clean

Unplanned Repair	28/04/2020	16:17	28/04/2020	16:21	333,024	Gloucester	GC013751
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	EML on . Power loss..Carry out static regen
99 Diagnostic Test	Carry out check with diag equpment

Unplanned Repair	12/05/2020	15:44	12/05/2020	15:52	333,905	Gloucester	GC013865
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	EML on
99 Diagnostic Test	
Road Test	

Breakdown	14/05/2020	18:47	15/05/2020	15:02	334,062	Gloucester	GC013880
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	stretcher not locking in place						
Breakdown	15/05/2020	14:15	15/05/2020	16:26	334,200	Gloucester	GC013887
Breakdown	stretcher malfunctioning						
Vehicle Deep Clean	19/05/2020	09:30	22/05/2020	14:02	334,308	Gloucester	GC013902
01 Air Conditioning 1	a/c leak from pipework onto compressor. replace parts as required						
01 Heating 1	rear heater exhaust						
13 Brakes 1	front pad and disc kit						
27 Transmission Automatic	some vibration from brake retarder						
43 Exhaust System 1	exhaust tail pipe						
52 Electrical Aux	plug covers and led warning						
56 Comms Equipment	repair handheld battery charger in cab						
71 Body Exterior Acc Repair	o/s rear lower corner section						
85 Body Interior 1	CCTV check						
87a - Medical Equipment Repair	mobili med check						
Travel Time	take to station						
Vehicle Deep Clean	Vehicle Deep Clean						
Engine Change Oil & Filter							
18 Wheels Check Torques							
Safety Inspection							
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service NOT FITTED						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
ACCIDENT	15/06/2020	12:25	18/06/2020	09:04	335,210	Gloucester	GC014115
71 Body External Steps	Step damage						
Travel Time	bring in from staverton ,take to body tech.						
Vehicle Deep Clean	29/06/2020	08:08	01/07/2020	14:41	336,430	Gloucester	GC014225
31 Battery Chassis	Replace battery						
Vehicle Deep Clean	Vehicle Deep Clean						
Annual Heater Service	Annual Heater Service						

Annual Air Con Service
 UB Fire Supp 12mts Service
 18 Wheels Check Torques
 Safety Inspection
 Tail Lift Inspection

Annual Air Condition Service
 Service of fire supression system

Breakdown	10/07/2020	23:06	13/07/2020	15:17	337,391	Gloucester	GC014339
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	tail lift dropping. Fluid leak fom metal pipes. Contractor repair						
Travel Time	Bring to workshop for repairs						

Breakdown	16/07/2020	21:56	17/07/2020	13:49	337,400	Gloucester	GC014389
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	wont go up automatically						
-----------	--------------------------	--	--	--	--	--	--

Breakdown	06/08/2020	10:04	06/08/2020	15:07	337,410	Gloucester	GC014558
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights Bulb Replacement	n/s/ind bulb.						
Breakdown	head light bulb out						

Vehicle Deep Clean	12/08/2020	05:57	14/08/2020	13:43	338,164	Gloucester	GC014604
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers							
13 Brake Pads	rear.						
17 Tyres Replace	o/s/f						
71 Body Exterior 1	repair rust indrivers door & spray.						
Vehicle Deep Clean	Vehicle Deep Clean						
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
18 Wheels Check Torques							
Safety Inspection							

Unplanned Repair	04/09/2020	13:18	04/09/2020	14:10	338,164	Gloucester	GC014789
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace

Breakdown	12/09/2020	07:22	13/09/2020	15:32	338,164	Gloucester	GC014867
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

03 Instruments & Sensors 1 Breakdown	SPARE KEY SENT TO STATION FOR VEHICLE WITHN KD KEY WILL NOT UNLOCK VEHICLE						
---	---	--	--	--	--	--	--

Breakdown	19/09/2020	17:55	21/09/2020	08:49	340,024	Gloucester	GC014946
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	doors locking system not working						
-----------	----------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	30/09/2020	15:55	02/10/2020	14:43	341,427	Gloucester	GC015069
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

15 Steering 1	Steering strong vibration at 60+ mph. old defect						
18 Wheels Check Torques							
27 Transmission Automatic	some vibration from brake retarder						
34 Lights	replace bulbs and cover						
55 Tail Lift	Ramp/Lift/Tail Hoist tail lift alarming as deployed. no fault round during roadt						
85 Body Interior 1	fix various cupboard hinges						
85 Body Interior 2	saloon light unit replace						
86 Doors	Other Side door sticking. bearings replaced						
99 Diagnostic Test	service light						
Road Test							
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	28/10/2020	09:47	28/10/2020	09:49	346,916	Gloucester	GC015328
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

52 Electrical Aux	Front Genisys control panel broken. Replace panel and repair dash						
-------------------	---	--	--	--	--	--	--

SAFETY INSPECTION	06/11/2020	09:19	08/11/2020	12:27	347,330	Gloucester	GC015425
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	Retorque only wheels not removed
45 Engine Oil Top Up	
55 Tail Lift	replace damaged stow buffer
71 Body Exterior Acc Repair	refit rear bumper pads
85 Body Interior 1	CCTV check
85 Body Interior 2	repair rear cupboards
86 Doors Rear	Adjust catches and strickers . clean and lub
87 Boards	Scoop No- 087208 (not on system)
87a - Medical Equipment Repair	Mobi Med check
Check Winter Pack	
Safety Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service NOT FITTED

Vehicle Deep Clean	10/11/2020	07:36	10/11/2020	15:07	347,735	Gloucester	GC015459
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	03/12/2020	08:35	04/12/2020	08:34	350,421	Gloucester	GC015677
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	foot long chip on the passengers side
-----------	---------------------------------------

Vehicle Deep Clean	21/12/2020	08:14	21/12/2020	14:25	351,769	Gloucester	GC015878
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	21/12/2020	13:55	22/12/2020	14:47	351,778	Gloucester	GC015882
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1	heater starting to blow blue smoke, suspect on way out(monitor 22/12/2020)	Monitoring
18 Wheels Check Torques		
85 Body Interior 1	interior cuboard back broken, carried out repair	
85 Body Interior 2	fit new pas window switch	
Safety Inspection		
Travel Time		
Tail Lift Inspection		

Unplanned Repair	28/12/2020	13:37	28/12/2020	13:41	352,044	Gloucester	GC015939
86 Doors Rear	adjust top catch & switch.						
Unplanned Repair	06/01/2021	09:50	06/01/2021	09:53	353,020	Gloucester	GC016011
34 Lights Bulb Replacement	n/s/f ind in mirror .						
Breakdown	08/01/2021	21:32	10/01/2021	09:55	353,323	Gloucester	GC016037
86 Doors Rear Breakdown	replace catch & pin readjust. Rear Door keeps coming open						
Breakdown	08/01/2021	21:33	10/01/2021	09:56	353,323	Gloucester	GC016038
42 Coolant System Breakdown	found viscous fan blades broken , bearing has play & noisy.order on part. Vehicle Shuderring when Stationary						
Breakdown	08/01/2021	21:34	12/01/2021	14:12	353,323	Gloucester	GC016039
13 Brake Test 13 Brakes 2 45 Engine 1 86 Doors Rear Breakdown Road Test Travel Time	remove prop & check Telma . Vibration .. Viscous fan damaged Not closing correctly catches and pins Retarder Not Holding						
Breakdown	02/02/2021	13:10	02/02/2021	15:56	355,994	Gloucester	GC016247
86 Doors Rear Breakdown	rear handle and lock jammed . Repair as required amber ABS, traction control&anti skid lights Diag check & clear codes						
Breakdown	04/02/2021	13:38	08/02/2021	14:07	356,337	Gloucester	GC016276
99 Diagnostic Test Breakdown Road Test	FOUND ABS SENSOR INOP N/S/R order parts. ABS & traction lights on						

Vehicle Deep Clean	08/02/2021	09:04	08/02/2021	12:21	356,477	Gloucester	GC016304
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/02/2021	13:34	10/02/2021	10:40	356,483	Gloucester	GC016307
01 Heating 1	heater starting to blow blue smoke, suspect on way out(monitor 22/12/2020)						
16 Suspension 1	replace rear antiroll bar bushies.						
17 Tyres Replace	replace front tyres w/ new and old fronts to go on o/s rear						
18 Wheels	clean and respray wheels						
18 Wheels Check Torques							
27 Transmission Automatic	telma required, awaiting new one					Awaiting Parts	
43 Exhaust System 1	replace exhaust rubber						
85 Body Interior 1	replace kick bin latches						
86 Door Lock	locks and key						
Road Test							
Safety Inspection							
Travel Time							
Replace Handbrake Cables	Replace Handbrake Cables						
Unplanned Repair	20/02/2021	14:30	20/02/2021	14:35	357,138	Gloucester	GC016427
34 Lights Bulb Replacement	n/s/f ind bulb.						
Breakdown	27/02/2021	16:39	28/02/2021	13:52	358,022	Gloucester	GC016500
99 Diagnostic Test							
Breakdown	EML , Traction , SRS amber lights						
Unplanned Repair	09/03/2021	12:14	10/03/2021	12:32	358,572	Gloucester	GC016593
02 Windscreen Wipers	washers not working poss pump						
18 Wheels	respray o/s rear outer wheel						
34 Lighting System	Lighting System N/S indicator bulb blown						
41 Air Intake	replace pipe.						

86 Doors Rear
 Tail Lift Inspection
 18 Wheels Check Torques
 Safety Inspection
 Engine Change Oil & Filter

rer n/s door not open lock/handle jammed

Vehicle Deep Clean	16/03/2021	10:38	16/03/2021	14:59	358,895	Gloucester	GC016654
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair	26/03/2021	11:45	26/03/2021	15:50	359,825	Gloucester	GC016766
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 2
 11 Axle Front
 18 Wheels
 18 Wheels Balance & Alignment
 18 Wheels Check Torques
 27 Transmission Automatic
 Road Test

rear heater smoking . (NOTE found on cold setting no prper startup)
 clean flanges
 clean mating surfaces
 rebalance roadwheels and check suspension
 telma required, awaiting new one

Awaiting Parts

Breakdown	08/04/2021	12:02	08/04/2021	15:26	361,093	Gloucester	GC016900
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown Rattling sound from under rear driver side area check & replace propshaft

Vehicle Deep Clean	23/04/2021	07:36	23/04/2021	07:42	362,655	Gloucester	GC017062
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	23/04/2021	09:28	24/04/2021	14:57	362,669	Gloucester	GC017065
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher
 16 Suspension 1
 18 Wheels Check Torques
 27 Transmission Automatic
 34 Lights

replaced defective extinguisher
 rear arb bush splt
 telma required, awaiting new one
 replace o/s rear upper indicator

85 Body Interior 1	floor mats	Parts ordered in store
Road Test		
Safety Inspection		
Travel Time		
Wheel Hub Flanges Replaceme		
MOT		
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service	
Tail Lift Inspection		

Breakdown	07/05/2021	19:05	11/05/2021	07:08	364,040	Gloucester	GC017210
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	stretcher secure mechanism not working	Lack of Labour
-----------	--	----------------

Unplanned Repair	17/05/2021	12:50	17/05/2021	12:55	365,407	Gloucester	GC017285
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

54 Warn Dev/System	cctv
--------------------	------

Breakdown	22/05/2021	23:27	24/05/2021	07:31	366,702	Gloucester	GC017346
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Driver side light bulb out	Lack of Labour
-----------	----------------------------	----------------

Breakdown	05/06/2021	00:05	07/06/2021	07:37	369,713	Gloucester	GC017470
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	passenger's side headlight out	Lack of Labour
-----------	--------------------------------	----------------

Unplanned Repair	11/06/2021	08:13	11/06/2021	08:18	370,794	Gloucester	GC017538
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windows/Glass	repair window switch.
34 Lights	replace o/s/f ind lens & bulb.
Travel Time	

Vehicle Deep Clean	15/06/2021	08:17	15/06/2021	13:00	371,008	Gloucester	GC017564
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/06/2021	14:40	20/06/2021	16:25	371,017	Gloucester	GC017565
02 Windscreen	washer bottle leaking						
13 Brakes 1	front pads and discs						
13 Brakes 2	rear pads and discs						
17 Tyres Replace	All 4 Rear tyres						
18 Wheels	clean rims , flanges and pait rims as required						
18 Wheels Check Torques							
34 Lighting System	rear upper lamps						
41 Air Intake	replace leaking seals etc						
45 Engine 3	Engine "unusual" white smoke coming from the exhaust						
45 Engine Oil Top Up							
55 Tail Lift	replace distorted and fractured handrail, R.S REPAIR .						
85 Body Interior 1	floor mats. remove cab fittings and cut to fit						
85 Body Interior 2	CCTV check						
87a - Medical Equipment Repair	Mobi Med check						
Breakdown	passenger's side headlight out						
Safety Inspection							
Travel Time							
Wheel Hub Flanges Replaceme						Monitoring	
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Breakdown	30/06/2021	12:19	30/06/2021	14:47	371,780	Gloucester	GC017714
Breakdown	Orange EML on and limp mode					Lack of Labour	
Breakdown	25/07/2021	01:50	31/07/2021	13:48	375,179	Gloucester	GC017931
002 Major Unit Replace Gearbo:							
Breakdown	Not selecting gears						
Travel Time	deliver & pick up gearbox from Rygors						

Vehicle Deep Clean	09/08/2021	14:04	09/08/2021	23:02	375,942	Gloucester	GC018061
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	10/08/2021	08:32	11/08/2021	09:26	375,957	Gloucester	GC018079
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	Inop. nitrogen test found leaking condenser	Monitoring
02 Mirrors	n/s	
16 Suspension 1	leaf rubber X1	
18 Wheels Check Torques		
27 Transmission Automatic	replace telma with one from kug	
41 Air Intake	replace cracked pipe and seals	
45 Engine 1	replace weeping outer belt tensioner	
45 Engine Oil Top Up		
55 Tail Lift	hose X2	
86 Doors	cover rusty sharp area by drivers door handle	
87 Med Handling Equip Inspect	Med Equip & Devices stretcher backrest does not lock. NFF	
89 Seats	saloon seat base wobbly	
Breakdown	Orange EML on and limp mode	
Road Test		
Safety Inspection		
Wheel Hub Flanges Replaceme		
UB Fire Supp 12mts Service	Service of fire supression system	
Annual Air Con Service	Annual Air Condition Service	
Annual Heater Service	Annual Heater Service	

Breakdown	20/08/2021	21:41	21/08/2021	11:26	376,723	Gloucester	GC018183
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

43 Exhaust System 1	carried out regen, if requires regen again will require dpf
Breakdown	Orange EML & Limp mode
Travel Time	

Breakdown	31/08/2021	19:03	01/09/2021	08:38	377,291	Gloucester	GC018270
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

31 Battery Aux	replace battery
31 Charging System Battery	
86 Doors	repair sharp edge on door
99 Diagnostic Test	test batteries
Breakdown	AUX battery, side step, AirCon, VOR

Road Test
Travel Time

SAFETY INSPECTION	07/10/2021	12:09	07/10/2021	12:14	379,433	Gloucester	GC018632
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	07/10/2021	12:15	07/10/2021	15:15	379,433	Gloucester	GC018633
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	Inop. nitrogen test found leaking condenser
18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service

Vehicle Deep Clean	07/10/2021	23:11	07/10/2021	23:12	379,443	Gloucester	GC018638
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	07/10/2021	23:13	07/10/2021	23:16	379,443	Gloucester	GC018639
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	02/11/2021	20:22	04/11/2021	14:40	380,981	Gloucester	GC018843
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Heating 1	replace blower motor
99 Diagnostic Test	scan codes, clear codes, test heater
Breakdown	No heating in back

SAFETY INSPECTION	19/11/2021	10:59	19/11/2021	14:49	381,347	Gloucester	GC018989
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windscreen Wipers		
15 Steering 1	rack starting to leak	Monitoring
18 Wheels Check Torques		
41 Turbo	replace blown seals. refit boost pipe	
Road Test		

Safety Inspection
Tail Lift Inspection
Engine Change Oil & Filter

Vehicle Deep Clean **23/11/2021** **09:34** **23/11/2021** **14:18** **381,372** **Gloucester** **GC019013**

Vehicle Deep Clean Vehicle Deep Clean

Unplanned Repair **14/12/2021** **11:42** **14/12/2021** **11:43** **381,839** **Gloucester** **GC019186**

34 Lights Bulb Replacement

Breakdown **21/12/2021** **15:15** **22/12/2021** **11:59** **382,082** **Gloucester** **GC019240**

41 Turbo checked. looked ok
43 Exhaust System 1 dpf ash content full. carry out clean and regen
Breakdown Limp mode & orange EML
Road Test

Unplanned Repair **24/12/2021** **12:21** **24/12/2021** **14:54** **382,102** **Gloucester** **GC019267**

34 Lights o/s upper rear side light out

Vehicle Deep Clean **04/01/2022** **14:20** **05/01/2022** **11:15** **382,171** **Gloucester** **GC019334**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **05/01/2022** **12:01** **06/01/2022** **09:45** **382,185** **Gloucester** **GC019339**

18 Wheels Check Torques
34 Lights Carry out repair to wiring harness for N/S Headlamp
55 Tail Lift oil leaking from return.
86 Sliding Door replace rollers.
Road Test
Safety Inspection

Breakdown	07/01/2022	06:49	10/01/2022	11:43	382,185	Gloucester	GC019352
11 Axle Front	Clean flange						
13 Brakes 1	found Telma faulty , replace unit.						
18 Wheels	Clean wheel						
18 Wheels Check Torques							
Breakdown	Grinding from rear brakes, road test to confirm concern.						
Road Test							
Breakdown	13/02/2022	19:34	14/02/2022	10:36	382,558	Gloucester	GC019634
Breakdown	ENG MAN LIGHT ON LIMP MODE, DPF req						Lack of Labour
Unplanned Repair	18/02/2022	15:40	18/02/2022	15:45	382,660	Gloucester	GC019692
86 Doors	o/s front door stay broken						
02 Pipeline Annual Inspection	14/02/2022	08:52	14/02/2022	08:54	382,560	MDT Gloucester	MG001200
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
SAFETY INSPECTION	23/02/2022	14:11	24/02/2022	11:41	383,279	Gloucester	GC019718
15 Steering 1	Slight play in steering rack.						
16 Suspension 1	Slight play both front bottom ball joints and shock absorbers						
18 Wheels Check Torques							
52 Electrical Aux	Rewire Stryker charging base and re-route charging cable						
54 Warn Dev/System	CCTV Check						
Breakdown	ENG MAN LIGHT ON LIMP MODE, DPF req, no warning lights on at time of test						
Medical Devices Check	Mobi Med Check						
Road Test							
Safety Inspection							
Tail Lift Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						Awaiting Parts

SAFETY INSPECTION	20/04/2022	09:37	21/04/2022	15:08	384,148	Gloucester	GC020206
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Brake Fluid Change	Brake Fluid Change
MOT	
16 Suspension 1	replace both front lower arms and n/s wheel bearing w/ abs sensor
13 Brakes 1	check condition of rear shoes due to grinding noise
85 Body Interior 1	seat adjusters
11 Axle Front	clean flange and wheels
Road Test	
17 Tyres Tracking	
45 Engine 1	oil leak from pipes, replace engine mount as well
85 Body Interior 2	zoll

Unplanned Repair	13/05/2022	12:32	13/05/2022	14:31	384,811	Gloucester	GC020398
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	eml on
43 Exhaust System 1	dpf fault, regen carried out

Emergency Deep Clean	23/06/2022	12:39	23/06/2022	12:41	386,295	Gloucester	GC020736
-----------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Emergency Deep Clean

SAFETY INSPECTION	01/07/2022	11:01	01/07/2022	11:01	386,461	Gloucester	GC020812
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	01/07/2022	11:02	01/07/2022	14:00	386,461	Gloucester	GC020813
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection
Tail Lift Inspection
Tail Lift 12M Service & Weight Tail Lift 12M Service & Weight

Breakdown	06/07/2022	22:31	08/07/2022	09:44	387,429	Gloucester	GC020854
Breakdown	STR Not locking in place						
Vehicle Deep Clean	07/07/2022	15:04	07/07/2022	15:04	386,461	Gloucester	GC020859
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	07/07/2022	15:05	07/07/2022	15:05	386,461	Gloucester	GC020860
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	07/07/2022	15:05	07/07/2022	15:06	386,461	Gloucester	GC020861
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	07/07/2022	15:06	07/07/2022	15:08	386,461	Gloucester	GC020862
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	19/07/2022	15:55	21/07/2022	12:38	387,430	Gloucester	GC020969
01 Air Conditioning 1	01 condensor ordered						
SAFETY INSPECTION	25/07/2022	07:15	25/07/2022	12:08	387,500	Gloucester	GC021001
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
Annual Heater Service	Annual Heater Service						
UB Fire Supp 12mts Service	Service of fire suppression system						
Annual Air Con Service	Annual Air Condition Service						
85 Body Interior 1	Zoll holes						
Road Test							
89 Seats	O/S/F seat height adjuster broken						

Breakdown	14/12/2022	16:06	15/12/2022	17:03	390,481	Gloucester	GC022137
Breakdown 17 Tyres Replace	OFFSIDE REAR OUTER PUNCTURE By ATS at Staverton offside rear outer						
Vehicle Deep Clean	10/02/2023	07:51	10/02/2023	14:42	393,068	Gloucester	GC022621
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/02/2023	12:11	08/03/2023	14:12	393,435	Gloucester	GC022646
18 Wheels Check Torques Safety Inspection 17 Tyres Tail Lift Inspection UB Fire Supp 6mts Service Engine Change Oil & Filter 34 Emergency Lights 43 Exhaust System 1 17 Tyres Replace	Tyres O/S REAR PUNCTURE UB Fire Supp 6mts Service replace both rear blue lights exhaust clamp replace both front tyres						
Medical devices repair	16/02/2023	09:55	16/02/2023	10:01	393,435	MDT Gloucester	MG002050
Decontaminated Defect Sheet Present No Defect Sheet Present Yes Medical Devices Repair	Cleaned with clinell wipes SKTU001 service pack fitted to port see notes						
02 Pipeline Annual Inspection	16/02/2023	10:02	16/02/2023	10:05	393,435	MDT Gloucester	MG002051
02 Pipeline Annual Inspection	New probes,shrink and ferrules fitted cost £77.16+Vat pressure/leak test pass						
SAFETY INSPECTION	08/03/2023	14:12	08/03/2023	15:57	393,473	Gloucester	GC022824
18 Wheels Check Torques							

Safety Inspection
Tail Lift Inspection

Vehicle Deep Clean **03/04/2023** **06:22** **03/04/2023** **09:45** **394,596** **Gloucester** **GC023042**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **16/04/2023** **12:18** **18/04/2023** **10:37** **394,862** **Gloucester** **GC023181**

18 Wheels Check Torques
Safety Inspection
45 Engine Oil Top Up Top up
34 Lights Head light condition poor
02 Glass / Windows O/S window switch broken
16 Suspension 1 Rear shock absorbers U/S
13 Handbrake Excessive travel
34 Lighting System Scene light N/S inop
71 Body External Steps N/S Step wheel arch corrosion
Tail Lift Inspection
MOT

Vehicle Deep Clean **17/05/2023** **07:13** **17/05/2023** **10:58** **395,638** **Gloucester** **GC023402**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **17/05/2023** **14:05** **18/05/2023** **14:28** **395,862** **Gloucester** **GC023405**

18 Wheels Check Torques
Safety Inspection
89 Seatbelts both front
16 Suspension 1 monitor front shocks Monitoring
01 Heating 1 heater exhaust p clip
02 Windscreen Wipers
55 Tail Lift split metal pipe replaced by pirtek

Vehicle Deep Clean	28/06/2023	14:04	29/06/2023	11:02	396,313	Gloucester	GC023778
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	01/07/2023	22:18	02/07/2023	16:03	396,360	Gloucester	GC023804
Breakdown	EML/LOP						
Forced DPF Regeneration	Carry Out Forced DPF Regeneration						
SAFETY INSPECTION	02/07/2023	08:34	03/07/2023	14:28	396,411	Gloucester	GC023806
18 Wheels Check Torques							
Safety Inspection							
16 Suspension 1	monitor front shocks						
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Tail Lift Inspection							
UB Fire Supp 12mts Service	Service of fire supression system						
27 Transmission Automatic	Play in short prop.						
41 Turbo	Charge pipe broken & seals leaking.						
Engine Oil & Filter Change	Engine Oil & Filter Change						
Pollen Filter Change	Pollen Filter Change						
Air Filter Change	Air Filter Change						
85 Body Interior 1	Rear door interior light not working.						
Road Test							
Replace Vehicle Fuel Card	24/07/2023	11:05	24/07/2023	11:06	396,411	Gloucester	GC024033
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Unplanned Repair	28/07/2023	08:18	01/08/2023	08:59	396,880	Gloucester	GC024131
45 Engine 1	Engine EML on						
45 Engine 2	Replace DPF						
Vehicle Deep Clean	18/08/2023	11:21	18/08/2023	14:51	397,451	Gloucester	GC024275
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	20/08/2023	14:45	22/08/2023	08:56	397,467	Gloucester	GC024297
18 Wheels Check Torques							
Safety Inspection							
Annual Air Con Service	Annual Air Condition Service						
Tail Lift Inspection							
Engine Change Oil & Filter	only done 1000 miles since last						
Vehicle Deep Clean	20/09/2023	08:50	20/09/2023	12:50	397,588	Gloucester	GC024544
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	21/09/2023	09:40	21/09/2023	15:28	397,597	Gloucester	GC024554
18 Wheels Check Torques							
Safety Inspection							
Annual Heater Service	Annual Heater Service						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Road Test							
Vehicle Deep Clean	04/11/2023	16:08	05/11/2023	16:11	398,192	Gloucester	GC024914
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	05/11/2023	16:24	05/11/2023	16:27	398,195	Gloucester	GC024919
18 Wheels Check Torques							
Safety Inspection							
16 Suspension 1	monitor rear shackles					Monitoring	
13 Discs	front pad and d required net safety					Monitoring	

Vehicle Deep Clean	14/12/2023	14:27	15/12/2023	08:33	399,023	Gloucester	GC025240
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

ACCIDENT	08/01/2024	22:10	09/01/2024	07:10	399,023	Gloucester	GC025441
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	N/s wing mirror missing swapped
-----------	---------------------------------

Vehicle Deep Clean	18/01/2024	12:45	18/01/2024	16:15	399,666	Gloucester	GC025527
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	22/01/2024	14:00	26/01/2024	11:22	399,699	Gloucester	GC025558
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
16 Suspension 1	monitor rear shackles
13 Discs	front pad and d required net safety
Tail Lift Inspection	
86 Doors	scoop door lock broken
02 Windscreen Wipers	washer hoses adrift
71 Body Exterior 1	repair damaged arches as holed / parts missing prev repair fail;, general tidy
16 Suspension 2	renewed worn front dampers
18 Wheels Balance & Alignment	
17 Tyres Replace	renewe punched rear inner o/s tyre and renew damaged nsr outer wheel
11 Axle Rear	clean flnges and wheel faces
Heater Service	exh maounts corrded thro, and hanging low , renew as ness
71 Body External Steps	repair damaged / holes rear step sharp edges
Road Test	
87 - Stretchers/Chairs/Boards	c/o checks repar as ness

SAFETY INSPECTION	21/02/2024	07:14	21/02/2024	10:26	400,002	Gloucester	GC025765
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection

13 Brakes 1 Road Test	telma inop						
Medical devices repair	22/02/2024	08:34	22/02/2024	08:48	400,004	MDT Gloucester	MG003113
Decontaminated Defect Sheet Present No Defect Sheet Present Yes Medical Devices Repair	Cleaned with clinell wipes 2x 90° angle probe 2x ferrules & 2x white shrink cost £77.29+Vat						
O2 Pipeline Annual Inspection	22/02/2024	08:48	22/02/2024	08:50	400,002	MDT Gloucester	MG003114
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
Vehicle Deep Clean	05/03/2024	07:30	05/03/2024	15:00	400,408	Gloucester	GC025859
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	07/04/2024	23:29	11/04/2024	15:42	401,758	Gloucester	GC026116
Breakdown Tail Lift Inspection 18 Wheels Check Torques Safety Inspection UB Fire Supp 6mts Service MOT	carry chair strap broken unable to secure UB Fire Supp 6mts Service						
Vehicle Deep Clean	15/04/2024	10:30	15/04/2024	14:00	401,815	Gloucester	GC026165
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	27/05/2024	19:30	28/05/2024	03:30	403,001	Gloucester	GC026572
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	28/05/2024	11:42	29/05/2024	11:38	403,010	Gloucester	GC026577
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
Road Test							
15 Steering 1		Slight misting from steering rack pinion.				Monitoring	
Wash Vehicle	09/06/2024	05:00	09/06/2024	05:30	403,287	Gloucester	GC026716
Wash Vehicle							
Vehicle Deep Clean	11/07/2024	12:00	11/07/2024	18:33	403,729	Gloucester	GC027108
Vehicle Deep Clean		Vehicle Deep Clean					
SAFETY INSPECTION	12/07/2024	09:01	13/07/2024	14:11	403,742	Gloucester	GC027117
18 Wheels Check Torques							
Safety Inspection							
15 Steering 1		Slight misting from steering rack pinion.				Monitoring	
Brake Fluid Change		Brake Fluid Change					
Tail Lift 12M Service & Weight		Tail Lift 12M Service & Weight					
Engine Change Oil & Filter							
Pollen Filter Change		Pollen Filter Change					
Air Filter Change		Air Filter Change					
86 Sliding Door		replace top door magent					
13 Brakes 1		rear brakes required next safety (cables to replace then as well)				Monitoring	
SAFETY INSPECTION	16/08/2024	15:36	16/08/2024	16:26	403,985	Gloucester	GC027549
18 Wheels Check Torques							
Safety Inspection							

Vehicle Deep Clean	26/08/2024	13:30	26/08/2024	18:15	404,105	Gloucester	GC027691
Vehicle Deep Clean	Vehicle Deep Clean						
ACCIDENT	02/09/2024	19:15	02/09/2024	19:29	404,517	Gloucester	GC027812
71 Body External Steps 34 Lights	side step inop from impact with kerb os headlamp impact marked						
Vehicle Deep Clean	08/10/2024	15:00	09/10/2024	14:44	405,509	Gloucester	GC028498
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/10/2024	07:24	13/10/2024	10:50	405,520	Gloucester	GC028536
18 Wheels Check Torques Safety Inspection 15 Steering 1 13 Brakes 1 Tail Lift Inspection	Slight misting from steering rack pinion. rear brakes required next safety (cables to replace then as well)						
Unplanned Repair	13/10/2024	09:46	13/10/2024	10:48	405,569	Gloucester	GC028610
02 Mirrors	N/S mirror broken						
Vehicle Deep Clean	26/11/2024	15:45	27/11/2024	10:06	406,685	Gloucester	GC029510
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	21/01/2025	11:15	21/01/2025	16:45	407,671	Gloucester	GC030753
Vehicle Deep Clean	Vehicle Deep Clean						

02 Pipeline Annual Inspection	25/02/2025	09:23	26/02/2025	09:24	408,106	MDT Gloucester	MG004073
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	-----------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
-------------------------------	-------------------------------------	--	--	--	--	--	--

Vehicle Deep Clean	03/03/2025	10:53	03/03/2025	14:00	408,711	Gloucester	GC031726
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	18/03/2025	14:53	19/03/2025	12:33	408,765	Gloucester	GC032055
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Safety Inspection	Safety Inspection						
18 Wheels Check Torques	18 Wheels Check Torques						
Road Test	Road Test						
Replace Handbrake Cables	Replace Handbrake Cables						
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present						
UB Fire Supp 12mts Service	Service of fire suppression system						
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Tail Lift Inspection	Tail Lift Inspection						
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
Engine Change Oil & Filter	Engine Change Oil & Filter						
43 Exhaust System 1	replace exhaust tip						

MOT EXPIRES	22/04/2025	10:16	23/04/2025	09:19	408,765	Gloucester	GC032963
--------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

MOT	MOT						
-----	-----	--	--	--	--	--	--

Vehicle Deep Clean	03/05/2025	17:23	04/05/2025	00:00	408,799	Gloucester	GC033227
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	04/05/2025	07:04	04/05/2025	11:58	408,811	Gloucester	GC033241
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test	Check and Install MDVS windows update						
Vehicle Deep Clean	18/06/2025	13:00	18/06/2025	16:00	409,583	Gloucester	GC034474
Vehicle Deep Clean	Vehicle Deep Clean						
Decommission Vehicle	17/07/2025	08:00			409,583	Unallocated	Un001177
Decommission vehicle	Decommission vehicle						