

Vehicle Detail	YT15ZHB	VAUXHALL	Ampera	No
Date	Odo	Job Type	Description	
01/05/2025		0 RFL	RFL May 2025	
17/03/2025		0 RFL	RFL Apr 2025	
19/03/2024		0 RFL	RFL APRIL 2024	
08/02/2023		0 SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
08/02/2023		0 REPAIRS TO BODY (NON ACCIDENT)	DAMAGED WING MIRROR	
30/09/2022		0 REPAIRS FOR MISUSE OR DAMAGE	Change Tyre	
30/09/2022		0 REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair	
30/09/2022		0 REPAIRS FOR MISUSE OR DAMAGE	Disposal of Tyre Casing	
30/09/2022		0 REPAIRS FOR MISUSE OR DAMAGE	Wheel Balance	
20/09/2022		0 SERV/SAFETY INS (+ TEST FEE)	S7 SERVICE	
24/03/2022		0 RFL	RFL Mar 2022	
17/02/2022		0 SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
19/10/2021		0 SERV/SAFETY INS (+ TEST FEE)	S6 SERVICE	
16/03/2021		0 RFL	RFL March 2021	
22/02/2021	88,900	SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
22/02/2021	88,900	REPAIRS TO SUSPENSION	Hub bearing(s) (one wheel) (Front Susp.) left	
22/02/2021	88,900	REPAIRS TO ELECTRICS/BATTERY	Infrared remote control batteries	
22/02/2021	88,900	REPAIRS TO BRAKES	Pads - rear (axle set)	
13/01/2021	88,900	REPAIRS TO ENGINE, EXHAUST	99994/engine warning light on plug in and che	
15/09/2020	80,031	SERV/SAFETY INS (+ TEST FEE)	S5 SERVICE	
13/02/2020		0 BREAKDOWN RECOVERY	RECOVERY ONLY - AFTER BREAKDOWN	
12/02/2020		0 TYRES	Wheel Balance	
12/02/2020		0 TYRES	Change Tyre	
12/02/2020		0 TYRES	Wheel Balance	
12/02/2020		0 TYRES	Tyre Valve Inner Repair	
12/02/2020		0 TYRES	Disposal of Tyre Casing	
12/02/2020		0 TYRES	Tyre Valve Inner Repair	
12/02/2020		0 TYRES	Disposal of Tyre Casing	
12/02/2020		0 TYRES	Tyre Call Out	
12/02/2020		0 TYRES	Change Tyre	
23/09/2019		0 REPAIRS TO MOWING EQUIPMENT	REPLACED GREASE NIPPLES BROKEN ON ROLLER	
23/09/2019		0 REPAIRS TO MOWING EQUIPMENT	REPLACED GREASE NIPPLES BROKEN ON ROLLER	
12/09/2019		0 SERV/SAFETY INS (+ TEST FEE)	S4 SERVICE	
12/09/2019		0 REPAIRS TO ENGINE, EXHAUST	Auxiliary drive belt (polyrib belt)	
09/09/2019		0 REPAIRS TO STEERING	Alignment - toe-in/out (Front Susp.)	
09/09/2019		0 REPAIRS TO STEERING	Alignment - toe-in/out (Front Susp.)	
09/09/2019		0 REPAIRS TO STEERING	Alignment - toe-in/out (Front Susp.)	
05/09/2019		0 REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair	
05/09/2019		0 REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair	
05/09/2019		0 REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair	
13/03/2019		0 BREAKDOWN RECOVERY	GEARBOX	
27/02/2019		0 SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	
27/02/2019		0 REPAIRS TO ELECTRICS/BATTERY	ECU - engine management - ignition	
18/10/2018		0 REPAIRS TO BODY (NON ACCIDENT)	Door mirror glass left	
18/10/2018		0 SERV/SAFETY INS (+ TEST FEE)	S3 SERVICE	
15/04/2018		0 RFL	RFL April 2018	
23/03/2018		0 SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test	

16/03/2018	0 BREAKDOWN RECOVERY	/WON/T START
16/03/2018	0 BREAKDOWN RECOVERY	/WON/T START
16/03/2018	0 BREAKDOWN RECOVERY	/WON/T START
16/03/2018	0 BREAKDOWN RECOVERY	/WON/T START
15/03/2018	0 RFL	RFL April 2018
24/01/2018	51,000 BREAKDOWN RECOVERY	WON/T START
12/04/2017	0 REPAIRS FOR MISUSE OR DAMAGE	Tyre tread damage, NSR 5mm left, fit 2155517HESAVG - Parts
12/04/2017	0 TYRES	Tyres - Environmental Disposal,OSR - Parts
12/04/2017	0 TYRES	Tyres - Environmental Disposal,NSR - Parts
12/04/2017	0 TYRES	Tyres - Environmental Disposal,OSF - Parts
12/04/2017	0 TYRES	Tyres - Environmental Disposal,NSF - Parts
12/04/2017	0 REPAIRS FOR MISUSE OR DAMAGE	Tyre tread damage, OSR 5mm left, fit 2155517HESAVG - Parts
12/04/2017	0 TYRES	Tyre worn out, OSF 3mm left, fit 2155517HESAVG - Parts
12/04/2017	0 TYRES	Tyre worn out, NSF 0mm left, fit 2155517HESAVG - Parts
31/03/2017	0 RFL	RFL March 2018
13/06/2016	0 MAINTENANCE	Puncture Repair,NSF - Parts
13/06/2016	0 MAINTENANCE	Wheel Balance,NSR - Parts
13/06/2016	0 MAINTENANCE	Tyre Valve,OSF - Parts
10/03/2016	0 MAINTENANCE	Refit damaged charging point cap - Labour