Vehicle Detail	LS62NFE	TOYOTA	HI-LUX 4X4 DIESEL
Date	Odo	Job Type	Description
25/11/2024	0	RFL	RFL Dec 2024
20/11/2023	0	RFL	RFL Dec 2023
03/01/2023	0	RFL	RFL Dec 2022
03/01/2023	0	RFL	RFL Dec 2022
03/01/2023	0	RFL	RFL Dec 2022
28/11/2022	0	RFL	RFL Nov 2022
25/11/2021	0	RFL	RFL Dec 2021
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Disposal of Tyre Casing
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Change Tyre
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Change Tyre
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Tyre Call Out
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Wheel Balance
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Tyre Call Out
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Disposal of Tyre Casing
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Wheel Balance
16/04/2021	35,049	REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair
13/01/2021	33,172	WINDSCREEN & GLASS	Rubber-Moulding-Trims Windscreens
13/01/2021	33,172	WINDSCREEN & GLASS	Wipers
13/01/2021	33,172	WINDSCREEN & GLASS	Glass - windscreen
13/01/2021	33,172	WINDSCREEN & GLASS	Rubber-Moulding-Trims Windscreens
13/01/2021	33,172	WINDSCREEN & GLASS	Wipers
13/01/2021	33,172	WINDSCREEN & GLASS	Wipers
13/01/2021	33,172	WINDSCREEN & GLASS	Glass - windscreen
13/01/2021	33,172	WINDSCREEN & GLASS	Wipers
26/11/2020	0	RFL	RFL Nov 2020
20/08/2020	0	REPAIRS TO BODY (NON ACCIDENT)	Bumper assy - front
20/08/2020	0	COLLECTION & DELIVERY	Collection & Delivery
20/08/2020	0	SERV/SAFETY INS (+ TEST FEE)	S8 SERVICE
20/08/2020	0	SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
20/08/2020	0	REPAIRS TO BODY (NON ACCIDENT)	check body as recomened on service tick
20/08/2020	0	REPAIRS TO BRAKES	Brake shoes (manually adjusted)
20/08/2020	0	REPAIRS INTERNAL FITTINGS	replace missing no smoking sticker
20/08/2020		REPAIRS TO ELECTRICS/BATTERY	Lamps exterior - number plate lamp bulb
15/11/2017	0	RFL	RFL November 2017
04/09/2017	0	REPAIRS TO ENGINE, EXHAUST	DEF0117 Vehicle Description Audit recall end date =30-APR-2018
04/09/2017	0	SERV/SAFETY INS (+ TEST FEE)	S5 SERVICE
04/09/2017		SERV/SAFETY INS (+ TEST FEE)	Class IV MoT Test
15/08/2017	0	WINDSCREEN & GLASS	Glass - windscreen repair

No