

WX15NHE	A&E		Nailsea Amb Stn				
Breakdown	07/12/2015	03:56	07/12/2015	13:36	5,847	Bristol	BL000084
86 Door Lock Breakdown	adjusted side door lower catch Side door wont open from inside.						
Unplanned Repair	24/12/2015	07:24	29/12/2015	16:07	8,974	Bristol	BL000248
17 Tyres	replace tyre						
Unplanned Repair	28/12/2015	08:50	28/12/2015	10:13	8,973	Bristol	BL000256
44 Fuel System 1	Doors Side door issues						
SAFETY INSPECTION	30/12/2015	12:33	30/12/2015	14:20	9,212	Bristol	BL000285
18 Wheels Check Torques Safety Inspection							
Unplanned Repair	08/01/2016	09:00	08/01/2016	09:15	10,233	Taunton	TN013901
44 Add Ad Blue	topped up by duty officer						
Breakdown	10/01/2016	04:44	11/01/2016	10:05	10,616	Bristol	BL000411
Breakdown	central locking gone on side door						
Unplanned Repair	04/02/2016	12:41	05/02/2016	10:15	14,468	Bristol	BL000721
34 Lights 55 Tail Lift	refit new top white light remove taillift bars ajust and refit						

Veh Deep Clean	04/02/2016	12:40	04/02/2016	12:42	14,468	Bristol	BL000722
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	09/02/2016	10:16	10/02/2016	10:45	15,149	Bristol	BL000765
Breakdown	side door flew open and sensor not working, door catches adjusted						
SAFETY INSPECTION	10/02/2016	20:47	10/02/2016	21:02	15,331	Bristol	BL000804
55 Ramp 71 Body Exterior Roof 86 Sliding Door Safety Inspection	Side step not coming out lubricate mechanism and test all ok nsf corner cap missing replace corner cap Side door not opening adjust mechanism and test all ok Carry out safety inspection						
Breakdown	21/02/2016	17:07	22/02/2016	14:40	16,209	Bristol	BL000932
Breakdown	Side door setting alarms off.Strip panels and adjust side door.						
Unplanned Repair	22/02/2016	18:39	22/02/2016	20:01	16,254	Bristol	BL000950
86 Sliding Door	adjust sliding door top lock and road test						
Unplanned Vehicle Clean	03/03/2016	10:30	03/03/2016	14:00	17,579	Bristol	BL001082
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	22/03/2016	07:21	23/03/2016	15:30	19,564	Bristol	BL001339
18 Wheels Check Torques Safety Inspection							
Veh Deep Clean	22/03/2016	09:15	23/03/2016	02:50	19,574	Bristol	BL001343
Vehicle Deep Clean	Vehicle Deep Clean						

Breakdown	25/04/2016	00:18	25/04/2016	06:40	23,766	Bristol	BL001706
Breakdown	headlight out replace os headlight bulb						
Unplanned Repair	25/04/2016	14:09	25/04/2016	17:10	23,807	Bristol	BL001711
34 Emergency Lights	ns blue led light broken / replaced light unit						
45 Engine Ad Blue	topped up adblue						
86 Sliding Door	sliding door not opening from outside / replaced door lock motor / warranty						
Unplanned Repair	28/04/2016	13:27	28/04/2016	13:30	23,909	Bristol	BL001763
86 Sliding Door	Door not staying open replace bottom magnet and test						
Breakdown	03/05/2016	14:30	03/05/2016	23:00	24,851	Bristol	BL001803
Breakdown	flat rear drivers side tyre						
Breakdown	03/05/2016	17:45	03/05/2016	23:00	24,852	Bristol	BL001806
Breakdown	ATS saw earlier, advised other tyre needs changing						
Unplanned Repair	04/05/2016	15:30	04/05/2016	15:33	24,859	Bristol	BL001823
17 Tyres Replace	ats call out and replace tyre						
SAFETY INSPECTION	05/05/2016	07:54	05/05/2016	12:04	24,982	Bristol	BL001828
18 Wheels Check Torques							
Safety Inspection							
92 - C Service							
Service C							
UB Fire Suppression Service							
Tail Lift Inspection							

Unplanned Repair	02/06/2016	16:01	02/06/2016	16:03	28,660	Bristol	BL002150
55 Tail Lift	tail lift will not go up..repair wiring and fuse holder						
Unplanned Repair	07/06/2016	11:53	07/06/2016	14:07	29,375	Bristol	BL002195
02 Mirrors	new o/s mirror and covers						
Veh Deep Clean	23/06/2016	22:45	24/06/2016	04:00	31,342	Bristol	BL002379
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	24/06/2016	10:48	24/06/2016	15:07	31,345	Bristol	BL002385
18 Wheels Check Torques 34 Emergency Lights Safety Inspection Tail Lift Inspection	Other revering beacon intermittent.NFF						
Breakdown	06/07/2016	08:05	07/07/2016	10:22	33,060	Bristol	BL002535
Breakdown	reversing beeper not sounding						
SAFETY INSPECTION	03/08/2016	14:22	03/08/2016	21:46	37,545	Bristol	BL002869
13 Brakes 1 18 Wheels Check Torques 45 Engine Ad Blue 45 Engine Oil Top Up Safety Inspection Tail Lift Inspection Travel Time MOT	replaced front discs and pads topped up adblue						

Defect Repair	16/08/2016	15:05	16/08/2016	15:09	39,528	Bristol	BL003026
44 Add Ad Blue	top up ad blue						
Unplanned Repair	25/08/2016	16:35	25/08/2016	16:38	40,830	Bristol	BL003127
44 Fuel System 1	Fuel angel jammed remove and fit fuel cap						
SAFETY INSPECTION	13/09/2016	07:38	14/09/2016	12:44	43,279	Bristol	BL003334
02 Cab Ass Fire Extinguisher	replaced cab and saloon fire extinguishers as no date stickers						
02 Cab Assembly 1	replaced brake pedal rubber						
02 Mirrors	Body Exterior DAMAGE TO OFFSIDE WING MIRROR CASE, replaced surround						
02 Windscreen	topped up screen wash						
13 Brakes 1	changed brake fluid parts booked on d service						
13 Handbrake	adjusted handbrake cable						
17 Tyres Replace	replaced nsf tyre						
18 Wheels Check Torques							
44 Add Ad Blue	topped up adblue						
55 Tail Lift	lubed tail lift and adjusted						
86 Sliding Door	repaired side door stay magnet						
89 Seats	repaired saloon seat arm rest						
Safety Inspection							
Handbrake Cable Replacement	not replaced as not over 3yrs old						
93 - D Service							
Service D							
Vehicle Deep Clean	24/10/2016	10:45	25/10/2016	05:43	48,884	Bristol	BL003827
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/10/2016	21:00	26/10/2016	21:13	48,884	Bristol	BL003853
02 Windscreen	top up wash fluid						
17 Tyres Replace	fit 5 new tyres						
18 Wheels Check Torques							

44 Add Ad Blue	top up ad blue
45 Engine Oil Top Up	top up engine oil
55 Tail Lift	tail lift damaged, carry out repair to tail lift
Safety Inspection	
Tail Lift Inspection	carry out tail lift inspection

Unplanned Repair	22/11/2016	14:41	22/11/2016	14:46	53,056	Bristol	BL004193
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

44 Add Ad Blue	topped up ad blue
----------------	-------------------

Breakdown	29/11/2016	02:27	29/11/2016	13:36	54,189	Bristol	BL004291
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown	audio warning about pressure low
-----------	----------------------------------

Unplanned Repair	01/12/2016	18:26	01/12/2016	20:29	54,554	Bristol	BL004360
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

45 Engine Ad Blue	top up
-------------------	--------

Unplanned Repair	05/12/2016	10:04	05/12/2016	10:10	55,083	Bristol	BL004390
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Mirrors	Replace ns mirror glass
------------	-------------------------

Breakdown	07/12/2016	12:51	07/12/2016	21:21	55,484	Bristol	BL004425
------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Breakdown	fire suppression warning replace fire trace unit
-----------	--

SAFETY INSPECTION	07/12/2016	17:42	07/12/2016	19:46	55,486	Bristol	BL004431
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	Top up washers
18 Wheels Check Torques	
34 Lights	Replace nsr stop and tail light
44 Add Ad Blue	Top up ad blue
Safety Inspection	Carry out safety inspection
UB Fire Suppression Service	fit new
Gearbox Oil & Filter Change	Carry out gearbox oil and filter change
Tail Lift Inspection	Carry out tail lift inspection

Vehicle Deep Clean	07/12/2016	10:00	08/12/2016	02:30	55,486	Bristol	BL004434
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	10/01/2017	07:10	10/01/2017	18:06	60,679	Bristol	BL004920
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	topped up screen wash
13 Brake Pads	replaced rear pads
13 Discs	replaced rear discs
17 Tyres Replace	replaced osf tyre
18 Wheels Check Torques	
44 Add Ad Blue	topped up ad blue
Safety Inspection	
Fit Throw Lines & SOP	
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill
UB Fire Suppression Service	
Wheel Hub Flanges Replacement	not reqd as not over 3yrs old
Medical Device and Equip Check	checked Lsu already updated , all ok
Annual Heater Service	Annual Heater Service
92 - C Service	
Service C	
Tail Lift Inspection	

Vehicle Deep Clean	10/01/2017	21:15	11/01/2017	05:19	60,679	Bristol	BL004927
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	21/02/2017	08:17	21/02/2017	14:00	65,937	Bristol	BL005539
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Mirrors	replaced ns mirror parts as reqd
02 Windscreen	topped up screen wash
13 Brake Test	Carry out brake test
18 Wheels	cleaned all wheel hubs
18 Wheels Check Torques	
44 Add Ad Blue	topped up adblue
45 Engine Oil Top Up	topped up engine oil
89 Seats	carried out repair to saloon seat
Safety Inspection	
Annual Air Con Service	Annual Air Condition Service

Vehicle Deep Clean	21/02/2017	21:15	22/02/2017	02:40	65,937	Bristol	BL005550
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	07/03/2017	11:49	10/03/2017	15:53	65,937	Bristol	BL005791
55 Tail Lift	taillift will not operate - passed to alfa						
Breakdown	16/03/2017	13:43	17/03/2017	17:59	68,798	Bristol	BL005821
16 Suspension 1	check on lift and road test,suspect o/s front shocker (warranty) replace o/s running lamp bulb inop (no stock) replace N/s front knocking noise.						
34 Lights Bulb Replacement							
Breakdown							
Vehicle Deep Clean	06/04/2017	12:13	06/04/2017	12:14	71,263	Bristol	BL006062
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	06/04/2017	15:01	06/04/2017	21:00	71,263	Bristol	BL006064
02 Windscreen	top up new tyres clean up front and rear hubes top up refit new door bearings (drill out old top onces)						
17 Tyres Replace							
18 Wheels							
18 Wheels Check Torques							
45 Engine Oil Top Up							
86 Sliding Door							
Safety Inspection							
Vehicle Deep Clean	06/04/2017	07:00	06/04/2017	10:30	71,263	Bristol	BL006073
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	26/04/2017	15:31	26/04/2017	21:06	74,201	Bristol	BL006291

16 Suspension 1
Breakdown

replace N/S/F shock absorber
knocking noise

Breakdown **06/05/2017** **20:29** **07/05/2017** **16:07** **75,464** **Bristol** **BL006402**

44 Add Ad Blue topped up adblue
52 Electrical Aux carried out repair to damaged shoe line socket
55 Tail Lift carried out repair to bent toe plate
Breakdown Ramp has bent plate & not deploying

Breakdown **14/05/2017** **12:18** **15/05/2017** **15:52** **76,145** **Bristol** **BL006488**

Breakdown tail lift has a bent bar

Vehicle Deep Clean **15/05/2017** **11:00** **15/05/2017** **14:15** **76,159** **Bristol** **BL006493**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **15/05/2017** **16:08** **15/05/2017** **19:43** **76,159** **Bristol** **BL006497**

02 Windscreen Top up washers
13 Brakes 1 Replace front discs and pads
18 Wheels Check Torques
44 Add Ad Blue Top up ad blue
55 Tail Lift Straighten os tail lift rail
85 Body Interior 1 Straighten bracket for carry chair
87 - Stretchers/Chairs/Boards Bracket for stair pro on carry chair bent new chair required
Safety Inspection Carry out safety inspection

Awaiting Parts

Unplanned Repair **23/05/2017** **10:00** **23/05/2017** **13:12** **77,226** **Bristol** **BL006579**

44 Add Ad Blue topped up ad blue
86 Doors Rear Doors rear door stay loose / replaced door stay

Defect Repair	05/06/2017	10:16	05/06/2017	10:21	78,513	Bristol	BL006725
----------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

45 Engine 1	eml light on engine cut out,non start and no gears,star test clear codes/r/test						
-------------	---	--	--	--	--	--	--

Vehicle Deep Clean	14/06/2017	11:20	15/06/2017	04:15	79,776	Bristol	BL006883
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

MGS Gas Storage Modifications	15/06/2017	07:35	16/06/2017	13:49	79,776	Bristol	BL006884
--------------------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

MGS Gas Storage Modifications	MGS Gas Storage Modifications						
WAS Firetrace rework & Service							
UB Fire Suppression Service							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						

Emergency Deep Clean	19/06/2017	13:37	19/06/2017	13:40	79,987	Bristol	BL006927
-----------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Emergency Deep Clean							
----------------------	--	--	--	--	--	--	--

Unplanned Repair	22/06/2017	14:30	22/06/2017	14:45	80,480	Bristol	BL006973
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

44 Add Ad Blue	topped up adblue						
----------------	------------------	--	--	--	--	--	--

MRO Refresh	29/06/2017	03:45	29/06/2017	06:45	81,345	Bristol	BL007048
--------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

MRO Refresh							
-------------	--	--	--	--	--	--	--

SAFETY INSPECTION	29/06/2017	14:22	29/06/2017	21:36	81,348	Bristol	BL007055
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	Top up washers						
02 Windscreen Wipers	Replace wiper blades						
16 Suspension 1	All 4 spring buffers split only 1 in stock replace 1						
17 Tyres Replace	Replace nsf tyre						
18 Wheels Check Torques							
41 Air Intake	Replace turbo hoses						
44 Add Ad Blue	Top up ad blue						
55 Tail Lift	Resecure tail lift bars and straighten os rail						
	Awaiting Parts						

86 Sliding Door	Replace side door roller bearings
Safety Inspection	Carry out safety inspection
Tail Lift Annual Service	Statutory Inspection and Weight Test
Service D	Carry out D service
Tail Lift Inspection	Carry out tail lift inspection
Handbrake Cable Replacement	Not due until 3 years old
Travel Time	
MOT	

Vehicle Deep Clean	07/08/2017	21:30	08/08/2017	02:30	87,667	Bristol	BL007588
---------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	08/08/2017	17:23	09/08/2017	14:54	87,667	Bristol	BL007598
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

16 Suspension 1	All 4 spring buffers split only 1 in stock replace 1- this is an old deferral
18 Wheels Check Torques	
55 Tail Lift	Ramp/Lift/Tail Hoist damage to rear frame under tail lift
87 Chairs	Body Interior back seat in rear for patient loose, rocking (repair locks)
Safety Inspection	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card

Unplanned Repair	26/08/2017	11:21	26/08/2017	11:32	89,408	Bristol	BL007777
-------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

55 Tail Lift	o/s lift rail broken off (drill weild and cut repair and refit)
--------------	---

SAFETY INSPECTION	19/09/2017	13:36	19/09/2017	15:19	91,552	Bristol	BL008069
--------------------------	-------------------	--------------	-------------------	--------------	---------------	----------------	-----------------

02 Windscreen	Top up washers	
16 Suspension 1	Replace both nsr suspension buffers	
17 Tyres Replace	Replace osf and both nsr tyres	
18 Wheels Check Torques		
45 Engine Oil Top Up	Top up engine oil	
55 Tail Lift	Tail lift bridgeplate bars missing	Awaiting Parts
Safety Inspection	Carry out safety inspection	
UB Fire Suppression Service	Carry out fire suppression service	
Tail Lift Inspection	Carry out tail lift inspection	

Vehicle Deep Clean	19/09/2017	20:00	20/09/2017	01:30	91,552	Bristol	BL008076
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	29/09/2017	13:13	29/09/2017	13:19	93,275	Bristol	BL008219
71 Body External Steps	Other step motor running longer than needed, fit new motor and spindle,and lube						
Unplanned Repair	04/10/2017	07:59	09/10/2017	13:46	93,643	Bristol	BL008281
44 Add Ad Blue	top up						
55 Ramp	Ramp/Lift/Tail Hoist yellow side bar broken, fall off (n f f)						
71 Body Exterior 1	Body Interior passenger seat control panel has noise (n f f)						
71 Body External Steps	check out side step n/w right						
87 Chairs	chair lock and holder damaged refit new parts (drill out bolts and repair)						
Breakdown	22/10/2017	13:53	23/10/2017	19:24	95,443	Bristol	BL008486
34 Lights Bulb Replacement	replaced osf day running bulb						
45 Engine Ad Blue	topped up ad blue						
71 Body External Steps	side step not deploying / carried out repair to step assy						
Breakdown	side step not moving properly screws undone						
SAFETY INSPECTION	02/11/2017	06:57	02/11/2017	08:14	96,507	Bristol	BL008621
02 Windscreen	topped up screenwash						
17 Tyres Replace	replaced rear tyre						
18 Wheels Check Torques							
18 Wheels Removal	cleaned all wheel hubs						
41 Air Intake	replaced air filter						
45 Engine Ad Blue	topped up adblue						
52 Electrical Aux	replaced shoreline cover						
55 Tail Lift	Both tail lift rails siezed free off and lubricate						
71 Body Exterior 1	Two striker plate guides missing fit new guides						

Safety Inspection
92 - C Service
Service C
Tail Lift Inspection

Vehicle Deep Clean **02/11/2017** **17:00** **02/11/2017** **23:30** **96,507** **Bristol** **BL008634**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **15/11/2017** **14:34** **16/11/2017** **13:05** **97,605** **Bristol** **BL008777**

Breakdown Locker door on the outside

Breakdown **11/12/2017** **13:11** **11/12/2017** **13:59** **100,220** **Bristol** **BL009034**

Breakdown F/N/S TREAD

Vehicle Deep Clean **15/12/2017** **02:40** **15/12/2017** **08:30** **100,539** **Bristol** **BL009080**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **15/12/2017** **15:28** **15/12/2017** **20:43** **100,539** **Bristol** **BL009090**

02 Windscreen Top up washers
17 Tyres Replace Replace osr outer tyre
18 Wheels Check Torques
86 Door Lock Rear door lock siezed replace lock set
87 - Stretchers/Chairs/Boards Tracks missing replace with SNCT05314T
Safety Inspection Carry out safety inspection
Annual Heater Service Annual Heater Service
Annual Air Con Service Annual Air Condition Service
Tail Lift Inspection Carry out tail lift inspection

Awaiting Parts
Awaiting Parts

Breakdown **01/01/2018** **07:02** **01/01/2018** **13:39** **102,163** **Bristol** **BL009265**

Breakdown Puncture

Breakdown	21/01/2018	09:27	22/01/2018	08:11	102,170	Bristol	BL009521
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	key not turn ignition,called weston station,and got crew to check all ok.						
-----------	---	--	--	--	--	--	--

Vehicle Deep Clean	23/01/2018	06:57	23/01/2018	10:27	102,172	Bristol	BL009538
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	23/01/2018	16:39	23/01/2018	19:30	102,180	Bristol	BL009548
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	x2						
13 Brake Pads	new rear pads						
18 Wheels Check Torques							
18 Wheels Removal	clean hubs						
87 Stretcher Harness Replaced	single belt						
Safety Inspection							
Tail Lift Annual Service	Statutory Inspection and Weight Test						

Breakdown	03/03/2018	01:19	05/03/2018	08:46	102,190	Bristol	BL010033
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	key broken on station						
-----------	-----------------------	--	--	--	--	--	--

SAFETY INSPECTION	08/03/2018	12:16	09/03/2018	14:32	102,837	Bristol	BL010104
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

16 Suspension 1	front shochs						
18 Wheels Check Torques							
18 Wheels Removal	clean hubs						
45 Engine Ad Blue	top up						
45 Engine Oil Top Up	top up						
87 Chairs	Med Equip & Devices carry chair bracket for tracks buckled (repair)						
Safety Inspection							
85 Body Int Alcohol Gel Dispen							
UB Fire Suppression Service							
Gearbox Oil & Filter Change							
Tail Lift Inspection							
Travel Time							
MOT							

Tail Lift Annual Service	Statutory Inspection and Weight Test						
Vehicle Deep Clean	08/03/2018	16:00	08/03/2018	22:30	102,837	Bristol	BL010111
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	01/04/2018	13:57	02/04/2018	13:45	110,386	Bristol	BL010373
Breakdown	flat battery,non start						
Unplanned Repair	04/04/2018	17:56	04/04/2018	18:01	110,733	Bristol	BL010409
02 Mirrors	carry out repair to O/S mirror						
SAFETY INSPECTION	17/04/2018	15:18	17/04/2018	21:50	111,860	Bristol	BL010531
02 Cab Ass Fire Extinguisher	fire extinguisher out of date - replace						
02 Windscreen	top up screenwash						
17 Tyres Replace	n/s/f wheel damaged and n/s/r tyres 3mm - replace						
18 Wheels Check Torques							
18 Wheels Removal	remove and clean wheel flanges						
34 Emergency Lights	n/s/r top blue lens smashed						
34 Lighting System	n/s/f top side light and n/s marker light not working - carry out repair						
52 Electrical Aux	Electrical Auxs Charging port on driver side of vehicle pins bent						
55 Tail Lift	guard rails siezed - free off and lubricate						
71 Body Exterior 1	camera bracket bent - straighten so camera is visible						
71 Body Exterior 2	front registration plate cracked						
71 Body External Steps	other side step hazard plastic damaged - carry out repair						
87 Stretcher	refit straps to correct locations						
Safety Inspection	Carry out safety inspection						
Fit Poster Holder	Fit Poster Holder						
Vehicle Deep Clean	18/04/2018	07:01	18/04/2018	13:52	111,860	Bristol	BL010533
Vehicle Deep Clean	Vehicle Deep Clean						

Awaiting Parts

Breakdown	11/05/2018	18:22	11/05/2018	20:22	113,916	Bristol	BL010807
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

31 Battery Chassis	replaced battery
31 Charging System	tested charge rate and tested battery
Breakdown	Failed to start

Breakdown	26/05/2018	21:14	01/06/2018	09:05	115,755	Bristol	BL010989
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	stuck in mud
-----------	--------------

Vehicle Deep Clean	30/05/2018	09:45	04/06/2018	22:08	116,110	Bristol	BL011012
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	30/05/2018	14:59	11/06/2018	09:34	116,111	Bristol	BL011018
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	engine non start.emergency button ok,need look at	
16 Suspension 1	rear arb bushes	
18 Wheels Check Torques		
43 Exhaust System 1	replace tail pipe	
52 Electrical Aux	aux distributor unit faulty	Awaiting Parts
71 Body Exterior 2	front registration plate cracked,replace number plate	
99 Diagnostic Test	aux system check	
Safety Inspection		
93 - D Service		
Service D		
Handbrake Cable Replacement	Replace rear handbrake cables	

Vehicle Deep Clean	19/07/2018	08:00	19/07/2018	13:30	119,883	Bristol	BL011557
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	19/07/2018	14:40	23/07/2018	06:55	119,883	Bristol	BL011563
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windows/Glass	top up windscreen washers	
13 Brake Pads	front pads worn low	Awaiting Parts
18 Wheels Check Torques		

34 Lights checked for problem with bulbs failing all ok
 52 Electrical Aux aux distributor unit faulty old defect
 55 Tail Lift rear bump bars drilled and repaired
 86 Doors nsf window switch broken
 Safety Inspection
 Wheel Hub Flanges Replacemefront hub flanges and nuts replaced

Breakdown 28/07/2018 00:07 28/07/2018 00:10 120,246 Bristol BL011660

Breakdown 7403 O/S headlight out

Unplanned Repair 16/08/2018 14:09 17/08/2018 14:13 122,131 Bristol BL011867

02 Mirrors nsf mirrors and refit casings

Vehicle Deep Clean 24/08/2018 01:14 24/08/2018 13:58 123,023 Bristol BL011936

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 24/08/2018 08:56 24/08/2018 15:29 123,023 Bristol BL011939

18 Wheels Check Torques
 86 Doors Rear repair kit rear door (o\s and n\s doors)
 Safety Inspection
 Tail Lift Inspection
 UB Fire Suppression Service

Vehicle Deep Clean 04/10/2018 07:10 04/10/2018 23:42 127,475 Bristol BL012341

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 04/10/2018 07:55 05/10/2018 08:48 127,475 Bristol BL012343

17 Tyres Replace new tyre
 18 Wheels Check Torques

18 Wheels Removal clean hubs
 71 Body External W&T Repair drill and repair rear mud flap
 Safety Inspection

SAFETY INSPECTION 13/11/2018 07:16 14/11/2018 09:14 131,204 Bristol BL012767

13 Brakes 1 front pads and discs with sensors (clean and lub caliper pins)
 13 Brakes 2 new rear pads discs and sensors (clean and lub caliper pins)
 16 Suspension 1 front shocks
 16 Suspension 2 spring rubbers rear
 17 Tyres Replace 5x tyres
 18 Wheels Check Torques
 18 Wheels Removal clean hubs
 Safety Inspection
 Fit 3rd Helmet Restraint Fit 3rd Helmet Restraint in Cab
 Sealing of stretcher clamp Sealing of stretcher clamp
 Tail Lift Inspection
 Annual Air Con Service Annual Air Condition Service
 Annual Heater Service Annual Heater Service
 92 - C Service
 Service C

Vehicle Deep Clean 14/11/2018 10:30 15/11/2018 00:01 131,207 Bristol BL012788

Vehicle Deep Clean Vehicle Deep Clean

Breakdown 05/12/2018 19:11 07/12/2018 15:05 134,018 Bristol BL012992

31 Charging System tested alternator not charging replaced alternator and rechecked
 Breakdown Aux battery warning and lose of power
 Road Test carried out roadtest after engine and belt work

SAFETY INSPECTION 11/12/2018 11:01 12/12/2018 06:58 134,251 Bristol BL013055

15 Steering 1 Steering pulling to right check and adjust steering
 16 Suspension 1 clinking noise from front (remove all rear brakes check all ok)
 16 Suspension 2 road test for noise and pulling

18 Wheels
55 Ramp
Safety Inspection
Wheel Hub Flanges Replaceme

play in old type wheels and rusty hubs
ramp plate damaged remove repair and refit with new bolt
refit new pedmate (not a safety inspection)

Vehicle Deep Clean **11/12/2018** **15:37** **13/12/2018** **07:07** **134,253** **Bristol** **BL013059**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **27/12/2018** **11:44** **28/12/2018** **11:02** **134,803** **Bristol** **BL013221**

17 Tyres Replace
18 Wheels Check Torques
Safety Inspection

BREAKDOWN **15/01/2019** **21:43** **25/01/2019** **12:11** **136,222** **Bristol** **BL013399**

41 Turbo
45 Engine 1
45 Engine Ad Blue
99 Diagnostic Test

citywest to replace turbo
EML On - Loss Of Power - Turbo Failure
Ad-Blue Bottle Cap Missing - Fitted New Cap
Diagnostic Test For EML - Code For Turbo Pressure Stored

Breakdown **25/01/2019** **18:24** **29/01/2019** **15:17** **136,222** **Bristol** **BL013495**

Breakdown Fumes in cab/ exhaust leak

Vehicle Deep Clean **06/02/2019** **07:29** **06/02/2019** **13:02** **139,058** **Bristol** **BL013598**

Vehicle Deep Clean Vehicle Deep Clean

RE-ISSUE INSPECTION **07/02/2019** **08:25** **07/02/2019** **12:31** **139,058** **Bristol** **BL013617**

Re-Issue Inspection
UB Fire Suppression Service
Tail Lift Inspection

saftey inspection

Travel Time
MOT
Tail Lift Annual Service Statutory Inspection and Weight Test

Breakdown 19/02/2019 11:37 19/02/2019 13:33 140,618 Bristol BL013734

Breakdown 7403 - OSF headlight changed

Vehicle Deep Clean 20/03/2019 12:31 20/03/2019 12:32 144,798 Bristol BL013985

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 20/03/2019 15:45 21/03/2019 08:21 144,798 Bristol BL013988

16 Suspension 1 replace rear spring buffers
18 Wheels Check Torques
45 Engine Ad Blue top up ad blue
45 Engine Oil Top Up top up engine oil
86 Doors replace sliding door rollers
89 Seats tighten seat swivel pin
Safety Inspection

Vehicle Deep Clean 01/05/2019 07:00 01/05/2019 20:00 150,456 Bristol BL014389

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 03/05/2019 12:24 06/05/2019 12:16 150,456 Bristol BL014411

02 Cab Ass Fire Extinguisher Replaced CAB And Saloon Fire Extinguishers
02 Windscreen Topped Up Screenwash
17 Tyres Replace Replaced Both Front Tyres
18 Wheels Check Torques
18 Wheels Removal Cleaned All Hubs And Flanges
44 Add Ad Blue Topped Up Ad-Blue
44 Fuel System 1 Fitted Fuel Solo
Safety Inspection Carried Out Safety Inspection
Tail Lift Inspection Carried Out Tail Lift Inspection

Breakdown	26/05/2019	07:16	28/05/2019	10:20	153,235	Bristol	BL014600
Breakdown	not charging when charge/engine on;stretcher						
SAFETY INSPECTION	11/06/2019	10:59	12/06/2019	12:05	154,903	Bristol	BL014731
02 Windscreen	Topped Up Screenwash						
02 Windscreen Wipers	Replaced Wiper Blades						
15 Steering 1	renew rack arms						
18 Wheels Check Torques							
18 Wheels Removal	Clean All Hubs And Flanges						
31 Battery Comms	Replace Faulty Comms Battery						
34 Lighting System	Nearside Front Orange Marker Light Not Working						
52 Electrical Aux	fit new distribution box check charging system all ok						
Fire suppression Service	Fire Suppression Warning - Carried Out Bypass						
Safety Inspection	Carry Out Safety Inspection						
Pollen Filter Change	Pollen Filter Change						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Replace Handbrake Cables	Replace Handbrake Cables - Inspection Only						
Vehicle Deep Clean	14/06/2019	16:00	14/06/2019	23:59	155,348	Bristol	BL014791
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	30/06/2019	23:02	01/07/2019	11:46	155,400	Bristol	BL014904
Breakdown	stryker battery dead						
Breakdown	13/07/2019	20:21	18/07/2019	08:56	158,464	Bristol	BL015046
01 Air Conditioning 1	RENEW REAR CONDENSOR AND FAN						
15 Steering 1	DRAIN AND REFIL POWER STEERING FLUID						
16 Suspension 1	RENEW FRONT SHOCKERS						

Breakdown heavy steering

Vehicle Deep Clean 31/07/2019 12:27 31/07/2019 12:29 159,464 Bristol BL015223

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION 31/07/2019 15:05 01/08/2019 11:23 159,465 Bristol BL015224

02 Windscreen	Top Up Screenwash
17 Tyres Replace	Replaced All 4 Tyres Across The Rear Axle
18 Wheels Check Torques	Torque All Wheel Nuts
18 Wheels Removal	Clean All Hubs And Flanges
Medical Devices Service	Medical Devices Paediatric restraint system - parts missing.
Safety Inspection	Carry Out Safety Inspection
UB Fire Supp 12mts Service	Carry Out Service Of Fire Suppression System
Tail Lift Inspection	Carry Out Tail Lift Inspection

SAFETY INSPECTION 03/09/2019 08:00 05/09/2019 15:07 162,372 Bristol BL015472

02 Cab Assembly 1	replaced brake pedal rubber
02 Windscreen	topped up screen wash
13 Brake Pads	replaced rear pads
16 Suspension 1	removed rear springs and replaced worn bushes
18 Wheels	cleaned and sprayed road wheels
18 Wheels Check Torques	
18 Wheels Removal	cleaned wheel hubs
44 Add Ad Blue	refilled adblue
45 Engine Oil Top Up	topped up engine oil
71 Body External Steps	replaced step mudflap
86 Door Seals	replaced os door seal
86 Doors	replaced os door control panel
Safety Inspection	
Tail Lift Inspection	
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service

Vehicle Deep Clean 05/09/2019 17:30 05/09/2019 23:59 162,372 Bristol BL015503

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean	24/10/2019	21:30	25/10/2019	03:30	168,652	Bristol	BL015927
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	25/10/2019	07:50	28/10/2019	11:12	168,652	Bristol	BL015942
02 Windows/Glass 13 Brakes 1 15 Steering 1 17 Tyres Replace 17 Tyres Tracking 18 Wheels Check Torques 45 Engine Oil Top Up 85 Body Interior 1 Safety Inspection	front discs and pads steering rack replaced						
Breakdown	13/11/2019	22:43	14/11/2019	09:38	170,454	Bristol	BL016122
01 Heating 1 Breakdown	Blower Motor And Resister Faulty - Replaced Faulty Parts Demisters Not Working						
Breakdown	24/11/2019	09:19	25/11/2019	09:11	171,193	Bristol	BL016219
17 Tyres Replace 45 Engine Ad Blue Breakdown	replaced nsr outer tyre topped up adblue rear near side outer tyre						
Breakdown	30/11/2019	19:20	30/11/2019	19:21	172,157	Bristol	BL016281
Breakdown	7403 - nearside mirror lens missing						
Breakdown	30/11/2019	20:51	03/12/2019	07:33	172,157	Bristol	BL016282
Breakdown	7403 - wing mirror detached - In Weston						

SAFETY INSPECTION	03/12/2019	07:15	04/12/2019	07:40	172,526	Bristol	BL016297
02 Cab Assembly 1	replaced tool box cover						
02 Windscreen	topped up screen wash						
13 Handbrake	refitted handbrake cover						
18 Wheels Check Torques							
18 Wheels Removal	cleaned wheel hubs						
44 Add Ad Blue	topped up adblue						
55 Tail Lift	replaced tilt switch and lubed handrail						
Safety Inspection							
Wheel Hub Flanges Replacement	replaced rear hubs						
Engine Change Oil & Filter							
Vehicle Deep Clean	03/12/2019	16:00	03/12/2019	21:00	172,526	Bristol	BL016309
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	06/12/2019	10:00	06/12/2019	10:44	172,640	Bristol	BL016384
34 Lights Bulb Replacement	replaced ns headlight bulb						
44 Add Ad Blue	topped up adblue						
Vehicle Deep Clean	20/01/2020	12:49	20/01/2020	12:51	178,141	Bristol	BL016798
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/01/2020	19:42	23/01/2020	12:22	178,144	Bristol	BL016803
02 Windscreen	Topped Up Screenwash						
02 Windscreen Wipers	Replaced Wiper Blades						
18 Wheels Check Torques	Torqued All Wheel Nuts						
18 Wheels Removal	Cleaned All Hubs And Flanges						
86 Sliding Door	Roller Bearings Noisy						
87 Stretcher	Replaced Split Mattress						
89 Seats	Rear Captain Seat Base Cushion Split						
Road Test	Take Vehicle To MOT - Wait - Return With Vehicle						
Safety Inspection	Carried Out Safety Inspection						
Tail Lift Inspection	Carry Out Tail Lift Inspection						
Auto G/box Oil & Filter Change	Carried Out Auto G/Box Oil & Filter Change						
MOT	Carry Out MOT Test						

Brakes Replace Brake Fluid	Carried Out Brake Fluid Change
Tail Lift 12M Service & Weight	Carry Out Tail Lift 12M Service & Weight Test
Engine Change Oil & Filter	Carried Out Engine Oil And Filter Change
Pollen Filter Change	Carried Out Pollen Filter Change
Axle Oil Change	Carried Out Rear Axle Oil Change
Fuel Filter Change	Carried Out Fuel Filter Change
Air Filter Change	Carried Out Air Filter Change

UB Fire Supp 6mts Service	19/02/2020	14:07	19/02/2020	14:25	181,355	Bristol	BL017159
----------------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	replaced os headlight
----------------------------	-----------------------

Vehicle Deep Clean	26/02/2020	07:10	26/02/2020	10:13	182,294	Bristol	BL017213
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	27/02/2020	16:08	27/02/2020	16:27	182,297	Bristol	BL017237
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Ass Fire Extinguisher	Replaced cab fir extinguisher
13 Brakes 1	Replaced rear discs and pads
18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service

Breakdown	14/03/2020	07:27	14/03/2020	08:42	184,551	Bristol	BL017361
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	O/S rear Outer
-----------	----------------

SAFETY INSPECTION	27/03/2020	08:48	27/03/2020	14:08	186,138	Bristol	BL017528
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

16 Suspension 1	Replace anti roll bar bushes
17 Tyres Replace	Both front tyres and outer nearside rear
18 Wheels Check Torques	
44 Add Ad Blue	Top up

45 Engine Oil Top Up	Top up
55 Tail Lift	Tilt switch
71 Body Exterior 1	Replace address on side door
85 Body Interior 1	Side door equip strap
Pollen Filter Change	Pollen Filter Change
Safety Inspection	

Vehicle Deep Clean	29/03/2020	11:29	29/03/2020	14:18	186,141	Bristol	BL017543
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

MRO Refresh	20/04/2020	13:35	20/04/2020	13:36	188,690	Bristol	BL017838
--------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

MRO Refresh	
-------------	--

SAFETY INSPECTION	06/05/2020	18:40	07/05/2020	15:20	190,209	Bristol	BL018032
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

01 Air Conditioning 1	Rear air con inop removed a/c unit tested found faulty fuse
18 Wheels Check Torques	
34 Lighting System	replace rear door interior light
34 Lights Bulb Replacement	nearside drl
55 Tail Lift	Replaced slow tilt and light murcary switch
86 Doors Rear	Replace offside rear door stay and block
86 Sliding Door	readjust door magnet
Heater Service	Heater repair blower tube and fan
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables

Vehicle Deep Clean	07/05/2020	13:17	07/05/2020	22:00	190,209	Bristol	BL018045
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	18/06/2020	13:26	19/06/2020	09:14	195,046	Bristol	BL018441
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	stiff steering
-----------	----------------

Vehicle Deep Clean	19/06/2020	13:09	19/06/2020	13:10	195,069	Bristol	BL018455
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	20/06/2020	10:10	21/06/2020	12:24	195,069	Bristol	BL018463
02 Cab Assembly 1	Replace 1 Faulty Hand Torch						
02 Windscreen	Top Up Screenwash						
18 Wheels Check Torques	Torque All Wheel Nuts						
86 Doors Rear	Doors Rear Door Stay Broken - OLD DEFECT						
Safety Inspection	Carry Out Safety Inspection						
Tail Lift Inspection	Carry Out Tail Lift Inspection						
Breakdown	30/07/2020	07:08	30/07/2020	15:43	198,841	Bristol	BL018816
Breakdown	No PAS,fitted both belts and both tensioners						
Vehicle Deep Clean	04/08/2020	22:30	05/08/2020	05:30	199,262	Bristol	BL018875
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	05/08/2020	11:31	07/08/2020	12:40	199,262	Bristol	BL018880
02 Windscreen	Top Up Screenwash						
13 Brake Pads	Replace Worn Front Brake Pads						
17 Tyres Replace	Replace Both Front Worn Tyres						
18 Wheels Check Torques	Torque All Wheel Nuts						
18 Wheels Removal	Clean All Hubs And Flanges						
71 Body Exterior 1	Nearside Bodywork Damage						
85 Body Interior 1	Carry Out Repair To Pull-Out Work Shelf In The Saloon						
Safety Inspection	Carry Out Safety Inspection						
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
UB Fire Supp 12mts Service	Carry Out Service Of Fire Supression System						
UB Fire Supp 6mts Service	Carry Out UB Fire Supp 6mts Service						
Annual Air Con Service	Carry Out Annual Air Condition Service						
Annual Heater Service	Carry Out Annual Heater Service						

Unplanned Repair	17/08/2020	15:31	17/08/2020	15:42	200,090	Bristol	BL019020
87 Stretcher	Replace strecher base plate						
Vehicle Deep Clean	09/09/2020	19:00	09/09/2020	23:59	201,154	Bristol	BL019259
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	10/09/2020	08:28	14/09/2020	15:53	201,154	Bristol	BL019263
13 Brake Pads	Replaced rear pads						
16 Suspension 1	Replaced both front anti roll bar links						
16 Suspension 2	Replace rear spring buffers						
18 Wheels Check Torques							
27 Transmission Automatic	Replace front prop bush						
45 Engine 1	injectors leaking						
55 Tail Lift	Replaced nearside hydrolic hose and stow buffer						
56 Comms Equipment	Replace comms airel						
85 Body Interior 1	Replaced side door equip strap						
85 Body Interior 2	Blower fan in rear inop replaced fuse						
87 Chairs	Replaced leg strap						
87 Stretcher Harness Replaced							
Safety Inspection							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
Tail Lift Inspection							
Unplanned Repair	21/09/2020	19:00	21/09/2020	19:15	201,816	Bristol	BL019376
44 Add Ad Blue	topped up ad blue						
Breakdown	27/09/2020	14:41	28/09/2020	08:21	202,397	Bristol	BL019436
02 Mirrors	replaced ns mirror parts						
Breakdown	N/S Wing Mirror and Housing Broke						

Unplanned Repair	07/10/2020	18:15	07/10/2020	18:39	203,198	Bristol	BL019568
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	replaced ns headlight bulb
----------------------------	----------------------------

Unplanned Repair	11/10/2020	07:00	11/10/2020	12:00	203,198	Bristol	BL019617
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

87a - Medical Equipment Repair	VSM charging lead missing - find wiring and repair plug
89 Seatbelts	renew saloon seat belt stalk

Vehicle Deep Clean	28/10/2020	11:46	29/10/2020	12:17	204,802	Bristol	BL019818
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	28/10/2020	16:03	31/10/2020	07:26	204,802	Bristol	BL019822
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	replaced centre console button
02 Windows/Glass	Replace Damaged Nearside Window Control Switch Unit
02 Windscreen	Top Up Screenwash
18 Wheels Check Torques	Torque All Wheel Nuts
18 Wheels Removal	Clean All Hubs And Flanges
27 Transmission Automatic	Replace Faulty Rear Short Propshaft
42 Coolant System	Replace Coolant Bottle And Cap
45 Engine 1	EML On Dash - Faulty Coolant Level Sensor
87 Stretcher	Shoulder Belts Missing On Stretcher - Old Defect
Safety Inspection	Carry Out Safety Inspection
Engine Change Oil & Filter	Carry Out Engine Oil And Filter Change
Tail Lift Inspection	Carry Out Tail Lift Inspection
MOT	Carry Out MOT Test
Tail Lift 12M Service & Weight	Carry Out Tail Lift 12M Service And Weight Test

Breakdown	10/11/2020	11:51	11/11/2020	21:30	206,457	Bristol	BL019939
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	replaced missing fuse box cover
02 Windscreen Wipers	replaced wiper kit
43 Exhaust System 1	replaced exhaust nox sensors / adblue injector / dpf clean and regen
44 Add Ad Blue	topped up adblue

99 Diagnostic Test	carried out test nox sensors and adblue injector on order
Breakdown	Adblue warning on
Road Test	carried out motorway road test

Breakdown	28/11/2020	11:04	30/11/2020	09:07	206,457	Bristol	BL020159
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

43 Exhaust System 1	Carry Out DPF Regen
99 Diagnostic Test	Found DPF At 189% Blocked
Breakdown	Loss of Power
Road Test	Carry Out Extended Road Test After Work Carried Out

Vehicle Deep Clean	03/12/2020	12:50	03/12/2020	12:51	207,456	Bristol	BL020219
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	03/12/2020	09:43	04/12/2020	14:46	207,456	Bristol	BL020236
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brakes 1	renew front discs and pads
17 Tyres Replace	x 4
18 Wheels Check Torques	
89 Seats	replace seat fram, cover and foam
Safety Inspection	

O2 Pipeline Annual Inspection	04/12/2020	14:24	04/12/2020	14:28	207,456	MDT Bristol	TB001827
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Pipeline Annual Inspection	Replace O2 Probes (75.32 + vat), Terminal service pack SKTU001 (£8.07 + Vat)
-------------------------------	--

Breakdown	17/12/2020	08:51	17/12/2020	19:39	211,397	Bristol	BL020360
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

43 Exhaust System 1	Carried out dpf re-gen twice and reconfigured nox sensors
43 Exhaust System 2	Carried out dpf flush
99 Diagnostic Test	
Breakdown	Limp mode - eml on
Road Test	

Unplanned Repair	31/12/2020	10:48	14/01/2021	12:37	212,588	Bristol	BL020513
33 Ignition System	replace lost key and fob						
Unplanned Repair	01/01/2021	09:37	06/01/2021	15:44	211,500	Bristol	BL020518
02 Mirrors	Mirrors Missing off side bottom wing mirror requires new dpf and egr cooler test system found fill level of dpf full						
43 Exhaust System 1							
99 Diagnostic Test							
Breakdown	07/01/2021	10:50	07/01/2021	16:03	211,550	Bristol	BL020584
Breakdown	Saloon Heating No Hot Air,strip down and repair heater using second hand parts						
SAFETY INSPECTION	15/01/2021	14:23	15/01/2021	21:33	213,588	Bristol	BL020673
02 Windscreen	topped up screen wash adjusted handbrake						
13 Handbrake							
18 Wheels Check Torques	topped up adblue topped up engine oil replaced linen cupboard trim						
44 Add Ad Blue							
45 Engine Oil Top Up							
85 Body Interior 1	replaced linen cupboard trim						
Safety Inspection							
Wheel Hub Flanges Replaceme							
UB Fire Supp 6mts Service							
	UB Fire Supp 6mts Service						
Vehicle Deep Clean	15/01/2021	17:00	16/01/2021	10:37	214,588	Bristol	BL020679
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	18/01/2021	08:17	18/01/2021	19:18	214,588	Bristol	BL020697
Breakdown	offside headlight not working on dipped beam						

Breakdown	30/01/2021	05:59	31/01/2021	15:03	215,500	Bristol	BL020813
34 Lights	replace flasher bulb						
34 Lights Bulb Replacement	replace h/light bulb						
71 Body External Steps	Replaced step switch and sliding door buffers						
86 Sliding Door	replace sliding door centre hinge and rollers and adjust ,clean runners lube						
99 Diagnostic Test	Checked step module wiring loom						
Breakdown	side door opens whilst driving,replace innder handle and adjust cables						
Breakdown	06/02/2021	20:13	07/02/2021	06:27	217,351	Bristol	BL020908
Breakdown	O/S headlight blown						
Unplanned Repair	08/02/2021	13:17	08/02/2021	13:20	217,351	Bristol	BL020917
71 Body External Steps	not extending fully						
86 Sliding Door	not staying shut						
Vehicle Deep Clean	02/03/2021	21:38	03/03/2021	18:20	221,332	Bristol	BL021128
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	04/03/2021	06:43	09/03/2021	13:39	221,332	Bristol	BL021155
02 Mirrors	o/s mirror damaged						
13 Brakes 1	renew rear discs, pads and shoes						
17 Tyres Replace	renew tyres x 4						
18 Wheels Check Torques							
27 Transmission Automatic	replace gearbox pipes						
34 Lighting System	renew marker light						
34 Lights	Lighting System side repeater blown - Indicators flashing fast						
55 Tail Lift	replace mercury switch						
71 Body Exterior 2	renew scoop strap						
85 Body Interior 1	replace toolbox cover						
86 Sliding Door	renew magnets						
Road Test	road tested after gearbox work						
Safety Inspection							

UB Fire Supp 12mts Service Service of fire suppression system
Wheel Hub Flanges Replaceme

Breakdown	30/03/2021	20:36	31/03/2021	15:19	224,995	Bristol	BL021401
Breakdown	Side door handle snapped off						
Unplanned Repair	31/03/2021	21:53	31/03/2021	21:55	225,116	Bristol	BL021411
86 Sliding Door	outer door handle replaced pcs						
Unplanned Repair	06/04/2021	14:15	06/04/2021	15:23	226,199	Bristol	BL021458
86 Sliding Door	side door not opening / stripped and repaired / replaced top lock rivets						
Breakdown	11/04/2021	22:06	12/04/2021	07:55	226,967	Bristol	BL021509
Breakdown	side door sticking from outside						
Unplanned Repair	12/04/2021	15:17	12/04/2021	15:21	227,021	Bristol	BL021517
34 Lights	Electrical Auxs N/S SIDELIFGT OUT Step noisy/Replaced motor						
71 Body External Steps							
SAFETY INSPECTION	14/04/2021	07:29	14/04/2021	16:07	227,164	Bristol	BL021536
13 Brakes 1	replace front brake pads and discs and o/s/f caliper						
18 Wheels Check Torques							
34 Lights	replace broken map light						
34 Lights Bulb Replacement	replace both daytime running lights and n/s headlight bulb						
45 Engine Ad Blue	top up ad blue						
45 Engine Oil Top Up	top up engine oil						
86 Doors	repair side door centre hinge and adjust door						
87a - Medical Equipment Repair	replace stryker harness						
Safety Inspection							
Tail Lift Inspection							
Fuel Filter Change	Change Fuel Filter						

Air Filter Change Pollen Filter Change	Air Filter Change Pollen Filter Change						
Vehicle Deep Clean	15/04/2021	13:43	15/04/2021	13:46	227,175	Bristol	BL021554
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	02/05/2021	13:47	03/05/2021	13:24	229,555	Bristol	BL021736
44 Fuel System 1 85 Body Interior 1 86 Door handle Replace Handbrake Cables	Fuel leak CCTV diagnostics- re-formatted hard drive 02/05/2021 Doors Rear door handle Cracked Replace Handbrake Cables						
Breakdown	10/05/2021	16:43	10/05/2021	16:51	230,467	Bristol	BL021843
86 Doors Rear 86 Sliding Door Breakdown	re fit rear door latches and adjust all ok sliding door top magnet re fit all ok 2403 - rear door latch detached						
Breakdown	19/05/2021	18:00	20/05/2021	11:39	231,342	Bristol	BL021956
Breakdown	7403 - Stryker stretcher wing not locking						
Unplanned Repair	20/05/2021	10:31	20/05/2021	10:34	231,402	Bristol	BL021971
85 Body Interior 1	CCTV Check - All Ok						
Breakdown	22/05/2021	02:07	22/05/2021	08:38	231,608	Bristol	BL022005
99 Diagnostic Test Breakdown Install Saloon CCTV Camera Road Test	Code read faults and live data found DPF Blocked regen DPF 7403 - limp mode CCTV checked ok Road tested after DPF regen code read ok						

Breakdown	23/05/2021	23:50	01/06/2021	08:25	231,769	Bristol	BL022018
45 Engine 1 Breakdown	rygor chilcompton Limp mode						
SAFETY INSPECTION	01/06/2021	16:14	01/06/2021	16:29	231,798	Bristol	BL022102
02 Windows/Glass 18 Wheels Check Torques 44 Fuel System 1 Safety Inspection Engine Change Oil & Filter Tail Lift Inspection	pcs fuel tank heat shield loose pcs to carry out						
Vehicle Deep Clean	01/06/2021	16:15	01/06/2021	22:15	231,798	Bristol	BL022106
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	03/06/2021	19:08	04/06/2021	08:47	231,922	Bristol	BL022127
Breakdown	Tail lift won't stow cews have not come in						
Breakdown	04/06/2021	18:17	06/06/2021	11:52	231,953	Bristol	BL022139
55 Tail Lift 99 Diagnostic Test Breakdown	replace mercury switch and repair wiring and toggle switch tested all ok test tail lidt faul found with switch wiring and toggle switch Query Battery Gone. Not deploying						
Unplanned Repair	16/06/2021	10:45	16/06/2021	17:15	232,600	Bristol	BL022268
01 Air Conditioning 1	air con not working / checked system and replaced rear fan assy						
Breakdown	27/06/2021	13:20	28/06/2021	08:33	233,649	Bristol	BL022378
45 Engine 1 Air Filter Change Breakdown	carry out star tests and check codes Air Filter Change,change air filter as blocked LIMP MODE NO WARNING LIGHTS						

Fuel Filter Change Road Test	Change Fuel Filter,replace fuel filter as heater element faulty. carry out r/test after fitting parts and clearing codes ok at time of test						
Unplanned Repair	30/06/2021	08:51	02/07/2021	21:40	233,759	Bristol	BL022397
01 Air Conditioning 1	Saloon Air Con Not Working - Check - Test - Replace Blown Fuse						
02 Windscreen	Top Up Screenwash						
02 Windscreen Wipers	Replace Wiper Blades						
18 Wheels Removal	Clean All Hubs And Flanges						
34 Lights Bulb Replacement	Replace Blown Nearside Front Side Light And DRL Bulbs						
44 Add Ad Blue	Top Up Ad Blue						
44 Fuel System 1	Replace Missing Fuel Flap Buffers						
89 Seats	Replace Rear Swivel Seat Arm Rest						
99 Diagnostic Test	Carried out diag test						
18 Wheels Check Torques	Torque All Wheel Nuts						
Safety Inspection	Carry Out Safety Inspection						
Vehicle Deep Clean	30/06/2021	16:00	30/06/2021	23:59	233,759	Bristol	BL022405
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	03/07/2021	18:28	05/07/2021	07:08	233,770	Bristol	BL022425
31 Battery Chassis	Replace Faulty Chassis Battery						
43 Exhaust System 1	Dpf 89% full carried out re-gen						
99 Diagnostic Test	Carried out diag, no lights on, old fault codes						
Breakdown	loss of power						
Breakdown	06/07/2021	21:13	08/07/2021	07:04	233,974	Bristol	BL022500
99 Diagnostic Test	Carry Out Fault Code Read - See Notes						
Breakdown	7403 - gearbox not changing up - limited to 40mph						
Unplanned Repair	11/07/2021	07:59	11/07/2021	11:44	234,202	Bristol	BL022537
41 Air Intake	Replaced mass air flow sensor and coded in						
43 Exhaust System 1	Replaced oxygen sensor and coded in						
45 Engine 1	Reset all values						
99 Diagnostic Test	Carried out diag-found bank 1 mixture rich						

SAFETY INSPECTION	16/08/2021	09:02	17/08/2021	07:37	236,399	Bristol	BL023018
02 Windows/Glass	replace drivers window switch						
13 Brakes 1	replace rear pads and discs						
18 Wheels	clean corrosion from flanges						
18 Wheels Check Torques							
34 Emergency Lights	replace o/s and n/s rear top blue led light pods and repair damage on roof						
45 Engine Ad Blue	top up ad blue						
45 Engine Oil Top Up	top up engine oil						
87a - Medical Equipment Repair	replace sryker mattress						
89 Seats	strip down and repair broken arm rest plate refit back again						
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Tail Lift Inspection							
Vehicle Deep Clean	16/08/2021	16:00	16/08/2021	22:59	236,398	Bristol	BL023024
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	14/09/2021	03:57	14/09/2021	17:57	239,116	Bristol	BL023315
45 Engine 1	replace 2045 belt 1400 belt with tenshioner						
99 Diagnostic Test	check for fault with belt and pulleys						
Breakdown	heavy steering						
Breakdown	17/09/2021	20:19	19/09/2021	14:56	239,476	Bristol	BL023368
45 Engine 1	replace egr valve use old gasket no stock reset all values						
99 Diagnostic Test	test system found egr short to ground values wrong requires new						
Breakdown	Adblue Malfuction/Limp mode						
SAFETY INSPECTION	04/10/2021	14:00	06/10/2021	09:13	240,611	Bristol	BL023580
02 Cab Assembly 1	replaced brake pedal rubber						

02 Windscreen	topped up screen wash
13 Brake Pads	replaced front brake pads
13 Brakes 1	Telma system not working / investigation reqd Replaced contact box
17 Tyres Replace	replaced 3 x tyres
18 Wheels Check Torques	
31 Charging System	replaced faulty alternator
44 Add Ad Blue	topped up adblue
45 Engine Oil Top Up	topped up engine oil
55 Tail Lift	replaced handrail cap
86 Sliding Door	replaced side door top magnet
87 Stretcher	replaced missing leg belt
89 Seats	replaced ns seat cover and cushion
Road Test	carried out roatest after brake work / found Telma not operating/working ok
Safety Inspection	

Vehicle Deep Clean	06/10/2021	12:56	06/10/2021	20:00	240,617	Bristol	BL023604
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Defect Repair	16/10/2021	07:05	16/10/2021	07:08	241,124	Bristol	BL023713
----------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brakes 1	traction control on,carry out star test check wires and brakes and r/test all ok
31 Battery Aux	Electrical Auxs MM531 NOT HOLDING CHARGE WIRING ISSUE.old defect

Unplanned Repair	20/10/2021	18:30	20/10/2021	19:15	241,359	Bristol	BL023762
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Cab Assembly 1	replaced interior cab bulb
56 Comms Equipment	carried out repair to loose mdt screen assy

Emergency Deep Clean	27/10/2021	07:07	29/10/2021	08:27	241,617	Bristol	BL023818
-----------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Emergency Deep Clean	
----------------------	--

SAFETY INSPECTION	26/11/2021	08:23	26/11/2021	15:21	243,654	Bristol	BL024158
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

17 Tyres Replace	replace o/s/r inner and outer tyres
18 Wheels Check Torques	
18 Wheels Removal	clean corrosion from hubs and flanges
34 Lights	replace n/s/f flasher bulb
34 Lights Bulb Replacement	replace o/s/f day running light
43 Exhaust System 1	replace holed tail pipe
45 Engine Oil Top Up	top up engine oil
87 Stretcher	replace mattress
87 Stretcher Harness Replaced	replace stryker harness
Safety Inspection	
Tail Lift Inspection	
Pollen Filter Change	Pollen Filter Change

Vehicle Deep Clean	28/11/2021	08:00	28/11/2021	14:00	243,657	Bristol	BL024185
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	06/12/2021	08:19	06/12/2021	08:34	243,999	Bristol	BL024272
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Lights Bulb Replacement	osf dip bulb
----------------------------	--------------

Vehicle Deep Clean	27/12/2021	11:00	27/12/2021	14:30	244,923	Bristol	BL024515
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	28/12/2021	07:38	28/12/2021	13:46	244,923	Bristol	BL024521
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Glass / Windows	
02 Windscreen Wipers	Replaced offside washer jet
13 Brakes 1	top up fluid
17 Tyres Replace	Osf tyre
18 Wheels Check Torques	
45 Engine Oil Top Up	
55 Tail Lift	unsieze arms and fit new mercury switch
71 Body Exterior 1	Body Interior no damage recorded old defect
89 Seats	seat arm rest pulled off saloon
Medical Devices Check	turn off leaking o2 tap left open

Safety Inspection

Breakdown	06/01/2022	21:39	07/01/2022	06:46	245,551	Bristol	BL024625
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	N/S headlight blown						
-----------	---------------------	--	--	--	--	--	--

Breakdown	21/02/2022	22:12	22/02/2022	08:54	248,900	Bristol	BL025144
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Batt. check required						
-----------	----------------------	--	--	--	--	--	--

Vehicle Deep Clean	23/02/2022	17:30	23/02/2022	23:15	249,750	Bristol	BL025172
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	24/02/2022	07:39	24/02/2022	13:52	250,137	Bristol	BL025174
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Glass / Windows							
18 Wheels Check Torques							
18 Wheels Removal	clean hubs and wheels						
45 Engine Oil Top Up							
55 Tail Lift	diagnose tail lift fault alfa to fit switch unseize handrail grease						
Safety Inspection							
Tail Lift Inspection							

02 Pipeline Annual Inspection	24/02/2022	10:30	24/02/2022	10:32	250,137	MDT Bristol	TB005515
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test - Passed all Tests						
-------------------------------	--	--	--	--	--	--	--

Unplanned Repair	28/02/2022	09:00	28/02/2022	16:43	250,204	Bristol	BL025219
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

54 Warn Dev/System	Broken/damaged terrafix screen						
--------------------	--------------------------------	--	--	--	--	--	--

SAFETY INSPECTION	29/03/2022	10:41	30/03/2022	14:23	252,577	Bristol	BL025509
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	Torque All Wheel Nuts						
-------------------------	-----------------------	--	--	--	--	--	--

Safety Inspection	Carry Out Safety Inspection
Brake Fluid Change	Carry Out Brake Fluid Change
UB Fire Supp 6mts Service	Carry Out UB Fire Supp 6mts Service
UB Fire Supp 12mts Service	Carry Out Service Of Fire Supression System
MOT	Carry Out MOT Test
Tail Lift 12M Service & Weight	Carry Out Tail Lift 12M Service And Weight Test
02 Windscreen Wipers	Replace Wiper Blades
02 Windscreen	Top Up Screenwash
02 Glass / Windows	Replace Damaged Nearside Window Switch Pack
18 Wheels Removal	Clean All Hubs And Flanges
45 Engine 1	Engine Noisy
27 Transmission Automatic	Transmission Out Put Shaft Worn
16 Suspension 1	Replace All Split Rear Spring Buffer Pads
16 Suspension 2	Replace Worn Rear Anti Roll Bar Link Bushes
34 Emergency Light System	Nearside Rear Top Corner LED And Lens Damaged
Med Dev/Equip Failure	VSM Not Charging - Fault With In The DCA
71 Body Exterior 1	Nearside Front Lower Corner Cap Damaged
44 Add Ad Blue	Ad Blue Injector Leaking
45 Engine 2	Right Hand Cylinder Head Damaged

Vehicle Deep Clean	30/03/2022	16:30	30/03/2022	23:59	252,580	Bristol	BL025526
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	02/04/2022	06:49	02/04/2022	06:50	252,700	Bristol	BL025548
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	EML amber & side step not deploying
-----------	-------------------------------------

Breakdown	10/05/2022	21:59	11/05/2022	11:37	255,206	Bristol	BL025899
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	side light bulb out front passenger
-----------	-------------------------------------

SAFETY INSPECTION	14/05/2022	08:15	17/05/2022	09:54	255,348	Bristol	BL025944
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
45 Engine Oil Top Up	
15 Steering 1	Steering heavy reported in log book checked for leak, levels and tyre pressures
56 Comms Equipment	Terafix blank reported in log book, working ok
13 Brake Pads	Replaced rear pads

24 Driveshaft 1	Replaced front propshaft
Pollen Filter Change	Pollen Filter Change
18 Wheels	Clean wheels and flanges
Fire suppression Service	Replaced system with jactone system
89 Seats	Replaced offside seat height adjust handle
34 Lights Bulb Replacement	Replaced nearside DRL bulb
86 Door Lock	Replaced locker door lock
13 Brakes 1	Replaced osf wear sensor

Vehicle Deep Clean	17/05/2022	16:30	17/05/2022	22:30	255,348	Bristol	BL025976
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	04/06/2022	23:39	05/06/2022	08:36	256,168	Bristol	BL026143
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Engine Not Holding Charge
99 Diagnostic Test	Carried out battery drain tests
31 Charging System	Carried out charging systems tests
31 Battery Aux	Replaced aux batteries

SAFETY INSPECTION	01/07/2022	15:11	03/07/2022	11:56	257,462	Bristol	BL026394
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
Engine Change Oil & Filter	
55 Tail Lift	Replaced mercury switch
34 Lights Bulb Replacement	nearside DRL
44 Add Ad Blue	
87 Stretcher	Replaced battery
13 Brakes 1	Replaced front discs and pads
01 Air Conditioning 1	Rear a/c inop
85 Body Interior 1	Fitted 'p' clips

Vehicle Deep Clean	04/07/2022	22:00	05/07/2022	12:13	257,462	Bristol	BL026428
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	27/07/2022	13:43	28/07/2022	07:04	257,462	Bristol	BL026715
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
85 Body Interior 1	replace cab light bulb
86 Sliding Door	replce sliding door rollers
85 Body Interior 2	replace locker straps
34 Emergency Lights	replace blue light above side door
85 Body Interior Roof	replace extractor fan

Vehicle Deep Clean	01/08/2022	19:00	01/08/2022	23:00	258,568	Bristol	BL026765
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	07/09/2022	21:30	08/09/2022	11:48	261,985	Bristol	BL027106
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	12/09/2022	13:42	13/09/2022	12:31	261,985	Bristol	BL027134
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Tail Lift Inspection	
44 Add Ad Blue	
54 Warn Dev/System	Cctv inop, found faulty hard drive, replaced
86 Sliding Door	Adjusted magnets
02 Cab Ass Fire Extinguisher	Replaced 2

Breakdown	04/10/2022	10:10	04/10/2022	16:08	263,088	Bristol	BL027332
Breakdown	FLAT TYRE						
SAFETY INSPECTION	13/10/2022	07:31	13/10/2022	10:31	264,271	Bristol	BL027423
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
45 Engine Oil Top Up	top up engine oil						
45 Engine Ad Blue	top up adblue						
18 Wheels Removal	clean corrosion from hubs and flanges						
86 Doors Rear	replace broken door stay block						
85 Body Interior 1	replace broken female door catch						
86 Doors	adjust top door slider and magnet						
Vehicle Deep Clean	13/10/2022	13:30	13/10/2022	19:00	264,275	Bristol	BL027434
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	16/11/2022	11:33	18/11/2022	13:03	267,074	Bristol	BL027784
Breakdown	Add Blue Needed						
42 Coolant System	radiator leaking - replace						
18 Wheels Check Torques							
Safety Inspection							
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
Engine Change Oil & Filter							
34 Lights	replace broken n/s head light						
18 Wheels Removal	clean corrosion from hubs and flanges						
55 Tail Lift	repair bent hand rails and free off sliders						

Vehicle Deep Clean	21/11/2022	07:25	21/11/2022	12:22	267,089	Bristol	BL027811
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	23/11/2022	12:43	24/11/2022	14:42	267,186	Bristol	BL027860
Breakdown	right indicator not working						
Breakdown	24/11/2022	23:16	25/11/2022	08:58	267,296	Bristol	BL027874
Breakdown	O/S Wing Mirror indicator						
Breakdown	25/11/2022	13:13	25/11/2022	16:57	267,360	Bristol	BL027877
Breakdown	right indicator light out						
34 Lights Bulb Replacement	Replaced offside repeater bulb and cleaned connections on multiplug						
Breakdown	02/12/2022	16:49	02/12/2022	17:07	267,801	Bristol	BL027945
Breakdown	low vcoolent						
42 Coolant System	check for leaks - none found - top up						
ACCIDENT	04/12/2022	01:41	26/12/2022	08:24	268,131	Bristol	BL027951
Breakdown	N/S rear bodywork damage						
Vehicle Deep Clean	22/12/2022	16:30	22/12/2022	23:30	268,131	Bristol	BL028106
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	02/01/2023	07:53	02/01/2023	09:08	269,015	Bristol	BL028193
Breakdown	OS side repeater						
34 Lights Bulb Replacement	Offside repeater						
34 Lighting System	Offside repeater has poor connection and needs repairing next time						
						Lack of Labour	

MRO Refresh	05/01/2023	09:17	05/01/2023	14:39	269,224	Bristol	BL028238
MRO Refresh							
SAFETY INSPECTION	07/01/2023	11:00	08/01/2023	09:23	269,224	Bristol	BL028263
18 Wheels Check Torques							
Safety Inspection							
34 Lights Bulb Replacement							
45 Engine 1							
Tail Lift Inspection							
34 Lighting System							
89 Seats							
45 Engine Oil Top Up							
44 Add Ad Blue							
02 Pipeline Annual Inspection	05/01/2023	19:11	05/01/2023	19:13	269,224	MDT Bristol	TB007217
02 Pipeline Annual Inspection							
34 Lighting System							
Vehicle Deep Clean	12/02/2023	22:00	13/02/2023	04:00	271,689	Bristol	BL028837
Vehicle Deep Clean							
SAFETY INSPECTION	13/02/2023	10:40	13/02/2023	10:43	271,689	Bristol	BL028841
18 Wheels Check Torques							
Safety Inspection							
86 Doors							
86 Sliding Door							
44 Add Ad Blue							
17 Tyres Replace							
Breakdown	16/02/2023	21:40	17/02/2023	18:13	272,187	Bristol	BL028922
Breakdown							

Defect Repair	21/02/2023	18:08	21/02/2023	18:10	272,735	Bristol	BL028994
99 Diagnostic Test 43 Exhaust System 1	Carried out diag, found cat temp sensor faulty Replaced cat temp sensor and coded in.						
Defect Repair	01/03/2023	10:35	01/03/2023	10:36	273,519	Bristol	BL029183
42 Coolant System	Topped up system						
Breakdown	21/03/2023	16:06	21/03/2023	17:11	275,185	Bristol	BL029562
Breakdown	ESP dashboard warning						
99 Diagnostic Test							
15 Steering 1	Replaced clock spring						
SAFETY INSPECTION	27/03/2023	15:50	28/03/2023	15:14	275,853	Bristol	BL029650
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
02 Mirrors	Replaced nearside mirror						
Pollen Filter Change	Pollen Filter Change						
55 Tail Lift	Replaced mercury switch by US AND both hoses by ALFA						
89 Seatbelts	Replaced saloon bee-gee seat belt						
MOT							
Vehicle Deep Clean	28/03/2023	14:15	28/03/2023	20:23	275,860	Bristol	BL029667
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	09/04/2023	11:26	10/04/2023	09:17	276,399	Bristol	BL029949
56 Comms Equipment	Terafix inop tested with a OO no fault found						

Breakdown	11/04/2023	02:41	11/04/2023	06:45	276,869	Bristol	BL029978
Breakdown	O/S Headlight Out						
Defect Repair	22/04/2023	07:21	22/04/2023	07:23	277,878	Bristol	BL030233
44 Add Ad Blue							
Unplanned Repair	26/04/2023	10:24	26/04/2023	10:26	278,128	Bristol	BL030317
42 Coolant System	top up coolant						
Breakdown	30/04/2023	13:06	02/05/2023	17:47	278,630	Bristol	BL030373
Breakdown	No Coolant						
42 Coolant System	REPLACED EGR COOLER AND CHANGEOVER FLAP						
SAFETY INSPECTION	08/05/2023	16:24	09/05/2023	18:05	278,630	Bristol	BL030550
18 Wheels Check Torques							
Safety Inspection							
UB Fire Supp 12mts Service	Service of fire supression system						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
17 Tyres Replace	x 6						
02 Glass / Windows	Replaced drivers window switch						
16 Suspension 1	Replaced both front lower arms						
16 Suspension 2	Replaced both front shocks						
13 Brake Pads	Replaced front brake pads and rear pads and discs						
Vehicle Deep Clean	10/05/2023	13:00	10/05/2023	20:00	279,195	Bristol	BL030612
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	12/05/2023	02:36	12/05/2023	08:47	279,239	Bristol	BL030645

Breakdown	amber engine warning light						
Breakdown	28/05/2023	06:43	28/05/2023	08:28	280,681	Bristol	BL030966
Breakdown	Puncture						
Vehicle Deep Clean	24/06/2023	07:00	24/06/2023	11:40	283,148	Bristol	BL031401
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	26/06/2023	07:12	26/06/2023	16:31	283,148	Bristol	BL031418
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
Engine Change Oil & Filter	change oil and filter						
45 Engine 1	report engine noisy on idle,						
45 Engine Ad Blue	top up adblue						
Air Filter Change	Air Filter Change						
16 Suspension 1	replace both rear shocks						
02 Cab Assembly 1	replace glove holder						
Breakdown	01/07/2023	20:56	02/07/2023	11:43	284,027	Bristol	BL031507
Breakdown	Side Step Not Working In use					Monitoring	
Breakdown	25/07/2023	07:15	06/09/2023	14:54	286,326	Bristol	BL031987
Breakdown	Flat battery - unable to bump start						
45 Engine 1	engine rattle - timing chain						
31 Battery Chassis	battery loosing charge						
002 Major Unit Replace Eng	replaced at Citywest						

SAFETY INSPECTION	01/08/2023	08:06	01/08/2023	15:07	286,320	Bristol	BL032147
18 Wheels Check Torques	ALL WHEELS						
Safety Inspection							
Breakdown	Side Step rough, LUBRICATED						
56 Comms Equipment	WIRING CHECK FOR TERRAFIX OLD DEFECT						
52 Electrical Aux	new chassis battery required						Monitoring
Replace Handbrake Cables	Replace Handbrake Cables						
55 Tail Lift	Tail lift buffers loose, new mounting plate required						Awaiting Parts
89 Seats	Resecured janny seat arm rest						
Recall Notification	01/08/2023	16:00	01/08/2023	16:01	286,320	Bristol	BL032158
Recall Notification	AIR BAGGS						
SAFETY INSPECTION	07/09/2023	09:55	07/09/2023	14:56	286,384	Bristol	BL033037
18 Wheels Check Torques							
Safety Inspection							
52 Electrical Aux	Replaced genisys pannel						
55 Tail Lift	Tail lift buffers loose, new mounting plate required NO PARTS						
Tail Lift Inspection	carried out repair to tail lift lower bars						
31 Battery Chassis	Replaced chassis battery, carried out repair to battery box						
Unplanned Repair	08/09/2023	17:17	08/09/2023	17:18	286,482	Bristol	BL033077
44 Add Ad Blue							
Vehicle Deep Clean	08/09/2023	11:30	08/09/2023	16:30	286,387	Bristol	BL033094
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	27/09/2023	19:02	28/09/2023	10:37	288,482	Bristol	BL033679
Breakdown	headlight out IN USE						

Vehicle Deep Clean	28/10/2023	14:50	28/10/2023	19:00	290,044	Bristol	BL034767
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	03/11/2023	09:31	04/11/2023	09:44	290,344	Bristol	BL034953
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Engine Change Oil & Filter	
02 Windscreen Wipers	Replaced linkage and motor
44 Add Ad Blue	
34 Lights	Replaced osf fog lamp (NON STOCK)
31 Charging System	Replaced non stock auto eject and repaired wiring to engine loom
52 Electrical Aux	Replaced 4 inverter led's
85 Body Interior 1	Replaced cctv cupboard struts
Fire suppression Service	Re-routed jactone correctly after engine replacement
55 Tail Lift	Tail lift tank rusty but not leaking
01 Air Conditioning 1	Rear condensor fan seized replaced fan and fuse
13 Brakes 1	Telma control box broken and rusty
34 Lighting System	Nsr marker light defective
13 Brakes 2	Replaced telma relay box
56 Comms Equipment	Replaced nearside saloon mic

ACCIDENT	08/11/2023	17:36	08/11/2023	17:40	290,713	Bristol	BL035126
-----------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

34 Emergency Lights	Body Exterior O/S/R top blue light damage	Replaced blue lens and led unit
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card	

Unplanned Repair	22/11/2023	16:44	22/11/2023	16:48	290,713	Bristol	BL035632
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

44 Add Ad Blue

Breakdown	24/11/2023	19:36	25/11/2023	07:55	291,713	Bristol	BL035695
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Rear Door Stay Bar Broke
86 Doors Rear	Replace Broken Offside Rear Door Stay Bar

Vehicle Deep Clean	15/12/2023	13:30	22/12/2023	10:45	294,987	Bristol	BL036692
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	18/12/2023	07:06	18/12/2023	13:24	294,923	Bristol	BL036472
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
13 Brakes 1	free off sticking o/s/r brake caliper
16 Suspension 1	replace worn rear lower arb bushes
02 Cab Assembly 1	replace n/s cab torch
34 Lights	replace interior light bulb
45 Engine Oil Top Up	top up engine oil
45 Engine Ad Blue	top up adblue
Pollen Filter Change	Pollen Filter Change

O2 Pipeline Annual Inspection	18/12/2023	13:03	18/12/2023	13:10	294,923	MDT Bristol	TB009142
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

O2 Pipeline Annual Inspection	Annual Inspection and Pressure Test - Please See Notes
-------------------------------	--

Breakdown	28/12/2023	16:01	28/12/2023	16:51	295,985	Bristol	BL036901
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	Nail In Tyre
17 Tyres Replace	N/S/F
18 Wheels Check Torques	N/S/F only

BREAKDOWN	29/12/2023	14:23	29/12/2023	14:30	296,044	Bristol	BL036951
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

02 Windscreen Wipers	Windscreen Wipers Not Working - Replace Faulty Wiper/Indicator Switch
----------------------	---

Unplanned Repair	07/01/2024	13:22	07/01/2024	13:26	296,990	Bristol	BL037290
86 Doors Rear	Replace Snapped Offside Rear Door Lower Release Cable						
Unplanned Repair	10/01/2024	08:10	10/01/2024	10:27	297,265	Bristol	BL037406
86 Doors Rear	Doors REAR DOOR ROD HOLDER HAS SNAPPED - old defect						
86 Doors	Doors Rear door pin doesnot coming up.door locked.						
01 Heating 1	A/C System Saloon heating in saloon not working - tested all working correctly						
Vehicle Deep Clean	27/01/2024	21:05	28/01/2024	00:00	298,590	Bristol	BL038054
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	28/01/2024	07:11	30/01/2024	08:22	298,600	Bristol	BL038061
18 Wheels Check Torques							
Safety Inspection							
02 Windscreen Wipers	Replaced nearside washer jet and wiper blades						
56 Comms Equipment	Replaced offside saloon mic						
85 Body Interior 1	Replaced240v socket cover						
Check Winter Pack	Replaced salt stick						
43 Exhaust System 1	Replaced DPF pipe bracket						
16 Suspension 1	replaced all 4 spring buffers and spring eye bushes						
13 Brakes 1	unseized offside rear caliper sliders and replaced both front caliper sider kits						
45 Engine Oil Top Up							
55 Tail Lift	Lift ram and tank badly corroded						Awaiting Parts
89 Seats	Air wave seat worn no stock						Awaiting Parts
Breakdown	04/02/2024	22:07	05/02/2024	07:19	299,119	Bristol	BL038329
Breakdown	Issue going through 1st and 2nd no fault found no faults						
34 Lights Bulb Replacement	nsf h7 bulb replaced						
Breakdown	04/02/2024	22:08	05/02/2024	08:24	299,119	Bristol	BL038330
Breakdown	Headlight Out						

Defect Repair	10/02/2024	17:20	10/02/2024	17:23	299,414	Bristol	BL038527
71 Body External Steps	Chain snapped on side step, repaired and lubricated						
Vehicle Deep Clean	28/02/2024	14:20	28/02/2024	18:20	301,017	Bristol	BL039194
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	01/03/2024	07:09	01/03/2024	13:19	301,062	Bristol	BL039215
18 Wheels Check Torques							
Safety Inspection							
55 Tail Lift	Lift ram and tank badly corroded						
43 Exhaust System 1	Exhaust System White smoke omitting						
27 Transmission Automatic	Clutch Gearbox shutting down.						
Tail Lift Inspection							
89 Seats	Air wave seat worn no stock						
13 Brakes 1	replace front brake pads and discs						
34 Lights	replace n/s head light bulb						
45 Engine Ad Blue	top up adblue						
45 Engine Oil Top Up	top up engine oil						
ACCIDENT	08/03/2024	12:54	03/04/2024	10:39	301,300	Bristol	BL039482
02 Glass / Windows	Other o/s squared window shattered accident						
MOT							
Breakdown	05/04/2024	16:13	05/04/2024	16:25	301,916	Bristol	BL040454
Breakdown	O/S rear outer puncture						
17 Tyres Replace	Replace Offside Rear Outer Tyre - Puncture						
18 Wheels Check Torques	Offside Rear Only - 180NM -#2						

SAFETY INSPECTION	09/04/2024	09:06	09/04/2024	16:02	302,258	Bristol	BL040568
18 Wheels Check Torques	torque wheels						
Safety Inspection	carry out safety inspection						
Brake Fluid Change	Brake Fluid Change						
17 Tyres Replace	replace o/s/ inner and noth N/S/R tyres						
17 Tyres Tracking	Carry out tracking						
55 Tail Lift	guard rail siezed - free off and lubricate						
Vehicle Deep Clean	09/04/2024	16:00	09/04/2024	17:57	302,258	Bristol	BL040584
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	05/05/2024	16:52	07/05/2024	11:06	304,115	Bristol	BL041485
Breakdown	The MDT turning off itself during the job						
Breakdown	05/05/2024	16:55	06/05/2024	09:46	304,115	Bristol	BL041486
Breakdown	The side door is not functioning properly						
Vehicle Deep Clean	18/05/2024	20:00	18/05/2024	23:30	305,064	Bristol	BL041955
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	21/05/2024	16:25	22/05/2024	11:10	305,094	Bristol	BL042038
18 Wheels Check Torques	Torque All Wheel Nuts - 180NM #2						
Safety Inspection	Carry Out Safety Inspection						
85 Body Interior 1	Kit Locker Door Not Closing. Door Stays Open						
UB Fire Supp 6mts Service	Carry Out UB Fire Supp 6mts Service						
UB Fire Supp 12mts Service	Carry Out Service Of Fire Supression System						
02 Windscreen	Top Up Screenwash						
18 Wheels Removal	Clean All Hubs And Flanges						
Road Test	Carry Out Road Test						

Vehicle Deep Clean	01/07/2024	21:15	02/07/2024	02:05	309,184	Bristol	BL043412
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	03/07/2024	09:08	03/07/2024	14:23	309,185	Bristol	BL043456
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
55 Tail Lift	replace faulty tilt switch
45 Engine Oil Top Up	top up engine oil
43 Exhaust System 1	replace holed tail pipe

Breakdown	09/07/2024	01:40	09/07/2024	10:21	311,000	Bristol	BL043633
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	EML
99 Diagnostic Test	Carry Out Fault Code Read - Code For Faulty DPF Pressure Sensor Stored
43 Exhaust System 1	Replace Faulty DPF Pressure Sensor - Clear Code
Road Test	Carry Out Road Test

Unplanned Repair	25/07/2024	08:41	26/07/2024	08:53	311,000	Bristol	BL044168
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

89 Seats	Driver seat base faulty, Parts ordered
02 Cab Assembly 1	Replaced drivers seat base frame

Breakdown	02/08/2024	07:08	02/08/2024	10:06	311,843	Bristol	BL044401
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	OSR tyre punctured
-----------	--------------------

SAFETY INSPECTION	10/08/2024	09:07	11/08/2024	08:50	312,417	Bristol	BL044705
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques
Safety Inspection

33 Ignition System	Replaced key battery
31 Charging System	Other shoreline auto eject broken - OLD DEFECT
86 Doors	Doors side door not locking open
85 Body Interior Roof	Body Interior internal drawer not opening
Replace Handbrake Cables	Replace Handbrake Cables
34 Lights Bulb Replacement	Nearside headlamp
34 Lighting System	Replaced nearside front marker light
42 Coolant System	Heater pipe leaking
85 Body Interior 1	Replaced saloon luggage strap
85 Body Interior 2	Re-secured saloon clock
85 Body Interior 3	Replaced IV cupboard latch
86 Sliding Door	Adjusted top magmnet and replaced top latch cover
71 Body Exterior 1	Tail lift tank heavily corroded
13 Brake Pads	Replaced rears

Awaiting Parts

Vehicle Deep Clean	14/08/2024	19:51	15/08/2024	20:30	312,417	Bristol	BL044855
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	04/09/2024	07:32	04/09/2024	07:34	314,758	Bristol	BL045593
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	O/S headlight bulb replaced
-----------	-----------------------------

Breakdown	10/09/2024	09:43	10/09/2024	14:34	315,405	Bristol	BL045830
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	tail lift warning
55 Tail Lift	tail lift contact switch pushed in and arm bent

SAFETY INSPECTION	21/09/2024	12:36	21/09/2024	14:47	316,546	Bristol	BL046226
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Engine Change Oil & Filter	
Tail Lift Inspection	replace broken platform light
85 Body Interior 1	replace broken bio safe strap

85 Body Interior 2	replace broken cuboard angle						
Vehicle Deep Clean	24/09/2024	07:00	24/09/2024	12:00	316,549	Bristol	BL046323
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	23/10/2024	11:31	23/10/2024	14:36	319,400	Bristol	BL047340
Breakdown 99 Diagnostic Test 71 Body External Steps	Side step wont deploy Check And Test Side Step - Motor Faulty Replace Faulty Side Step Motor						
SAFETY INSPECTION	05/11/2024	12:34	05/11/2024	14:46	319,400	Bristol	BL047807
18 Wheels Check Torques Safety Inspection 42 Coolant System 86 Doors Air Filter Change 02 Cab Assembly 1 Road Test	Heater pipe leaking, REPLACED Doors Sliding side door doesn't stays in open AJUSTED MAGNET Air Filter Change Replaced drivers torch						
Vehicle Deep Clean	06/11/2024	14:30	07/11/2024	18:30	319,400	Bristol	BL047848
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	20/11/2024	18:29	22/11/2024	13:07	322,230	Bristol	BL048334
Breakdown 99 Diagnostic Test 32 Starting System 1	BURNING SMELL Check For Burning Smell - Found Starter Motor Burnt Out Replace Faulty Starter Motor						
ACCIDENT	23/11/2024	06:23	23/11/2024	08:19	322,230	Bristol	BL048434
18 Wheels	Cable Wrapped Around Offside Rear Wheels						

18 Wheels Removal	Remove Offside Rear Wheels To Remove Shoreline Cableing
18 Wheels Check Torques	Offside Rear Only - 180NM #2

Unplanned Repair	02/12/2024	15:16	02/12/2024	16:32	322,940	Bristol	BL048796
-------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

86 Sliding Door	Side Door Not Locking - Carry Out Repair To Wiring
34 Lights Bulb Replacement	Replace Blown Offside DRL Bulb
44 Add Ad Blue	Top Up Ad Blue System

Breakdown	10/12/2024	07:29	10/12/2024	16:15	322,980	Bristol	BL049092
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	SIDE STEPS STUCK OUT
71 Body External Steps	Repaired step chain

Breakdown	12/12/2024	23:24	13/12/2024	07:45	323,190	Bristol	BL049182
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown	screen wiper not working,check linkage and tighten up wiper nuts
-----------	--

SAFETY INSPECTION	14/12/2024	09:27	14/12/2024	15:44	323,747	Bristol	BL049249
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Road Test	

85 Body Interior 1	Replaced saloon luggage strap
34 Lights Bulb Replacement	Interior light
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
13 Brakes 1	Telma noisy
85 Body Interior 2	Re-fitted saloon clock and repaired angle plastic in cupboard
86 Sliding Door	Replaced centre door arm and adjusted magnets
45 Engine Oil Top Up	

Lack of Labour

Vehicle Deep Clean	14/12/2024	14:00	14/12/2024	17:00	323,747	Bristol	BL049259
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

02 Pipeline Annual Inspection	17/12/2024	14:00	17/12/2024	15:00	323,747	MDT Bristol	TB011750
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	--------------------	-----------------

02 Pipeline Annual Inspection Annual Inspection and Pressure Tested By SMC - Please See Notes

Vehicle Deep Clean	27/01/2025	12:00	27/01/2025	18:00	327,768	Bristol	BL050909
---------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION	28/01/2025	16:24	29/01/2025	14:12	327,768	Bristol	BL050932
--------------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Check MDVS for Update	Check and Install MDVS windows update
Safety Inspection	Carry Out Safety Inspection
18 Wheels Check Torques	Torque All Wheel Nuts - 180Nm #2
Road Test	Carry Out Road Test
13 Brakes 1	Telma Noisy
UB Fire Supp 6mts Service	Carry Out UB Fire Supp 6mts Service
Tail Lift Inspection	Carry Out Tail Lift Inspection
02 Windscreen	Top Up Screenwash
02 Windscreen Wipers	Replace Worn Wiper Blades
18 Wheels Removal	Clean All Hubs And Flanges
86 Sliding Door	Adjust Side Door Top Magnet
13 Brakes 2	Replace Worn Front Brake Discs And Pads
17 Tyres Replace	Replace Both Front Tyres - 2.5mm

Awaiting Parts

BREAKDOWN	13/02/2025	07:00	13/02/2025	10:35	328,882	Bristol	BL051525
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

13 Brakes 1	Telma Noisy
34 Lights	Lighting System Offside headlight not working
27 Transmission Automatic	Replace long propshaft

Breakdown	17/02/2025	20:24	18/02/2025	08:59	329,585	Bristol	BL051671
------------------	-------------------	--------------	-------------------	--------------	----------------	----------------	-----------------

Breakdown n/s headlight out

Defect Repair	23/02/2025	14:35	23/02/2025	14:38	330,129	Bristol	BL051872
34 Emergency Lights	Re-attached osf top blue light						
SAFETY INSPECTION	11/03/2025	10:49	14/03/2025	07:09	331,344	Bristol	BL052431
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection	Carry Out Safety Inspection						
18 Wheels Check Torques	Torque All Wheel Nuts -180Nm #3						
Road Test	Carry Out RoadTest						
Wheel Hub Flanges Replaceme	Replace Front And Rear Hub Flanges						
Tail Lift Inspection	Carry Out Tail Lift Inspection						
MOT	Carry Out MOT Test						
02 Windscreen	Top Up Screenwash						
18 Wheels Removal	Clean All Hubs For New Flanges						
17 Tyres Replace	Replace Both N/S/R And O/S/R Inner Tyres - 3.0mm						
Vehicle Deep Clean	13/03/2025	13:30	13/03/2025	17:30	331,344	Bristol	BL052510
Vehicle Deep Clean	Vehicle Deep Clean						
Defect Repair	26/03/2025	16:32	01/04/2025	15:01	332,000	Bristol	BL052974
33 Ignition System	Other Unable to lock the DCA swapped key and ordered new						
SAFETY INSPECTION	19/04/2025	09:27	21/04/2025	15:49	333,483	Bristol	BL053856
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
31 Battery Comms	Radio & Comm System MDT keeps turning off itself-old defect						
85 Body Int Alcohol Gel Dispen							
13 Brakes 1	rear brake pads too low						

Vehicle Deep Clean	20/04/2025	11:00	20/04/2025	13:00	333,483	Bristol	BL053897
Vehicle Deep Clean	Vehicle Deep Clean						
UB Fire Supp 12mts Service	27/04/2025	11:22	27/04/2025	11:25	333,483	Bristol	BL054144
86 Doors Rear	unable to open door, replaced seised lock mechanisim						
Breakdown	03/06/2025	08:52	03/06/2025	18:35	337,766	Bristol	BL055359
Breakdown 86 Doors Rear	door stop sheared off Replace Offside Door Block						
Vehicle Deep Clean	03/06/2025	21:00	04/06/2025	00:00	337,793	Bristol	BL055394
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	04/06/2025	10:39	04/06/2025	18:15	337,793	Bristol	BL055404
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test Tail Lift Inspection 86 Sliding Door 01 Air Conditioning 1 45 Engine Oil Top Up	Check and Install MDVS windows update Adjusted top magnet Replaced rear condensor and fan, modified wiring and repaired leaks						
Unplanned Repair	18/06/2025	12:24	25/06/2025	14:58	338,672	Bristol	BL055857
31 Charging System 15 Steering 1 Breakdown 17 Tyres Tracking	Battery/Charging Sys Battery not holding charge Replaced steering rack and pump power steering heavy when turning, level overfilled Carry out tracking						

Vehicle Deep Clean	12/07/2025	14:00	12/07/2025	16:00	341,099	Bristol	BL056646
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	13/07/2025	12:08	18/07/2025	17:52	341,099	Bristol	BL056675
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
Engine Change Oil & Filter							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
31 Charging System	Replaced alternator						
01 Air Conditioning 1	Replaced cab compressor						
Breakdown	29/07/2025	08:14	29/07/2025	14:25	342,305	Bristol	BL057182
Breakdown	N/S front tyre making scraping sound on turning						
16 Suspension 1	Replaced both front shock absorbers (excess play in both)						
ACCIDENT	09/08/2025	16:48	11/08/2025	08:16	343,320	Bristol	BL057599
Breakdown	NOT PRESENTED TO WOKRSHOP Hit a fence, damaged side of truck.						
Breakdown	20/08/2025	11:12	20/08/2025	12:00	343,500	Bristol	BL057950
Breakdown	side step not deploying						
Unplanned Repair	20/08/2025	10:30	20/08/2025	11:46	344,747	Gloucester	GC036475
71 Body External Steps	Body Exterior side step getting stuck						
45 Engine Oil Top Up							
44 Add Ad Blue							

SAFETY INSPECTION	01/09/2025	07:34	01/09/2025	11:33	346,330	Bristol	BL058339
Check MDVS for Update	Check and Install MDVS windows update						
Safety Inspection							
18 Wheels Check Torques							
Road Test							
Replace Handbrake Cables	Replace Handbrake Cables.not due yet						
Pollen Filter Change	Pollen Filter Change						
16 Suspension 1	replace rear lower arb buhes						
45 Engine Ad Blue	top up low adblue						
71 Body External Steps	replace missing roller						
17 Tyres Replace	replace below limit o/s/r outer tyre						
89 Seats	replace drivers seat cover						
Breakdown	03/09/2025	22:27	04/09/2025	08:29	346,538	Bristol	BL058465
Breakdown	headlight out						
Decommission Vehicle	10/09/2025	10:30	15/09/2025	10:03	346,538	Bristol	BL058741
Decommission vehicle	Decommission vehicle						