Vehicle Detail	YC12WVY FORD	TRAN 125 T350 AWD
	Odo Job Type	Description
02/06/2025	0 RFL	RFL Jun 2025
22/04/2025	0 TYRES	VALVE - TYR
22/04/2025	0 TYRES	BALANCE - TYR
22/04/2025	0 TYRES	215/75R16 - TYR
22/04/2025	0 BREAKDOWN RECOVERY	CALLOUT CHARGE(S) - ADD
17/04/2025	0 SERV/SAFETY INS (+ TEST FEE)	ENVIRONMENTAL CHARGE
17/04/2025	0 TYRES	BALANCE - TYR
17/04/2025	0 TYRES	215/75R16 - TYR
17/04/2025	0 BREAKDOWN RECOVERY	CALLOUT CHARGE(S) - ADD
17/04/2025	0 TYRES	VALVE - TYR
16/04/2025	0 REPAIRS TO SUSPENSION	WISHBONE RADIUS ARM - SUS
16/04/2025	0 REPAIRS TO STEERING	O/S/F WISHBONE RADIUS LOWER AR
16/04/2025	0 REPAIRS FOR MISUSE OR DAMAGE	NUMBER PLATE - BOD
16/04/2025	0 REPAIRS FOR MISUSE OR DAMAGE	NUMBER PLATE - BOD
16/04/2025	0 REPAIRS TO STEERING	N/S/F WISHBONE RADIUS LOWER AR
16/04/2025	0 Admin Charges	CONSUMABLE CHARGE - ADD
16/04/2025	0 REPAIRS FOR MISUSE OR DAMAGE	BULB MISC - ELE
16/04/2025	0 REPAIRS TO ELECTRICS/BATTERY	Bulb Misc
16/04/2025	0 SERV/SAFETY INS (+ TEST FEE)	ENGINE OIL - FRIENGINE OIL & F/FILTER CHANGEFUEL FILTER(S) - ENGINSPECTION & PREV. MAINT.MOT TES
16/04/2025	0 REPAIRS TO STEERING	TRACKING SYSTEM - ELE
05/11/2024	0 REPAIRS TO STEERING 0 REPAIRS TO ELECTRICS/BATTERY	Recharge Remove & Refit, Battery - Remove & Refit, Charging circuit - battery, Rchg From Inv: pinv51
05/11/2024	0 REPAIRS TO ELECTRICS/BATTERY	Recharge Check, Braking System Fault Diagnosis - Check, ABS - fault diagnosis, Rchg From Inv: pinv51
04/11/2024	0 TYRES	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: B 1, Location: 4 Meadow Close Hetherse
04/11/2024	0 REPAIRS FOR MISUSE OR DAMAGE	Recharge Recharge For: Removed Tyre, Position: B 1, 2157516NEXENROADIANCT8116114R, NEXEN, Removal Re
		Recharge Recharge For: New Tyre, Position: B 1, 2157516NEXENROADIANCT8116114R, NEXEN, Location: 4 Me
04/11/2024 04/11/2024	0 TYRES 0 TYRES	Recharge Recharge For: WHEEL BALANCED - VAN, Position: B 1, Location: 4 Meadow Close Hethersett Norw
04/11/2024	0 TYRES	Recharge Recharge For: Tyres - Environmental Disposal, Position: B 1, Location: 4 Meadow Close Hethe
26/06/2024	0 ROAD TEST	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 10883 dpf issue
26/06/2024	0 ROAD TEST 0 REPAIRS TO FUEL SYSTEM	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 10883 remove DPF
26/06/2024 20/06/2024	0 REPAIRS TO FUEL STSTEIN 0 REPAIRS TO FITTINGS	Recharge Remove & Refit, Exhaust gas recirculation (EGR) valve, Rchg From Inv: 10883
23/05/2024	0 RFL	RFL Jun 2024
08/05/2024	160,760 BREAKDOWN RECOVERY	Recharge Routine, Other Unspecified Work - Routine, Breakdown, Rchg From Inv: 1249883 SIF - N08/05/2
30/04/2024 30/04/2024	160,645 ROAD TEST	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 10099 smoke from rear
	160,645 SERV/SAFETY INS (+ TEST FEE)	Recharge Routine 150000 mls/kms Service, Rchg From Inv: 10099
30/04/2024	160,645 REPAIRS TO ELECTRICS/BATTERY	Recharge Check & Adjust, Headlamp alignment, Rchg From Inv: 10099 Gone Opaque/milky
30/04/2024	160,645 REPAIRS TO BRAKES	Recharge Remove & Refit, Pedal assy (Brake), Rchg From Inv: 10099 Brake Pedal Rubber Split - Mot
30/04/2024 30/04/2024	160,645 REPAIRS TO BRAKES 160,645 REPAIRS TO BODY (NON ACCIDENT)	Recharge Remove & Refit, Hydraulic fluid (Brake), Rchg From Inv: 10099 Brake Fluid Change Recharge Remove & Refit, Sill panel, Rchg From Inv: 10099 N/S/R Sill Excessively Corrode
30/04/2024	160,645 MOT	
30/04/2024	160,645 REPAIRS TO ELECTRICS/BATTERY	Recharge Routine, MOT - Class IV Cars (Up To 8 Passenger Seats), Rchg From Inv: 10099 Recharge Remove & Refit, Windscreen wiper - blade/s, Rchg From Inv: 10099 Wipers Streaking
08/04/2024	0 REPAIRS TO ELECTRICS/BATTERY	
	160,645 COLLECTION & DELIVERY	Recharge Remove & Refit Diesel Particulate Filter Sensor, Rchg From Inv: 135591 Investigate DPF faul
02/04/2024	160,590 COLLECTION & DELIVERY	Recharge Routine, Movement - Routine, Movement ? Novuna Request, Rchg From Inv: 00-777892 02/04 RECO
13/02/2024	•	Recharge Routine, Movement - Routine, Movement - Collection & Delivery, Rchg From Inv: 00-743269 13/
09/02/2024 09/02/2024	160,578 COLLECTION & DELIVERY	Recharge Routine, Movement - Routine, Movement - Miscellaneous, Rchg From Inv: 00-507958 Environment Recharge Routine, Other Unspecified Work - Routine, Call Out Charge, Rchg From Inv: 00-507958 09/02/
	160,578 COLLECTION & DELIVERY	
09/02/2024	160,578 ROAD TEST	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 00-507958 checked reported faul
15/01/2024	160,166 COLLECTION & DELIVERY	Recharge Routine, Movement - Routine, Movement - Collection & Delivery, Rchg From Inv: 00-723314 15/
15/01/2024	160,166 COLLECTION & DELIVERY	Recharge Routine, Movement - Routine, Movement - Collection & Delivery, Rchg From Inv: 00-717640 15/
15/01/2024	160,166 COLLECTION & DELIVERY	Recharge Routine, Movement - Routine, Movement - Collection & Delivery, Rchg From Inv: 00-717640 15/
08/01/2024	0 REPAIRS TO ENGINE, EXHAUST	Recharge Remove & Refit Engine assy, Rchg From Inv: 134425 Supply and fit long recon engine as reque
29/11/2023	160,134 COLLECTION & DELIVERY	Recharge Routine, Movement - Routine, Non-Standard Vehicle Movement, Rchg From Inv: 00-690111 STORAG
29/11/2023	160,134 COLLECTION & DELIVERY	Recharge Routine, Movement - Routine, Non-Standard Vehicle Movement, Rchg From Inv: 00-690111 ABBEYG
23/11/2023	160,134 ROAD TEST	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 87517

No

```
Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 87517 Oil leaking need to clean
23/11/2023
             160,134 ROAD TEST
23/11/2023
             160,134 REPAIRS TO ENGINE, EXHAUST
                                                          Recharge Remove & Refit, Turbocharger inlet hose, Rchg From Inv: 87517 Chaffed very badly Chaffed ve
23/11/2023
                                                          Recharge Check, Compression pressure test, Rchg From Inv: 87517
             160,134 REPAIRS TO ENGINE, EXHAUST
23/11/2023
             160,134 REPAIRS TO ELECTRICS/BATTERY
                                                          Recharge Remove & Refit, Lamps exterior - rear lamp bulb, Rchg From Inv: 87517 Both sides need chang
23/11/2023
             160,134 REPAIRS TO ELECTRICS/BATTERY
                                                          Recharge Remove & Refit, Lamps exterior - number plate lamp assy, Rchg From Inv: 87517
23/11/2023
             160,134 REPAIRS TO BRAKES
                                                          Recharge Remove & Refit, Pads - rear (axle set), Rchg From Inv: 87517 PAD MIN:1.60MM,PAD ACT:2.00MM
23/11/2023
             160,134 Admin Charges
                                                          Recharge Routine, Other Unspecified Work - Routine, Unscheduled Labour, Rchg From Inv: 87517 Front a
21/11/2023
             160,134 COLLECTION & DELIVERY
                                                          Recharge Routine, Movement - Routine, Non-Standard Vehicle Movement, Rchg From Inv: 00-689385 ABBEYG
05/10/2023
                   0 REPAIRS TO ENGINE, EXHAUST
                                                          Glow plug removal
05/10/2023
                   0 REPAIRS TO OTHER ATTACHMENTS
                                                          NON - STATER
05/10/2023
                   0 REPAIRS TO ENGINE, EXHAUST
                                                          NON - STATER
05/10/2023
                   0 REPAIRS TO ENGINE, EXHAUST
                                                          Glow plug removal
05/10/2023
                   0 REPAIRS TO ENGINE. EXHAUST
                                                          NON - STATER
05/10/2023
                   0 REPAIRS TO ENGINE. EXHAUST
                                                          EML - AMBER /ABS - AMBER /NO POWER /
25/07/2023
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                          High level brake light
25/07/2023
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                          High level brake light
25/07/2023
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                          High level brake light
06/06/2023
                   0 RFL
                                                          RFL Jun 2023
02/03/2023
                   0 REPAIRS TO BRAKES
                                                          ROLLER BRAKE TEST
                                                          REPLACE N/S/F BOTTOM BALL JOINT - GAITER SPLI
02/03/2023
                   0 REPAIRS TO SUSPENSION
02/03/2023
                   0 REPAIRS TO BODY (NON ACCIDENT)
                                                          MAKE UP PLATE AND WELD TO N/S/R OUTER SILL -
02/03/2023
                   0 REPAIRS TO STEERING
                                                          Centralize Steering Wheel
02/03/2023
                   0 REPAIRS TO STEERING
                                                          Check & Adjust Wheel Alianment (Front)
02/03/2023
                                                          Brake Fluid Change
                   0 REPAIRS TO BRAKES
                                                          Parking brake cable right
02/03/2023
                   0 REPAIRS TO BRAKES
02/03/2023
                   0 REPAIRS TO BRAKES
                                                          Caliper - rear (one)
02/03/2023
                                                          Lamps exterior (front) - side light bulb left
                   0 REPAIRS TO ELECTRICS/BATTERY
02/03/2023
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                          Lamps exterior - number plate lamp bulb
02/03/2023
                   0 REPAIRS TO SUSPENSION
                                                          REPLACE FRONT ANTI ROLL BAR BUSHES - HAVE EXC
02/03/2023
                   0 REPAIRS TO SUSPENSION
                                                          Front Suspension Lower Arm Bracket Left
02/03/2023
                                                          Disc (incl. pads) - rear (pair)
                   0 REPAIRS TO BRAKES
                                                          Disc (incl. pads) - front (pair)
02/03/2023
                   0 REPAIRS TO BRAKES
02/03/2023
                   0 REPAIRS INTERNAL FITTINGS
                                                          Empty rear of vehicle to gain access to inver
                                                          HANDBRAKE STICKING ON - DRIVER REPORTED FAULT
02/03/2023
                   0 REPAIRS TO BRAKES
                   0 SERV/SAFETY INS (+ TEST FEE)
02/03/2023
                                                          240 Volt Inverter & Associated Wiring Equipme
02/03/2023
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                          Class VII MoT Test
02/03/2023
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                          S1 SERVICE
02/03/2023
                   0 REPAIRS INTERNAL FITTINGS
                                                          Empty rear of vehicle to gain access to inver
                                                          ROLLER BRAKE TEST
02/03/2023
                   0 REPAIRS TO BRAKES
                                                          REPLACE N/S/F BOTTOM BALL JOINT - GAITER SPLI
02/03/2023
                   0 REPAIRS TO SUSPENSION
                                                          MAKE UP PLATE AND WELD TO N/S/R OUTER SILL -
02/03/2023
                   0 REPAIRS TO BODY (NON ACCIDENT)
02/03/2023
                   0 REPAIRS TO STEERING
                                                          Centralize Steering Wheel
02/03/2023
                   0 REPAIRS TO STEERING
                                                          Check & Adjust Wheel Alignment (Front)
02/03/2023
                   0 REPAIRS TO BRAKES
                                                          Brake Fluid Change
02/03/2023
                   0 REPAIRS TO BRAKES
                                                          Parking brake cable right
02/03/2023
                                                          Caliper - rear (one)
                   0 REPAIRS TO BRAKES
02/03/2023
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                          Lamps exterior (front) - side light bulb left
02/03/2023
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                          Lamps exterior - number plate lamp bulb
02/03/2023
                                                          REPLACE FRONT ANTI ROLL BAR BUSHES - HAVE EXC
                   0 REPAIRS TO SUSPENSION
02/03/2023
                   0 REPAIRS TO SUSPENSION
                                                          Front Suspension Lower Arm Bracket Left
02/03/2023
                   0 REPAIRS TO BRAKES
                                                          Disc (incl. pads) - rear (pair)
02/03/2023
                   0 REPAIRS TO BRAKES
                                                          Disc (incl. pads) - front (pair)
02/03/2023
                   0 REPAIRS TO FUEL SYSTEM
                                                          Fuel filter element - in line
02/03/2023
                   0 REPAIRS TO BRAKES
                                                          HANDBRAKE STICKING ON - DRIVER REPORTED FAULT
02/03/2023
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                          240 Volt Inverter & Associated Wiring Equipme
02/03/2023
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                          Class VII MoT Test
```

02/03/2023	0 SERV/SAFETY INS (+ TEST FEE)	S1 SERVICE
02/03/2023	0 REPAIRS TO FUEL SYSTEM	Fuel filter element - in line
03/01/2023	0 REPAIRS TO STEERING	Alignment - camber/castor/KPI (Front Susp.)
03/01/2023	0 REPAIRS TO SUSPENSION	Spring/torsion bar (Front Susp.) right
03/01/2023	0 REPAIRS TO SUSPENSION	Strut top bearing (Front Susp.) right
03/01/2023	0 BREAKDOWN RECOVERY	SUSPENSION
03/01/2023	0 SERV/SAFETY INS (+ TEST FEE)	RECOVERY - Vehicle sagged on one side/ front
07/12/2022	0 REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair
07/12/2022	0 REPAIRS FOR MISUSE OR DAMAGE	Wheel Balance
07/12/2022	0 REPAIRS FOR MISUSE OR DAMAGE	Disposal of Tyre Casing
07/12/2022	0 REPAIRS FOR MISUSE OR DAMAGE	Change Tyre
06/12/2022	0 TYRES	/1 PUNCTURE AND A SERVICEABLE SPARE
02/11/2022	0 COLLECTION & DELIVERY	Basic road test (add once only)
02/11/2022	0 REPAIRS TO FUEL SYSTEM	Regeneration of Particulate Filter(s)
02/11/2022	0 REPAIRS TO ENGINE, EXHAUST	test vapouriser
02/11/2022	0 REPAIRS TO ELECTRICS/BATTERY	Battery
02/11/2022	0 REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - blade/s
02/11/2022	0 REPAIRS TO ENGINE, EXHAUST	EML IN LIMP MODE
10/06/2022	0 RFL	RFL Jun 2022
20/05/2022	137,299 REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair
20/05/2022	137,299 REPAIRS FOR MISUSE OR DAMAGE	Change Tyre
20/05/2022	137,299 REPAIRS FOR MISUSE OR DAMAGE	Wheel Balance
20/05/2022	137,299 REPAIRS FOR MISUSE OR DAMAGE	Disposal of Tyre Casing
25/11/2021	0 RFL	RFL Dec 2021
01/06/2021	121,746 REPAIRS TO COOLING SYSTEM	29439/Hoses/Pipes
01/06/2021	121,746 REPAIRS TO SUSPENSION	Anti-roll/stabiliser link (Front Susp.) left
01/06/2021	121,746 REPAIRS TO SUSPENSION	Anti-roll/stabiliser link (Front Susp.) left
01/06/2021	121,746 REPAIRS TO COOLING SYSTEM	29439/Hoses/Pipes
28/05/2021	0 BREAKDOWN RECOVERY	RECOVERY ONLY - AFTER BREAKDOWN
30/04/2021	121,451 SERV/SAFETY INS (+ TEST FEE)	240 Volt Inverter & Associated Wiring Equipme
30/04/2021	121,451 SERV/SAFETY INS (+ TEST FEE)	240 Volt Inverter & Associated Wiring Equipme
12/04/2021	0 BREAKDOWN RECOVERY	RECOVERY ONLY - REPAIRED VEHICLE
12/04/2021	0 BREAKDOWN RECOVERY	RECOVERY ONLY - REPAIRED VEHICLE
09/04/2021	121,451 REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - blade/s
09/04/2021	121,451 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
09/04/2021	121,451 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
09/04/2021	121,451 REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - blade/s
09/04/2021	121,451 REPAIRS TO BRAKES	Disc (incl. pads) - rear (pair)
09/04/2021	121,451 REPAIRS TO BRAKES	Disc (incl. pads) - rear (pair)
09/04/2021	121,451 SERV/SAFETY INS (+ TEST FEE)	S9 SERVICE
09/04/2021	121,451 SERV/SAFETY INS (+ TEST FEE)	S9 SERVICE
04/03/2021	118,372 COLLECTION & DELIVERY	ATTENDED TO DO 240V TEST BUT APPOINTMENT HAD
28/01/2021	118,372 REPAIRS TO BODY (NON ACCIDENT)	SIDE DOOR NOT RUNNING WELL AND NEEDS ADJUSTIN
28/01/2021	118,372 ACCIDENT REPAIRS	Door mirror glass left
28/01/2021	118,372 REPAIRS TO BRAKES	Parking brake cables right
28/01/2021	118,372 REPAIRS TO BODY (NON ACCIDENT)	Door (rear) - handle (outer) left
15/12/2020	0 REPAIRS FOR MISUSE OR DAMAGE	Change Tyre
15/12/2020	0 REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair
15/12/2020	0 REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair
15/12/2020	0 REPAIRS FOR MISUSE OR DAMAGE	Disposal of Tyre Casing
15/12/2020	0 REPAIRS FOR MISUSE OR DAMAGE	Wheel Balance
15/12/2020	0 REPAIRS FOR MISUSE OR DAMAGE	Change Tyre
15/12/2020	0 REPAIRS FOR MISUSE OR DAMAGE	Wheel Balance
15/12/2020	0 REPAIRS FOR MISUSE OR DAMAGE	Disposal of Tyre Casing
26/11/2020	0 RFL	RFL Nov 2020
24/11/2020	0 REPAIRS FOR MISUSE OR DAMAGE	MRQ01962607/MRT05068647

24/11/2020	0 REPAIRS FOR MISUSE OR DAMAGE	MRQ01962607/MRT05068649
24/11/2020	0 REPAIRS FOR MISUSE OR DAMAGE	MRQ01962607/MRT05068642
24/11/2020	0 REPAIRS FOR MISUSE OR DAMAGE	MRQ01962607/MRT05068644
24/11/2020	0 REPAIRS FOR MISUSE OR DAMAGE	MRQ01962607/MRT05068645
24/11/2020	0 REPAIRS FOR MISUSE OR DAMAGE	MRQ01962607/MRT05068643
24/11/2020	0 REPAIRS FOR MISUSE OR DAMAGE	MRQ01962607/MRT05068646
24/11/2020	0 REPAIRS FOR MISUSE OR DAMAGE	MRQ01962607/MRT05068641
24/11/2020	0 REPAIRS FOR MISUSE OR DAMAGE	MRQ01962607/MRT05068648
23/07/2020	0 REPAIRS TO BRAKES	Pads - front (axle set)
23/07/2020	0 SERV/SAFETY INS (+ TEST FEE)	29135/Checks - Check/ Investigate & Report
23/07/2020	0 BREAKDOWN RECOVERY	29113/Other Unspecified Work - Routine/ Other
23/07/2020	0 REPAIRS TO BRAKES	Pads - rear (axle set)
07/05/2020	0 SERV/SAFETY INS (+ TEST FEE)	240 Volt Inverter & Associated Wiring Equipment Test
07/05/2020	0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
07/05/2020	0 SERV/SAFETY INS (+ TEST FEE)	S8 SERVICE
31/03/2020	0 TYRES	ORDER SPARE RIM FOR TYRE AND WHEEL NUT INDICATORS. DEFECT NO 0909917
12/03/2020	0 SERV/SAFETY INS (+ TEST FEE)	29135/Checks - Check/ Investigate & Report
12/03/2020	0 REPAIRS TO SUSPENSION	Wheel stud (rear)
28/11/2019	0 SERV/SAFETY INS (+ TEST FEE)	S4 SERVICE
28/11/2019	0 SERV/SAFETY INS (+ TEST FEE)	S4 SERVICE
12/11/2019	0 REPAIRS FOR MISUSE OR DAMAGE	34 SERVICE
12/11/2019	0 REPAIRS FOR MISUSE OR DAMAGE	
12/11/2019	0 REPAIRS FOR MISUSE OR DAMAGE	
12/11/2019	0 REPAIRS FOR MISUSE OR DAMAGE	
29/10/2019	0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
29/10/2019		Class VII MoT Test
	0 SERV/SAFETY INS (+ TEST FEE)	Wheel Balance
17/10/2019 17/10/2019	0 TYRES 0 TYRES	Wheel Balance
11/10/2019	0 500 HR SERVICE & INSP 6 MONTHS	ROUTINE INSPECTION INCLUDING ATTACHMENTSA SERVICE FIXED PRICE PM
		ROUTINE INSPECTION INCLUDING ATTACHMENTSA SERVICE FIXED PRICE PM ROUTINE INSPECTION INCLUDING ATTACHMENTSA SERVICE FIXED PRICE PM
11/10/2019	0 500 HR SERVICE & INSP 6 MONTHS	
24/04/2019	0 REPAIRS TO BRAKES 0 REPAIRS TO ELECTRICS/BATTERY	Disc (incl. pads) - front (pair) REPLACE INVERTOR AND COMPLETE WIRING LOOM/CHECKS SHOW FAILURE WITHIN INVERTER. REQUIRES REWIRING
24/04/2019		
24/04/2019	0 REPAIRS TO BRAKES 0 REPAIRS TO ELECTRICS/BATTERY	Disc (incl. pads) - rear (pair)
24/04/2019	0 REPAIRS TO ELECTRICS/BATTERY	Lamps exterior (rear) - fog lamp bulb left
24/04/2019	0 REPAIRS TO ELECTRICS/BATTERY	Wiring loom repair Windowson winer, blade/e
24/04/2019 24/04/2019		Windscreen wiper - blade/s
	0 REPAIRS TO SUSPENSION	Hub oil seal (one) (Rear Susp.) S7 SERVICE
24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT)	
24/04/2019 24/04/2019		
		Inspect condition of fixed and fold out steps as per service sheet
	0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT)	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet
24/04/2019 24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT)	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away
24/04/2019 24/04/2019 24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT)	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy
24/04/2019 24/04/2019 24/04/2019 24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO ELECTRICS/BATTERY	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO COOLING SYSTEM	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO COOLING SYSTEM 0 REPAIRS TO ELECTRICS/BATTERY	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO COOLING SYSTEM 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO ELECTRICS/BATTERY	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy Lamps exterior (rear) - high level brake light bulb
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO COOLING SYSTEM 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO BODY (NON ACCIDENT)	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy Lamps exterior (rear) - high level brake light bulb Check tow bar and fixings lubricate as required as per service sheet
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	0 SERV/SAFETY INS (+ TEST FEE) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO COOLING SYSTEM 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO ELECTRICS/BATTERY 0 REPAIRS TO BODY (NON ACCIDENT) 0 REPAIRS TO FUEL SYSTEM	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy Lamps exterior (rear) - high level brake light bulb Check tow bar and fixings lubricate as required as per service sheet Fuel filter - complete
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	O SERV/SAFETY INS (+ TEST FEE) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO COOLING SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO FUEL SYSTEM O REPAIRS TO ELECTRICS/BATTERY	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy Lamps exterior (rear) - high level brake light bulb Check tow bar and fixings lubricate as required as per service sheet Fuel filter - complete Lamps exterior - rear lamp bulb
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	O SERV/SAFETY INS (+ TEST FEE) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO COOLING SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO FUEL SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy Lamps exterior (rear) - high level brake light bulb Check tow bar and fixings lubricate as required as per service sheet Fuel filter - complete Lamps exterior - rear lamp bulb Headlamp alignment
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	O SERV/SAFETY INS (+ TEST FEE) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO COOLING SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO FUEL SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy Lamps exterior (rear) - high level brake light bulb Check tow bar and fixings lubricate as required as per service sheet Fuel filter - complete Lamps exterior - rear lamp bulb Headlamp alignment 240 Volt System Equipment Test
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	O SERV/SAFETY INS (+ TEST FEE) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO COOLING SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO FUEL SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O SERV/SAFETY INS (+ TEST FEE) O REPAIRS TO BRAKES	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy Lamps exterior (rear) - high level brake light bulb Check tow bar and fixings lubricate as required as per service sheet Fuel filter - complete Lamps exterior - rear lamp bulb Headlamp alignment 240 Volt System Equipment Test Metal brake pipes
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 31/10/2018	O SERV/SAFETY INS (+ TEST FEE) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO FUEL SYSTEM O REPAIRS TO FUEL SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O SERV/SAFETY INS (+ TEST FEE) O REPAIRS TO BRAKES O REPAIRS TO ENGINE, EXHAUST	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy Lamps exterior (rear) - high level brake light bulb Check tow bar and fixings lubricate as required as per service sheet Fuel filter - complete Lamps exterior - rear lamp bulb Headlamp alignment 240 Volt System Equipment Test Metal brake pipes bleed fuel vaporizer
24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019 24/04/2019	O SERV/SAFETY INS (+ TEST FEE) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO COOLING SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO BODY (NON ACCIDENT) O REPAIRS TO FUEL SYSTEM O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O REPAIRS TO ELECTRICS/BATTERY O SERV/SAFETY INS (+ TEST FEE) O REPAIRS TO BRAKES	Class VII MoT Test Optional Equipment e.g Tubes and Flashing Beacons as per service sheet Body Exterior - side door roller guide worn away Inverter assy rear anderson plug corroded away Pollen filter Lamps exterior - number plate lamp assy Lamps exterior (rear) - high level brake light bulb Check tow bar and fixings lubricate as required as per service sheet Fuel filter - complete Lamps exterior - rear lamp bulb Headlamp alignment 240 Volt System Equipment Test Metal brake pipes

```
31/10/2018
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         regen diesel particular filter after repair.
31/10/2018
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         ENGINE MANAGMENT LIGHT ON/ POWERTRAIN WARNING LIGHT DEFECT 0909913
17/10/2018
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         Engine management - fault diagnosis
17/10/2018
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         29135/Investigate & Report
13/08/2018
                   0 REPAIRS TO DIFF/FINAL DRIVE
                                                         BT3918 Ford Transit Rear Axle Check recall end date =31-DEC-2018
24/05/2018
                                                         Oil sump (Engine)
              83,054 REPAIRS TO ENGINE, EXHAUST
24/05/2018
              83,054 REPAIRS TO BRAKES
                                                         Caliper - rear (one) left
24/05/2018
              83,054 REPAIRS TO COOLING SYSTEM
                                                         Pollen filter
24/05/2018
              83,054 SERV/SAFETY INS (+ TEST FEE)
                                                         INVESTIGATE FAULT WITH BRAKE WARNING LIGHT PERMANENTLY ILLUMINATED
24/05/2018
              83,054 REPAIRS TO BRAKES
                                                         Hydraulic fluid (Brake)
24/05/2018
              83,054 SERV/SAFETY INS (+ TEST FEE)
                                                         INVESTIGATE OIL LEAK
24/05/2018
              83,054 REPAIRS TO BRAKES
                                                         ROLLER BRAKE TEST
24/05/2018
              83.054 REPAIRS TO BRAKES
                                                         Pads - rear (axle set)
24/05/2018
              83,054 REPAIRS TO BODY (NON ACCIDENT)
                                                         Steam Clean
24/05/2018
              83.054 REPAIRS TO BRAKES
                                                         Parking brake
22/05/2018
                                                         OIL LOSS/PRESSURE
                   0 BREAKDOWN RECOVERY
16/05/2018
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         Class VII MoT Test
16/05/2018
                                                         S6 SERVICE
                   0 SERV/SAFETY INS (+ TEST FEE)
16/05/2018
                   0 REPAIRS TO BODY (NON ACCIDENT)
                                                         EA0517 Vehicle condition report recall end date =30-SEP-2018
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Windscreen wiper - blade/s
16/05/2018
15/12/2017
                   0 RFL
                                                         RFLDec17
15/11/2017
                   0 RFL
                                                         RFL November 2017
14/06/2017
                   0 COLLECTION & DELIVERY
                                                         Collection & Delivery
14/06/2017
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         S1 SERVICE
05/06/2017
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         Class VII MoT Test
05/06/2017
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         S5 SERVICE
05/06/2017
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Lamps exterior - number plate lamp bulb
05/06/2017
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Lamps exterior - number plate lamp bulb
05/06/2017
                   0 COLLECTION & DELIVERY
                                                         Collection & Delivery
30/05/2017
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         N2 - INSPECT AND GREASE
                                                         HGV Steam Clean
22/05/2017
                   0 REPAIRS TO BODY (NON ACCIDENT)
22/05/2017
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Wiring loom repair
22/05/2017
                   0 REPAIRS TO BODY (NON ACCIDENT)
                                                         REAR MARKER TAPE WITHIN 200MM OF STOP LAMP REMOVE OLD TAPE AND FIT NEW TYPE TO MOT COMPLIANCE.
22/05/2017
                                                         LOAD AND UNLOAD WITH CONCRETE BLOCKS FOR LOAD AIMULATION FOR MOT
                   0 REPAIRS TO BODY (NON ACCIDENT)
22/05/2017
                   0 REPAIRS TO BODY (NON ACCIDENT)
                                                         Mudflaps - Front
22/05/2017
                   0 REPAIRS TO HYDRAULIC UNITS
                                                         Repair Landing Leg
22/05/2017
                   0 REPAIRS TO BODY (NON ACCIDENT)
                                                         VOSA Multi Checks (RBT H/Aim S/Test)
08/05/2017
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         S1 SERVICE
                                                         N1 - INSPECT AND GREASE
18/04/2017
                   0 SERV/SAFETY INS (+ TEST FEE)
31/01/2017
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         Pads - rear (axle set)
                                                         29135/Investigate & Report
31/01/2017
                   0 SERV/SAFETY INS (+ TEST FEE)
15/11/2016
                   0 RFL
                                                         RFL DEC 2016
13/10/2016
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Charging circuit - battery - Labour
13/10/2016
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Lamps exterior - headlamp bulb - Labour
13/10/2016
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Lamps exterior - headlamp bulb - Parts
13/10/2016
                                                         Investigate & Report - Labour
                   0 ROAD TEST
13/10/2016
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Lamps exterior - headlamp bulb - Parts
13/10/2016
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Lamps exterior - headlamp bulb - Labour
09/06/2016
                                                         Lamps exterior - headlamp bulb - Parts
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Lamps exterior - number plate lamp bulb - Parts
09/06/2016
                   0 REPAIRS TO ELECTRICS/BATTERY
                   0 REPAIRS TO ELECTRICS/BATTERY
                                                         Windscreen wiper - blade/s - Parts
09/06/2016
09/06/2016
                   0 REPAIRS TO BRAKES
                                                         Hydraulic fluid (Brake) - Labour
                                                         Hydraulic fluid (Brake) - Parts
09/06/2016
                   0 REPAIRS TO BRAKES
                                                         MOT - Class VII (Goods Vehicles) - Labour
09/06/2016
                   0 MOT
                   0 SERV/SAFETY INS (+ TEST FEE)
                                                         48 month Service - Labour
09/06/2016
19/01/2016
                   0 TYRES
                                                         Tyres - Environmental Disposal.NSF - Parts
```

19/01/2016	0 TYRES	NSF 4mm left, fit 2157516AGILPG - Parts
15/11/2015	0 RFL	RFL December 2015
02/11/2015	0 MAINTENANCE	MANAGEMENT FEES
30/10/2015	0 WINDSCREEN & GLASS	Glass - windscreen repair Labour
23/10/2015	0 REPAIRS TO BRAKES	Brakes - front - Labour
23/10/2015	0 REPAIRS TO FUEL SYSTEM	Fuel filter element - in line - Labour
23/10/2015	0 REPAIRS TO BRAKES	Disc (incl. pads) - rear (pair) - Labour
19/05/2015	0 REPAIRS TO ELECTRICS/BATTERY	Lamps exterior - number plate lamp bulb - Parts
19/05/2015	0 REPAIRS TO BRAKES	Pedal assy (Brake) - Parts
19/05/2015	0 REPAIRS TO BRAKES	Pads - front (axle set) - Labour
19/05/2015	0 MOT	MOT - Class VII (Goods Vehicles) - Labour
19/05/2015	0 SERV/SAFETY INS (+ TEST FEE)	36 month Service - Labour
01/12/2014	0 REPAIRS FOR MISUSE OR DAMAGE	Glass - windscreen repair - Labour
15/11/2014	0 RFL	
28/08/2014	0 TYRES	Wheel Balance,OSF - Parts
28/08/2014	0 TYRES	Tyres - Environmental Disposal,NSF - Parts
28/08/2014	0 REPAIRS FOR MISUSE OR DAMAGE	Tyre irregular wear, NSF 3mm left,- Parts
18/06/2014	0 REPAIRS TO ELECTRICS/BATTERY	Lamps exterior - number plate lamp assy - Parts
18/06/2014	0 SERV/SAFETY INS (+ TEST FEE)	24 month Service - Labour
18/06/2014	0 REPAIRS TO ELECTRICS/BATTERY	Lamps exterior - number plate lamp assy - Labour
18/06/2014	0 REPAIRS TO ELECTRICS/BATTERY	Lamps exterior - indicator/parking light bulb - Parts
18/06/2014	0 REPAIRS TO ELECTRICS/BATTERY	Lamps exterior - indicator/parking light bulb - Labour
18/06/2014	0 ROAD TEST	Investigate & Report - Labour
18/06/2014	0 REPAIRS TO BRAKES	Pads - rear (axle set) - Labour
12/05/2014	0 TYRES	NSR,2157516AGILPG,PUNCTURED,100% Recharged - Parts
12/05/2014	0 TYRES	Tyres - Environmental Disposal - Parts
03/04/2014	0 REPAIRS FOR MISUSE OR DAMAGE	Bodywork Repairs Decal FittingHCAMH1806910 - Parts
03/04/2014	0 REPAIRS FOR MISUSE OR DAMAGE	Bodywork Repairs signs -HCAMH1806910 - Parts
01/11/2013	0 RFL	RFL November 2013
16/09/2013	0 FUEL	Fuel - Labour
16/09/2013	0 COLLECTION & DELIVERY	Vehicle Movement - Labour
16/09/2013	0 COLLECTION & DELIVERY	Vehicle Movement - Labour
24/07/2013	0 REPAIRS FOR MISUSE OR DAMAGE	,2157516G91,CORDS EXPOSED,100% Recharged - Parts
24/07/2013	0 REPAIRS FOR MISUSE OR DAMAGE	Tyres - Environmental Disposal - Parts
17/06/2013	12,286 REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - blade/s-replace worn - Labour
17/06/2013	12,286 SERV/SAFETY INS (+ TEST FEE)	12 month Service - Labour
18/03/2013	8,989 REPAIRS FOR MISUSE OR DAMAGE	Replace OS mirror glass-0909902 - Labour
18/03/2013	8,989 REPAIRS FOR MISUSE OR DAMAGE	Replace OS mirror glass-0909902 - Parts
09/11/2012	3,898 Admin Charges	Fit invertor (as per Dave Birkby)
09/11/2012	3,898 Admin Charges	Fit invertor (as per Dave Birkby)
06/11/2012	0 RFL	RFL November 2012
25/08/2012	0 ECARDS	Fit roof ventilators to AN040432
1		