

Vehicle Identification

Registration	BG15OPU	Lot Number	314
Make	ISUZU		
Model	D-MAX E/C TWIN TURBO TD		
Type	Pick-up		
Date of Registration	31/03/2015		
MoT Expires	15/01/2026		
V5	V5 here		
Service History	Yes - Service Number: 8 - Service Date: 16/01/2023		
CAP Values	Clean: £3,975.00, Average: £3,225.00, Poor: £2,225.00		
Engine	Non Runner		
Transmission	Non Runner		
Gearbox / Clutch	Inoperative		
Suspension	Inoperative		
Steering	Non Runner		
Brakes	Inoperative		
Tyres	Medium		
Interior	Minor cosmetic damage		
General Condition	Requires attention (Bodyshop repairs)		
General Comments	All panels chipped and scratched, corrosion around exterior, wheels in need of refurbishment, interior soiled. Non-runner - engine partly dismantled, no gearbox, no bucket		

Images



Vehicle Identification

Registration BG15OPU


Lot Number 314



Vehicle Identification

Registration BG150PU

Lot Number 314



Vehicle Identification

Registration BG15OPU

Lot Number 314

Items in this auction are all sold as seen and without warranty, which means there is no guarantee of the following (but not limited to): condition, working condition, description, volumes, hours, mileages, testing, condition reporting, mechanics, electrics, bodywork, parts, spares, paperwork, completeness or fitness for use.

Condition reports are prepared on the "Inspection Date" and it is entirely possible that an item's condition or working ability may change after the date we have inspected it. Brightwells do not accept any responsibility for errors, misstatements or omissions within the condition report. Any repair and refurbishment prices are estimates only. Some parts may be missing from the item and if the item is described as not working or a non-runner, this is highly likely. We strongly advise that prospective buyers come to our site and view the items.