

Vehicle Detail	BJ65HXY	FORD	TRANSIT350 L3H3 AWD
Date	Odo	Job Typ	Description
28/11/2025		0 Admin C	MISC ADDITIONAL CHARGE - ADD
12/11/2025		0 Admin C	INVESTIGATION & REPORT - ADD
11/09/2025		0 REPAIR	WISHBONE RADIUS ARM - SUS
11/09/2025		0 REPAIR	REFLECTIVE DEVICES - BOD
11/09/2025		0 REPAIR	REFLECTIVE DEVICES - BOD
11/09/2025		0 REPAIR	N/S/F WISHBONE RADIUS UPPER AR
11/09/2025		0 REPAIR	N/S/F WISHBONE RADIUS LOWER AR
11/09/2025		0 REPAIR	INDICATOR UNIT - ELE
11/09/2025		0 REPAIR	INDICATOR RELAY - ELE
11/09/2025		0 REPAIR	HORN - ELE
11/09/2025		0 REPAIR	HORN - ELE
11/09/2025		0 REPAIR	BULB MISC - ELE
11/09/2025		0 REPAIR	Bulb Misc
11/09/2025		0 REPAIR	BRAKE PIPES/HOSE/UNIONS - BRA
11/09/2025		0 REPAIR	BRAKE PIPES/HOSE/UNIONS - BRA
11/09/2025		0 REPAIR	BRAKE AXLE 2-DISCS - BRA
11/09/2025		0 REPAIR	BRAKE AXLE 2-DISCS - BRA
11/09/2025		0 SERV/S	ENGINE OIL - ENGGEARBOX OIL (ATF) - ADDINSPECTION & PREV. MAINT.MOT TEST FEE - ADD
28/08/2025		0 RFL	RFL Sept 2025
14/08/2025		0 REPAIR	ALTERNATOR - ELE
14/08/2025		0 REPAIR	ALTERNATOR - ELE
14/08/2025		0 SERV/S	EBER Drive Belt
14/08/2025		0 COLLE	(TRAVEL CHARGE(S) - ADD
14/08/2025		0 BREAKI	CALLOUT CHARGE(S) - ADD
14/08/2025		0 REPAIR	MISC FIXINGS - ADD
14/08/2025		0 Admin C	INVESTIGATION & REPORT - ADD
20/05/2025		0 REPAIR	T3 Non-scheduled Services
01/02/2025		0 REPAIR	COOLANT / ANTIFREEZE - ENG
01/02/2025		0 REPAIR	A/C REGAS - A/C
01/02/2025		0 REPAIR	CRANKSHAFT - ENG
01/02/2025		0 REPAIR	ELECTRICAL SWITCH(ES) - ELE
01/02/2025		0 REPAIR	A/C REGAS - A/C
01/02/2025		0 REPAIR	FAN BELT - ENG
01/02/2025		0 REPAIR	FRONT CRANK SEAL - ENG
01/02/2025		0 TYRES	VALVE - TYR
01/02/2025		0 TYRES	VALVE - TYR
01/02/2025		0 SERV/S	ENVIRONMENTAL CHARGE
01/02/2025		0 SERV/S	ENVIRONMENTAL CHARGE
01/02/2025		0 TYRES	BALANCE - TYR
01/02/2025		0 TYRES	BALANCE - TYR
01/02/2025		0 TYRES	235/65R16 - TYR
01/02/2025		0 TYRES	235/65R16 - TYR
01/02/2025		0 TYRES	235/65R16 - TYR
01/02/2025		0 TYRES	235/65R16 - TYR
01/02/2025		0 Admin C	INVESTIGATION & REPORT - ADD
01/02/2025		0 Admin C	Defect (Accrual Line)
01/02/2025		0 SERV/S	FUEL FILTER(S) - ENGFUEL FILTER(S) - ENG

01/02/2025	0 REPAIR WIRING / LOOM(S) - ELE
01/02/2025	0 CAM BE TIMING CHAIN / BELT - ENG
01/02/2025	0 CAM BE TIMING CASE/COVER - ENG
01/02/2025	0 REPAIR SEALANT / GASKET / DEVICES - A
01/02/2025	0 REPAIR SEALANT / GASKET / DEVICES - A
01/02/2025	0 REPAIR SEALANT / GASKET / DEVICES - A
01/02/2025	0 REPAIR Rocker Cover Gasket
01/02/2025	0 REPAIR REGULATOR - ELE
23/01/2025	0 SERV/S T3 Non-scheduled Services
23/01/2025	0 SERV/S T1 Scheduled Services - routine
23/01/2025	0 SERV/S T3 Non-scheduled Services
09/01/2025	0 BREAKI RECOVERY - NON CONTRACTUAL
09/01/2025	0 BREAKI OUT OF HOURS CALL OUT
03/01/2025	0 BREAKI RECOVERY - NON CONTRACTUAL
03/01/2025	0 BREAKI OUT OF HOURS CALL OUT
30/09/2024	0 REPAIR Recharge Remove & Refit, Turbocharger - Remove & Refit, Intercooler, Rchg From Inv: 2242 replace spl
30/09/2024	0 REPAIR Recharge Check, Engine Management Fault Diagnosis - Check, Engine management - read fault codes, Rch
30/09/2024	0 REPAIR Recharge Check, Engine Management Fault Diagnosis - Check, Engine management - fault diagnosis, Rchg
11/09/2024	0 MOT Recharge Routine, MOT - Class VII (Goods Vehicles), Rchg From Inv: 54335
11/09/2024	0 REPAIR Recharge Remove & Refit, Lamps - Remove & Refit, Lamps exterior (rear) - number plate bulb left, Rch
11/09/2024	0 REPAIR Recharge Remove & Refit, Linings (Pads & Shoes) - Remove & Refit, Pads - front (axle set), Rchg From
11/09/2024	0 SERV/S Recharge Routine, Service - Annual - Novuna Bespoke Event, Rchg From Inv: 54335
11/09/2024	0 MOT Recharge Routine, MOT - Class VII (Goods Vehicles), Rchg From Inv: 54335
11/09/2024	0 REPAIR Recharge Remove & Refit, Lamps - Remove & Refit, Lamps exterior (rear) - number plate bulb left, Rc
11/09/2024	0 REPAIR Recharge Remove & Refit, Linings (Pads & Shoes) - Remove & Refit, Pads - front (axle set), Rchg Fro
11/09/2024	0 SERV/S Recharge Routine, Service - Annual - Novuna Bespoke Event, Rchg From Inv: 54335
21/08/2024	0 RFL RFL Aug 2024
11/07/2024	0 REPAIR Recharge Check Battery - Check, Rchg From Inv: A38306 Test batteries, both OK.
10/07/2024	0 REPAIR Recharge Remove & Refit, Battery - Remove & Refit, Charging circuit - battery, Rchg From Inv: 12793
10/07/2024	0 BREAKI Recharge Routine, Other Unspecified Work - Routine, Breakdown, Rchg From Inv: 1279385 SIF - F10/07/
19/04/2024	69,582 TYRES Recharge Recharge For: WHEEL BALANCED - VAN, Position: A 4, Location: ASIDE OF Furzeleigh Mill Count
19/04/2024	69,582 TYRES Recharge Recharge For: Tyres - Environmental Disposal, Position: A 4, Location: ASIDE OF Furzeleigh
19/04/2024	69,582 TYRES Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: A 4, Location: ASIDE OF Furzeleigh Mil
19/04/2024	69,582 TYRES Recharge Recharge For: Removed Tyre, Position: A 4, 2356516HANKOOVANTRALT115113R, HANKOOK, Removal R
19/04/2024	69,582 TYRES Recharge Recharge For: R/RESP R/SIDE VAN NORMAL HRS, Location: ASIDE OF Furzeleigh Mill Country Hote
19/04/2024	69,582 TYRES Recharge Recharge For: New Tyre, Position: A 4, 2356516HANKOOVANTRALT115113R, HANKOOK, Location: ASI
30/08/2023	0 RFL RFL Sept 2023
03/05/2023	0 REPAIR offside rear abs tone wheel replaced as broke
03/05/2023	0 REPAIR R&R Reflector
03/05/2023	0 REPAIR straighten offside beacon
03/05/2023	0 REPAIR R&R Roof Beacon
03/05/2023	0 REPAIR Oil sump (Engine)
03/05/2023	0 REPAIR Lamps exterior - indicator/parking light assy
03/05/2023	0 SERV/S Engine management - fault diagnosis
03/05/2023	0 SERV/S SRS (airbag) - fault diagnosis
03/05/2023	0 SERV/S ABS - fault diagnosis
03/05/2023	0 COLLE(Collection and Delivery >5 Up to 10 miles
03/05/2023	0 SERV/S CHECK OFF ROAD SENSORS ARE STAYING ON/found t
03/05/2023	0 SERV/S SLIGHT OIL LEAK FROM FRONT/ confirmed lek/ ra

03/05/2023	0 SERV/S 240 Volt System Equipment Test
03/05/2023	0 SERV/S S7 SERVICE
03/05/2023	0 REPAIR carried out additional service checks of a/c/
31/08/2022	0 COLLE(Basic road test (add once only)
31/08/2022	0 TYRES Change Tyre
31/08/2022	0 COLLE(Collection & Delivery
31/08/2022	0 SERV/S PreMOT Test
31/08/2022	0 SERV/S Class VII MoT Test
23/08/2022	0 RFL RFL Aug 2022
23/05/2022	53,284 REPAIR check air conditioning
23/05/2022	53,284 REPAIR Door mirror glass
23/05/2022	53,284 REPAIR additional service tasks / check optional equ
23/05/2022	53,284 REPAIR Fuel filter - complete
23/05/2022	53,284 SERV/S 240 Volt System Equipment Test
23/05/2022	53,284 COLLE(Collection & Delivery
23/05/2022	53,284 REPAIR ROLLER BRAKE TEST
23/05/2022	53,284 SERV/S S6 SERVICE
16/02/2022	0 REPAIR FLAT BATTERY
22/09/2021	0 SERV/S PASSENGER LOWER MIRROR MIRROR MISSING -
22/09/2021	0 SERV/S PreMOT Test
22/09/2021	0 COLLE(Collection & Delivery
22/09/2021	0 REPAIR Metal brake pipes
22/09/2021	0 REPAIR Metal brake pipes
22/09/2021	0 REPAIR Bleed Brakes (VRS)
22/09/2021	0 REPAIR Lamps exterior - headlamp assy left
22/09/2021	0 REPAIR Lamps exterior (front) - side light bulb left
22/09/2021	0 REPAIR ROLLER BRAKE TEST
22/09/2021	0 COLLE(Basic road test (add once only)
22/09/2021	0 REPAIR Refit OSF door outer wheel arch trim as found
22/09/2021	0 SERV/S Class VII MoT Test
07/09/2021	0 RFL RFL AUG 2021
06/05/2021	52,373 SERV/S S5 SERVICE
06/05/2021	52,373 REPAIR REPAIR REAR STEP
06/05/2021	52,373 SERV/S 240 Volt System Equipment Test
06/05/2021	52,373 REPAIR Fuel filter - complete
06/05/2021	52,373 REPAIR Windscreen wiper - blade/s
06/05/2021	52,373 REPAIR A.W. as per service sheet - check all beacons
06/05/2021	52,373 REPAIR Replace missing no smoking sticker.
06/05/2021	52,373 REPAIR ROLLER BRAKE TEST
06/05/2021	52,373 SERV/S Air conditioning - fault diagnosis
06/05/2021	52,373 REPAIR Replace missing no smoking sticker.
06/05/2021	52,373 REPAIR REPAIR REAR STEP
06/05/2021	52,373 SERV/S 240 Volt System Equipment Test
06/05/2021	52,373 REPAIR ROLLER BRAKE TEST
06/05/2021	52,373 REPAIR Fuel filter - complete
06/05/2021	52,373 REPAIR Windscreen wiper - blade/s
06/05/2021	52,373 REPAIR A.W. as per service sheet - check all beacons
06/05/2021	52,373 SERV/S Air conditioning - fault diagnosis
06/05/2021	52,373 SERV/S S5 SERVICE

24/09/2020	0 SERV/S Class VII MoT Test
24/09/2020	0 SERV/S PreMOT Test
24/09/2020	0 REPAIR Headlamp Alignment
24/09/2020	0 REPAIR Windscreen wiper - blade/s
13/01/2020	0 REPAIR Rear exhaust temperature sensor
13/01/2020	0 REPAIR Fuel filter element - in line
13/01/2020	0 REPAIR DFCT0925537 - DRIVER REPORTED CONCERN - CARRY OUT DIAGNOSTICS
13/01/2020	0 REPAIR Regeneration of Particulate Filter(s)
17/10/2019	0 SERV/S Class VII MoT Test
17/10/2019	0 SERV/S Class VII MoT Test
17/10/2019	0 SERV/S Class VII MoT Test
10/10/2019	0 SERV/S Class VII MoT Test
10/10/2019	0 SERV/S Class VII MoT Test
10/10/2019	0 SERV/S Class VII MoT Test
07/10/2019	0 SERV/S S5 SERVICE
07/10/2019	0 SERV/S S5 SERVICE
07/10/2019	0 SERV/S S5 SERVICE
03/10/2019	0 REPAIR Disposal of Tyre Casing
03/10/2019	0 REPAIR Disposal of Tyre Casing
03/10/2019	0 REPAIR Wheel Balance
03/10/2019	0 REPAIR Disposal of Tyre Casing
03/10/2019	0 REPAIR Wheel Balance
03/10/2019	0 REPAIR Wheel Balance
02/10/2019	0 REPAIR Tailgate wiper - blade
02/10/2019	0 REPAIR Tailgate wiper - blade
02/10/2019	0 REPAIR Tailgate wiper - blade
27/09/2019	0 SERV/S Class VII MoT Test
27/09/2019	0 REPAIR replace n/s/r bump stop
27/09/2019	0 REPAIR R&R Roof Beacon
27/09/2019	0 SERV/S PreMOT Test
27/09/2019	0 REPAIR replace o/s/r bump stop
27/09/2019	0 REPAIR Disc (incl. pads) - front (pair)
27/09/2019	0 REPAIR Headlamp alignment
27/09/2019	0 REPAIR POWER OUTLET SOCKETS IN REAR NOT WORKING ?
27/09/2019	0 REPAIR Disc (incl. pads) - rear (pair)
27/09/2019	0 ACCIDE REPLACE SIDE REPEATER LAMP - DAMAGED
27/09/2019	0 REPAIR Change Tyre
26/09/2019	0 TYRES Disposal of Tyre Casing
26/09/2019	0 TYRES Disposal of Tyre Casing
26/09/2019	0 TYRES Disposal of Tyre Casing
17/09/2019	0 REPAIR FLAT BATTERY
17/09/2019	0 REPAIR FLAT BATTERY
17/09/2019	0 REPAIR FLAT BATTERY
16/09/2019	0 SERV/S 230 Volt Inverter & Associated Wiring Equipment Test
16/09/2019	0 SERV/S 230 Volt Inverter & Associated Wiring Equipment Test
16/09/2019	0 SERV/S 230 Volt Inverter & Associated Wiring Equipment Test
12/09/2019	0 500 HR FULL SERVICE AND INSPECTION INCLUDING ATTACHMENTS B SERVICE FIXED PRICE PM
12/09/2019	0 500 HR FULL SERVICE AND INSPECTION INCLUDING ATTACHMENTS B SERVICE FIXED PRICE PM
10/09/2019	0 REPAIR Removed o/s door panel tested speakers. Removed wires from door shut tested loom.

10/09/2019	0 REPAIR Removed o/s door panel tested speakers. Removed wires from door shut tested loom.
10/09/2019	0 REPAIR Removed o/s door panel tested speakers. Removed wires from door shut tested loom.
04/09/2019	0 REPAIR Tyre Valve Inner Repair
04/09/2019	0 REPAIR Tyre Valve Inner Repair
04/09/2019	0 REPAIR Tyre Valve Inner Repair
30/04/2019	0 SERV/S S3 SERVICE
30/04/2019	0 REPAIR 29337/Other Unspecified Work - Routine/ Brake Efficiency Test
05/12/2018	0 REPAIR Wheel Balance
05/12/2018	0 REPAIR Disposal of Tyre Casing
05/12/2018	0 REPAIR Tyre Valve Inner Repair
05/12/2018	0 REPAIR Change Tyre
25/09/2018	0 SERV/S Class VII MoT Test
25/09/2018	0 SERV/S PreMOT Test
11/07/2018	0 REPAIR Change Tyre
11/07/2018	0 REPAIR Wheel Balance
11/07/2018	0 REPAIR Tyre Valve Inner Repair
11/07/2018	0 REPAIR Disposal of Tyre Casing
11/07/2018	0 REPAIR Disposal of Tyre Casing
11/07/2018	0 REPAIR Tyre Valve Inner Repair
11/07/2018	0 REPAIR Wheel Balance
11/07/2018	0 REPAIR Change Tyre
02/05/2018	25,558 SERV/S NSF WHINNING /POSSIBLE DRIVESHAFT
20/03/2018	0 ACCIDE Lamps exterior - indicator/parking light assy
20/03/2018	0 REPAIR R&R Roof Beacon
20/03/2018	0 REPAIR Pads - front (axle set)
20/03/2018	0 SERV/S S2 SERVICE
20/03/2018	0 REPAIR Fuel filter element - in line
20/03/2018	0 REPAIR EA0517 Vehicle condition report recall end date =30-SEP-2018
20/03/2018	0 REPAIR CHECK REAR STEP
20/03/2018	0 REPAIR ROLLER BRAKE TEST
20/03/2018	0 REPAIR CHECK OPTIONAL EQUIPMENT
20/03/2018	0 REPAIR CHECK AIR CONDITIONING
20/03/2018	0 REPAIR CHECK & CLEAR EBERSPACHER FAULT CODES + RETEDT UNIT
20/03/2018	0 ACCIDE Lamps exterior - rear lamp assy
20/03/2018	0 REPAIR R&R Roof Beacon
15/08/2017	0 RFL RFL SEPT 2017
15/03/2017	0 SERV/S S1 SERVICE
15/03/2017	0 REPAIR Pads - front (axle set)
15/03/2017	0 REPAIR ROLLER BRAKE TEST
18/10/2016	0 SERV/S Inspection Service - Labour
15/08/2016	0 RFL RFL SEPT 2016
30/04/2016	0 RFL RFL APR 16
08/03/2016	0 REPAIR Cabin Heater - Supply and fit inverter & night heater - Code 75 - Parts
08/03/2016	0 REPAIR Inverter assy - Supply and fit inverter & night heater - Code 75 - Labour
08/03/2016	0 REPAIR Inverter assy - Supply and fit inverter & night heater - Code 75 - Parts
08/03/2016	0 COLLEC Vehicle Movement - Supply and fit inverter & night heater - Code 75 - Labour
08/03/2016	0 BREAKI Out Of Hours Charge - Supply and fit inverter & night heater - Code 75 - Labour
08/03/2016	0 REPAIR Cabin Heater - Supply and fit inverter & night heater - Code 75 - Labour