

Vehicle Detail	BN11ZSU	TOYOTA	HI-LUX 4X4 DIESEL	No
Date	Odo	Job Type	Description	
24/02/2025	0	RFL	RFL Mar 2025	
28/02/2024	0	RFL	RFL Mar 24	
06/03/2023	54,453	BREAKDOWN RECOVERY	29113/Other Unspecified Work - Routine/ Other	
06/03/2023	54,453	BREAKDOWN RECOVERY	29113/Other Unspecified Work - Routine/ Other	
06/03/2023	54,453	BREAKDOWN RECOVERY	29113/Other Unspecified Work - Routine/ Other	
06/03/2023	54,453	REPAIRS TO BRAKES	Hydraulic fluid (Brake)	
06/03/2023	54,453	BREAKDOWN RECOVERY	29113/Other Unspecified Work - Routine/ Other	
06/03/2023	54,453	SERV/SAFETY INS (+ TEST FEE)	S2 SERVICE	
06/03/2023	54,453	REPAIRS TO FUEL SYSTEM	Air cleaner/filter - element	
06/03/2023	54,453	SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test	
28/02/2023	0	RFL	RFL Mar 2023	
28/02/2022	0	RFL	RFL Feb 2022	
01/03/2021	0	RFL	RFL Feb 2021	
01/02/2021	46,431	SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test	
01/02/2021	46,431	REPAIRS TO BRAKES	Hydraulic fluid (Brake)	
01/02/2021	46,431	REPAIRS TO BODY (NON ACCIDENT)	CHECK LIVERY (PAINT WORK & BODY WORK)	
01/02/2021	46,431	SERV/SAFETY INS (+ TEST FEE)	S10 SERVICE	
01/02/2021	46,431	REPAIRS TO SUSPENSION	Spring/torsion bar (one) (Rear Susp.) left	
29/02/2020	0	RFL	RFL FEB 2020	
01/03/2019	0	RFL	RFL February 2019	
15/02/2018	0	RFL	RFL NE MAR 18	
31/01/2018	37,496	SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test	
31/01/2018	37,496	REPAIRS TO ENGINE, EXHAUST	DEF0117 Vehicle Description Audit recall end date =30-APR-2018	
31/01/2018	37,496	REPAIRS TO BODY (NON ACCIDENT)	EA0517 Vehicle condition report recall end date =30-SEP-2018	
31/01/2018	37,496	SERV/SAFETY INS (+ TEST FEE)	S7 SERVICE	
28/09/2017	0	TYRES	29130/Wheel Balance	
28/09/2017	0	REPAIRS TO SUSPENSION	Wheel Alignment - front/rear	
28/09/2017	0	REPAIRS TO BRAKES	Disc (incl. pads) - front (pair)	
1				