

Vehicle Identification

|                      |                                                                                                                  |            |     |
|----------------------|------------------------------------------------------------------------------------------------------------------|------------|-----|
| Registration         | LP12VMR                                                                                                          | Lot Number | 322 |
| Make                 | TOYOTA                                                                                                           |            |     |
| Model                | HILUX HL2 D-4D 4X4 DCB                                                                                           |            |     |
| Type                 | Light 4X4 Utility                                                                                                |            |     |
| Date of Registration | 17/08/2012                                                                                                       |            |     |
| Miles / KMs / Hours  | 90,960 miles - Warranted                                                                                         |            |     |
| MoT Expires          | 15/07/2026                                                                                                       |            |     |
| V5                   | V5 here                                                                                                          |            |     |
| Service History      | Yes - Service Number: 2 - Service Date: 19/08/2020                                                               |            |     |
| CAP Values           | Clean: £4,825.00, Average: £3,775.00, Poor: £2,500.00                                                            |            |     |
| Engine               | OK                                                                                                               |            |     |
| Transmission         | OK                                                                                                               |            |     |
| Gearbox / Clutch     | OK                                                                                                               |            |     |
| Suspension           | OK                                                                                                               |            |     |
| Steering             | OK                                                                                                               |            |     |
| Brakes               | OK                                                                                                               |            |     |
| Tyres                | Medium                                                                                                           |            |     |
| Interior             | Holes/Missing items                                                                                              |            |     |
| General Condition    | Requires attention (Bodyshop repairs)                                                                            |            |     |
| General Comments     | All panels chipped and scratched, some panels dented, corrosion around exterior, wheels in need of refurbishment |            |     |

Images



Vehicle Identification

Registration LP12VMR

Lot Number 322



## Vehicle Identification

Registration LP12VMR

Lot Number 322



Vehicle Identification

Registration LP12VMR

Lot Number 322



### Vehicle Identification

Registration LP12VMR

Lot Number 322



Items in this auction are all sold as seen and without warranty, which means there is no guarantee of the following (but not limited to): condition, working condition, description, volumes, hours, mileages, testing, condition reporting, mechanics, electrics, bodywork, parts, spares, paperwork, completeness or fitness for use.

Condition reports are prepared on the "Inspection Date" and it is entirely possible that an item's condition or working ability may change after the date we have inspected it. Brightwells do not accept any responsibility for errors, misstatements or omissions within the condition report. Any repair and refurbishment prices are estimates only. Some parts may be missing from the item and if the item is described as not working or a non-runner, this is highly likely. We strongly advise that prospective buyers come to our site and view the items.