
Vehicle Identification

Registration	<input type="text" value="R321OFO"/>	Lot Number	<input type="text" value="262"/>
Serial Number	<input type="text" value="WDB6770842K231203"/>	Fleet Number	<input type="text"/>

Inspection Date	01/12/2020
Make	MERCEDES
Model	1124 Automatic Rescue Appliance
Year	1997
Miles / KMs / Hours	41,425 kms - Unwarranted
Attachments	Engine will not cut out on its own, will not drive due to air issues, brakes wound off. Buyer Passport Id Required For Mod Approval Before Collection, Sold As Seen, VAT at 20% will be added to the sale price of this lot, A Buyers Premium will be charged at 5% plus VAT on the sale price and added to your invoice.
Registration Number	R321OFO
Serial Number	WDB6770842K231203
Engine	Engine appears to be in working order, the vehicle requires a jump pack to start up, runs on its own power once started. Will not cut out on its own.
Transmission / Functionality	Transmission is not in working order, the vehicle appears to not air up properly, brakes have been wound off to allow movement.
Tyres & undercarriage	Tyres are worn
Aesthetic condition	Aesthetically in an average condition, there is some paint fade over the vehicle. Some heavy scratching in areas, paint has been chipped and flaking.
Brakes & Steering	Brakes and steering have not been tested as the vehicle cannot be driven

Images

Vehicle Identification

Registration

Lot Number

Serial Number

Fleet Number

