

Vehicle Detail	MJ17HCX	FORD	No
Date	Odo	Job Type	Description
23/10/2025	0	REPAIRS TO STEERING	WHEEL BEARING(S) - AXL
23/10/2025	0	REPAIRS TO STEERING	WHEEL BEARING(S) - AXL
23/10/2025	0	CAM BELT/TIMING BELT	TIMING CHAIN / BELT - ENG
23/10/2025	0	REPAIRS TO STEERING	STEERING TRACK ROD - STE
23/10/2025	0	REPAIRS TO STEERING	STEERING TRACK ROD - STE
23/10/2025	0	REPAIRS TO ENGINE, EXHAUST	SEALANT / GASKET / DEVICES - A
23/10/2025	0	REPAIRS TO ENGINE, EXHAUST	OIL PICK UP PIPE - G/B
23/10/2025	0	REPAIRS TO DIFF/FINAL DRIVE	HUB NUT - AXL
23/10/2025	0	REPAIRS TO SUSPENSION	HUB ASSEMBLY - AXL
23/10/2025	0	REPAIRS TO SUSPENSION	HUB ASSEMBLY - AXL
23/10/2025	0	REPAIRS TO ENGINE, EXHAUST	FRONT CRANK SEAL - ENG
23/10/2025	0	SERV/SAFETY INS (+ TEST FEE)	ENGINE OIL FILTER - ENG
23/10/2025	0	SERV/SAFETY INS (+ TEST FEE)	ENGINE OIL (LOW ASH) - ADD
23/10/2025	0	REPAIRS TO DIFF/FINAL DRIVE	DRIVE SHAFT O/S - TRS
23/10/2025	0	REPAIRS TO DIFF/FINAL DRIVE	DRIVE SHAFT O/S - TRS
23/10/2025	0	REPAIRS TO ENGINE, EXHAUST	Diagnostics
23/10/2025	0	REPAIRS TO BRAKES	BRAKE AXLE 2-PADS - BRA
23/10/2025	0	REPAIRS TO BRAKES	BRAKE AXLE 2-DISCS - BRA
23/10/2025	0	REPAIRS TO BRAKES	BRAKE AXLE 2-DISCS - BRA
23/10/2025	0	REPAIRS TO BRAKES	BRAKE AXLE 1-PADS - BRA
23/10/2025	0	REPAIRS TO BRAKES	BRAKE AXLE 1-DISCS - BRA
23/10/2025	0	REPAIRS TO BRAKES	BRAKE AXLE 1-DISCS - BRA
23/10/2025	0	REPAIRS TO SUSPENSION	BOTTOM BALL JOINT - SUS
23/10/2025	0	REPAIRS TO SUSPENSION	BOTTOM BALL JOINT - SUS
13/10/2025	0	COLLECTION & DELIVERY	TRAVEL CHARGE(S) - ADD
13/10/2025	0	BREAKDOWN RECOVERY	CALLOUT CHARGE(S) - ADD
13/10/2025	0	REPAIRS TO FITTINGS	MISC FIXINGS - ADD
13/10/2025	0	Admin Charges	INVESTIGATION & REPORT - ADD
13/10/2025	0	SERV/SAFETY INS (+ TEST FEE)	BELTS - FRI
13/10/2025	0	SERV/SAFETY INS (+ TEST FEE)	BELTS - FRI
02/06/2025	0	RFL	RFL Jun 2025
30/08/2024	0	REPAIRS FOR MISUSE OR DAMAGE	Recharge Recharge For: Removed Tyre, Position: B 4, 2156515HANKOOVANTRALT104102T, HANKOOK, Removal R
30/08/2024	0	TYRES	Recharge Recharge For: WHEEL BALANCED - VAN, Position: B 4, Location: 13 Sefton Road Ashton-in-Maker
30/08/2024	0	TYRES	Recharge Recharge For: WHEEL BALANCED - VAN, Position: B 1, Location: 13 Sefton Road Ashton-in-Maker
30/08/2024	0	TYRES	Recharge Recharge For: Tyres - Environmental Disposal, Position: B 4, Location: 13 Sefton Road Ashto
30/08/2024	0	TYRES	Recharge Recharge For: Tyres - Environmental Disposal, Position: B 1, Location: 13 Sefton Road Ashto
30/08/2024	0	TYRES	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: B 4, Location: 13 Sefton Road Ashton-i
30/08/2024	0	TYRES	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: B 1, Location: 13 Sefton Road Ashton-i
30/08/2024	0	TYRES	Recharge Recharge For: Removed Tyre, Position: B 1, 2156515HANKOOVANTRALT104102T, HANKOOK, Removal R
30/08/2024	0	TYRES	Recharge Recharge For: R/RESP R/SIDE VAN NORMAL HRS, Location: 13 Sefton Road Ashton-in-Makerfield W
30/08/2024	0	TYRES	Recharge Recharge For: New Tyre, Position: B 4, 2156515HANKOOVANTRALT104102T, HANKOOK, Location: 13
30/08/2024	0	TYRES	Recharge Recharge For: New Tyre, Position: B 1, 2156515HANKOOVANTRALT104102T, HANKOOK, Location: 13
30/08/2024	0	REPAIRS FOR MISUSE OR DAMAGE	Recharge Recharge For: Removed Tyre, Position: B 4, 2156515HANKOOVANTRALT104102T, HANKOOK, Removal
30/08/2024	0	TYRES	Recharge Recharge For: WHEEL BALANCED - VAN, Position: B 4, Location: 13 Sefton Road Ashton-in-Make
30/08/2024	0	TYRES	Recharge Recharge For: WHEEL BALANCED - VAN, Position: B 1, Location: 13 Sefton Road Ashton-in-Make
30/08/2024	0	TYRES	Recharge Recharge For: Tyres - Environmental Disposal, Position: B 4, Location: 13 Sefton Road Asht
30/08/2024	0	TYRES	Recharge Recharge For: Tyres - Environmental Disposal, Position: B 1, Location: 13 Sefton Road Asht
30/08/2024	0	TYRES	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: B 4, Location: 13 Sefton Road Ashton-
30/08/2024	0	TYRES	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: B 1, Location: 13 Sefton Road Ashton-
30/08/2024	0	TYRES	Recharge Recharge For: Removed Tyre, Position: B 1, 2156515HANKOOVANTRALT104102T, HANKOOK, Removal
30/08/2024	0	TYRES	Recharge Recharge For: R/RESP R/SIDE VAN NORMAL HRS, Location: 13 Sefton Road Ashton-in-Makerfield
30/08/2024	0	TYRES	Recharge Recharge For: New Tyre, Position: B 4, 2156515HANKOOVANTRALT104102T, HANKOOK, Location: 13
30/08/2024	0	TYRES	Recharge Recharge For: New Tyre, Position: B 1, 2156515HANKOOVANTRALT104102T, HANKOOK, Location: 13
31/07/2024	0	REPAIRS TO BRAKES	Recharge Remove & Refit, Disc - Remove & Refit, Disc (incl. pads) - front (pair), Rchg From Inv: 38

31/07/2024	0 REPAIRS TO BODY (NON ACCIDENT)	Recharge Remove & Refit, Bonnet - Remove & Refit, Bonnet release cable, Rchg From Inv: 38431 Cables
31/07/2024	0 REPAIRS TO BODY (NON ACCIDENT)	Recharge Remove & Refit, Bonnet - Remove & Refit, Bonnet - lock cylinder, Rchg From Inv: 38431 Lock
31/07/2024	0 REPAIRS TO BODY (NON ACCIDENT)	Recharge Remove & Refit, Bonnet - Remove & Refit, Bonnet - lock assy, Rchg From Inv: 38431 bonnet w
31/07/2024	0 ROAD TEST	Recharge Check, Checks - Check, Investigate & Report, Rchg From Inv: 38431 Brake pad light lit on d
23/05/2024	0 RFL	RFL Jun 2024
13/05/2024	122,806 TYRES	Recharge Recharge For: MINOR PUNCTURE REPAIR - CAR, Position: B 4, Location: 13 Sefton Road Ashton-i
13/05/2024	122,806 TYRES	Recharge Recharge For: TUBELESS VALVE FITTED - CAR, Position: B 4, Location: 13 Sefton Road Ashton-i
13/05/2024	122,806 TYRES	Recharge Recharge For: WHEEL BALANCED - VAN, Position: B 4, Location: 13 Sefton Road Ashton-in-Maker
16/02/2024	117,994 SERV/SAFETY INS (+ TEST FEE)	Recharge Routine, 8 year Service - 2016/18 Transit Custom, Tourneo Custom (36,000 Intervals), Rchg
16/02/2024	117,994 REPAIRS TO ELECTRICS/BATTERY	Recharge Remove & Refit, Lamps - Remove & Refit, Lamps exterior (front) - side repeater bulb left, R
16/02/2024	117,994 REPAIRS TO BRAKES	Recharge Remove & Refit, Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake), Rchg From Inv: 3
16/02/2024	117,994 REPAIRS TO BRAKES	Recharge Remove & Refit, Disc - Remove & Refit, Disc (incl. pads) - rear (pair), Rchg From Inv: 3703
16/02/2024	117,994 REPAIRS TO BRAKES	Recharge Remove & Refit, Calipers - Remove & Refit, Caliper - rear (one) right, Rchg From Inv: 37035
16/02/2024	117,994 MOT	Recharge Routine, MOT - Class VII (Goods Vehicles), Rchg From Inv: 37035
16/02/2024	117,994 Admin Charges	Recharge Routine, Other Unspecified Work - Routine, Unscheduled Labour, Rchg From Inv: 37035 FAIL -
21/12/2023	115,390 TYRES	Recharge Recharge For: WHEEL BALANCED - VAN, Position: A 1, Location: 13 Sefton Road Ashton-in-Maker
21/12/2023	115,390 TYRES	Recharge Recharge For: Tyres - Environmental Disposal, Position: A 4, Location: 13 Sefton Road Ashto
21/12/2023	115,390 TYRES	Recharge Recharge For: Tyres - Environmental Disposal, Position: A 4, Location: 13 Sefton Road Ashto
21/12/2023	115,390 TYRES	Recharge Recharge For: Tyres - Environmental Disposal, Position: A 1, Location: 13 Sefton Road Ashto
21/12/2023	115,390 TYRES	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: A 4, Location: 13 Sefton Road Ashton-i
21/12/2023	115,390 TYRES	Recharge Recharge For: TUBELESS VALVE FITTED - VAN, Position: A 1, Location: 13 Sefton Road Ashton-i
21/12/2023	115,390 TYRES	Recharge Recharge For: Removed Tyre, Position: A 4, 2156515MICHELAGILISCROSSCLIMATE104T, MICHELIN, R
21/12/2023	115,390 TYRES	Recharge Recharge For: Removed Tyre, Position: A 1, 2156515MICHELAGILISCROSSCLIMATE104T, MICHELIN, R
21/12/2023	115,390 TYRES	Recharge Recharge For: New Tyre, Position: A 4, 2156515MICHELAGILISCROSSCLIMATE104T, MICHELIN, Locat
21/12/2023	115,390 TYRES	Recharge Recharge For: New Tyre, Position: A 1, 2156515MICHELAGILISCROSSCLIMATE104T, MICHELIN, Locat
10/11/2023	113,665 COLLECTION & DELIVERY	Recharge Routine Vehicle Movement approved by CFM (Terry Cook), Rchg From Inv: UV491048/A
10/11/2023	113,665 FUEL	Recharge Fit Fuel, Rchg From Inv: UV491048/A
17/10/2023	113,665 COLLECTION & DELIVERY	Recharge Routine, Movement - Routine, Movement - Miscellaneous, Rchg From Inv: 00-669351 MOVEMENT TO
12/10/2023	0 REPAIRS TO FUEL SYSTEM	Recharge Remove & Refit All Injectors (all), Rchg From Inv: 133719
12/10/2023	0 REPAIRS TO ENGINE, EXHAUST	Recharge Remove & Refit Engine assy, Rchg From Inv: 133719 Replace engine and injectors Replace engi
12/10/2023	0 REPAIRS TO ELECTRICS/BATTERY	Recharge Check & Adjust Alternator/dynamo charging rate, Rchg From Inv: 133719 on road test (after i
12/10/2023	0 REPAIRS TO COOLING SYSTEM	Recharge Remove & Refit Water pump, Rchg From Inv: 133719
12/10/2023	0 REPAIRS TO ELECTRICS/BATTERY	Recharge Remove & Refit Air Conditioning System - compressor, Rchg From Inv: 133719
12/10/2023	0 REPAIRS TO BRAKES	Recharge Remove & Refit Vacuum pump, Rchg From Inv: 133719
12/10/2023	0 REPAIRS TO ENGINE, EXHAUST	Recharge Remove & Refit Low AdBlue Fluid, Rchg From Inv: 133719 part of repair part of repair
12/10/2023	0 REPAIRS TO ENGINE, EXHAUST	Recharge Remove & Refit Exhaust Gas Recirculation (EGR) cooler, Rchg From Inv: 133719
09/10/2023	0 BREAKDOWN RECOVERY	Recharge Routine, Other Unspecified Work - Routine, Breakdown, Rchg From Inv: 1145536 09/10/202310:4
06/06/2023	0 RFL	RFL Jun 2023
26/05/2023	0 MAINTENANCE	BASIC ROAD TEST
26/05/2023	0 REPAIRS TO ELECTRICS/BATTERY	REPLACE BRAKE LIGHT BULB
26/05/2023	0 REPAIRS TO CLUTCH	Slave cylinder (Clutch)
26/05/2023	0 REPAIRS TO ELECTRICS/BATTERY	BRAKE LIGHT INOP. DIAGNOSE
26/05/2023	0 REPAIRS TO CLUTCH	CLUTCH ISSUE. DIAGNOSE
24/05/2023	0 BREAKDOWN RECOVERY	LOSS OF FLUID
20/02/2023	0 REPAIRS TO SUSPENSION	Arm (Front Susp.) - lower assy/wishbone (one
20/02/2023	0 REPAIRS TO ELECTRICS/BATTERY	Charging circuit - battery
20/02/2023	0 REPAIRS TO SUSPENSION	Rear Wheel Bearing Left
20/02/2023	0 REPAIRS TO SUSPENSION	Rear Wheel Bearing Right
20/02/2023	0 REPAIRS TO BRAKES	Disc (incl. pads) - rear (pair)
20/02/2023	0 REPAIRS TO COOLING SYSTEM	Coolant pressure cap
20/02/2023	0 REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - blade/s
20/02/2023	0 REPAIRS INTERNAL FITTINGS	check internal racking additional work as per
20/02/2023	0 REPAIRS TO BODY (NON ACCIDENT)	check all steps additional work as per servic
20/02/2023	0 REPAIRS TO BRAKES	Pads - front (axle set)
20/02/2023	0 REPAIRS TO ELECTRICS/BATTERY	check all beacons additional work as per serv
20/02/2023	0 REPAIRS TO COOLING SYSTEM	Pollen filter

20/02/2023	0 REPAIRS TO BRAKES	ROLLER BRAKE TEST
20/02/2023	0 SERV/SAFETY INS (+ TEST FEE)	STICKING BRAKE PAD OR CALAPER ON FRONT - rear
20/02/2023	0 SERV/SAFETY INS (+ TEST FEE)	S6 SERVICE
20/02/2023	0 REPAIRS TO BODY (NON ACCIDENT)	check tow bar additional work as per service
20/02/2023	0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
01/11/2022	0 REPAIRS FOR MISUSE OR DAMAGE	DOOR JAMMED CLOSED
10/06/2022	0 RFL	RFL Jun 2022
01/04/2022	0 REPAIRS TO BODY (NON ACCIDENT)	Body Exterior - Bonnet catch need looking at/
01/04/2022	0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
01/04/2022	0 SERV/SAFETY INS (+ TEST FEE)	S5 SERVICE
01/04/2022	0 REPAIRS TO COOLING SYSTEM	Radiator (Cooling)
01/04/2022	0 REPAIRS TO BODY (NON ACCIDENT)	Bonnet - lock assy
01/04/2022	0 REPAIRS TO BRAKES	Pads - rear (axle set)
14/01/2022	84,646 TYRES	Wheel Balance
14/01/2022	84,646 TYRES	Tyre Valve Inner Repair
14/01/2022	84,646 TYRES	Change Tyre
14/01/2022	84,646 TYRES	C&A Wheel Alignment
14/01/2022	84,646 TYRES	Disposal of Tyre Casing
10/01/2022	84,403 REPAIRS TO BRAKES	Disc (incl. pads) - front (pair)
10/01/2022	84,404 BREAKDOWN RECOVERY	BRAKES
16/09/2021	0 REPAIRS TO BODY (NON ACCIDENT)	Door (front) - checkstrap
16/09/2021	0 REPAIRS TO BRAKES	Disc (incl. pads) - rear (pair)
16/09/2021	0 REPAIRS TO BRAKES	Pads - rear (axle set)
16/09/2021	0 SERV/SAFETY INS (+ TEST FEE)	SMALL HINGE ON ONE OF DOORS HAS CRACKED//chec
16/09/2021	0 SERV/SAFETY INS (+ TEST FEE)	SQUEAKING FROM ONE OF BACK WHEELS/ POSSIBLE B
07/06/2021	0 RFL	RFL June 2021
10/03/2021	67,806 REPAIRS TO BODY (NON ACCIDENT)	optional equipment. combined 5 tasks 5 x 0.1
10/03/2021	67,806 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
10/03/2021	67,806 SERV/SAFETY INS (+ TEST FEE)	S4 SERVICE
10/03/2021	67,806 REPAIRS TO ELECTRICS/BATTERY	adjust headlight aim
10/03/2021	67,806 SERV/SAFETY INS (+ TEST FEE)	PreMOT Test
16/02/2021	67,461 REPAIRS FOR MISUSE OR DAMAGE	Disposal of Tyre Casing
16/02/2021	67,461 REPAIRS FOR MISUSE OR DAMAGE	Tyre Valve Inner Repair
16/02/2021	67,461 REPAIRS FOR MISUSE OR DAMAGE	Tyre Call Out
16/02/2021	67,461 REPAIRS FOR MISUSE OR DAMAGE	Wheel Balance
16/02/2021	67,461 REPAIRS FOR MISUSE OR DAMAGE	Change Tyre
07/12/2020	0 REPAIRS TO BODY (NON ACCIDENT)	JOB07212605/TSK15287713
07/12/2020	0 MAINTENANCE	JOB07212605/TSK15287688
07/12/2020	0 REPAIRS TO ELECTRICS/BATTERY	JOB07212605/TSK15283849
11/11/2020	0 REPAIRS TO ELECTRICS/BATTERY	**SAFETY RECALL** - EA0220 Ford Transit Run o
11/11/2020	0 COLLECTION & DELIVERY	Collection & Delivery
29/06/2020	0 RFL	RFL May 2020
25/03/2020	0 REPAIRS TO BRAKES	Pads - front (axle set)
25/03/2020	0 REPAIRS TO COOLING SYSTEM	service sheet states to check air conditioning as extra work so did this as extra task
25/03/2020	0 REPAIRS TO BRAKES	customer fault for brake s binding. will have to carry out investigation part of this will include a
25/03/2020	0 REPAIRS TO BODY (NON ACCIDENT)	bonnet fault reported by driver appears to be the latch itself on the front grille so going to order
25/03/2020	0 SERV/SAFETY INS (+ TEST FEE)	Class VII MoT Test
25/03/2020	0 REPAIRS TO BRAKES	Pads - rear (axle set)
25/03/2020	0 REPAIRS TO BODY (NON ACCIDENT)	check operation and security of steps and beacons these are extra work on service sheet with combine
25/03/2020	0 REPAIRS TO ENGINE, EXHAUST	oil light on the dash saying replace oil. it is additional work if this happens as stated in service
25/03/2020	0 SERV/SAFETY INS (+ TEST FEE)	S3 SERVICE
25/03/2020	0 REPAIRS TO BODY (NON ACCIDENT)	fit complete bonnet lock mechanism the old one is seized solid. strip front grille to remove latch a
06/09/2019	0 500 HR SERVICE & INSP 6 MONTHS	INSPECTION - PUMP
06/09/2019	0 500 HR SERVICE & INSP 6 MONTHS	INSPECTION - PUMP
15/05/2019	0 RFL	RFL June 2019
09/05/2019	0 REPAIRS TO BODY (NON ACCIDENT)	check internal racking as per service sheet

09/05/2019	0 REPAIRS TO BODY (NON ACCIDENT)	wipers
09/05/2019	0 SERV/SAFETY INS (+ TEST FEE)	S2 SERVICE
09/05/2019	0 REPAIRS TO BRAKES	brake test aw
09/05/2019	0 REPAIRS TO BODY (NON ACCIDENT)	check optional equipment as per service sheet
25/03/2019	0 COLLECTION & DELIVERY	Basic road test (add once only)
25/03/2019	0 SERV/SAFETY INS (+ TEST FEE)	Engine management - fault diagnosis
25/03/2019	0 REPAIRS TO BRAKES	Pads - rear (axle set)
25/03/2019	0 REPAIRS TO FUEL SYSTEM	Regeneration of Particulate Filter(s)
25/03/2019	0 REPAIRS TO BRAKES	Pads - front (axle set)
25/03/2019	0 REPAIRS TO FUEL SYSTEM	Regeneration of Particulate Filter(s)
25/03/2019	0 REPAIRS TO BRAKES	BRAKES WARNING LIGHT
25/03/2019	0 REPAIRS TO BRAKES	Pads - front (axle set)
25/03/2019	0 REPAIRS TO BRAKES	Pads - rear (axle set)
25/03/2019	0 SERV/SAFETY INS (+ TEST FEE)	Engine management - fault diagnosis
25/03/2019	0 REPAIRS TO BRAKES	BRAKES WARNING LIGHT
25/03/2019	0 COLLECTION & DELIVERY	Basic road test (add once only)
08/03/2019	0 REPAIRS FOR MISUSE OR DAMAGE	REPAIR PUNCTURE
08/03/2019	0 REPAIRS FOR MISUSE OR DAMAGE	REPAIR PUNCTURE
17/12/2018	0 TYRES	Disposal of Tyre Casing
17/12/2018	0 TYRES	Tyre Valve Inner Repair
17/12/2018	0 TYRES	Change Tyre
17/12/2018	0 TYRES	Tyre Valve Inner Repair
17/12/2018	0 TYRES	Wheel Balance
17/12/2018	0 TYRES	Disposal of Tyre Casing
17/12/2018	0 TYRES	Change Tyre
17/12/2018	0 TYRES	Wheel Balance
26/09/2018	0 REPAIRS TO ELECTRICS/BATTERY	Windscreen wiper - blade/s
02/07/2018	0 REPAIRS TO ELECTRICS/BATTERY	Electric window motor - front door
02/07/2018	0 COLLECTION & DELIVERY	Collection & Delivery
02/07/2018	0 REPAIRS TO BRAKES	ROLLER BRAKE TEST
02/07/2018	0 REPAIRS TO BODY (NON ACCIDENT)	EA0517 Vehicle condition report recall end date =30-SEP-2018
02/07/2018	0 SERV/SAFETY INS (+ TEST FEE)	S1 SERVICE
15/06/2018	0 RFL	RFLJun18