

Vehicle Identification

Registration	AN83AB	Lot Number	900
Make	VOLVO		
Model	Saxon		
Type	Fire Appliance FL6 H 4x2		
CAP Values	Clean: £0.00, Average: £0.00, Poor: £0.00		
General Comments	Unable to ascertain mileage due to dashboard display not working		

Images





Vehicle Identification

Registration

AN83AB

Lot Number

900



Vehicle Identification

Registration

AN83AB

Lot Number

900



Items in this auction are all sold as seen and without warranty, which means there is no guarantee of the following (but not limited to): condition, working condition, description, volumes, hours, mileages, testing, condition reporting, mechanics, electrics, bodywork, parts, spares, paperwork, completeness or fitness for use.

Condition reports are prepared on the “Inspection Date” and it is entirely possible that an item’s condition or working ability may change after the date we have inspected it. Brightwells do not accept any responsibility for errors, misstatements or omissions within the condition report. Any repair and refurbishment prices are estimates only. Some parts may be missing from the item and if the item is described as not working or a non-runner, this is highly likely. We strongly advise that prospective buyers come to our site and view the items.