

WX15NHU	A&E		Staverton Amb Stn				
Veh Deep Clean	07/01/2016	14:56	07/01/2016	14:58	11,786	Gloucester	GC000345
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	07/02/2016	17:54	07/02/2016	21:00	16,625	Gloucester	GC000582
Breakdown	O/S front has nail in it						
BREAKDOWN	09/02/2016	07:39	10/02/2016	12:24	16,725	Gloucester	GC000592
17 Tyres 89 Seats	at staverton check tyre pressures . Other Rear passenger arm rest floppy						
Veh Deep Clean	09/02/2016	10:20	09/02/2016	10:29	16,725	Gloucester	GC000597
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/02/2016	09:54	20/02/2016	12:00	18,329	Gloucester	GC000664
17 Tyres Replace 18 Wheels Check Torques 34 Lights 85 Body Interior 1 Safety Inspection Travel Time Tail Lift Inspection 92 - C Service Service C UB Fire Suppression Service	replaced all 4 rear tyres n/s/r marker lamp repair arm rest bring in from staverton						
SAFETY INSPECTION	22/02/2016	14:44	22/02/2016	14:45	18,329	Gloucester	GC000677
18 Wheels Check Torques Safety Inspection							

SAFETY INSPECTION	22/02/2016	14:45	22/02/2016	14:46	18,329	Gloucester	GC000678
18 Wheels Check Torques Safety Inspection							
BREAKDOWN	04/03/2016	10:36	08/03/2016	11:22	20,346	Gloucester	GC000753
71 Body External Steps Travel Time	frame bent						
Veh Deep Clean	07/04/2016	10:33	07/04/2016	10:35	26,202	Gloucester	GC000950
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	07/04/2016	12:36	07/04/2016	15:02	26,217	Gloucester	GC000952
13 Handbrake 18 Wheels Check Torques 44 Add Ad Blue 55 Tail Lift Road Test Safety Inspection	adjust h/brakeshoes top up 10lts check clean lube/grease lift + free release valves						
Breakdown	01/05/2016	19:24	03/05/2016	09:22	29,056	Gloucester	GC001100
17 Tyres Replace Breakdown	Screw through tyre F/N/S						
Veh Deep Clean	16/05/2016	13:36	16/05/2016	13:38	31,223	Gloucester	GC001181
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	17/05/2016	08:59	20/05/2016	15:14	31,246	Gloucester	GC001185
18 Wheels Check Torques							

34 Lighting System	replace both fog lamps
44 Fuel System 1	Other 824 No fuel cap
71 Body Exterior 1	fit call sign
Safety Inspection	
Tail Lift Inspection	

SAFETY INSPECTION	30/06/2016	14:46	02/07/2016	16:00	41,361	Gloucester	GC001449
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

13 Brake Pads	front pads
17 Tyres Replace	replace five tyres
18 Wheels Check Torques	
71 Body External Steps	
Safety Inspection	
Handbrake Cable Replacement	Replace rear handbrake cables
93 - D Service	
Service D	
Travel Time	
MOT	

Veh Deep Clean	30/06/2016	14:59	30/06/2016	15:01	41,048	Gloucester	GC001452
-----------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	28/07/2016	17:53	01/08/2016	08:15	46,266	Gloucester	GC001603
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

02 Windscreen	
34 Lights	
Breakdown	smashed
Wash & Vacuum	vacuum glass from interior

Vehicle Deep Clean	25/08/2016	01:38	25/08/2016	01:39	52,032	Gloucester	GC001748
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	25/08/2016	09:25	25/08/2016	09:28	52,032	Gloucester	GC001999
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	29/08/2016	08:39	31/08/2016	11:05	52,045	Gloucester	GC001765
01 Air Conditioning 1							
02 Windscreen Wipers							Monitoring
13 Discs							
16 Suspension 1							Monitoring
18 Wheels							
18 Wheels Check Torques							
34 Lighting System							
34 Lights							
34 Lights Bulb Replacement							
45 Engine Ad Blue							
85 Body Interior 1							
86 Door Lock							
Safety Inspection							
Tail Lift Annual Service							
UB Fire Suppression Service							
Tail Lift Inspection							
Gearbox Oil & Filter Change							
Breakdown	16/10/2016	11:28	17/10/2016	07:28	61,709	Gloucester	GC002096
44 Fuel System 1							
Breakdown							
Travel Time							
Vehicle Deep Clean	18/10/2016	21:09	18/10/2016	21:12	61,715	Gloucester	GC002118
Vehicle Deep Clean							
BREAKDOWN	28/10/2016	10:15	28/10/2016	15:06	63,628	Gloucester	GC002192
17 Tyres Replace							

SAFETY INSPECTION	01/11/2016	12:02	01/11/2016	12:03	64,966	Gloucester	GC002223
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection

SAFETY INSPECTION	01/11/2016	12:03	03/11/2016	08:05	64,966	Gloucester	GC002224
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

02 Windscreen Wipers	replace
11 Axle Front	clean flanges
13 Brake Test	
13 Brakes 1	fit front pads and discs
18 Wheels Check Torques	
44 Add Ad Blue	top up
85 Body Interior 1	refit stryker door close strip
99 Diagnostic Test	reset service indicator
Safety Inspection	
Fit Throw Lines & SOP	SV put on vehicle.
92 - C Service	
Service C	
Remove Ventilator Brackets	Remove Ventilator Brackets and Fill
Tail Lift Inspection	

BREAKDOWN	20/11/2016	12:50	21/11/2016	14:52	67,070	Gloucester	GC002419
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

44 Add Ad Blue	on sunday top up
85 Body Interior 1	cctv keeps coming on ,clean out switch .

Vehicle Deep Clean	30/11/2016	21:37	01/12/2016	02:30	68,090	Gloucester	GC002499
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	16/12/2016	08:28	16/12/2016	14:18	69,820	Gloucester	GC002623
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

17 Tyres Replace	
18 Wheels Check Torques	
45 Engine Ad Blue	
55 Tail Lift	bridge plate guide bolt broken

56 Comms Equipment	Emg Warning Devices genesis panel CCTV warning on going over bumps
87 Chairs	Body Interior carry chair back, zip is broken
Safety Inspection	
Travel Time	take to dursley

SAFETY INSPECTION	25/01/2017	12:45	26/01/2017	14:46	78,115	Gloucester	GC002946
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

17 Tyres Replace	
18 Wheels Check Torques	
45 Engine Ad Blue	
Safety Inspection	
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Medical Device and Equip Chec	
Tail Lift Inspection	
UB Fire Suppression Service	

BREAKDOWN	16/02/2017	02:30	16/02/2017	02:39	81,369	Gloucester	GC003114
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

34 Lights Bulb Replacement	Replace O/S headlamp bulb H7
----------------------------	------------------------------

Unplanned Repair	04/03/2017	13:48	04/03/2017	13:51	84,362	Gloucester	GC003269
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

34 Lights Bulb Replacement	
56 Comms Equipment	refit
86 Door handle	door hard to open

Vehicle Deep Clean	06/03/2017	08:00	06/03/2017	12:00	84,405	Gloucester	GC003281
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	07/03/2017	11:54	09/03/2017	08:38	84,419	Gloucester	GC003297
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

18 Wheels Check Torques
45 Engine Ad Blue

71 Body Exterior 1 front number plate.
 Safety Inspection
 Travel Time
 WAS Firetrace rework & Service
 93 - D Service
 Service D

Vehicle Deep Clean	15/03/2017	00:11	15/03/2017	00:13	84,419	Gloucester	GC003363
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	28/03/2017	04:06	05/04/2017	11:37	88,651	Gloucester	GC003488
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

52 Electrical Aux Breakdown	aux drive belt aux batt fault Rygor attended
-----------------------------	---

Unplanned Repair	05/04/2017	09:40	05/04/2017	09:44	88,931	Gloucester	GC003562
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

34 Lights	o/s head light.& side light.
-----------	------------------------------

Unplanned Repair	10/04/2017	08:09	11/04/2017	08:21	89,694	Gloucester	GC003595
-------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

86 Doors Rear

Vehicle Deep Clean	17/04/2017	21:45	18/04/2017	02:25	90,368	Gloucester	GC003629
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

BREAKDOWN	06/05/2017	17:13	07/05/2017	19:15	93,083	Gloucester	GC004129
------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

45 Engine 1	AA called ref engine problem. Advice given, no repair necessary
-------------	---

SAFETY INSPECTION	09/05/2017	08:39	12/05/2017	08:38	93,513	Gloucester	GC003794
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

02 Mirrors	replace o/s mirror glass and backing
13 Brakes 1	replace pedal rubber
16 Suspension 1	replace rear a/r/b bushes
17 Tyres Replace	replace all rear and n/s/f inc cleaning hubs and flanges
18 Wheels Check Torques	
44 Add Ad Blue	
45 Engine Oil Top Up	
55 Tail Lift	tighten guard side rails
71 Body Exterior 1	refit rear protection bar and repair rear panel
71 Body Exterior 2	Body Exterior rear door staybar detached
Safety Inspection	
Tail Lift Inspection	

Vehicle Deep Clean	24/05/2017	08:00	25/05/2017	08:15	94,752	Gloucester	GC003965
---------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

87 Stretcher Harness Replaced	
Vehicle Deep Clean	Vehicle Deep Clean

SAFETY INSPECTION	31/05/2017	13:39	06/06/2017	13:05	95,291	Gloucester	GC004016
--------------------------	-------------------	--------------	-------------------	--------------	---------------	-------------------	-----------------

15 Steering 1	movement in upper steering coloum	Awaiting Warranty
18 Wheels Check Torques		
44 Add Ad Blue		
45 Engine Oil Top Up		
85 Body Interior 1	repair glovebox retaining bar in rear of vehicle	
Safety Inspection		
MGS Gas Storage Modifications	MGS Gas Storage Modifications	
Handbrake Cable Replacement	Replace rear handbrake cables NOT DONE . VEHICLE UNDER WARRANTY	
Travel Time		
MOT		

Unplanned Repair	21/06/2017	15:58	23/06/2017	09:52	96,796	Gloucester	GC004230
01 Air Conditioning 1	rear a/c u/s						
Vehicle Deep Clean	17/07/2017	07:00	17/07/2017	11:00	99,331	Gloucester	GC004427
SAFETY INSPECTION	22/07/2017	09:16	27/07/2017	14:30	99,344	Gloucester	GC004488
18 Wheels Check Torques							
45 Engine Ad Blue	top up adblue						
85 Body Interior 1	fire trace re route						
86 Door handle	sliding door outer door handle						
86 Sliding Door	runner bearings replaced						
87 Med Handling Equip Inspect	replace missing pedimate						
Safety Inspection							
Tail Lift Inspection							
Tail Lift Annual Service	Statutory Inspection and Weight Test						
Unplanned Repair	15/08/2017	07:44	15/08/2017	07:45	102,641	Swindon	SD003402
34 Lights Bulb Replacement	o/s headlight bulb replaced by night OO						
Replace Vehicle Fuel Card	23/08/2017	09:39	23/08/2017	09:40	102,641	Gloucester	GC004800
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card						
Vehicle Deep Clean	19/09/2017	07:55	19/09/2017	11:55	107,972	Gloucester	GC005031
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/09/2017	14:58	22/09/2017	11:45	107,985	Gloucester	GC005033
13 Brakes 1							

17 Tyres Replace							
18 Wheels Check Torques							
71 Body Exterior 1	nsr wheel arch damaged					Awaiting Body Repair	
Safety Inspection							
UB Fire Suppression Service							
Gearbox Oil & Filter Change							
92 - C Service							
Service C							
Tail Lift Inspection							
Annual Heater Service	Annual Heater Service						

Breakdown	02/10/2017	05:19	03/10/2017	14:00	108,364	Gloucester	GC005140
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Battery light on						
-----------	------------------	--	--	--	--	--	--

BREAKDOWN	01/10/2017	07:26	02/10/2017	08:50	108,364	Gloucester	GC005141
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Sliding Door	will not open from inside						
89 Seats	saloon side seat .						

Breakdown	30/10/2017	08:23	30/10/2017	11:14	113,630	Gloucester	GC005408
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace							
Breakdown	rear O/S inner?						

Breakdown	11/11/2017	00:06	13/11/2017	08:50	113,700	Gloucester	GC005556
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	staverton side step tail lift not moving properly					Lack of Labour	
-----------	---	--	--	--	--	----------------	--

Breakdown	11/11/2017	00:11	13/11/2017	08:51	113,700	Gloucester	GC005557
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	no washer fluid & not accelerating properly					Lack of Labour	
Travel Time							

SAFETY INSPECTION	13/11/2017	08:51	01/12/2017	09:13	113,700	Gloucester	GC005571
15 Steering 1	movement in upper steering coloum						
18 Wheels Check Torques							
71 Body Exterior 1	nsr wheel arch damaged						
86 Sliding Door	Doors side door not open from inside						
Breakdown	no washer fluid & not accelerating properly						
Road Test							
Safety Inspection							
Travel Time	take to Rygor						
Annual Air Con Service	Annual Air Condition Service						
Vehicle Deep Clean	29/11/2017	21:54	29/11/2017	21:55	113,700	Gloucester	GC005759
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	29/11/2017	21:30	30/11/2017	03:10	113,700	Gloucester	GC005760
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	30/11/2017	08:38	01/12/2017	10:55	113,784	Gloucester	GC005772
01 Air Conditioning 1	drive belt						
SAFETY INSPECTION	06/12/2017	11:51	09/12/2017	14:38	116,292	Gloucester	GC005812
03 Instruments & Sensors 1	eml on code for DPF sensor, Rygor						
18 Wheels Check Torques							
Safety Inspection							
Travel Time	collect from Rygor						
UB Fire Suppression Service							
Tail Lift Inspection							
Breakdown	14/12/2017	04:59	16/12/2017	13:15	116,946	Gloucester	GC005895
55 Tail Lift	Fit used stop switch						
Breakdown	tail lift not working						

Travel Time	take to staverton						
Unplanned Repair	04/01/2018	13:44	04/01/2018	13:48	119,870	Gloucester	GC006085
55 Tail Lift	not lowering intermitantly						
71 Body External Steps							
Vehicle Deep Clean	18/01/2018	07:57	18/01/2018	13:00	122,224	Gloucester	GC006210
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	19/01/2018	11:39	20/01/2018	14:19	122,240	Gloucester	GC006225
13 Handbrake	adjust						
17 Tyres Replace	n/s/f & both n/s/r =3						
18 Wheels Check Torques							
18 Wheels Removal	NUTS						
34 Lights	Lighting System O/S middle scene light lense broken						
43 Exhaust System 1	replace tail pipe.						
55 Tail Lift	no slow close						
Safety Inspection							
Travel Time							
Breakdown	26/01/2018	19:43	27/01/2018	09:52	122,658	Gloucester	GC006315
27 Transmission Automatic	top up with 1.5 ltrs & road test.						
Breakdown	gears slipping - defect 038060 raised by accident						
Travel Time	bring in w/shops.						
Breakdown	28/02/2018	14:47	09/03/2018	07:07	127,426	Gloucester	GC006612
15 Steering 1	fluid leak from pipes						
16 Suspension 1	rear spring buffers						
31 Charging System	shoreline cover broken						
44 Add Ad Blue							

55 Tail Lift	replace defective hydraulic hose	
Breakdown	ENG MGMT LIGHT Diag check . Rygor top up GB oil ONLY 2Lls in GB	Monitoring
Travel Time	take to dealer . warranty repairs	
85 Body Int Alcohol Gel Dispen		
93 - D Service		
Service D		
18 Wheels Check Torques		
Safety Inspection		
Tail Lift Inspection		

Vehicle Deep Clean	13/03/2018	08:00	13/03/2018	11:42	127,859	Gloucester	GC006712
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	29/03/2018	14:43	06/04/2018	14:25	129,228	Gloucester	GC006862
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

17 Tyres Replace	found bolt in tread o/s/r/inner
27 Transmission Automatic	Gearbox gears fault when changing 2 to 3
55 Tail Lift	
71 Body External Steps	
86 Door Lock	key remote inop, o/s/f not opening with blade
Breakdown	ENG MGMT LIGHT Diag check . Rygor top up GB oil ONLY 2Lls in GB
Road Test	aulto box

Vehicle Deep Clean	06/04/2018	00:05	06/04/2018	14:29	129,299	Gloucester	GC006908
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	10/04/2018	08:02	11/04/2018	14:07	129,615	Gloucester	GC006929
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

16 Suspension 1	
18 Wheels Check Torques	
31 Charging System	drive belt
34 Lights	
86 Door Lock	

Safety Inspection Fit Poster Holder	Fit Poster Holder						
Breakdown	14/04/2018	19:03	16/04/2018	15:03	129,940	Gloucester	GC006997
18 Wheels Removal Breakdown Travel Time	n/s/f rim damaged . nsf suspension noise bring in from staverton.						
Breakdown	16/04/2018	13:31	19/04/2018	14:32	129,974	Gloucester	GC007006
Breakdown	knocking noise on LH wheel						
Breakdown	05/05/2018	11:26	08/05/2018	08:56	131,721	Gloucester	GC007231
17 Tyres Replace Breakdown	ATS one tyre tyre pressure						
Vehicle Deep Clean	25/05/2018	08:00	25/05/2018	13:00	133,666	Gloucester	GC007420
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	25/05/2018	13:28	29/05/2018	14:16	133,678	Gloucester	GC007423
02 Windows/Glass 17 Tyres Replace 18 Wheels Check Torques 45 Engine Ad Blue Safety Inspection Handbrake Cable Replacement Tail Lift Annual Service UB Fire Suppression Service Wheel Hub Flanges Replaceme Tail Lift Inspection	O/S WINDOW switch. o/s/f . Replace rear handbrake cables Statutory Inspection and Weight Test						

SAFETY INSPECTION	26/06/2018	12:55	27/06/2018	14:45	138,150	Gloucester	GC007684
02 Cab Assembly 1			replace defective handtorch				
02 Windscreen Wipers			replace front blades				
03 Instruments & Sensors 1			reset dash display with texa				
13 Handbrake			Adjust handbrake				
18 Wheels Check Torques							
44 Add Ad Blue							
45 Engine Oil Top Up							
56 Comms Equipment			repair internal comms mic,s				
71 Body External Steps			Replace torn side step mudflap				
85 Body Interior 1			replace broken straps in scoop locker				
86 Sliding Door			repair top door catch and replace cover				
87a - Medical Equipment Repaimobi med check. both batteries ok							
Safety Inspection							
Travel Time			collect from stroud station				
MOT							
Vehicle Deep Clean	29/06/2018	08:00	29/06/2018	13:00	138,168	Gloucester	GC007712
Vehicle Deep Clean			Vehicle Deep Clean				
Unplanned Repair	11/07/2018	14:31	11/07/2018	14:33	139,617	Gloucester	GC007817
54 Warn Dev/System			cctv at Cinderford				
Unplanned Repair	20/07/2018	15:15	25/07/2018	12:32	139,871	Gloucester	GC007914
31 Charging System							
Travel Time			collect from dealer and return to station				
Breakdown	30/07/2018	14:41	01/08/2018	15:51	139,900	Gloucester	GC007989
02 Windscreen			refit trim around screen				
56 Comms Equipment			Handheld radio battery charger fault . part broken				
Breakdown			tail lift not operating on handheld control. check wiring replace tilt sensors				
Travel Time			take vehicle to station				

Unplanned Repair	15/08/2018	10:45	15/08/2018	10:52	139,900	Gloucester	GC008126
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	condenser
-----------------------	-----------

Breakdown	05/09/2018	18:21	27/09/2018	15:23	147,650	Gloucester	GC008287
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	n/s switch
03 Instruments & Sensors 1	reset dash display with teta
13 Brakes 2	replace rear pads and discs
13 Handbrake	replace rear shoes and necessary parts
15 Steering 1	fluid leak from PAS pipework
17 Tyres Replace	
18 Wheels Balance & Alignment	
44 Add Ad Blue	
71 Body Exterior 1	n/s lower corner cap and reflector
86 Sliding Door	inner door panel
87a - Medical Equipment Repair	mobi med check.. Batteries ok
89 Seats	replace damaged arm rest n/s saloon seat
Breakdown	deep tear to the rear driver side
18 Wheels Check Torques	
Safety Inspection	
92 - C Service	
Service C	
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Tail Lift Inspection	

Awaiting Body Repair

ACCIDENT	27/09/2018	15:24	02/10/2018	08:01	147,650	Gloucester	GC008485
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
71 Body Exterior Acc Repair	o/s panel
86 Sliding Door	adjust
Safety Inspection	

Vehicle Deep Clean	02/10/2018	10:16	02/10/2018	10:17	147,680	Gloucester	GC008520
Breakdown Vehicle Deep Clean	deep tear to the rear driver side Vehicle Deep Clean						
Vehicle Deep Clean	02/10/2018	10:18	02/10/2018	10:24	147,680	Gloucester	GC008521
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	19/10/2018	12:55	22/10/2018	08:01	149,717	Gloucester	GC008708
Breakdown	side step not deploying						
BREAKDOWN	28/10/2018	08:31	30/10/2018	08:57	150,535	Gloucester	GC008802
45 Engine Ad Blue 71 Body External Steps Travel Time	top up . will not come out . staverton to w/s.						
Vehicle Deep Clean	06/11/2018	08:00	08/11/2018	14:37	151,494	Gloucester	GC008900
02 Windscreen 17 Tyres Replace 34 Lights Bulb Replacement 44 Add Ad Blue 45 Engine Oil Top Up 55 Tail Lift 87a - Medical Equipment Repair Vehicle Deep Clean Fit 3rd Helmet Restraint Sealing of stretcher clamp 18 Wheels Check Torques Safety Inspection UB Fire Suppression Service Tail Lift Inspection	front washers inop n/s rear outer front side lamps replace hydraulic hose and repair to ram mobili med check Vehicle Deep Clean Fit 3rd Helmet Restraint in Cab Sealing of stretcher clamp						

Breakdown	11/11/2018	18:07	12/11/2018	10:59	151,965	Gloucester	GC008951
Breakdown Travel Time	824 - sidestep will notg retract						
BREAKDOWN	25/11/2018	10:53	25/11/2018	11:08	153,685	Gloucester	GC009086
45 Engine Ad Blue	tank empty .						
Breakdown	13/12/2018	14:27	18/12/2018	09:23	153,685	Gloucester	GC009245
03 Instruments & Sensors 1	key battery						
13 Brakes 1	replace front brakes						
17 Tyres	replace tyres and 1 valve extension						
18 Wheels	replace incorrect road wheel						
24 Driveshaft 1	repalce short prop						
44 Add Ad Blue	top up						
44 Fuel System 1	N/S/F replace injector seal						
45 Engine Oil Top Up							
86 Doors	replace O/S/F door seal						
86 Doors Rear	replace lock barrel						
Breakdown	Fumes in cab and back						
Travel Time	bring into w/s .						
18 Wheels Check Torques							
Safety Inspection							
Tail Lift Inspection							
Vehicle Deep Clean	18/12/2018	21:00	19/12/2018	02:30	154,124	Gloucester	GC009294
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	22/12/2018	08:34	24/12/2018	10:36	155,346	Gloucester	GC009340
Breakdown	Side step not delpoying						

Breakdown	01/01/2019	06:24	01/01/2019	13:56	155,346	Gloucester	GC009388
Breakdown Travel Time	SIDE STEP NOT DEPLOYING. straighten frame and lube bring into workshop from station						
Breakdown	01/01/2019	15:17	02/01/2019	14:00	156,315	Gloucester	GC009391
86 Sliding Door Breakdown	repair top catch side step wont come out. repair wiring in door						
Unplanned Repair	08/01/2019	11:27	08/01/2019	11:31	156,884	Gloucester	GC009455
45 Engine Ad Blue							
Breakdown	19/01/2019	22:34	20/01/2019	13:01	159,378	Gloucester	GC009554
01 Heating 1 33 Ignition System 45 Engine Ad Blue Breakdown Travel Time	rear heater inop key fob battery no heating in back						
Breakdown	23/01/2019	11:40	23/01/2019	14:35	159,837	Gloucester	GC009592
01 Heating 1 Breakdown	test & replace control box. cold air instead of hot at the back						
SAFETY INSPECTION	29/01/2019	08:01	30/01/2019	08:28	160,350	Gloucester	GC009649
18 Wheels Check Torques 45 Engine Ad Blue 56 Comms Equipment 86 Doors Safety Inspection	Other HH battery charge not charging?wiring Doors N/S door not locking						

Travel Time bring in from staverton & take back.
Gearbox Oil & Filter Change

Vehicle Deep Clean **30/01/2019** **09:00** **30/01/2019** **15:05** **160,364** **Gloucester** **GC009674**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **24/02/2019** **10:37** **24/02/2019** **15:55** **166,667** **Gloucester** **GC009895**

17 Tyres Replace n/s/r/inner. ATS unable to do job.
Breakdown flat rear left outer

Vehicle Deep Clean **12/03/2019** **08:00** **12/03/2019** **12:15** **166,667** **Gloucester** **GC010024**

Vehicle Deep Clean Vehicle Deep Clean

SAFETY INSPECTION **12/03/2019** **15:22** **14/03/2019** **11:18** **166,667** **Gloucester** **GC010034**

01 Air Conditioning 1 drive belt & pulley.
02 Windscreen Wipers
16 Suspension 1 rear shackles & bushies
18 Wheels Check Torques
33 Ignition System replace key fob battery
44 Fuel System 1 replace fuel solo device
89 Seats saloon seat repair
Safety Inspection
93 - D Service
Service D
Handbrake Cable Replacement Replace rear handbrake cables

Breakdown **17/03/2019** **02:59** **17/03/2019** **07:52** **166,668** **Gloucester** **GC010077**

Breakdown central locking not working Monitoring

Breakdown **18/03/2019** **20:33** **20/03/2019** **08:04** **167,000** **Gloucester** **GC010080**

17 Tyres Replace

Breakdown	flat tyre						
Unplanned Repair	30/03/2019	13:17	30/03/2019	13:27	167,138	Gloucester	GC010169
86 Sliding Door Breakdown	refit catch and replace broken cover central locking not working						
Unplanned Repair	12/04/2019	12:03	12/04/2019	12:05	169,337	Gloucester	GC010297
44 Add Ad Blue	top up						
Unplanned Repair	15/04/2019	16:11	15/04/2019	16:15	169,870	Gloucester	GC010312
17 Tyres Replace	replace o/ front and o/s rear outer tyres						
BREAKDOWN	01/05/2019	12:37	01/05/2019	12:42	172,222	Gloucester	GC010430
17 Tyres Replace 18 Wheels Check Torques	o/s/f large screw in tread.						
Vehicle Deep Clean	09/05/2019	21:40	14/05/2019	14:59	173,820	Gloucester	GC010516
03 Instruments & Sensors 1 13 Handbrake 16 Suspension 1 17 Tyres Replace 34 Lights 44 Add Ad Blue 85 Body Interior Roof Vehicle Deep Clean 18 Wheels Check Torques Safety Inspection Tail Lift 12M Service & Weight	reset service light adjust rear antiroll bar bushies. n/s/f n/s/f marker air vent broken. Vehicle Deep Clean Tail Lift 12M Service & Weight						

Tail Lift Inspection
 UB Fire Supp 12mts Service Service of fire supression system

Breakdown	26/05/2019	10:16	27/05/2019	12:23	175,322	Gloucester	GC010660
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	tail lift not working at all. Trace and repair fault						
Travel Time							

Breakdown	28/05/2019	21:44	30/05/2019	09:39	175,700	Gloucester	GC010672
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	back door latch malfunctioning					Lack of Labour	
-----------	--------------------------------	--	--	--	--	----------------	--

Breakdown	29/05/2019	20:15	31/05/2019	13:23	175,700	Gloucester	GC010682
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	rear door stay bar broken					Lack of Labour	
-----------	---------------------------	--	--	--	--	----------------	--

Unplanned Repair	01/06/2019	09:16	01/06/2019	09:19	175,776	Gloucester	GC010698
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Doors Rear	door stay broken . fit reclaimed parts						
Travel Time							

SAFETY INSPECTION	26/06/2019	07:25	27/06/2019	16:00	179,581	Gloucester	GC010916
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	rear a/c fan noisy						
13 Brakes 2	replace pads and discs on rear						
13 Handbrake	adjust as required						
15 Steering 1	o/s track rod end						
16 Suspension 1	replace rear spring buffers						
17 Tyres Replace	o/s rear inner						
18 Wheels Check Torques							
34 Emergency Light System	genesis panel on dash button fault						
44 Add Ad Blue							
45 Engine Oil Top Up							
71 Body Exterior 1	o/s/r corner damage						
85 Body Interior 1	replace missing equipment strap						
89 Seats	cab seats covers worn and frayed					Monitoring	
Breakdown	rear door stay bar broken						
Install Saloon CCTV Camera	suspect fault with cctv recording system			Awaiting repair		Monitoring	
Safety Inspection							

MOT

Vehicle Deep Clean	27/06/2019	23:00	28/06/2019	04:40	179,594	Gloucester	GC010958
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	18/07/2019	07:46	22/07/2019	08:04	183,637	Gloucester	GC011149
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

44 Add Ad Blue	
55 Tail Lift	Adjust grab rail sliders
71 Body Exterior 1	Secure mudflap
71 Body Exterior 2	o/s/r cctv camera dome lens damaged
89 Seats	o/s/f seat base torn & tight cab seat armrests
99 Diagnostic Test	Reset service light
Travel Time	
Vehicle Deep Clean	Vehicle Deep Clean
18 Wheels Check Torques	
Safety Inspection	
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service
Brakes Replace Brake Fluid	
Tail Lift Inspection	
Engine Change Oil & Filter	

Breakdown	23/07/2019	21:20	05/08/2019	08:26	183,962	Gloucester	GC011198
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

41 Turbo	
Breakdown	824 - limp mode Turbo broken apart
Travel Time	

BREAKDOWN	08/08/2019	13:20	09/08/2019	13:32	184,261	Gloucester	GC011319
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

01 Air Conditioning 1	pollen /filter
02 Windscreen Wipers	washer bottle cap
34 Lights Bulb Replacement	
44 Fuel System 1	No 5 injector leaking (smoke)
45 Engine 1	n/s inter cooler hose.

Breakdown Road Test	recovery						
Breakdown	12/08/2019	09:49	16/08/2019	14:53	184,261	Gloucester	GC011343
Breakdown	Smoke from the engine and warning lights						
Vehicle Deep Clean	28/08/2019	21:34	29/08/2019	04:10	186,127	Gloucester	GC011501
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	30/08/2019	10:48	05/09/2019	11:58	186,138	Gloucester	GC011516
18 Wheels Check Torques							
44 Add Ad Blue							
45 Engine Oil Top Up							
86 Doors Rear	adjust cables						
89 Seatbelts	n/s belt twisted						
89 Seats	cab seats covers worn and frayed						
Install Saloon CCTV Camera	suspect fault with cctv recording system			Awaiting repair			
Medical Devices Check	mobimed battery						
Safety Inspection							
Breakdown	16/09/2019	19:58	18/09/2019	12:19	187,439	Gloucester	GC011638
45 Engine 1	fault with oxygen ensor bank 1 sensor 1						
71 Body Exterior 1	replace bulk head crommet						
99 Diagnostic Test	check for EML						
Breakdown	AMBER EML						
Road Test							
Unplanned Repair	29/09/2019	08:09	30/09/2019	16:00	188,573	Gloucester	GC011724
18 Wheels Balance & Alignment							
Travel Time							

Unplanned Repair	26/10/2019	11:25	26/10/2019	11:29	192,471	Gloucester	GC011958
34 Lights	o/s/r lower indicator not working						
Travel Time	go to station to carryout repairs						
SAFETY INSPECTION	29/10/2019	07:40	30/10/2019	14:53	192,778	Gloucester	GC011972
02 Cab Assembly 1	repair cupboard btween seats in cab and replace strut						
02 Windscreen Wipers							
13 Brakes 1	front pads and discs next inspection						Monitoring
16 Suspension 1	rear spring buffers						
17 Tyres Replace	4xrear tyres						
18 Wheels Check Torques							
44 Add Ad Blue							
45 Engine Oil Top Up							
85 Body Interior 1	CCTV check						
85 Body Interior 3	rear genisis panel fault . panel replaced						
86 Sliding Door	replace centre and top rollers						
87a - Medical Equipment Repair	mobi med check						
89 Seats	front seat covers worn						Monitoring
Check Winter Pack							
Safety Inspection							
Travel Time							
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Vehicle Deep Clean	30/10/2019	21:30	31/10/2019	04:56	192,788	Gloucester	GC011991
Travel Time	Take vehicle to Coleford						
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	05/11/2019	12:58	05/11/2019	13:00	193,510	Gloucester	GC012052
34 Lights	o/s rear stop lamp inop and o/s rear indicator						

Breakdown	06/11/2019	23:38	07/11/2019	09:16	193,698	Gloucester	GC012063
02 Mirrors	o/s asb .						
33 Ignition System	key battery.						
Breakdown	O/S mirror removed						
Travel Time	BRING IN FROM STAVERTON.						
SAFETY INSPECTION	22/11/2019	12:23	26/11/2019	10:51	195,904	Gloucester	GC012193
01 Heating 1	Other Windscreen de-mister failure						
13 Brakes 1	front pads next inspection						
18 Wheels Check Torques							
86 Door Seals	rear						
89 Seats	front seat covers worn						
Safety Inspection							
Travel Time	take to staverton deep clean.						
Vehicle Deep Clean	26/11/2019	21:30	27/11/2019	00:10	195,927	Gloucester	GC012233
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	18/12/2019	11:48	19/12/2019	07:10	198,550	Gloucester	GC012459
17 Tyres Replace							
Breakdown	rear drivers outer tyre flat						
Unplanned Repair	26/12/2019	13:26	26/12/2019	13:29	199,436	Gloucester	GC012512
02 Cab Assembly 1	replace missing dash trim						
44 Add Ad Blue							
Breakdown	05/01/2020	17:51	09/01/2020	16:00	200,933	Gloucester	GC012580

34 Lights Bulb Replacement
 45 Engine Ad Blue
 86 Sliding Door
 Breakdown
 Axle Oil Change
 18 Wheels Check Torques
 Safety Inspection
 Pollen Filter Change
 Fuel Filter Change
 Air Filter Change
 Tail Lift Inspection

CARRY OUT REPAIR & ADJUST
 side door off rail at top
 Axle Oil Change

 Pollen Filter Change
 Change Fuel Filter
 Air Filter Change

Vehicle Deep Clean **06/01/2020** **08:00** **06/01/2020** **12:14** **200,933** **Gloucester** **GC012592**

Vehicle Deep Clean Vehicle Deep Clean

Breakdown **10/01/2020** **04:55** **31/01/2020** **16:00** **200,933** **Gloucester** **GC012632**

002 Major Unit Replace Eng
 41 Air Intake
 99 Diagnostic Test
 Breakdown
 Travel Time

replace been throw flood water.
 low no compression !
 Engine cut out
 recovered to rygor.

Breakdown **08/02/2020** **06:50** **11/02/2020** **09:36** **200,933** **Gloucester** **GC012912**

Breakdown crew reported grinding sound from engine

BREAKDOWN **10/02/2020** **12:44** **15/02/2020** **14:00** **201,859** **Gloucester** **GC012934**

01 Air Conditioning 1 compressor noise
 13 Handbrake adjust
 17 Tyres Replace o/s/f tyre
 34 Lights saloon lights not working on bright. tighten connection on genysys panel
 34 Lights Bulb Replacement n/s sidelight bulb
 42 Coolant System adjust coolant level (too full)
 44 Add Ad Blue
 45 Engine 1 NEW ENGINE fitted last week noise from it take to rygor.
 85 Body Interior 1 repair cabinet

86 Door Lock	replace catch cover
Travel Time	take to rygor.
18 Wheels Check Torques	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
Vehicle Deep Clean	Vehicle Deep Clean

Breakdown	02/03/2020	15:33	03/03/2020	14:01	203,963	Gloucester	GC013170
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	side step noisy
Breakdown	Fire supressant warning
Travel Time	

Fire suppression Service	27/03/2020	14:41	27/03/2020	14:47	203,963	Gloucester	GC013369
---------------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

16 Suspension 1	check for noise heard during reversing . no fault found
UB Fire Suppression Service	PARTS ONLY

SAFETY INSPECTION	02/04/2020	10:48	03/04/2020	16:29	205,146	Gloucester	GC013421
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Handbrake	adjust as required
18 Wheels	n/s/f whheel nuts and studs damaged by impact replaced flange and nuts
18 Wheels Check Torques	retoque all wheels not all removed
44 Add Ad Blue	
45 Engine Oil Top Up	
71 Body External Steps	replace safety bar and mudflap
85 Body Interior 1	CCTV check
87 - Stretchers/Chairs/Boards	Med Equip & Devices Stretcher Battery not charging.(Already Repaired)
87a - Medical Equipment Repaimobi med check	
Safety Inspection	
Tail Lift Inspection	refit rear cover on tail lift frame
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service... Replace system

Vehicle Deep Clean	01/04/2020	10:14	03/04/2020	10:17	205,146	Gloucester	GC013440
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	28/04/2020	11:46	01/05/2020	13:02	210,659	Gloucester	GC013739
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Ass Fire Extinguisher	replace						
11 Axle Front	clean flanges						
11 Axle Rear	clean flanges - diff has slight whine					Monitoring	
16 Suspension 1	replace front shocks						
17 Tyres Replace	X6						
18 Wheels	clean						
18 Wheels Check Torques							
34 Emergency Lights	grill light fault						
34 Lights	interior light not working - replace fuse						
43 Exhaust System 1	replace tail pipe						
55 Tail Lift	replace hose						
71 Body External Steps	Body Exterior Side step not depling fully - clean and lube.						
85 Body Interior 1	diagnose faulty extractor...					Monitoring	
Road Test	diff whining						
Safety Inspection							
Travel Time							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
UB Fire Supp 12mts Service	Service of fire supression system. reroute piping						
Vehicle Deep Clean	Vehicle Deep Clean						
Engine Change Oil & Filter							

Breakdown	04/06/2020	16:49	08/06/2020	10:27	214,430	Gloucester	GC014038
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	fire suppression system alarming					Awaiting Parts	
-----------	----------------------------------	--	--	--	--	----------------	--

Vehicle Deep Clean	12/06/2020	00:01	12/06/2020	04:23	214,732	Gloucester	GC014097
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	12/06/2020	08:35	15/07/2020	08:33	214,761	Gloucester	GC014098
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

11 Axle Rear	diff has slight whine					Monitoring	
13 Brake Pads	rear						
15 Steering 1	replace power steering hose.						
18 Wheels Check Torques							

45 Engine Ad Blue	
71 Body Exterior Acc Repair	needs n/s/r wheel arch. & sill etc.
71 Body External Steps	Body Exterior side step Grinding
85 Body Interior 1	diagnose faulty extractor...
86 Doors Rear	fit o/s door mod.
Breakdown	fire suppression system alarming
Safety Inspection	
Travel Time	bring in from staverton.
UB Fire Supp Replace	Replacement of UB Fire System (bottle only)
MOT	
Tail Lift Inspection	
Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
Annual Air Con Service	Annual Air Condition Service
Annual Heater Service	Annual Heater Service

Vehicle Deep Clean	31/07/2020	07:30	05/08/2020	08:29	216,582	Gloucester	GC014520
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Cab Assembly 1	replace tool box cover.
02 Windscreen Wipers	replace.
24 Driveshaft 1	replace front long prop.remove rear prop & replace greese nippels.
71 Body External Steps	side step stuck out
Vehicle Deep Clean	Vehicle Deep Clean
18 Wheels Check Torques	
Safety Inspection	

Unplanned Repair	11/08/2020	15:38	12/08/2020	08:02	217,565	Gloucester	GC014600
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

31 Battery Comms	replace
------------------	---------

Unplanned Repair	31/08/2020	10:01	31/08/2020	10:09	220,017	Gloucester	GC014744
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

85 Body Interior 1	Swap CCTV hard drive
--------------------	----------------------

Vehicle Deep Clean	15/09/2020	07:30	15/09/2020	11:41	221,983	Gloucester	GC014888
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/09/2020	13:01	18/09/2020	15:46	221,998	Gloucester	GC014899
11 Axle Rear	diff has slight whine					Monitoring	
18 Wheels Check Torques							
56 Comms Equipment	Comms Power Check TFX shutting down					Monitoring	
86 Sliding Door	Remove brackets, weld, make strengthening plate, refit						
Safety Inspection							
UB Fire Suppression Discharge	Under Bonnet Fire Suppression 5 Year Discharge Test						
Tail Lift Inspection							
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Breakdown	22/10/2020	07:42	22/10/2020	14:24	225,287	Gloucester	GC015277
Breakdown	Flat battery had to use energy button						
Breakdown	03/11/2020	10:34	04/11/2020	07:19	226,752	Gloucester	GC015382
Breakdown	Crew think Battery is going dead					Lack of Labour	
Vehicle Deep Clean	04/11/2020	07:40	04/11/2020	13:19	226,779	Gloucester	GC015392
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	04/11/2020	14:52	08/11/2020	08:31	226,795	Gloucester	GC015403
13 Discs	fronts						
17 Tyres	fit reclaimed tyre & balance'						
17 Tyres Replace	tyres.						
17 Tyres Tracking	adjust.						
18 Wheels Check Torques							
18 Wheels Removal	Remove, refit and cleaned O/S rear wheels						
31 Battery Chassis	replaced Chassis battery						
31 Charging System Battery	Battery/Charging Sys non start used emerg restart button						
34 Lights Bulb Replacement	replace both front day time running bulbs						
52 Electrical Aux	Replaced drivers window switch						
56 Comms Equipment	Comms Power Check TFX shutting down						
71 Body External Steps	Body Exterior side step stuck out						

85 Body Interior 1
 85 Body Interior 2
 Breakdown
 Safety Inspection

Replace long bio strap
 Replace passenger front seat base
 Crew think Battery is going dead

Breakdown	18/11/2020	02:58	19/11/2020	08:09	228,095	Gloucester	GC015526
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Key fob battery dead					Lack of Labour	
-----------	----------------------	--	--	--	--	----------------	--

Breakdown	22/11/2020	20:46	24/11/2020	08:23	228,609	Gloucester	GC015559
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	MDT not powering on					Monitoring	
-----------	---------------------	--	--	--	--	------------	--

Breakdown	25/11/2020	14:48	26/11/2020	10:45	229,081	Gloucester	GC015598
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	stretcher box is not charging					Lack of Labour	
-----------	-------------------------------	--	--	--	--	----------------	--

Breakdown	30/11/2020	20:28	02/12/2020	08:31	229,755	Gloucester	GC015642
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Terrafox Will turn on but will not stay on. Batt Check Req					Lack of Labour	
-----------	--	--	--	--	--	----------------	--

Unplanned Repair	02/12/2020	16:04	02/12/2020	16:11	229,925	Gloucester	GC015672
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

87a - Medical Equipment Repair
 Check EPCR & diag block . Replace docking cradle . Halls replaced

Vehicle Deep Clean	10/12/2020	03:30	10/12/2020	03:36	230,732	Gloucester	GC015760
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
--------------------	--------------------	--	--	--	--	--	--

SAFETY INSPECTION	10/12/2020	08:33	12/12/2020	14:37	230,742	Gloucester	GC015762
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques 31 Charging System 45 Engine Oil Top Up 71 Body External Steps	Aux belt squeal other side step not retracting/sticking when in use
---	--

85 Body Interior 1	lower cupboard back broken
85 Body Interior 2	fit new window switch
Breakdown	Terrafix Will turn on but will not stay on. Batt Check Req
Road Test	
Safety Inspection	
Travel Time	take vehicle back to stav

Breakdown	15/12/2020	12:02	18/12/2020	11:28	231,126	Gloucester	GC015811
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

43 Exhaust System 1	replace DPF & CAT
86 Door Lock	N/S front door lock faulty operation . Fit lock assembly
Breakdown	Orange EML
Travel Time	C7D to dealer and collect parts

Breakdown	23/12/2020	16:55	30/12/2020	08:47	231,803	Gloucester	GC015913
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

99 Diagnostic Test	rygor needs knock sensor ,out of stock.
Breakdown	Adblue system malfunction
Travel Time	

Breakdown	09/01/2021	09:36	10/01/2021	14:17	233,253	Gloucester	GC016041
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	Add blue (knock sensor) issue have to take to rygors as under warranty 23/12
99 Diagnostic Test	Vehicle in operational use . to be repaired
Breakdown	Orange Adblue malfunction

Unplanned Repair	11/01/2021	07:49	11/01/2021	17:00	233,253	Gloucester	GC016055
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

44 Add Ad Blue	
Travel Time	

Vehicle Deep Clean	03/02/2021	09:37	03/02/2021	13:05	236,737	Gloucester	GC016259
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	03/02/2021	12:59	07/02/2021	12:12	236,752	Gloucester	GC016264
01 Air Conditioning 1	front drive belt split and tensioner leaking						
02 Cab Assembly 1	replace bulbs interior lamps						
02 Windows/Glass	fit window switches						
16 Suspension 1	rear spring buffers						
18 Wheels Check Torques							
41 Air Intake	seals leaking and damper split						
44 Add Ad Blue							
85 Body Interior 1	CCTV check						
85 Body Interior 2	replace catch covers on doors						
87 Chairs	110940988 Stryker chair . (not on system)						
87a - Medical Equipment Repaimobi med check							
Safety Inspection							
Tail Lift Inspection							
Auto G/box Oil & Filter Change	Auto G/box Oil & Filter Change						
Replace Handbrake Cables	Replace Handbrake Cables						
Engine Change Oil & Filter							

Vehicle Deep Clean	18/02/2021	13:57	18/02/2021	13:58	237,025	Gloucester	GC016410
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/02/2021	13:58	25/02/2021	14:27	237,040	Gloucester	GC016411
01 Heating 1	exhaust split						
11 Axle Front	Clean flanges						
15 Steering 1	replace leaking steering rack						
17 Tyres Tracking	Check and adjust tracking						
18 Wheels	Clean mating surfaces, clean and respray silver (both front wheels)						
18 Wheels Check Torques							
44 Add Ad Blue							
44 Fuel System 1	repair damaged fuel filler neck						
45 Engine 1	replace engine/gearbox mounts						
45 Engine Oil Top Up							
71 Body Exterior 3	Large rear mudflap insecure, fabricate brackets to secure mudflap & fit						
85 Body Interior 1	boost pipe improperly fitted						
85 Body Interior 2	paper folders insecure, cupboard hinge broken, white board deteriorated.						
85 Body Interior 3	Radio & Comm System Terrafix screen faulty						

86 Door Lock	Locker door lock barrel broken, strip, remove, clean & replace.
86 Sliding Door	sliding door bearings very rough, remove and replace.
87 Boards	Scoop not on system serial number 041163
87 Chairs	Chair not on system serial number CC00592
Medical Devices Check	Mobi Med check
Road Test	
Safety Inspection	
Tail Lift Inspection	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service

Unplanned Repair	17/03/2021	14:40	18/03/2021	11:41	240,090	Gloucester	GC016667
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

03 Instruments & Sensors 1	reset dash display with diag equipment
03 Instruments & Sensors 2	replace key fob batteries ands reset system
13 Brake Test	carryout rolling road brake test . printout done
13 Brakes 1	grinding noise. Check brakes O/K. Roadtest vehicle
31 Charging System	Battery/Charging Sys Shoreline pins bent. not charging/not ejecting. straighen

Unplanned Repair	23/03/2021	13:48	23/03/2021	13:50	240,858	Gloucester	GC016731
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

71 Body External Steps	Body Exterior Side step not deploying repaired frame . (damaged)
------------------------	--

Unplanned Repair	28/03/2021	15:45	28/03/2021	15:48	241,268	Gloucester	GC016780
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

03 Instruments & Sensors 1	replace keyfob batteries and rest dash with diag wquipt
87 Stretcher	repair stretcher clamps and replace stretcher with correct type

Vehicle Deep Clean	22/04/2021	07:01	22/04/2021	07:28	244,532	Gloucester	GC017048
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	22/04/2021	07:28	27/04/2021	10:42	244,547	Gloucester	GC017049
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Windows/Glass	n/s/f window switch broken
11 Axle Front	clean flanges

11 Axle Rear	clean flanges
13 Brake Pads	replace rear pads & discs
13 Brake Test	
13 Brakes 1	Clean calliper carriers
13 Brakes 2	rear slide pins seized, clean & replace slide pins both sides.
18 Wheels	clean & respray
18 Wheels Check Torques	
44 Add Ad Blue	
45 Engine Oil Top Up	
85 Body Interior 1	repair lose hinges on cupboard doors
85 Body Interior 2	CCTV check
85 Body Interior Roof	Other Extractor fan not working
86 Door Lock	key fob battery
86 Doors	rear door lock seized
87 - Stretchers/Chairs/Boards	Chair CC004592
87 Med Handling Equip Inspect	scoop 041163
Medical Devices Check	mobi med check
Road Test	
Safety Inspection	
Travel Time	
UB Fire Supp 12mts Service	Service of fire supression system
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight

Unplanned Repair	01/05/2021	09:34	01/05/2021	09:38	245,136	Gloucester	GC017133
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Sliding Door	retighten sliding door upper lock as cover broken and loose
-----------------	---

ACCIDENT	26/05/2021	18:05	26/05/2021	18:09	248,952	Gloucester	GC017388
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

02 Mirrors	Repair and replace o/s door mirror . (Accident Damage)
------------	--

Unplanned Repair	10/06/2021	11:47	10/06/2021	11:55	251,462	Gloucester	GC017531
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

86 Door Lock	central locking not working, check operation, requires new key battery.
--------------	---

Vehicle Deep Clean	23/06/2021	07:50	23/06/2021	07:52	253,300	Gloucester	GC017639
Vehicle Deep Clean	Vehicle Deep Clean						
Vehicle Deep Clean	23/06/2021	07:52	23/06/2021	11:42	253,312	Gloucester	GC017640
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	23/06/2021	14:25	23/06/2021	14:26	253,127	Gloucester	GC017647
18 Wheels Check Torques Safety Inspection							
SAFETY INSPECTION	23/06/2021	14:26	26/06/2021	15:43	253,325	Gloucester	GC017648
13 Brakes 1	Replace pedal rubber						
17 Tyres Replace	replace 2 tyres						
18 Wheels Check Torques							
34 Lights Bulb Replacement	front DRL and side lamp bulbs						
44 Add Ad Blue							
45 Engine Oil Top Up							
55 Tail Lift	tilt ram slow to deploy						
85 Body Interior 1	cctv check						
86 Sliding Door	Doors side door fixing loose Old defect . Repaired						
87a - Medical Equipment Repair	mobility med check						
89 Seats	o/s seat base						
Safety Inspection							
Travel Time							
Tail Lift Inspection	marker lams and battery and buffer						
Fuel Filter Change	Change Fuel Filter						
Air Filter Change	Air Filter Change						
Pollen Filter Change	Pollen Filter Change						
MOT							
Breakdown	18/08/2021	00:05	18/08/2021	07:57	261,834	Gloucester	GC018148
17 Tyres Replace							
Breakdown	Front near side tyre worn edge no tread						

Monitoring

ACCIDENT	02/09/2021	12:41	03/09/2021	12:07	263,867	Gloucester	GC018287
11 Axle Front	clean flange						
11 Axle Rear	clean flanges						
15 Steering 1	pulls to left. worn tyre X5						
18 Wheels	clean/paint rear outer wheels						
18 Wheels Balance & Alignment							
18 Wheels Check Torques							
34 Lights Bulb Replacement	DLR Bulb						
45 Engine 1	oil leak					Lack of Labour	
71 Body External Steps	straighten/weld/lube step						
Road Test							

SAFETY INSPECTION	20/09/2021	07:50	20/09/2021	07:51	265,556	Gloucester	GC018444
18 Wheels Check Torques							
Safety Inspection							

SAFETY INSPECTION	20/09/2021	07:51	24/09/2021	11:30	265,578	Gloucester	GC018445
13 Brakes 1	TELMA needs replacing soon. TELMAS BEING OVERHAULED.					Awaiting Parts	
17 Tyres Replace	replace o/s rear inner as punctured						
18 Wheels Check Torques							
45 Engine 1	oil leak ,GOING TO RYGOR.						
55 Tail Lift	replace both merc switches						
86 Sliding Door	door seal broken, replaced						
Check Winter Pack							
Pollen Filter Change	Pollen Filter Change						
Safety Inspection							
Travel Time	SORT OUT STAVERTON & BRING IN TO W/S.						
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Brake Fluid Change	Brake Fluid Change						
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service						
Engine Change Oil & Filter							
Tail Lift Inspection							

Vehicle Deep Clean	21/09/2021	13:45	21/09/2021	13:47	265,560	Gloucester	GC018462
Vehicle Deep Clean	Vehicle Deep Clean						

Vehicle Deep Clean	21/09/2021	14:44	21/09/2021	22:09	265,578	Gloucester	GC018463
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	08/10/2021	09:08	08/10/2021	09:09	267,454	Gloucester	GC018643
54 Warn Dev/System Check Winter Pack	recover CCTV						
SAFETY INSPECTION	11/11/2021	14:17	13/11/2021	07:49	271,845	Gloucester	GC018920
13 Brake Pads 13 Brakes 1 15 Steering 1 16 Suspension 1 17 Tyres Tracking 18 Wheels Check Torques 18 Wheels Removal 24 Driveshaft 1 42 Coolant System 45 Engine Ad Blue Safety Inspection Tail Lift Inspection	rear TELMA needs replacing soon. TELMAS BEING OVERHAULED. noise n/s/f replace bottom arms etc. adjust. clean wheels and flanges replace TELMA & LONG PROP. replace tank & cap						
Vehicle Deep Clean	15/11/2021	07:51	15/11/2021	13:17	271,869	Gloucester	GC018942
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	06/12/2021	17:52	07/12/2021	10:35	273,572	Gloucester	GC019131
86 Sliding Door Breakdown	TOP CATCH BRACKET FOULTY. side door is coming off its hinge						

Vehicle Deep Clean	17/12/2021	10:22	17/12/2021	14:44	274,709	Gloucester	GC019210
--------------------	------------	-------	------------	-------	---------	------------	----------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	13/01/2022	08:13	14/01/2022	07:12	278,105	Gloucester	GC019392
-------------------	------------	-------	------------	-------	---------	------------	----------

02 Windscreen Wipers	
18 Wheels Check Torques	
31 Battery Chassis	Battery failed drop test, replace battery.
34 Lights	O/S/R sidemarker inop
45 Engine 1	Turbo seals leaking & turbo charge pipe damaged
85 Body Interior 1	Catch cover insecure 240v plug cover missing
Camera Installation	N/S/F microdome smashed
Road Test	
Safety Inspection	

Vehicle Deep Clean	08/02/2022	08:21	08/02/2022	11:20	279,951	Gloucester	GC019593
--------------------	------------	-------	------------	-------	---------	------------	----------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	09/02/2022	07:09	09/02/2022	11:34	279,966	Gloucester	GC019602
-------------------	------------	-------	------------	-------	---------	------------	----------

18 Wheels Check Torques	
45 Engine Ad Blue	
71 Body Exterior 1	Body Exterior Reversed into TP, possible damage to rear of DCA
Road Test	
Safety Inspection	
Replace Handbrake Cables	Replace Handbrake Cables
Tail Lift Inspection	Awaiting Parts

Breakdown	05/03/2022	10:57	05/03/2022	12:57	284,229	Gloucester	GC019790
-----------	------------	-------	------------	-------	---------	------------	----------

Breakdown	side door not secured/malfunctioning; VOR
44 Add Ad Blue	
86 Sliding Door	top catch issue

Vehicle Deep Clean	07/03/2022	14:35	08/03/2022	07:50	284,418	Gloucester	GC019808
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/03/2022	08:23	08/03/2022	12:07	284,428	Gloucester	GC019812
18 Wheels Check Torques Safety Inspection Replace Handbrake Cables UB Fire Supp 6mts Service 33 Ignition System 17 Tyres Replace 01 Air Conditioning 1 Road Test	Replace Handbrake Cables UB Fire Supp 6mts Service key fob battery replace n/s front replace drive belt					Awaiting Parts	
Unplanned Repair	10/03/2022	07:54	10/03/2022	10:53	284,554	Gloucester	GC019843
54 Warn Dev/System							
Unplanned Repair	11/03/2022	11:02	11/03/2022	14:39	284,619	Gloucester	GC019858
45 Engine 1 44 Fuel System 1 Road Test	Belt shredded, replace drive belt. fuel smell						
02 Pipeline Annual Inspection	08/03/2022	12:40	09/03/2022	12:42	284,438	MDT Gloucester	MG001273
02 Pipeline Annual Inspection	Annual Inspection and Pressure Test						
Breakdown	18/04/2022	07:49	18/04/2022	09:16	288,178	Gloucester	GC020188
Breakdown 34 Lights 44 Add Ad Blue 45 Engine Oil Top Up 99 Diagnostic Test	blue light not working, working at time of test. N/S/F head lamp not working Reset service light						
SAFETY INSPECTION	19/04/2022	08:42	20/04/2022	09:35	288,353	Gloucester	GC020194
18 Wheels Check Torques							

Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
UB Fire Supp 12mts Service	Service of fire suppression system						
Engine Change Oil & Filter							
86 Door Lock	central locking not working						
45 Engine 1	oil leak monitor					Monitoring	
16 Suspension 1	replace rear arb bushes						
Road Test							
85 Body Interior 1	zoll fitting holes						

Vehicle Deep Clean	03/05/2022	15:15	03/05/2022	22:45	289,055	Gloucester	GC020321
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Vehicle Deep Clean	10/06/2022	08:25	10/06/2022	15:08	292,354	Gloucester	GC020606
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	30/06/2022	11:00	01/07/2022	11:49	294,230	Gloucester	GC020805
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques							
Safety Inspection							
45 Engine 1	oil leak monitor					Monitoring	
Tail Lift Inspection							
Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight						
Wheel Hub Flanges Replaceme						Awaiting Parts	
MOT							
13 Brakes 1	replace rear pads discs and shoes						
34 Lights	n/s front headlight required						
16 Suspension 1	spring buffers						
18 Wheels	Cleaning flanges rear						
17 Tyres Replace	All 6						
Road Test							

SAFETY INSPECTION	26/07/2022	08:46	26/07/2022	14:15	295,812	Gloucester	GC021016
18 Wheels Check Torques Safety Inspection Tail Lift Inspection UB Fire Supp 6mts Service 55 Tail Lift Road Test 86 Sliding Door 44 Add Ad Blue	UB Fire Supp 6mts Service tail lift rails loose/insecure. Replaced sliding door top magnet as rubber boot split/perished.						
Vehicle Deep Clean	27/07/2022	15:52	28/07/2022	10:59	295,834	Gloucester	GC021024
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	03/08/2022	10:00	03/08/2022	10:02	296,364	Gloucester	GC021073
34 Lights	Clean nearside wing indicator connections						
SAFETY INSPECTION	22/08/2022	08:33	22/08/2022	12:12	297,788	Gloucester	GC021207
18 Wheels Check Torques Safety Inspection 45 Engine 1 Wheel Hub Flanges Replacemerear flange still on back order 85 Body Interior 1 02 Windscreen Wipers	oil leak monitor pas window switch replace					Awaiting Parts	
Vehicle Deep Clean	23/08/2022	14:47	24/08/2022	11:00	297,800	Gloucester	GC021219
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	08/09/2022	05:48	08/09/2022	16:36	299,010	Gloucester	GC021345
Breakdown 15 Steering 1 01 Heating 1	Heating In Saloon smoke under Amb Replaced steering wheel Tested saloon heater working ok at the time of test						

Breakdown	26/09/2022	14:58	27/09/2022	11:52	299,020	Gloucester	GC021505
Breakdown	BLACK SMOKE FROM ENGINE						
45 Engine 1	found firewall fabric came loose, cut away,checked underneath as well						
Road Test	road tested with heater on and no black smoke						
SAFETY INSPECTION	07/10/2022	13:43	12/10/2022	08:59	301,533	Gloucester	GC021586
18 Wheels Check Torques							
Safety Inspection							
Wheel Hub Flanges Replacemerear flange still on back order							Awaiting Parts
45 Engine 1	EML on. Interrogate systems & found Air Mass sensor at fault						
Annual Air Con Service	Annual Air Condition Service						
Annual Heater Service	Annual Heater Service						
Tail Lift Inspection							
Pollen Filter Change	Pollen Filter Change						
Air Filter Change	Air Filter Change						
Fuel Filter Change	Change Fuel Filter						
02 Glass / Windows	O/S/F window switch broken						
45 Engine 2	Replace Air Mass sensor, erase faults & program new sensor to vehicle.						
85 Body Interior 1	Cab torch not working						
71 Body External Steps	Clean and lube side step.						
45 Engine Oil Top Up							
89 Seats	O/S/F seat base insecure.						
85 Body Interior 2	Saloon extractor fan not working. Tested and found wires broken repaired wiring						
85 Body Interior 3	Replaced cupboard gas struts						
Road Test							
Vehicle Deep Clean	12/10/2022	13:19	13/10/2022	13:10	301,555	Gloucester	GC021627
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	24/11/2022	05:34	24/11/2022	16:09	307,023	Gloucester	GC021944

Breakdown	sidestep not deploying						
Breakdown	24/11/2022	05:35	24/11/2022	16:15	307,023	Gloucester	GC021945
Breakdown	Ramp Intermittant Working						
34 Lights	Number plate lamp broken, replace lamp unit						
Breakdown	24/11/2022	05:37	27/11/2022	14:20	307,023	Gloucester	GC021946
Breakdown	Aux Battery Draining due to radio not turn off						
SAFETY INSPECTION	26/11/2022	09:10	27/11/2022	14:24	307,023	Gloucester	GC021971
18 Wheels Check Torques							
Safety Inspection							
Wheel Hub Flanges Replacement	rear flange still on back order						
34 Lights	Lighting System Rear number plate light- casing off						
13 Brake Pads	replace fronts						
55 Tail Lift	Replaced tilt ram						
Vehicle Deep Clean	01/12/2022	16:00	02/12/2022	12:30	307,559	Gloucester	GC022036
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	08/12/2022	15:59	09/12/2022	07:22	308,066	Gloucester	GC022090
Breakdown	heater is not working						
01 Heating 1	Removed heater replaced service kit and blower motor						
Breakdown	19/12/2022	12:37	20/12/2022	16:10	309,872	Gloucester	GC022176
Breakdown	Driverside front wheel makes knocking sound						
18 Wheels	replace o/s front wheel and flange as loose						
SAFETY INSPECTION	21/12/2022	06:40	23/12/2022	15:06	309,874	Gloucester	GC022207
18 Wheels Check Torques							

Safety Inspection
 Auto G/box Oil & Filter Change Auto G/box Oil & Filter Change
 Tail Lift Inspection
 UB Fire Supp 6mts Service UB Fire Supp 6mts Service
 Engine Change Oil & Filter
 03 Instruments & Sensors 1 Reset service light
 44 Add Ad Blue
 71 Body External Steps Clean & lube step, fit new suppressor flap (missing).
 34 Lights O/S/R top marker not working.
 31 Battery Chassis Test chassis battery.
 85 Body Interior 1 Step light not working & tool box cover broken.
 Road Test

Unplanned Repair **24/12/2022** **11:43** **24/12/2022** **14:26** **309,887** **Gloucester** **GC022221**

45 Engine 1 EML light on. Connect diag & interrogate systems found Cat temp sensor fault
 45 Engine 2 Fit new cat temp sensor.
 Road Test

Breakdown **28/12/2022** **12:16** **28/12/2022** **13:58** **309,929** **Gloucester** **GC022240**

Breakdown Only Starting Occasionally

Unplanned Repair **28/12/2022** **14:02** **28/12/2022** **14:08** **309,939** **Gloucester** **GC022242**

86 Sliding Door Repaired top catch rivited metal plate back on

ACCIDENT **10/01/2023** **16:32** **10/01/2023** **16:34** **310,021** **Gloucester** **GC022358**

71 Body External Steps Body Exterior rear step damage replaced

Vehicle Deep Clean **18/01/2023** **09:59** **18/01/2023** **15:56** **311,408** **Gloucester** **GC022421**

Vehicle Deep Clean Vehicle Deep Clean

Vehicle Deep Clean	07/02/2023	13:13	08/02/2023	15:05	313,168	Gloucester	GC022590
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	09/02/2023	13:53	10/02/2023	11:43	313,178	Gloucester	GC022616
18 Wheels Check Torques							
Safety Inspection							
Replace Handbrake Cables	Replace Handbrake Cables						
Wheel Hub Flanges Replacement	replaced both rear flanges						
Wheel Studs & Nuts Replacement	replaced all rear wheel nuts						
13 Brakes 1	replaced rear pads, both sides						
Road Test							
85 Body Interior 1	fit floor mats as floor split and brake pedal rubber						
Breakdown	28/02/2023	17:45	01/03/2023	07:29	313,178	Gloucester	GC022773
Breakdown	adblue blue tag isn't working, not vor						
02 Pipeline Annual Inspection	17/03/2023	09:19	17/03/2023	09:23	313,179	MDT Gloucester	MG002189
02 Pipeline Annual Inspection	New probes,ferrules and shrink cost £79.16+Vat,pressure/leak test pass						
Medical devices repair	17/03/2023	09:24	17/03/2023	09:29	313,179	MDT Gloucester	MG002190
Decontaminated	Cleaned with clinell wipes						
Defect Sheet Present No							
Defect Sheet Present Yes							
Medical Devices Repair	New SKTU001 fitted to port cost £8.10+Vat see notes						
Breakdown	20/03/2023	09:38	20/03/2023	11:56	313,179	Gloucester	GC022911
Breakdown	seat adjusting lever faulty						
Vehicle Deep Clean	21/03/2023	12:59	21/03/2023	16:26	313,179	Gloucester	GC022926
Vehicle Deep Clean	Vehicle Deep Clean						

SAFETY INSPECTION	24/04/2023	08:54	24/04/2023	17:21	316,033	Gloucester	GC023241
18 Wheels Check Torques							
Safety Inspection							
02 Windscreen Wipers			Body Exterior windscreen wiper come off				
54 Reversing Systems			Other REVERSING WARNING ALARM FAULT				
Tail Lift Inspection							
UB Fire Supp 12mts Service			Service of fire supression system				
Tail Lift 12M Service & Weight			Tail Lift 12M Service & Weight				
31 Charging System			110 cover				
Road Test							
16 Suspension 1			replace o/s leaf spring due to failure				
13 Discs			fronts				
17 Tyres Replace			n/s front				
Vehicle Deep Clean	27/04/2023	13:45	28/04/2023	07:32	316,033	Gloucester	GC023263
Vehicle Deep Clean			Vehicle Deep Clean				
Unplanned Repair	14/05/2023	12:15	14/05/2023	12:19	322,607	Gloucester	GC023376
44 Add Ad Blue			Top up Adblue				
45 Engine Oil Top Up							
Breakdown	05/06/2023	01:26	08/06/2023	13:55	325,000	Gloucester	GC023554
Breakdown			losing cooland				
42 Radiator			rad failure				
Road Test							
Vehicle Deep Clean	12/06/2023	07:04	12/06/2023	11:30	325,371	Gloucester	GC023615
Vehicle Deep Clean			Vehicle Deep Clean				

SAFETY INSPECTION	13/06/2023	08:16	14/06/2023	08:45	325,381	Gloucester	GC023621
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
85 Body Interior 3	MDT Failure/Issue mdt unable to log on, Showing communication error
71 Body Exterior 1	Body Exterior Scrape to N/S/R wheel arch
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	
Engine Change Oil & Filter	
Pollen Filter Change	Pollen Filter Change
02 Windscreen Wipers	Excessive play in wiper linkage
45 Engine Ad Blue	
86 Doors	
86 Door Seals	
34 Lights	
34 Lights Bulb Replacement	
71 Body Exterior 2	
85 Body Interior 1	
85 Body Interior 2	
02 Windscreen	
Air Filter Change	Air Filter Change
Road Test	

MOT EXPIRES	29/06/2023	10:03	30/06/2023	09:30	325,817	Gloucester	GC023787
--------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

MOT	going to rygors done for friday
-----	---------------------------------

Replace Vehicle Fuel Card	19/07/2023	13:39	19/07/2023	13:41	328,171	Gloucester	GC023971
----------------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Replace Vehicle Fuel Card	Replace Vehicle Fuel Card
---------------------------	---------------------------

Vehicle Deep Clean	28/07/2023	12:37	29/07/2023	09:58	330,975	Gloucester	GC024114
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean	
85 Body Interior 1	MISSING LIFEHAMMER FROM ABOVE BULKHEAD SEAT	Lack of Labour
02 Cab Assembly 1	DRIVER SIDE WINDOW SWITCH BROKEN	Lack of Labour

Breakdown	02/08/2023	13:18	05/08/2023	17:00	331,317	Gloucester	GC024140
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	side step wont deploy						
-----------	-----------------------	--	--	--	--	--	--

SAFETY INSPECTION	05/08/2023	07:30	06/08/2023	14:09	331,412	Gloucester	GC024158
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
85 Body Interior 1	MISSING LIFEHAMMER FROM ABOVE BULKHEAD SEAT
02 Cab Assembly 1	DRIVER SIDE WINDOW SWITCH BROKEN
Engine Change Oil & Filter	
Tail Lift Inspection	
45 Engine Ad Blue	
85 Body Interior 2	replace straps.
34 Emergency Lights	replace o/s/r/top blue lamp lens.
01 Air Conditioning 1	A/C HOSE blown off compressor carry out repair.
17 Tyres Replace	4 x rears.
02 Windscreen Wipers	

Breakdown	12/08/2023	08:30	12/08/2023	09:25	331,983	Gloucester	GC024225
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	O/S Brake Light Out						
-----------	---------------------	--	--	--	--	--	--

Install Saloon CCTV Camera	04/09/2023	09:12	04/09/2023	09:17	334,077	Gloucester	GC024415
-----------------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Install Saloon CCTV Camera	Swap CCTV hard drive						
----------------------------	----------------------	--	--	--	--	--	--

SAFETY INSPECTION	07/09/2023	07:25	08/09/2023	15:05	334,556	Gloucester	GC024433
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
71 Body External Steps	Side step not operating.
71 Body Exterior 1	Ramp/Lift/Tail Hoist Safety bar has malfunctioned on the tail lift. Check operat
Engine Oil & Filter Change	Engine Oil & Filter Change
Brake Fluid Change	Brake Fluid Change
16 Suspension 1	rear ARB bushes worn
13 Brakes 1	Rear brakes worn, will not make next inspection.

Road Test	
11 Axle Rear	Clean flanges
18 Wheels	Clean wheels
86 Sliding Door	Door wiring & micro switch fault.

Vehicle Deep Clean	11/09/2023	12:36	12/09/2023	08:01	334,781	Gloucester	GC024475
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	24/09/2023	14:09	24/09/2023	14:20	336,074	Gloucester	GC024575
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

34 Lights	tail lights inop
02 Windscreen Wipers	washer jets poor / u/s investigate

Unplanned Repair	07/10/2023	15:27	08/10/2023	07:22	336,955	Gloucester	GC024669
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

52 Electrical Aux	Shoreline unit broken
Install Saloon CCTV Camera	Pull hard drive as requested & format new hard drive.
44 Add Ad Blue	

SAFETY INSPECTION	20/10/2023	11:51	21/10/2023	08:47	338,574	Gloucester	GC024768
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
85 Body Interior 1	Other break glass hammer missing
52 Electrical Aux	Electrical Auxs WIRING CHECK FOR TERRAFIX REQ
55 Tail Lift	Ramp/Lift/Tail Hoist TAIL LIFT NOT DEPLOYING
31 Charging System	Battery/Charging Sys charging pin damaged on vehicle
56 Comms Power Failure	Comms Power Check jobs not going to MDT shassy battery low
Annual Heater Service	Annual Heater Service
Annual Air Con Service	Annual Air Condition Service
Pollen Filter Change	Pollen Filter Change
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
Engine Change Oil & Filter	

18 Wheels 56 Comms Equipment 17 Tyres Replace	O/S/R wheel nuts rust lines Aerial missing two fronts						
Vehicle Deep Clean	22/10/2023	15:14	23/10/2023	11:00	339,438	Gloucester	GC024782
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	05/11/2023	17:58	06/11/2023	11:51	341,178	Gloucester	GC024920
Breakdown	no heating at the back of the vehicle in use					Monitoring	
Unplanned Repair	11/11/2023	14:12	11/11/2023	14:14	341,636	Gloucester	GC024967
34 Lights Bulb Replacement	O/S Headlight bulb blown						
SAFETY INSPECTION	19/11/2023	17:01	20/11/2023	16:30	342,506	Gloucester	GC025028
18 Wheels Check Torques Safety Inspection 13 Discs Brake Fluid Change 31 Battery Chassis 13 Brakes 1 11 Axle Front 18 Wheels Road Test	Brakes Amber brake light - at Staverton replaced front Brake Fluid Change Check chassis battery, failed drop test. Replace battery. Replace front pads & discs. Clean flanges Clean wheels						
Unplanned Repair	25/11/2023	08:11	25/11/2023	09:28	342,878	Gloucester	GC025077
01 Heating 2	A/C System Saloon No heating						
Vehicle Deep Clean	27/11/2023	07:26	27/11/2023	10:46	342,997	Gloucester	GC025092
Vehicle Deep Clean	Vehicle Deep Clean						

Unplanned Repair	06/12/2023	09:56	06/12/2023	11:56	343,124	Gloucester	GC025166
02 Mirrors 71 Body Exterior 1	Mirrors PASSENGER WING MIRROR KNOCKED OFF Body Exterior N/S wing mirror						
Unplanned Repair	21/12/2023	10:10	22/12/2023	14:26	345,080	Gloucester	GC025298
27 Transmission Automatic Road Test	selector fault, not recognising park						
Emergency Deep Clean	29/12/2023	11:00	29/12/2023	12:26	345,542	Gloucester	GC025366
Emergency Deep Clean							
Vehicle Deep Clean	07/01/2024	11:00	07/01/2024	15:30	346,273	Gloucester	GC025433
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	08/01/2024	09:53	10/01/2024	10:39	346,342	Gloucester	GC025434
18 Wheels Check Torques Safety Inspection 89 Seatbelts UB Fire Supp 6mts Service Tail Lift Inspection Air Filter Change Fuel Filter Change Pollen Filter Change Engine Change Oil & Filter 45 Engine 1 41 Turbo Road Test	Other SEAT BELT WARNING UB Fire Supp 6mts Service Air Filter Change Change Fuel Filter Pollen Filter Change Fumes in engine bay, injectors leaking. Turbo seals leaking.						

02 Pipeline Annual Inspection	19/01/2024	10:56	19/01/2024	10:58	347,088	MDT Gloucester	MG002987
02 Pipeline Annual Inspection Annual Inspection and Pressure Test							
Medical devices repair	19/01/2024	10:59	19/01/2024	11:01	347,088	MDT Gloucester	MG002988
Decontaminated Cleaned with clinell wipes							
Defect Sheet Present No							
Defect Sheet Present Yes							
Medical Devices Repair Airflo 24 charging dock fitted							
Vehicle Deep Clean	20/02/2024	13:57	21/02/2024	07:45	351,057	Gloucester	GC025758
Vehicle Deep Clean Vehicle Deep Clean							
SAFETY INSPECTION	21/02/2024	10:47	21/02/2024	13:53	351,071	Gloucester	GC025768
18 Wheels Check Torques							
Safety Inspection							
87 Stretcher battery replace							
17 Tyres Replace replace o/s inner							
Breakdown	02/04/2024	20:01	05/04/2024	15:44	355,565	Gloucester	GC026076
Breakdown Red Battery Alternator light							
Replace Handbrake Cables Replace Handbrake Cables next inspection or when rear brakes next replaced.							
Tail Lift Inspection							
18 Wheels Check Torques							
Safety Inspection							
Engine Oil & Filter Change Engine Oil & Filter Change							
13 Brake Pads Rear brake pads low.							
55 Tail Lift Tail lift rails insecure.							
11 Axle Rear Clean flanges							
18 Wheels Clean wheels.							
44 Add Ad Blue							
99 Diagnostic Test Reset service light.							
Road Test							
71 Body Exterior 1 Note: N/S/R corner cap damaged but reflector still intact. Next inspection.							

Vehicle Deep Clean	03/04/2024	11:47	03/04/2024	15:00	355,545	Gloucester	GC026081
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	10/04/2024	16:29	11/04/2024	14:49	356,066	Gloucester	GC026141
01 Air Conditioning 1 34 Lights Bulb Replacement	AC belt thrown O/S side light bulb inop						
Breakdown	26/04/2024	02:12	26/04/2024	07:13	357,119	Gloucester	GC026250
Breakdown	n/S headlight out						
Unplanned Repair	27/04/2024	10:48	27/04/2024	10:53	357,120	Gloucester	GC026261
45 Engine 1	inv loss power / limp mode						
Unplanned Repair	29/04/2024	11:36	29/04/2024	11:41	357,424	Gloucester	GC026283
34 Lighting System	replace o/s/r fog lamp.						
Unplanned Repair	04/05/2024	09:47	04/05/2024	09:52	357,941	Gloucester	GC026335
02 Mirrors	Body Exterior N/S wing mirror gone						
Vehicle Deep Clean	13/05/2024	20:46	14/05/2024	02:00	358,892	Gloucester	GC026414
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	15/05/2024	14:16	17/05/2024	15:14	358,958	Gloucester	GC026437
18 Wheels Check Torques Safety Inspection UB Fire Supp 12mts Service	Service of fire suppression system						

Tail Lift 12M Service & Weight	Tail Lift 12M Service & Weight
85 Body Interior 1	Air vent broken
31 Battery Aux	Test all batteries, replace TL battery as failed test.
32 Starting System 1	Vehicle will not start. Carried out checks, found starter motor has failed.
Road Test	
Pollen Filter Change	Pollen Filter Change
31 Charging System Battery	110v system not charging correctly. Strip & inspect. found poor connection.

Unplanned Repair	29/05/2024	14:20	29/05/2024	14:26	359,494	Gloucester	GC026587
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

31 Battery Aux	Warning message for auxilliary battery, low voltage.
----------------	--

Vehicle Deep Clean	27/06/2024	18:45	27/06/2024	23:00	362,459	Gloucester	GC026926
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	27/06/2024	22:53	28/06/2024	14:00	362,459	Gloucester	GC026927
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	loss of hydraulic fluid
-----------	-------------------------

SAFETY INSPECTION	29/06/2024	12:55	05/07/2024	10:54	362,552	Gloucester	GC026950
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques
Safety Inspection
Tail Lift Inspection
MOT

41 Turbo	turbo has failed (front propeller broken off)
17 Tyres Replace	O\S\F and N\S\F as both was heavily worn on inside edge
55 Tail Lift	wire broken in controller, repaired and is now working
13 Handbrake	adjusted as had to many clicks
17 Tyres	N\S\R\I is on 4.5mm check next safety
34 Emergency Lights	top row led for blue lights ha two leds out-monitor
34 Lights	both front alley lamps has one blown bulb- parts arriving soon
13 Brake Pads	replaced fronts

Monitoring
Monitoring

Unplanned Repair	21/07/2024	16:31	26/07/2024	16:08	364,925	Gloucester	GC027223
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

42 Coolant System	Coolant leak suspect water pump (see notes)
Engine Change Oil & Filter	because im changing oil filter housing so might aswell
Aux drive belt change	changing both as i have all the front off
45 Engine 1	replacing all tensioners, vac pump, water pump and idlers

SAFETY INSPECTION	05/08/2024	06:52	06/08/2024	16:36	365,934	Gloucester	GC027381
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Check and Fit P-Clips	Check for the presence of P-Clips and fit if not present
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
17 Tyres Replace	replace n/s rear inner and out
02 Windscreen Wipers	
71 Body Exterior 1	shoreline cover was damaged, replaced
34 Lights	N\S white led was out, replaced
45 Engine 1	gearbox rubber broken, replaced
13 Brakes 1	rear disks and pads next saftey-7.5mm 06/08/24
55 Tail Lift	merc switch is faulty, investigate

Monitoring

Vehicle Deep Clean	11/08/2024	10:30	11/08/2024	15:00	366,340	Gloucester	GC027463
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Breakdown	13/08/2024	10:45	13/08/2024	14:49	366,340	Gloucester	GC027492
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Small stone chip in drivers line.
02 Mirrors	N/S mirror wobbling

Emergency Deep Clean	25/08/2024	09:58	25/08/2024	16:16	367,799	Gloucester	GC027671
-----------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Emergency Deep Clean	
----------------------	--

Unplanned Repair	27/08/2024	09:38	27/08/2024	14:17	367,895	Gloucester	GC027702
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

13 Brakes 1	rear disks and pads next saftey-7.5mm 06/08/24
34 Lights	Lighting System O/S side light out
34 Lighting System	Lighting System O/S rear tail light cover missing

02 Mirrors	Mirrors Glass portion of wing mirror loose
56 Comms Power Failure	Terrafix tablet shutting down
31 Battery Chassis	Battery warning showing low battery
Travel Time	

ACCIDENT	02/09/2024	03:11	03/09/2024	07:32	368,364	Gloucester	GC027798
-----------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	N/S wing mirror accident damage to glass in use
-----------	---

Breakdown	20/09/2024	14:16	20/09/2024	15:54	369,882	Gloucester	GC028133
------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Breakdown	Low oil warning
71 Body Exterior 2	Refit O/S/R reflector panel

Vehicle Deep Clean	22/09/2024	11:30	22/09/2024	16:30	370,048	Gloucester	GC028172
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

SAFETY INSPECTION	23/09/2024	07:33	28/09/2024	14:13	370,061	Gloucester	GC028183
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

18 Wheels Check Torques	
Safety Inspection	
Tail Lift Inspection	
87 Stretcher	Spare battery faulty
Engine Change Oil & Filter	
Air Filter Change	Air Filter Change
Fuel Filter Change	Change Fuel Filter
Pollen Filter Change	Pollen Filter Change
86 Doors Rear	lock barrels on scoop locker and rear door inop inv
85 Body Interior Roof	blind damaged , jammed in hatch causing water ingress. retify
01 Air Conditioning 1	rear condensor corroded and falling out of vehicle/ insecure.
Road Test	
24 Driveshaft 2	Thelma not working control box water ingress
34 Lights Bulb Replacement	N/S alley light bulb inop
71 Body Exterior 1	Damage to N/S door & sill

Unplanned Repair	18/10/2024	16:29	19/10/2024	07:59	372,715	Gloucester	GC028726
71 Body Exterior 1 16 Suspension 1 road test	Body Exterior rear reflector knocked off Noise from wheel bearing						
Vehicle Deep Clean	02/11/2024	10:30	02/11/2024	16:20	374,209	Gloucester	GC029020
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	18/11/2024	14:02	21/11/2024	11:53	376,594	Gloucester	GC029347
18 Wheels Check Torques Safety Inspection 56 Comms Equipment 89 Seats 34 Lights Bulb Replacement Engine Change Oil & Filter 13 Brakes 1 13 Brakes 2 11 Axle Front 11 Axle Rear 18 Wheels 43 Exhaust System 1 45 Engine Ad Blue	Radio & Comm System The unit is not tracking. Rear Jany seat insecure N/S side light bulb inop Replace front brake pads Replace rear brake pads Clean flanges Clean flanges Clean wheels Replace exhaust clamps						
Unplanned Repair	23/11/2024	07:41	23/11/2024	15:00	376,780	Gloucester	GC029438
86 Sliding Door 86 Door Hinges	SLD opening when driving SLD hinge rollers partially seized						
Unplanned Repair	30/11/2024	15:47	01/12/2024	06:56	377,735	Gloucester	GC029596
86 Sliding Door	opens randomly on self, and constant door open warning						

Vehicle Deep Clean	16/12/2024	04:00	16/12/2024	12:00	379,651	Gloucester	GC029933
---------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Vehicle Deep Clean	Vehicle Deep Clean
--------------------	--------------------

Unplanned Repair	11/01/2025	07:06	16/01/2025	16:33	382,203	Gloucester	GC030542
-------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

45 Engine 1	Fumes in cab
Tail Lift Inspection	
Annual Heater Service	Annual Heater Service
Safety Inspection	
18 Wheels Check Torques	
Road Test	
Engine Change Oil & Filter	
44 Add Ad Blue	
34 Lights	Front side lights not working.
87 - Stretchers/Chairs/Boards	Scoop 113492, Chair CC005506C, Track 10340988 , Stretcher 70539901

02 Pipeline Annual Inspection	14/01/2025	10:41	14/01/2025	10:42	382,203	MDT Gloucester	MG003927
--------------------------------------	-------------------	--------------	-------------------	--------------	----------------	-----------------------	-----------------

02 Pipeline Annual Inspection	Annual Inspection and Pressure Test
-------------------------------	-------------------------------------

SAFETY INSPECTION	22/02/2025	15:32	25/02/2025	11:37	387,657	Gloucester	GC031496
--------------------------	-------------------	--------------	-------------------	--------------	----------------	-------------------	-----------------

Safety Inspection	
18 Wheels Check Torques	
Road Test	
UB Fire Supp 6mts Service	UB Fire Supp 6mts Service
Tail Lift Inspection	
Engine Change Oil & Filter	
86 Sliding Door	Opening when driving
34 Lights Bulb Replacement	DRL bulbs gone black
34 Lights	O/S side repeater lens broken
16 Suspension 1	O/S/F shock leaking
Air Filter Change	Air Filter Change
Pollen Filter Change	Pollen Filter Change
44 Add Ad Blue	

Vehicle Deep Clean	05/03/2025	06:52	05/03/2025	13:47	387,657	Gloucester	GC031767
Vehicle Deep Clean	Vehicle Deep Clean						
SAFETY INSPECTION	05/03/2025	15:51	05/03/2025	15:52	388,465	Gloucester	GC031775
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test	Check and Install MDVS windows update						
BREAKDOWN	09/03/2025	15:56	10/03/2025	15:21	388,658	Gloucester	GC031860
86 Sliding Door 56 Comms Equipment	sliding door mech broken on top hinge Radio & Comm System Power adapter/ Dock for HH radio is faulty						
Breakdown	16/03/2025	10:19	16/03/2025	15:00	389,309	Gloucester	GC031997
Breakdown	oxygen storage door not closing						
Unplanned Repair	28/03/2025	12:47	02/04/2025	08:46	391,052	Gloucester	GC032315
01 Heating 1 31 Charging System 31 Battery Comms	A/C System Cab HEATING ON FULL. TERRAFIX NOT TURNING OFF Shore line not charging batteries coms battery at 10.8 volts						
SAFETY INSPECTION	20/04/2025	15:04	20/04/2025	15:39	392,485	Gloucester	GC032890
Check MDVS for Update Safety Inspection 18 Wheels Check Torques Road Test	Check and Install MDVS windows update						

54 Sirens 17 Tyres	Other Reverse sensor silent monitor o/s front tyre (not replaced due to being decom next)						
Vehicle Deep Clean	22/04/2025	13:30	22/04/2025	17:30	392,897	Gloucester	GC032941
Vehicle Deep Clean	Vehicle Deep Clean						
Unplanned Repair	17/05/2025	09:22	18/05/2025	11:22	392,897	Gloucester	GC033552
55 Tail Lift	TAILIFT CONTROL - BUTTONS ON WANDER LEAD N/W						
SAFETY INSPECTION	28/05/2025	07:56	29/05/2025	14:02	393,152	Gloucester	GC033856
Safety Inspection 18 Wheels Check Torques Road Test 56 Comms Power Failure 55 Tail Lift 17 Tyres Annual Air Con Service 44 Add Ad Blue 34 Lights 18 Wheels Balance & Alignmen 86 Doors Rear 17 Tyres Replace 43 Exhaust System 2 71 Body Exterior 3 44 Fuel System 2 45 Engine Oil Top Up	Comms Power Check WIRING CHECK ON MDT Battery/Charging Sys Battery issue - tail lift intermittent also lamp inop RH Tyres Front offside bald Annual Air Condition Service O/S side light bulb fallen out of holder Balance new wheel & tyre N/S/F RH door retainer block broken OS/R & N/S/R outer tyres cut to cord Tail pipe holed Spray flap loose Fuel tank heat shield loose						
Breakdown	06/06/2025	01:10	06/06/2025	12:17	393,200	Gloucester	GC034099
Breakdown	left lights on, battery dead						
Breakdown	07/06/2025	06:27	08/06/2025	08:10	393,699	Gloucester	GC034135
Breakdown	alternator not working						

31 Battery Comms	Radio battery u/s						
Vehicle Deep Clean	09/06/2025	09:00	09/06/2025	16:00	393,699	Gloucester	GC034204
Vehicle Deep Clean	Vehicle Deep Clean						
Breakdown	26/06/2025	13:59	28/06/2025	08:15	394,010	Gloucester	GC034720
Breakdown MOT	vehicle in limp mode						
Decommission Vehicle	28/06/2025	17:23			394,512	Gloucester	GC034789
Decommission vehicle	Decommission vehicle						